


Ollie?s

411 West 42nd Street
New York, NY 10036

Inquiry Number: 4056019.6s
September 04, 2014

The EDR Radius Map™ Report with GeoCheck®



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1624
Government Records Searched/Data Currency Tracking	GR-1
 <u>GEOCHECK ADDENDUM</u>	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2014 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

411 WEST 42ND STREET
NEW YORK, NY 10036

COORDINATES

Latitude (North): 40.7589000 - 40° 45' 32.04"
Longitude (West): 73.9931000 - 73° 59' 35.16"
Universal Transverse Mercator: Zone 18
UTM X (Meters): 584992.6
UTM Y (Meters): 4512269.5
Elevation: 32 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 40073-G8 CENTRAL PARK, NY NJ
Most Recent Revision: 1995

South Map: 40073-F8 BROOKLYN, NY
Most Recent Revision: 1995

Southwest Map: 40074-F1 JERSEY CITY, NJ NY
Most Recent Revision: 1981

West Map: 40074-G1 WEEHAWKEN, NJ NY
Most Recent Revision: 1995

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from: 20100731, 20110705
Source: USDA

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
CON EDISON 411 W 42ND ST NEW YORK, NY 10036	FINDS	N/A
CON EDISON 411 W 42ND ST NEW YORK, NY 10001	RCRA-CESQG	NYP004167219

EXECUTIVE SUMMARY

CONSOLIDATED EDISON
411 W 42ND ST
NEW YORK, NY 10001

NY MANIFEST

N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL..... Proposed National Priority List Sites
NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY..... Federal Facility Site Information listing

Federal RCRA CORRACTS facilities list

CORRACTS..... Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF..... RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS..... Land Use Control Information System

Federal ERNS list

ERNS..... Emergency Response Notification System

State- and tribal - equivalent CERCLIS

NJ SHWS..... Known Contaminated Sites in New Jersey
NY VAPOR REOPENED..... Vapor Intrusion Legacy Site List

State and tribal landfill and/or solid waste disposal site lists

NJ SWF/LF..... Solid Waste Facility Directory

EXECUTIVE SUMMARY

State and tribal leaking storage tank lists

NY HIST LTANKS..... Listing of Leaking Storage Tanks
INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

NJ UST..... Underground Storage Tank Data
NY MOSF UST..... Major Oil Storage Facilities Database
NY MOSF AST..... Major Oil Storage Facilities Database
NY MOSF..... Major Oil Storage Facility Site Listing
INDIAN UST..... Underground Storage Tanks on Indian Land
FEMA UST..... Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

NJ ENG CONTROLS..... Declaration Environmental Restriction/Deed Notice Sites
NJ INST CONTROL..... Classification Exception Area Sites
NY RES DECL..... Restrictive Declarations Listing

State and tribal voluntary cleanup sites

NJ VCP..... Voluntary Cleanup Program Sites
INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP..... Environmental Restoration Program Listing
NJ BROWNFIELDS..... Brownfields Database

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations
ODI..... Open Dump Inventory
NY SWTIRE..... Registered Waste Tire Storage & Facility List
NY SWRCY..... Registered Recycling Facility List
NJ SWRCY..... Approved Class B Recycling Facilities
INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs
NY DEL SHWS..... Delisted Registry Sites
US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

EXECUTIVE SUMMARY

NY LIENS..... Spill Liens Information
NJ LIENS..... Environmental LIENS

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System
NY Hist Spills..... SPILLS Database
NY SPILLS 80..... SPILLS 80 data from FirstSearch
NY SPILLS 90..... SPILLS 90 data from FirstSearch
NJ SPILLS 90..... SPILLS 90 data from FirstSearch
NJ SPILLS 80..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOT OPS..... Incident and Accident Data
DOD..... Department of Defense Sites
FUDS..... Formerly Used Defense Sites
UMTRA..... Uranium Mill Tailings Sites
US MINES..... Mines Master Index File
TRIS..... Toxic Chemical Release Inventory System
TSCA..... Toxic Substances Control Act
FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing
SSTS..... Section 7 Tracking Systems
PADS..... PCB Activity Database System
MLTS..... Material Licensing Tracking System
RADINFO..... Radiation Information Database
RAATS..... RCRA Administrative Action Tracking System
RMP..... Risk Management Plans
NY UIC..... Underground Injection Control Wells
NJ UIC..... Underground Injection Wells Database
NJ DRYCLEANERS..... Drycleaner List
NY SPDES..... State Pollutant Discharge Elimination System
NJ NPDES..... New Jersey Pollutant Discharge Elimination System Dischargers
NY AIRS..... Air Emissions Data
INDIAN RESERV..... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
NY Financial Assurance..... Financial Assurance Information Listing
NY COAL ASH..... Coal Ash Disposal Site Listing
2020 COR ACTION..... 2020 Corrective Action Program List
COAL ASH DOE..... Steam-Electric Plant Operation Data
PCB TRANSFORMER..... PCB Transformer Registration Database
COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List
NJ Financial Assurance..... Financial Assurance Information Listing
US FIN ASSUR..... Financial Assurance Information
NJ COAL ASH..... Coal Ash Listing
LEAD SMELTERS..... Lead Smelter Sites

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List
NJ RGA LF..... Recovered Government Archive Solid Waste Facilities List
NJ RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
<i>HUDSON RIVER PCBS</i>	<i>NO STREET APPLICABLE</i>	<i>WNW 1/2 - 1 (0.532 mi.)</i>	<i>0</i>	<i>12</i>

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
<i>NEW YORK TIMES CO</i>	<i>229 W 43 ST</i>	<i>ESE 1/4 - 1/2 (0.329 mi.)</i>	<i>CU584</i>	<i>1411</i>

EXECUTIVE SUMMARY

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/11/2014 has revealed that there are 7 RCRA-LQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON - MANHOLE 39880	NWC W 43 ST	ENE 0 - 1/8 (0.052 mi.)	G50	112
HOLY CROSS CHURCH	331 WEST 42ND STREET	SE 1/8 - 1/4 (0.159 mi.)	AJ243	465
THE STAYBRIDGE	334 -340 WEST 40TH STRE	SSE 1/8 - 1/4 (0.184 mi.)	AX305	595
CON EDISON - MANHOLE 32350	W 42 ST. & 8 AVE.	ESE 1/8 - 1/4 (0.208 mi.)	BL384	794
WEST 39TH STREET LLC	328-336 W 39TH ST	SSE 1/8 - 1/4 (0.227 mi.)	BR459	987
PABT - PORT AUTHORITY BUS TERM	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC479	1051
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
PUBLIC SCHOOL 51M	515-533 W 44TH ST	NW 1/8 - 1/4 (0.198 mi.)	BF350	687

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/11/2014 has revealed that there are 6 RCRA-SQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
315 ASSOCIATES	315 W 39TH ST	SSE 1/8 - 1/4 (0.219 mi.)	BR427	916
REMCO MAINTENANCE CORPORATION	10TH AVE	WSW 1/8 - 1/4 (0.248 mi.)	CO547	1248
A S I SIGN SYSTEMS INC	500 10TH AVE 6TH FLOOR	WSW 1/8 - 1/4 (0.248 mi.)	CO548	1267
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CVS PHARMACY #2940	500 W 42ND ST	WNW 1/8 - 1/4 (0.135 mi.)	AC172	336
OMNI CLEANERS CORP	595 10TH AVE	NW 1/8 - 1/4 (0.142 mi.)	AE202	401
NY PUBLIC LIBRARY - 43RD ST AN	521 W 43RD ST	NW 1/8 - 1/4 (0.199 mi.)	BE354	693

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/11/2014 has revealed that there are

EXECUTIVE SUMMARY

77 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE BOX: 8106	402 W 42ND ST	SSE 0 - 1/8 (0.037 mi.)	B11	54
CON EDISON MANHOLE: 39875	584 9TH AVE	SE 0 - 1/8 (0.041 mi.)	B20	67
CON EDISON SERVICE BOX: 8120	W 42ND ST & 9TH AVE	SE 0 - 1/8 (0.042 mi.)	B24	71
CON EDISON SERVICE BOX: 8323	434 W 43RD ST	N 0 - 1/8 (0.043 mi.)	F26	72
CON EDISON SERVICE BOX: 39866	576 9TH AVE	SSE 0 - 1/8 (0.050 mi.)	B43	102
CON EDISON MANHOLE: 39884	W 43RD ST & 9TH AVE NE	ENE 0 - 1/8 (0.052 mi.)	G47	109
CON EDISON SERVICE BOX: 39873	W 43RD ST & 9TH AVE SW	ENE 0 - 1/8 (0.052 mi.)	G48	110
CON EDISON SERVICE BOX: 39865	572 9TH AVE	SSE 0 - 1/8 (0.054 mi.)	H54	119
CON EDISON SERVICE BOX: 39885	606 9TH AVE	ENE 0 - 1/8 (0.062 mi.)	G67	148
CON EDISON SERVICE BOX: 8121	358 W 42ND ST	SE 0 - 1/8 (0.108 mi.)	T125	242
CON EDISON SERVICE BOX: 8123	348 W 42ND ST	SE 1/8 - 1/4 (0.126 mi.)	T160	307
CON EDISON SERVICE BOX: 8491	357 W 44TH ST	E 1/8 - 1/4 (0.141 mi.)	AI197	395
CON EDISON SERVICE BOX: 8519	642 9TH AVE	NE 1/8 - 1/4 (0.142 mi.)	AG200	400
CON EDISON SERVICE BOX: 8125	336 W 42ND ST	SE 1/8 - 1/4 (0.146 mi.)	AJ209	411
CON EDISON SERVICE BOX: 8492	351 W 44TH ST	E 1/8 - 1/4 (0.149 mi.)	AI213	419
CON EDISON MANHOLE: 8504	344 W 44TH	E 1/8 - 1/4 (0.156 mi.)	AI232	447
CON EDISON SERVICE BOX: 8122	327 W 42ND ST	SE 1/8 - 1/4 (0.162 mi.)	AJ250	476
CON EDISON SERVICE BOX: 8128	324 W 42ND ST	SE 1/8 - 1/4 (0.165 mi.)	AJ255	481
CON EDISON	W 39TH ST & 9TH AVE	SSW 1/8 - 1/4 (0.171 mi.)	AO270	507
CON EDISON MANHOLE: 7401	400 W 39TH ST	SSW 1/8 - 1/4 (0.171 mi.)	AO276	518
CON EDISON SERVICE BOX: 39829	515 9TH AVE	SSW 1/8 - 1/4 (0.186 mi.)	AO314	619
CINERIC INC	321 W 44TH ST - 4TH FL	E 1/8 - 1/4 (0.189 mi.)	AP326	642
CON EDISON SERVICE BOX: 39914	W 46TH ST & 9TH AVE NE	NE 1/8 - 1/4 (0.189 mi.)	BA328	648
CON EDISON SERVICE BOX: 8863	425 W 46TH & 9TH AVE FR	NNE 1/8 - 1/4 (0.197 mi.)	AV345	683
CON EDISON SERVICE BOX: 8858	459 W 46TH ST	N 1/8 - 1/4 (0.205 mi.)	BJ373	747
CON EDISON SILO: 8693	328 W 45TH ST	ENE 1/8 - 1/4 (0.207 mi.)	BD381	791
CON EDISON	W 42ND ST & 8TH AVE	ESE 1/8 - 1/4 (0.208 mi.)	BL383	793
NYCTA - W 42ND ST & 8TH AVE ST	W 42ND ST & 8TH AVE	ESE 1/8 - 1/4 (0.208 mi.)	BL385	795
CON EDISON SERVICE BOX: 32367	672 8TH AVE	ESE 1/8 - 1/4 (0.209 mi.)	BM388	814
TECHNICOLOR	321 W 44TH ST	E 1/8 - 1/4 (0.210 mi.)	BI401	837
CON EDISON SERVICE BOX: 8879	363 W 46TH ST	ENE 1/8 - 1/4 (0.212 mi.)	BS409	882
CON EDISON SERVICE BOX: 39821	503 9TH AVE	SSW 1/8 - 1/4 (0.213 mi.)	BH414	889
CON EDISON SERVICE BOX: 8500	305 W 44TH ST	E 1/8 - 1/4 (0.214 mi.)	BI415	890
CON EDISON SERVICE BOX: 8880	357 W 46TH ST	ENE 1/8 - 1/4 (0.217 mi.)	BS420	902
CON EDISON SERVICE BOX: 7671	312 W 40TH ST	SSE 1/8 - 1/4 (0.218 mi.)	BN422	904
CON EDISON SERVICE BOX: 8510	300 W 44TH	E 1/8 - 1/4 (0.220 mi.)	BI433	929
CON EDISON SERVICE BOX: 8881	353 W 46TH ST	ENE 1/8 - 1/4 (0.220 mi.)	BS436	937
EMPIRE CLEANERS	674 9TH AVE.	NE 1/8 - 1/4 (0.221 mi.)	BQ437	938
CON EDISON SERVICE BOX: 8892	346 W 46TH & 8TH AVE FR	ENE 1/8 - 1/4 (0.222 mi.)	BX443	958
CON EDISON SERVICE BOX: 7173	350 W 38TH ST	SSW 1/8 - 1/4 (0.225 mi.)	BY449	966
CON EDISON SERVICE BOX: 39820	497 9TH AVE	SSW 1/8 - 1/4 (0.227 mi.)	BY460	989
CON EDISON SERVICE BOX: 7674	304 W 40TH ST	SSE 1/8 - 1/4 (0.229 mi.)	BN469	1030
CON EDISON SERVICE BOX: 39825	498 9TH AVE	SSW 1/8 - 1/4 (0.231 mi.)	BY475	1041
CON EDISON	416 W 47TH ST	NNE 1/8 - 1/4 (0.233 mi.)	CF491	1120
CON EDISON SERVICE BOX: 7152	456 W 38TH ST	SW 1/8 - 1/4 (0.235 mi.)	CA504	1148
CON EDISON SERVICE BOX: 7419	316 W 39TH ST	SSE 1/8 - 1/4 (0.243 mi.)	CL530	1220
NEW YORK TRANSIT AUTH	560 TENTH AVE	WSW 1/8 - 1/4 (0.248 mi.)	CO550	1289
CON EDISON SERVICE BOX: 7420	310 W 39TH ST	SSE 1/8 - 1/4 (0.250 mi.)	CL555	1326
Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	425 W 42ND ST	W 0 - 1/8 (0.037 mi.)	C13	57
CON EDISON SERVICE BOX: 8103	427 W 42ND ST	W 0 - 1/8 (0.043 mi.)	C28	75
CON EDISON SERVICE BOX: 8320	456 W 43RD ST	NNW 0 - 1/8 (0.070 mi.)	J72	157
CON EDISON	436 W 42ND ST	WNW 0 - 1/8 (0.071 mi.)	I74	161

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	469 W 42ND ST OPPOSITE	WNW 0 - 1/8 (0.095 mi.)	P110	217
CON EDISON SERVICE BOX: 43272	582 10TH AVE	WNW 1/8 - 1/4 (0.132 mi.)	AC164	325
CON EDISON SERVICE BOX: 8049	587 10TH AVE	NW 1/8 - 1/4 (0.137 mi.)	AC178	361
CON EDISON MANHOLE: 43279	W 43RD ST & 10TH AVE NE	NW 1/8 - 1/4 (0.138 mi.)	AE183	371
CON EDISON SERVICE BOX: 43260	561 10TH AVE OPPOSITE O	W 1/8 - 1/4 (0.145 mi.)	AH207	409
CON EDISON SERVICE BOX: 8301	503 W 43RD ST	NW 1/8 - 1/4 (0.151 mi.)	AE218	425
CON EDISON SERVICE BOX: 43254	548 10TH AVE	W 1/8 - 1/4 (0.153 mi.)	AL224	432
CON EDISON SERVICE BOX: 43253	544 10TH AVE	W 1/8 - 1/4 (0.157 mi.)	AL237	459
CON EDISON SERVICE BOX: 43249	547 10TH AVE	W 1/8 - 1/4 (0.161 mi.)	AL247	472
CON EDISON SERVICE BOX: 7392	405 W 39TH ST	SSW 1/8 - 1/4 (0.169 mi.)	AO260	489
CON EDISON	626 10TH AVE	NNW 1/8 - 1/4 (0.169 mi.)	AR263	496
CON EDISON SERVICE BOX: 43286	628 10TH AVE OPPOSITE	NNW 1/8 - 1/4 (0.177 mi.)	AR283	529
CON EDISON MANHOLE: 43247	W 40TH ST & 10TH AVE NW	WSW 1/8 - 1/4 (0.178 mi.)	AU287	534
CON EDISON SERVICE BOX: 7873	510 W 41ST ST	W 1/8 - 1/4 (0.185 mi.)	AZ310	614
CON EDISON SERVICE BOX: 8068	519 W 42ND ST	WNW 1/8 - 1/4 (0.186 mi.)	AW316	622
CON EDISON SERVICE BOX: 7623	535 W 40TH ST	W 1/8 - 1/4 (0.209 mi.)	BO395	827
CON EDISON SERVICE BOX: 43239	519 10TH AVE OPPOSITE	WSW 1/8 - 1/4 (0.209 mi.)	BP399	832
CON EDISON SERVICE BOX: 8074	546 W 42ND ST	WNW 1/8 - 1/4 (0.223 mi.)	BW446	963
CON EDISON MANHOLE: 8295	541 W 43RD ST	NW 1/8 - 1/4 (0.226 mi.)	BT451	972
MERCEDES-BENZ MANHATTAN INC	528 W 41ST ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ462	992
CON EDISON SERVICE BOX: 8073	550 W 42ND ST	WNW 1/8 - 1/4 (0.229 mi.)	BW472	1034
CON EDISON SERVICE BOX: 7384	514 W 39TH ST	WSW 1/8 - 1/4 (0.233 mi.)	CD484	1108
CON EDISON SERVICE BOX: 7621	549 W 40TH ST	W 1/8 - 1/4 (0.234 mi.)	CH496	1130
MERCEDES BENZ MANHATTAN INC	528 W 39TH ST	WSW 1/8 - 1/4 (0.242 mi.)	CD526	1198
CON EDISON SERVICE BOX: 7871	551 W 41ST ST	WNW 1/8 - 1/4 (0.244 mi.)	BZ533	1223

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 07/16/2014 has revealed that there is 1 NY SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARTKRAFT STRAUSS SIGN CO	500 W 56TH ST	N 1/2 - 1 (0.874 mi.)	676	1616

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 07/08/2014 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON (12TH AVE AND 45TH	12TH AVENUE AND 45TH ST	NW 1/4 - 1/2 (0.448 mi.)	DE644	1553

EXECUTIVE SUMMARY

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON-EDISON @ SERVICE CENTER	12TH AVENUE & 45TH STREE	NW 1/4 - 1/2 (0.448 mi.)	DE645	1554

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/19/2014 has revealed that there are 126 NY LTANKS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
611 9TH AVE Spill Number/Closed Date: 9406176 / 2/17/2004	611 9TH AVENUE	ENE 0 - 1/8 (0.063 mi.)	G68	149
RESIDENCE TTF Spill Number/Closed Date: 1112434 / 5/31/2012	351 WEST 42ND ST	ESE 0 - 1/8 (0.077 mi.)	L78	165
APARTMENT COMPLEX Spill Number/Closed Date: 9911768 / 3/6/2006	438 W.45TH ST	NNE 0 - 1/8 (0.102 mi.)	Q119	231
BAPTIST CHURCH Spill Number/Closed Date: 0713240 / 8/14/2008	410 WEST 40TH	SSW 0 - 1/8 (0.120 mi.)	Y142	280
351 WEST 41 ST BUILDING Spill Number/Closed Date: 0203840 / 3/15/2005	351 WEST 41 STREET	SE 0 - 1/8 (0.124 mi.)	AA158	302
330 WEST 43RD STREET Spill Number/Closed Date: 9512825 / 1/16/1996	330 WEST 43RD STREET	ESE 1/8 - 1/4 (0.158 mi.)	AN239	461
ST CLEMENTS Spill Number/Closed Date: 0308286 / 4/12/2006	423 WEST 46TH ST	NNE 1/8 - 1/4 (0.187 mi.)	AY324	637
TANK TEST FAILURE TTF Spill Number/Closed Date: 1009654 / 1/13/2011	341 W 45TH ST	ENE 1/8 - 1/4 (0.194 mi.)	BD338	668
METRO Spill Number/Closed Date: 0713297 / 6/19/2008	9TH AVE 38TH STREET	SSW 1/8 - 1/4 (0.219 mi.)	BH432	927
416 WEST 47TH STREET Spill Number/Closed Date: 9909811 / 6/13/2005	416 WEST 47TH ST	NNE 1/8 - 1/4 (0.233 mi.)	CF490	1118
RESIDENCE Spill Number/Closed Date: 0206941 / 11/29/2002	454 WEST 47TH ST	NNE 1/8 - 1/4 (0.242 mi.)	CK524	1196
326 W 46TH ST Spill Number/Closed Date: 9301069 / 4/22/1993	326 W 46TH ST	ENE 1/8 - 1/4 (0.247 mi.)	539	1237
307 W 39TH ST Spill Number/Closed Date: 9602492 / 12/31/1997	307 W 39TH ST	SSE 1/4 - 1/2 (0.253 mi.)	CL558	1330
509 WEST 38TH ST Spill Number/Closed Date: 9505232 / 7/28/1995	509 WEST 38TH ST	WSW 1/4 - 1/2 (0.263 mi.)	CO560	1336
37TH & 9TH ST/BKLYN Spill Number/Closed Date: 9012156 / 3/14/2002	37TH/9TH STREET	SSW 1/4 - 1/2 (0.267 mi.)	562	1338
695 9TH AVE/MANH Spill Number/Closed Date: 9010299 / 11/16/1994	695 9TH AVENUE	NE 1/4 - 1/2 (0.274 mi.)	565	1348
TERRIFIC TENEMENTS Spill Number/Closed Date: 0102069 / 4/13/2002	425 WEST 48TH STREET	NNE 1/4 - 1/2 (0.285 mi.)	566	1349

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
COMMERCIAL PROPERTY	255 WEST 43RD ST	ESE 1/4 - 1/2 (0.287 mi.)	567	1352
Spill Number/Closed Date: 9707270 / 9/20/1997				
346 WEST 48TH ST	346 WEST 48TH ST	NE 1/4 - 1/2 (0.311 mi.)	573	1381
Spill Number/Closed Date: 9413070 / 12/30/1994				
NATIONAL CAR RENTAL	252 WEST 40TH ST	SE 1/4 - 1/2 (0.312 mi.)	CR574	1382
Spill Number/Closed Date: 9502512 / 9/5/2006				
Spill Number/Closed Date: 0308028 / 8/1/2005				
TANK TEST FAILURE TTF	250 WEST 40TH STREET	SE 1/4 - 1/2 (0.314 mi.)	CR575	1388
Spill Number/Closed Date: 1113493 / 6/21/2012				
SPILL NUMBER 9003992	475 10TH AVE	SW 1/4 - 1/2 (0.321 mi.)	CS577	1390
Spill Number/Closed Date: 9003992 / 1/26/1996				
SPILL NUMBER 0008894	236 W. 40TH ST	SE 1/4 - 1/2 (0.328 mi.)	CR583	1409
Spill Number/Closed Date: 0008894 / 3/18/2003				
360 W 36TH ST	360 W 36TH ST	SSW 1/4 - 1/2 (0.336 mi.)	586	1415
Spill Number/Closed Date: 9614241 / 3/7/1997				
ENGINE CO. 054 FDNY -DDC	782 8TH AVENUE	ENE 1/4 - 1/2 (0.338 mi.)	CV588	1417
Spill Number/Closed Date: 9812690 / 6/6/2005				
BP AMOCO	466 10TH AVE	SW 1/4 - 1/2 (0.339 mi.)	CS589	1419
Spill Number/Closed Date: 0301220 / 12/17/2003				
LNF PLATING	535 8 AVE.	S 1/4 - 1/2 (0.341 mi.)	590	1431
Spill Number/Closed Date: 9313545 / 2/18/1994				
330 W. 36TH ST	330 W. 36TH ST	S 1/4 - 1/2 (0.348 mi.)	597	1455
Spill Number/Closed Date: 9409495 / 10/17/1994				
APT BUILDING TTF	256 WEST 38 ST	SSE 1/4 - 1/2 (0.349 mi.)	598	1456
Spill Number/Closed Date: 1203417 / Not Reported				
460 10TH AVE	460 10TH AVENUE	SW 1/4 - 1/2 (0.351 mi.)	599	1457
Spill Number/Closed Date: 9412295 / 12/20/1994				
454 9TH AVE	454 9TH AVE.	SSW 1/4 - 1/2 (0.352 mi.)	600	1458
Spill Number/Closed Date: 9401631 / 5/4/1994				
DAYS HOTEL	790 8TH AVE	ENE 1/4 - 1/2 (0.354 mi.)	CV602	1467
Spill Number/Closed Date: 9903737 / 2/25/2003				
Spill Number/Closed Date: 0505733 / 3/9/2006				
SEE SPILL #04-09483	254 WEST 47TH STREET	ENE 1/4 - 1/2 (0.360 mi.)	603	1473
Spill Number/Closed Date: 0409264 / 11/23/2004				
Spill Number/Closed Date: 0409483 / 9/30/2005				
AD SCHEUMANN LUMBER	524 WEST 36TH STREET	WSW 1/4 - 1/2 (0.364 mi.)	605	1477
Spill Number/Closed Date: 9510491 / 1/16/1998				
307 WEST 36TH STREET	307 WEST 36TH STREET	S 1/4 - 1/2 (0.366 mi.)	606	1478
Spill Number/Closed Date: 9212082 / 7/10/1993				
570 7TH AVE	570 7TH AVENUE	SE 1/4 - 1/2 (0.369 mi.)	608	1483
Spill Number/Closed Date: 9006935 / 12/19/2005				
246 WEST 38TH STREET	246 WEST 38TH STREET	SSE 1/4 - 1/2 (0.370 mi.)	609	1484
Spill Number/Closed Date: 9313628 / 1/9/1995				
MIDTOWN SOUTH PRECINCT NYPD -D	357 WEST 35TH STREET	SSW 1/4 - 1/2 (0.371 mi.)	CY610	1485
Spill Number/Closed Date: 0100463 / 1/10/2005				
357 W 35TH ST/NYPD	357 W 35TH ST	SSW 1/4 - 1/2 (0.371 mi.)	CY611	1495
Spill Number/Closed Date: 9109281 / 12/1/1991				

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
AMERICAN SAVINGS BANK Spill Number/Closed Date: 8907585 / 10/31/1989	735 9TH AVENUE	NE 1/4 - 1/2 (0.373 mi.)	613	1501
725 10TH AVENUE Spill Number/Closed Date: 9308145 / 10/5/1993	725 10TH AVENUE	N 1/4 - 1/2 (0.381 mi.)	615	1504
442 WEST 50TH ST Spill Number/Closed Date: 9711517 / 1/14/1998	442 WEST 50TH ST	NNE 1/4 - 1/2 (0.385 mi.)	618	1507
PRIVATE REISDENCE Spill Number/Closed Date: 0409059 / 8/18/2006	252 WEST 37TH STREET	SSE 1/4 - 1/2 (0.391 mi.)	620	1509
VAULT #0708 Spill Number/Closed Date: 9600319 / 10/1/1998	214 WEST 38TH ST/7TH AV	SE 1/4 - 1/2 (0.394 mi.)	621	1511
7 TIMES SQUARE Spill Number/Closed Date: 0509142 / 11/1/2005	7 TIMES SQUARE	SE 1/4 - 1/2 (0.397 mi.)	622	1512
BASEMENT OF Spill Number/Closed Date: 0305833 / 11/14/2005	333 WEST 34TH ST	SSW 1/4 - 1/2 (0.404 mi.)	625	1520
APRT Spill Number/Closed Date: 0605725 / 3/26/2007	505 8TH AVE	S 1/4 - 1/2 (0.406 mi.)	626	1523
CONSTRUCTION SITE Spill Number/Closed Date: 0103274 / 12/13/2001	529 WEST 35TH ST	WSW 1/4 - 1/2 (0.414 mi.)	628	1526
APARTMENT BUILDING Spill Number/Closed Date: 0011776 / 3/22/2001	261 WEST 36TH STREET	SSE 1/4 - 1/2 (0.414 mi.)	629	1527
AMOCO Spill Number/Closed Date: 9905246 / 8/27/1999	436 TENTH AVE	SW 1/4 - 1/2 (0.424 mi.)	DB630	1529
AMOCO Spill Number/Closed Date: 9506257 / 5/3/2002	436 TENTH AVE	SW 1/4 - 1/2 (0.424 mi.)	DB631	1530
500 7TH AVENUE Spill Number/Closed Date: 8901132 / 2/13/2003	500 7TH AVENUE	SSE 1/4 - 1/2 (0.428 mi.)	632	1531
34TH ST. & 10TH AVE./AMOC Spill Number/Closed Date: 8705645 / 10/5/1987	34TH ST. & 10TH AVE.	SW 1/4 - 1/2 (0.435 mi.)	DD635	1536
34TH ST. AND 10TH AVE./AM Spill Number/Closed Date: 8704567 / 9/1/1987	34TH ST.& 10TH AVE.	SW 1/4 - 1/2 (0.435 mi.)	DD636	1537
240 WEST 36TH ST./COMMERC Spill Number/Closed Date: 8705735 / 10/7/1987	240 WEST 36TH ST.	SSE 1/4 - 1/2 (0.438 mi.)	638	1540
EXCAVATION SITE Spill Number/Closed Date: 0102767 / 5/10/2005	763 9TH AVE	NE 1/4 - 1/2 (0.439 mi.)	639	1541
527 WEST 34TH ST Spill Number/Closed Date: 0750112 / 4/23/2007	527 WEST 34TH ST	WSW 1/4 - 1/2 (0.441 mi.)	640	1544
233 W 49TH ST Spill Number/Closed Date: 9713530 / 3/6/1998	233 W 49TH ST	ENE 1/4 - 1/2 (0.444 mi.)	642	1551
360 WEST 51ST STREET Spill Number/Closed Date: 9911885 / 11/16/2005	360 WEST 51ST STREET	NE 1/4 - 1/2 (0.444 mi.)	643	1552
498 SEVENTH AVENUE Spill Number/Closed Date: 0006741 / 10/4/2000	498 7TH AVENUE	SSE 1/4 - 1/2 (0.453 mi.)	647	1557
SPILL NUMBER 9815045 Spill Number/Closed Date: 9815045 / 3/19/1999	305 W. 50TH ST	NE 1/4 - 1/2 (0.455 mi.)	DF648	1558
APARTMENT BUILDING Spill Number/Closed Date: 0406590 / 7/20/2006	501 7TH AVE.	SSE 1/4 - 1/2 (0.463 mi.)	DH650	1561

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SPILL NUMBER 0105774 Spill Number/Closed Date: 0105774 / 3/17/2004	1650 BROADWAY	ENE 1/4 - 1/2 (0.463 mi.)	651	1562
840 EAST 8TH ST. Spill Number/Closed Date: 9008696 / 9/30/1992	840 EAST 8TH STREET	NE 1/4 - 1/2 (0.463 mi.)	DF652	1563
ST MICHEAL'S SCHOOL Spill Number/Closed Date: 9608649 / 10/11/1996 Spill Number/Closed Date: 0606006 / 9/11/2006	425 WEST 33RD STREET	SSW 1/4 - 1/2 (0.466 mi.)	653	1565
JANOVIC PAINT Spill Number/Closed Date: 0209507 / 12/12/2007	771 9TH AV	NNE 1/4 - 1/2 (0.467 mi.)	654	1567
COMMERCIAL BUILDING Spill Number/Closed Date: 0501223 / 6/30/2006	701 7TH AVE	E 1/4 - 1/2 (0.467 mi.)	DI655	1568
528 W 34TH ST Spill Number/Closed Date: 9300804 / 4/16/1993	528 W 34TH ST	WSW 1/4 - 1/2 (0.473 mi.)	DK658	1576
131 WEST 42ND ST/MANH Spill Number/Closed Date: 8911074 / 2/22/1990	131 WEST 42ND STREET	ESE 1/4 - 1/2 (0.475 mi.)	659	1577
530 WEST 34TH ST/MANH Spill Number/Closed Date: 8910499 / 2/2/1990	530 WEST 34TH STREET	WSW 1/4 - 1/2 (0.477 mi.)	DK660	1578
237 WEST 35TH ST Spill Number/Closed Date: 9811630 / 2/11/1999	237 WEST 35TH ST	SSE 1/4 - 1/2 (0.480 mi.)	DL661	1579
491 7TH AVE Spill Number/Closed Date: 9213026 / 2/23/1993	491 7TH AVE.	SSE 1/4 - 1/2 (0.483 mi.)	DH663	1587
1410 BROADWAY OFFICE BLDG Spill Number/Closed Date: 9513787 / 2/11/2003	1410 BROADWAY	SE 1/4 - 1/2 (0.483 mi.)	DM664	1594
ROADWAY Spill Number/Closed Date: 0610898 / 12/28/2006	1410 BROADWAY	SE 1/4 - 1/2 (0.483 mi.)	DM665	1595
M B HAMPTONS LLC. - TTF Spill Number/Closed Date: 9806038 / Not Reported	224 WEST 30TH STREET	S 1/4 - 1/2 (0.484 mi.)	DL666	1597
COMMERCIAL PROPERTY Spill Number/Closed Date: 0007888 / 5/28/2004	150 W 47TH ST	E 1/4 - 1/2 (0.484 mi.)	DI667	1598
IN FORNT OF Spill Number/Closed Date: 0510869 / 12/16/2005	146 WEST 38TH ST	SE 1/4 - 1/2 (0.497 mi.)	673	1613
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
450 W. 41ST STREET Spill Number/Closed Date: 9504490 / 7/28/2005	450 W. 41ST STREET	WSW 1/8 - 1/4 (0.130 mi.)	AB163	324
ROADBED Spill Number/Closed Date: 1008791 / 11/30/2010	42NS ST 10TH AVE	WNW 1/8 - 1/4 (0.134 mi.)	AC170	334
SERVICE STATION Spill Number/Closed Date: 9713164 / 12/22/1998	624 10TH AVE	NNW 1/8 - 1/4 (0.158 mi.)	AK241	463
408 WEST 39TH ST Spill Number/Closed Date: 9612460 / 2/13/1997	408 WEST 39TH ST	SSW 1/8 - 1/4 (0.169 mi.)	AO259	488
HESS #32215 Spill Number/Closed Date: 8807538 / 10/18/2004	502 WEST 45TH STREET	NNW 1/8 - 1/4 (0.183 mi.)	AR300	571
502 WEST 45TH ST/HESS Spill Number/Closed Date: 8807198 / 3/19/2003	502 WEST 45TH STREET	NNW 1/8 - 1/4 (0.183 mi.)	AR302	582
WEST 45TH ST & 10TH AVE Spill Number/Closed Date: 9000492 / 8/2/1993	WEST 45TH ST & 10TH AVE	NNW 1/8 - 1/4 (0.190 mi.)	BC330	652

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON ED - V 3685 Spill Number/Closed Date: 8901904 / Not Reported	522 W 44 ST	NW 1/8 - 1/4 (0.207 mi.)	BF379	757
FDNY RESCUE 1 Spill Number/Closed Date: 9706580 / 7/6/1999	530 WEST 43RD ST	NW 1/8 - 1/4 (0.221 mi.)	BT440	954
APARTMENT COMPLEX Spill Number/Closed Date: 0108944 / 1/13/2006	560 W 43RD ST	NW 1/4 - 1/2 (0.251 mi.)	CM556	1327
RIVERBANK WEST APARTMENTS Spill Number/Closed Date: 0206678 / 4/28/2003	560 WEST 43RD ST	NW 1/4 - 1/2 (0.251 mi.)	CM557	1329
SPILL NUMBER 0206999 Spill Number/Closed Date: 0206999 / 6/3/2003	525 WEST 45TH ST	NNW 1/4 - 1/2 (0.254 mi.)	CJ559	1334
COACH USA/AMTRAK TUNNEL Spill Number/Closed Date: 0207335 / 9/18/2006	520 WEST 46TH STREET	NNW 1/4 - 1/2 (0.267 mi.)	563	1339
APT BUILDING Spill Number/Closed Date: 9711326 / 1/9/1998	545 WEST 45TH ST	NNW 1/4 - 1/2 (0.274 mi.)	564	1345
MOBIL S/S Spill Number/Closed Date: 9009655 / 7/2/2003	561 11TH AVENUE	WNW 1/4 - 1/2 (0.303 mi.)	CP568	1356
MOBIL OIL CORP SS #QDL Spill Number/Closed Date: 9905507 / 7/2/2003	561 11TH AVE	WNW 1/4 - 1/2 (0.305 mi.)	CP569	1357
TAX LOT 3 Spill Number/Closed Date: 0505659 / 12/20/2005	600 WEST 42ND ST	WNW 1/4 - 1/2 (0.307 mi.)	CQ570	1378
VERIZON Spill Number/Closed Date: 0103392 / 6/25/2002	605 WEST 42ND ST	WNW 1/4 - 1/2 (0.310 mi.)	CQ572	1380
BMW Spill Number/Closed Date: 9707785 / 10/1/1997	547 WEST 47TH ST	NNW 1/4 - 1/2 (0.324 mi.)	578	1391
MICHAEL J QUILL DEPOT Spill Number/Closed Date: 8700318 / 4/10/1987	525 11TH AVE	W 1/4 - 1/2 (0.325 mi.)	CT579	1392
MJ QUILL DEPOT -NYCT Spill Number/Closed Date: 8904384 / Not Reported	523 11TH AVENUE	W 1/4 - 1/2 (0.325 mi.)	CT580	1398
CLOSED-LACKOF RECENT INFO Spill Number/Closed Date: 9101412 / 3/7/2003	525 NORTH 11TH AVENUE	W 1/4 - 1/2 (0.325 mi.)	CT581	1401
UNITED PARCEL SERVICE Spill Number/Closed Date: 0412183 / 2/22/2005	525 11TH AVE	W 1/4 - 1/2 (0.325 mi.)	CT582	1403
608 W 40 ST - MAN Spill Number/Closed Date: 8909404 / 10/16/1997	608 W.40TH ST	W 1/4 - 1/2 (0.338 mi.)	CT587	1416
COMMERCIAL BUILDING Spill Number/Closed Date: 0409846 / 5/5/2005	541 WEST 37TH STREET	WSW 1/4 - 1/2 (0.344 mi.)	CW591	1440
609 11TH AVE Spill Number/Closed Date: 9900078 / 7/2/2003	609-611 11TH AVE	NW 1/4 - 1/2 (0.345 mi.)	CX592	1441
609-611 11TH AVE Spill Number/Closed Date: 9501693 / 9/16/2005	609-611 11TH AVENUE	NW 1/4 - 1/2 (0.345 mi.)	CX593	1445
612 W 45TH ST/UPS Spill Number/Closed Date: 9104075 / 2/12/2003	612 W 45TH ST	NW 1/4 - 1/2 (0.346 mi.)	CX594	1449
527 W 48TH ST Spill Number/Closed Date: 9612403 / 1/21/1997	527 W 48TH ST	N 1/4 - 1/2 (0.347 mi.)	596	1454
METROPOLITAN LUMBER COMPANY Spill Number/Closed Date: 9707347 / 1/8/1998	617 11TH AVE	NNW 1/4 - 1/2 (0.353 mi.)	CX601	1459

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
GAS STATION Spill Number/Closed Date: 0010648 / 3/17/2005	550 WEST 37TH ST	WSW 1/4 - 1/2 (0.360 mi.)	CW604	1475
643 W 43RD ST/UPS Spill Number/Closed Date: 9200470 / 8/7/1995 Spill Number/Closed Date: 9202362 / 3/31/1995	643 W 43RD ST/UPS	NW 1/4 - 1/2 (0.369 mi.)	607	1480
639 11TH AVE./MAHATTAN Spill Number/Closed Date: 8706049 / 7/31/1997	639 11TH AVE.	NNW 1/4 - 1/2 (0.377 mi.)	CZ614	1503
EMERGENCY GARAGE Spill Number/Closed Date: 8908614 / 2/27/2003	LINCOLN TUNNEL EMERG GA W 1/4 - 1/2 (0.390 mi.)		619	1508
SPILL NUMBER 0203467 Spill Number/Closed Date: 0203467 / 3/7/2003	612-614 WEST 47TH ST	NNW 1/4 - 1/2 (0.398 mi.)	CZ623	1513
CONSTRUCTION SITE Spill Number/Closed Date: 0506652 / 9/20/2006	617-623 WEST 47TH STREE	NNW 1/4 - 1/2 (0.400 mi.)	CZ624	1514
605 WEST 47TH STREET Spill Number/Closed Date: 0400961 / 11/17/2004	605 WEST 47TH STREET	NNW 1/4 - 1/2 (0.407 mi.)	627	1525
ATC MANAGEMENT Spill Number/Closed Date: 0509022 / 3/17/2006	605 WEST 48TH ST	NNW 1/4 - 1/2 (0.429 mi.)	DC633	1532
X Spill Number/Closed Date: 0209190 / 1/24/2006	520 WEST 50TH ST	N 1/4 - 1/2 (0.433 mi.)	634	1535
624 WEST 48TH ST Spill Number/Closed Date: 8709100 / 2/23/1993	624 WEST 48TH ST	NNW 1/4 - 1/2 (0.438 mi.)	DC637	1538
624 W. 48TH STREET Spill Number/Closed Date: 9408956 / 8/6/1996	624 WEST 48TH STREET	NNW 1/4 - 1/2 (0.443 mi.)	641	1545
CLOSED-LACKOF RECENT INFO Spill Number/Closed Date: 8804962 / 3/5/2003	711 12TH AVENUE	NW 1/4 - 1/2 (0.461 mi.)	DG649	1559
660 12TH AVE (A/K/A) Spill Number/Closed Date: 0008970 / 2/4/2002	618-628 W 49TH ST	NNW 1/4 - 1/2 (0.469 mi.)	DJ656	1573
WEST 49TH ST SUBSTATION Spill Number/Closed Date: 0306463 / 10/15/2003	637 WEST 49TH STREET	NNW 1/4 - 1/2 (0.481 mi.)	DJ662	1580
ASTOR SUBSTATION BCP SITE Spill Number/Closed Date: 0103148 / Not Reported Spill Number/Closed Date: 0605854 / 12/21/2006	700 11TH AVE	N 1/4 - 1/2 (0.488 mi.)	DN669	1600
BETWEEN 11TH & 12TH Spill Number/Closed Date: 0306468 / 9/18/2003	49TH	NNW 1/4 - 1/2 (0.494 mi.)	670	1608
COMMERCIAL BUILDING Spill Number/Closed Date: 1100355 / 4/15/2014	500 WEST 52ND STREET	NNE 1/4 - 1/2 (0.494 mi.)	671	1609
SILVERSTEIN 42ND ASSOC. Spill Number/Closed Date: 9504838 / 7/3/1996	500-516 12TH AVE	W 1/4 - 1/2 (0.497 mi.)	DO672	1612
PIER 79 Spill Number/Closed Date: 0301651 / 1/30/2004	WEST ST & 39TH ST	W 1/4 - 1/2 (0.498 mi.)	DO674	1614

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, and dated 07/01/2014 has revealed that there are 3 NY TANKS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
406 WEST 46TH STREET CORP.	406 WEST 46TH STREET	NE 1/8 - 1/4 (0.186 mi.)	AY313	619
509 9TH AVE	509 NINTH AVENUE	SSW 1/8 - 1/4 (0.199 mi.)	BH352	692
485-497 NINTH AVE PARTNERS LLC	493 9TH AVE	SSW 1/8 - 1/4 (0.240 mi.)	518	1181

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 07/01/2014 has revealed that there are 28 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PLAYWRIGHT'S HORIZONS	416 WEST 42ND STREET	SW 0 - 1/8 (0.021 mi.)	A6	42
42ND STREET THEATRE ROW	420 WEST 42ND STREET	WSW 0 - 1/8 (0.022 mi.)	A7	44
MANHATTAN PLAZA	400 WEST 43RD STREET	ENE 0 - 1/8 (0.049 mi.)	E40	95
WESTSIDE 414, LLC.	414 W 44TH ST	NE 0 - 1/8 (0.086 mi.)	O88	181
HOLLAND HOUSE	351 WEST 42ND STREET	SE 0 - 1/8 (0.122 mi.)	T146	285
PARKING GARAGE	415-419 WEST 45TH STREE	NNE 1/8 - 1/4 (0.136 mi.)	AD176	351
445 W 45 DEVELOPMENT CORP	445 W 45TH ST	N 1/8 - 1/4 (0.157 mi.)	AM233	448
THE STAY BRIDGE	334-340 WEST 40TH STREE	SSE 1/8 - 1/4 (0.184 mi.)	AX304	590
TOWN HOUSE MANAGEMENT	330 WEST 45TH STREET	ENE 1/8 - 1/4 (0.205 mi.)	BD366	732
DIVISION OF PAROLE	314 WEST 40TH STREET	SSE 1/8 - 1/4 (0.209 mi.)	BN392	820
WEST 44TH STREE HOTEL	306 WEST 44TH STREET	E 1/8 - 1/4 (0.210 mi.)	BI402	864
WEST 39TH STREET DEVELOPMENT	328-339 WEST 39TH STREE	SSE 1/8 - 1/4 (0.227 mi.)	BR457	981
PORT AUTHORITY BUS TERMINAL	625 EIGHTH AVENUE	SE 1/8 - 1/4 (0.232 mi.)	CC477	1046
500 LINCOLN, LLC	501 TENTH AVENUE	WSW 1/8 - 1/4 (0.250 mi.)	CO553	1295

Lower Elevation	Address	Direction / Distance	Map ID	Page
DYER AVENUE ASSOCIATES, LLC	424 W. 42ND STREET	W 0 - 1/8 (0.030 mi.)	C10	51
LINCOLN TUNNEL/PROJECT FIND/DR	402 WEST 41ST STREET	WSW 0 - 1/8 (0.080 mi.)	M84	171
AVIS RENT A CAR	460 W 42 ST	WNW 0 - 1/8 (0.082 mi.)	I86	175
AVIS RENT A CAR SYSTEM, INC.	460 WEST 42ND STREET	WNW 0 - 1/8 (0.082 mi.)	I87	177
COVENANT HOUSE	460 W 41ST STREET	WSW 1/8 - 1/4 (0.148 mi.)	AB212	417
PHIL'S WEST 44TH ST SERV/STA	614/626 TENTH AVENUE	NNW 1/8 - 1/4 (0.169 mi.)	AR261	490
HESS #32215	502 WEST 45TH STREET	NNW 1/8 - 1/4 (0.183 mi.)	AR300	571
AVIS RENT A CAR SYSTEM LLC	515 WEST 43RD STREET	NW 1/8 - 1/4 (0.192 mi.)	BE336	662
F.D.N.Y.-RESCUE CO. 1	530 WEST 43RD STREET	NW 1/8 - 1/4 (0.216 mi.)	BT419	899
PORT AUTH NY&NJ-LINC TUN NY EM	WEST 38TH ST / DYER AVE	SW 1/8 - 1/4 (0.219 mi.)	431	925
43RD PARKING CORP	541 W 43 ST	NW 1/8 - 1/4 (0.226 mi.)	BT450	967
MARVIN MITHELL	541 WEST 43RD STREET	NW 1/8 - 1/4 (0.226 mi.)	BT453	974
MERCEDES/BENZ MANHATTAN INC	536 W 41 ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ463	1004
517-525 WEST 45TH STREET	517-525 WEST 45TH STREE	NNW 1/8 - 1/4 (0.247 mi.)	CJ543	1245

EXECUTIVE SUMMARY

NY CBS UST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS UST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MANHATTAN PLAZA HEALTH CLUB	482 W.43RD STREET	NW 0 - 1/8 (0.111 mi.)	131	253

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 07/01/2014 has revealed that there are 131 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
42ND STREET THEATRE ROW	420 WEST 42ND STREET	WSW 0 - 1/8 (0.022 mi.)	A8	46
417 W 43RD STREET	417 W 43 RD ST	NE 0 - 1/8 (0.038 mi.)	E15	60
NINTH AVENUE REALTY LLC	435 WEST 43 STREET	N 0 - 1/8 (0.045 mi.)	F33	81
570 9TH AVENUE	570 9TH AVENUE	SSE 0 - 1/8 (0.057 mi.)	H58	125
609 NINTH AVENUE	609 NINTH AVENUE	ENE 0 - 1/8 (0.058 mi.)	G61	134
606-604 9TH AVENUE	606-604 NINTH AVENUE	ENE 0 - 1/8 (0.072 mi.)	G75	162
408-410 W 44TH STREET	408-410 W 44TH STREET	NE 0 - 1/8 (0.088 mi.)	N92	187
406 WEST 44TH ST	406 WEST 44TH ST	NE 0 - 1/8 (0.088 mi.)	N94	192
411 W 44 ST	411 WEST 44TH STREET	NE 0 - 1/8 (0.090 mi.)	O97	198
402 WEST 44TH ST	402 WEST 44TH ST	NE 0 - 1/8 (0.090 mi.)	N98	200
437-9 WEST 44TH STREET	437-9 WEST 44TH STREET	NNE 0 - 1/8 (0.091 mi.)	Q101	204
44-45 REALTY ASSOC, LP	449 WEST 44TH STREET	N 0 - 1/8 (0.097 mi.)	Q115	224
630 9TH AVENUE	630 9TH AVENUE	NE 0 - 1/8 (0.115 mi.)	X136	268
356 WEST 43 STREET	356 WEST 43 ST.	ESE 0 - 1/8 (0.116 mi.)	V140	277
FORMER QUATRO PROPERTIES ASSOC	351 WEST 41 STREET	SE 0 - 1/8 (0.124 mi.)	AA156	299
IVY TOWER	350 WEST 43RD STREET	ESE 1/8 - 1/4 (0.126 mi.)	V159	305
414-420 WEST 45TH STREET	414-420 WEST 45TH STREE	NNE 1/8 - 1/4 (0.133 mi.)	AD166	328
411 WEST 45TH STREET	411 WEST 45TH STREET	NNE 1/8 - 1/4 (0.136 mi.)	AD177	359
CHATSWORTH LLC	405 WEST 45TH STREET	NE 1/8 - 1/4 (0.138 mi.)	AD180	363
HPD	534 9TH AVE	SSW 1/8 - 1/4 (0.138 mi.)	Y182	368
WEST 45TH STREET ASSOCIATES	425 W. 45TH STREET	NNE 1/8 - 1/4 (0.139 mi.)	AF187	376
427 WEST 45ST C/O B. HAVIV ASS	427 WEST 45 TH ST	NNE 1/8 - 1/4 (0.140 mi.)	AF191	383
BARUCH HAVIV	431 W 45TH ST	N 1/8 - 1/4 (0.140 mi.)	AF194	388
432 WEST 45TH STREET	432 WEST 45TH STREET	NNE 1/8 - 1/4 (0.141 mi.)	AF196	393
536 9TH AVE	536 NINTH AVENUE	SSW 1/8 - 1/4 (0.141 mi.)	Y198	396
644 NINTH AVE	644 NINTH AVENUE	NE 1/8 - 1/4 (0.147 mi.)	AG211	414
AMETHYST WEST HDFC	646 9TH AVENUE	NE 1/8 - 1/4 (0.152 mi.)	AG222	428
CHURCH OF THE HOLY CROSS & SCH	332 WEST 42ND STREET	SE 1/8 - 1/4 (0.152 mi.)	AJ223	430
347-349 W. 44 ST.	347-349 WEST 44TH STREE	E 1/8 - 1/4 (0.154 mi.)	AI226	437
649-9TH AVE	649 NINTH AVENUE	NE 1/8 - 1/4 (0.155 mi.)	AG228	439
445 W 45 DEVELOPMENT CORP	445 W 45TH ST	N 1/8 - 1/4 (0.157 mi.)	AM233	448
648 NINTH AVE	648 NINTH AVENUE	NE 1/8 - 1/4 (0.157 mi.)	AG236	455
339 W. 44 REALTY LLC	339 W. 44TH STREET	E 1/8 - 1/4 (0.165 mi.)	AP254	479
650 NINTH AVENUE	650 NINTH AVENUE	NE 1/8 - 1/4 (0.168 mi.)	AQ257	484
THERA REALTY, LLC	321-325 WEST 42ND STREE	SE 1/8 - 1/4 (0.172 mi.)	AS277	519
356 W 45 ST	356 WEST 45TH STREET	ENE 1/8 - 1/4 (0.175 mi.)	AT280	523
319 WEST 42ND STREET	319 WEST 42ND STREET	SE 1/8 - 1/4 (0.175 mi.)	AS281	526

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WEST 45TH ST VENTURE LLC	355 WEST 45 STREET	ENE 1/8 - 1/4 (0.178 mi.)	AT288	535
VITO SACCHETTI	328 WEST 44TH STREET	E 1/8 - 1/4 (0.178 mi.)	AP289	537
426-428 W. 46TH OWNER'S CORP.	428 WEST 46TH STREET	NNE 1/8 - 1/4 (0.179 mi.)	AV293	552
STAGING ASSOCIATES LTD	342 WEST 40TH STREET	SSE 1/8 - 1/4 (0.182 mi.)	AX296	558
BROADWAY & ELLWOOD REALTY, LLC	348 WEST 45TH STREET	ENE 1/8 - 1/4 (0.183 mi.)	AT298	561
416 WEST 46TH LLC	416 WEST 46TH STREET	NNE 1/8 - 1/4 (0.184 mi.)	AY306	608
HIGHPOINT ASSOCIATES XII, LLC	410-412 WEST 46TH STREE	NNE 1/8 - 1/4 (0.185 mi.)	AY309	612
424 WEST OWNERS LTD.	424 WEST 46TH STREET	NNE 1/8 - 1/4 (0.185 mi.)	AV312	617
HARTLEY HOUSE	413 WEST 46TH ST	NNE 1/8 - 1/4 (0.187 mi.)	AY319	625
ST CLEMENTS CHURCH	423 W 46TH ST	NNE 1/8 - 1/4 (0.187 mi.)	AY320	628
EMPIREFFECTS INCORPORATED	311 WEST 43RD STREET	ESE 1/8 - 1/4 (0.187 mi.)	BB322	633
433 W 46TH HDFC ASSOC.	433 WEST 46TH STREET	NNE 1/8 - 1/4 (0.189 mi.)	AV327	646
665-7-9 9TH AVE	665-7-9 9TH AVE	NE 1/8 - 1/4 (0.189 mi.)	AQ329	649
L&F REALTY CO	435 WEST 46TH STREET	NNE 1/8 - 1/4 (0.190 mi.)	AV332	654
439 WEST 46TH ST	439 WEST 46TH ST	NNE 1/8 - 1/4 (0.191 mi.)	AV335	659
309 W 43 ST	309 W 43RD ST	ESE 1/8 - 1/4 (0.192 mi.)	BB337	665
341 WEST 45TH STREET	341 WEST 45TH STREET	ENE 1/8 - 1/4 (0.194 mi.)	BD339	669
LEERO REALTY, LLC	425 WEST 46TH STREET	NNE 1/8 - 1/4 (0.197 mi.)	AV341	676
LEERO REALTY CO	425 W 46TH ST	NNE 1/8 - 1/4 (0.197 mi.)	AV342	678
506-508 NINTH AVENUE	506/508 NINTH AVENUE	SSW 1/8 - 1/4 (0.200 mi.)	BH357	714
449 W46TH STREET	449 W46TH STREET	N 1/8 - 1/4 (0.201 mi.)	BJ360	720
448-450 WEST 46TH STREET	448-450 WEST 46TH ST	N 1/8 - 1/4 (0.201 mi.)	BJ361	722
510	510 9TH AVE	SSW 1/8 - 1/4 (0.203 mi.)	BH362	725
TOWN HOUSE MANAGEMENT	330 WEST 45TH STREET	ENE 1/8 - 1/4 (0.205 mi.)	BD367	734
300 W 43RD STREET	300 W 43RD STREET	ESE 1/8 - 1/4 (0.205 mi.)	BB371	743
MARTIN BECK THEATRE CORP	302 WEST 45TH STREET	E 1/8 - 1/4 (0.206 mi.)	BK376	752
WEST SIDE LOFTS LTD	347 WEST 39TH STREET	S 1/8 - 1/4 (0.209 mi.)	BG391	818
DIVISION OF PAROLE	314 WEST 40TH STREET	SSE 1/8 - 1/4 (0.209 mi.)	BN393	822
321 W 44 ST	321 WEST 44TH STREET	E 1/8 - 1/4 (0.210 mi.)	BI400	833
CLINTON 510 OWNERS H.D.F.C.	465 W. 46 ST.	N 1/8 - 1/4 (0.211 mi.)	BJ403	866
325 W 45 ST	325 WEST 45TH STREET	E 1/8 - 1/4 (0.213 mi.)	BK413	886
HACELS, INC	305 W 44TH ST	E 1/8 - 1/4 (0.214 mi.)	BI416	891
672 NINTH AVE.,LLC	672 9TH AVENUE	NE 1/8 - 1/4 (0.216 mi.)	BQ417	894
338-340 WEST 39 ST	338 WEST 39TH ST	S 1/8 - 1/4 (0.218 mi.)	BR423	905
352 WEST 46TH STREET	352 WEST 46TH STREET	ENE 1/8 - 1/4 (0.218 mi.)	BS424	909
765-8TH AVENUE	765 8TH AVENUE	SE 1/8 - 1/4 (0.219 mi.)	BU425	912
315 ASSOCIATES LLC	315 WEST 39TH STREET	SSE 1/8 - 1/4 (0.219 mi.)	BR426	914
GLOBE AFFILIATES	300 WEST 44TH STREET	E 1/8 - 1/4 (0.220 mi.)	BI434	930
333 WEST 39TH ST	333 WEST 39TH ST	SSE 1/8 - 1/4 (0.223 mi.)	BR445	960
341-343 WEST 38TH STREET	341-343 WEST 38TH STREE	S 1/8 - 1/4 (0.226 mi.)	BY456	979
WEST 39TH STREET DEVELOPMENT	328-339 WEST 39TH STREE	SSE 1/8 - 1/4 (0.227 mi.)	BR458	984
MILFORD PLAZA HOTEL	700 EIGHTH AVENUE	E 1/8 - 1/4 (0.227 mi.)	465	1014
ENGINE CO. 34 / LADDER 21	440 WEST 38TH STREET	SW 1/8 - 1/4 (0.230 mi.)	CA473	1035
PABT - PORT AUTHORITY BUS TERM	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC479	1051
335 WEST 38TH ST	335 WEST 38TH ST	S 1/8 - 1/4 (0.233 mi.)	CE488	1114
416 WEST 47TH STREET ASSOCIATE	416 WEST 47TH STREET	NNE 1/8 - 1/4 (0.233 mi.)	CF492	1121
426 WEST 47TH STREET	426 WEST 47TH STREET	NNE 1/8 - 1/4 (0.234 mi.)	CF493	1123
432-434 WEST 47TH ST. TENANTS	432-434 WEST 47TH ST	NNE 1/8 - 1/4 (0.234 mi.)	CG494	1126
406 WEST 47TH ST H.D.F.C.	406 WEST 47TH ST	NE 1/8 - 1/4 (0.234 mi.)	CF498	1132
498 NINTH AVENUE	498 NINTH AVENUE	SSW 1/8 - 1/4 (0.235 mi.)	BY501	1142
415 REALTY ASSOCIATES LLC	415 WEST 47TH STREET	NNE 1/8 - 1/4 (0.235 mi.)	CF503	1144
GAMO REALTY CO	428 WEST 47TH ST	NNE 1/8 - 1/4 (0.236 mi.)	CF507	1160
709 EIGHTH AVENUE	709 8TH AVENUE	E 1/8 - 1/4 (0.236 mi.)	CI508	1164
436-438 WEST 47TH APARTMENT OW	436 WEST 47TH STREET	NNE 1/8 - 1/4 (0.238 mi.)	CG510	1168
331- WEST 38TH ST	331 WEST 38TH STREET	S 1/8 - 1/4 (0.238 mi.)	CE512	1170
344 WEST 38TH STREET	344 WEST 38TH STREET	S 1/8 - 1/4 (0.238 mi.)	BY513	1173

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK TIMES BUILDING	620 EIGHTH AVENUE	SSE 1/8 - 1/4 (0.239 mi.)	CC515	1175
305 WEST 45TH STREET	305 WEST 45TH STREET	E 1/8 - 1/4 (0.239 mi.)	CI516	1177
GAMO REALTY CO	454 WEST 47TH ST	NNE 1/8 - 1/4 (0.240 mi.)	CK519	1181
318 W 39 ST	318 WEST 39TH STREET	SSE 1/8 - 1/4 (0.241 mi.)	CL520	1184
456 W 47 ST	456 W 47 ST	NNE 1/8 - 1/4 (0.241 mi.)	CK521	1187
314-316 WEST 39TH STREET CORP.	316 WEST 39TH STREET	SSE 1/8 - 1/4 (0.243 mi.)	CL528	1214
301 WEST 45TH STREET	301 WEST 45TH STREET	E 1/8 - 1/4 (0.245 mi.)	CI535	1229
CAMELOT	301 W. 45TH STREET	E 1/8 - 1/4 (0.245 mi.)	CI536	1231
NINHURSAG PROPERTIES N.V. LTD.	325 W. 38TH ST.	S 1/8 - 1/4 (0.247 mi.)	CN538	1235
276 WEST 43 STREET	276 WEST 43 STREET	ESE 1/8 - 1/4 (0.249 mi.)	552	1292
500 LINCOLN, LLC	501 TENTH AVENUE	WSW 1/8 - 1/4 (0.250 mi.)	CO553	1295
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
447 9 WEST 43RD ST	447-9 WEST 43RD ST	NNW 0 - 1/8 (0.058 mi.)	F60	130
455 WEST 44TH STREET	455 WEST 44TH STREET	N 0 - 1/8 (0.104 mi.)	U121	233
461 WEST 44TH STREET OWNERS CO	461 WEST 44TH STREET	N 0 - 1/8 (0.110 mi.)	U126	243
HUNTER COLLEGE, MFA	450 WEST 41ST STREET	W 0 - 1/8 (0.111 mi.)	W130	251
THE STRAND CONDOMINIUM	500 WEST 43RD STREET	NW 1/8 - 1/4 (0.139 mi.)	AE185	372
TEN STAR CORP.	501 WEST 43RD STREET	NW 1/8 - 1/4 (0.139 mi.)	AE186	374
501 WEST 41ST STREET ASSOCIATE	561 10TH AVENUE	W 1/8 - 1/4 (0.145 mi.)	AH206	406
10TH AVE DEVELOPMENT CORP	506 W 42ND ST	WNW 1/8 - 1/4 (0.154 mi.)	225	433
408 W 39 ST	408 WEST 39TH STREET	SSW 1/8 - 1/4 (0.170 mi.)	AO266	499
406 WEST 39TH STREET	406 WEST 39TH STREET	SSW 1/8 - 1/4 (0.170 mi.)	AO267	501
TRAVEL INN HOTEL	515 WEST 42ND STREET	WNW 1/8 - 1/4 (0.180 mi.)	AW294	554
MERCEDES-BENZ MANHATTAN INC.	536 WEST 41TH ST.	W 1/8 - 1/4 (0.188 mi.)	AZ325	639
640 10TH ASSOC	642 10TH AVE	NNW 1/8 - 1/4 (0.196 mi.)	BC340	673
STYLE MGMT CO	514-518 WEST 44TH STREE	NW 1/8 - 1/4 (0.197 mi.)	BF347	684
AMERICAN RED CROSS EMERGENCY F	515 WEST 41ST STREET	W 1/8 - 1/4 (0.198 mi.)	AZ351	689
BEACON HIGH SCHOOL	521 WEST 43RD STREET	NW 1/8 - 1/4 (0.199 mi.)	BE355	707
THE ARMORY OWNERS, INC.	529-543 WEST 42 STREET	WNW 1/8 - 1/4 (0.200 mi.)	AW356	710
641 10TH AVE	641 TENTH AVE	NNW 1/8 - 1/4 (0.201 mi.)	BC359	716
NEW GOTHAM	520 WEST 43RD STREET	NW 1/8 - 1/4 (0.205 mi.)	BE370	741
ORSAP TAXI CORPORATION	520 WEST 44TH ST	NW 1/8 - 1/4 (0.206 mi.)	BF374	748
F.D.N.Y.-RESCUE CO. 1	530 WEST 43RD STREET	NW 1/8 - 1/4 (0.216 mi.)	BT418	896
MERCEDES/BENZ MANHATTAN INC	536 W 41 ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ464	1006
UNITED RENTALS (NORTH AMERICA)	540 WEST 44TH STREET	NW 1/8 - 1/4 (0.232 mi.)	CB476	1042
CITYWIDE AUTO REPAIR LLC	514 WEST 39TH STREET	WSW 1/8 - 1/4 (0.233 mi.)	CD486	1110
MERCHANDISING WORKSHOP INC	550 W 43RD ST	NW 1/8 - 1/4 (0.241 mi.)	CM522	1190
MERCEDES-BENZ MANHATTAN, INC.	537 W 38 ST	WSW 1/8 - 1/4 (0.242 mi.)	CD527	1211
517-525 WEST 45TH STREET	517-525 WEST 45TH STREE	NNW 1/8 - 1/4 (0.247 mi.)	CJ540	1238

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
GUFFANTI FILM LABORATORIES INC	630 9TH AVE	NE 0 - 1/8 (0.115 mi.)	X133	259

EXECUTIVE SUMMARY

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 07/01/2014 has revealed that there are 2 NY CBS sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
GUFFANTI FILM LABORATORY	630 9TH AVE	NE 0 - 1/8 (0.115 mi.)	X138	274
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MANHATTAN PLAZA HEALTH CLUB	482 W.43RD STREET	NW 0 - 1/8 (0.111 mi.)	131	253

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 07/16/2014 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CE - W. 42ND ST. GAS WORKS	640 W 42ND STREET	WNW 1/4 - 1/2 (0.371 mi.)	612	1496

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 07/16/2014 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CE - W. 42ND ST. GAS WORKS	640 W 42ND STREET	WNW 1/4 - 1/2 (0.371 mi.)	612	1496

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, and dated 07/16/2014 has revealed that there are 2 NY VCP sites within approximately 0.5 miles of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CE - W. 42ND ST. GAS WORKS	640 W 42ND STREET	WNW 1/4 - 1/2 (0.371 mi.)	612	1496
CE - W. 45TH ST. GAS WORKS	12TH AVE.BETWEEN WEST 4	NW 1/4 - 1/2 (0.470 mi.)	DG657	1574

EXECUTIVE SUMMARY

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 07/16/2014 has revealed that there are 7 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HUDSON MEWS PROPERTY - MARTY F	403 WEST 37TH STREET AN	SW 1/4 - 1/2 (0.266 mi.)	561	1337
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MERCEDES-BENZ MANHATTAN INC	528 W 41ST ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ462	992
WEST 42ND STREET REDEVELOPMENT	605/615 WEST 42ND STREE	WNW 1/4 - 1/2 (0.310 mi.)	CQ571	1379
MYRON GARFINKEL	627 WEST 42ND STREET	WNW 1/4 - 1/2 (0.347 mi.)	595	1450
CE - W. 42ND ST. GAS WORKS	640 W 42ND STREET	WNW 1/4 - 1/2 (0.371 mi.)	612	1496
CLINTON GREEN DEVELOPMENT PROJ	51ST - 53RD ST. & 10TH	NNE 1/4 - 1/2 (0.452 mi.)	646	1556
ASTOR SUBSTATION PROJECT SITE	700 11TH AVE, 549-551 &	N 1/4 - 1/2 (0.488 mi.)	DN668	1599

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Registered Storage Tanks

NY HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 14 NY HIST UST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
WESTSIDE 414, LLC.	414 W 44TH ST	NE 0 - 1/8 (0.086 mi.)	O88	181
HOLLAND HOUSE	351 WEST 42ND STREET	SE 0 - 1/8 (0.122 mi.)	T146	285
351 WEST 41 ST BUILDING	351 WEST 41 STREET	SE 0 - 1/8 (0.124 mi.)	AA158	302
PARKING GARAGE	415-419 WEST 45TH STREE	NNE 1/8 - 1/4 (0.136 mi.)	AD176	351
445 W 45 DEVELOPMENT CORP	445 W 45TH ST	N 1/8 - 1/4 (0.157 mi.)	AM235	454
TOWN HOUSE MANAGEMENT	330 WEST 45TH STREET	ENE 1/8 - 1/4 (0.205 mi.)	BD367	734
DIVISION OF PAROLE	314 WEST 40TH STREET	SSE 1/8 - 1/4 (0.209 mi.)	BN393	822
500 LINCOLN, LLC	501 TENTH AVENUE	WSW 1/8 - 1/4 (0.250 mi.)	CO553	1295
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
DYER AVENUE ASSOCIATES, LLC	424 W. 42ND STREET	W 0 - 1/8 (0.030 mi.)	C10	51
AVIS RENT A CAR SYSTEM, INC.	460 WEST 42ND STREET	WNW 0 - 1/8 (0.082 mi.)	I87	177
43RD PARKING CORP	541 W 43 ST	NW 1/8 - 1/4 (0.226 mi.)	BT450	967
MARVIN MITHELL	541 WEST 43RD STREET	NW 1/8 - 1/4 (0.226 mi.)	BT453	974
MERCEDES/BENZ MANHATTAN INC	536 W 41 ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ464	1006
517-525 WEST 45TH STREET	517 WEST 45TH STREET	NNW 1/8 - 1/4 (0.247 mi.)	CJ542	1243

EXECUTIVE SUMMARY

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/19/2014 has revealed that there are 43 NY Spills sites within approximately 0.125 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
THEATER ROW Spill Number/Closed Date: 0006482 / 11/29/2002	410 WEST 42ND STREET	S 0 - 1/8 (0.020 mi.)	A5	41
588 9TH AVENUE Spill Number/Closed Date: 9311040 / 12/13/1993	588 9TH AVENUE	ESE 0 - 1/8 (0.038 mi.)	D16	62
MH 39875 Spill Number/Closed Date: 0004083 / 4/2/2004	584 9TH AVE	SE 0 - 1/8 (0.040 mi.)	B17	64
IFO 400 W42ND ST Spill Number/Closed Date: 0010988 / 6/13/2003	IFO 400 W. 42ND ST	SSE 0 - 1/8 (0.040 mi.)	B19	66
APARTMENT BLDG Spill Number/Closed Date: 0106458 / 9/28/2001	435 W 43RD DT	N 0 - 1/8 (0.042 mi.)	F22	68
MANHOLE #56655 Spill Number/Closed Date: 0310144 / 2/3/2004	C64E W 42 ST / 9TH AVE	SE 0 - 1/8 (0.042 mi.)	B23	69
SPILL NUMBER 9815161 Spill Number/Closed Date: 9815161 / 2/26/2003	437 WEST 43RD ST	N 0 - 1/8 (0.044 mi.)	F32	80
SIDEWALK - VAULT 9536 Spill Number/Closed Date: 0913539 / 5/26/2010	583 9TH AVE	SSE 0 - 1/8 (0.046 mi.)	B36	87
216163; W 43 ST AND 9 AVE Spill Number/Closed Date: 0914117 / 4/2/2009	W 43 ST AND 9 AVE	ENE 0 - 1/8 (0.052 mi.)	G49	111
SPILL NUMBER 9909864 Spill Number/Closed Date: 9909864 / 2/3/2003	43RD STREET & 9TH AVENUE	ENE 0 - 1/8 (0.053 mi.)	G52	117
MANHOLE 60213 Spill Number/Closed Date: 9907937 / 8/17/2000	WEST 43RD ST & 9TH AVE	ENE 0 - 1/8 (0.053 mi.)	G53	118
BUSINESS Spill Number/Closed Date: 1107029 / 9/6/2011	351 WEST 42 ND ST MANHA	ESE 0 - 1/8 (0.077 mi.)	L77	164
MANHOLE #8110 Spill Number/Closed Date: 0608385 / 3/19/2007	351 WEST 42 STREET @ 8	ESE 0 - 1/8 (0.077 mi.)	L79	167
APARTMENT BLDG Spill Number/Closed Date: 1113807 / 5/29/2012	414 W 44TH ST	NE 0 - 1/8 (0.086 mi.)	O89	185
419 WEST 44TH STREET Spill Number/Closed Date: 9510453 / 11/20/1995	419 WEST 44TH STREET	NNE 0 - 1/8 (0.086 mi.)	O90	186
COMMERCIAL BLDG Spill Number/Closed Date: 9513489 / 2/28/2003	347 WEST 41ST ST	SSE 0 - 1/8 (0.091 mi.)	K99	203
BEACH LANE MNGT Spill Number/Closed Date: 0209670 / 12/31/2002	402 WEST 44TH ST	NE 0 - 1/8 (0.093 mi.)	N103	209
WEST 44 STREET & 9TH AVE Spill Number/Closed Date: 0604129 / 7/14/2006	WEST 44 STREET & 9TH AV	NE 0 - 1/8 (0.094 mi.)	N105	210
VAULT 2002 Spill Number/Closed Date: 0404557 / 12/10/2004	WEST 44TH ST/9TH AVE	NE 0 - 1/8 (0.095 mi.)	N107	212
MANHOLE #M39883 Spill Number/Closed Date: 0207191 / 9/29/2004	WEST 44TH ST & 9TH AVE	NE 0 - 1/8 (0.095 mi.)	N108	213

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
447 WEST 44TH ST Spill Number/Closed Date: 8604108 / 9/25/1986	447 WEST 44TH ST	N 0 - 1/8 (0.096 mi.)	Q112	220
40TH & 41ST ST. 9TH AVE Spill Number/Closed Date: 9207152 / 9/21/1992	40TH & 41ST ST 9TH AVE.	S 0 - 1/8 (0.097 mi.)	S114	223
SPILL NUMBER 9909986 Spill Number/Closed Date: 9909986 / 2/19/2003	449 WEST 44TH ST	N 0 - 1/8 (0.097 mi.)	Q116	228
SPILL NUMBER 0111202 Spill Number/Closed Date: 0111202 / 4/11/2002 Spill Number/Closed Date: 0710714 / 1/11/2008	360 WEST 43RD ST	E 0 - 1/8 (0.110 mi.)	V127	246
APARTMENT BUILDING Spill Number/Closed Date: 0514678 / 3/31/2006 Spill Number/Closed Date: 0509345 / 11/7/2005	360 W 43RD ST	E 0 - 1/8 (0.110 mi.)	V128	248
BETWEEN WEST 40TH & 41 Spill Number/Closed Date: 0411407 / 7/12/2006	9TH AVENUE	SSW 0 - 1/8 (0.121 mi.)	Y143	281
GASETERIA Spill Number/Closed Date: 9411896 / 1/26/1996	403 W. 40TH ST	SSW 0 - 1/8 (0.122 mi.)	Y144	283
INFRONT Spill Number/Closed Date: 9907804 / 2/25/2003	330 WEST 42ND ST	SE 0 - 1/8 (0.122 mi.)	T145	284
IN TANK ROOM Spill Number/Closed Date: 0503905 / 7/1/2005	351 WEST 42ND ST	SE 0 - 1/8 (0.123 mi.)	T148	290
MANHOLE 39842 Spill Number/Closed Date: 0008526 / 2/12/2004	9TH AVE/WEST 40TH ST	S 0 - 1/8 (0.124 mi.)	Y149	291
214070; W 40 ST AND 9TH AVE Spill Number/Closed Date: 0814532 / 10/19/2008	W 40 ST AND 9TH AVE	S 0 - 1/8 (0.124 mi.)	Y153	296
CENTRAL PARKING SYSTEMS Spill Number/Closed Date: 0006951 / 9/12/2001	350-358 W 42ND ST	SE 0 - 1/8 (0.124 mi.)	AA157	301
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
MANHOLE #56659 Spill Number/Closed Date: 9900983 / 5/11/1999	W 42ND ST & DYER AVE	W 0 - 1/8 (0.044 mi.)	C29	76
CONSTRUCTION SITE Spill Number/Closed Date: 0511511 / 1/5/2006	WEST 42 /DIER AVE	W 0 - 1/8 (0.044 mi.)	C30	77
MH56659 Spill Number/Closed Date: 0105665 / 3/17/2004	W 42ND ST&DYER AVE	W 0 - 1/8 (0.044 mi.)	C31	78
WEST 41ST ST Spill Number/Closed Date: 9808978 / 10/20/1998	DYER AVE & W.41ST ST	WSW 0 - 1/8 (0.080 mi.)	M80	168
SITE L OF #7 LINE Spill Number/Closed Date: 1102550 / 6/6/2011	W 41ST ST AND DYER AVE	WSW 0 - 1/8 (0.080 mi.)	M81	169
460 WEST 42 ST Spill Number/Closed Date: 0400537 / 2/14/2007	460 WEST 42ND ST	WNW 0 - 1/8 (0.081 mi.)	I85	173
IN STREET Spill Number/Closed Date: 1003287 / 6/24/2010	440 WEST 41ST	WSW 0 - 1/8 (0.102 mi.)	M118	230
40TH STREET Spill Number/Closed Date: 9608237 / 10/10/1996	DYER STREET/9TH & 10TH	SSW 0 - 1/8 (0.117 mi.)	141	279
W 40TH ST AND DYER AVE Spill Number/Closed Date: 9705983 / 8/17/1997	W 40TH ST AND DYER AVE	SW 0 - 1/8 (0.124 mi.)	Z150	292

EXECUTIVE SUMMARY

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NYS PORT AUTHORITY Spill Number/Closed Date: 0106530 / 10/2/2001	40TH ST/DYER AVE	SW 0 - 1/8 (0.124 mi.)	Z151	293
RAMP 96 ABOVE 40TH ST Spill Number/Closed Date: 9705984 / 2/25/2003	AND DYER AVE	SW 0 - 1/8 (0.124 mi.)	Z152	295

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/11/2014 has revealed that there are 48 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON V9191	584 9TH AVE & 42ND ST F 583 9TH AVENUE	SE 0 - 1/8 (0.040 mi.) SSE 0 - 1/8 (0.046 mi.)	B18 B35	65 86
CON EDISION - V 1558	327 W 41 ST 327 W 41 ST	SSE 0 - 1/8 (0.095 mi.)	R111	218
V1558	327 WEST 41ST STREET	SSE 0 - 1/8 (0.096 mi.)	R113	221
CON EDISION - MH61468	547- 9TH AVE 547- 9TH A	S 0 - 1/8 (0.104 mi.)	S122	237
GUFFANTI FILM LABORATORIES INC	630 9TH AVE	NE 0 - 1/8 (0.115 mi.)	X133	259
CINE 60 INC	630 9TH AVE - ROOM #209	NE 0 - 1/8 (0.115 mi.)	X134	265
ACCUTREAT FILMS INC	630 NINTH AVE - ROOM 11	NE 0 - 1/8 (0.115 mi.)	X135	267
FILM CENTER	630 9TH AVE ROOM 208	NE 0 - 1/8 (0.115 mi.)	X137	272
SHERMAN GRINBERG FILM LIBRARY	630 9TH AVE	NE 0 - 1/8 (0.115 mi.)	X139	275
STELLOS PIANO INC	351 W 41ST ST	SE 0 - 1/8 (0.124 mi.)	AA155	297
CON EDISON - MH M39899	9TH AVE & W. 45TH STREE	NE 1/8 - 1/4 (0.140 mi.)	AG190	379
CON EDISION - MH39899	45TH ST & 9TH AVENUE 45	NE 1/8 - 1/4 (0.140 mi.)	AG193	386
O K CLEANERS	647 9TH AVE	NE 1/8 - 1/4 (0.150 mi.)	AG217	423
CON EDISON SERVICE BOX 39834	W 39TH ST & 9TH AVE NW	SSW 1/8 - 1/4 (0.170 mi.)	AO269	506
PORT AUTH OF NY & NJ 9TH AVE &	9TH AVE BETW 38TH & 39T	SSW 1/8 - 1/4 (0.171 mi.)	AO271	508
BELL ATLANTIC-NY	W 39TH ST/9 AVE	SSW 1/8 - 1/4 (0.171 mi.)	AO274	516
INVESTMENT DEV CO WEST NINTH C	359 W 45TH ST	ENE 1/8 - 1/4 (0.174 mi.)	AT278	521
DRY CLEANERS	659 9TH AVE	NE 1/8 - 1/4 (0.178 mi.)	AQ290	540
EMPIREFFECTS INC	214 E 21ST ST	ESE 1/8 - 1/4 (0.187 mi.)	BB321	632
T V C LABORATORIES INC C/O CIT	311 W 43RD ST - 10TH &	ESE 1/8 - 1/4 (0.187 mi.)	BB323	636
VERIZON LOG 32912 NAHOLE R320	W 46TH ST & 9TH AVE	NE 1/8 - 1/4 (0.190 mi.)	BA331	653
CON ED - V 0989	315 W 44 ST	E 1/8 - 1/4 (0.199 mi.)	BI353	692
R GREENBURG ASSOCIATES	350 W 39TH ST	S 1/8 - 1/4 (0.205 mi.)	BG368	738
MARTIN BECK THEATRE	302 W 45TH ST	E 1/8 - 1/4 (0.206 mi.)	BK377	755
CON EDISON	W 42 ST & 8TH AVE	ESE 1/8 - 1/4 (0.208 mi.)	BL382	792
V1056	314 W. 40TH STREET	SSE 1/8 - 1/4 (0.209 mi.)	BN394	825
HAP ENGRAVING OF NY LTD	323 W 39TH ST	SSE 1/8 - 1/4 (0.211 mi.)	BR405	869
CON EDISON MANHOLE 60250	W 41 ST 336' WW COR 8 A	SE 1/8 - 1/4 (0.219 mi.)	BU430	923
PORT AUTH OF NY & NJ 9TH AVE &	38TH ST & 9TH AVE	SSW 1/8 - 1/4 (0.220 mi.)	BH435	932
CON EDISON SERVICE BOX: 4158	557 W 23RD ST	E 1/8 - 1/4 (0.223 mi.)	BK448	965
CON EDISON AT PORT AUTHORITY O	625 8TH AVE - BASEMENT	SE 1/8 - 1/4 (0.232 mi.)	CC478	1049
L & L PAINTING CO INC	625 8TH AVE - BLOCK 103	SE 1/8 - 1/4 (0.232 mi.)	CC480	1102
PORT AUTHORITY BUS TERMINAL	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC481	1104
KNICKERBOCKER BIOLOGICALS INC	300 W 40TH ST	SSE 1/8 - 1/4 (0.235 mi.)	CC499	1137

EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEWBRIDGE COMMUNICATIONS	333 E 38TH ST - 8TH FLO	S 1/8 - 1/4 (0.236 mi.)	CE506	1150
CORONET BUTTON DYERS INC	325 W 38TH ST	S 1/8 - 1/4 (0.247 mi.)	CN537	1233

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HUNTER COLLEGE - MFA	450 W 41ST ST	WSW 1/8 - 1/4 (0.130 mi.)	AB162	310
CON EDISON - GM 16 INCH	10TH AVE WEST 42 /WEST	NW 1/8 - 1/4 (0.138 mi.)	AE181	366
NEW YORK TRANSIT AUTH	565 TENTH AVE	WNW 1/8 - 1/4 (0.141 mi.)	AH195	392
FAST TOWING & AUTO REPAIR	547 10TH ST	W 1/8 - 1/4 (0.161 mi.)	AL246	470
HESS CORPORATION	502 W 45TH ST	NNW 1/8 - 1/4 (0.183 mi.)	AR299	563
STYLE MANG & CO	518 W 44TH ST	NW 1/8 - 1/4 (0.203 mi.)	BF364	729
CON ED - V 3685	522 W 44 ST	NW 1/8 - 1/4 (0.207 mi.)	BF379	757
CON EDISON - MH43240	W39TH ST & 10TH AVE W39	WSW 1/8 - 1/4 (0.212 mi.)	BP407	880
PORT AUTH OF NY & NJ 10TH AVE	10TH AVE BETW 38TH & 39	WSW 1/8 - 1/4 (0.212 mi.)	BP410	883
TRAILWAYS INC	544 W 41ST ST	WNW 1/8 - 1/4 (0.237 mi.)	BZ509	1166
FEDERAL EXPRESS CORP	560 W 42ND ST	WNW 1/8 - 1/4 (0.245 mi.)	BW534	1224

CONSENT: Major Legal settlements that establish responsibility and standards for cleanup at NPL (superfund) sites. Released periodically by U.S. District Courts after settlement by parties to litigation matters.

A review of the CONSENT list, as provided by EDR, and dated 12/31/2013 has revealed that there is 1 CONSENT site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HUDSON RIVER PCBS	NO STREET APPLICABLE	WNW 1/2 - 1 (0.532 mi.)	0	12

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 11/25/2013 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HUDSON RIVER PCBS	NO STREET APPLICABLE	WNW 1/2 - 1 (0.532 mi.)	0	12

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK TIMES CO.	229 W 431ST STREET	ESE 1/4 - 1/2 (0.329 mi.)	CU585	1413

EXECUTIVE SUMMARY

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 05/01/2014 has revealed that there are 136 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	427 W.42 ST	SW 0 - 1/8 (0.019 mi.)	A4	39
CON EDISON	402 W 42ND ST	SSE 0 - 1/8 (0.037 mi.)	B12	56
CONSOLIDATED EDISON	595 9TH AVE	ESE 0 - 1/8 (0.038 mi.)	D14	58
CON EDISON	434 W 43RD ST	N 0 - 1/8 (0.043 mi.)	F27	73
V9191	583 9TH AVENUE	SSE 0 - 1/8 (0.046 mi.)	B35	86
CON EDISON	576 9TH AVE	SSE 0 - 1/8 (0.050 mi.)	B42	100
CON EDISON	572 9TH AVE	SSE 0 - 1/8 (0.054 mi.)	H55	120
CON EDISON	606 9TH AVE	ENE 0 - 1/8 (0.062 mi.)	G66	147
CONSOLIDATED EDISON	348 WEST 41ST STREET	SSE 0 - 1/8 (0.092 mi.)	K102	208
CON EDISON - MH 39883	W44TH ST AND 9TH AVE	NE 0 - 1/8 (0.094 mi.)	N104	210
CONSOLIDATED EDISON	44TH & 9TH MH39883	NE 0 - 1/8 (0.095 mi.)	N106	211
CON EDISON - V 1558	327 W 41 ST 327 W 41 ST	SSE 0 - 1/8 (0.095 mi.)	R111	218
V1558	327 WEST 41ST STREET	SSE 0 - 1/8 (0.096 mi.)	R113	221
CON EDISON	W.42 ST & 9TH AVE	SE 0 - 1/8 (0.102 mi.)	T117	229
CON EDISON - MH61468	547- 9TH AVE 547- 9TH A	S 0 - 1/8 (0.104 mi.)	S122	237
CONSOLIDATED EDISON	V0365-144 W 43RD ST	E 0 - 1/8 (0.105 mi.)	V123	239
CON EDISON	358 W 42ND ST	SE 0 - 1/8 (0.108 mi.)	T124	241
CINE 60 INC	630 9TH AVE - ROOM #209	NE 0 - 1/8 (0.115 mi.)	X134	265
FILM CENTER	630 9TH AVE ROOM 208	NE 0 - 1/8 (0.115 mi.)	X137	272
GUFFANTI FILM LABORATORY	630 9TH AVE	NE 0 - 1/8 (0.115 mi.)	X138	274
STELLOS PIANO INC	351 W 41ST ST	SE 0 - 1/8 (0.124 mi.)	AA155	297
CON EDISON	348 W 42ND ST	SE 1/8 - 1/4 (0.126 mi.)	T161	308
CON EDISON - MH M39899	9TH AVE & W. 45TH STREE	NE 1/8 - 1/4 (0.140 mi.)	AG190	379
CON EDISON - MH39899	45TH ST & 9TH AVENUE 45	NE 1/8 - 1/4 (0.140 mi.)	AG193	386
CON EDISON	642 NINTH AVE	NE 1/8 - 1/4 (0.142 mi.)	AG199	398
CON EDISON	336 W 42ND ST	SE 1/8 - 1/4 (0.146 mi.)	AJ208	410
CON EDISON	351 W 44	E 1/8 - 1/4 (0.149 mi.)	AI214	420
OK CLEANERS INCORPORATED	647 9TH AVENUE	NE 1/8 - 1/4 (0.150 mi.)	AG216	422
HOLY CROSS CHURCH	331 WEST 42ND STREET	SE 1/8 - 1/4 (0.155 mi.)	AJ229	443
CON EDISON	344 W 44 ST	E 1/8 - 1/4 (0.156 mi.)	AI231	446
CONSOLIDATED EDISON	329 W 42 ST MH56654	SE 1/8 - 1/4 (0.159 mi.)	AJ244	468
CON EDISON	342 W 44 ST	E 1/8 - 1/4 (0.159 mi.)	AI245	469
CON EDISON	327 W 42ND ST	SE 1/8 - 1/4 (0.162 mi.)	AJ249	474
CON EDISON	324 W 42ND ST	SE 1/8 - 1/4 (0.165 mi.)	AJ256	482
CON EDISON	337 W 44	E 1/8 - 1/4 (0.170 mi.)	AP264	497
CON EDISON	F/O 323 WEST 43RD ST.	ESE 1/8 - 1/4 (0.170 mi.)	AN268	505
PORT AUTH OF NY & NJ 9TH AVE &	9TH AVE BETW 38TH & 39T	SSW 1/8 - 1/4 (0.171 mi.)	AO271	508
CONSOLIDATED EDISON	WEST 39 ST & 9TH AVE	SSW 1/8 - 1/4 (0.171 mi.)	AO272	510
BELL ATLANTIC-NY	W 39TH ST/9 AVE	SSW 1/8 - 1/4 (0.171 mi.)	AO273	515
CON EDISON	400 W 39TH ST	SSW 1/8 - 1/4 (0.171 mi.)	AO275	517
CON EDISON	F/O 354 W45 ST & 8TH AV	ENE 1/8 - 1/4 (0.177 mi.)	AT285	532
CONSOLIDATED EDISON	656 9TH AVE	NE 1/8 - 1/4 (0.178 mi.)	AQ286	533
DRY CLEANERS	659 9TH AVE	NE 1/8 - 1/4 (0.178 mi.)	AQ290	540
CON EDISON	661 9TH AVE	NE 1/8 - 1/4 (0.183 mi.)	AQ297	560
THE STAYBRIDGE	334 -340 WEST 40TH STRE	SSE 1/8 - 1/4 (0.184 mi.)	AX305	595
CON EDISON	515 9TH AVE	SSW 1/8 - 1/4 (0.186 mi.)	AO315	620
EMPIREFFECTS INCORPORATED	311 WEST 43RD STREET	ESE 1/8 - 1/4 (0.187 mi.)	BB322	633
CON EDISON	342 W 45 ST	ENE 1/8 - 1/4 (0.190 mi.)	BD333	657
CON EDISON	F/O 425 WEST 46TH ST	NNE 1/8 - 1/4 (0.197 mi.)	AV343	680
CON EDISON	F/O 425 W 46 ST & 9TH A	NNE 1/8 - 1/4 (0.197 mi.)	AV344	681
CON ED - V 0989	315 W 44 ST	E 1/8 - 1/4 (0.199 mi.)	BI353	692

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	506 9TH AVE	SSW 1/8 - 1/4 (0.203 mi.)	BH365	731
R GREENBURG ASSOCIATES	350 W 39TH ST	S 1/8 - 1/4 (0.205 mi.)	BG368	738
CON EDISON	459 W 46 ST	N 1/8 - 1/4 (0.205 mi.)	BJ372	745
NYCTA - W 42ND ST & 8TH AVE ST	W 42ND ST & 8TH AVE	ESE 1/8 - 1/4 (0.208 mi.)	BL385	795
CONSOLIDATED EDISON	W 42ND ST & 8TH AVE	ESE 1/8 - 1/4 (0.208 mi.)	BL386	808
CONSOLIDATED EDISON	W 42 ST. & 8 AVE.	ESE 1/8 - 1/4 (0.208 mi.)	BL387	812
CON EDISON	672 8TH AVE	ESE 1/8 - 1/4 (0.209 mi.)	BM389	815
CON ED	505 9 AVE	SSW 1/8 - 1/4 (0.209 mi.)	BH390	817
V1056	314 W. 40TH STREET	SSE 1/8 - 1/4 (0.209 mi.)	BN394	825
TECHNICOLOR	321 W 44TH ST	E 1/8 - 1/4 (0.210 mi.)	BI401	837
HAP ENGRAVING OF NY LTD	323 W 39TH ST	SSE 1/8 - 1/4 (0.211 mi.)	BR405	869
CON EDISON	312 W 40TH ST	SSE 1/8 - 1/4 (0.218 mi.)	BN421	903
315 ASSOCIATES LLC/HANDRO MANG	315 W 39TH ST	SSE 1/8 - 1/4 (0.219 mi.)	BR428	918
PORT AUTH OF NY & NJ 9TH AVE & EMPIRE CLEANERS	38TH ST & 9TH AVE	SSW 1/8 - 1/4 (0.220 mi.)	BH435	932
CON EDISON	674 9TH AVE.	NE 1/8 - 1/4 (0.221 mi.)	BQ437	938
CON EDISON	F/O 346 W 46 & 9TH AVE	ENE 1/8 - 1/4 (0.222 mi.)	BX442	956
CON EDISON	497 9TH AVE	SSW 1/8 - 1/4 (0.227 mi.)	BY461	990
WEST 39TH STREET LLC	328 -336 W 39TH ST	SSE 1/8 - 1/4 (0.229 mi.)	BR468	1017
CON EDISON	304 W 40TH ST	SSE 1/8 - 1/4 (0.229 mi.)	BN470	1031
CON EDISON	498 9TH AVE	SSW 1/8 - 1/4 (0.231 mi.)	BY474	1039
CON EDISON AT PORT AUTHORITY O PABT - PORT AUTHORITY BUS TERM	625 8TH AVE - BASEMENT	SE 1/8 - 1/4 (0.232 mi.)	CC478	1049
L & L PAINTING CO INC	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC479	1051
CONSOLIDATED EDISON	625 8TH AVE - BLOCK 103	SE 1/8 - 1/4 (0.232 mi.)	CC482	1107
CON EDISON	416 WEST 47TH STREET	NNE 1/8 - 1/4 (0.235 mi.)	CF500	1139
NEWBRIDGE COMMUNICATIONS	333 E 38TH ST - 8TH FLO	S 1/8 - 1/4 (0.236 mi.)	CE506	1150
CON EDISON	316 W 39TH ST	SSE 1/8 - 1/4 (0.243 mi.)	CL529	1217
REMCO MAINTENANCE CORPORATION	10TH AVE	WSW 1/8 - 1/4 (0.248 mi.)	CO547	1248
A S I SIGN SYSTEMS INC	500 10TH AVE 6TH FLOOR	WSW 1/8 - 1/4 (0.248 mi.)	CO548	1267
ASI INC	500 10TH AVE 7TH FL	WSW 1/8 - 1/4 (0.248 mi.)	CO549	1288
CON EDISON	310 W 39TH ST	SSE 1/8 - 1/4 (0.250 mi.)	CL554	1325
Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	456 W 43RD ST	NNW 0 - 1/8 (0.070 mi.)	J71	155
CONSOLIDATED EDISON	469 W 42ND ST	WNW 0 - 1/8 (0.095 mi.)	P109	215
HUNTER COLLEGE - MFA	450 W 41ST ST	WSW 1/8 - 1/4 (0.130 mi.)	AB162	310
CON EDISON	582 10TH AVE	WNW 1/8 - 1/4 (0.132 mi.)	AC165	326
CONSOLIDATED EDISON	W 42 ST & 10 AVE MH4326	WNW 1/8 - 1/4 (0.134 mi.)	AC167	331
CONSOLIDATED EDISON	42ND & 10TH AVE MH60134	WNW 1/8 - 1/4 (0.134 mi.)	AC168	333
CONSOLIDATED EDISON	42ND ST & 10TH AVE	WNW 1/8 - 1/4 (0.134 mi.)	AC169	333
CVS PHARMACY #2940	500 W 42ND ST	WNW 1/8 - 1/4 (0.135 mi.)	AC173	338
CON EDISON	587 10TH AVE	NW 1/8 - 1/4 (0.137 mi.)	AC179	362
CON EDISON - GM 16 INCH	10TH AVE WEST 42 /WEST	NW 1/8 - 1/4 (0.138 mi.)	AE181	366
CONSOLIDATED EDISON	W 43 ST & 10TH AVE	NW 1/8 - 1/4 (0.139 mi.)	AE188	379
OMNI CLEANERS	595 10TH AVENUE	NW 1/8 - 1/4 (0.142 mi.)	AE203	403
CON EDISON	563 10TH AVE	W 1/8 - 1/4 (0.143 mi.)	AH204	403
CON EDISON	OPP 561 10TH AVE	W 1/8 - 1/4 (0.145 mi.)	AH205	405
CON EDISON	OPP 461 W 40TH ST	WSW 1/8 - 1/4 (0.146 mi.)	AB210	412
CON EDISON	503 W 43RD ST	NW 1/8 - 1/4 (0.151 mi.)	AE219	426
CON EDISON	548 10TH AVE	W 1/8 - 1/4 (0.158 mi.)	AL238	460
CON EDISON	547 10TH AVE	W 1/8 - 1/4 (0.158 mi.)	AL242	464
FAST TOWING & AUTO REPAIR	547 10TH ST	W 1/8 - 1/4 (0.161 mi.)	AL246	470
CON EDISON	544 10TH AVE	W 1/8 - 1/4 (0.165 mi.)	AL253	478
CONSOLIDATED EDISON	626 10TH AVE 44TH & 45T	NNW 1/8 - 1/4 (0.169 mi.)	AR262	495
CON EDISON	OPP 628 10TH AVE	NNW 1/8 - 1/4 (0.177 mi.)	AR284	530

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	OPP 503 W 40TH ST	W 1/8 - 1/4 (0.182 mi.)	AU295	556
HESS CORPORATION	502 W 45TH ST	NNW 1/8 - 1/4 (0.183 mi.)	AR299	563
CON EDISON	465 W 39 ST.	SW 1/8 - 1/4 (0.184 mi.)	303	589
CON EDISON	OPP 509 W 40TH ST	W 1/8 - 1/4 (0.185 mi.)	AU307	610
CON EDISON	510 W 41ST ST	W 1/8 - 1/4 (0.185 mi.)	AZ311	615
CON EDISON	519 W 42ND ST	WNW 1/8 - 1/4 (0.186 mi.)	AW317	623
NYC DEPT OF ED - PUBLIC SCHOOL	515-533 WEST 44TH STREE	NW 1/8 - 1/4 (0.198 mi.)	BF349	687
NY PUBLIC LIBRARY - 43RD ST AN	521 W 43RD ST	NW 1/8 - 1/4 (0.199 mi.)	BE354	693
CON ED - V 3685	522 W 44 ST	NW 1/8 - 1/4 (0.207 mi.)	BF379	757
CON EDISON	522 WEST 44TH ST	NW 1/8 - 1/4 (0.207 mi.)	BF380	790
CON EDISON	535 W 40TH ST	W 1/8 - 1/4 (0.209 mi.)	BO396	828
CON EDISON	OPP 535 W 40TH ST	W 1/8 - 1/4 (0.209 mi.)	BO397	829
CON EDISON	OPP 519 10TH AVE	WSW 1/8 - 1/4 (0.209 mi.)	BP398	831
CON EDISON - MH43240	W39TH ST & 10TH AVE W39	WSW 1/8 - 1/4 (0.212 mi.)	BP407	880
PORT AUTH OF NY & NJ 10TH AVE	10TH AVE BETW 38TH & 39	WSW 1/8 - 1/4 (0.212 mi.)	BP410	883
CONSOLIDATED EDISON	#43240 W 39TH ST & 10TH	WSW 1/8 - 1/4 (0.212 mi.)	BP411	885
NEW YORK CITY DEP	39TH ST BET 11TH&10	WSW 1/8 - 1/4 (0.213 mi.)	BP412	886
CON EDISON	OPP 543 W 40TH ST	W 1/8 - 1/4 (0.222 mi.)	BO444	959
CON EDISON	546 W 42ND ST	WNW 1/8 - 1/4 (0.223 mi.)	BW447	964
CON EDISON	541 W 43RD ST	NW 1/8 - 1/4 (0.226 mi.)	BT452	973
MERCEDES-BENZ MANHATTAN INC	528 W 41ST ST	WNW 1/8 - 1/4 (0.227 mi.)	BZ462	992
CONSOLIDATED EDISON	46 ST & 10TH AVE	N 1/8 - 1/4 (0.228 mi.)	BV466	1016
CON EDISON	550 W 42ND ST	WNW 1/8 - 1/4 (0.229 mi.)	BW471	1032
CON EDISON	514 W 39TH ST	WSW 1/8 - 1/4 (0.233 mi.)	CD487	1112
CON EDISON	549 W 40TH ST	W 1/8 - 1/4 (0.234 mi.)	CH497	1131
TRAILWAYS INC	544 W 41ST ST	WNW 1/8 - 1/4 (0.237 mi.)	BZ509	1166
MERCHANDISING WORKSHOP	550 WEST 43RD ST	NW 1/8 - 1/4 (0.241 mi.)	CM523	1193
MERCEDES BENZ MANHATTAN INC	528 W 39TH ST	WSW 1/8 - 1/4 (0.242 mi.)	CD526	1198
CON EDISON	551 W 41ST ST	WNW 1/8 - 1/4 (0.244 mi.)	BZ532	1221
FEDERAL EXPRESS CORP	560 W 42ND ST	WNW 1/8 - 1/4 (0.245 mi.)	BW534	1224
CON EDISON	FT OF 517 W. 45TH ST	NNW 1/8 - 1/4 (0.247 mi.)	CJ541	1242
CONED	557 W41ST ST	WNW 1/8 - 1/4 (0.249 mi.)	551	1291

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 05/01/2014 has revealed that there are 3 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CINERIC INC	321 W 44TH ST - 4TH FL	E 1/8 - 1/4 (0.189 mi.)	AP326	642
PABT - PORT AUTHORITY BUS TERM	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC479	1051
REMCO MAINTENANCE CORPORATION	10TH AVE	WSW 1/8 - 1/4 (0.248 mi.)	CO547	1248

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 05/01/2014 has revealed that there are 2 RI MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PABT - PORT AUTHORITY BUS TERM	625 8TH AVE	SE 1/8 - 1/4 (0.232 mi.)	CC479	1051
Lower Elevation	Address	Direction / Distance	Map ID	Page
FEDERAL EXPRESS CORP	560 W 42ND ST	WNW 1/8 - 1/4 (0.245 mi.)	BW534	1224

EXECUTIVE SUMMARY

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 07/17/2014 has revealed that there are 6 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
NINTH AVENUE CLEANERS	617 9TH AVENUE	NE 0 - 1/8 (0.080 mi.)	N82	170
OK CLEANERS INCORPORATED	647 9TH AVENUE	NE 1/8 - 1/4 (0.150 mi.)	AG216	422
REGAL TAILORS CLEANERS	659 9TH AVE	NE 1/8 - 1/4 (0.178 mi.)	AQ291	551
EMPIRE CLEANER	674 NINTH AVE.	NE 1/8 - 1/4 (0.221 mi.)	BQ439	953
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
OMNI CLEANERS	595 10TH AVENUE	NW 1/8 - 1/4 (0.142 mi.)	AE203	403
OMNI DRY CLEANERS	608 10TH AVE	NNW 1/8 - 1/4 (0.152 mi.)	AK221	428

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 06/18/2014 has revealed that there are 23 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
LOT 138,TAXBLOCK 1051	406 WEST 42 STREET	SSE 0 - 1/8 (0.028 mi.)	B9	48
LOT 36,TAXBLOCK 1051	581 9 AVENUE	SSE 0 - 1/8 (0.049 mi.)	B39	92
LOT 135,TAXBLOCK 1051	579 9 AVENUE	SSE 0 - 1/8 (0.050 mi.)	B41	97
LOT 162,TAXBLOCK 1032	576 9 AVENUE	SSE 0 - 1/8 (0.050 mi.)	B44	103
LOT 63,TAXBLOCK 1032	574 9 AVENUE	SSE 0 - 1/8 (0.051 mi.)	B46	108
LOT 35,TAXBLOCK 1051	577 9 AVENUE	SSE 0 - 1/8 (0.052 mi.)	B51	114
LOT 64,TAXBLOCK 1032	572 9 AVENUE	SSE 0 - 1/8 (0.054 mi.)	H56	122
LOT 61,TAXBLOCK 1032	578 9 AVENUE	SSE 0 - 1/8 (0.055 mi.)	H57	124
LOT 4,TAXBLOCK 1032	570 9 AVENUE	SSE 0 - 1/8 (0.057 mi.)	H59	129
LOT 33,TAXBLOCK 1051	573 9 AVENUE	S 0 - 1/8 (0.058 mi.)	H62	136
LOT 103,TAXBLOCK 1032	568 9 AVENUE	SSE 0 - 1/8 (0.061 mi.)	H64	142
LOT 32,TAXBLOCK 1051	571 9 AVENUE	S 0 - 1/8 (0.061 mi.)	H65	143
LOT 1,TAXBLOCK 1032	566 9 AVENUE	S 0 - 1/8 (0.064 mi.)	H69	150
LOT 31,TAXBLOCK 1051	567 9 AVENUE	S 0 - 1/8 (0.068 mi.)	H70	152
LOT 101,TAXBLOCK 1032	355 WEST 41 STREET	S 0 - 1/8 (0.088 mi.)	K93	191
LOT 7,TAXBLOCK 1032	347 WEST 41 STREET	SSE 0 - 1/8 (0.090 mi.)	K96	196
LOT 7501,TAXBLOCK 1032	350 WEST 42 STREET	SE 0 - 1/8 (0.123 mi.)	T147	288
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
LOT 49,TAXBLOCK 1051	432 WEST 42 STREET	W 0 - 1/8 (0.045 mi.)	C34	83
LOT 50,TAXBLOCK 1051	434 WEST 42 STREET	W 0 - 1/8 (0.048 mi.)	C37	89
LOT 51,TAXBLOCK 1051	436 WEST 42 STREET	W 0 - 1/8 (0.051 mi.)	C45	105
LOT 53,TAXBLOCK 1051	440 WEST 42 STREET	WNW 0 - 1/8 (0.059 mi.)	I63	139
LOT 57,TAXBLOCK 1051	450 WEST 42 STREET	WNW 0 - 1/8 (0.071 mi.)	I73	158
LOT 158,TAXBLOCK 1050	454 WEST 41 STREET	W 0 - 1/8 (0.113 mi.)	W132	256

EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 4 EDR MGP sites within approximately 1 mile of the target property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CON EDISON - WEST 42ND ST. GAS	WEST 41ST - WEST 42ND S	WNW 1/4 - 1/2 (0.316 mi.)	576	1389
CON EDISON - WEST 45TH ST. GAS	12TH AVE BETWEEN WEST 4	NW 1/4 - 1/2 (0.382 mi.)	DA616	1506
CON EDISON - 12TH AVE. WORKS M	12TH AVE BETWEEN W 46TH	NW 1/4 - 1/2 (0.382 mi.)	DA617	1506
CON EDISON - WEST 58TH ST. STA	11TH AVE. BETWEEN W. 58	N 1/2 - 1 (0.859 mi.)	675	1616

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 40 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
Not reported	582 9TH AVE	SE 0 - 1/8 (0.042 mi.)	B25	72
Not reported	581 9TH AVE	SSE 0 - 1/8 (0.049 mi.)	B38	92
Not reported	563 9TH AVE	S 0 - 1/8 (0.075 mi.)	K76	164
Not reported	356 W 41ST ST	S 0 - 1/8 (0.087 mi.)	K91	187
Not reported	413 W 45TH ST	NNE 1/8 - 1/4 (0.136 mi.)	AD174	351
Not reported	415 W 45TH ST	NNE 1/8 - 1/4 (0.136 mi.)	AD175	351
Not reported	401 W 45TH ST	NE 1/8 - 1/4 (0.139 mi.)	AG189	379
Not reported	427 W 45TH ST	NNE 1/8 - 1/4 (0.140 mi.)	AF192	386
Not reported	445 W 45TH ST	N 1/8 - 1/4 (0.157 mi.)	AM234	454
Not reported	349 W 45TH ST	ENE 1/8 - 1/4 (0.185 mi.)	AT308	612
Not reported	661 8TH AVE	ESE 1/8 - 1/4 (0.207 mi.)	BL378	757
Not reported	450 W 38 AT I 495	SW 1/8 - 1/4 (0.233 mi.)	CA483	1108
Not reported	450 W 38TH ST	SW 1/8 - 1/4 (0.233 mi.)	CA489	1117
Not reported	620 8TH AVE	SSE 1/8 - 1/4 (0.239 mi.)	CC514	1175
Not reported	500 10TH AVE	WSW 1/8 - 1/4 (0.248 mi.)	CO546	1248
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
Not reported	466 W 42ND ST	WNW 0 - 1/8 (0.090 mi.)	P95	196

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	575 10TH AVE	WNW 1/8 - 1/4 (0.135 mi.)	AC171	336
Not reported	551 10TH AVE	W 1/8 - 1/4 (0.156 mi.)	AL230	445
Not reported	614 10TH AVE	NNW 1/8 - 1/4 (0.158 mi.)	AK240	462
Not reported	547 10TH AVE	W 1/8 - 1/4 (0.161 mi.)	AL248	474
Not reported	615 10TH AVE	NNW 1/8 - 1/4 (0.163 mi.)	AK251	477
Not reported	538 10TH AVE	WSW 1/8 - 1/4 (0.176 mi.)	AU282	529
Not reported	500 W 40TH ST	WSW 1/8 - 1/4 (0.179 mi.)	AU292	552
Not reported	502 W 45TH ST	NNW 1/8 - 1/4 (0.183 mi.)	AR301	582
Not reported	637 10TH AVE	NNW 1/8 - 1/4 (0.191 mi.)	BC334	659
Not reported	514 W 44TH ST	NW 1/8 - 1/4 (0.197 mi.)	BF346	684
Not reported	518 W 44TH ST	NW 1/8 - 1/4 (0.203 mi.)	BF363	729
Not reported	520 W 44TH ST	NW 1/8 - 1/4 (0.206 mi.)	BF375	751
Not reported	510 10TH AVE	WSW 1/8 - 1/4 (0.212 mi.)	BP406	880
Not reported	545 W 42ND ST	WNW 1/8 - 1/4 (0.221 mi.)	BW441	956
Not reported	541 W 43RD ST	NW 1/8 - 1/4 (0.226 mi.)	BT454	979
Not reported	514 W 39TH ST	WSW 1/8 - 1/4 (0.233 mi.)	CD485	1109
Not reported	516 W 39TH ST	WSW 1/8 - 1/4 (0.234 mi.)	CD495	1129
Not reported	555 W 42ND ST	WNW 1/8 - 1/4 (0.235 mi.)	BW502	1144
Not reported	522 W 39TH ST	WSW 1/8 - 1/4 (0.238 mi.)	CD511	1170
Not reported	509 W 45TH ST	NNW 1/8 - 1/4 (0.239 mi.)	CJ517	1180
Not reported	548 W 41ST ST	WNW 1/8 - 1/4 (0.242 mi.)	BZ525	1197
Not reported	551 W 41ST ST	WNW 1/8 - 1/4 (0.244 mi.)	BZ531	1221
Not reported	517 W 45TH ST	NNW 1/8 - 1/4 (0.247 mi.)	CJ544	1247
Not reported	551 W 44TH ST	NW 1/8 - 1/4 (0.248 mi.)	CB545	1247

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 25 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	400 W 42ND ST	SE 0 - 1/8 (0.041 mi.)	B21	68
Not reported	617 9TH AVE	NE 0 - 1/8 (0.080 mi.)	N83	170
Not reported	405 W 44TH ST	NE 0 - 1/8 (0.091 mi.)	N100	204
Not reported	360 W 43RD ST	E 0 - 1/8 (0.110 mi.)	V129	250
Not reported	400 W 40TH ST	SSW 0 - 1/8 (0.124 mi.)	Y154	297
Not reported	647 9TH AVE	NE 1/8 - 1/4 (0.150 mi.)	AG215	422
Not reported	347 W 44TH ST	E 1/8 - 1/4 (0.154 mi.)	AI227	439
Not reported	525 9TH AVE	SSW 1/8 - 1/4 (0.164 mi.)	AO252	477
Not reported	652 9TH AVE	NE 1/8 - 1/4 (0.168 mi.)	AQ258	487
Not reported	524 9TH AVE	SSW 1/8 - 1/4 (0.170 mi.)	AO265	499
Not reported	359 W 45TH ST	ENE 1/8 - 1/4 (0.174 mi.)	AT279	523
Not reported	404 W 46TH ST	NE 1/8 - 1/4 (0.186 mi.)	BA318	624
Not reported	359 W 39TH ST	S 1/8 - 1/4 (0.197 mi.)	BG348	687
Not reported	453 W 46TH ST	N 1/8 - 1/4 (0.200 mi.)	BJ358	716
Not reported	670 9TH AVE	NE 1/8 - 1/4 (0.211 mi.)	BQ404	868
Not reported	674 9TH AVE	NE 1/8 - 1/4 (0.221 mi.)	BQ438	953

EXECUTIVE SUMMARY


<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
Not reported	676 9TH AVE	NE 1/8 - 1/4 (0.226 mi.)	BQ455	979
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
Not reported	455 W 44TH ST	N 0 - 1/8 (0.104 mi.)	U120	233
Not reported	500 W 43RD ST	NW 1/8 - 1/4 (0.139 mi.)	AE184	372
Not reported	595 10TH AVE	NW 1/8 - 1/4 (0.142 mi.)	AE201	401
Not reported	608 10TH AVE	NNW 1/8 - 1/4 (0.152 mi.)	AK220	427
Not reported	520 W 43RD ST	NW 1/8 - 1/4 (0.205 mi.)	BE369	741
Not reported	460 W 46TH ST	N 1/8 - 1/4 (0.212 mi.)	408	882
Not reported	656 10TH AVE	N 1/8 - 1/4 (0.219 mi.)	BV429	923
Not reported	543 W 43RD ST	NW 1/8 - 1/4 (0.228 mi.)	BT467	1017

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 21 records.

<u>Site Name</u>	<u>Database(s)</u>
FORMER LOCKPORT AIR FORCE THE	RCRA NonGen / NLR, NY MANIFEST
VERIZON NEW YORK INC. MANHOLE	NY MANIFEST
RIVERSIDE PARK	RCRA-SQG, NJ MANIFEST, NY
	MANIFEST
BELL ATLANTIC NY	NY MANIFEST
BELL ATLANTIC NY	NY MANIFEST
SUNOHIO PCBX UNIT LONG ISLAND RAIL	RCRA NonGen / NLR, NY MANIFEST
CONSOLIDATED EDISON	NY MANIFEST
NYCDOT BIN 2257569	NY MANIFEST
LAW & ORDER PRODUCTIONS	RCRA-CESQG, NJ MANIFEST, NY
	MANIFEST
VS3610	RCRA NonGen / NLR, NY MANIFEST
NYC DOS WEST 30TH STREET RECYCLING	NY SWF/LF
NYCDOS WEST 59TH STREET MTS	NY SWF/LF
NYS DOT BIN 107706C	RCRA-LQG
NYS DOT BIN 107706A	RCRA-LQG
NYS DOT BIN 107706B	RCRA-LQG
NYCDOT BIN 2257569	RCRA-LQG
VERIZON NEW YORK INC	RCRA NonGen / NLR
BELL ATLANTIC-NY	RCRA NonGen / NLR
59TH GENERATION STATION	NY Spills
THE CONTAINER STORE	NJ VCP
S BRUNSWICK SQUARE SHOPPING CENTER	NJ VCP

overview MAP - 4056019.6s




★	Target Property		
▲	Sites at elevations higher than or equal to the target property		Indian Reservations BIA
◆	Sites at elevations lower than the target property		County Boundary
⚙	Manufactured Gas Plants		Oil & Gas pipelines from USGS
⚙	Sensitive Receptors		100-year flood zone
	National Priority List Sites		500-year flood zone
	Dept. Defense Sites		National Wetland Inventory
			State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Ollie?s
ADDRESS: 411 West 42nd Street
New York NY 10036
LAT/LONG: 40.7589 / 73.9931

CLIENT: Environmental Data Resources
CONTACT: Thomas M. Valentine
INQUIRY #: 4056019.6s
DATE: September 04, 2014 11:43 am

detail MAP - 4056019.6s



★ Target Property

▲ Sites at elevations higher than or equal to the target property

◆ Sites at elevations lower than the target property

⚙ Manufactured Gas Plants

⚠ Sensitive Receptors

🚒 National Priority List Sites

🏢 Dept. Defense Sites

🏠 Indian Reservations BIA

🛢 Oil & Gas pipelines from USGS

🌊 100-year flood zone

🌊 500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Ollie's
ADDRESS: 411 West 42nd Street
New York NY 10036
LAT/LONG: 40.7589 / 73.9931

CLIENT: Environmental Data Resources
CONTACT: Thomas M. Valentine
INQUIRY #: 4056019.6s
DATE: September 04, 2014 11:44 am

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
<u>STANDARD ENVIRONMENTAL RECORDS</u>								
<i>Federal NPL site list</i>								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
<i>Federal Delisted NPL site list</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Federal CERCLIS list</i>								
CERCLIS	0.500		0	0	0	NR	NR	0
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
<i>Federal CERCLIS NFRAP site List</i>								
CERC-NFRAP	0.500		0	0	1	NR	NR	1
<i>Federal RCRA CORRACTS facilities list</i>								
CORRACTS	1.000		0	0	0	0	NR	0
<i>Federal RCRA non-CORRACTS TSD facilities list</i>								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
<i>Federal RCRA generators list</i>								
RCRA-LQG	0.250		1	6	NR	NR	NR	7
RCRA-SQG	0.250		0	6	NR	NR	NR	6
RCRA-CESQG	0.250	1	15	62	NR	NR	NR	78
<i>Federal institutional controls / engineering controls registries</i>								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	TP		NR	NR	NR	NR	NR	0
<i>State- and tribal - equivalent CERCLIS</i>								
NY SHWS	1.000		0	0	0	1	NR	1
NJ SHWS	1.000		0	0	0	0	NR	0
NY VAPOR REOPENED	1.000		0	0	0	0	NR	0
<i>State and tribal landfill and/or solid waste disposal site lists</i>								
NY SWF/LF	0.500		0	0	2	NR	NR	2
NJ SWF/LF	0.500		0	0	0	NR	NR	0
<i>State and tribal leaking storage tank lists</i>								
NY LTANKS	0.500		5	16	105	NR	NR	126

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
INDIAN LUST	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
NY TANKS	0.250		0	3	NR	NR	NR	3
NY UST	0.250		9	19	NR	NR	NR	28
NJ UST	0.250		0	0	NR	NR	NR	0
NY CBS UST	0.250		1	0	NR	NR	NR	1
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY AST	0.250		19	112	NR	NR	NR	131
NY CBS AST	0.250		1	0	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		2	0	NR	NR	NR	2
NY MOSF	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY ENG CONTROLS	0.500		0	0	1	NR	NR	1
NJ ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	1	NR	NR	1
NJ INST CONTROL	0.500		0	0	0	NR	NR	0
NY RES DECL	0.125		0	NR	NR	NR	NR	0
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	2	NR	NR	2
NJ VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY ERP	0.500		0	0	0	NR	NR	0
NY BROWNFIELDS	0.500		0	1	6	NR	NR	7
NJ BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
NJ SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY DEL SHWS	1.000		0	0	0	0	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		5	9	NR	NR	NR	14
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
NY LIENS	TP		NR	NR	NR	NR	NR	0
NJ LIENS	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		43	NR	NR	NR	NR	43
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NJ SPILLS 90	0.125		0	NR	NR	NR	NR	0
NJ SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		11	37	NR	NR	NR	48
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	1	NR	1
ROD	1.000		0	0	0	1	NR	1
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP	1	NR	NR	NR	NR	NR	1
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY UIC	TP		NR	NR	NR	NR	NR	0
NJ UIC	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250	1	23	113	NR	NR	NR	137
NJ MANIFEST	0.250		0	3	NR	NR	NR	3
RI MANIFEST	0.250		0	2	NR	NR	NR	2
NY DRYCLEANERS	0.250		1	5	NR	NR	NR	6
NJ DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY SPDES	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NJ NPDES	TP		NR	NR	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY E DESIGNATION	0.125		23	NR	NR	NR	NR	23
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
NJ Financial Assurance	TP		NR	NR	NR	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
NJ COAL ASH	0.500		0	0	0	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	3	1	NR	4
EDR US Hist Auto Stat	0.250		5	35	NR	NR	NR	40
EDR US Hist Cleaners	0.250		6	19	NR	NR	NR	25

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
NJ RGA LF	TP		NR	NR	NR	NR	NR	0
NJ RGA HWS	TP		NR	NR	NR	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A1
Target
Property **CON EDISON**
411 W 42ND ST
NEW YORK, NY 10036

FINDS **1012240816**
N/A

Site 1 of 8 in cluster A

Actual:
32 ft.

FINDS:

Registry ID: 110039571727

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A2
Target
Property **CON EDISON**
411 W 42ND ST
NEW YORK, NY 10001

RCRA-CESQG **1012185886**
NYP004167219

Site 2 of 8 in cluster A

Actual:
32 ft.

RCRA-CESQG:

Date form received by agency: 04/14/2009

Facility name: CON EDISON

Facility address: 411 W 42ND ST
NEW YORK, NY 10001

EPA ID: NYP004167219

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003

Contact: DENNIS MICHAELIDES

Contact address: Not reported

Contact country: Not reported

Contact telephone: (718) 204-4297

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185886

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

A3
Target
Property

CONSOLIDATED EDISON
411 W 42ND ST
NEW YORK, NY 10001

NY MANIFEST **S109584123**
N/A

Site 3 of 8 in cluster A

Actual:
32 ft.

NY MANIFEST:
EPA ID: NYP004167219
Country: USA

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: CONSOLIDATED EDISON
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167219
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 300.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028113JJK
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584123

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167219
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 300.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584123

Part B Recv Date: Not reported
Generator EPA ID: NYP004167219
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 300.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167219
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 300.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584123

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

**NPL
Region
WNW
1/2-1
2811 ft.**

**HUDSON RIVER PCBS
NO STREET APPLICABLE
HUDSON RIVER, NY 12801**

**NPL 1000384273
CERCLIS NYD980763841
RCRA-LQG
US ENG CONTROLS
US INST CONTROL
CONSENT
ROD
NY Spills
PRP**

NPL:
EPA ID: NYD980763841
EPA Region: 02
Federal: N
Final Date: 1984-09-21 00:00:00

Category Details:
NPL Status: Currently on the Final NPL
Category Description: Depth To Aquifer-<= 10 Feet
Category Value: 0

NPL Status: Currently on the Final NPL
Category Description: Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value: 10

Site Details:
Site Name: HUDSON RIVER PCBS
Site Status: Final
Site Zip: 12801
Site City: HUDSON RIVER
Site State: NY
Federal Site: No
Site County: WASHINGTON
EPA Region: 02
Date Proposed: 09/08/83
Date Deleted: Not reported
Date Finalized: 09/21/84

Substance Details:
NPL Status: Currently on the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: A046
Substance: POLYCHLORINATED BIPHENYLS
CAS #: 1336-36-3
Pathway: AIR PATHWAY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: A046
Substance: POLYCHLORINATED BIPHENYLS
CAS #: 1336-36-3
Pathway: SURFACE WATER PATHWAY
Scoring: 4

Summary Details:

Conditions at listing September 1983): The Hudson River PCBs Site is a 40-mile stretch of the Hudson River between Mechanicville and Fort Edward, New York. General Electric Co. discharged an estimated 1.1 million pounds of PCBs into this stretch of river. The State has identified 40 hot spots, defined as sediments contaminated with greater than 50 parts per million ppm) of PCBs. Also included in the site are five remnant areas, which are river sediments exposed when the level of the river was lowered due to removal of the Fort Edward Dam. The State has taken initial measures to stabilize the remnant areas from erosion. In September 1980, Congress passed an amendment to the Clean Water Act (CWA) that included the Hudson River PCB Reclamation Demonstration Project. Under this legislation, the EPA Administrator could authorize a 75 percent grant, not to exceed 20 million. EPA issued a final Environmental Impact Statement in October 1982 evaluating various dredging alternatives for a demonstration project. EPA has prepared a feasibility study to evaluate alternative remedial actions under CERCLA. The Administrator has determined that CERCLA funds may be used for remedial action at the remnant areas and for evaluating the effectiveness of the water supply system at Waterford, New York. Status June 1984): EPA has completed a draft feasibility study identifying alternatives for remedial action. A search for parties potentially responsible for wastes associated with the site has been completed, and EPA has sent letters to two potentially responsible parties notifying them of possible legal action under CERCLA.

Site Status Details:

NPL Status: Final
Proposed Date: 09/08/1983
Final Date: 09/21/1984
Deleted Date: Not reported

Narratives Details:

NPL Name: HUDSON RIVER PCBS
City: HUDSON RIVER
State: NY

CERCLIS:

Site ID: 0202229
EPA ID: NYD980763841
Facility County: WASHINGTON
Short Name: HUDSON RIVER PCBS
Congressional District: 21
IFMS ID: 0284
SMSA Number: 2975
USGC Hydro Unit: 02020003
Federal Facility: Not a Federal Facility
DMNSN Number: 0.00000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Site Orphan Flag: N
RCRA ID: Not reported
USGS Quadrangle: Not reported
Site Init By Prog: Not reported
NFRAP Flag: Not reported
Parent ID: Not reported
RST Code: Not reported
EPA Region: 02
Classification: Waterways/Creeks/Rivers
Site Settings Code: SU
NPL Status: Currently on the Final NPL
DMNSN Unit Code: Not reported
RBRAC Code: Not reported
RResp Fed Agency Code: Not reported
Non NPL Status: Not reported
Non NPL Status Date: / /
Site Fips Code: 36115
CC Concurrence Date: / /
CC Concurrence FY: Not reported
Alias EPA ID: Not reported
Site FUDS Flag: Not reported

CERCLIS Site Contact Name(s):

Contact ID: 13002796.00000
Contact Name: JENNIFER LAPOMA
Contact Tel: (212) 637-4328
Contact Title: Remedial Project Manager (RPM)
Contact Email: Not reported

CERCLIS Site Alias Name(s):

Alias ID: 101
Alias Name: HUDSON RIVER PCBS
Alias Address: Not reported
WARREN, NY
Alias ID: 102
Alias Name: HUDSON RIVER PCBS
Alias Address: NO STREET APPLICABLE
NO CITY APPLICABLE, NY 12801
Alias ID: 103
Alias Name: HUDSON RIVER PCBS
Alias Address: NO STREET APPLICABLE
HUDSON RIVER, NY 12801
Alias Comments: Not reported

Site Description: The Hudson River PCBs Site includes a nearly 200 river-mile stretch of the Hudson River in eastern New York State from the Village of Hudson Falls to the Battery in New York City. The Hudson River has been designated an American Heritage River because of its important role in American history and culture. This federal Superfund Record of Decision (ROD) addresses the risks to people and ecological receptors associated with polychlorinated biphenyls (PCBs) in the in-place sediments of the Upper Hudson River. The Site is divided into the Upper Hudson River which is the length of river between Hudson Falls and the Federal Dam at Troy, New York and the Lower Hudson River which is the length of river between Federal Dam at Troy and the Battery. For purposes of this project, EPA further divided the Upper Hudson River area into three main sections known as River Section 1, River Section 2, and River Section 3. The Site also includes five Remnant Deposits, which are areas of PCB-contaminated

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

sediment that became exposed after the river water level dropped following removal of the Fort Edward Dam in 1973. The Upper Hudson River portion of the Site extends from the Fenimore Bridge in Hudson Falls to the Federal Dam at Troy, a distance of just over 43 river miles. The Lower Hudson River extends from the Federal Dam to the southern tip of Manhattan at the Battery in New York City. The Mid-Hudson River, which is primarily a subset of the Lower Hudson River, extends from the Federal Dam at Troy to just south of Poughkeepsie. The predominant sources of PCB contamination to the Upper Hudson River were two capacitor manufacturing plants owned and operated by GE. The plants are located adjacent to or near the Hudson River in the Village of Hudson Falls and the Town of Fort Edward. Over a 30-year period, the plants discharged a substantial amount of PCBs into the river. At the GE Hudson Falls plant, leakage of non-aqueous phase PCB-bearing oils through bedrock to the river continues to be a source of PCB contamination. Regarding the former outfall to the Hudson River from the GE Fort Edward plant, New York State Department of Environmental Conservation (NYSDEC) issued a Record of Decision in January 2000 that calls for the excavation of PCB-contaminated soil and sediment in this area of the Upper Hudson River shoreline in order to eliminate this source of PCBs to the river. EPA's analysis assumes a significantly reduced PCB loading to the river from these sources once the State's plans for remediation are implemented. PCBs, the chemicals of concern addressed in this decision document, have been classified by EPA as probable human carcinogens. They are also linked to other serious non-cancer adverse health effects based on observations in animals and emerging evidence in humans. Once discharged from the GE plants, the PCBs adhered to river sediment and accumulated downstream as they settled in impounded pools and other depositional areas. Historic fish and sediment data indicated PCBs were accumulating downstream of the old Fort Edward Dam as well as accumulating behind the dam. The removal of the dam in 1973 resulted in a remobilization and downstream distribution of PCBs that had accumulated behind the dam. Historically, the highest PCB sediment concentrations have been detected in the cohesive sediments within the Upper Hudson River. River scouring/erosion and other mechanisms have mobilized PCB-contaminated sediments from the extensive cohesive deposits, redepositing them farther downstream all the way to the Battery. The preponderance of data indicates that burial of contaminated sediment by cleaner materials is not universally or uniformly occurring. Data also indicate that contaminated sediments in River Sections 1, 2 and 3 continue to serve as the major source of PCBs to the water column and the fish within the Upper Hudson River. During an approximate 30-year period ending in 1977, PCBs were used in capacitor manufacturing operations Hudson Falls and Fort Edward, New York facilities. PCB oils were discharged both directly and indirectly from these plants into the Hudson River. This included both non-permitted and permitted discharges. Even after permits were received in 1975, permit exceedances occurred. Estimates of the total quantity of PCBs discharged directly from the two plants into the river from the 1940s to 1977 are as high as 1,330,000 pounds (about 605,000 kg). Many of the PCBs discharged to the river adhered to sediments and accumulated with the sediments as they settled in the impounded pool behind the Fort Edward Dam, as well as other depositional areas farther downstream. Because of its deteriorating condition, the Fort Edward Dam was removed in 1973. Five areas of PCB-contaminated sediments were exposed due to the lowering of the river water level when the Fort Edward Dam was removed. These five areas are known as the Remnant Deposits. During subsequent floods, PCB-contaminated sediments from the Fort Edward Dam area were scoured and transported downstream. EPA notified the company that had the two plants of the remedy selected in the 1984 ROD and offered the company the opportunity to implement the selected remedy with respect to the Remnant Deposits and the Waterford drinking water supply

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

evaluation. The company declined EPA's offer. NYSDEC, with funding provided by EPA, conducted the evaluation at the Waterford Water Works. In addition, NYSDEC prepared a design for the in-place containment of the Remnant Deposits. This design was completed in 1988. In March 1989, the company offered to assume responsibility for the implementation of the in-place containment remedy for the Remnant Deposits. EPA issued a September 27, 1989 Administrative Order on Consent to the company which required the company to prepare a remedial design report for the construction of access roads to the Remnant Deposits and to submit a design for the in-place containment of the Remnant Deposits incorporating the NYSDEC-prepared design, plus any EPA-approved refinements to that design. EPA also issued a September 27, 1989 Administrative Order to the company requiring the company to construct and maintain the access roads to the Remnant Deposits. The company constructed the in-place containment of the Remnant Deposits under a 1990 Consent Decree with EPA. EPA will evaluate the need for further remedial action for the Remnant Deposits after completion of a 5-year review of the Remnant Deposit containment remedy, performed pursuant to CERCLA §121(c). The company's manufacturing plants in Hudson Falls and Fort Edward are listed under the New York State Inactive Hazardous Waste Disposal Sites Remedial program. The company currently is conducting remedial activities near the Hudson Falls and Fort Edward plants pursuant to Orders on Consent with NYSDEC. The company has thus far declined to implement the January 2000 NYSDEC Record of Decision for the Fort Edward plant Outfall 004. The NYSDEC is conducting the remedial design for that ROD. As one of America's great rivers, the Hudson has played and will continue to play a major role in the history, culture, and economy of the area. The Hudson has been designated an American Heritage River because of its important role in American history and culture. Current and reasonably-anticipated future land use and surface water use are described below. Current land use includes a variety of residential, commercial and industrial activities. Use of the river and lands surrounding the river are projected to remain the same. At this time, no changes in future land use are known, nor are any new uses expected. The Site passes through 14 different counties as the river flows to its final discharge point in New York Harbor. Four counties (Albany, Washington, Rensselaer, and Saratoga) lie adjacent to the more highly contaminated portions (areas of proposed active remediation in River Sections 1, 2 and 3) of the Upper Hudson River between Troy (Federal Dam) and Hudson Falls. Within these four counties, forests and farmlands surround urban centers and historic villages. There are apple orchards and dairy farms, parks, nature preserves and gardens. In addition to the GE Hudson Falls and Fort Edward plants, the area is home to technology companies, oil service companies and food companies. Saratoga and Washington Counties have experienced population growth between 1990 and 1999 of 10.2 percent and 1.4 percent, respectively, while Rensselaer and Albany Counties have experienced population declines of 1.9 percent and 0.3 percent, respectively. Total population of these four counties, according to July 1999 estimates by the US Department of Commerce Bureau of the Census, is just under 700,000. Warren County, in which the City of Glens Falls is located, has a population of just over 60,000 and is just to the northwest of the Hudson River PCBs Site. A Record of Decision (ROD) addressing operable unit 1 (OU 01) was completed in September 1984. A Record of Decision addressing OU 2 was completed in February 2002.

CERCLIS Assessment History:

Action Code: 001
Action: DISCOVERY
Date Started: / /
Date Completed: 07/01/83
Priority Level: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: SITE INSPECTION
Date Started: 08/01/83
Date Completed: 09/01/83
Priority Level: Higher priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/01/83
Priority Level: Low priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: PROPOSAL TO NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 09/08/83
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: NATIONAL PRIORITIES LIST RESPONSIBLE PARTY SEARCH
Date Started: / /
Date Completed: 11/15/83
Priority Level: Search Complete, Viable PRPs
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: FINAL LISTING ON NATIONAL PRIORITIES LIST
Date Started: / /
Date Completed: 09/21/84
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 03/30/84
Date Completed: 09/25/84
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: RECORD OF DECISION
Date Started: / /
Date Completed: 09/25/84
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 10/27/83
Date Completed: 09/28/84
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Action Code: 001
Action: ADMINISTRATIVE/VOLUNTARY COST RECOVERY
Date Started: / /
Date Completed: 05/04/88
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMEDIAL DESIGN
Date Started: 02/02/89
Date Completed: 06/05/89
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Original Action Take Over

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 06/09/89
Date Completed: 09/27/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 06/09/89
Date Completed: 09/27/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 09/27/89

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 09/27/89
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 03/03/89
Date Completed: 04/06/90
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMEDIAL DESIGN
Date Started: 09/28/84
Date Completed: 05/18/90
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: State, Fund Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Original Action Take Over

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Lodged By DOJ
Date Started: / /
Date Completed: 05/18/90
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Federal Enforcement
Planning Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: CONSENT DECREE
Date Started: 04/06/90
Date Completed: 07/21/90
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMOVAL ASSESSMENT
Date Started: 04/17/90
Date Completed: 08/21/90
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL DESIGN
Date Started: 09/27/89
Date Completed: 09/28/90
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: New Action Resulting from Take Over

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY NEGOTIATIONS
Date Started: 03/12/90
Date Completed: 10/04/90
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Alternate
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL DESIGN
Date Started: 05/18/89
Date Completed: 01/07/91
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: New Action Resulting from Take Over

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL ACTION
Date Started: 10/13/89
Date Completed: 09/29/92
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL ACTION
Date Started: 09/28/90
Date Completed: 09/29/92
Priority Level: Not reported
Operable Unit: REMNANT DEPOSIT CAPPING
Primary Responsibility: Responsible Party
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMOVAL ASSESSMENT
Date Started: 11/19/92
Date Completed: 12/01/92
Priority Level: Stabilized
Operable Unit: ROGER'S ISLAND
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: COMFORT/STATUS LETTER
Date Started: / /
Date Completed: 11/02/98
Priority Level: Not reported
Operable Unit: SITEWIDE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: REMOVAL ASSESSMENT
Date Started: 10/14/98
Date Completed: 01/07/99
Priority Level: Not reported
Operable Unit: ROGER'S ISLAND
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: REMOVAL ASSESSMENT
Date Started: 06/03/98
Date Completed: 06/24/99
Priority Level: Not reported
Operable Unit: ROGER'S ISLAND
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Public Notice Published
Date Started: / /
Date Completed: 03/28/00
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMOVAL
Date Started: 10/06/99
Date Completed: 09/14/01
Priority Level: Stabilized
Operable Unit: ROGER'S ISLAND
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Time Critical
Action Anomaly: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: COMBINED REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 07/25/90
Date Completed: 02/01/02
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: RECORD OF DECISION
Date Started: / /
Date Completed: 02/01/02
Priority Level: Final Remedy Selected at Site
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: Special Notice Issued
Date Started: / /
Date Completed: 02/04/02
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: Special Notice Issued
Date Started: / /
Date Completed: 02/04/02
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: Special Notice Issued

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Date Started: / /
Date Completed: 02/04/02
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 005
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 02/04/02
Date Completed: 07/23/02
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 07/23/02
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 07/23/02
Date Completed: 08/13/03
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 08/13/03
Priority Level: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: EXPANDED SITE INSPECTION/REMEDIAL INVESTIGATION
Date Started: / /
Date Completed: 08/31/05
Priority Level: Referred to Removal, no further Rmdl Asmt
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 007
Action: REMEDIAL DESIGN/REMEDIAL ACTION NEGOTIATIONS
Date Started: 02/04/02
Date Completed: 09/06/05
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: TECHNICAL ASSISTANCE GRANT
Date Started: 09/29/95
Date Completed: 09/20/05
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: Lodged By DOJ
Date Started: / /
Date Completed: 10/06/05
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: COMMUNITY INVOLVEMENT
Date Started: 03/25/02
Date Completed: 11/02/06
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Remedial
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: CONSENT DECREE
Date Started: 09/06/05
Date Completed: 11/02/06
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 03/29/07
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: STATE SUPPORT AGENCY COOPERATIVE AGREEMENT
Date Started: 02/22/91
Date Completed: 04/03/07
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Action: REMOVAL NEGOTIATIONS
Date Started: / /
Date Completed: 07/11/07
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 005
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 07/11/07
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY EMERGENCY REMOVAL
Date Started: 08/24/07
Date Completed: 08/27/07
Priority Level: Cleaned up
Operable Unit: SITEWIDE
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Emergency
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL DESIGN
Date Started: 08/14/03
Date Completed: 01/25/08
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Phased Start

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: SECTION 104(E) REF LITIGATION
Date Started: 09/27/07
Date Completed: 07/28/08
Priority Level: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 09/05/08
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 09/05/08
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMEDIAL INVESTIGATION/FEASIBILITY STUDY NEGOTIATIONS
Date Started: 02/04/02
Date Completed: 09/08/08
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006
Action: ADMINISTRATIVE ORDER ON CONSENT
Date Started: / /
Date Completed: 09/08/08
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Federal Enforcement
Planning Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 005
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 09/11/08
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 10/14/08
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 007
Action: UNILATERAL ADMIN ORDER
Date Started: / /
Date Completed: 02/03/09
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: REMEDIAL ACTION
Date Started: 05/09/08
Date Completed: 11/24/09
Priority Level: Final RA Report
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Special Account Financed Action - EPA
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: REMEDIAL ACTION
Date Started: 12/04/08
Date Completed: 12/23/09
Priority Level: Final RA Report
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Special Account Financed Action - EPA
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL DESIGN
Date Started: 08/14/03
Date Completed: 04/26/11
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMOVAL
Date Started: 09/11/07
Date Completed: 04/10/12
Priority Level: Stabilized
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Time Critical
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: FIVE-YEAR REVIEW
Date Started: / /
Date Completed: 06/01/12
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL ACTION
Date Started: 09/06/05

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Date Completed: 09/04/12
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: TECHNICAL ASSISTANCE
Date Started: 09/30/97
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: REMEDIAL DESIGN
Date Started: 02/15/02
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Special Account Financed Action - EPA
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Other Completion Anomaly

For detailed financial records, contact EDR for a Site Report.:

Action Code: 003
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL DESIGN
Date Started: 07/23/02
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Phased Start & Completion

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: TECHNICAL ASSISTANCE
Date Started: 07/08/03
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REMEDIAL ACTION
Date Started: 01/19/07
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Special Account Financed Action - State
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Other Start and Completion Anomaly

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: REAL PROPERTY ACQUISITION
Date Started: 02/15/08
Date Completed: / /
Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Not reported
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL INVESTIGATION/FEASIBILITY STUDY
Date Started: 09/08/08
Date Completed: / /
Priority Level: Not reported
Operable Unit: FLOODPLAINS OU
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002
Action: TECHNICAL ASSISTANCE GRANT
Date Started: 11/17/09
Date Completed: / /
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 004
Action: POTENTIALLY RESPONSIBLE PARTY REMEDIAL ACTION
Date Started: 12/31/10
Date Completed: / /

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Priority Level: Not reported
Operable Unit: REASSESSMENT RIVER
Primary Responsibility: Responsible Party
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Federal Register Details:

Fed Register Date: 09/21/84
Fed Register Volume: 49
Page Number: 37070

Fed Register Date: 09/08/83
Fed Register Volume: 48
Page Number: 40674

[Click this hyperlink](#) while viewing on your computer to access
3292 additional US CERCLIS Financial: record(s) in the EDR Site Report.

RCRA-LQG:

Date form received by agency: 03/01/2012
Facility name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION
FACILITY
Facility address: 446 LOCK 8 WAY
HUDSON FALLS, NY 12839
EPA ID: NYD980763841
Mailing address: BROADWAY, BLDG 40
FORT EDWARD, NY 12828
Contact: ROBERT G GIBSON
Contact address: BROADWAY, BLDG 40
FORT EDWARD, NY 12828
Contact country: US
Contact telephone: (518) 746-5253
Contact email: BOB.GIBSON@GE.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: GENERAL ELECTRIC COMPANY
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/23/2007
Owner/Op end date: Not reported

Owner/operator name: SEE SECTION 11 COMMENTS
Owner/operator address: Not reported
NY
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 05/02/2007
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 03/03/2010
Site name: GE HUDSON RIVER SEDIMENT REMEDIATION PROCESSING AND TRANSPORTATION FACILITY
Classification: Large Quantity Generator

Date form received by agency: 08/29/2008
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) SUPERFUND USEPA
Classification: Large Quantity Generator

Date form received by agency: 01/01/2007
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: HUDSON RIVER PCBS (ROGERS ISLAND) USEPA
Classification: Large Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Hazardous Waste Summary:

Waste code: B002
Waste name: B002

Waste code: B007
Waste name: B007

Violation Status: No violations found

US ENG CONTROLS:

EPA ID: NYD980763841
Site ID: 0202229
Name: HUDSON RIVER PCBS
Address: NO STREET APPLICABLE
HUDSON RIVER, NY 12801
EPA Region: 02
County: WASHINGTON
Event Code: Not reported
Actual Date: 12/30/2001

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Containment, (N.O.S.)

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: No Action

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Revegetation

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 09/25/1984
Operable Unit: 01
Contaminated Media : Sediment
Engineering Control: Slope Stabilization

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Dewatering

Action ID: 002
Action Name: RECORD OF DECISION

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Disposal

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Excavation

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Sediment
Engineering Control: Solidification/Stabilization (Ex-Situ)

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water
Engineering Control: Monitoring

Action ID: 002
Action Name: RECORD OF DECISION
Action Completion date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water
Engineering Control: Natural Attenuation

US INST CONTROL:

EPA ID: NYD980763841
Site ID: 0202229
Name: HUDSON RIVER PCBS
Action Name: RECORD OF DECISION
Address: NO STREET APPLICABLE
HUDSON RIVER, NY 12801

EPA Region: 02
County: WASHINGTON
Event Code: Not reported
Inst. Control: Fishing Advisory
Actual Date: 12/30/2001
Comple. Date: 02/01/2002
Operable Unit: 02
Contaminated Media : Surface Water

CONSENT:

EPA ID: NYD980763841
Site ID: 0284
Case Title: U.S.V. GENERAL ELECTRIC COMPANY (HUDSON RIVER) (EPA-SUPERFUND)
Court Num: 05-1270
District: New York, North

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Entered Date: 11/02/06
Full-text of the consent decree for this site issued by the United States District Court is available from EDR. Contact your EDR Account Executive.

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

SPILLS:

Facility ID: 0308107
Facility Type: ER
DER Facility ID: 278391
Site ID: 237813
DEC Region: 3
Spill Date: 10/31/2003
Spill Number/Closed Date: 0308107 / 10/31/2003
Spill Cause: Abandoned Drums
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 6000
Investigator: rxamato
Referred To: Not reported
Reported to Dept: 10/31/2003
CID: 297
Water Affected: HUDSON RIVER
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/31/2003
Spill Record Last Update: 11/6/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller Company: 001
Contact Name: PETTY OFFICER HAWKINS
Contact Phone: (718) 354-4121
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SMITH"10/31/03: MEG hired by USCG to remove test and dispose.

Container did not leak.
Remarks: CALL TO NRC REPORTING A 55 GALLON DRUM OF UNKNOWN PETROLEUM FLOATING - USCG IS REPOSNDING TO THE SITE

Material:

Site ID: 237813
Operable Unit ID: 874400
Operable Unit: 01
Material ID: 501630
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON RIVER PCBS (Continued)

1000384273

Material FA: Petroleum
Quantity: 55
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

PRP:

PRP name: DELAWARE AND HUDSON RAILWAY CO INC
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GENERAL ELECTRIC COMPANY
GOLUB PROPERTIES OF WATERVLIET INC
NEW YORK STATE CANAL CORPORATION
NIAGARA MOHAWK POWER COMPANY
TOWN OF HALFMOON NEW YORK
VILLAGE OF STILLWATER
WATER COMMISSIONERS OF THE TOWN OF WATERFORD

A4
SW
< 1/8
0.019 mi.
100 ft.
CON EDISON
427 W.42 ST
NEW YORK, NY 10036
Site 4 of 8 in cluster A

NY MANIFEST **S112210642**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268280
Country: USA

Actual:
32 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268280

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210642

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457021JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268280
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457021JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210642

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

A5
South
< 1/8
0.020 mi.
107 ft.

THEATER ROW
410 WEST 42ND STREET
NEW YORK, NY

NY Spills S104788997
N/A

Site 5 of 8 in cluster A

Relative:
Higher

Actual:
33 ft.

SPILLS:

Facility ID: 0006482
Facility Type: ER
DER Facility ID: 185474
Site ID: 224410
DEC Region: 2
Spill Date: 8/20/2000
Spill Number/Closed Date: 0006482 / 11/29/2002
Spill Cause: Housekeeping
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS:

Investigator: 3101
Referred To: SIGONA
Reported to Dept: Not reported
CID: 8/31/2000
Water Affected: 390
Spill Source: Not reported
Spill Notifier: Unknown
Cleanup Ceased: Local Agency
Cleanup Meets Std: Not reported
Last Inspection: False
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/31/2000
Spill Record Last Update: 3/13/2003
Spiller Name: RICH MURPHY
Spiller Company: DYER AVENUE ASSOCIATES
Spiller Address: 400 WEST 59TH STREET
Spiller City,St,Zip: NEW YORK, NY 10019-
Spiller Company: 001
Contact Name: RICH MURPHY
Contact Phone: (212) 896-5515
DEC Memo: Not reported
Remarks: In May-June 2000, excavation began to construct a foundation at the site for new theaters. Approximately 10,000 tons of petroleum contaminated soils were excavated and disposed at Carterett Bio-Cycle during July 2000.

Material:

Site ID: 224410
Operable Unit ID: 829312
Operable Unit: 01
Material ID: 547598
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THEATER ROW (Continued)

S104788997

Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**A6
SW
< 1/8
0.021 mi.
111 ft.**

**PLAYWRIGHT'S HORIZONS
416 WEST 42ND STREET
NEW YORK, NY 10036**

**NY UST U004047991
N/A**

Site 6 of 8 in cluster A

**Relative:
Higher**

UST:
Id/Status: 2-607316 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 01/16/2007
UTM X: 584970.1931399999
UTM Y: 4512453.5105900001
Site Type: Other

**Actual:
32 ft.**

Affiliation Records:
Site Id: 29169
Affiliation Type: Facility Owner
Company Name: PLAYWRIGHTS HORIZON, INC.
Contact Type: CONTROLLER
Contact Name: DANIEL C. SMITH
Address1: 416 WEST 42ND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 564-1235
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 5/15/2007

Site Id: 29169
Affiliation Type: Mail Contact
Company Name: PLAYWRIGHTS HORIZONS
Contact Type: Not reported
Contact Name: CHRISTOPHER BOLL
Address1: 416 W 42ND ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 564-1235
EMail: CBOLL@PLAYWRIGHTSHORIZONS.ORG
Fax Number: Not reported
Modified By: DXLIVING

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PLAYWRIGHT'S HORIZONS (Continued)

U004047991

Date Last Modified: 5/15/2007

Site Id: 29169
Affiliation Type: On-Site Operator
Company Name: PLAYWRIGHTS HORIZONS
Contact Type: Not reported
Contact Name: CHRISTOPHER BOLL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 564-1235
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 5/15/2007

Site Id: 29169
Affiliation Type: Emergency Contact
Company Name: PLAYWRIGHTS HORIZON, INC.
Contact Type: Not reported
Contact Name: CHRISTOPHER BOLL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 564-1235
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 5/15/2007

Tank Info:

Tank Number: 001
Tank ID: 62726
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: Not reported
Date Tank Closed: 01/20/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DXLIVING
Last Modified: 05/15/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PLAYWRIGHT'S HORIZONS (Continued)

U004047991

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
I00 - Overfill - None

A7 **42ND STREET THEATRE ROW**
WSW **420 WEST 42ND STREET**
< 1/8 **NEW YORK, NY 10019**
0.022 mi.
117 ft. **Site 7 of 8 in cluster A**

NY UST **U004078014**
 N/A

Relative:
Higher

UST:

Actual:
32 ft.

Id/Status: 2-364290 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/15/2016
UTM X: 584952.43394000002
UTM Y: 4512466.64353
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18458
Affiliation Type: Facility Owner
Company Name: 420 WEST 42ND STREET, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 400 WEST 59TH STREET, 3RD FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Site Id: 18458
Affiliation Type: Mail Contact
Company Name: URBAN ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: PETER PERACCHI
Address1: 400 WEST 59TH STREET
Address2: 3RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (312) 315-5555

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

42ND STREET THEATRE ROW (Continued)

U004078014

Email: PPERACCHIO@BRODSKYORG.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Site Id: 18458
Affiliation Type: On-Site Operator
Company Name: 42ND STREET THEATRE ROW
Contact Type: Not reported
Contact Name: FRED LUMAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 290-9586
Email: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/30/2011

Site Id: 18458
Affiliation Type: Emergency Contact
Company Name: 420 WEST 42ND STREET, LLC
Contact Type: Not reported
Contact Name: PETER PERACCHIO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 896-5518
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Tank Info:

Tank Number: 001
Tank ID: 22550
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1977
Date Tank Closed: 01/01/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 14
Date Test: 09/01/1998
Next Test Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

42ND STREET THEATRE ROW (Continued)

U004078014

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B07 - Tank External Protection - Retrofitted Sacrificial Anode
H00 - Tank Leak Detection - None
G07 - Tank Secondary Containment - Excavation Liner

A8
WSW
< 1/8
0.022 mi.
117 ft.

42ND STREET THEATRE ROW
420 WEST 42ND STREET
NEW YORK, NY 10019
Site 8 of 8 in cluster A

NY AST **A100292353**
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-364290
Program Type: PBS
UTM X: 584952.43394000002
UTM Y: 4512466.64353
Expiration Date: 10/15/2016
Site Type: Apartment Building/Office Building

Actual:
32 ft.

Affiliation Records:

Site Id: 18458
Affiliation Type: Facility Owner
Company Name: 420 WEST 42ND STREET, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 400 WEST 59TH STREET, 3RD FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Site Id: 18458
Affiliation Type: Mail Contact
Company Name: URBAN ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: PETER PERACCHI
Address1: 400 WEST 59TH STREET
Address2: 3RD FLOOR
City: NEW YORK
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

42ND STREET THEATRE ROW (Continued)

A100292353

Zip Code: 10019
Country Code: 001
Phone: (312) 315-5555
EMail: PPERACCHIO@BRODSKYORG.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Site Id: 18458
Affiliation Type: On-Site Operator
Company Name: 42ND STREET THEATRE ROW
Contact Type: Not reported
Contact Name: FRED LUMAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 290-9586
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/30/2011

Site Id: 18458
Affiliation Type: Emergency Contact
Company Name: 420 WEST 42ND STREET, LLC
Contact Type: Not reported
Contact Name: PETER PERACCHIO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 896-5518
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/17/2014

Tank Info:

Tank Number: 01
Tank Id: 65434
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

42ND STREET THEATRE ROW (Continued)

A100292353

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/2002
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/17/2014
Material Name: #4 Fuel Oil (On-Site Consumption)

B9
SSE
< 1/8
0.028 mi.
146 ft.

LOT 138,TAXBLOCK 1051
406 WEST 42 STREET
MANHATTAN, NY 10036

Site 1 of 21 in cluster B

NY E DESIGNATION **S108075848**
N/A

Relative:
Higher

E DESIGNATION:
Tax Lot(s): 138
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported

Actual:
33 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 138,TAXBLOCK 1051 (Continued)

S108075848

Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000001601
Total Building Floor Area: 00000003393
Commercial Floor Area: 00000003393
Office Floor Area: 00000003393
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code:7
Number of Buildings: 00001
Number of Floors: 003.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0020.33
Lot Depth: 0078.75
Building Frontage: 0020.00
Building Depth: 0036.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000077850
Total Assessed Value: 00000170100
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.12
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510138
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986135
Y Coordinate: 0215620
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 138
E-No: E-137

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 138,TAXBLOCK 1051 (Continued)

S108075848

Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000001601
Total Building Floor Area: 00000003393
Commercial Floor Area: 00000003393
Office Floor Area: 00000003393
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 003.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0020.33
Lot Depth: 0078.75
Building Frontage: 0020.00
Building Depth: 0036.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000077850
Total Assessed Value: 00000170100
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 138,TAXBLOCK 1051 (Continued)

S108075848

Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.12
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510138
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986135
Y Coordinate: 0215620
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

C10 **DYER AVENUE ASSOCIATES, LLC**
West **424 W. 42ND STREET**
< 1/8 **NEW YORK, NY 10036**
0.030 mi.
160 ft. **Site 1 of 9 in cluster C**

NY UST **U003749702**
NY HIST UST **N/A**

Relative: **UST:**
Lower Id/Status: 2-604623 / Unregulated/Closed
Program Type: PBS
Actual: Region: STATE
31 ft. DEC Region: 2
Expiration Date: 07/14/2005
UTM X: 584978.69995000004
UTM Y: 4512479.7575700004
Site Type: Other

Affiliation Records:
Site Id: 26494
Affiliation Type: Facility Owner
Company Name: SAL PANICO
Contact Type: Not reported
Contact Name: Not reported
Address1: 400 WEST 59TH ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 315-5555
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DYER AVENUE ASSOCIATES, LLC (Continued)

U003749702

Date Last Modified: 8/11/2004

Site Id: 26494
Affiliation Type: Mail Contact
Company Name: BOVIS LEND LEASE
Contact Type: Not reported
Contact Name: FRANK STEPHAN
Address1: 400 WEST 59TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 845-6815
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 26494
Affiliation Type: On-Site Operator
Company Name: DYER AVENUE ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: BREEZE NAT. INC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 845-6815
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 26494
Affiliation Type: Emergency Contact
Company Name: SAL PANICO
Contact Type: Not reported
Contact Name: TOBY ROMANO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 266-7336
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 01
Tank ID: 58372

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DYER AVENUE ASSOCIATES, LLC (Continued)

U003749702

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 05/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-604623
SPDES Number: Not reported
Emergency Contact: TOBY ROMANO
Emergency Telephone: (718) 266-7336
Operator: BREEZE NAT. INC
Operator Telephone: (212) 845-6815
Owner Name: SAL PANICO
Owner Address: 400 WEST 59TH ST.
Owner City,St,Zip: NEW YORK, NY 10019
Owner Telephone: (212) 315-5555
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: BOVIS LEND LEASE
Mailing Address: 400 WEST 59TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10019
Mailing Contact: FRANK STEPHAN
Mailing Telephone: (212) 845-6815
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)
and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DYER AVENUE ASSOCIATES, LLC (Continued)

U003749702

Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: Not reported
Expiration Date: 07/14/2005
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: Major Data Missing (which is on the certificate)
Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 01
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 05/01/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

B11
SSE
< 1/8
0.037 mi.
193 ft.

CON EDISON SERVICE BOX: 8106
402 W 42ND ST
NEW YORK, NY 10036
Site 2 of 21 in cluster B

RCRA-CESQG 1016144047
FINDS NYP004268348

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 8106
Facility address: 402 W 42ND ST
NEW YORK, NY 10036
EPA ID: NYP004268348
Mailing address: IRVING PL, RM 828

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8106 (Continued)

1016144047

NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428176

Environmental Interest/Information System

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

B12
SSE
< 1/8
0.037 mi.
193 ft.

CON EDISON
402 W 42ND ST
NEW YORK, NY 10036

Site 3 of 21 in cluster B

NY MANIFEST **S112210648**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268348
Country: USA

Actual:
34 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268348
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457022JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210648

Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268348
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457022JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

C13
West
< 1/8
0.037 mi.
197 ft.

CON EDISON
425 W 42ND ST
NEW YORK, NY 10001

RCRA-CESQG **1012185888**
NYP004167235

Relative:
Lower

RCRA-CESQG:

Actual:
31 ft.

Date form received by agency: 04/14/2009
Facility name: CON EDISON
Facility address: 425 W 42ND ST
NEW YORK, NY 10001
EPA ID: NYP004167235
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS MICHAELIDES
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 204-4297
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185888

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

D14
ESE
< 1/8
0.038 mi.
198 ft.

**CONSOLIDATED EDISON
595 9TH AVE
NEW YORK, NY 10020**

**NY MANIFEST S109825587
N/A**

Site 1 of 2 in cluster D

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004174868
Country: USA

**Actual:
34 ft.**

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-23
Trans1 Recv Date: 2009-06-23
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004174868
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109825587

Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000961237GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-23
Trans1 Recv Date: 2009-06-23
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004174868
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000961237GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109825587

Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-23
Trans1 Recv Date: 2009-06-23
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004174868
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000961237GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

E15
NE
< 1/8
0.038 mi.
199 ft.

417 W 43RD STREET
417 W 43 RD ST
NY, NY 10036
Site 1 of 2 in cluster E

NY AST A100153902
N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-237566
Program Type: PBS
UTM X: 585066.03393000003
UTM Y: 4512542.37653
Expiration Date: 08/24/2014
Site Type: Apartment Building/Office Building

Actual:
33 ft.

Affiliation Records:
Site Id: 8858
Affiliation Type: Facility Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

417 W 43RD STREET (Continued)

A100153902

Company Name: NINTH AVENUE REALTY. LLC.
Contact Type: AGENT
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL AVE
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 997-2435
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/17/2009

Site Id: 8858
Affiliation Type: Mail Contact
Company Name: BEACH LANE MGT.,LLC.
Contact Type: Not reported
Contact Name: NINTH AVENUE REALTY. LLC.
Address1: 111 NORTH CENTRAL AVE. SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 577-8800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/17/2009

Site Id: 8858
Affiliation Type: On-Site Operator
Company Name: 417 W 43RD STREET
Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/17/2009

Site Id: 8858
Affiliation Type: Emergency Contact
Company Name: NINTH AVENUE REALTY. LLC.
Contact Type: Not reported
Contact Name: BERNARD DE CHALUS
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

417 W 43RD STREET (Continued)

A100153902

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 438-7019
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 9/8/2004

Tank Info:

Tank Number: 001
Tank Id: 17277
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1986
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 09/17/2009
Material Name: #2 Fuel Oil (On-Site Consumption)

D16
ESE
< 1/8
0.038 mi.
202 ft.

588 9TH AVENUE
588 9TH AVENUE
MANHATTAN, NY
Site 2 of 2 in cluster D

NY Spills **S102147423**
N/A

Relative:
Higher

SPILLS:
Facility ID: 9311040
Facility Type: ER
DER Facility ID: 62093
Site ID: 64432
DEC Region: 2
Spill Date: 12/11/1993

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

588 9TH AVENUE (Continued)

S102147423

Spill Number/Closed Date: 9311040 / 12/13/1993
Spill Cause: Deliberate
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 12/11/1993
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Fire Department
Cleanup Ceased: 12/13/1993
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/16/1993
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"
Remarks: SOMEONE POURED OIL IN SEWER. MAN FD ON SCENE - OPENING HYDRANT TO
FLUSH.

Material:
Site ID: 64432
Operable Unit ID: 992922
Operable Unit: 01
Material ID: 390100
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

B17
SE
< 1/8
0.040 mi.
211 ft.

MH 39875
584 9TH AVE
MANHATTAN, NY
Site 4 of 21 in cluster B

NY Spills **S104654299**
N/A

Relative:
Higher

Actual:
34 ft.

SPILLS:

Facility ID: 0004083
Facility Type: ER
DER Facility ID: 246617
Site ID: 305291
DEC Region: 2
Spill Date: 7/5/2000
Spill Number/Closed Date: 0004083 / 4/2/2004
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: JHOCONE
Referred To: Not reported
Reported to Dept: 7/5/2000
CID: 396
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/5/2000
Spill Record Last Update: 4/9/2004
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller Company: 001
Contact Name: TONY LOPEZ
Contact Phone: (212) 580-6763
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Con Ed e2mis Notes:7/5/00 10gal unknown oil on top of 100gal water in manhole. There is a sewer connection. Cannot be determined if any oil entered the sewer. PCB count returned <1ppm. Liquids removed by <50ppm tanker. Hole cleaned with degreaser.Underground South Supervisor S. Falkowski verified that the strucutre is oil free and the cable ends are sealed as of October 10, 2003.

Remarks: 10 gal on 100 gal of water. invest. underway. clean up pending test results.

Material:

Site ID: 305291
Operable Unit ID: 825315
Operable Unit: 01
Material ID: 548834
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MH 39875 (Continued)

S104654299

Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**B18
SE
< 1/8
0.040 mi.
211 ft.**

**CON EDISON
584 9TH AVE & 42ND ST FO
NEW YORK, NY 10112**

RCRA NonGen / NLR

**1014398133
NYP004204848**

Site 5 of 21 in cluster B

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
34 ft.**

Date form received by agency: 03/28/2010
Facility name: CON EDISON
Facility address: 584 9TH AVE & 42ND ST FO
NEW YORK, NY 10112
EPA ID: NYP004204848
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL BETO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (917) 337-5519
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

B19
SSE
< 1/8
0.040 mi.
213 ft.

IFO 400 W42ND ST
IFO 400 W. 42ND ST
MANHATTAN, NY
Site 6 of 21 in cluster B

NY Spills S105235209
N/A

Relative:
Higher

SPILLS:

Facility ID: 0010988
Facility Type: ER
DER Facility ID: 141638
Site ID: 168121
DEC Region: 2
Spill Date: 1/8/2001
Spill Number/Closed Date: 0010988 / 6/13/2003
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 1/8/2001
CID: 323
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/8/2001
Spill Record Last Update: 6/16/2003
Spiller Name: SAME
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: SCHLAGEL
Contact Phone: (212) 580-6763
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY"E2MIS 135013On 01/08/01 at 06:30 J. Pirrello #12120 crew chief of cable gang found that cable truck # 60582 was leaking hydraulic fluid. He discovered this at 400 W. 42 St. and it had started leaking at the S/W/C of W. 41 St. & 9 Ave at that time the entire length of the spill was barricaded & contained to the street with no sewers or waterways affected. At that time a cleanup was started, Mr. Pirrello will notify when cleanup is complete. The total amount of spill is 7 gallons. The cleanup people were George Rosario # 11464, Joe Rotondi # 11602, Joe Napolitano # 19711 al of the cable gang. Mr. Pirrello has contacted transportation & they are on the way.This call came in on 01/08/01 at 06:34 and at this time there in no more hydraulic fluid leaking from the truck. This job was reported to CIG M. Schlagel # 18276 at07:24 before it was logged into E2MIS because of a computer problem which was verified by Brian Keegan of the Con- Ed help desk& was logged in at 10:4501/08/01 at 08:36 J. Pirrello reports that the cleanup is complete. R. Bruns # 2110612/19/2002A review of the Transportaion Department records shows that the repair of the hydraulic leak on vehicle 60582 was completed 1/18/2001.

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IFO 400 W42ND ST (Continued)

S105235209

Remarks: FAULTY FILTER, CLEAN UP IN PROGRESS. TRUCK # 60582.

Material:

Site ID: 168121

Operable Unit ID: 832379

Operable Unit: 01

Material ID: 544849

Material Code: 0010

Material Name: Hydraulic Oil

Case No.: Not reported

Material FA: Petroleum

Quantity: 7

Units: Gallons

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

B20
SE
< 1/8
0.041 mi.
215 ft.

CON EDISON MANHOLE: 39875
584 9TH AVE
NEW YORK, NY 10036

RCRA-CESQG 1016143310
NYP004260477

Site 7 of 21 in cluster B

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 07/30/2012
Facility name: CON EDISON MANHOLE: 39875
Facility address: 584 9TH AVE

Actual:
34 ft.

NEW YORK, NY 10036
EPA ID: NYP004260477
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: RICARDO CARTY
Contact address: Not reported

Not reported
Contact country: Not reported
Contact telephone: (212) 643-3044

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 39875 (Continued)

1016143310

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

B21
SE
< 1/8
0.041 mi.
219 ft.

400 W 42ND ST
NEW YORK, NY 10036
Site 8 of 21 in cluster B

EDR US Hist Cleaners 1015054573
N/A

Relative:
Higher

EDR Historical Cleaners:
Name: 42 TIMES CLEANERS & TAILORS
Year: 2007
Address: 400 W 42ND ST

Actual:
34 ft.

F22
North
< 1/8
0.042 mi.
223 ft.

APARTMENT BLDG
435 W 43RD DT
MANHATTAN, NY
Site 1 of 6 in cluster F

NY Spills S105142325
N/A

Relative:
Higher

SPILLS:
Facility ID: 0106458
Facility Type: ER
DER Facility ID: 253245
Site ID: 314087
DEC Region: 2
Spill Date: 9/20/2001
Spill Number/Closed Date: 0106458 / 9/28/2001
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 9/20/2001
CID: 390
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False

Actual:
32 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BLDG (Continued)

S105142325

Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/20/2001
Spill Record Last Update: 9/28/2001
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: UNK
Spiller City,St,Zip: UNK, ZZ
Spiller Company: 001
Contact Name: BEACH LANE MGMT
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"GHIOSAY"SEPT. 28, 2001 LOCATION WAS INSPECTED AND FOUND TO BE CLEAN.
NFA.T. GHIOSAY
Remarks: caller reports when tank is filled - each time oil is spilled - they
don't clean it up - it happens all the time - apparently there is a
problem there because this is the only bldg that spills the oil
Material:
Site ID: 314087
Operable Unit ID: 843370
Operable Unit: 01
Material ID: 531313
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**B23
SE
< 1/8
0.042 mi.
223 ft.**

**MANHOLE #56655
C64E W 42 ST / 9TH AVE
MANHATTAN, NY**

**NY Spills S106126763
N/A**

Site 9 of 21 in cluster B

**Relative:
Higher**

SPILLS:

**Actual:
34 ft.**

Facility ID: 0310144
Facility Type: ER
DER Facility ID: 220311
Site ID: 270594
DEC Region: 2
Spill Date: 12/1/2003
Spill Number/Closed Date: 0310144 / 2/3/2004
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #56655 (Continued)

S106126763

Reported to Dept: 12/1/2003
CID: 73
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: Not reported
Spill Record Last Update: 2/3/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: MICHAEL DAUGHTREY
Contact Phone: (212) 580-8383
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"E2MIS 15131012-1-03 @ 03:30R Pecoraro # 44162 reports that while doing dead cable work in m56655 c/o w 42 st 64' e/o 9 av, he discovered 1 gallon of unknown green oil ontop of 200 gallons of water in the structure. No smoke or fire was or is involved. No sewer or waterway affected. No injuries and weather had no affect. Account # 42224 is being used for this incident. No measuring device was used to determine the amount of the spill. Source and cause of spill are unknown. No private property affected. Environmetal yellow tag # 41027 was applied. Water is standing , no visual water movement. No sewer connection as per conduit plate 26-e-4. Sump not verified.No substantial cracks. No dielectric filled feeder. Access anytime. 2 liquid samples were taken by R Pecoraro # 44162 from the spill, 1 for id and 1 for pcb. Sample priority "E". Chain of custody # cc16680. Cleanup is going to be scheduled for 12-01-03 @ 23:00 due to the location of the structure .Update 12/03/03Analysis indicate substance similar to petrolatum filling. Cleanup completed 12/3/03. Source of spill could not be located.
Remarks: CLEAN UP WON'T BEGIN UNTIL APPROX 23:00 DUE TO VEHICLES PARKED NEAR SITE.CALLER ANSWERED NO TO ALL 5 QUESTIONS ON THE CONED OFF-HOUR REPORTING FORM.
Material:
Site ID: 270594
Operable Unit ID: 875232
Operable Unit: 01
Material ID: 499081
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #56655 (Continued)

S106126763

Tank Test:

**B24
SE
< 1/8
0.042 mi.
224 ft.**

**CON EDISON SERVICE BOX: 8120
W 42ND ST & 9TH AVE
NEW YORK, NY 10036**

RCRA-CESQG

**1016144033
NYP004268207**

Site 10 of 21 in cluster B

**Relative:
Higher**

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8120

Facility address: W 42ND ST & 9TH AVE
NEW YORK, NY 10036

EPA ID: NYP004268207

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8120 (Continued)

1016144033

Violation Status: No violations found

**B25
SE
< 1/8
0.042 mi.
224 ft.**

**582 9TH AVE
NEW YORK, NY 10036**

**EDR US Hist Auto Stat 1015561057
N/A**

Site 11 of 21 in cluster B

**Relative:
Higher**

EDR Historical Auto Stations:

Name: CAR TOWING 24 HOUR
Year: 2010

**Actual:
34 ft.**

Address: 582 9TH AVE

Name: CAR TOW TWENTY FOUR HR
Year: 2011
Address: 582 9TH AVE

**F26
North
< 1/8
0.043 mi.
226 ft.**

**CON EDISON SERVICE BOX: 8323
434 W 43RD ST
NEW YORK, NY 10036**

**RCRA-CESQG 1016144042
FINDS NYP004268298**

Site 2 of 6 in cluster F

**Relative:
Higher**

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8323

**Actual:
32 ft.**

Facility address: 434 W 43RD ST
NEW YORK, NY 10036

EPA ID: NYP004268298

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8323 (Continued)

1016144042

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428158

Environmental Interest/Information System

F27
North
< 1/8
0.043 mi.
226 ft.

CON EDISON
434 W 43RD ST
NEW YORK, NY 10036

NY MANIFEST **S112210643**
N/A

Site 3 of 6 in cluster F

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268298
Country: USA

Actual:
32 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268298
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210643

Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457020JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268298
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457020JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

C28
West
< 1/8
0.043 mi.
227 ft.

CON EDISON SERVICE BOX: 8103
427 W 42ND ST
NEW YORK, NY 10036
Site 3 of 9 in cluster C

RCRA-CESQG
FINDS

1016144041
NYP004268280

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8103

Facility address: 427 W 42ND ST

NEW YORK, NY 10036

EPA ID: NYP004268280

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458883

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8103 (Continued)

1016144041

Environmental Interest/Information System

C29
West
< 1/8
0.044 mi.
232 ft.

MANHOLE #56659
W 42ND ST & DYER AVE
MANHATTAN, NY
Site 4 of 9 in cluster C

NY Spills S103936629
N/A

Relative:
Lower

Actual:
30 ft.

SPILLS:

Facility ID: 9900983
Facility Type: ER
DER Facility ID: 158812
Site ID: 190384
DEC Region: 2
Spill Date: 4/26/1999
Spill Number/Closed Date: 9900983 / 5/11/1999
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS:

Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 4/26/1999
CID: 257
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/26/1999
Spill Record Last Update: 6/14/2000
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: RICHARD ROACH
Contact Phone: (212) 580-6764
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"O'CONNELL"DEC INSPECTOR NOTES:LEAK ON A FEEDER - 1 GAL IN 4 GALS OF
WATER.con ed e2mis notes:Found 1 gallon of dielectric cable oil in
mh, c/o w. 42nd st opp/swc dyer ave...have 4 gallons of water. Leak
appears to have been caused by open ends. PCB 4ppm; Aroclor
1254.R.Valenzuela reports clean up complete in mh.Wastestream was
treated as >50 ppmRemoved 200 gals oil/water to >50 tanker.Double
washed and rinsed structure.Generated 2 drums solid debris - Taken to
chem waste via Corporate Transportation.Spill tag was left in place
pending receipt of lab report.4/28/99: spill tag was removed on
4/28/99 @ 9:00 hrs by K.Eckert (Splicer).
Remarks: LEAK ON A FEEDER - 1GAL IN 4GALS OF WATER - CLEANUP PENDING TEST
RESULTS CON ED REF #124444

Material:

Site ID: 190384

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #56659 (Continued)

S103936629

Operable Unit ID: 1079756
Operable Unit: 01
Material ID: 304524
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

C30
West
< 1/8
0.044 mi.
232 ft.

CONSTRUCTION SITE
WEST 42 /DIER AVE
MANHATTAN, NY

NY Spills

S107521741
N/A

Site 5 of 9 in cluster C

Relative:
Lower

SPILLS:

Facility ID: 0511511
Facility Type: ER
DER Facility ID: 307725
Site ID: 357681
DEC Region: 2
Spill Date: 1/5/2006
Spill Number/Closed Date: 0511511 / 1/5/2006
Spill Cause: Other
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 1/5/2006
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/5/2006
Spill Record Last Update: 1/5/2006
Spiller Name: ANDREW KELLY
Spiller Company: CONSTRUCTION SITE
Spiller Address: WEST 42 /DIER AVE
Spiller City,St,Zip: MANHATTEN, NY 001
Spiller Company: 001
Contact Name: ANDREW KELLY
Contact Phone: (718) 595-4761

Actual:
30 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107521741

DEC Memo: This was a formal spill call for a site Ryan Piper "unofficially" was asked to visit 2 days ago. At the time Ryan said the site was a typical construction site and the "green" water was actually clear water in a puddle with a greenish cement dust layer on the bottom of the puddle. No smell, no spill found. Closed

Remarks: AT THIS CONSTRUCTION SITE FOUND GREENISH WATER, UNSURE WHAT IT IS WOULD LIKE DEC TO LOOK AT

Material:

Site ID: 357681
Operable Unit ID: 1114954
Operable Unit: 01
Material ID: 2105014
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 357681
Operable Unit ID: 1114954
Operable Unit: 01
Material ID: 2105013
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

C31
West
< 1/8
0.044 mi.
232 ft.

MH56659
W 42ND ST&DYER AVE
MANHATTAN, NY
Site 6 of 9 in cluster C

NY Spills S105141817
N/A

Relative:
Lower

SPILLS:

Actual:
30 ft.

Facility ID: 0105665
Facility Type: ER
DER Facility ID: 138191
Site ID: 163856
DEC Region: 2
Spill Date: 8/26/2001
Spill Number/Closed Date: 0105665 / 3/17/2004
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: AERODRIG

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MH56659 (Continued)

S105141817

Referred To: Not reported
Reported to Dept: 8/26/2001
CID: 207
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/26/2001
Spill Record Last Update: 3/17/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: CHARLIE MCCARTHY
Contact Phone: (212) 580-6765
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"RODRIGUEZ"e2mis 1391288-26-01 @ 10:20 . C Hartage #18363 reports he discovered 2 oz. of an unknown oil that spilled on the concrete floor. source and cause of spill is unknown . No fire involved, no waterways or sewer affected. 2 samples were taken, 1 for id and 1 for pcb.Update 8-26-01 @ 10:50 . C Hartage #18363 reports that he discovered a leaking feeder in the structure.Lab Sequence #01-08560-001Total PCB = 8 ppmUPDATE 10/14/2001 @ 04:55 HRS#9 is on location repairing leaky cable(s).UPDATE 10/16/2001 @ 01:15 HRSSpoke to J. Selesky # 20525 and he informed me the cleanup was completed 10/16 @ 01:00 HRS. Three(3) ounces of oil was removed by Flush truck forces. The structure was Double-washed with " Slix." sample taken - cleanup for >50 ppm pcbcon ed # 1391282 oz unk oil

Remarks:

Material:

Site ID: 163856
Operable Unit ID: 844016
Operable Unit: 01
Material ID: 534121
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

F32
North
< 1/8
0.044 mi.
233 ft.

SPILL NUMBER 9815161
437 WEST 43RD ST
MANHATTAN, NY
Site 4 of 6 in cluster F

NY Spills **S104648724**
N/A

Relative:
Higher

Actual:
32 ft.

SPILLS:

Facility ID: 9815161
Facility Type: ER
DER Facility ID: 175740
Site ID: 212078
DEC Region: 2
Spill Date: 3/23/1999
Spill Number/Closed Date: 9815161 / 2/26/2003
Spill Cause: Housekeeping
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/23/1999
CID: 257
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/23/1999
Spill Record Last Update: 2/26/2003
Spiller Name: Not reported
Spiller Company: SUMMIT TRAN CORP
Spiller Address: Not reported
Spiller City,St,Zip: NJ
Spiller Company: 001
Contact Name: ROBERT ROMAN
Contact Phone: (212) 315-2626
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"SANGESLAND"Oil company cleaned up and moved vent line.

Remarks: caller says il company spills oil and it gets into air vent and the
hole building smells of oil - some might have gotten into sewer

Material:

Site ID: 212078
Operable Unit ID: 1073188
Operable Unit: 01
Material ID: 308280
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9815161 (Continued)

S104648724

Tank Test:

F33
North
< 1/8
0.045 mi.
235 ft.

NINTH AVENUE REALTY LLC
435 WEST 43 STREET
NEW YORK, NY 10036

NY AST **A100295279**
N/A

Site 5 of 6 in cluster F

Relative:
Higher

AST:

Actual:
32 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608345
Program Type: PBS
UTM X: 584987.51078999997
UTM Y: 4512555.5164700001
Expiration Date: 02/21/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30197
Affiliation Type: Facility Owner
Company Name: NINTH AVENUE REALTY LLC
Contact Type: AGENT
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE, SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/21/2009

Site Id: 30197
Affiliation Type: Mail Contact
Company Name: C/O NINTH AVENUE REALTY LLC
Contact Type: Not reported
Contact Name: BEACH LANE MGT.
Address1: 111 NORTH CENTRAL PARK AVE, SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: EMONROE@APTSNY.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/21/2013

Site Id: 30197
Affiliation Type: On-Site Operator
Company Name: NINTH AVENUE REALTY LLC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NINTH AVENUE REALTY LLC (Continued)

A100295279

Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/21/2013

Site Id: 30197
Affiliation Type: Emergency Contact
Company Name: NINTH AVENUE REALTY LLC
Contact Type: Not reported
Contact Name: DAN DUBROW
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 552-4131
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/21/2013

Tank Info:

Tank Number: 001
Tank Id: 65059
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Concrete
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1970
Capacity Gallons: 1500
Tightness Test Method: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NINTH AVENUE REALTY LLC (Continued)

A100295279

Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 02/21/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

C34 **LOT 49,TAXBLOCK 1051**
West **432 WEST 42 STREET**
< 1/8 **MANHATTAN, NY 10036**
0.045 mi.
238 ft. **Site 7 of 9 in cluster C**

NY E DESIGNATION **S108075996**
N/A

Relative:
Lower

E DESIGNATION:
Tax Lot(s): 49
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002469
Total Building Floor Area: 00000008645
Commercial Floor Area: 00000002069
Office Floor Area: 00000000000
Retail Floor Area: 00000002069
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 005.00

Actual:
30 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 49,TAXBLOCK 1051 (Continued)

S108075996

Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0025.00
Building Depth: 0065.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000235350
Total Assessed Value: 00000598500
Land Exempt Value: 00000235350
Total Exempt Value: 00000598500
Year Built: 1940
Year Built Code: E
Year Altered1: 1957
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.50
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510049
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985857
Y Coordinate: 0215775
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 49
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 49,TAXBLOCK 1051 (Continued)

S108075996

Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002469
Total Building Floor Area: 00000008645
Commercial Floor Area: 00000002069
Office Floor Area: 00000000000
Retail Floor Area: 00000002069
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 005.00
Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0025.00
Building Depth: 0065.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000235350
Total Assessed Value: 00000598500
Land Exempt Value: 00000235350
Total Exempt Value: 00000598500
Year Built: 1940
Year Built Code: E
Year Altered1: 1957
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.50
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510049
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985857
Y Coordinate: 0215775
Zoning Map: 08D

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 49,TAXBLOCK 1051 (Continued)

S108075996

Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

B35 **V9191**
SSE **583 9TH AVENUE**
< 1/8 **NEW YORK CITY, NY 10018**
0.046 mi.
243 ft.

RCRA NonGen / NLR **1007207093**
NY MANIFEST **NYP004037347**

Relative:
Higher

RCRA NonGen / NLR:

Actual:
34 ft.

Date form received by agency: 01/03/2001
Facility name: V9191
Facility address: 583 9TH AVENUE
NEW YORK CITY, NY 10018
EPA ID: NYP004037347
Mailing address: CONSOLIDATED EDISON INC.
4 IRVING PLACE -- ROOM 300
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC.
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/02/2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V9191 (Continued)

1007207093

Site name: V9191
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V9191
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004037347
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0233526
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/21/1999
Trans1 Recv Date: 05/21/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/21/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004037347
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: GX3216
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 03178
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 99

B36
SSE
< 1/8
0.046 mi.
243 ft.

SIDEWALK - VAULT 9536
583 9TH AVE
MANHATTAN, NY
Site 13 of 21 in cluster B

NY Spills **S110243561**
N/A

Relative:
Higher

SPILLS:
Facility ID: 0913539
Facility Type: ER
DER Facility ID: 375358
Site ID: 426489
DEC Region: 2
Spill Date: 3/23/2010
Spill Number/Closed Date: 0913539 / 5/26/2010

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIDEWALK - VAULT 9536 (Continued)

S110243561

Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: Con Ed Unassigned
Referred To: Not reported
Reported to Dept: 3/23/2010
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/23/2010
Spill Record Last Update: 5/26/2010
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: ERT
Contact Phone: (212) 580-8383
DEC Memo: 05/26/10 - See eDocs for Con Ed report detailing cleanup and closure.
Remarks: ON GOING LEAK - WILL GO OVER 5 GAL MARK - UNDERGROUND STRUCTURE -
CLEANUP PENDING

Material:
Site ID: 426489
Operable Unit ID: 1182168
Operable Unit: 01
Material ID: 2176324
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C37
West
< 1/8
0.048 mi.
253 ft.

LOT 50,TAXBLOCK 1051
434 WEST 42 STREET
MANHATTAN, NY 10036

Site 8 of 9 in cluster C

NY E DESIGNATION **S108076006**
N/A

Relative:
Lower

E DESIGNATION:

Actual:
30 ft.

Tax Lot(s): 50
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K1
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002450
Total Building Floor Area: 00000000627
Commercial Floor Area: 00000000627
Office Floor Area: 00000000000
Retail Floor Area: 00000000627
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 001.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0019.00
Building Depth: 0033.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 50,TAXBLOCK 1051 (Continued)

S108076006

Basement Type Grade: 5
Land Assessed Value: 00000235350
Total Assessed Value: 00000301050
Land Exempt Value: 00000235350
Total Exempt Value: 00000301050
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.26
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510050
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985816
Y Coordinate: 0215751
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 50
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 50,TAXBLOCK 1051 (Continued)

S108076006

All Components2: Not reported
Split Boundary Indicator: N
Building Class: K1
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002450
Total Building Floor Area: 00000000627
Commercial Floor Area: 00000000627
Office Floor Area: 00000000000
Retail Floor Area: 00000000627
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 001.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0019.00
Building Depth: 0033.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000235350
Total Assessed Value: 00000301050
Land Exempt Value: 00000235350
Total Exempt Value: 00000301050
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.26
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510050
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985816
Y Coordinate: 0215751
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 50,TAXBLOCK 1051 (Continued)

S108076006

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**B38
SSE
< 1/8
0.049 mi.
257 ft.**

**581 9TH AVE
NEW YORK, NY 10036
Site 14 of 21 in cluster B**

**EDR US Hist Auto Stat 1015560661
N/A**

**Relative:
Higher**

EDR Historical Auto Stations:
Name: ENGINE RECORDINGS
Year: 2002
Address: 581 9TH AVE

**Actual:
34 ft.**

**B39
SSE
< 1/8
0.049 mi.
257 ft.**

**LOT 36,TAXBLOCK 1051
581 9 AVENUE
MANHATTAN, NY 10036
Site 15 of 21 in cluster B**

**NY E DESIGNATION S108075940
N/A**

**Relative:
Higher**

E DESIGNATION:
Tax Lot(s): 36
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: FISHMAN, BARBARA TRUS
Lot Area: 000003500
Total Building Floor Area: 00000007573
Commercial Floor Area: 00000007573

**Actual:
34 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 36,TAXBLOCK 1051 (Continued)

S108075940

Office Floor Area: 00000003773
Retail Floor Area: 00000003800
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00005
Lot Frontage: 0019.33
Lot Depth: 0079.67
Building Frontage: 0019.33
Building Depth: 0079.67
Proximity Code: 0
Irregular Lot Code: Y
Lot Type: 3
Basement Type Grade: 5
Land Assessed Value: 00001080000
Total Assessed Value: 00001350000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.16
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510036
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986146
Y Coordinate: 0215571
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 36
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 36,TAXBLOCK 1051 (Continued)

S108075940

Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: FISHMAN, BARBARA TRUS
Lot Area: 000003500
Total Building Floor Area: 00000007573
Commercial Floor Area: 00000007573
Office Floor Area: 00000003773
Retail Floor Area: 00000003800
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00005
Lot Frontage: 0019.33
Lot Depth: 0079.67
Building Frontage: 0019.33
Building Depth: 0079.67
Proximity Code: 0
Irregular Lot Code: Y
Lot Type: 3
Basement Type Grade: 5
Land Assessed Value: 00001080000
Total Assessed Value: 00001350000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 36,TAXBLOCK 1051 (Continued)

S108075940

Built Floor Area Ratio-Far: 0002.16
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510036
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986146
Y Coordinate: 0215571
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

E40
ENE
< 1/8
0.049 mi.
260 ft.

MANHATTAN PLAZA
400 WEST 43RD STREET
NEW YORK, NY 10036
Site 2 of 2 in cluster E

NY UST **U001838193**
N/A

Relative:
Higher

UST:
Id/Status: 2-400041 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/15/2012
UTM X: 585098.808560000003
UTM Y: 4512511.33440000001
Site Type: Other

Actual:
34 ft.

Affiliation Records:
Site Id: 19072
Affiliation Type: Facility Owner
Company Name: MANHATTAN PLAZA ASSOC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 400 WEST 43RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 971-0682
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/19/2011

Site Id: 19072
Affiliation Type: Mail Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHATTAN PLAZA (Continued)

U001838193

Company Name: MANHATTAN PLAZA ASSOC.
Contact Type: Not reported
Contact Name: PETER HOYLE
Address1: RELATED MANAGEMENT
Address2: 400 WEST 43RD STREET
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 971-0682
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/19/2011

Site Id: 19072
Affiliation Type: On-Site Operator
Company Name: MANHATTAN PLAZA
Contact Type: Not reported
Contact Name: ROBERT KETLOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 698-6186
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/19/2011

Site Id: 19072
Affiliation Type: Emergency Contact
Company Name: MANHATTAN PLAZA ASSOC.
Contact Type: Not reported
Contact Name: ROBERT KELTON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 698-6186
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/19/2011

Tank Info:

Tank Number: 001
Tank ID: 24578
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: 12/01/1977

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHATTAN PLAZA (Continued)

U001838193

Date Tank Closed: 06/23/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 06/27/2007
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 07/19/2011

Equipment Records:

K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
C03 - Pipe Location - Aboveground/Underground Combination

B41
SSE
< 1/8
0.050 mi.
262 ft.

LOT 135,TAXBLOCK 1051
579 9 AVENUE
MANHATTAN, NY 10036

NY E DESIGNATION

S108075846
N/A

Site 16 of 21 in cluster B

Relative:
Higher

E DESIGNATION:

Tax Lot(s): 135
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 135,TAXBLOCK 1051 (Continued)

S108075846

Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: LEAGUE MUTUAL TAXI ET
Lot Area: 000000825
Total Building Floor Area: 00000002800
Commercial Floor Area: 00000002800
Office Floor Area: 00000002800
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0020.42
Lot Depth: 0040.42
Building Frontage: 0020.00
Building Depth: 0040.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000073350
Total Assessed Value: 00000112050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1920
Year Built Code: E
Year Altered1: 1980
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.39
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510135
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986180
Y Coordinate: 0215574
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 135,TAXBLOCK 1051 (Continued)

S108075846

Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 135
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: LEAGUE MUTUAL TAXI ET
Lot Area: 000000825
Total Building Floor Area: 00000002800
Commercial Floor Area: 00000002800
Office Floor Area: 00000002800
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0020.42
Lot Depth: 0040.42
Building Frontage: 0020.00
Building Depth: 0040.00
Proximity Code: 3
Irregular Lot Code: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 135,TAXBLOCK 1051 (Continued)

S108075846

Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000073350
Total Assessed Value: 00000112050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1920
Year Built Code: E
Year Altered1: 1980
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.39
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510135
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986180
Y Coordinate: 0215574
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

B42
SSE
< 1/8
0.050 mi.
265 ft.

CON EDISON
576 9TH AVE
NEW YORK, NY 10036
Site 17 of 21 in cluster B

NY MANIFEST **S112210626**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268124
Country: USA

Actual:
34 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210626

Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268124
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457006JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268124
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457006JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210626

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

B43
SSE
< 1/8
0.050 mi.
265 ft.

CON EDISON SERVICE BOX: 39866
576 9TH AVE
NEW YORK, NY 10036
Site 18 of 21 in cluster B

RCRA-CESQG 1016144025
FINDS NYP004268124

Relative:
Higher

RCRA-CESQG:

Actual:
34 ft.

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 39866
Facility address: 576 9TH AVE
NEW YORK, NY 10036
EPA ID: NYP004268124
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39866 (Continued)

1016144025

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055457928

Environmental Interest/Information System

B44
SSE
< 1/8
0.050 mi.
265 ft.

LOT 162,TAXBLOCK 1032
576 9 AVENUE
MANHATTAN, NY 10036
Site 19 of 21 in cluster B

NY E DESIGNATION S108075859
N/A

Relative:
Higher

E DESIGNATION:

Actual:
34 ft.

Tax Lot(s): 162
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: S2
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000001287
Total Building Floor Area: 00000005173
Commercial Floor Area: 00000002075
Office Floor Area: 00000000000
Retail Floor Area: 00000002075
Garage Floor Area: 00000000000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 162,TAXBLOCK 1032 (Continued)

S108075859

Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00002
Non and Residential Units: 00003
Lot Frontage: 0019.67
Lot Depth: 0065.00
Building Frontage: 0020.00
Building Depth: 0065.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000023310
Total Assessed Value: 00000079820
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1989
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0004.02
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320162
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986293
Y Coordinate: 0215475
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C45
West
< 1/8
0.051 mi.
268 ft.

LOT 51,TAXBLOCK 1051
436 WEST 42 STREET
MANHATTAN, NY 10036

Site 9 of 9 in cluster C

NY E DESIGNATION

S108076010
N/A

Relative:
Lower

E DESIGNATION:

Actual:
30 ft.

Tax Lot(s): 51
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002450
Total Building Floor Area: 00000006546
Commercial Floor Area: 00000001000
Office Floor Area: 00000000000
Retail Floor Area: 00000001000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 005.00
Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0025.00
Building Depth: 0053.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 51,TAXBLOCK 1051 (Continued)

S108076010

Basement Type Grade: 5
Land Assessed Value: 00000234000
Total Assessed Value: 00000327150
Land Exempt Value: 00000234000
Total Exempt Value: 00000327150
Year Built: 1910
Year Built Code: E
Year Altered1: 1958
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.67
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510051
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985813
Y Coordinate: 0215800
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 51
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 51,TAXBLOCK 1051 (Continued)

S108076010

All Components2: Not reported
Split Boundary Indicator: N
Building Class: K9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002450
Total Building Floor Area: 00000006546
Commercial Floor Area: 00000001000
Office Floor Area: 00000000000
Retail Floor Area: 00000001000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 005.00
Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0025.00
Building Depth: 0053.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000234000
Total Assessed Value: 00000327150
Land Exempt Value: 00000234000
Total Exempt Value: 00000327150
Year Built: 1910
Year Built Code: E
Year Altered1: 1958
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.67
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510051
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985813
Y Coordinate: 0215800
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 51,TAXBLOCK 1051 (Continued)

S108076010

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**B46
SSE
< 1/8
0.051 mi.
269 ft.**

**LOT 63,TAXBLOCK 1032
574 9 AVENUE
MANHATTAN, NY 10036
Site 20 of 21 in cluster B**

NY E DESIGNATION

**S108076067
N/A**

**Relative:
Higher**

E DESIGNATION:

**Actual:
34 ft.**

Tax Lot(s): 63
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: S5
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000001280
Total Building Floor Area: 00000004016
Commercial Floor Area: 00000001016
Office Floor Area: 00000000000
Retail Floor Area: 00000001016
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 004.00
Residential Units: 00006
Non and Residential Units: 00007
Lot Frontage: 0019.67
Lot Depth: 0065.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 63,TAXBLOCK 1032 (Continued)

S108076067

Building Frontage: 0020.00
Building Depth: 0049.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000043737
Total Assessed Value: 00000233766
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1990
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.14
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320063
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986313
Y Coordinate: 0215438
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

G47
ENE
< 1/8
0.052 mi.
275 ft.

CON EDISON MANHOLE: 39884
W 43RD ST & 9TH AVE NE COR
NEW YORK, NY 10036

RCRA-CESQG 1016144031
NYP004268181

Site 1 of 11 in cluster G

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/13/2012
Facility name: CON EDISON MANHOLE: 39884
Facility address: W 43RD ST & 9TH AVE NE COR
NEW YORK, NY 10036
EPA ID: NYP004268181
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 39884 (Continued)

1016144031

EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

G48
ENE
< 1/8
0.052 mi.
275 ft.

CON EDISON SERVICE BOX: 39873
W 43RD ST & 9TH AVE SW COR
NEW YORK, NY 10036

RCRA-CESQG 1016149075
NYP004277323

Site 2 of 11 in cluster G

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 11/08/2012
Facility name: CON EDISON SERVICE BOX: 39873
Facility address: W 43RD ST & 9TH AVE SW COR
NEW YORK, NY 10036

Actual:
34 ft.

EPA ID: NYP004277323
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39873 (Continued)

1016149075

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

G49
ENE
< 1/8
0.052 mi.
276 ft.

216163; W 43 ST AND 9 AVE
W 43 ST AND 9 AVE
NEW YORK, NY

Site 3 of 11 in cluster G

NY Spills S110307058
N/A

Relative:
Higher

SPILLS:

Facility ID: 0914117
Facility Type: ER
DER Facility ID: 387216
Site ID: 433208
DEC Region: 2
Spill Date: 3/28/2009
Spill Number/Closed Date: 0914117 / 4/2/2009
Spill Cause: Unknown
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Actual:
34 ft.

SWIS: 3101
Investigator: DMPOKRZY
Referred To: Not reported
Reported to Dept: 3/30/2009
CID: Not reported
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

216163; W 43 ST AND 9 AVE (Continued)

S110307058

Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/16/2010
Spill Record Last Update: 4/16/2010
Spiller Name: ERT DESK
Spiller Company: CON EDISON
Spiller Address: 5030 BROADWAY
Spiller City,St,Zip: New York, NY
Spiller Company: 001
Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Memo: Not reported
Remarks: Not reported

Material:
Site ID: 433208
Operable Unit ID: 1184119
Operable Unit: 01
Material ID: 2178354
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

G50
ENE
< 1/8
0.052 mi.
276 ft.

CON EDISON - MANHOLE 39880
NWC W 43 ST
NEW YORK, NY 10023
Site 4 of 11 in cluster G

RCRA-LQG **1012185695**
NYP004165288

Relative:
Higher

RCRA-LQG:
Date form received by agency: 03/23/2010
Facility name: CON EDISON - MANHOLE 39880
Facility address: NWC W 43 ST
NEW YORK, NY 10023
EPA ID: NYP004165288
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-2808
Contact email: MURRAYFR@CONED.COM

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 39880 (Continued)

1012185695

EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/28/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/28/2009
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 03/31/2009
Site name: CON EDISON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 39880 (Continued)

1012185695

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

**B51
SSE
< 1/8
0.052 mi.
277 ft.**

**LOT 35,TAXBLOCK 1051
577 9 AVENUE
MANHATTAN, NY 10036
Site 21 of 21 in cluster B**

**NY E DESIGNATION S108075937
N/A**

**Relative:
Higher**

E DESIGNATION:

**Actual:
34 ft.**

Tax Lot(s): 35
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: LEAGUE MUTUAL TAXI ET
Lot Area: 000000797
Total Building Floor Area: 00000003212
Commercial Floor Area: 00000003212
Office Floor Area: 00000003212
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 003.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 35,TAXBLOCK 1051 (Continued)

S108075937

Residential Units: 00000
Non and Residential Units: 00002
Lot Frontage: 0019.58
Lot Depth: 0040.42
Building Frontage: 0020.00
Building Depth: 0040.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000076950
Total Assessed Value: 00000129600
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1980
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0004.03
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510035
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986183
Y Coordinate: 0215545
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 35
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 35,TAXBLOCK 1051 (Continued)

S108075937

Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: LEAGUE MUTUAL TAXI ET
Lot Area: 000000797
Total Building Floor Area: 00000003212
Commercial Floor Area: 00000003212
Office Floor Area: 00000003212
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 003.00
Residential Units: 00000
Non and Residential Units: 00002
Lot Frontage: 0019.58
Lot Depth: 0040.42
Building Frontage: 0020.00
Building Depth: 0040.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000076950
Total Assessed Value: 00000129600
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1980
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0004.03
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510035
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986183
Y Coordinate: 0215545
Zoning Map: 08D

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 35,TAXBLOCK 1051 (Continued)

S108075937

Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

G52
ENE
< 1/8
0.053 mi.
279 ft.

SPILL NUMBER 9909864
43RD STREET & 9TH AVENUE
MANHATTAN, NY

NY Spills S104649936
N/A

Site 5 of 11 in cluster G

Relative:
Higher

SPILLS:

Facility ID: 9909864
Facility Type: ER
DER Facility ID: 241147
Site ID: 298052
DEC Region: 2
Spill Date: 11/15/1999
Spill Number/Closed Date: 9909864 / 2/3/2003
Spill Cause: Unknown
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Actual:
34 ft.

SWIS: 3101
Investigator: COMENALE
Referred To: Not reported
Reported to Dept: 11/15/1999
CID: 266
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/15/1999
Spill Record Last Update: 11/17/2004
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: e2mis no. 128980:11/15/99 0124 VINCENT MIRANCE #58484 CABLE OPERATIONS CREW CHIEF REPORTS ONE GALLON OF OIL (UNKNOWN TYPE) IN MANHOLE #60212 C/O W43RD ST 40' W/O 9TH AVE -- OIL IN MANHOLE NOT NEAR SUMP -- BLOCKED SUMP WITH SPILL KIT -- NO VISUAL MOVEMENT -- NO

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9909864 (Continued)

S104649936

Remarks:

SMOKE - NO FIRE -- VINCENT MIRANCE #58484 TOOK SAMPLE FOR ID AND PCB -- COUDUIT RECORDS NOT ON FILE -- FOUND OIL IN MANHOLE WHILE PULLING CABLE ON FEEDER 21M35-----CLEANUP PENDING TEST RESULTS--NO WATER IN MANHOLE RESULTS OF LAB ANALYSIS 99-11978, RECEIVED ON 11/15/99 @ 0536 HRS. AROCLOR 1254, PCB 5 PPM 12-02-99 Operating Supervisor J. velez reports clean up complete in MH - 60212 on 12-02-99 @ 04:40 hrs. 5. ppm PCB. No water found in structure. Cleaned oil found on floor and capped a cable end. Double washed & rinsed the structure. Generated 1 drum ppe. Removed Spill Tag #00741 upon completion. MANHOLE 60212. NO WATER. CONTAINED WITHIN MANHOLE. SAMPLES TAKEN. CLEAN UP PENDING TEST RESULTS. CON EDISON REFERENCE 128980.

Material:

Site ID: 298052
Operable Unit ID: 1084616
Operable Unit: 01
Material ID: 298931
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:

G53
ENE
< 1/8
0.053 mi.
279 ft.

MANHOLE 60213
WEST 43RD ST & 9TH AVE
MANHATTAN, NY

NY Spills S104195794
N/A

Site 6 of 11 in cluster G

Relative:
Higher

SPILLS:

Facility ID: 9907937
Facility Type: ER
DER Facility ID: 63094
Site ID: 65791
DEC Region: 2
Spill Date: 9/30/1999
Spill Number/Closed Date: 9907937 / 8/17/2000
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: COMENALE
Referred To: Not reported
Reported to Dept: 9/30/1999
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 60213 (Continued)

S104195794

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/30/1999
Spill Record Last Update: 1/12/2001
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"COMEENALE"e2MIS Notes:2 Quarts of oil and 60 gallons of water in
MH60213. PCBs <1ppm. Removed 1000 gallons oil/water to <50 tanker.
Used flush truck to clean and rinse structure.

Remarks: 2QT'S OIL ON 60 GALLONS WATER. CON ED #128132

Material:

Site ID: 65791
Operable Unit ID: 1086595
Operable Unit: 01
Material ID: 300621
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

H54
SSE
< 1/8
0.054 mi.
286 ft.

CON EDISON SERVICE BOX: 39865
572 9TH AVE
NEW YORK, NY 10036

RCRA-CESQG **1016144030**
FINDS **NYP004268173**

Site 1 of 11 in cluster H

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 39865
Facility address: 572 9TH AVE
NEW YORK, NY 10036

Actual:
34 ft.

EPA ID: NYP004268173
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported

Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported

EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39865 (Continued)

1016144030

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458801

Environmental Interest/Information System

H55
SSE
< 1/8
0.054 mi.
286 ft.

CON EDISON
572 9TH AVE
NEW YORK, NY 10036
Site 2 of 11 in cluster H

NY MANIFEST S112210631
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268173
Country: USA

Actual:
34 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210631

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268173
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457007JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268173
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210631

Year: 2012
Manifest Tracking Num: 010457007JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

H56
SSE
< 1/8
0.054 mi.
286 ft.

LOT 64,TAXBLOCK 1032
572 9 AVENUE
MANHATTAN, NY 10036
Site 3 of 11 in cluster H

NY E DESIGNATION S108076072
N/A

Relative:
Higher

E DESIGNATION:

Tax Lot(s): 64
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: S3
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: MINT REALTY, LLC
Lot Area: 000001280
Total Building Floor Area: 00000004013
Commercial Floor Area: 00000001013
Office Floor Area: 00000000000
Retail Floor Area: 00000001013
Garage Floor Area: 00000000000

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 64,TAXBLOCK 1032 (Continued)

S108076072

Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00003
Non and Residential Units: 00004
Lot Frontage: 0019.67
Lot Depth: 0065.00
Building Frontage: 0020.00
Building Depth: 0049.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000157500
Total Assessed Value: 00000243000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1926
Year Built Code: E
Year Altered1: 1986
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.14
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320064
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986274
Y Coordinate: 0215440
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

H57
SSE
< 1/8
0.055 mi.
290 ft.

LOT 61,TAXBLOCK 1032
578 9 AVENUE
MANHATTAN, NY 10036
Site 4 of 11 in cluster H

NY E DESIGNATION

S108076054
N/A

Relative:
Higher

E DESIGNATION:

Actual:
34 ft.

Tax Lot(s): 61
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: H9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000004251
Total Building Floor Area: 00000013026
Commercial Floor Area: 00000013026
Office Floor Area: 00000000000
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000013026
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00005
Lot Frontage: 0039.67
Lot Depth: 0082.00
Building Frontage: 0039.00
Building Depth: 0082.00
Proximity Code: 2
Irregular Lot Code: Y
Lot Type: 3

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 61,TAXBLOCK 1032 (Continued)

S108076054

Basement Type Grade: 5
Land Assessed Value: 00000425700
Total Assessed Value: 00000526500
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1988
Year Built Code: Not reported
Year Altered1: 1989
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.06
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320061
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986329
Y Coordinate: 0215489
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

H58 **570 9TH AVENUE**
SSE **570 9TH AVENUE**
< 1/8 **NEW YORK, NY 10036**
0.057 mi.
303 ft. **Site 5 of 11 in cluster H**

NY AST **U003383959**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
34 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-070408
Program Type: PBS
UTM X: 585054.96773999999
UTM Y: 4512403.2521400005
Expiration Date: 09/30/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 1558
Affiliation Type: Facility Owner
Company Name: MOLLANEY LLC
Contact Type: MANAGING AGENT
Contact Name: SERGIO SPODEK
Address1: 570 NINTH AVENUE
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

570 9TH AVENUE (Continued)

U003383959

City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 348-5337
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 11/3/2011

Site Id: 1558
Affiliation Type: Mail Contact
Company Name: DMB PROPERTIES INC
Contact Type: Not reported
Contact Name: SERGIO SPODEK
Address1: 128 E 86ST #1FR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 348-5337
EMail: INFO@AOLMBPROPERTIES.COM
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 11/3/2011

Site Id: 1558
Affiliation Type: On-Site Operator
Company Name: 570 9TH AVENUE
Contact Type: Not reported
Contact Name: MOLLANEY LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-5790
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1558
Affiliation Type: Emergency Contact
Company Name: MOLLANEY LLC
Contact Type: Not reported
Contact Name: SERGIO SPODEK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 348-5337
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

570 9TH AVENUE (Continued)

U003383959

Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 11/3/2011

Tank Info:

Tank Number: 001
Tank Id: 2647
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1992
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 09/19/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-070408
SWIS Code: 6201
Operator: HARRY HOROWITZ
Facility Phone: (718) 748-5394
Facility Addr2: 570 9TH AVENUE
Facility Type: Not reported
Emergency: HARRY HOROWITZ
Emergency Tel: (718) 748-5394
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: BERGRO REALTY CORP
Owner Address: 8206 3RD AVENUE
Owner City,St,Zip: BROOKLYN, NY 11209

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

570 9TH AVENUE (Continued)

U003383959

Federal ID: Not reported
Owner Tel: (718) 748-5394
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: BERGRO REALTY CORP
Mailing Address: 8206 3RD AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11209
Mailing Telephone: (718) 748-5394
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/24/1996
Expiration: 01/14/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 00
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: None
Leak Detection: 3
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

H59
SSE
< 1/8
0.057 mi.
303 ft.

LOT 4,TAXBLOCK 1032
570 9 AVENUE
MANHATTAN, NY 10036
Site 6 of 11 in cluster H

NY E DESIGNATION

S108075954
N/A

Relative:
Higher

E DESIGNATION:

Actual:
34 ft.

Tax Lot(s): 4
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: S5
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: MOLLANEY LLC
Lot Area: 000001474
Total Building Floor Area: 00000004492
Commercial Floor Area: 00000001380
Office Floor Area: 00000000000
Retail Floor Area: 00000001380
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00006
Non and Residential Units: 00007
Lot Frontage: 0019.67
Lot Depth: 0075.00
Building Frontage: 0020.00
Building Depth: 0075.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 4,TAXBLOCK 1032 (Continued)

S108075954

Basement Type Grade: 5
Land Assessed Value: 00000045016
Total Assessed Value: 00000240084
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1983
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.05
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320004
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986295
Y Coordinate: 0215406
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

F60
NNW
< 1/8
0.058 mi.
304 ft.
447 9 WEST 43RD ST
447-9 WEST 43RD ST
NEW YORK, NY 10036
Site 6 of 6 in cluster F

NY AST
NY HIST AST
U003385160
N/A

Relative:
Lower

AST:

Actual:
31 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-097829
Program Type: PBS
UTM X: 584947.45859000005
UTM Y: 4512569.6924999999
Expiration Date: 05/14/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2815
Affiliation Type: Facility Owner
Company Name: NINTH AVENUE REALTY, LLC
Contact Type: OWNER
Contact Name: MARK SCHARFMAN
Address1: 111 N. CENTRAL PARK AVE. #400
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

447 9 WEST 43RD ST (Continued)

U003385160

City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2/22/2012

Site Id: 2815
Affiliation Type: Mail Contact
Company Name: NINTH AVENUE REALTY, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 111 N. CENTRAL PARK AVE.
Address2: #400
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: HANY@APTSNY.COM
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2/22/2012

Site Id: 2815
Affiliation Type: On-Site Operator
Company Name: NINTH AVENUE REALTY, LLC
Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2/22/2012

Site Id: 2815
Affiliation Type: Emergency Contact
Company Name: NINTH AVENUE REALTY, LLC
Contact Type: Not reported
Contact Name: BERNARD DA CHALUS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 438-7019
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

447 9 WEST 43RD ST (Continued)

U003385160

Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 1/29/2007

Tank Info:

Tank Number: 001
Tank Id: 5150
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/29/1939
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 01/29/2007
Material Name: #4 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-097829
SWIS Code: 6201
Operator: BRICK MGMT CORP
Facility Phone: (212) 789-1180
Facility Addr2: 447 9 WEST 43RD ST
Facility Type: APARTMENT BUILDING
Emergency: BRICK MGMT CORP
Emergency Tel: (212) 789-1180
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: EASTERN PORK PRODUCTS CO
Owner Address: 1133 AVE OF AMERICAS
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 789-1180
Owner Type: Corporate/Commercial

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

447 9 WEST 43RD ST (Continued)

U003385160

Owner Subtype: Not reported
Mailing Contact: MARTYN CORDERO
Mailing Name: ROYAL REALTY CORPORATION
Mailing Address: 1155 SIXTH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 789-1180
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/28/2000
Expiration: 08/24/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 4000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 4000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

G61
ENE
< 1/8
0.058 mi.
305 ft.
609 NINTH AVENUE
609 NINTH AVENUE
NEW YORK, NY 10036
Site 7 of 11 in cluster G

NY AST **U004045689**
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-329142
Program Type: PBS
UTM X: 585114.12113999994
UTM Y: 4512537.9331999999
Expiration Date: 01/07/1998
Site Type: Apartment Building/Office Building

Actual:
34 ft.

Affiliation Records:

Site Id: 15446
Affiliation Type: Facility Owner
Company Name: EASTERN PORK PRODUCTS
Contact Type: Not reported
Contact Name: Not reported
Address1: 1133 AVE OF AMERICAS
Address2: Not reported
City: NY
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 764-1133
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15446
Affiliation Type: Mail Contact
Company Name: ROYAL REALTY CORPORATION
Contact Type: Not reported
Contact Name: MARTYN CORDERO
Address1: 1155 SIXTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 789-1180
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15446
Affiliation Type: On-Site Operator
Company Name: 609 NINTH AVENUE
Contact Type: Not reported
Contact Name: BRICK MANAGEMENT CORP
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 NINTH AVENUE (Continued)

U004045689

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 789-1180
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15446
Affiliation Type: Emergency Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: WILFRED GOODING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 438-7001
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 3/23/2004

Tank Info:

Tank Number: 001
Tank Id: 25698
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 NINTH AVENUE (Continued)

U004045689

Material Name: #2 Fuel Oil (On-Site Consumption)

H62
South
< 1/8
0.058 mi.
307 ft.

LOT 33,TAXBLOCK 1051
573 9 AVENUE
MANHATTAN, NY 10036
Site 7 of 11 in cluster H

NY E DESIGNATION S108075929
N/A

Relative:
Higher

E DESIGNATION:

Actual:
34 ft.

Tax Lot(s): 33
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: C7
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: P
Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000003975
Total Building Floor Area: 00000009542
Commercial Floor Area: 00000003000
Office Floor Area: 00000000000
Retail Floor Area: 00000003000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0039.75
Lot Depth: 0100.00
Building Frontage: 0040.00
Building Depth: 0100.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 33,TAXBLOCK 1051 (Continued)

S108075929

Proximity Code: 3
Irregular Lot Code: Y
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000120682
Total Assessed Value: 00000460102
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.40
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510033
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986140
Y Coordinate: 0215536
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 33
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 33,TAXBLOCK 1051 (Continued)

S108075929

Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: C7
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: P
Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000003975
Total Building Floor Area: 00000009542
Commercial Floor Area: 00000003000
Office Floor Area: 00000000000
Retail Floor Area: 00000003000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00008
Non and Residential Units: 00009
Lot Frontage: 0039.75
Lot Depth: 0100.00
Building Frontage: 0040.00
Building Depth: 0100.00
Proximity Code: 3
Irregular Lot Code: Y
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000120682
Total Assessed Value: 00000460102
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.40
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510033
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986140
Y Coordinate: 0215536
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 33,TAXBLOCK 1051 (Continued)

S108075929

Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**I63
WNW
< 1/8
0.059 mi.
313 ft.**

**LOT 53,TAXBLOCK 1051
440 WEST 42 STREET
MANHATTAN, NY 10036**

NY E DESIGNATION

**S108076016
N/A**

Site 1 of 6 in cluster I

**Relative:
Lower**

E DESIGNATION:

Tax Lot(s): 53
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000009628
Total Building Floor Area: 00000029132
Commercial Floor Area: 00000029132
Office Floor Area: 00000019832
Retail Floor Area: 00000009300
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 004.00
Residential Units: 00000

**Actual:
30 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 53,TAXBLOCK 1051 (Continued)

S108076016

Non and Residential Units: 00004
Lot Frontage: 0097.50
Lot Depth: 0098.75
Building Frontage: 0097.50
Building Depth: 0098.75
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000783000
Total Assessed Value: 00001300500
Land Exempt Value: 00000783000
Total Exempt Value: 00001300500
Year Built: 1965
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.03
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510053
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985719
Y Coordinate: 0215806
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 53
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 53,TAXBLOCK 1051 (Continued)

S108076016

Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000009628
Total Building Floor Area: 00000029132
Commercial Floor Area: 00000029132
Office Floor Area: 00000019832
Retail Floor Area: 00000009300
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00004
Lot Frontage: 0097.50
Lot Depth: 0098.75
Building Frontage: 0097.50
Building Depth: 0098.75
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000783000
Total Assessed Value: 00001300500
Land Exempt Value: 00000783000
Total Exempt Value: 00001300500
Year Built: 1965
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.03
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510053
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985719
Y Coordinate: 0215806
Zoning Map: 08D
Sanborn Map: 105N041

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 53,TAXBLOCK 1051 (Continued)

S108076016

Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**H64
SSE
< 1/8
0.061 mi.
320 ft.**

**LOT 103,TAXBLOCK 1032
568 9 AVENUE
MANHATTAN, NY 10036**

NY E DESIGNATION

**S108075831
N/A**

Site 8 of 11 in cluster H

**Relative:
Higher**

E DESIGNATION:

**Actual:
34 ft.**

Tax Lot(s): 103
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: S5
Land Use Category: 04
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000001474
Total Building Floor Area: 00000004594
Commercial Floor Area: 00000001474
Office Floor Area: 00000000000
Retail Floor Area: 00000001474
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 103,TAXBLOCK 1032 (Continued)

S108075831

Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00006
Non and Residential Units: 00007
Lot Frontage: 0019.67
Lot Depth: 0075.00
Building Frontage: 0020.00
Building Depth: 0075.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000044634
Total Assessed Value: 00000197879
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1910
Year Built Code: E
Year Altered1: 1989
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.12
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320103
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986253
Y Coordinate: 0215403
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

H65
South
< 1/8
0.061 mi.
323 ft.

LOT 32,TAXBLOCK 1051
571 9 AVENUE
MANHATTAN, NY 10036
Site 9 of 11 in cluster H

NY E DESIGNATION **S108075924**
N/A

Relative:
Higher

E DESIGNATION:
Tax Lot(s): 32
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M

Actual:
33 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 32,TAXBLOCK 1051 (Continued)

S108075924

Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K1
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000001850
Total Building Floor Area: 00000001400
Commercial Floor Area: 00000001400
Office Floor Area: 00000000000
Retail Floor Area: 00000001400
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 001.00
Residential Units: 00000
Non and Residential Units: 00002
Lot Frontage: 0018.50
Lot Depth: 0100.00
Building Frontage: 0019.00
Building Depth: 0100.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000155700
Total Assessed Value: 00000274050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1981
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 32,TAXBLOCK 1051 (Continued)

S108075924

Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.76
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510032
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986159
Y Coordinate: 0215498
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 32
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: K1
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: Not reported
Owner Name: WASHINGTON BEEF COMPA
Lot Area: 000001850
Total Building Floor Area: 00000001400
Commercial Floor Area: 00000001400

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 32,TAXBLOCK 1051 (Continued)

S108075924

Office Floor Area: 00000000000
Retail Floor Area: 00000001400
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 001.00
Residential Units: 00000
Non and Residential Units: 00002
Lot Frontage: 0018.50
Lot Depth: 0100.00
Building Frontage: 0019.00
Building Depth: 0100.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000155700
Total Assessed Value: 00000274050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1981
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.76
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510032
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986159
Y Coordinate: 0215498
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

G66
ENE
< 1/8
0.062 mi.
327 ft.
CON EDISON
606 9TH AVE
NEW YORK, NY 10036
Site 8 of 11 in cluster G

NY MANIFEST **S112210636**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268223
Country: USA

Actual:
35 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268223
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457009JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210636

Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268223
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457009JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

G67
ENE
< 1/8
0.062 mi.
327 ft.

CON EDISON SERVICE BOX: 39885
606 9TH AVE
NEW YORK, NY 10036

RCRA-CESQG **1016144035**
FINDS **NYP004268223**

Site 9 of 11 in cluster G

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 39885
Facility address: 606 9TH AVE
NEW YORK, NY 10036
EPA ID: NYP004268223
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

Actual:
35 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39885 (Continued)

1016144035

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458847

Environmental Interest/Information System

G68
ENE
< 1/8
0.063 mi.
331 ft.

611 9TH AVE
611 9TH AVENUE
NEW YORK, NY

NY LTANKS **S104495734**
N/A

Site 10 of 11 in cluster G

Relative:
Higher

LTANKS:

Actual:
34 ft.

Site ID: 98887
Spill Number/Closed Date: 9406176 / 2/17/2004
Spill Date: 8/5/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 8/5/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

611 9TH AVE (Continued)

S104495734

Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/19/1994
Spill Record Last Update: 2/17/2004
Spiller Name: Not reported
Spiller Company: PUBLIC OIL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 87930
DEC Memo: Not reported
Remarks: CAP LEFT OFF TANK-SPILL CONTAINED IN BASEMENT. MILLER ENVIRONMENT
ENROUTE.

Material:

Site ID: 98887
Operable Unit ID: 1000329
Operable Unit: 01
Material ID: 379230
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 40
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

H69
South
< 1/8
0.064 mi.
340 ft.

LOT 1,TAXBLOCK 1032
566 9 AVENUE
MANHATTAN, NY 10036

NY E DESIGNATION

S108075804
N/A

Site 10 of 11 in cluster H

Relative:
Higher

E DESIGNATION:

Tax Lot(s): 1
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 1,TAXBLOCK 1032 (Continued)

S108075804

City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: T1
Land Use Category: 07
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000004454
Total Building Floor Area: 00000013950
Commercial Floor Area: 00000013950
Office Floor Area: 00000000000
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000013950
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 004.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0039.00
Lot Depth: 0075.00
Building Frontage: 0036.00
Building Depth: 0078.00
Proximity Code: 3
Irregular Lot Code: Y
Lot Type: 3
Basement Type Grade: 5
Land Assessed Value: 00001044000
Total Assessed Value: 00001831500
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1979
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.13
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320001
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986263

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 1,TAXBLOCK 1032 (Continued)

S108075804

Y Coordinate: 0215360
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

H70
South
< 1/8
0.068 mi.
358 ft.

LOT 31,TAXBLOCK 1051
567 9 AVENUE
MANHATTAN, NY 10036
Site 11 of 11 in cluster H

NY E DESIGNATION **S108075917**
N/A

Relative:
Higher

E DESIGNATION:
Tax Lot(s): 31
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: Z9
Land Use Category: Not reported
Number of Easements: 0
Owner, Type of Code: P
Owner Name: SCOTT 42 DEVEL LTD
Lot Area: 000003700
Total Building Floor Area: 00000000000
Commercial Floor Area: 00000000000
Office Floor Area: 00000000000
Retail Floor Area: 00000000000

Actual:
33 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 31,TAXBLOCK 1051 (Continued)

S108075917

Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00000
Number of Floors: 000.00
Residential Units: 00000
Non and Residential Units: 00000
Lot Frontage: 0037.00
Lot Depth: 0100.00
Building Frontage: 0000.00
Building Depth: 0000.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 3
Basement Type Grade: 5
Land Assessed Value: 00000531000
Total Assessed Value: 00000531000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 0000
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.00
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510031
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986109
Y Coordinate: 0215493
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 31
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 31,TAXBLOCK 1051 (Continued)

S108075917

Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: Z9
Land Use Category: Not reported
Number of Easements: 0
Owner, Type of Code: P
Owner Name: SCOTT 42 DEVEL LTD
Lot Area: 000003700
Total Building Floor Area: 00000000000
Commercial Floor Area: 00000000000
Office Floor Area: 00000000000
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00000
Number of Floors: 000.00
Residential Units: 00000
Non and Residential Units: 00000
Lot Frontage: 0037.00
Lot Depth: 0100.00
Building Frontage: 0000.00
Building Depth: 0000.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 3
Basement Type Grade: 5
Land Assessed Value: 00000531000
Total Assessed Value: 00000531000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 0000
Year Built Code: Not reported
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0000.00
Maximum Allowable Far: 10.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 31,TAXBLOCK 1051 (Continued)

S108075917

Borough Code: 1
Borough Tax Block And Lot: 1010510031
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986109
Y Coordinate: 0215493
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

J71
NNW
< 1/8
0.070 mi.
368 ft.

CON EDISON
456 W 43RD ST
NEW YORK, NY 10036

Site 1 of 2 in cluster J

NY MANIFEST **S112210633**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268199
Country: USA

Actual:
30 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268199
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210633

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457019JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268199
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457019JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

J72
NNW
< 1/8
0.070 mi.
368 ft.

CON EDISON SERVICE BOX: 8320
456 W 43RD ST
NEW YORK, NY 10036
Site 2 of 2 in cluster J

RCRA-CESQG
FINDS
1016144032
NYP004268199

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8320

Facility address: 456 W 43RD ST

NEW YORK, NY 10036

EPA ID: NYP004268199

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458829

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8320 (Continued)

1016144032

Environmental Interest/Information System

I73
WNW
< 1/8
0.071 mi.
376 ft.

LOT 57,TAXBLOCK 1051
450 WEST 42 STREET
MANHATTAN, NY 10036

NY E DESIGNATION S108076031
N/A

Site 2 of 6 in cluster I

Relative:
Lower

E DESIGNATION:

Actual:
29 ft.

Tax Lot(s): 57
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: J9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002221
Total Building Floor Area: 00000006549
Commercial Floor Area: 00000006549
Office Floor Area: 00000000000
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000006549
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 002.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0022.50
Lot Depth: 0098.75
Building Frontage: 0022.50
Building Depth: 0055.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 57,TAXBLOCK 1051 (Continued)

S108076031

Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000225000
Total Assessed Value: 00000400500
Land Exempt Value: 00000225000
Total Exempt Value: 00000400500
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.95
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510057
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985667
Y Coordinate: 0215834
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 57
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2001
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 57,TAXBLOCK 1051 (Continued)

S108076031

Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: J9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CITY WIDE ADMINISTRAT
Lot Area: 000002221
Total Building Floor Area: 00000006549
Commercial Floor Area: 00000006549
Office Floor Area: 00000000000
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000006549
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 002.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0022.50
Lot Depth: 0098.75
Building Frontage: 0022.50
Building Depth: 0055.00
Proximity Code: 0
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000225000
Total Assessed Value: 00000400500
Land Exempt Value: 00000225000
Total Exempt Value: 00000400500
Year Built: 1910
Year Built Code: E
Year Altered1: 0000
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.95
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010510057
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985667
Y Coordinate: 0215834
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 57,TAXBLOCK 1051 (Continued)

S108076031

Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**I74
WNW
< 1/8
0.071 mi.
376 ft.**

**CON EDISON
436 W 42ND ST
NEW YORK, NY 10036**

RCRA-CESQG

**1012185937
NYP004167722**

Site 3 of 6 in cluster I

**Relative:
Lower**

RCRA-CESQG:

Date form received by agency: 04/20/2009

Facility name: CON EDISON

Facility address: 436 W 42ND ST
NEW YORK, NY 10036

EPA ID: NYP004167722

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003

Contact: MICHAEL BETO

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (917) 337-5519

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185937

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

G75
ENE
< 1/8
0.072 mi.
380 ft.

606-604 9TH AVENUE
606-604 NINTH AVENUE
NEW YORK, NY 10036
Site 11 of 11 in cluster G

NY AST **A100183487**
N/A

Relative:
Higher

AST:

Actual:
35 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606919
Program Type: PBS
UTM X: 585087.35828000004
UTM Y: 4512520.5806799997
Expiration Date: 09/10/2016
Site Type: Private Residence

Affiliation Records:

Site Id: 28774
Affiliation Type: Facility Owner
Company Name: CHRISTOS TSOUMPAS
Contact Type: PRES
Contact Name: JOANNE TSOUMPAS
Address1: 110-112 EAST 23RD ST., #400 4FL
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 677-8180
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 6/21/2011

Site Id: 28774
Affiliation Type: Mail Contact
Company Name: CHRISTOS TSOUMPAS
Contact Type: Not reported
Contact Name: JOANNE TSOUMPAS
Address1: 110-112 EAST 23RD STREET
Address2: #400 4FL
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 677-8180
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/5/2006

Site Id: 28774

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

606-604 9TH AVENUE (Continued)

A100183487

Affiliation Type: On-Site Operator
Company Name: 606-604 9TH AVENUE
Contact Type: Not reported
Contact Name: CHRISTOS TSOUMPAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 677-8180
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28774
Affiliation Type: Emergency Contact
Company Name: CHRISTOS TSOUMPAS
Contact Type: Not reported
Contact Name: RAYMON PADILLA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 947-1138
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 62036
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

606-604 9TH AVENUE (Continued)

A100183487

Install Date: 05/08/1965
Capacity Gallons: 2500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 06/21/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

K76
South
< 1/8
0.075 mi.
394 ft.

563 9TH AVE
NEW YORK, NY 10036

EDR US Hist Auto Stat 1015554871
N/A

Site 1 of 6 in cluster K

Relative:
Higher

EDR Historical Auto Stations:

Name: CAR TOW & REPAIR
Year: 2004
Address: 563 9TH AVE

Actual:
33 ft.

Name: CAR TOWING & REPAIR
Year: 2010
Address: 563 9TH AVE

Name: CAR TOW & REPAIR
Year: 2011
Address: 563 9TH AVE

L77
ESE
< 1/8
0.077 mi.
407 ft.

BUSINESS
351 WEST 42 ND ST MANHATTEN
MANHATTEN, NY

NY Spills S111238400
N/A

Site 1 of 3 in cluster L

Relative:
Higher

SPILLS:

Facility ID: 1107029
Facility Type: ER
DER Facility ID: 409314
Site ID: 454715
DEC Region: 2
Spill Date: 9/6/2011
Spill Number/Closed Date: 1107029 / 9/6/2011
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Actual:
36 ft.

SWIS: 3101
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 9/6/2011
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Local Agency
Cleanup Ceased: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BUSINESS (Continued)

S111238400

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/6/2011
Spill Record Last Update: 9/6/2011
Spiller Name: TONY MURTAUGH
Spiller Company: OIL COMPANY
Spiller Address: 351 WEST 42 ND ST MANHATTEN
Spiller City,St,Zip: MANHATTEN, NY
Spiller Company: 999
Contact Name: TONY MURTAUGH
Contact Phone: (518) 766-2462
DEC Memo: Overfill out vent onto sidewalk 8 gal Milro did a powerwash. Cleanup complete
Remarks: affected ares side walk - clean up in progress

Material:
Site ID: 454715
Operable Unit ID: 1204867
Operable Unit: 01
Material ID: 2201665
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 8
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

L78
ESE
< 1/8
0.077 mi.
407 ft.

RESIDENCE TTF
351 WEST 42ND ST
NEW YORK CITY, NY

NY LTANKS S111458638
N/A

Site 2 of 3 in cluster L

Relative:
Higher

LTANKS:
Site ID: 460370
Spill Number/Closed Date: 1112434 / 5/31/2012
Spill Date: 1/26/2012
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 1/26/2012
CID: Not reported
Water Affected: Not reported

Actual:
36 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE TTF (Continued)

S111458638

Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/26/2012
Spill Record Last Update: 5/31/2012
Spiller Name: Not reported
Spiller Company: GEFFNER HOUSE
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: CHRIS QUINTANA
Spiller Phone: (347) 397-8298
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 414829
DEC Memo: Tank has been emptied and temp tank set up in place5/30/2012 - Sangesland got an e-mail from Donna at ABC Tank - They submitted a proposal to the owner a while ago, but never heard back. Job was "Probably done" by someone else 5/31/2012 Sangesland spoke with Edwin Colon, Facilities Mgr 212-245-6600 x250. He said Eastmond was hired to do repairs. Neil Tomasetti at Eastmond said both fill line and vent line failed test. Sidewalk was opened and fill line went directly through old coal chute down to tank vault (former coal room). Fill line dripped into coal chute and ran down to tank vault. Tank was cleaned (no holes) but ulltrasound showed pitting on tank bottom. Tank was raised into saddles and bottom of tank was relined with metal plates. New fill lines and vent lines installed. No contamination was found and the new system passed a pressure test. Spill Closed.
Remarks: repair/retest pending - all fittings looseUpdate - Tank has been emptied and temp set up in place

Material:
Site ID: 460370
Operable Unit ID: 1210462
Operable Unit: 01
Material ID: 2208102
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L79
ESE
< 1/8
0.077 mi.
407 ft.

MANHOLE #8110
351 WEST 42 STREET @ 8 AVENUE
MANHATTAN, NY

NY Spills S108295294
N/A

Site 3 of 3 in cluster L

Relative:
Higher

Actual:
36 ft.

SPILLS:

Facility ID: 0608385
Facility Type: ER
DER Facility ID: 322058
Site ID: 372329
DEC Region: 2
Spill Date: 10/20/2006
Spill Number/Closed Date: 0608385 / 3/19/2007
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 10/22/2006
CID: 72
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/23/2006
Spill Record Last Update: 3/19/2007
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller Company: 999
Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Memo: 03/19/07 - See e-docs for Con Ed report detailing cleanup and closure.202972. see eDocs

Remarks: ConEd #: 202972

Material:

Site ID: 372329
Operable Unit ID: 1130072
Operable Unit: 01
Material ID: 2119739
Material Code: 0013
Material Name: Lube Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #8110 (Continued)

S108295294

Tank Test:

**M80
WSW
< 1/8
0.080 mi.
421 ft.**

**WEST 41ST ST
DYER AVE & W.41ST ST
MANHATTAN, NY**

**NY Spills S103573144
N/A**

Site 1 of 4 in cluster M

**Relative:
Lower**

SPILLS:

**Actual:
30 ft.**

Facility ID: 9808978
Facility Type: ER
DER Facility ID: 193213
Site ID: 234561
DEC Region: 2
Spill Date: 10/19/1998
Spill Number/Closed Date: 9808978 / 10/20/1998
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 10/19/1998
CID: 233
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/19/1998
Spill Record Last Update: 10/4/2002
Spiller Name: Not reported
Spiller Company: PA LINCOLN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE" FAXED TO DEP. FDNY RECIEVED CALL AT 1352. PAPD LINCOLN BOB M
CARTON 201-617-8443. SAVLOID. PIPE AT BUS TERMINAL WAS LEAKING ON TO
STREET AND SEWER. LEAK STOPPED. NYCDEP ON SCENE. SMALL AMOUNT IN
STORM SEWER. CLEANED BY PA.

Remarks: NYC BUS LEAKED UNK MATERIAL ONTO ROADWAY FD WAS DISPATCHED TO SCENE

Material:
Site ID: 234561
Operable Unit ID: 1070161
Operable Unit: 01
Material ID: 316450
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 41ST ST (Continued)

S103573144

Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**M81
WSW
< 1/8
0.080 mi.
421 ft.**

**SITE L OF #7 LINE
W 41ST ST AND DYER AVE
MANHATTAN, NY**

NY Spills

**S111064437
N/A**

Site 2 of 4 in cluster M

**Relative:
Lower**

**Actual:
30 ft.**

SPILLS:

Facility ID: 1102550
Facility Type: ER
DER Facility ID: 404653
Site ID: 450067
DEC Region: 2
Spill Date: 6/1/2011
Spill Number/Closed Date: 1102550 / 6/6/2011
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 6/6/2011
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/6/2011
Spill Record Last Update: 6/6/2011
Spiller Name: Not reported
Spiller Company: CCA-HALMAR
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: MICHAEL BYRNES
Contact Phone: Not reported
DEC Memo: hydraulic spill to soil from construction equipment leak.Spill has
been cleaned. Dug out area and put in drum for removal.

Remarks: Caller advised 5 gallons of hydraulic oil spilled onto soil. Clean up
is pending.

Material:

Site ID: 450067
Operable Unit ID: 1200267

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SITE L OF #7 LINE (Continued)

S111064437

Operable Unit: 01
Material ID: 2196672
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**N82
NE
< 1/8
0.080 mi.
424 ft.**

**NINTH AVENUE CLEANERS
617 9TH AVENUE
NEW YORK, NY 10036**

NY DRYCLEANERS

**S110247473
N/A**

Site 1 of 12 in cluster N

**Relative:
Higher**

DRYCLEANERS:
Facility ID: 2-6202-01660
Phone Number: 212-977-7882
Region: Not reported
Registration Effective Date: 3/17/2003 12:10:47:406
Inspection Date: 06MAR17
Install Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: DF2000
Current Business: Not reported

**Actual:
35 ft.**

**N83
NE
< 1/8
0.080 mi.
424 ft.**

**617 9TH AVE
NEW YORK, NY 10036**

EDR US Hist Cleaners

**1015081497
N/A**

Site 2 of 12 in cluster N

**Relative:
Higher**

EDR Historical Cleaners:
Name: DENNIS LAUNDRY
Year: 1999
Address: 617 9TH AVE

Name: DENNIS LAUNDRY
Year: 2000
Address: 617 9TH AVE

Name: DENNIS LAUNDRY
Year: 2001
Address: 617 9TH AVE

Name: PSN 9TH AVENUE CLEANERS
Year: 2005
Address: 617 9TH AVE

**Actual:
35 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015081497

Name: 9TH AVENUE SUNNY CLEANERS CORP
Year: 2008
Address: 617 9TH AVE

Name: 9TH AVENUE CLEANERS
Year: 2010
Address: 617 9TH AVE

Name: 9TH AVENUE SUNNY CLEANERS CORP
Year: 2011
Address: 617 9TH AVE

Name: 9TH AVENUE SUNNY CLEANERS CORP
Year: 2012
Address: 617 9TH AVE

M84
WSW
< 1/8
0.080 mi.
425 ft.

LINCOLN TUNNEL/PROJECT FIND/DROP-IN-CENT
402 WEST 41ST STREET
NEW YORK, NY 10036
Site 3 of 4 in cluster M

NY UST U001841428
N/A

Relative:
Lower

UST:
Id/Status: 2-600388 / Inactive
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/11/1996
UTM X: 586966.58354000002
UTM Y: 4511302.4806000004
Site Type: Unknown

Actual:
30 ft.

Affiliation Records:
Site Id: 22371
Affiliation Type: Facility Owner
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 WORLD TRADE CENTER
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10048
Country Code: 001
Phone: (212) 466-7000
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 6/15/2010

Site Id: 22371
Affiliation Type: Mail Contact
Company Name: JEROME CALO
Contact Type: Not reported
Contact Name: Not reported
Address1: 500 BOULEVARD EAST
Address2: Not reported
City: WEEHAWKEN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINCOLN TUNNEL/PROJECT FIND/DROP-IN-CENT (Continued)

U001841428

State: NJ
Zip Code: 07087
Country Code: 001
Phone: (201) 617-8036
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22371
Affiliation Type: On-Site Operator
Company Name: LINCOLN TUNNEL/PROJECT FIND/DROP-IN-CENT
Contact Type: Not reported
Contact Name: LISA KIRKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 465-0975
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22371
Affiliation Type: Emergency Contact
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: TOUR COMMANDER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 617-8526
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 10
Tank ID: 42427
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 2000
Install Date: 12/01/1957
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LINCOLN TUNNEL/PROJECT FIND/DROP-IN-CENT (Continued)

U001841428

Tightness Test Method: 03
Date Test: 10/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: ajsigona
Last Modified: 05/28/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

185
WNW
< 1/8
0.081 mi.
429 ft.

460 WEST 42 ST
460 WEST 42ND ST
MANHATTAN, NY
Site 4 of 6 in cluster I

NY Spills S106384969
N/A

Relative:
Lower

SPILLS:

Actual:
28 ft.

Facility ID: 0400537
Facility Type: ER
DER Facility ID: 152632
Site ID: 182048
DEC Region: 2
Spill Date: 4/16/2004
Spill Number/Closed Date: 0400537 / 2/14/2007
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: qxabidi
Referred To: Not reported
Reported to Dept: 4/16/2004
CID: 403
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/16/2004
Spill Record Last Update: 2/14/2007
Spiller Name: JULIE FLOEY
Spiller Company: Not reported
Spiller Address: 460 WEST 42ND ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: JULIE FLOEY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

460 WEST 42 ST (Continued)

S106384969

Contact Phone:

(646) 459-3524

DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"8/19/04 work ongoing// report to be submitted to DEC once it is completed.10-06-05: NYCT was performing soil borings for the #7 line extension. Contamination was discovered in the boring in front of this location. See spill # 0404424. Boring log and notes in eDocs. MCT.06/19/06: This spill is transferred from Mr. Koon Tang to Q.Abidi.Called to Mr. Michael Feeley (973)496-3467 left message to call me back regarding spill.11/06/04: Called Mr. Michael Feeley and left message to call me back regarding information of the spill. -QA11/10/06: Called Mr. Mike Feeley he said to contact Ms. Rose Pelino (Environmental Management)AZIS Company at (973)496-3447. Called Ms. Rose Pelino and left message to call me back.Mr. Philip Angle (Environmental Management, Parsipanny, NJ) called me back and said they removed the tank in August 2005. He will mail me the soil sample report. -QA01/22/07: Called Mr. Phillips Angle at (973)496-6942 and left message to call me back regarding soil sample report of the spill. -QA02/05/07: Called Mr. Phil Angle to discuss regarding information of this spill. I requested him to send me Electronic version Pdf of the report and owner's name address phone number and e-mail address. He said he will send these informations very soon. -QA02/14/07: Reviewed report of UST Closure by Langan Engineering and Environmental Services. At the time of removal of tank, Excavated two drums of petroleum contaminated soil (500 pounds in quantity). After taking End-point samples, Excavated area has been filled by clean soil. All end-point soil samples are clean. On the basis of provided data of Langan Engineering DEC staff closed the spill. Approval to close the spill has been taken from Mr. Jon Kolleeny supervisor. -QA

Remarks:

soil borings as part of a phase 2.the spill is beleived yo be associated with under ground fuel oil tank and NYC DOB records state it was closed in place under direction of NYC fire dept. in 1993 and the tank is under the side walk not in the buildings basement

Material:

Site ID: 182048
Operable Unit ID: 884820
Operable Unit: 01
Material ID: 571256
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

186
WNW
< 1/8
0.082 mi.
434 ft.

AVIS RENT A CAR
460 W 42 ST
NY, NY 10036
Site 5 of 6 in cluster I

NY UST U001841245
N/A

Relative:
Lower

UST:

Actual:
28 ft.

Id/Status: 2-511854 / Inactive
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/21/1996
UTM X: 584896.88367000001
UTM Y: 4512524.8924500002
Site Type: Unknown

Affiliation Records:

Site Id: 21982
Affiliation Type: Facility Owner
Company Name: AVIS RENT A CAR
Contact Type: Not reported
Contact Name: Not reported
Address1: 900 OLD COUNTRY RD
Address2: Not reported
City: GARDEN CITY
State: NY
Zip Code: 11530
Country Code: 001
Phone: (516) 222-3780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21982
Affiliation Type: Mail Contact
Company Name: AVIS RENT A CAR
Contact Type: Not reported
Contact Name: Not reported
Address1: 900 OLD COUNTRY RD
Address2: Not reported
City: GARDEN CITY
State: NY
Zip Code: 11530
Country Code: 001
Phone: (516) 222-3780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21982
Affiliation Type: On-Site Operator
Company Name: AVIS RENT A CAR
Contact Type: Not reported
Contact Name: JEFF KONEN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR (Continued)

U001841245

Zip Code: Not reported
Country Code: 001
Phone: (516) 222-3780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21982
Affiliation Type: Emergency Contact
Company Name: AVIS RENT A CAR
Contact Type: Not reported
Contact Name: JEFF KONEN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 222-3780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 39921
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 4000
Install Date: 01/01/1978
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR (Continued)

U001841245

Tank Number: 002
Tank ID: 39922
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 2500
Install Date: 03/01/1991
Date Tank Closed: 11/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H00 - Tank Leak Detection - None

187
WNW
< 1/8
0.082 mi.
434 ft.

AVIS RENT A CAR SYSTEM, INC.
460 WEST 42ND STREET
NEW YORK, NY 10036

Site 6 of 6 in cluster I

NY UST **U003030985**
NY HIST UST **N/A**

Relative:
Lower

UST:
Id/Status: 2-364401 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/15/2007
UTM X: 584896.88367000001
UTM Y: 4512524.8924500002
Site Type: Other

Actual:
28 ft.

Affiliation Records:

Site Id: 18468
Affiliation Type: Facility Owner
Company Name: AVIS RENT A CAR SYSTEM, INC.
Contact Type: SENIOR VICE PRESIDENT
Contact Name: ROBERT BOUTA
Address1: 6 SYLVAN WAY
Address2: DEPT. 29-C93-36
City: PARSIPPANY
State: NJ
Zip Code: 07054
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM, INC. (Continued)

U003030985

Phone: (973) 496-3467
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/5/2005

Site Id: 18468
Affiliation Type: Mail Contact
Company Name: AVIS RENT A CAR SYSTEM INC
Contact Type: Not reported
Contact Name: MICHAEL FEELEY
Address1: 6 SYLVAN WAY
Address2: DEPT 29-C93-36
City: PARSIPPANY
State: NJ
Zip Code: 07054
Country Code: 001
Phone: (973) 496-3467
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/15/2007

Site Id: 18468
Affiliation Type: On-Site Operator
Company Name: AVIS RENT A CAR SYSTEM, INC.
Contact Type: Not reported
Contact Name: AVIS RENT A CAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 593-8450
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 8/13/2008

Site Id: 18468
Affiliation Type: Emergency Contact
Company Name: AVIS RENT A CAR SYSTEM, INC.
Contact Type: Not reported
Contact Name: LAUREL DAVIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 593-1065
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/16/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM, INC. (Continued)

U003030985

Tank Info:

Tank Number: 001
Tank ID: 22565
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1978
Date Tank Closed: 10/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 43586
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2500
Install Date: Not reported
Date Tank Closed: 08/04/2005
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 04/01/1990
Next Test Date: Not reported
Pipe Model: D
Modified By: NRLOMBAR
Last Modified: 10/05/2005

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM, INC. (Continued)

U003030985

I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

HIST UST:

PBS Number: 2-364401
SPDES Number: Not reported
Emergency Contact: BOB REYNOLDS
Emergency Telephone: (212) 593-8361
Operator: AVIS RENT A CAR
Operator Telephone: (212) 593-8450
Owner Name: AVIS RENT A CAR SYSTEM INC
Owner Address: 900 OLD COUNTRY RD DEPT 93-1T
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Telephone: (516) 222-3432
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: AVIS RENT A CAR SYSTEM INC
Mailing Address: 900 OLD COUNTRY RD
Mailing Address 2: DEPT 93-1T
Mailing City,St,Zip: GARDEN CITY, NY 11530
Mailing Contact: MICHAEL FEELEY
Mailing Telephone: (516) 222-3432
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 460 W 42ND ST
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 11/03/1997
Expiration Date: 10/15/2002
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 2500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM, INC. (Continued)

U003030985

Region: 2

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: 10/01/1991
Capacity (gals): 2500
Product Stored: UNLEADED GASOLINE
Tank Type: Fiberglass reinforced plastic [FRP]
Tank Internal: Fiberglass Liner (FRP)
Tank External: Fiberglass
Pipe Location: Underground
Pipe Type: STAINLESS STEEL ALLOY
Pipe Internal: Fiberglass Liner (FRP)
Pipe External: Fiberglass
Second Containment: Vault (w/access)
Leak Detection: 14
Overfill Prot: High Level Alarm, Catch Basin
Dispenser: Submersible
Date Tested: 04/01/1990
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Petro-Tite
Deleted: False
Updated: True
Lat/long: Not reported

O88
NE
< 1/8
0.086 mi.
454 ft.

WESTSIDE 414, LLC.
414 W 44TH ST
NY, NY 10036

Site 1 of 4 in cluster O

NY UST
NY HIST UST

U003067730
N/A

Relative:
Higher

UST:

Actual:
35 ft.

Id/Status: 2-256978 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 06/07/2016
UTM X: 585103.96579000005
UTM Y: 4512598.8776099999
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 10574
Affiliation Type: Mail Contact
Company Name: BRONSTEIN PROPERTIES, LLC
Contact Type: Not reported
Contact Name: JOE MASINO
Address1: 108-18 QUEENS BLVD. SUITE 302
Address2: Not reported
City: FOREST HILLS
State: NY
Zip Code: 11375
Country Code: 001
Phone: (718) 261-5235
Email: CAMILLE@BRONSTEINPROPERTIES.COM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WESTSIDE 414, LLC. (Continued)

U003067730

Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/15/2014

Site Id: 10574
Affiliation Type: On-Site Operator
Company Name: WESTSIDE 414, LLC.
Contact Type: Not reported
Contact Name: LOUIE BERISHA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 334-1810
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 12/14/2012

Site Id: 10574
Affiliation Type: Emergency Contact
Company Name: WESTSIDE 414, LLC.
Contact Type: Not reported
Contact Name: BARRY RUDOFISKY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 261-5235
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 12/14/2012

Site Id: 10574
Affiliation Type: Facility Owner
Company Name: WESTSIDE 414, LLC.
Contact Type: DIRECTOR OF MGMT
Contact Name: JOE MASINO
Address1: 108-18 QUEENS BLVD. SUITE 302
Address2: Not reported
City: FOREST HILLS
State: NY
Zip Code: 11375
Country Code: 001
Phone: (718) 261-5235
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 12/14/2012

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WESTSIDE 414, LLC. (Continued)

U003067730

Tank Number: 001
Tank ID: 15021
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 10/02/1927
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DXLIVING
Last Modified: 06/06/2007

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
B05 - Tank External Protection - Jacketed
F02 - Pipe External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground

HIST UST:

PBS Number: 2-256978
SPDES Number: Not reported
Emergency Contact: HOWARD SORKIN
Emergency Telephone: (914) 993-0300
Operator: FRANK VAVOSA
Operator Telephone: (212) 582-0614
Owner Name: LEWIS KAYE
Owner Address: 6 BRUCE ROAD BOX 146
Owner City,St,Zip: MAMARONECK, NY 10543
Owner Telephone: (914) 993-0300
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Name: SIERRA ASSETS GROUP, LTD.
Mailing Address: 30 GLENN STREET - BOX 399
Mailing Address 2: Not reported
Mailing City,St,Zip: WHITE PLAINS, NY 10403
Mailing Contact: LEWIS KAYE C/O
Mailing Telephone: (914) 993-0300
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 414 W 44TH ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WESTSIDE 414, LLC. (Continued)

U003067730

SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 08/19/1997
Expiration Date: 07/14/2002
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 5000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Jacketed
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: Epoxy Liner
Pipe External: Sacrificial Anode
Second Containment: Remote Impounding Area
Leak Detection: Double Bottom
Overfill Prot: Vent Whistle
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

O89
NE
< 1/8
0.086 mi.
454 ft.

APARTMENT BLDG
414 W 44TH ST
NEW YORK, NY
Site 2 of 4 in cluster O

NY Spills S111738385
N/A

Relative:
Higher

Actual:
35 ft.

SPILLS:

Facility ID: 1113807
Facility Type: ER
DER Facility ID: 416268
Site ID: 461821
DEC Region: 2
Spill Date: 3/12/2012
Spill Number/Closed Date: 1113807 / 5/29/2012
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 3/12/2012
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/12/2012
Spill Record Last Update: 5/29/2012
Spiller Name: Not reported
Spiller Company: PROPERTY OWNER
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: RENE LEWIS
Contact Phone: Not reported
DEC Memo:

Rene Lewis working on a leaking tank. Tank has been drained and cleaned and is now filling with water. Alliance will be checking to see if oil leaked out.3/27/2012 - Sangesland spoke to Rene Lewis- Tank was tested and failed. Tank was filled with water and water leaked out. Owner signed a proposal to have the tank removed. Rene is planning on pulling the tank on Friday 3/30/2012.They will then begin digging out contamination.05/29/12 Alliance removed UST from the vault.Removed contaminated soil and debris down to bedrock.Water intruding into the excavation traced back to broken sewer line. Alliance installed/plugged broken line and water stopped. Wall is being recemented.Soil samples were taken from each side of the fill line.Results show VOCs non detect.NFA required.(sr)
TANK WAS CLEANED AND WATER IS LEAKING BACK INTO IT, WILL BE PRESSURE TESTING TANK IN MEAN TIME. UNKNOWN IF ANY OIL HAS BEEN RELEASED

Remarks:

Material:

Site ID: 461821
Operable Unit ID: 1211902
Operable Unit: 01
Material ID: 2209730

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BLDG (Continued)

S111738385

Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

O90
NNE
< 1/8
0.086 mi.
456 ft.

419 WEST 44TH STREET
419 WEST 44TH STREET
MANHATTAN, NY
Site 3 of 4 in cluster O

NY Spills **S104500343**
N/A

Relative:
Higher

Actual:
35 ft.

SPILLS:
Facility ID: 9510453
Facility Type: ER
DER Facility ID: 113419
Site ID: 131642
DEC Region: 2
Spill Date: 11/20/1995
Spill Number/Closed Date: 9510453 / 11/20/1995
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS:
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 11/20/1995
CID: 205
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/20/1995
Spill Record Last Update: 11/29/1995
Spiller Name: Not reported
Spiller Company: BAERENLKAU FUEL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: SHALOM MANAGEMENT
Contact Phone: (718) 699-8863
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MULQUEEN"
Remarks: DRIVER TRIED TO FILL A FULL TANK. OIL CAME OUT OVERFILL PIPE.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

419 WEST 44TH STREET (Continued)

S104500343

Material:

Site ID: 131642
Operable Unit ID: 1020983
Operable Unit: 01
Material ID: 357817
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: 2
Resource Affected: Not reported
Oxygenate: False

Tank Test:

K91
South
< 1/8
0.087 mi.
459 ft.

356 W 41ST ST
NEW YORK, NY 10036

EDR US Hist Auto Stat 1015446377
N/A

Site 2 of 6 in cluster K

Relative:
Higher

EDR Historical Auto Stations:

Name: AUTOMOTIVE CENTEREMERGENCY
Year: 2010
Address: 356 W 41ST ST

Actual:
34 ft.

N92
NE
< 1/8
0.088 mi.
463 ft.

408-410 W 44TH STREET
408-410 W 44TH STREET
MANHATTAN, NY 10036

NY AST U003384082
NY HIST AST N/A

Site 3 of 12 in cluster N

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-082031
Program Type: PBS
UTM X: 585069.88905999996
UTM Y: 4512588.0422599996
Expiration Date: 10/30/2018
Site Type: Apartment Building/Office Building

Actual:
35 ft.

Affiliation Records:

Site Id: 1749
Affiliation Type: Facility Owner
Company Name: NINTH AVE REALTY, LLC
Contact Type: OWNER
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE. #400
Address2: Not reported
City: HARTSDALE
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408-410 W 44TH STREET (Continued)

U003384082

Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/11/2013

Site Id: 1749
Affiliation Type: Mail Contact
Company Name: NINTH AVE REALTY, LLC
Contact Type: Not reported
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE. SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: EMILY@APTSNY.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/11/2013

Site Id: 1749
Affiliation Type: On-Site Operator
Company Name: NINTH AVE REALTY LLC
Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/11/2013

Site Id: 1749
Affiliation Type: Emergency Contact
Company Name: NINTH AVE REALTY, LLC
Contact Type: Not reported
Contact Name: MARK SCHARFMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 799-0497
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408-410 W 44TH STREET (Continued)

U003384082

Date Last Modified: 9/11/2013

Tank Info:

Tank Number: 001
Tank Id: 2962
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1982
Capacity Gallons: 3500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 09/11/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-082031
SWIS Code: 6201
Operator: ROYAL REALTY CORP.
Facility Phone: (212) 789-1180
Facility Addr2: 408 W 44TH STREET
Facility Type: APARTMENT BUILDING
Emergency: ROYAL REALTY CORP.
Emergency Tel: (212) 789-1180
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: DURST PARTNERS
Owner Address: 1155 AVENUE OF THE AMERICAS
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 789-1180
Owner Type: Corporate/Commercial

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408-410 W 44TH STREET (Continued)

U003384082

Owner Subtype: Not reported
Mailing Contact: MARTYN CORDERO
Mailing Name: DURST PARTNERS
Mailing Address: C/O ROYAL REALTY CORP.
Mailing Address 2: 1155 AVENUE OF THE AMERICAS
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 789-1180
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/28/2000
Expiration: 03/24/2002
Renew Flag: False
Renew Date: 11/13/2001
Total Capacity: 3300
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3300
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Not reported
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

K93
South
< 1/8
0.088 mi.
463 ft.

LOT 101,TAXBLOCK 1032
355 WEST 41 STREET
MANHATTAN, NY 10036
Site 3 of 6 in cluster K

NY E DESIGNATION

S108075830
N/A

Relative:
Higher

E DESIGNATION:

Actual:
34 ft.

Tax Lot(s): 101
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: C4
Land Use Category: 02
Number of Easements: 0
Owner, Type of Code: P
Owner Name: CRP/IMICO 350 WEST 4
Lot Area: 000002469
Total Building Floor Area: 00000009045
Commercial Floor Area: 00000001500
Office Floor Area: 00000000000
Retail Floor Area: 00000001500
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00002
Number of Floors: 005.00
Residential Units: 00016
Non and Residential Units: 00017
Lot Frontage: 0025.00
Lot Depth: 0098.75
Building Frontage: 0025.00
Building Depth: 0097.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 101,TAXBLOCK 1032 (Continued)

S108075830

Basement Type Grade: 5
Land Assessed Value: 00000090000
Total Assessed Value: 00000495000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1930
Year Built Code: E
Year Altered1: 1986
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0003.66
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320101
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986312
Y Coordinate: 0215351
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

N94 **406 WEST 44TH ST**
NE **406 WEST 44TH ST**
< 1/8 **NEW YORK, NY 10036**
0.088 mi.
467 ft. **Site 4 of 12 in cluster N**

NY AST **U003392945**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
35 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-329118
Program Type: PBS
UTM X: 585122.73652999999
UTM Y: 4512588.99053000001
Expiration Date: 03/23/2019
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 15443
Affiliation Type: Mail Contact
Company Name: NINTH AVE REALTY
Contact Type: Not reported
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE.
Address2: SUITE 400

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 44TH ST (Continued)

U003392945

City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Site Id: 15443
Affiliation Type: On-Site Operator
Company Name: 406 WEST 44TH STREET
Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Site Id: 15443
Affiliation Type: Emergency Contact
Company Name: NINTH AVE REALTY, LLC
Contact Type: Not reported
Contact Name: DAN DUBROW
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (914) 552-4131
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Site Id: 15443
Affiliation Type: Facility Owner
Company Name: NINTH AVE REALTY, LLC
Contact Type: OWNER
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE. SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 44TH ST (Continued)

U003392945

Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Tank Info:

Tank Number: 001
Tank Id: 25695
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/30/1998
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 01/28/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-329118
SWIS Code: 6201
Operator: BRICK MANAGEMENT CORP
Facility Phone: (212) 789-1180
Facility Addr2: 406 WEST 44TH ST
Facility Type: APARTMENT BUILDING
Emergency: BRICK MANAGEMENT CORP
Emergency Tel: (212) 789-1180
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: EASTERN PORK PRODUCTS
Owner Address: 1133 AVE OF AMERICAS
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 789-1180
Owner Type: Corporate/Commercial
Owner Subtype: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 44TH ST (Continued)

U003392945

Mailing Contact: MARTIN CORDERO
Mailing Name: ROYAL REALTY CORPORATION
Mailing Address: 1155 SIXTH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 789-1180
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/28/2000
Expiration: 01/07/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

P95
WNW
< 1/8
0.090 mi.
474 ft.

466 W 42ND ST
NEW YORK, NY 10036

EDR US Hist Auto Stat **1015508953**
N/A

Site 1 of 3 in cluster P

Relative:
Lower

EDR Historical Auto Stations:

Name: RAPID TOW & REPAIR
Year: 2010
Address: 466 W 42ND ST

Actual:
27 ft.

Name: RAPID TOW & REPAIR
Year: 2011
Address: 466 W 42ND ST

Name: RAPID TOW & REPAIR
Year: 2012
Address: 466 W 42ND ST

K96
SSE
< 1/8
0.090 mi.
474 ft.

LOT 7,TAXBLOCK 1032
347 WEST 41 STREET
MANHATTAN, NY 10036

NY E DESIGNATION **S108076091**
N/A

Site 4 of 6 in cluster K

Relative:
Higher

E DESIGNATION:

Tax Lot(s): 7
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 1000
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 014
Zone District 1: C6-4
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: CL
Special Purpose District2: Not reported
All Components1: C6-4/CL
All Components2: Not reported
Split Boundary Indicator: N
Building Class: O9
Land Use Category: 05
Number of Easements: 0
Owner, Type of Code: P
Owner Name: 347 WEST 41ST ST INC
Lot Area: 000004945
Total Building Floor Area: 00000009875
Commercial Floor Area: 00000009875

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 7,TAXBLOCK 1032 (Continued)

S108076091

Office Floor Area: 00000004937
Retail Floor Area: 00000000000
Garage Floor Area: 00000004938
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 002.00
Residential Units: 00000
Non and Residential Units: 00001
Lot Frontage: 0050.00
Lot Depth: 0098.75
Building Frontage: 0050.00
Building Depth: 0099.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000327150
Total Assessed Value: 00000522000
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1985
Year Built Code: E
Year Altered1: 1984
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.00
Maximum Allowable Far: 10.00
Borough Code: 1
Borough Tax Block And Lot: 1010320007
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0986387
Y Coordinate: 0215310
Zoning Map: 08D
Sanborn Map: 105N043
Tax Map: 10403
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

O97
NE
< 1/8
0.090 mi.
474 ft.

411 W 44 ST
411 WEST 44TH STREET
NEW YORK, NY 10036

Site 4 of 4 in cluster O

NY AST U004045531
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-279986
Program Type: PBS
UTM X: 585117.82206999999
UTM Y: 4512605.2540100003
Expiration Date: 06/30/2008
Site Type: Apartment Building/Office Building

Actual:
35 ft.

Affiliation Records:

Site Id: 12211
Affiliation Type: Facility Owner
Company Name: TURFS KITCHEN APARTMENT CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 411 WEST 44 ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12211
Affiliation Type: Mail Contact
Company Name: TURF COMPANY, INC.
Contact Type: Not reported
Contact Name: JOHN TOUHEY
Address1: 397 BRIDGE STREET
Address2: 7TH FLOOR
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12211
Affiliation Type: On-Site Operator
Company Name: 411 W 44 ST
Contact Type: Not reported
Contact Name: JOHN TOUHEY
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

411 W 44 ST (Continued)

U004045531

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12211
Affiliation Type: Emergency Contact
Company Name: TURFS KITCHEN APARTMENT CORP.
Contact Type: Not reported
Contact Name: ZOHAR HALFON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-6500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 14544
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/22/2003
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

N98
NE
< 1/8
0.090 mi.
477 ft.
402 WEST 44TH ST
402 WEST 44TH ST
NEW YORK, NY 10036
Site 5 of 12 in cluster N

NY AST
NY HIST AST
U003392942
N/A

Relative:
Higher

AST:

Actual:
35 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-329061
Program Type: PBS
UTM X: 585132.16347999999
UTM Y: 4512584.1029899996
Expiration Date: 03/23/2019
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 15440
Affiliation Type: Mail Contact
Company Name: NINTH AVE REALTY
Contact Type: Not reported
Contact Name: MARK SCHARFMAN
Address1: 111 NORTH CENTRAL PARK AVE SUITE 400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Site Id: 15440
Affiliation Type: On-Site Operator
Company Name: 402 WEST 44TH STREET
Contact Type: Not reported
Contact Name: JOSE CASTRO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 682-7394
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Site Id: 15440
Affiliation Type: Emergency Contact
Company Name: NINTH AVE REALTY
Contact Type: Not reported
Contact Name: JEFFERY CARLETON
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

402 WEST 44TH ST (Continued)

U003392942

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 408-6039
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/28/2010

Site Id: 15440
Affiliation Type: Facility Owner
Company Name: NINTH AVE REALTY, LLC
Contact Type: MANAGER
Contact Name: MARK SCHARFMAN
Address1: 111 N. CENTRAL PARK AVE. #400
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/27/2014

Tank Info:

Tank Number: 001
Tank Id: 25692
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
D03 - Pipe Type - Stainless Steel Alloy
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/30/1998
Capacity Gallons: 3200
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 01/28/2014

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

402 WEST 44TH ST (Continued)

U003392942

Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-329061
SWIS Code: 6201
Operator: BRICK MANAGEMENT CORP
Facility Phone: (212) 789-1180
Facility Addr2: 402 WEST 44TH ST
Facility Type: APARTMENT BUILDING
Emergency: BRICK MANAGEMENT CORP
Emergency Tel: (212) 789-1180
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: EASTERN PORK PRODUCTS
Owner Address: 1133 AVE OF AMERICAS
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 789-1133
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: MASTYN CORDERO
Mailing Name: ROYAL REALTY CORPORATION
Mailing Address: 1155 SIXTH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 789-1180
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/28/2000
Expiration: 02/03/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3200
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3200
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

402 WEST 44TH ST (Continued)

U003392942

Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

K99
SSE
< 1/8
0.091 mi.
479 ft.

COMMERCIAL BLDG
347 WEST 41ST ST
MANHATTAN, NY

NY Spills **S104501181**
N/A

Site 5 of 6 in cluster K

Relative:
Higher

SPILLS:

Actual:
34 ft.

Facility ID: 9513489
Facility Type: ER
DER Facility ID: 157639
Site ID: 188791
DEC Region: 2
Spill Date: 1/24/1996
Spill Number/Closed Date: 9513489 / 2/28/2003
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1/25/1996
CID: 297
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/25/1996
Spill Record Last Update: 2/28/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: CHRIS HAAS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BLDG (Continued)

S104501181

Contact Phone: (718) 595-4664
DEC Memo: Not reported
Remarks: NYC DEP RECEIVED A CALL FROM THE ABOVE COMPLAINANT OF ODORS IN THE BUILDING THEY SMELLED LIKE DIESEL FUEL BUT NO SPILL COULD BE FOUND - THIS IS THE 3RD COMPLAINT AND IN THE BUILDING - FIRE DEPT WAS ALSO CALLED AND COULD NOT FIND THE SOURCE

Material:

Site ID: 188791
Operable Unit ID: 1024427
Operable Unit: 01
Material ID: 357207
Material Code: 0065A
Material Name: UNKNOWN NON-PETRO/NON-HAZ MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

N100
NE
< 1/8
0.091 mi.
481 ft.

405 W 44TH ST
NEW YORK, NY 10036

Site 6 of 12 in cluster N

Relative:
Higher

EDR Historical Cleaners:

Name: 9 AVE & 44 ST CORNER CLEANERS
Year: 2010
Address: 405 W 44TH ST

Actual:
35 ft.

EDR US Hist Cleaners

1015055942
N/A

Q101
NNE
< 1/8
0.091 mi.
483 ft.

437-9 WEST 44TH STREET
437-9 WEST 44TH STREET
NEW YORK, NY 10036

Site 1 of 5 in cluster Q

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-095591
Program Type: PBS
UTM X: 585006.08271999995
UTM Y: 4512623.2908500005
Expiration Date: 05/07/2017
Site Type: Other

Actual:
33 ft.

Affiliation Records:

Site Id: 2656
Affiliation Type: Facility Owner
Company Name: M-WAY HOLDING CORPORATION

NY AST
NY HIST AST

U003384830
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

437-9 WEST 44TH STREET (Continued)

U003384830

Contact Type: VICE-PRESIDENT
Contact Name: DOMINICK RUTIGLIANO
Address1: 1140 BRONX RIVER AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10472
Country Code: 001
Phone: (212) 585-7743
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 3/20/2012

Site Id: 2656
Affiliation Type: Mail Contact
Company Name: M-WAY HOLDING CORPORATION
Contact Type: Not reported
Contact Name: DOMINICK RUTIGLIANO
Address1: 1140 BRONX RIVER AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10472
Country Code: 001
Phone: (718) 585-7743
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 3/20/2012

Site Id: 2656
Affiliation Type: On-Site Operator
Company Name: M-WAY HOLDING CORPORATION
Contact Type: Not reported
Contact Name: EMILY RIVAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 791-9226
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 3/20/2012

Site Id: 2656
Affiliation Type: Emergency Contact
Company Name: M-WAY HOLDING CORPORATION
Contact Type: Not reported
Contact Name: PICASSO MALJUGIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

437-9 WEST 44TH STREET (Continued)

U003384830

Zip Code: Not reported
Country Code: 999
Phone: (646) 935-0032
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/24/2006

Tank Info:

Tank Number: 001
Tank Id: 4548
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/15/1964
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KXTANG
Last Modified: 02/08/2007
Material Name: #6 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-095591
SWIS Code: 6201
Operator: RUSSELL CHAMBERS
Facility Phone: (212) 582-7945
Facility Addr2: 437 WEST 44TH STREET
Facility Type: Not reported
Emergency: RUSSELL CHAMBERS
Emergency Tel: (212) 582-7945
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: M-WAY HOLDING CORPORATION
Owner Address: 729 EAST 140TH STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

437-9 WEST 44TH STREET (Continued)

U003384830

Owner City,St,Zip: BRONX, NY 10454
Federal ID: Not reported
Owner Tel: (212) 585-7743
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: M-WAY HOLDING CORPORATION
Mailing Address: 729 EAST 140TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: BRONX, NY 10454
Mailing Telephone: (212) 585-7743
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/20/1997
Expiration: 05/07/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

437-9 WEST 44TH STREET (Continued)

U003384830

Lat/Long: Not reported

**K102
SSE
< 1/8
0.092 mi.
484 ft.**

**CONSOLIDATED EDISON
348 WEST 41ST STREET
NEW YORK, NY 10023**

NY MANIFEST

**S110709642
N/A**

Site 6 of 6 in cluster K

**Relative:
Higher**

NY MANIFEST:

EPA ID: NYP004222667
Country: USA

**Actual:
34 ft.**

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-31
Trans1 Recv Date: 2010-12-31
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-01-03
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004222667
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 001128766GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

N103
NE
< 1/8
0.093 mi.
491 ft.

BEACH LANE MNGT
402 WEST 44TH ST
MANHATTAN, NY
Site 7 of 12 in cluster N

NY Spills S106010215
N/A

Relative:
Higher

Actual:
35 ft.

SPILLS:

Facility ID: 0209670
Facility Type: ER
DER Facility ID: 144371
Site ID: 171552
DEC Region: 2
Spill Date: 12/20/2002
Spill Number/Closed Date: 0209670 / 12/31/2002
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 12/20/2002
CID: 396
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/20/2002
Spill Record Last Update: 12/31/2002
Spiller Name: WOLFORD GRODINGS
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: FF RIBISI
Contact Phone: (917) 769-0483
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT" Summit Transportation 973-777-0404. Crew is on the way. Fire Dept. is trying to cover spills in basement (most cases like which is contained). May has some spills on drive way. 3,000 gls. 12/31/2002-Vought-Site visit by Vought on 12/20/2002. Speedy dry applied to floor and crew collecting impacted material. Spill caused by corroded fill and vent pipe. Spill may have also come out of vent pipe however rain prevented final determination. Spill confined to basement. Spill on poured concrete floor with no cracks or pathways to subsurface. No sewers or drains affected. Spill amount was approximately 40 gallons. Spill closed by Vought.

Remarks:

poss line rupture. spill is coming through the wall. fd on scene investigation and cleaning up.

Material:

Site ID: 171552
Operable Unit ID: 860928
Operable Unit: 01
Material ID: 513099
Material Code: 0003A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH LANE MNGT (Continued)

S106010215

Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

N104
NE
< 1/8
0.094 mi.
496 ft.

CON EDISION - MH 39883
W44TH ST AND 9TH AVE
NEW YORK, NY 10036
Site 8 of 12 in cluster N

NY MANIFEST **S109064698**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004103545
Country: USA

Actual:
35 ft.

Mailing Info:
Name: CON EDISION - MH 39883
Contact: Not reported
Address: Not reported
City/State/Zip: Not reported
Country: Not reported
Phone: Not reported

NY MANIFEST:
No Manifest Records Available

N105
NE
< 1/8
0.094 mi.
497 ft.

WEST 44 STREET & 9TH AVE
WEST 44 STREET & 9TH AVE
NEW YORK, NY
Site 9 of 12 in cluster N

NY Spills **S108058450**
N/A

Relative:
Higher

SPILLS:
Facility ID: 0604129
Facility Type: ER
DER Facility ID: 317058
Site ID: 367037
DEC Region: 2
Spill Date: 7/14/2006
Spill Number/Closed Date: 0604129 / 7/14/2006
Spill Cause: Other
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.

Actual:
35 ft.

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 7/14/2006
CID: 444

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 44 STREET & 9TH AVE (Continued)

S108058450

Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/14/2006
Spill Record Last Update: 7/14/2006
Spiller Name: MANHATTEN FIRE
Spiller Company: Not reported
Spiller Address: WEST 44 STREET & 9TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: MANHATTEN FIRE
Contact Phone: (718) 999-7900
DEC Memo: Sangesland called Fire Dispatch, but could not find anyone who was at the scene. Unknown what the "white material" was.
Remarks: WHIT SUBSTANCE FOUND AND FIRE DEPT ON SCENE NO FURTHER INFO AVAILABLE

Material:
Site ID: 367037
Operable Unit ID: 1124964
Operable Unit: 01
Material ID: 2114472
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

N106
NE
< 1/8
0.095 mi.
499 ft.

CONSOLIDATED EDISON
44TH & 9TH MH39883
NEW YOR, NY 10027
Site 10 of 12 in cluster N

NY MANIFEST **1009226192**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYD004103545
Country: USA

Actual:
35 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009226192

Document ID: NYG2413395
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 10/12/2002
Trans1 Recv Date: 10/12/2002
Trans2 Recv Date: 10/15/2002
TSD Site Recv Date: 10/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD004103545
Trans1 EPA ID: PAD981113749
Trans2 EPA ID: Not reported
TSD ID: JA391
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00728
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00507
Units: K - Kilograms (2.2 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

**N107
NE
< 1/8
0.095 mi.
499 ft.**

**VAULT 2002
WEST 44TH ST/9TH AVE
MANHATTAN, NY**

**NY Spills S106697728
N/A**

Site 11 of 12 in cluster N

**Relative:
Higher**

SPILLS:

**Actual:
35 ft.**

Facility ID: 0404557
Facility Type: ER
DER Facility ID: 118404
Site ID: 138476
DEC Region: 2
Spill Date: 7/28/2004
Spill Number/Closed Date: 0404557 / 12/10/2004
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 7/28/2004
CID: 74
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VAULT 2002 (Continued)

S106697728

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/28/2004
Spill Record Last Update: 12/10/2004
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Memo: e2mis no. 154559:5 gal. of a unknown substance, flooding on 50 gal. of water in V2002. 3 samples taken oil id, pcb and flash point.Lab Sequence Number: 04-05912-001 - Flash Point, PMCC >140 deg F Lab Sequence Number: 04-05911-001 - PCBs < 1 ppm Lab Sequence Number: 04-05913-001 - Insufficient amount of sample extracted to perform oil identification 09-27-04 10:35 Update:@ 10:00 A final clean-up has been completed. 110 gal. of water was removed. No solids. Vactor and tanker was used. Vault was double washed w/slix. Environmental tag was removed #41374. Source of spill is unknown. No repairs were needed.
Remarks: Approximately 5 gallons of unknown oil on 50 gallons of water in a vault. Contained in the vault.samples taken - cleanup pending sample results.Ref # 154559.

Material:
Site ID: 138476
Operable Unit ID: 887503
Operable Unit: 01
Material ID: 488544
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**N108
NE
< 1/8
0.095 mi.
499 ft.**

**MANHOLE #M39883
WEST 44TH ST & 9TH AVE
MANHATTAN, NY**

Site 12 of 12 in cluster N

**NY Spills S106008276
N/A**

**Relative:
Higher**

SPIILLS:
Facility ID: 0207191
Facility Type: ER
DER Facility ID: 195514
Site ID: 237377
DEC Region: 2
Spill Date: 10/10/2002
Spill Number/Closed Date: 0207191 / 9/29/2004

**Actual:
35 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE #M39883 (Continued)

S106008276

Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: AERODRIG
Referred To: Not reported
Reported to Dept: 10/10/2002
CID: 322
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/10/2002
Spill Record Last Update: 9/29/2004
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003-001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "RODRIGUEZ"E2MIS NOTES 145538Flush Dept reports that in M39883, Mr. Valenzuela foundApprox 3 OZ. Of cable oil on concrete floor, mixed 15 lbs of oil absorbent. No sewer connection. Clean up will be done as 50/499.10/12/02 04:30 Al Munro # 13615 Underground (cleanup) forman called to report that the cleanup has been completed 100% at 03:30. They treated this 50-499 ppm. there was 2 barrels of waste consisting of dirt, debris, & ppe generated from this structure. There was 150 gallons of liquid removed. The structure was triple washed with slix & rinsed down. did he see Any leaking cable & he said he did not see any leaks.

Remarks: 3 OZ DIELECTRIC FLUID - FROM A CABLE IN MANHOLE -THERE IS A RODENT PROBLEM IN THE MANHOLE - SO ONCE THEY EXTERMINATE THE RODENTS THEY WILL WORK ON CLEAN UP & REPAIRCON ED #145538

Material:
Site ID: 237377
Operable Unit ID: 860022
Operable Unit: 01
Material ID: 517771
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

P109
WNW
< 1/8
0.095 mi.
500 ft.

CONSOLIDATED EDISON
469 W 42ND ST
NEW YORK, NY 10001

Site 2 of 3 in cluster P

NY MANIFEST **S109584153**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004167243
Country: USA

Actual:
26 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: CONSOLIDATED EDISON
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167243
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584153

Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167243
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167243
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584153

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167243
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

P110
WNW
< 1/8
0.095 mi.
501 ft.

CON EDISON
469 W 42ND ST OPPOSITE OF
NEW YORK, NY 10001
Site 3 of 3 in cluster P

RCRA-CESQG 1012185889
NYP004167243

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 04/14/2009
Facility name: CON EDISON
Facility address: 469 W 42ND ST OPPOSITE OF
NEW YORK, NY 10001
EPA ID: NYP004167243
Mailing address: 4 IRVING PL, RM 828

Actual:
26 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185889

NEW YORK, NY 10003
Contact: DENNIS MICHAELIDES
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 204-4297
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

R111
SSE
< 1/8
0.095 mi.
503 ft.

CON EDISION - V 1558
327 W 41 ST 327 W 41 ST
NEW YORK, NY 10003
Site 1 of 2 in cluster R

RCRA NonGen / NLR 1007208457
NY MANIFEST NYP004090387

Relative:
Higher

RCRA NonGen / NLR:
Date form received by agency: 06/02/2002
Facility name: CON EDISION - V 1558
Facility address: 327 W 41 ST 327 W 41 ST
NEW YORK, NY 10003
EPA ID: NYP004090387
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS

Actual:
35 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - V 1558 (Continued)

1007208457

Contact address: IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 06/01/2002
Site name: CON EDISION - V 1558
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - V 1558
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004090387
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0622512
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/16/2001
Trans1 Recv Date: 10/16/2001
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - V 1558 (Continued)

1007208457

TSD Site Recv Date: 10/16/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004090387
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 01427
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Q112
North
< 1/8
0.096 mi.
505 ft.

447 WEST 44TH ST
447 WEST 44TH ST
NEW YORK CITY, NY
Site 2 of 5 in cluster Q

NY Spills S104495112
N/A

Relative:
Higher

Actual:
32 ft.

SPILLS:
Facility ID: 8604108
Facility Type: ER
DER Facility ID: 126872
Site ID: 149117
DEC Region: 2
Spill Date: 9/25/1986
Spill Number/Closed Date: 8604108 / 9/25/1986
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3101
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 9/25/1986
CID: Not reported
Water Affected: NONE
Spill Source: Private Dwelling
Spill Notifier: Fire Department
Cleanup Ceased: 9/25/1986
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/3/1986
Spill Record Last Update: 6/29/2006
Spiller Name: Not reported
Spiller Company: MR BERK
Spiller Address: SAME
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "
Not reported
Remarks: LEAKING FO TANK (275 GAL)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

447 WEST 44TH ST (Continued)

S104495112

Material:

Site ID: 149117
Operable Unit ID: 901353
Operable Unit: 01
Material ID: 476929
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 149117
Operable Unit ID: 901353
Operable Unit: 01
Material ID: 476930
Material Code: 0630A
Material Name: NONENE
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

R113
SSE
< 1/8
0.096 mi.
509 ft.

V1558
327 WEST 41ST STREET
NEW YORK CITY, NY 10018
Site 2 of 2 in cluster R

RCRA NonGen / NLR 1007207436
NY MANIFEST NYP004045548

Relative:
Higher

RCRA NonGen / NLR:
Date form received by agency: 01/03/2001

Actual:
35 ft.

Facility name: V1558
Facility address: 327 WEST 41ST STREET
NEW YORK CITY, NY 10018
EPA ID: NYP004045548
Mailing address: CONSOLIDATED EDISON INC.
4 IRVING PLACE -- ROOM 300
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC.
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V1558 (Continued)

1007207436

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/02/2001
Site name: V1558
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V1558
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004045548
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0405225
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/02/1999
Trans1 Recv Date: 11/02/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/02/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004045548
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 01245

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V1558 (Continued)

1007207436

Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

S114
South
< 1/8
0.097 mi.
510 ft.

40TH & 41ST ST. 9TH AVE
40TH & 41ST ST 9TH AVE.
MANHATTAN, NY

NY Spills

S102143276
N/A

Site 1 of 2 in cluster S

Relative:
Higher

Actual:
33 ft.

SPILLS:

Facility ID: 9207152
Facility Type: ER
DER Facility ID: 216053
Site ID: 265153
DEC Region: 2
Spill Date: 9/21/1992
Spill Number/Closed Date: 9207152 / 9/21/1992
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: WILSON
Referred To: Not reported
Reported to Dept: 9/21/1992
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: 9/21/1992
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/22/1992
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: EMPLOYEES WERE FILLING HEATING COILS FOR BUS RAMPS-AIR RELIEF VENT
CAPWAS LEFT OPEN & OIL OVERFLOWED FROM SYSTEM ONTO CONCRETE SIDEWALK
& CANOPY NYCFD &NYCDEP WAS NOTIFIED.

Material:

Site ID: 265153
Operable Unit ID: 974139
Operable Unit: 01
Material ID: 407810
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

40TH & 41ST ST. 9TH AVE (Continued)

S102143276

Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 265153
Operable Unit ID: 974139
Operable Unit: 01
Material ID: 407811
Material Code: 1793A
Material Name: THERMAL OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Q115
North
< 1/8
0.097 mi.
511 ft.

44-45 REALTY ASSOC, LP
449 WEST 44TH STREET
NEW YORK, NY 10036
Site 3 of 5 in cluster Q

NY AST U003396968
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
32 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603042
Program Type: PBS
UTM X: 585028.56163999997
UTM Y: 4512651.7451299997
Expiration Date: 06/11/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 24996
Affiliation Type: Facility Owner
Company Name: 44-45 REALTY ASSOC, LP
Contact Type: MANAGING AGENT
Contact Name: R.H. TOPOROVSKY
Address1: PO BOX 331
Address2: Not reported
City: TEANECK
State: NJ
Zip Code: 07666
Country Code: 001
Phone: (201) 836-1575
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

44-45 REALTY ASSOC, LP (Continued)

U003396968

Date Last Modified: 4/11/2012

Site Id: 24996
Affiliation Type: Mail Contact
Company Name: 44-45 REALTY ASSOC, LP
Contact Type: Not reported
Contact Name: DEBRA HERNANDEZ
Address1: PO BOX 331
Address2: Not reported
City: TEANECK
State: NJ
Zip Code: 07666
Country Code: 001
Phone: (201) 836-1575
EMail: DEBBIE@TOPOROVSKY.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/11/2012

Site Id: 24996
Affiliation Type: On-Site Operator
Company Name: 44-45 REALTY ASSOC, LP
Contact Type: Not reported
Contact Name: VICTOR CAMACHO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 836-1575
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24996
Affiliation Type: Emergency Contact
Company Name: 44-45 REALTY ASSOC, LP
Contact Type: Not reported
Contact Name: VICTOR CAMACHO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 836-1575
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 52762

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

44-45 REALTY ASSOC, LP (Continued)

U003396968

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 4
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/14/1985
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KXTANG
Last Modified: 03/09/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-603042
SWIS Code: 6201
Operator: VICTOR CAMACHO
Facility Phone: (201) 836-1575
Facility Addr2: Not reported
Facility Type: APARTMENT BUILDING
Emergency: VICTOR CAMACHO
Emergency Tel: (201) 836-1575
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 44-45 REALTY ASSOC, LP
Owner Address: PO BOX 331
Owner City,St,Zip: TEANECK, NJ 07666
Federal ID: Not reported
Owner Tel: (201) 836-1575
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: 44-45 REALTY ASSOC, LP
Mailing Address: PO BOX 331
Mailing Address 2: Not reported
Mailing City,St,Zip: TEANECK, NJ 07666

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

44-45 REALTY ASSOC, LP (Continued)

U003396968

Mailing Telephone: (201) 836-1575
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 06/18/1997
Expiration: 06/11/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND 10% OR MORE BELOW GROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 00
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: Diking
Leak Detection: 00
Overfill Protection: 06
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Q116
North
< 1/8
0.097 mi.
511 ft.

SPILL NUMBER 9909986
449 WEST 44TH ST
MANHATTAN, NY
Site 4 of 5 in cluster Q

NY Spills S104649947
N/A

Relative:
Higher

Actual:
32 ft.

SPILLS:

Facility ID: 9909986
Facility Type: ER
DER Facility ID: 65942
Site ID: 69356
DEC Region: 2
Spill Date: 11/17/1999
Spill Number/Closed Date: 9909986 / 2/19/2003
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 11/17/1999
CID: 382
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/17/1999
Spill Record Last Update: 2/19/2003
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: 449 WEST 44TH ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: (212) 956-8714
DEC Memo: Not reported
Remarks: BROKEN DECK HOSE CAUSED THE SPILL OUTSIDE IN THE BACK OF APT BUILDING. CLEAN UP CREW ENROUTE.

Material:

Site ID: 69356
Operable Unit ID: 1088676
Operable Unit: 01
Material ID: 299048
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9909986 (Continued)

S104649947

Tank Test:

T117
SE
< 1/8
0.102 mi.
536 ft.

CON EDISON
W.42 ST & 9TH AVE
NEW YORK, NY 10036

NY MANIFEST **S112210634**
N/A

Site 1 of 9 in cluster T

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268207
Country: USA

Actual:
37 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268207
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456575JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210634

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268207
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456575JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

M118
WSW
< 1/8
0.102 mi.
536 ft.

IN STREET
440 WEST 41ST
MANHATTAN, NY
Site 4 of 4 in cluster M

NY Spills S110488622
N/A

Relative:
Lower

SPILLS:

Actual:
29 ft.

Facility ID: 1003287
Facility Type: ER
DER Facility ID: 391435
Site ID: 436503
DEC Region: 2
Spill Date: 6/24/2010
Spill Number/Closed Date: 1003287 / 6/24/2010
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 6/24/2010
CID: Not reported
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IN STREET (Continued)

S110488622

Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/24/2010
Spill Record Last Update: 6/24/2010
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: FDNY HAZ MAT COMPANY 1
Contact Phone: (718) 476-6288
DEC Memo: Spoke with FD Hazmat Chief Rogers.He indicated that they emptied the saddle tank into 2 85 gallon drums and left the drums at the scene to be picked up by the tow truck. He said he explained it to the truck driver that it is their responsibility to remove the drums.Drum location is 440 41st street.Besides this, few gallons spilled on the street which was cleaned up with speedy dry. No drain was impacted. Diesel ran over a con ed manhole.FD did not open up the manhole,instead, notified ConEdision about the incident.Chief Rogers can be reached @(718)476-6288.Case closed.(sr)

Remarks: saddle tank punctured appor 30 gallons onto side of raod, no sewrs affected speedy dry has been applied.

Material:
Site ID: 436503
Operable Unit ID: 1187199
Operable Unit: 01
Material ID: 2182077
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 30
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Q119
NNE
< 1/8
0.102 mi.
540 ft.

APARTMENT COMPLEX
438 W.45TH ST
MANHATTAN, NY
Site 5 of 5 in cluster Q

NY LTANKS S104516285
N/A

Relative:
Higher

LTANKS:
Site ID: 192477
Spill Number/Closed Date: 9911768 / 3/6/2006
Spill Date: 1/10/2000
Spill Cause: Tank Test Failure

Actual:
34 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT COMPLEX (Continued)

S104516285

Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported

Cleanup Meets Standard: False

SWIS: 3101

Investigator: rshough

Referred To: Not reported

Reported to Dept: 1/10/2000

CID: 323

Water Affected: Not reported

Spill Notifier: Tank Tester

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: False

Remediation Phase: 0

Date Entered In Computer: 1/10/2000

Spill Record Last Update: 3/6/2006

Spiller Name: JONAS REAL ESTATE

Spiller Company: APARTMENT COMPLEX

Spiller Address: 438 W45TH ST

Spiller City,St,Zip: MANHATTAN, NY -

Spiller County: 001

Spiller Contact: JONAS REAL ESTATE

Spiller Phone: (631) 466-3333

Spiller Extention: Not reported

DEC Region: 2

DER Facility ID: 160477

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"3/6/06 R. Hough - The spill report indicates a tank test failure, with no release of product. Supporting documentation (PBS Registration issued 11/7/03) indicates that the tank is in service with no further requirement for tank testing. Thus this spill is closed.

Remarks: WILL ISOLATE AND RETEST.

Material:

Site ID: 192477

Operable Unit ID: 1086371

Operable Unit: 01

Material ID: 297214

Material Code: 0001A

Material Name: #2 Fuel Oil

Case No.: Not reported

Material FA: Petroleum

Quantity: 0

Units: Gallons

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

Site ID: 192477

Spill Tank Test: 1547980

Tank Number: 1

Tank Size: 2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT COMPLEX (Continued)

S104516285

Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

U120
North
< 1/8
0.104 mi.
549 ft.

455 W 44TH ST
NEW YORK, NY 10036

EDR US Hist Cleaners 1015063497
N/A

Site 1 of 3 in cluster U

Relative:
Lower

EDR Historical Cleaners:

Name: WESTLAKE CLEANERS & LAUNDERER
Year: 2007

Actual:
31 ft.

Address: 455 W 44TH ST

Name: WESTLAKE CLEANERS & LAUNDERER
Year: 2008
Address: 455 W 44TH ST

Name: WESTLAKE CLRS & LAUNDERER S
Year: 2009
Address: 455 W 44TH ST

U121
North
< 1/8
0.104 mi.
549 ft.

455 WEST 44TH STREET
455 WEST 44TH STREET
NEW YORK, NY 10036

NY AST U003393292
NY HIST AST N/A

Site 2 of 3 in cluster U

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-358436
Program Type: PBS
UTM X: 585014.46302000002
UTM Y: 4512659.1326099997
Expiration Date: 10/23/2017
Site Type: Apartment Building/Office Building

Actual:
31 ft.

Affiliation Records:

Site Id: 17979
Affiliation Type: Facility Owner
Company Name: ROMEO KILO CORPORATION
Contact Type: VP
Contact Name: ANTHONY M. KISSLING
Address1: 350 FIFTH AVENUE SUITE 7717
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10118
Country Code: 001
Phone: (212) 947-1540

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

455 WEST 44TH STREET (Continued)

U003393292

EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2/23/2012

Site Id: 17979
Affiliation Type: Mail Contact
Company Name: ROMEO KILO CORPORATION
Contact Type: Not reported
Contact Name: ANTHONY M. KISSLING
Address1: 350 FIFTH AVENUE, SUITE 7717
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10118
Country Code: 001
Phone: (212) 947-1540
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 10/11/2007

Site Id: 17979
Affiliation Type: On-Site Operator
Company Name: 455 WEST 44TH STREET
Contact Type: Not reported
Contact Name: GREGORY MCNALLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-8973
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 10/11/2007

Site Id: 17979
Affiliation Type: Emergency Contact
Company Name: ROMEO KILO CORPORATION
Contact Type: Not reported
Contact Name: ANTHONY M. KISSLING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 947-1540
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

455 WEST 44TH STREET (Continued)

U003393292

Tank Info:

Tank Number: 001
Tank Id: 26650
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/16/1946
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: msbaptis
Last Modified: 10/11/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-358436
SWIS Code: 6201
Operator: GREGORY MCNALLY
Facility Phone: (000) 000-0000
Facility Addr2: 455 WEST 44TH STREET
Facility Type: Not reported
Emergency: ANTHONY M. KISSLING
Emergency Tel: (212) 947-1540
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: ROMEO KILO CORPORATION
Owner Address: 350 FIFTH AVENUE SUITE 5519
Owner City,St,Zip: NEW YORK, NY 10118
Federal ID: Not reported
Owner Tel: (212) 947-1540
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: ANTHONY M. KISSLING
Mailing Name: ROMEO KILO CORPORATION
Mailing Address: 350 FIFTH AVENUE, SUITE 5519

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

455 WEST 44TH STREET (Continued)

U003393292

Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10118
Mailing Telephone: (212) 877-6222
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/07/1998
Expiration: 10/23/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Not reported
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

S122
South
< 1/8
0.104 mi.
550 ft.

CON EDISION - MH61468
547- 9TH AVE 547- 9TH AVE
NEW YORK, NY 10003

RCRA NonGen / NLR
NY MANIFEST

1007208073
NYP004081410

Site 2 of 2 in cluster S

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 06/02/2002

Facility name: CON EDISION - MH61468

Facility address: 547- 9TH AVE 547- 9TH AVE

NEW YORK, NY 10003

EPA ID: NYP004081410

Mailing address: IRVING PLACE

NEW YORK, NY 10003

Contact: ANTHONY DRUMMINGS

Contact address: IRVING PLACE

NEW YORK, NY 10003

Contact country: US

Contact telephone: (212) 460-3770

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
33 ft.

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Historical Generators:

Date form received by agency: 06/01/2002

Site name: CON EDISION - MH61468

Classification: Not a generator, verified

Date form received by agency: 05/31/2002

Site name: CON EDISION - MH61468

Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004081410

Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON

Contact: FRANKLIN MURRAY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - MH61468 (Continued)

1007208073

Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0760455
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/02/2001
Trans1 Recv Date: 05/02/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/03/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004081410
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 80416AB
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00790
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYE0680553
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: NYD006982359
Generator Ship Date: 05/02/2001
Trans1 Recv Date: 05/02/2001
Trans2 Recv Date: 05/03/2001
TSD Site Recv Date: 05/03/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004081410
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSD ID: 60913AX
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00219
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

V123
East
< 1/8
0.105 mi.
552 ft.

CONSOLIDATED EDISON
V0365-144 W 43RD ST
NEW YORK, NY 10020

Site 1 of 6 in cluster V

NY MANIFEST **1009239079**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004056917
Country: USA

Actual:
37 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0668457
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 06/19/2000
Trans1 Recv Date: 06/19/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004056917
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00874
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYE0669096
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2000
Trans1 Recv Date: 09/29/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/29/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004062899
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00929
Units: K - Kilograms (2.2 pounds)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009239079

Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

EPA ID: NYP004062899
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0668457
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 06/19/2000
Trans1 Recv Date: 06/19/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004056917
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00874
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

Document ID: NYE0669096
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/29/2000
Trans1 Recv Date: 09/29/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/29/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004062899
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20856AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00929

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009239079

Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2000

**T124
SE
< 1/8
0.108 mi.
570 ft.**

**CON EDISON
358 W 42ND ST
NEW YORK, NY 10036**

**NY MANIFEST S112210637
N/A**

Site 2 of 9 in cluster T

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004268231
Country: USA

**Actual:
37 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268231
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456576JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210637

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268231
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456576JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

T125
SE
< 1/8
0.108 mi.
570 ft.

CON EDISON SERVICE BOX: 8121
358 W 42ND ST
NEW YORK, NY 10036
Site 3 of 9 in cluster T

RCRA-CESQG 1016144036
FINDS NYP004268231

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 8121
Facility address: 358 W 42ND ST
NEW YORK, NY 10036
EPA ID: NYP004268231
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931

Actual:
37 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8121 (Continued)

1016144036

Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458856

Environmental Interest/Information System

U126
North
< 1/8
0.110 mi.
579 ft.
461 WEST 44TH STREET OWNERS CORP.
461 WEST 44TH STREET
NEW YORK, NY 10036
Site 3 of 3 in cluster U

NY AST **U003387601**
N/A

Relative:
Lower

AST:

Actual:
31 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-092118
Program Type: PBS
UTM X: 585000.36442
UTM Y: 4512666.5201300001
Expiration Date: 10/14/2018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

461 WEST 44TH STREET OWNERS CORP. (Continued)

U003387601

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2353
Affiliation Type: Facility Owner
Company Name: 461 W 44 ST OWNERS CORP % VERITAS MGMT
Contact Type: Not reported
Contact Name: Not reported
Address1: 180 W 80 ST, STE 218
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 799-2365
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2014

Site Id: 2353
Affiliation Type: Mail Contact
Company Name: VERITAS PROPERTY MANAGEMENT
Contact Type: Not reported
Contact Name: CARL BORENSTEIN
Address1: 180 WEST 80TH STREET
Address2: SUITE 218
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 799-2365
EMail: CARL@VERITASMANAGEMENT.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/9/2014

Site Id: 2353
Affiliation Type: On-Site Operator
Company Name: 461 WEST 44TH STREET OWNERS CORP.
Contact Type: Not reported
Contact Name: GREG KONOW
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-0776
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 12/11/2013

Site Id: 2353
Affiliation Type: Emergency Contact
Company Name: 461 WEST 44TH STREET OWNERS CORP.
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

461 WEST 44TH STREET OWNERS CORP. (Continued)

U003387601

Contact Name: GREG KONOW
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 228-4260
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 12/11/2013

Tank Info:

Tank Number: 001
Tank Id: 12270
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
H00 - Tank Leak Detection - None
K02 - Spill Prevention - Transfer Station Containment
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1931
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 12/11/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

V127
East
< 1/8
0.110 mi.
582 ft.

SPILL NUMBER 0111202
360 WEST 43RD ST
MANHATTAN, NY
Site 2 of 6 in cluster V

NY Spills S106001356
N/A

Relative:
Higher

Actual:
37 ft.

SPILLS:

Facility ID: 0111202
Facility Type: ER
DER Facility ID: 165473
Site ID: 198835
DEC Region: 2
Spill Date: 2/25/2002
Spill Number/Closed Date: 0111202 / 4/11/2002
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 2/25/2002
CID: 396
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/25/2002
Spill Record Last Update: 4/11/2002
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: JAMES MATTERN
Contact Phone: (610) 909-1659
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"02/27/2002 Material stockpiled, tank cleaned and removed. Overexcavation of contaminated soils is to occur, TANK REGISTRATION AND REPORT TO FOLLOW. ONE COMPOSITE SAMPLE TO BE TAKEN FROM BELOW STOCKPILE AS PER SITE VISIT DISCUSSION.04/11/2002 no further action sent based on site visit and submittal from hydroscience inc.

Remarks: SOME OF THE MATERIAL HAS BEEN STOCKPILED...CLEAN UP WILL CONTINUE TOMORROW...THEY WILL GET MORE INFO ON RP AND NOTIFY. SPILL WAS DUE TO AN EXCAVATOR HITTING AN UNDERGROUND TANK...TANK WAS NOT LOCATED ACCURALTY.

Material:

Site ID: 198835
Operable Unit ID: 848275
Operable Unit: 01
Material ID: 528795
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0111202 (Continued)

S106001356

Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0710714
Facility Type: ER
DER Facility ID: 165473
Site ID: 392055
DEC Region: 2
Spill Date: 1/10/2008
Spill Number/Closed Date: 0710714 / 1/11/2008
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 1/10/2008
CID: 27
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/10/2008
Spill Record Last Update: 6/16/2008
Spiller Name: Not reported
Spiller Company: ENTERPRISE TRANSPORTATION
Spiller Address: Not reported
Spiller City,St,Zip: BROOKLYN, NY 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: DEC Piper spoke w. PTC. As per Joe, spill was 30-40 gallons on sidewalk of 42nd and 9th ave. about 10 gal spilled out top of manway. All cleaned and powerwashed. closed.
Remarks: Patroleum Tank Cleaners are enroute for cleanup. Caller reports a faulty guage on a 15,000 gallon tank. Spill was from the vent pipe.

Material:

Site ID: 392055
Operable Unit ID: 1149083
Operable Unit: 01
Material ID: 2139588
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0111202 (Continued)

S106001356

Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

V128
East
< 1/8
0.110 mi.
582 ft.

APARTMENT BUILDING
360 W 43RD ST
MANHATTAN, NY

NY Spills S107416652
N/A

Site 3 of 6 in cluster V

Relative:
Higher

Actual:
37 ft.

SPILLS:

Facility ID: 0514678
Facility Type: ER
DER Facility ID: 311676
Site ID: 361456
DEC Region: 2
Spill Date: 3/23/2006
Spill Number/Closed Date: 0514678 / 3/31/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/23/2006
CID: 74
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/23/2006
Spill Record Last Update: 3/31/2006
Spiller Name: RUDY (SUPER)
Spiller Company: URBAN ASSOCIATES
Spiller Address: 360 W 43RD ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: (212) 245-1870
DEC Memo: Sangesland spoke to Hess. Cleanup was completed
Remarks: Contractor has been called to cleanup as well as Hess cleanup crewpossibly a bad gauge - spilled out of the vent during delivery - gauge indicated there was enough room.Spilled onto sidewalk and streetRudy (212) 765-2444

Material:
Site ID:

361456

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BUILDING (Continued)

S107416652

Operable Unit ID: 1119603
Operable Unit: 01
Material ID: 2109051
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0509345
Facility Type: ER
DER Facility ID: 311676
Site ID: 355111
DEC Region: 2
Spill Date: 11/4/2005
Spill Number/Closed Date: 0509345 / 11/7/2005
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 11/4/2005
CID: 77
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/4/2005
Spill Record Last Update: 6/16/2008
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: 360 W 43 RD ST
Spiller City,St,Zip: MANHATTAN, NY 001
Contact Name: NICHOLAS PASQUEL
Contact Phone: (201) 489-5100
DEC Memo: 11/7/05-Vought-Called Nicholas Paseal and spoke to Scott Williams and spill was on sidewalk and no sewers were affected. Owner contact info is: Rudy 212-765-2444 (Super), desk is 212-765-4204, 212-245-1870 (management company). Vought called desk (super was disconnected). Vought called super and spoke to him, he was content with cleanup of spill. Spill closed by Vought.
Remarks: oil came out of tank vent, faulty gauge. eastman tank cleaners contacted to perform clean-up.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BUILDING (Continued)

S107416652

Material:

Site ID: 355111
Operable Unit ID: 1112481
Operable Unit: 01
Material ID: 2102526
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

V129
East
< 1/8
0.110 mi.
582 ft.

360 W 43RD ST
NEW YORK, NY 10036

EDR US Hist Cleaners 1015049153
N/A

Site 4 of 6 in cluster V

Relative:
Higher

EDR Historical Cleaners:

Name: OXFORD CLEANERS
Year: 2006
Address: 360 W 43RD ST

Name: OXFORD CLEANERS
Year: 2007
Address: 360 W 43RD ST

Name: OXFORD CLEANERS
Year: 2008
Address: 360 W 43RD ST

Name: OXFORD CLEANERS
Year: 2010
Address: 360 W 43RD ST

Name: OXFORD CLEANERS
Year: 2011
Address: 360 W 43RD ST

Name: OXFORD CLEANERS
Year: 2012
Address: 360 W 43RD ST

Actual:
37 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W130
West
< 1/8
0.111 mi.
584 ft.
HUNTER COLLEGE, MFA
450 WEST 41ST STREET
NEW YORK, NY 10021
Site 1 of 2 in cluster W

NY AST **A100294437**
N/A

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609728
Program Type: PBS
UTM X: 584814.84354999999
UTM Y: 4512447.51123999999
Expiration Date: 10/12/2014
Site Type: School

Actual:
27 ft.

Affiliation Records:

Site Id: 332250
Affiliation Type: Facility Owner
Company Name: CITY UNIVERSITY OF NEW YORK
Contact Type: Not reported
Contact Name: Not reported
Address1: 205 EAST 42ND ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (616) 664-2354
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/11/2014

Site Id: 332250
Affiliation Type: Mail Contact
Company Name: HUNTER COLLEGE
Contact Type: Not reported
Contact Name: RICARDO FRANCO
Address1: 695 PARK AVENUE
Address2: ROOM E-1211A
City: NEW YORK
State: NY
Zip Code: 10055
Country Code: 001
Phone: (212) 772-4462
EMail: RFRANCO@HUNTER.CUNY.EDU
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/11/2014

Site Id: 332250
Affiliation Type: On-Site Operator
Company Name: HUNTER COLLEGE, MFA
Contact Type: Not reported
Contact Name: RICHARD MCGAULEY
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE, MFA (Continued)

A100294437

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-2154
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/11/2014

Site Id: 332250
Affiliation Type: Emergency Contact
Company Name: CITY UNIVERSITY OF NEW YORK
Contact Type: Not reported
Contact Name: RICARDO FRANCO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 772-4462
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/3/2009

Tank Info:

Tank Number: 001
Tank Id: 180404
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
E12 - Piping Secondary Containment - Double-Wall (Aboveground)
C03 - Pipe Location - Aboveground/Underground Combination
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1995
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE, MFA (Continued)

A100294437

Register: True
Modified By: NRLOMBAR
Last Modified: 03/11/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 180405
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
E12 - Piping Secondary Containment - Double-Wall (Aboveground)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2001
Capacity Gallons: 100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 03/11/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

131
NW
< 1/8
0.111 mi.
588 ft.

MANHATTAN PLAZA HEALTH CLUB
482 W.43RD STREET
NEW YORK, NY 10036

NY CBS UST **S102640974**
NY CBS **N/A**

Relative:
Lower

CBS UST:

Detail As of 1/1/2012:

Actual:
26 ft.

Id/Status: 2-000050 / TANK CONVERTED TO NON-REGULATED USE
Facility Type: FARM
Facility Tel: (212) 563-7001
Total Tanks: 0
Region: STATE
ICS No: 2-700271
PBS No: Not reported
MOSF No: Not reported
SPDES No: Not reported
Town: NEW YORK CITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHATTAN PLAZA HEALTH CLUB (Continued)

S102640974

Operator: JOHN SCHOLZ
Emergency Contact: ROBIN BAHR
Emergency Contact Phone: (212) 666-5397
Certification Date: 06/14/1989
Expiration Date: 06/02/1991
Owner Name: MANHATTAN PLAZA ASSOCIATES
Owner Address: 400 W.43RD STREET
Owner City,St,Zip: NEW YORK, NY 10036
Owner Phone: (212) 971-0660
Owner Type: 5
Owner Subtype: Not reported
Mail To Name: MANHATTAN PLAZA HEALTH CLUB
Mail To Contact: ROBIN BAHR
Mail To Address: 482 W.43RD STREET
Mail To Address 2: Not reported
Mail To City,St,Zip: NEW YORK, NY 10036
Mail To Telephone: (212) 563-7001

Tank Number: 001
Date Entered: 06/02/1989
Capacity: 500
Chemical: Chlorine
Tank Closed: 00/00
Tank Status: 2
Tank Type: Fiberglass reinforced plastic [FRP]
Install Date: 12/83
CAS No: 7782505
Substance: Not reported
Tank Location: Outdoors, Belowground
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Leak Detection: Not reported
Secondary Containment: None
Overfill Protection: Not reported
Haz Percent: 0
Pipe Containment: Not reported
Pipe Type: PLASTIC
Tank Error Status: Major Data Missing (which is on the certificate)
Tank Secret: False
Date Entered: 14:40:44
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6201
Cert Flag: False
Is it There: False
Is Updated: False
Owners Mark: First Owner
Lat/Long: Not reported
Renew Date: 03/13/91
Deliquent: False
Total Capacity: 0
Date Expired: 06/02/91
Case No: Not reported
Federal Amt: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHATTAN PLAZA HEALTH CLUB (Continued)

S102640974

Pipe Flag: False
Reserve Flag: False

Tank Number: 002
Date Entered: 06/02/1989
Capacity: 500
Chemical: Chlorine
Tank Closed: 00/00
Tank Status: 2
Tank Type: Fiberglass reinforced plastic [FRP]
Install Date: 12/83
CAS No: 7782505
Substance: Not reported
Tank Location: Outdoors, Belowground
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Leak Detection: Not reported
Secondary Containment: None
Overfill Protection: Not reported
Haz Percent: 0
Pipe Containment: Not reported
Pipe Type: PLASTIC
Tank Error Status: Major Data Missing (which is on the certificate)
Tank Secret: False
Date Entered: 14:41:13
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6201
Cert Flag: False
Is it There: False
Is Updated: False
Owners Mark: First Owner
Lat/Long: Not reported
Renew Date: 03/13/91
Deliquent: False
Total Capacity: 0
Date Expired: 06/02/91
Case No: Not reported
Federal Amt: True
Pipe Flag: False
Reserve Flag: False

CBS:
CBS Number: 2-000050
Program Type: CBS
Facility Status: Unregulated
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W132 **LOT 158,TAXBLOCK 1050**
West **454 WEST 41 STREET**
< 1/8 **MANHATTAN, NY 10036**
0.113 mi.
599 ft. **Site 2 of 2 in cluster W**

NY E DESIGNATION

S108075855
N/A

Relative:
Lower

E DESIGNATION:

Tax Lot(s): 158
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Underground Gasoline Storage Tanks* Testing Protocol.
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2002
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-3
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: HY
Special Purpose District2: Not reported
All Components1: C6-3/HY
All Components2: Not reported
Split Boundary Indicator: N
Building Class: L9
Land Use Category: 06
Number of Easements: 0
Owner, Type of Code: P
Owner Name: J. ALDEN ENTERPRISES,
Lot Area: 000001645
Total Building Floor Area: 00000003600
Commercial Floor Area: 00000001800
Office Floor Area: 00000001800
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 002.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0016.67
Lot Depth: 0098.75
Building Frontage: 0015.00
Building Depth: 0092.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5

Actual:
27 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 158,TAXBLOCK 1050 (Continued)

S108075855

Basement Type Grade: 5
Land Assessed Value: 00000078750
Total Assessed Value: 00000166050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1950
Year Built Code: E
Year Altered1: 1986
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.19
Maximum Allowable Far: 7.52
Borough Code: 1
Borough Tax Block And Lot: 1010500158
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985513
Y Coordinate: 0215598
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006
Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

Tax Lot(s): 158
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: MN
Community District: 104
Census Tract: 115
Census Block: 2002
School District: 02
City Council District: 03
Fire Company: L021
Health Area: 15
Police Precinct: 010
Zone District 1: C6-3
Zone District 2: Not reported
Commercial Overlay1: Not reported
Commercial Overlay2: Not reported
Special Purpose District1: HY
Special Purpose District2: Not reported
All Components1: C6-3/HY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 158,TAXBLOCK 1050 (Continued)

S108075855

All Components2: Not reported
Split Boundary Indicator: N
Building Class: L9
Land Use Category: 06
Number of Easements: 0
Owner, Type of Code: P
Owner Name: J. ALDEN ENTERPRISES,
Lot Area: 000001645
Total Building Floor Area: 00000003600
Commercial Floor Area: 00000001800
Office Floor Area: 00000001800
Retail Floor Area: 00000000000
Garage Floor Area: 00000000000
Storage Floor Area: 00000000000
Factory Floor Area: 00000000000
Other Floor Area: 00000000000
Floor Area,Total Bld Source Code7
Number of Buildings: 00001
Number of Floors: 002.00
Residential Units: 00000
Non and Residential Units: 00003
Lot Frontage: 0016.67
Lot Depth: 0098.75
Building Frontage: 0015.00
Building Depth: 0092.00
Proximity Code: 3
Irregular Lot Code: N
Lot Type: 5
Basement Type Grade: 5
Land Assessed Value: 00000078750
Total Assessed Value: 00000166050
Land Exempt Value: 00000000000
Total Exempt Value: 00000000000
Year Built: 1950
Year Built Code: E
Year Altered1: 1986
Year Altered2: 0000
Historic District Name: Not reported
Landmark Name: Not reported
Built Floor Area Ratio-Far: 0002.19
Maximum Allowable Far: 7.52
Borough Code: 1
Borough Tax Block And Lot: 1010500158
Condominium Number: 00000
Census Tract 2: 0115
X Coordinate: 0985513
Y Coordinate: 0215598
Zoning Map: 08D
Sanborn Map: 105N041
Tax Map: 10404
E Designation No: E-137
Date of RPAD Data: 11/2005
Date of DCAS Data: 01/2006
Date of Zoning Data: 11/2005
Date of Major Property Data: 11/2005
Date of Landmark Data: 12/2005
Date of Base Map Data: 01/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 158,TAXBLOCK 1050 (Continued)

S108075855

Date of Mass Appraisal Data: 11/2005
Date of Political and Adm Data: 08/2005
Pluto-Base Map Indicator: 1

**X133
NE
< 1/8
0.115 mi.
606 ft.**

**GUFFANTI FILM LABORATORIES INC
630 9TH AVE
NEW YORK, NY 10036
Site 1 of 7 in cluster X**

**RCRA NonGen / NLR 1000227831
NY CBS AST NYD064995665**

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
36 ft.**

Date form received by agency: 01/01/2007
Facility name: GUFFANTI FILM LABORATORIES INC
Facility address: 630 9TH AVE
NEW YORK, NY 10036
EPA ID: NYD064995665
Mailing address: 9TH AVE
NEW YORK, NY 10036
Contact: Not reported
Contact address: 9TH AVE
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: GUFFANTI PAUL
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: GUFFANTI PAUL
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: GUFFANTI FILM LABORATORIES INC
Classification: Not a generator, verified

Date form received by agency: 03/28/1995
Site name: GUFFANTI FILM LABORATORIES INC
Classification: Not a generator, verified

Date form received by agency: 11/20/1980
Site name: GUFFANTI FILM LABORATORIES INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/13/1989
Date achieved compliance: 02/09/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/13/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/27/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/09/1990
Evaluation lead agency: State

CBS AST:

CBS Number: 2-000090
ICS Number: 2-179646
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: D
Telephone: (212) 265-5530
Facility Town: NEW YORK CITY
Region: STATE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

Expiration Date: 07/07/1997
Total Capacity of All Active Tanks(gal): 0
Operator: GUFFANI FILM LABORATORY
Emergency Contact: FRANK HAUSER
Emergency Phone: (212) 265-5530
Owner Name: GUFFANI FILM LABORATORY
Owner Address: 630 9TH AVENUE
Owner City,St,Zip: NEW YORK, NY 10036
Owner Telephone: (212) 265-5530
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: GUFFANI FILM LABORATORY
Mail Contact Addr: 630 9TH AVENUE
Mail Contact Addr2: Not reported
Mail Contact Contact: FRANK HAUSER
Mail Contact City,St,Zip: NEW YORK, NY 10036
Mail Phone: (212) 265-5530

Tank Id: 4
CAS Number: 123319
Federal ID: Not reported
Tank Status: 0
Install Date: 09/40
Tank Closed: 11/97
Capacity (Gal): 200
Chemical: Hydroquinone
Tank Location: Indoors, Aboveground
Tank Type: Stainless steel alloy
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: None
Tank Error Status: No Missing Data
Date Entered: 07/07/1989
Certified Date: 06/06/1995
Substance: Single Hazardous Substance on DEC List
Internal Protection: Fiberglass Liner (FRP
External Protection: None
Pipe Location: Aboveground
Pipe Type: Double Walled Fiberglass
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 5
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6201
Lat/Long: Not reported
Is Updated: False
Renew Date: 04/01/93
Is It There: False
Delinquent: False
Date Expired: 07/07/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 10/08/1998

Tank Id: 5
CAS Number: 95807
Federal ID: Not reported
Tank Status: 0
Install Date: 07/87
Tank Closed: 11/97
Capacity (Gal): 400
Chemical: Toluenediamine
Tank Location: Indoors, Aboveground
Tank Type: Stainless steel alloy
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: None
Tank Error Status: No Missing Data
Date Entered: 07/07/1989
Certified Date: 06/06/1995
Substance: Single Hazardous Substance on DEC List
Internal Protection: None
External Protection: None
Pipe Location: Aboveground
Pipe Type: Double Walled Fiberglass
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 6
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6201
Lat/Long: Not reported
Is Updated: False
Renew Date: 04/01/93
Is It There: False
Delinquent: False
Date Expired: 07/07/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 10/08/1998

Tank Id: 1
CAS Number: 7783188
Federal ID: Not reported
Tank Status: 0
Install Date: 06/68
Tank Closed: 00/00
Capacity (Gal): 500
Chemical: Not reported
Tank Location: Indoors, Aboveground
Tank Type: Stainless steel alloy

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: None
Tank Error Status: No Missing Data
Date Entered: 07/07/1989
Certified Date: 06/06/1995
Substance: Single Hazardous Substance on DEC List
Internal Protection: None
External Protection: None
Pipe Location: Aboveground
Pipe Type: Double Walled Fiberglass
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 1
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6201
Lat/Long: Not reported
Is Updated: False
Renew Date: 04/01/93
Is It There: False
Delinquent: False
Date Expired: 07/07/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 10/08/1998

Tank Id: 2
CAS Number: 95807
Federal ID: Not reported
Tank Status: 0
Install Date: 06/68
Tank Closed: 11/97
Capacity (Gal): 500
Chemical: Toluenediamine
Tank Location: Indoors, Aboveground
Tank Type: Stainless steel alloy
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: None
Tank Error Status: No Missing Data
Date Entered: 07/07/1989
Certified Date: 06/06/1995
Substance: Single Hazardous Substance on DEC List
Internal Protection: None
External Protection: None
Pipe Location: Aboveground
Pipe Type: Double Walled Fiberglass
Pipe Internal: None
Pipe External: None
Pipe Flag: None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

Leak Detection:	None
Overfill Protection:	None
Haz Percent:	6
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6201
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	10/08/1998
Tank Id:	3
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	0
Install Date:	05/81
Tank Closed:	11/97
Capacity (Gal):	200
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data
Date Entered:	07/07/1989
Certified Date:	06/06/1995
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Fiberglass Liner (FRP)
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	5
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6201
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORIES INC (Continued)

1000227831

Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 10/08/1998

[Click this hyperlink](#) while viewing on your computer to access
additional NY_AST_CBS: detail in the EDR Site Report.

**X134
NE
< 1/8
0.115 mi.
606 ft.**

**CINE 60 INC
630 9TH AVE - ROOM #209
NEW YORK, NY 10036**

**RCRA NonGen / NLR 1000171927
NY MANIFEST NYD043176627**

Site 2 of 7 in cluster X

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
36 ft.**

Date form received by agency: 01/01/2007
Facility name: CINE 60 INC
Facility address: 630 9TH AVE - ROOM #209
NEW YORK, NY 100363708
EPA ID: NYD043176627
Mailing address: 9TH AVE - ROOM #209
NEW YORK, NY 100363708
Contact: Not reported
Contact address: 9TH AVE - ROOM #209
NEW YORK, NY 100363708
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NEWMARK & CO REAL ESTATE INC
Owner/operator address: 125 PARK AVE - 11TH FLOOR
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: (212) 354-2500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEWMARK & CO REAL ESTATE INC
Owner/operator address: 125 PARK AVE - 11TH FLOOR
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: (212) 354-2500
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CINE 60 INC (Continued)

1000171927

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: CINE 60 INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: CINE 60 INC
Classification: Not a generator, verified

Date form received by agency: 10/04/1995
Site name: CINE 60 INC
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD043176627
Country: USA

Mailing Info:

Name: CINE 60 INC
Contact: MAHENDRA SHAH
Address: 630 9TH AVENUE - ROOM #209
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-586-8782

Document ID: PAE4697991
Manifest Status: Completed copy
Trans1 State ID: PAAH0242
Trans2 State ID: PAAH0242
Generator Ship Date: 960322
Trans1 Recv Date: 960322
Trans2 Recv Date: 960324
TSD Site Recv Date: 960325
Part A Recv Date: Not reported
Part B Recv Date: 960402
Generator EPA ID: NYD043176627
Trans1 EPA ID: CTD983872748
Trans2 EPA ID: CTD983872748
TSD ID: PAD087561015
Waste Code: D006 - CADMIUM 1.0 MG/L TCLP
Quantity: 08040
Units: P - Pounds
Number of Containers: 120

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CINE 60 INC (Continued)

1000171927

Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

**X135
NE
< 1/8
0.115 mi.
606 ft.**

**ACCUTREAT FILMS INC
630 NINTH AVE - ROOM 1101
NEW YORK, NY 10019**

RCRA NonGen / NLR

**1000994286
NYD094324217**

Site 3 of 7 in cluster X

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: ACCUTREAT FILMS INC

Facility address: 630 NINTH AVE - ROOM 1101
NEW YORK, NY 10019

EPA ID: NYD094324217

Mailing address: NINTH AVE - ROOM 1101
NEW YORK, NY 10019

Contact: Not reported

Contact address: NINTH AVE - ROOM 1101
NEW YORK, NY 10019

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ROVIC VLADO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: ROVIC VLADO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ACCUTREAT FILMS INC (Continued)

1000994286

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: ACCUTREAT FILMS INC
Classification: Not a generator, verified

Date form received by agency: 04/05/1995
Site name: ACCUTREAT FILMS INC
Classification: Unverified

Date form received by agency: 06/16/1981
Site name: ACCUTREAT FILMS INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/09/1988
Date achieved compliance: 08/26/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/01/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 06/09/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/26/1988
Evaluation lead agency: State

X136
NE
< 1/8
0.115 mi.
606 ft.
630 9TH AVENUE
630 9TH AVENUE
NEW YORK, NY 10036

NY AST
NY HIST AST
U003395286
N/A

Site 4 of 7 in cluster X

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-481912

Actual:
36 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

630 9TH AVENUE (Continued)

U003395286

Program Type: PBS
UTM X: 585168.34826
UTM Y: 4512616.2708900003
Expiration Date: 09/11/2015
Site Type: Other

Affiliation Records:

Site Id: 21571
Affiliation Type: Facility Owner
Company Name: GSH ASSOCIATES % NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: Not reported
Address1: 1501 BROADWAY - SUITE 1914
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 354-2930
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2013

Site Id: 21571
Affiliation Type: Mail Contact
Company Name: NEWMARK GRUBB KNIGHT FRANK.
Contact Type: Not reported
Contact Name: SAM MOHABIR
Address1: 1501 BROADWAY
Address2: SUITE 1914
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 354-2930
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2013

Site Id: 21571
Affiliation Type: On-Site Operator
Company Name: 630 9TH AVENUE
Contact Type: Not reported
Contact Name: MIKE SANTOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 757-6995
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

630 9TH AVENUE (Continued)

U003395286

Site Id: 21571
Affiliation Type: Emergency Contact
Company Name: GSH ASSOCIATES % NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: MIKE SANTOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 757-6995
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2013

Tank Info:

Tank Number: 001
Tank Id: 39229
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1961
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 11/20/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-481912
SWIS Code: 6201

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

630 9TH AVENUE (Continued)

U003395286

Operator: NEWMARK & CO. REAL ESTATE
Facility Phone: (212) 757-6995
Facility Addr2: 630 9TH AVENUE
Facility Type: OTHER
Emergency: MENENDEZ
Emergency Tel: (718) 651-4252
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: GSH ASSOCIATES C/O NEWMARK COMPANY REAL EST. INC.
Owner Address: 125 PARK AVENUE
Owner City,St,Zip: NEW YORK, NY 10017
Federal ID: Not reported
Owner Tel: (212) 372-2000
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: GSH ASSOCIATES
Mailing Address: C/O NEWMARK & CO. REAL ESTATE, INC.
Mailing Address 2: 125 PARK AVENUE
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Telephone: (212) 372-2000
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/25/2000
Expiration: 09/11/2005
Renew Flag: False
Renew Date: Not reported
Total Capacity: 10000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 10000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

630 9TH AVENUE (Continued)

U003395286

Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

**X137
NE
< 1/8
0.115 mi.
606 ft.**

**FILM CENTER
630 9TH AVE ROOM 208
NEW YORK, NY 10036

Site 5 of 7 in cluster X**

**RCRA NonGen / NLR 1004760000
NY MANIFEST NYR000028910**

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: FILM CENTER

Facility address: 630 9TH AVE ROOM 208
NEW YORK, NY 10036

EPA ID: NYR000028910

Mailing address: 9TH AVE ROOM 208
NEW YORK, NY 10036

Contact: JAY WANDER

Contact address: 9TH AVE ROOM 208
NEW YORK, NY 10036

Contact country: US

Contact telephone: (212) 539-8944

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: KENNETH E SCHWARTZ

Owner/operator address: 630 9TH AVE
NEW YORK, NY 10036

Owner/operator country: US

Owner/operator telephone: (212) 596-2557

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: KENNETH E SCHWARTZ

Owner/operator address: 630 9TH AVE
NEW YORK, NY 10036

Owner/operator country: US

Owner/operator telephone: (212) 596-2557

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FILM CENTER (Continued)

1004760000

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: FILM CENTER
Classification: Not a generator, verified

Date form received by agency: 09/30/1996
Site name: FILM CENTER
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYR000028910
Country: USA

Mailing Info:

Name: FILM CENTER
Contact: JAY WANDER
Address: 630 9TH AVENUE ROOM 208
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-539-8944

Document ID: NYB7142265
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 0902205
Trans2 State ID: Not reported
Generator Ship Date: 961001
Trans1 Recv Date: 961001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961014
Part A Recv Date: 961016
Part B Recv Date: 961114
Generator EPA ID: NYR000028910
Trans1 EPA ID: OHD009865825
Trans2 EPA ID: Not reported
TSDF ID: GAD000222083

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FILM CENTER (Continued)

1004760000

Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00400
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

X138
NE
< 1/8
0.115 mi.
606 ft.

GUFFANTI FILM LABORATORY
630 9TH AVE
NEW YORK, NY 10036
Site 6 of 7 in cluster X

FINDS
NY MANIFEST
NY CBS

1010211141
N/A

Relative:
Higher

FINDS:

Registry ID: 110029252289

Actual:
36 ft.

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD094324217
Country: USA

Mailing Info:

Name: ACCUTREAT FILM INCORPORATED
Contact: NICK FALACCI
Address: 630 9TH AVENUE
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 000-000-0000

NY MANIFEST:

No Manifest Records Available

EPA ID: NYD064995665
Country: USA

Mailing Info:

Name: GUFFANTI FILM LABORATORY
Contact: HAUSER FRANK PLANT MGR
Address: 630 9TH AVE
City/State/Zip: NEW YORK, NY 10036

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GUFFANTI FILM LABORATORY (Continued)

1010211141

Country: USA
Phone: 212-265-5530

NY MANIFEST:

No Manifest Records Available

CBS:

CBS Number: 2-000090
Program Type: CBS
Facility Status: Unregulated
Expiration Date: Not reported
Dec Region: 2
UTMX: 585131.70976
UTMY: 4512602.2210900

**X139
NE
< 1/8
0.115 mi.
606 ft.**

**SHERMAN GRINBERG FILM LIBRARY
630 9TH AVE
NEW YORK, NY 10036
Site 7 of 7 in cluster X**

**RCRA NonGen / NLR 1000912349
FINDS NY0000615500**

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: SHERMAN GRINBERG FILM LIBRARY
Facility address: 630 9TH AVE
NEW YORK, NY 10036
EPA ID: NY0000615500
Mailing address: 9TH AVE
NEW YORK, NY 10036
Contact: Not reported
Contact address: 9TH AVE
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

**Actual:
36 ft.**

Owner/Operator Summary:

Owner/operator name: SEQUENT COMMUNICATIONS
Owner/operator address: 60 E 42ND ST
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: (212) 599-2300
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SEQUENT COMMUNICATIONS
Owner/operator address: 60 E 42ND ST
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: (212) 599-2300
Legal status: Private

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHERMAN GRINBERG FILM LIBRARY (Continued)

1000912349

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: SHERMAN GRINBERG FILM LIBRARY
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: SHERMAN GRINBERG FILM LIBRARY
Classification: Not a generator, verified

Date form received by agency: 08/25/1994
Site name: SHERMAN GRINBERG FILM LIBRARY
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002092761

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110009462492

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SHERMAN GRINBERG FILM LIBRARY (Continued)

1000912349

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

V140 **356 WEST 43 STREET**
ESE **356 WEST 43 ST.**
< 1/8 **NEW YORK, NY 10036**
0.116 mi.
615 ft.

NY AST **A100292229**
 N/A

Site 5 of 6 in cluster V

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608845
Program Type: PBS
UTM X: 585173.94588000001
UTM Y: 4512442.1951000001
Expiration Date: 04/15/2013
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30694
Affiliation Type: Facility Owner
Company Name: 42/9 RESIDENTIAL, LLC
Contact Type: PROPERTY MANAGER
Contact Name: RALPH CRUZ
Address1: 400 WEST 59 ST. 3RD FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 245-1870
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 1/30/2008

Site Id: 30694
Affiliation Type: Mail Contact
Company Name: 42/9 RESIDENTIAL LLC
Contact Type: Not reported
Contact Name: RALPH CRUZ
Address1: 400 WEST 59 STREET
Address2: 3RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 896-5527
EMail: RCRUZ@BRODSKYORG.COM
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 1/30/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

356 WEST 43 STREET (Continued)

A100292229

Site Id: 30694
Affiliation Type: On-Site Operator
Company Name: 356 WEST 43 STREET
Contact Type: Not reported
Contact Name: RUDY KOVIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 765-2444
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 30694
Affiliation Type: Emergency Contact
Company Name: 42/9 RESIDENTIAL, LLC
Contact Type: Not reported
Contact Name: RALPH CRUZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-1870
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 778
Tank Id: 65870
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

356 WEST 43 STREET (Continued)

A100292229

Pipe Model: Not reported
Install Date: 01/06/2003
Capacity Gallons: 15000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #6 Fuel Oil (On-Site Consumption)

**141
SSW
< 1/8
0.117 mi.
617 ft.**

**40TH STREET
DYER STREET/9TH & 10TH AV
NEW YORK, NY**

**NY Spills S102402100
N/A**

**Relative:
Lower**

SPILLS:

Facility ID: 9608237
Facility Type: ER
DER Facility ID: 153715
Site ID: 183654
DEC Region: 2
Spill Date: 10/2/1996
Spill Number/Closed Date: 9608237 / 10/10/1996
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 10/2/1996
CID: 205
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/2/1996
Spill Record Last Update: 10/18/1996
Spiller Name: CALLER
Spiller Company: PORT AUTHORITY
Spiller Address: PROVOST ST & 13TH ST
Spiller City,St,Zip: JERSEY CITY, NJ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: BROKEN PIPE, VALVE CLOSED FOR NOW TO STOP LEAK.

Material:

Site ID: 183654
Operable Unit ID: 1039268

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

40TH STREET (Continued)

S102402100

Operable Unit: 01
Material ID: 343976
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 30
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Y142
SSW
< 1/8
0.120 mi.
634 ft.

**BAPTIST CHURCH
410 WEST 40TH
NEW YORK, NY**

**NY LTANKS S109064182
N/A**

Site 1 of 8 in cluster Y

**Relative:
Higher**

LTANKS:

**Actual:
32 ft.**

Site ID: 394964
Spill Number/Closed Date: 0713240 / 8/14/2008
Spill Date: 3/14/2008
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 3/14/2008
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/14/2008
Spill Record Last Update: 8/14/2008
Spiller Name: ANITA MASSENGILL
Spiller Company: BAPTIST CHURCH
Spiller Address: 410 WEST 40TH
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: ANITA MASSENGILL
Spiller Phone: (212) 594-4464
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 344509
DEC Memo: Church thought they were using more oil than usual. Hired ProTest to pressure test the tank (outside/buried 1080 gal)(Non-PBS site). Tank could not hold any pressure (gross failure).ProTest is working with

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAPTIST CHURCH (Continued)

S109064182

the church to set up temp tanks and will begin the process of opening the old tank to see how much of a problem there is. Tank has been pumped and cleaned. Soilborings will be conducted shortly. 5/5/08- DECP iper reviewed closure report. As per report, tank was cut open and inspected. no holes were identified in tank. Geoprobe investigation revealed no vocs and no elevated SVOC.s Tan kwill be abandoned and new tan kwill be installed in basemnt. CLOsed. see e-docs if warranted.

Remarks: GROSS LEAK

Material:

Site ID: 394964
Operable Unit ID: 1151911
Operable Unit: 01
Material ID: 2142676
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 394964
Spill Tank Test: 2384845
Tank Number: Not reported
Tank Size: 1080
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 3/14/2008
Test Method: Horner EZ Check I or II

Y143
SSW
< 1/8
0.121 mi.
641 ft.

**BETWEEN WEST 40TH & 41
9TH AVENUE
MANHATTAN, NY**
Site 2 of 8 in cluster Y

**NY Spills S106736975
N/A**

**Relative:
Higher**

SPILLS:

Facility ID: 0411407
Facility Type: ER
DER Facility ID: 73205
Site ID: 336592
DEC Region: 2
Spill Date: 1/21/2005
Spill Number/Closed Date: 0411407 / 7/12/2006
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: SXLASDIN

**Actual:
32 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BETWEEN WEST 40TH & 41 (Continued)

S106736975

Referred To: Not reported
Reported to Dept: 1/21/2005
CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/21/2005
Spill Record Last Update: 7/12/2006
Spiller Name: SGT. SORAN
Spiller Company: BETWEEN WEST 40TH & 41
Spiller Address: 9TH AVE
Spiller City,St,Zip: MANHATTEN, NY
Spiller Company: 001
Contact Name: SGT. SORAN
Contact Phone: (212) 502-2504
DEC Memo: 1/21/05 Sangesland spoke with Bernie DeLeo of Port Authority Facilities Dept at the Bus Depot (tel # 212-502-2472) He said there was a leak in the warming fluid used within the driving ramps connecting the 2nd & 3rd floors of the Bus Depot with the Linclon Tunnel.A material known as "Savaloid"??? (could not find it on internet) is some type of oil/liquid which is heated up and then pumped through the system to warm up the ramps and prevent the formation of ice. Some where in the ramp, there is a leak which is dripping this product onto 9th Ave. NYPD has closed 9th Ave and Port Authority has spread Speedie Dry to absorb what has already fallen.Mr. DeLeo says that Port Authority is trying to locate the spill source and will stop the leak ASAP.07/12/06: spill on street, already cleaned up, DEP involved, assume leak was repaired. close
Remarks: OIL LEAKINGH FROM PORT AUTHORITY RAMP UNTO STREET: STREET HAS BEEN CLOSED AND POLICE ON SCENE:
Material:
Site ID: 336592
Operable Unit ID: 1098613
Operable Unit: 01
Material ID: 578782
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Y144
SSW
< 1/8
0.122 mi.
642 ft.

GASETERIA
403 W. 40TH ST
NEW YORK, NY

Site 3 of 8 in cluster Y

NY Spills **S104495851**
N/A

Relative:
Higher

Actual:
32 ft.

SPILLS:

Facility ID: 9411896
Facility Type: ER
DER Facility ID: 88885
Site ID: 100059
DEC Region: 2
Spill Date: 12/6/1994
Spill Number/Closed Date: 9411896 / 1/26/1996
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 12/6/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/24/1995
Spill Record Last Update: 1/12/2004
Spiller Name: Not reported
Spiller Company: GASETERIA
Spiller Address: 466 10TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ROMMEL"SEE SPILL # 8909614

Remarks: NOTIFIER SAYS STAINS ON FLOOR & WALL BOTTOM & HEAVY GASOLINE ODOR.
HAZMAT IS NOPTIFIED.

Material:

Site ID: 100059
Operable Unit ID: 1009760
Operable Unit: 01
Material ID: 374236
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GASETERIA (Continued)

S104495851

Tank Test:

**T145
SE
< 1/8
0.122 mi.
642 ft.**

**INFRONT
330 WEST 42ND ST
MANHATTAN, NY**

NY Spills

**S104508206
N/A**

Site 4 of 9 in cluster T

**Relative:
Higher**

SPILLS:

**Actual:
37 ft.**

Facility ID: 9907804
Facility Type: ER
DER Facility ID: 249511
Site ID: 308962
DEC Region: 2
Spill Date: 9/28/1999
Spill Number/Closed Date: 9907804 / 2/25/2003
Spill Cause: Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 9/28/1999
CID: 257
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/28/1999
Spill Record Last Update: 2/25/2003
Spiller Name: JOSEPH MANNEY
Spiller Company: INTERNATIONAL BUS SERVICE
Spiller Address: 17 FRANKLYN TURNPIKE
Spiller City,St,Zip: MAHWAH, NJ
Spiller Company: 001
Contact Name: FF DEMEO
Contact Phone: (917) 769-0483
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TOMSELLO"2/25/2003 - Closed Due To The Nature / Extent Of The Spill
Report

Remarks: BUS WAS ON FIRE SOME MIGHT HAVE GOTTEN INTO THE SEWER

Material:

Site ID: 308962
Operable Unit ID: 1086483
Operable Unit: 01
Material ID: 300486
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INFRONT (Continued)

S104508206

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 308962
Operable Unit ID: 1086483
Operable Unit: 01
Material ID: 300487
Material Code: 0021
Material Name: Transmission Fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

T146
SE
< 1/8
0.122 mi.
646 ft.

HOLLAND HOUSE
351 WEST 42ND STREET
NEW YORK, NY 10036

NY UST
NY HIST UST

U001842032
N/A

Site 5 of 9 in cluster T

Relative:
Higher

Actual:
38 ft.

UST:
Id/Status: 2-601680 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/30/2008
UTM X: 585187.62141000002
UTM Y: 4512379.1313100001
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 23642
Affiliation Type: Mail Contact
Company Name: PROJECT RENEWAL
Contact Type: Not reported
Contact Name: ERNIE TALBOT
Address1: 8 EAST 3RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10003
Country Code: 001
Phone: (212) 533-8400 113
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/19/2005

Site Id: 23642
Affiliation Type: On-Site Operator
Company Name: HOLLAND HOUSE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLLAND HOUSE (Continued)

U001842032

Contact Type: Not reported
Contact Name: PROJECT RENEWAL, INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-6600
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/19/2005

Site Id: 23642
Affiliation Type: Emergency Contact
Company Name: MRG PARTNERS
Contact Type: Not reported
Contact Name: ERNIE TALBOT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 533-8400
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/19/2005

Site Id: 23642
Affiliation Type: Facility Owner
Company Name: MRG PARTNERS
Contact Type: FACILITIES DIRECTOR
Contact Name: ERNIE TALBOT
Address1: 200 VARICK ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10014
Country Code: 001
Phone: (212) 620-0340
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/19/2005

Tank Info:

Tank Number: 001
Tank ID: 47467
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLLAND HOUSE (Continued)

U001842032

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: 12/27/1987
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-601680
SPDES Number: Not reported
Emergency Contact: ENGINEER
Emergency Telephone: (212) 206-3923
Operator: R. SHELDON
Operator Telephone: (212) 866-3158
Owner Name: CITY OF NEW YORK HUMAN RESOURCES ADMINISTRATION
Owner Address: 260 11TH AVENUE
Owner City,St,Zip: NEW YORK, NY 10001
Owner Telephone: (212) 630-3923
Owner Type: Local Government
Owner Subtype: Not reported
Mailing Name: CITY OF NEW YORK HUMAN RESOURCES ADMINISTRATION
Mailing Address: 260 11TH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10001
Mailing Contact: JAMES COPELAND
Mailing Telephone: (212) 630-3923
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: 351 WEST 42ND STREET
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLLAND HOUSE (Continued)

U001842032

Certification Date: 01/06/1994
Expiration Date: 01/05/1999
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: Diking
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

T147
SE
< 1/8
0.123 mi.
648 ft.

**LOT 7501,TAXBLOCK 1032
350 WEST 42 STREET
MANHATTAN, NY**

**NY E DESIGNATION S113453267
N/A**

Site 6 of 9 in cluster T

**Relative:
Higher**

E DESIGNATION:
Tax Lot(s): 7501
E-No: E-137
Effective Date: 1/19/2005
Satisfaction Date: Not reported
Ceqr Number: 03DCP031M
Ulurp Number: 040499 ZMM, 040507 MMM, 040508 MMM, 040499A ZMM
Zoning Map No: 8b,8c,8d
Description: Window Wall Attenuation & Alternate Ventilation
Borough Code: Not reported

**Actual:
38 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 7501,TAXBLOCK 1032 (Continued)

S113453267

Community District:	Not reported
Census Tract:	Not reported
Census Block:	Not reported
School District:	Not reported
City Council District:	Not reported
Fire Company:	Not reported
Health Area:	Not reported
Police Precinct:	Not reported
Zone District 1:	Not reported
Zone District 2:	Not reported
Commercial Overlay1:	Not reported
Commercial Overlay2:	Not reported
Special Purpose District1:	Not reported
Special Purpose District2:	Not reported
All Components1:	Not reported
All Components2:	Not reported
Split Boundary Indicator:	Not reported
Building Class:	Not reported
Land Use Category:	Not reported
Number of Easements:	Not reported
Owner, Type of Code:	Not reported
Owner Name:	Not reported
Lot Area:	Not reported
Total Building Floor Area:	Not reported
Commercial Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Floor Area,Total Bld Source Code	Not reported
Number of Buildings:	Not reported
Number of Floors:	Not reported
Residential Units:	Not reported
Non and Residential Units:	Not reported
Lot Frontage:	Not reported
Lot Depth:	Not reported
Building Frontage:	Not reported
Building Depth:	Not reported
Proximity Code:	Not reported
Irregular Lot Code:	Not reported
Lot Type:	Not reported
Basement Type Grade:	Not reported
Land Assessed Value:	Not reported
Total Assessed Value:	Not reported
Land Exempt Value:	Not reported
Total Exempt Value:	Not reported
Year Built:	Not reported
Year Built Code:	Not reported
Year Altered1:	Not reported
Year Altered2:	Not reported
Historic District Name:	Not reported
Landmark Name:	Not reported
Built Floor Area Ratio-Far:	Not reported
Maximum Allowable Far:	Not reported
Borough Code:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LOT 7501,TAXBLOCK 1032 (Continued)

S113453267

Borough Tax Block And Lot: Not reported
Condominium Number: Not reported
Census Tract 2: Not reported
X Coordinate: Not reported
Y Coordinate: Not reported
Zoning Map: Not reported
Sanborn Map: Not reported
Tax Map: Not reported
E Designation No: Not reported
Date of RPAD Data: Not reported
Date of DCAS Data: Not reported
Date of Zoning Data: Not reported
Date of Major Property Data: Not reported
Date of Landmark Data: Not reported
Date of Base Map Data: Not reported
Date of Mass Appraisal Data: Not reported
Date of Political and Adm Data: Not reported
Pluto-Base Map Indicator: Not reported

**T148
SE
< 1/8
0.123 mi.
652 ft.**

**IN TANK ROOM
351 WEST 42ND ST
MANHATTAN, NY**

**NY Spills S106969320
N/A**

Site 7 of 9 in cluster T

**Relative:
Higher**

SPILLS:

**Actual:
38 ft.**

Facility ID: 0503905
Facility Type: ER
DER Facility ID: 295044
Site ID: 348612
DEC Region: 2
Spill Date: 6/29/2005
Spill Number/Closed Date: 0503905 / 7/1/2005
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 7/1/2005
CID: 409
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/1/2005
Spill Record Last Update: 7/1/2005
Spiller Name: RAY LARA
Spiller Company: IN TANK ROOM
Spiller Address: 351 WETS 42ND ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: RAY LARA
Contact Phone: (646) 772-6884

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IN TANK ROOM (Continued)

S106969320

DEC Memo: Sangesland spoke to Ray Lara at PTC. He says spill from a couple of days ago. PTC Cleaned the site. Spill Closed

Remarks: clean up is done.

Material:

Site ID: 348612

Operable Unit ID: 1106263

Operable Unit: 01

Material ID: 1971190

Material Code: 0001A

Material Name: #2 Fuel Oil

Case No.: Not reported

Material FA: Petroleum

Quantity: 20

Units: Gallons

Recovered: 20

Resource Affected: Not reported

Oxygenate: False

Tank Test:

Y149
South
< 1/8
0.124 mi.
654 ft.

MANHOLE 39842
9TH AVE/WEST 40TH ST
MANHATTAN, NY
Site 4 of 8 in cluster Y

NY Spills **S104879909**
N/A

Relative:
Higher

Actual:
32 ft.

SPILLS:

Facility ID: 0008526

Facility Type: ER

DER Facility ID: 212598

Site ID: 259995

DEC Region: 2

Spill Date: 10/21/2000

Spill Number/Closed Date: 0008526 / 2/12/2004

Spill Cause: Unknown

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101

Investigator: KMFOLEY

Referred To: Not reported

Reported to Dept: 10/21/2000

CID: 397

Water Affected: Not reported

Spill Source: Unknown

Spill Notifier: Affected Persons

Cleanup Ceased: Not reported

Cleanup Meets Std: False

Last Inspection: Not reported

Recommended Penalty: False

UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 10/21/2000

Spill Record Last Update: 2/12/2004

Spiller Name: UNKNOWN

Spiller Company: UNKNOWN

Spiller Address: UNKNOWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MANHOLE 39842 (Continued)

S104879909

Spiller City,St,Zip: UNKNOWN, NY
Spiller Company: 999
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "FOLEY"13403910/21/00 12:10 S.TAYLOR BRONX UNDERGROUND REPORTS UPON ENTERING MH-39842 FOR TELLERGY INSPECTION FOUND 2-OZ. OF DIELECTRICFLUID HAD LEAKED FROM FEEDER JOINT ON WEST WALL OF MANHOLE7/7/03The signed 50 to 499 ppm and < 1 pound spill Cleanup Checklist was received from Matt Ketschke, Manager UG South, on July 3, 2003. Based on the information contained in this checklist, the following are the details of the cleanup: All liquids and loose solids were removed from the structure surface. All the contaminated surfaces of the structure that contained the spill were doubled washed with Sliks and rinsed. Two ounces of oil was recovered. Waste generated was transported by a Con Edison maintenance vehicle under the "One-Trip Rule" to the 28 St. Yard. Con Edison employee, Stanly Taylor directed the cleanup. The cleanup was completed at 13:50 hrs. on 10/21/2000.
Remarks: DISCOVERED 2 OZS OF CABLE OIL, CLEAN UP IS IN PROGRESS CON ED #134039

Material:
Site ID: 259995
Operable Unit ID: 829126
Operable Unit: 01
Material ID: 546031
Material Code: 9999
Material Name: Other -
Case No.: Not reported
Material FA: Other
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**Z150
SW
< 1/8
0.124 mi.
655 ft.**

**W 40TH ST AND DYER AVE
W 40TH ST AND DYER AVE
MANHATTAN, NY**

Site 1 of 3 in cluster Z

**NY Spills S102663495
N/A**

**Relative:
Lower**

SPILLS:
Facility ID: 9705983
Facility Type: ER
DER Facility ID: 87143
Site ID: 97876
DEC Region: 2
Spill Date: 8/17/1997
Spill Number/Closed Date: 9705983 / 8/17/1997
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: TOMASELLO

**Actual:
31 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

W 40TH ST AND DYER AVE (Continued)

S102663495

Referred To: Not reported
Reported to Dept: 8/17/1997
CID: 371
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/17/1997
Spill Record Last Update: 1/29/1998
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: EPA INSPECTOR MR LOCHAN ENROUTE TO SPILL - NO OTHER INFO AVAIL.

Material:
Site ID: 97876
Operable Unit ID: 1049234
Operable Unit: 01
Material ID: 331593
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**Z151
SW
< 1/8
0.124 mi.
655 ft.**

**NYS PORT AUTHORITY
40TH ST/DYER AVE
NEW YORK, NY**

Site 2 of 3 in cluster Z

**NY Spills S105142368
N/A**

**Relative:
Lower**

SPILLS:

**Actual:
31 ft.**

Facility ID: 0106530
Facility Type: ER
DER Facility ID: 94585
Site ID: 107534
DEC Region: 2
Spill Date: 9/21/2001
Spill Number/Closed Date: 0106530 / 10/2/2001
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYS PORT AUTHORITY (Continued)

S105142368

Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 9/22/2001
CID: 398
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/22/2001
Spill Record Last Update: 10/2/2001
Spiller Name: Not reported
Spiller Company: GRAYHOUND
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: RONDA DERK
Contact Phone: (972) 740-1707
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIPPLE"10/02 DIESEL SPILLED ONTO PAVED SURFACE, ALL CLEAN, NO DRAINS
IMPACTED

Remarks: all product cleaned up. possibly cause is road hazard. valve failed
on tank. no call back requested.

Material:
Site ID: 107534
Operable Unit ID: 844751
Operable Unit: 01
Material ID: 531378
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 7
Units: Gallons
Recovered: 7
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Z152
SW
< 1/8
0.124 mi.
655 ft.

RAMP 96 ABOVE 40TH ST
AND DYER AVE
MANHATTAN, NY

Site 3 of 3 in cluster Z

NY Spills S102663496
N/A

Relative:
Lower

SPILLS:

Facility ID: 9705984
Facility Type: ER
DER Facility ID: 128075
Site ID: 150651
DEC Region: 2
Spill Date: 8/17/1997
Spill Number/Closed Date: 9705984 / 2/25/2003
Spill Cause: Traffic Accident
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Actual:
30 ft.

SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 8/17/1997
CID: 322
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/17/1997
Spill Record Last Update: 2/25/2003
Spiller Name: FRANK MINERVINI
Spiller Company: PORT AUTHORITY
Spiller Address: 500 JFK BLVD EAST
Spiller City,St,Zip: WEEHAWKEN, NJ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: NJ TRANSIT BUS JUMPED SIDEWALK AND HIT PIPELINES SPILLING 100 GAL OF
SAVALOID (SP?) OIL ONTO STREET AND INTO CATCH BASIN WHICH IS CONTAINED
IN SUMPS - CLEAN UP ON SCENE AND S & D ENVIRONMENTAL ON WAY TO ASSIST

Material:

Site ID: 150651
Operable Unit ID: 1049236
Operable Unit: 01
Material ID: 331594
Material Code: 9999
Material Name: Other -
Case No.: Not reported
Material FA: Other
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RAMP 96 ABOVE 40TH ST (Continued)

S102663496

Tank Test:

Y153
South
< 1/8
0.124 mi.
655 ft.

214070; W 40 ST AND 9TH AVE
W 40 ST AND 9TH AVE
NEW YORK, NY

NY Spills S110306638
N/A

Site 5 of 8 in cluster Y

Relative:
Higher

Actual:
32 ft.

SPILLS:

Facility ID: 0814532
Facility Type: ER
DER Facility ID: 386741
Site ID: 432684
DEC Region: 2
Spill Date: 10/12/2008
Spill Number/Closed Date: 0814532 / 10/19/2008
Spill Cause: Unknown
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: DMPOKRZY
Referred To: Not reported
Reported to Dept: 12/31/2008
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/16/2010
Spill Record Last Update: 4/16/2010
Spiller Name: ERT DESK
Spiller Company: CON EDISON
Spiller Address: 5030 BROADWAY
Spiller City,St,Zip: New York, NY
Spiller Company: 001
Contact Name: ERT DESK
Contact Phone: (212) 580-8383
DEC Memo: Not reported
Remarks: Not reported

Material:

Site ID: 432684
Operable Unit ID: 1183745
Operable Unit: 01
Material ID: 2177933
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

214070; W 40 ST AND 9TH AVE (Continued)

S110306638

Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Y154
SSW
< 1/8
0.124 mi.
657 ft.

**400 W 40TH ST
NEW YORK, NY 10018
Site 6 of 8 in cluster Y**

**EDR US Hist Cleaners 1015054572
N/A**

**Relative:
Higher**

EDR Historical Cleaners:

Name: STANLEY STEEMER CARPET CLEANERS
Year: 1999

**Actual:
32 ft.**

Address: 400 W 40TH ST

AA155
SE
< 1/8
0.124 mi.
657 ft.

**STELLOS PIANO INC
351 W 41ST ST
NEW YORK, NY 10036
Site 1 of 4 in cluster AA**

**RCRA NonGen / NLR 1000790781
NY MANIFEST NYD987022688**

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: STELLOS PIANO INC

Facility address: 351 W 41ST ST
NEW YORK, NY 100366903

EPA ID: NYD987022688

Mailing address: W 41ST ST
NEW YORK, NY 10036

Contact: Not reported

Contact address: W 41ST ST
NEW YORK, NY 10036

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CARO MUSIC - 1ST FLOOR

Owner/operator address: 351 W 42ND ST
NEW YORK, NY 10036

Owner/operator country: US

Owner/operator telephone: (212) 868-4120

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: CARO MUSIC - 1ST FLOOR

Owner/operator address: 351 W 42ND ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STELLOS PIANO INC (Continued)

1000790781

NEW YORK, NY 10036

Owner/operator country: US
Owner/operator telephone: (212) 868-4120
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: STELLOS PIANO INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: STELLOS PIANO INC
Classification: Not a generator, verified

Date form received by agency: 12/02/1992
Site name: STELLOS PIANO INC
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD987022688
Country: USA

Mailing Info:

Name: STELLO PIANO
Contact: T CURRY
Address: 351 W 41ST ST
City/State/Zip: NEW YORK, NY 10011
Country: USA
Phone: 212-868-4126

Document ID: NYB4053888
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STELLOS PIANO INC (Continued)

1000790781

Generator Ship Date: 930309
Trans1 Recv Date: 930309
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930317
Part A Recv Date: Not reported
Part B Recv Date: 930405
Generator EPA ID: NYD987022688
Trans1 EPA ID: OHD982061350
Trans2 EPA ID: Not reported
TSD ID: GAD093380814
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 93

AA156
SE
< 1/8
0.124 mi.
657 ft.

FORMER QUATRO PROPERTIES ASSOCIATES FACILITY
351 WEST 41 STREET
NYC, NY 10036

NY AST **A100300652**
N/A

Site 2 of 4 in cluster AA

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-149020
Program Type: PBS
UTM X: 585150.59539999999
UTM Y: 4512309.8729400001
Expiration Date: 01/24/2010
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 4475
Affiliation Type: Mail Contact
Company Name: LANGAN ENGINEERING AND ENVIRONMENTAL SERVICES INC.
Contact Type: Not reported
Contact Name: STEVEN CIAMBRUSCHINI
Address1: RIVER DRIVE CENTER ONE
Address2: Not reported
City: ELMWOOD PARK
State: NJ
Zip Code: 07407
Country Code: 001
Phone: (201) 398-4549
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/24/2005

Site Id: 4475
Affiliation Type: On-Site Operator
Company Name: FORMER QUATRO PROPERTIES ASSOCIATES FACILITY
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER QUATRO PROPERTIES ASSOCIATES FACILITY (Continued)

A100300652

Contact Name: CARROLL MUSICAL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 868-4120
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/24/2005

Site Id: 4475
Affiliation Type: Emergency Contact
Company Name: INTELL MANAGEMENT AND INVESTMENT COMPANY
Contact Type: Not reported
Contact Name: KEVIN CURRY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (973) 543-5597
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/24/2005

Site Id: 4475
Affiliation Type: Facility Owner
Company Name: INTELL MANAGEMENT AND INVESTMENT COMPANY
Contact Type: PROJECT MANAGER
Contact Name: RAIZY HAAS
Address1: 255 WEST 86TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 712-6000
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/24/2005

Tank Info:

Tank Number: 001
Tank Id: 8101
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER QUATRO PROPERTIES ASSOCIATES FACILITY (Continued)

A100300652

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

Tank Location: 4
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4000
Tightness Test Method: 21
Date Test: 08/13/2002
Next Test Date: Not reported
Date Tank Closed: 08/01/2004
Register: True
Modified By: KXTANG
Last Modified: 01/24/2005
Material Name: #4 Fuel Oil (On-Site Consumption)

AA157 **CENTRAL PARKING SYSTEMS**
SE **350-358 W 42ND ST**
< 1/8 **NEW YORK, NY**
0.124 mi.
657 ft. **Site 3 of 4 in cluster AA**

NY Spills **S104789435**
N/A

Relative:
Higher

SPILLS:

Actual:
37 ft.

Facility ID: 0006951
Facility Type: ER
DER Facility ID: 255733
Site ID: 317242
DEC Region: 2
Spill Date: 9/12/2000
Spill Number/Closed Date: 0006951 / 9/12/2001
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: SJMILLER
Referred To: Not reported
Reported to Dept: 9/12/2000
CID: 390
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/12/2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRAL PARKING SYSTEMS (Continued)

S104789435

Spill Record Last Update: 9/12/2001
Spiller Name: UNK
Spiller Company: CENTRAL PARKING SYSTEMS
Spiller Address: 350-358 W 42ND ST
Spiller City,St,Zip: NEW YORK, ZZ
Spiller Company: 001
Contact Name: UNK
Contact Phone: (000) 000-0000
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MILLER"02/07/01Reassigned from Saccacio to Demeo9/12/2001, REASSIGNED FROM DEMEO TO MILLER. MILLER WROTE CLOSURE/NFA LETTER BASED ON REVIEW OF MARCH AND AUGUST 8, 2001 REPORT AND GROUND WATER ANALYTICAL, RESPECTIVELY.
Remarks: TEST BORINGS SHOWED SOIL CONTAMINATION - UNK WHERE IT'S FROMUNK WHAT WILL BE DONE AS OF YET - IT IS UNDER A PARKING LOT
Material:
Site ID: 317242
Operable Unit ID: 827817
Operable Unit: 01
Material ID: 548059
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AA158
SE
< 1/8
0.124 mi.
657 ft.

351 WEST 41 ST BUILDING
351 WEST 41 STREET
NYC, NY 10036
Site 4 of 4 in cluster AA

NY LTANKS **U001833174**
NY HIST UST **N/A**

Relative:
Higher

Actual:
37 ft.

LTANKS:
Site ID: 196934
Spill Number/Closed Date: 0203840 / 3/15/2005
Spill Date: 7/11/2002
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 7/11/2002
CID: 199
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

351 WEST 41 ST BUILDING (Continued)

U001833174

Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 7/11/2002
Spill Record Last Update: 7/11/2005
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: KEVIN
Spiller Phone: (212) 868-4122
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 4472
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"5/12/04. J.Krimgold spoke to Grag Peterson (Langan Engineering)@ 201-794-6900 a consultant for a potential buyer. He will submit a proposal for remediation of this site.3/15/05. J.Krimgold reviewed the Tank Closure Report submitted by LANGAN Eng. on December 8, 2004. Based on information provided 4000 gal #4 oil tank has been removed. Slightly contaminated soil found during tank's removal was excavated. Post-excavation samples show no residual soil contamination. NFA letter.

Remarks: TANK DOESN'T SEEM TO BE LEAKING - BUT LINED TO TANK ARE VERY OLD- TANK WILL BE CLEANED AND LINES ISLOATED - THAN RETESTED

Material:

Site ID: 196934
Operable Unit ID: 854974
Operable Unit: 01
Material ID: 521649
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 196934
Spill Tank Test: 1527277
Tank Number: 1
Tank Size: 4000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

351 WEST 41 ST BUILDING (Continued)

U001833174

HIST UST:

PBS Number: 2-149020
SPDES Number: Not reported
Emergency Contact: KEVIN CURRY
Emergency Telephone: (201) 543-5597
Operator: CARROLL MUSICAL
Operator Telephone: (212) 868-4120
Owner Name: QUATRO PROPERTIES ASSOCIATES
Owner Address: 60 EAST 42 STREET
Owner City,St,Zip: NYC, NY 10017
Owner Telephone: (212) 868-4120
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: QUATRO PROPERTIES ASSOCIATES
Mailing Address: 60 EAST 42 STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NYC, NY 10017
Mailing Contact: Not reported
Mailing Telephone: (212) 868-4120
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: 351 WEST 41 STREET
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER RETAIL SALES
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 07/23/1998
Expiration Date: 10/15/2002
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 4000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 4000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

351 WEST 41 ST BUILDING (Continued)

U001833174

Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge, Vent Whistle
Dispenser: Suction
Date Tested: 05/01/1998
Next Test Date: 05/01/2003
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Horner EZ Check
Deleted: False
Updated: True
Lat/long: Not reported

V159
ESE
1/8-1/4
0.126 mi.
663 ft.

IVY TOWER
350 WEST 43RD STREET
NEW YORK, NY 10036
Site 6 of 6 in cluster V

NY AST **U004078869**
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609467
Program Type: PBS
UTM X: 585187.87971000001
UTM Y: 4512434.4727800004
Expiration Date: 02/24/2019
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 31311
Affiliation Type: Facility Owner
Company Name: 42/43 REALTY LLC
Contact Type: MGR
Contact Name: BERNARD FRIEDMAN
Address1: 5 EAST 86 STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10028
Country Code: 001
Phone: (212) 876-4200
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/29/2014

Site Id: 31311
Affiliation Type: Mail Contact
Company Name: 42/43 REALTY LLC
Contact Type: Not reported
Contact Name: BERNARD FRIEDMAN
Address1: 770 LEXINGTON AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IVY TOWER (Continued)

U004078869

Address2: 18TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10028
Country Code: 001
Phone: (212) 876-4200
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/29/2014

Site Id: 31311
Affiliation Type: On-Site Operator
Company Name: IVY TOWER
Contact Type: Not reported
Contact Name: LOUIS GARCIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 485-6200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31311
Affiliation Type: Emergency Contact
Company Name: 42/43 REALTY LLC
Contact Type: Not reported
Contact Name: LOUIS GARCIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 956-1271
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/29/2014

Tank Info:

Tank Number: 001
Tank Id: 67544
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IVY TOWER (Continued)

U004078869

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F05 - Pipe External Protection - Jacketed
H99 - Tank Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
F01 - Pipe External Protection - Painted/Asphalt Coating
6
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/08/2001
Capacity Gallons: 12000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 01/29/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

T160
SE
1/8-1/4
0.126 mi.
665 ft.

CON EDISON SERVICE BOX: 8123
348 W 42ND ST
NEW YORK, NY 10036
Site 8 of 9 in cluster T

RCRA-CESQG 1016144039
FINDS NYP004268264

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8123

Facility address: 348 W 42ND ST
NEW YORK, NY 10036

EPA ID: NYP004268264

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8123 (Continued)

1016144039

hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458874

Environmental Interest/Information System

T161
SE
1/8-1/4
0.126 mi.
665 ft.

CON EDISON
348 W 42ND ST
NEW YORK, NY 10036

NY MANIFEST **S112210640**
N/A

Site 9 of 9 in cluster T

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268264
Country: USA

Actual:
38 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268264
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210640

Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456578JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268264
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456578JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210640

Mgmt Method Type Code: H111

AB162
WSW
1/8-1/4
0.130 mi.
687 ft.

HUNTER COLLEGE - MFA
450 W 41ST ST
NEW YORK, NY 10018

Site 1 of 4 in cluster AB

RCRA NonGen / NLR **1010328540**
NY MANIFEST **NYR000143685**

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: HUNTER COLLEGE - MFA

Facility address: 450 W 41ST ST
NEW YORK, NY 10018

EPA ID: NYR000143685

Mailing address: PARK AVE - ROOM E1211A
NEW YORK, NY 10021

Contact: RICARDO FRANCO

Contact address: PARK AVE - ROOM E1211A
NEW YORK, NY 10021

Contact country: US

Contact telephone: (212) 772-4462

Contact email: RICARDO.FRANCO@HUNTER.CUNY.EDU

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: DASNY
Owner/operator address: BROADWAY
ALBANY, NY 12207

Owner/operator country: US
Owner/operator telephone: Not reported

Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1989
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1989
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 12/22/2006
Site name: HUNTER COLLEGE - MFA
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/21/2006
Site name: HUNTER COLLEGE - MFA
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYR000143685
Country: USA

Mailing Info:

Name: HUNTER COLLEGE - MFA
Contact: MEL RODRIGUEZ
Address: 450 W 41ST ST
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-772-4462

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 21.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 135.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 52.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: OHD009865825
Generator Ship Date: 8/24/2007
Trans1 Recv Date: 8/24/2007
Trans2 Recv Date: 8/28/2007
TSD Site Recv Date: 9/17/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NCD000648451
Waste Code: Not reported
Quantity: 40
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000932420FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: OHD009865825
Generator Ship Date: 8/24/2007
Trans1 Recv Date: 8/24/2007
Trans2 Recv Date: 8/28/2007
TSD Site Recv Date: 9/17/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NCD000648451
Waste Code: Not reported
Quantity: 70
Units: P - Pounds
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000932420FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 52.0
Units: P - Pounds
Number of Containers: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 135.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Trans2 State ID: OHD009865825
Generator Ship Date: 2008-02-27
Trans1 Recv Date: 2008-02-27
Trans2 Recv Date: 2008-03-03
TSD Site Recv Date: 2008-03-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NCD000648451
Waste Code: Not reported
Quantity: 120.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001860236FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: OHD009865825
Generator Ship Date: 2008-02-27
Trans1 Recv Date: 2008-02-27
Trans2 Recv Date: 2008-03-03
TSD Site Recv Date: 2008-03-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NCD000648451
Waste Code: Not reported
Quantity: 30.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001860236FLE
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: Not reported
Quantity: 21.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 30.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 65.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 40.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Quantity: 2.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 2.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 21.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 135.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-02-06
Trans1 Recv Date: 2009-02-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-02-11
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 52.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004730188JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 2.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-02
Trans1 Recv Date: 2009-07-02
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000143685
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 5.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 004716602JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUNTER COLLEGE - MFA (Continued)

1010328540

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

[Click this hyperlink](#) while viewing on your computer to access
29 additional NY_MANIFEST: record(s) in the EDR Site Report.

AB163
WSW
1/8-1/4
0.130 mi.
687 ft.

450 W. 41ST STREET
450 W. 41ST STREET
MANHATTAN, NY

NY LTANKS **S102233197**
N/A

Site 2 of 4 in cluster AB

Relative:
Lower

LTANKS:

Actual:
29 ft.

Site ID: 210934
Spill Number/Closed Date: 9504490 / 7/28/2005
Spill Date: 7/14/1995
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: LNKLAAS
Referred To: Not reported
Reported to Dept: 7/14/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/10/1995
Spill Record Last Update: 7/28/2005
Spiller Name: Not reported
Spiller Company: HUNTER COLLEGE
Spiller Address: 450 WEST 41ST STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: DAVID RECINO
Spiller Phone: (212) 356-0648
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 174855
DEC Memo: 06/25/05 Called Aqua-X (212) 226-6189 - phone number disconnected.
LNK. 06/25/05 Called David Recino (Hunter College) - no answer.
LNK.07/28/05 2:00pm Called Roy Feinzig (914-682-4850) of Rose,
Beaton, and Rose. He confirmed that Con Edison vault was removed,
product was cleaned up, and monitoring wells were installed. He said
wells were monitored for several years and cleanup is complete.
Closed. LNK.

Remarks: TANK WAS EMPTIED AND CLEANED DURING A TEST TODAY - THEY FOUND AN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

450 W. 41ST STREET (Continued)

S102233197

UNKNOWN AMOUNT OF OIL UNDER TANK. CALLED DAVID KATZEN, PREPARING TO
ABANDON TANK - CLEANED OUT HTE TANK - DRILLED INSIDE THE TANK.

Material:

Site ID: 210934
Operable Unit ID: 1019239
Operable Unit: 01
Material ID: 366002
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AC164
WNW
1/8-1/4
0.132 mi.
698 ft.

CON EDISON SERVICE BOX: 43272
582 10TH AVE
NEW YORK, NY 10036
Site 1 of 11 in cluster AC

RCRA-CESQG 1016144066
FINDS NYP004268538

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/14/2012
Facility name: CON EDISON SERVICE BOX: 43272
Facility address: 582 10TH AVE
NEW YORK, NY 10036
EPA ID: NYP004268538
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Actual:
23 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43272 (Continued)

1016144066

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428256

Environmental Interest/Information System

AC165
WNW
1/8-1/4
0.132 mi.
698 ft.

CON EDISON
582 10TH AVE
NEW YORK, NY 10036

Site 2 of 11 in cluster AC

NY MANIFEST S112210667
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268538
Country: USA

Actual:
23 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268538
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210667

Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457026JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268538
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457026JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AD166 414-420 WEST 45TH STREET
NNE 414-420 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.133 mi.
702 ft. Site 1 of 6 in cluster AD

NY AST **U003395283**
NY HIST AST **N/A**

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-481874
Program Type: PBS
UTM X: 585096.78682000004
UTM Y: 4512670.0161600001
Expiration Date: 09/11/2015
Site Type: Other

Actual:
37 ft.

Affiliation Records:

Site Id: 21567
Affiliation Type: Facility Owner
Company Name: 410-22 ASSOCIATES
Contact Type: PROPERTY MANAGER
Contact Name: SAM MOHABIR
Address1: 125 PARK AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 372-2000
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 7/23/2010

Site Id: 21567
Affiliation Type: Mail Contact
Company Name: C/O NEWMARK & CO. REAL ESTATE
Contact Type: Not reported
Contact Name: 410-22 ASSOCIATES
Address1: 125 PARK AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 372-2000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21567
Affiliation Type: On-Site Operator
Company Name: 414-420 WEST 45TH STREET
Contact Type: Not reported
Contact Name: NEWMARK & CO. REAL ESTATE
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

414-420 WEST 45TH STREET (Continued)

U003395283

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 247-4355
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21567
Affiliation Type: Emergency Contact
Company Name: 410-22 ASSOCIATES
Contact Type: Not reported
Contact Name: WILLIAM DIAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 203-0184
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/10/2005

Tank Info:

Tank Number: 001
Tank Id: 39225
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/25/1925
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 07/23/2010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

414-420 WEST 45TH STREET (Continued)

U003395283

Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-481874
SWIS Code: 6201
Operator: NEWMARK & CO. REAL ESTATE
Facility Phone: (212) 247-4355
Facility Addr2: 414 WEST 45TH STREET
Facility Type: OTHER
Emergency: JEFF SWAYSE
Emergency Tel: (718) 641-8127
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 410-22 ASSOCIATES
Owner Address: 125 PARK AVENUE
Owner City,St,Zip: NEW YORK, NY 10017
Federal ID: Not reported
Owner Tel: (212) 372-2000
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: 410-22 ASSOCIATES
Mailing Name: C/O NEWMARK & CO. REAL ESTATE
Mailing Address: 125 PARK AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Telephone: (212) 372-2000
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/25/2000
Expiration: 09/11/2005
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

414-420 WEST 45TH STREET (Continued)

U003395283

Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Submersible
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

**AC167
WNW
1/8-1/4
0.134 mi.
705 ft.**

**CONSOLIDATED EDISON
W 42 ST & 10 AVE MH43263
NEW YORK, NY 10010**

**NY MANIFEST 1009242821
N/A**

Site 3 of 11 in cluster AC

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYP004120861
Country: USA

**Actual:
23 ft.**

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0638199
Manifest Status: Not reported
Trans1 State ID: 46235JM
Trans2 State ID: Not reported
Generator Ship Date: 05/24/2004
Trans1 Recv Date: 05/24/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/24/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004120861
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD980593
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 07182
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009242821

Specific Gravity: 01.00
Year: 2004

Document ID: NYE1564623
Manifest Status: Not reported
Trans1 State ID: 46826JM
Trans2 State ID: Not reported
Generator Ship Date: 05/24/2004
Trans1 Recv Date: 05/24/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/24/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004120861
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD980593
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00336
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYE0630738
Manifest Status: Not reported
Trans1 State ID: 46177JM
Trans2 State ID: Not reported
Generator Ship Date: 05/24/2004
Trans1 Recv Date: 05/24/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/24/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004120861
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD077444
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00115
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AC168
WNW
1/8-1/4
0.134 mi.
705 ft.

CONSOLIDATED EDISON
42ND & 10TH AVE MH60134
NEW YORK, NY 10003

Site 4 of 11 in cluster AC

NY MANIFEST **1009240921**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004090759
Country: USA

Actual:
23 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0622143
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/17/2001
Trans1 Recv Date: 10/17/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/17/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004090759
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: 31877AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00091
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

AC169
WNW
1/8-1/4
0.134 mi.
708 ft.

CONSOLIDATED EDISON
42ND ST & 10TH AVE
NEW YORK, NY

Site 5 of 11 in cluster AC

NY MANIFEST **1009238327**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004046389
Country: USA

Actual:
23 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009238327

Document ID: NYE0405963
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/12/1999
Trans1 Recv Date: 11/12/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/12/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004046389
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20854AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 00264
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

Document ID: NYE0407709
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 11/12/1999
Trans1 Recv Date: 11/12/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/15/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004046389
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSD ID: 4812AN
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00304
Units: K - Kilograms (2.2 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 99

AC170
WNW
1/8-1/4
0.134 mi.
708 ft.

**ROADBED
42NS ST 10TH AVE
NEW YORK, NY**

Site 6 of 11 in cluster AC

**NY LTANKS S110611375
N/A**

**Relative:
Lower**

LTANKS:
Site ID: 442310
Spill Number/Closed Date: 1008791 / 11/30/2010
Spill Date: 11/22/2010
Spill Cause: Tank Test Failure

**Actual:
23 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ROADBED (Continued)

S110611375

Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 11/22/2010
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/22/2010
Spill Record Last Update: 11/30/2010
Spiller Name: SHERRY
Spiller Company: NYC TRANSIT
Spiller Address: 42NS ST 10TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 999
Spiller Contact: SHERRY
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 397349
DEC Memo: minor antifreeze spill from a bus. Transit did cleanup.
Remarks: PDAA 2 GALLONS ANTIFREEZE INTO SEWER.

Material:
Site ID: 442310
Operable Unit ID: 1192820
Operable Unit: 01
Material ID: 2188164
Material Code: 0043A
Material Name: ANTIFREEZE
Case No.: Not reported
Material FA: Other
Quantity: 3
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AC171
WNW
1/8-1/4
0.135 mi.
712 ft.

575 10TH AVE
NEW YORK, NY 10036

Site 7 of 11 in cluster AC

EDR US Hist Auto Stat 1015558633
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: A 25 HR AUTO SALVAGE
Year: 2003
Address: 575 10TH AVE

Actual:
22 ft.

Name: A 25 HR AUTO SALVAGE
Year: 2005
Address: 575 10TH AVE

Name: A 25 HR AUTO SALVAGE
Year: 2010
Address: 575 10TH AVE

AC172
WNW
1/8-1/4
0.135 mi.
715 ft.

CVS PHARMACY #2940
500 W 42ND ST
NEW YORK, NY 10036

Site 8 of 11 in cluster AC

RCRA-SQG 1014958106
NYR000193433

Relative:
Lower

RCRA-SQG:

Date form received by agency: 03/05/2012

Facility name: CVS PHARMACY #2940
Facility address: 500 W 42ND ST
NEW YORK, NY 10036

EPA ID: NYR000193433
Mailing address: CVS DR
WOONSOCKET, RI 02895

Contact: WENDY L BRANT
Contact address: CVS DR
WOONSOCKET, RI 02895

Contact country: US
Contact telephone: (401) 765-1500
Contact email: WENDY.BRANT@CVSCAREMARK.COM
EPA Region: 02

Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: CVS ALBANY LLC
Owner/operator address: CVS DR
WOONSOCKET, RI 02895

Owner/operator country: US
Owner/operator telephone: (401) 765-1500
Legal status: Private

Owner/Operator Type: Operator
Owner/Op start date: 08/25/2003
Owner/Op end date: Not reported

Owner/operator name: 501 W 41ST STREET ASSOCIATES LLC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

1014958106

Owner/operator address: LOCK BOX 7826
PHILADELPHIA, PA 19178
Owner/operator country: US
Owner/operator telephone: (212) 427-9700
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/31/2001
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D011
Waste name: SILVER

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste code: P042
Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

Waste code: P075

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

1014958106

Waste name: NICOTINE, & SALTS
Waste code: P081
Waste name: NITROGLYCERINE (R)
Violation Status: No violations found

**AC173
WNW
1/8-1/4
0.135 mi.
715 ft.**

**CVS PHARMACY #2940
500 W 42ND ST
NEW YORK, NY 10036
Site 9 of 11 in cluster AC**

**NY MANIFEST S112211445
N/A**

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYR000193433
Country: USA

**Actual:
22 ft.**

Mailing Info:
Name: CVS PHARMACY #2940
Contact: CVS PHARMACY #2940
Address: 500 W 42ND ST
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-244-4285

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJD054126164
Generator Ship Date: 2012-10-16
Trans1 Recv Date: 2012-10-16
Trans2 Recv Date: 2012-10-19
TSD Site Recv Date: 2012-10-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 2.0
Units: P - Pounds
Number of Containers: 3.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005815162FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJD054126164
Generator Ship Date: 2012-10-16
Trans1 Recv Date: 2012-10-16
Trans2 Recv Date: 2012-10-19
TSD Site Recv Date: 2012-10-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 49.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005815162FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJD054126164
Generator Ship Date: 2012-10-16
Trans1 Recv Date: 2012-10-16
Trans2 Recv Date: 2012-10-19
TSD Site Recv Date: 2012-10-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 21.0
Units: P - Pounds
Number of Containers: 3.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005815162FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: NJD054126164
Generator Ship Date: 2012-10-16
Trans1 Recv Date: 2012-10-16
Trans2 Recv Date: 2012-10-19
TSD Site Recv Date: 2012-10-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 1.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005815162FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 4.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 14.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 35.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 11.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 12.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-24
Trans1 Recv Date: 2012-07-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 1.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005875911FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: PAD982661381
Generator Ship Date: 2012-08-21
Trans1 Recv Date: 2012-08-21
Trans2 Recv Date: 2012-08-22
TSD Site Recv Date: 2012-08-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID040098352
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Quantity: 90.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 3.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005703989FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: PAD982661381
Generator Ship Date: 2012-10-24
Trans1 Recv Date: 2012-10-24
Trans2 Recv Date: 2012-10-25
TSD Site Recv Date: 2012-10-26
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: RID040098352
Waste Code: Not reported
Quantity: 110.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005713602FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: PAD982661381
Generator Ship Date: 2012-06-19
Trans1 Recv Date: 2012-06-19
Trans2 Recv Date: 2012-06-20
TSD Site Recv Date: 2012-06-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: RID040098352
Waste Code: Not reported
Quantity: 30.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 005726416FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: INR000110197
Waste Code: Not reported
Quantity: 27
Units: P - Pounds
Number of Containers: 1
Container Type: BA - Burlap, plastic, paper bags
Handling Method: L Landfill.
Specific Gravity: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 25
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 44
Units: P - Pounds
Number of Containers: 3
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 1
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 25
Units: P - Pounds
Number of Containers: 2
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 1
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MNS000110924
Trans2 State ID: NJD054126164
Generator Ship Date: 2014-01-24
Trans1 Recv Date: 2014-01-24
Trans2 Recv Date: 2014-02-03
TSD Site Recv Date: 2014-02-12
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000193433
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: INR000110197
Waste Code: Not reported
Quantity: 16
Units: P - Pounds
Number of Containers: 1
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 005861858FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CVS PHARMACY #2940 (Continued)

S112211445

Mgmt Method Type Code: H141

[Click this hyperlink](#) while viewing on your computer to access
32 additional NY_MANIFEST: record(s) in the EDR Site Report.

AD174
NNE
1/8-1/4
0.136 mi.
717 ft.

413 W 45TH ST
NEW YORK, NY 10036
Site 2 of 6 in cluster AD

EDR US Hist Auto Stat 1015481480
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: MIDTOWN AUTO CARE SERVICE INC
Year: 2002
Address: 413 W 45TH ST

Actual:
37 ft.

AD175
NNE
1/8-1/4
0.136 mi.
718 ft.

415 W 45TH ST
NEW YORK, NY 10036
Site 3 of 6 in cluster AD

EDR US Hist Auto Stat 1015482833
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: AUTORENT CAR RENTAL CORPORATION
Year: 1999
Address: 415 W 45TH ST

Actual:
37 ft.

Name: AUTORENT CAR RENTAL CORPORATION
Year: 2000
Address: 415 W 45TH ST

AD176
NNE
1/8-1/4
0.136 mi.
718 ft.

PARKING GARAGE
415-419 WEST 45TH STREET
NEW YORK, NY 10036
Site 4 of 6 in cluster AD

NY UST U003127195
NY HIST UST N/A

Relative:
Higher

UST:

Id/Status: 2-602767 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 09/10/2001
UTM X: 585096.786820000004
UTM Y: 4512670.01616000001
Site Type: Other

Actual:
37 ft.

Affiliation Records:

Site Id: 24723
Affiliation Type: Facility Owner
Company Name: MIDTOWN AUTO CARE SERVICES, INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 415-419 WEST 45TH STREET
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 265-0774
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24723
Affiliation Type: Mail Contact
Company Name: MIDTOWN AUTO CARE SERVICES, INC.
Contact Type: Not reported
Contact Name: MICHAEL ZACHARIAR
Address1: 415-419 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 265-0774
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24723
Affiliation Type: On-Site Operator
Company Name: PARKING GARAGE
Contact Type: Not reported
Contact Name: MICHAEL ZACHARIAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-0774
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24723
Affiliation Type: Emergency Contact
Company Name: MIDTOWN AUTO CARE SERVICES, INC.
Contact Type: Not reported
Contact Name: MICHAEL ZACHARIAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-0774
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 51441
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 002
Tank ID: 51442
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 003
Tank ID: 51443
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 51444
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

Tank Number: 005
Tank ID: 51445
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground

HIST UST:

PBS Number: 2-602767
SPDES Number: Not reported
Emergency Contact: MICHAEL ZACHARIAR
Emergency Telephone: (212) 265-0774
Operator: MICHAEL ZACHARIAR
Operator Telephone: (212) 265-0774
Owner Name: MIDTOWN AUTO CARE SERVICES, INC.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Owner Address: 415-419 WEST 45TH STREET
Owner City,St,Zip: NEW YORK, NY 10036
Owner Telephone: (212) 265-0774
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: MIDTOWN AUTO CARE SERVICES, INC.
Mailing Address: 415-419 WEST 45TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Contact: MICHAEL ZACHARIAR
Mailing Telephone: (212) 265-0774
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)
and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: Not reported
Expiration Date: 09/10/2001
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: 40|38|54 / 74|00|30

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: 40|38|54 / 74|00|30

Tank Id: 003
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Test Method: Not reported
Deleted: False
Updated: True
Lat/long: 40|38|54 / 74|00|30

Tank Id: 004
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: 40|38|54 / 74|00|30

Tank Id: 005
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 550
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARKING GARAGE (Continued)

U003127195

Lat/long: 40|38|54 / 74|00|30

AD177
NNE
1/8-1/4
0.136 mi.
719 ft.

411 WEST 45TH STREET
411 WEST 45TH STREET
NEW YORK, NY 10036

NY AST **A100178351**
N/A

Site 5 of 6 in cluster AD

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606153
Program Type: PBS
UTM X: 585118.78547
UTM Y: 4512665.4925300004
Expiration Date: 07/02/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 28017
Affiliation Type: Facility Owner
Company Name: 411 WEST 45TH STREET LLC % SHORE ASSETS
Contact Type: MANAGING AGENT
Contact Name: MARC S. SHORE
Address1: 230 PARK AVE SUITE 539
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10169
Country Code: 001
Phone: (212) 953-7777
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/9/2012

Site Id: 28017
Affiliation Type: Mail Contact
Company Name: SIMON DEVELOPMENT GROUP
Contact Type: Not reported
Contact Name: JOHNATHAN SIMON
Address1: 230 PARK AVE SUITE 539
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10169
Country Code: 001
Phone: (212) 953-7777
EMail: JHSIMON@SIMON@DEV.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/10/2012

Site Id: 28017
Affiliation Type: On-Site Operator
Company Name: 411 WEST 45TH STREET
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

411 WEST 45TH STREET (Continued)

A100178351

Contact Name: DOWEN CHANDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 416-5825
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 6/14/2006

Site Id: 28017
Affiliation Type: Emergency Contact
Company Name: 411 WEST 45TH STREET LLC % SHORE ASSETS
Contact Type: Not reported
Contact Name: MARC S. SHORE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 400-0404
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 6/14/2006

Tank Info:

Tank Number: 001
Tank Id: 61016
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/21/1943
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

411 WEST 45TH STREET (Continued)

A100178351

Register: True
Modified By: MSBAPTIS
Last Modified: 01/09/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

**AC178
NW
1/8-1/4
0.137 mi.
721 ft.**

**CON EDISON SERVICE BOX: 8049
587 10TH AVE
NEW YORK, NY 10036**

**RCRA-CESQG 1016144063
FINDS NYP004268504**

Site 10 of 11 in cluster AC

**Relative:
Lower**

RCRA-CESQG:

Date form received by agency: 09/14/2012

Facility name: CON EDISON SERVICE BOX: 8049

Facility address: 587 10TH AVE
NEW YORK, NY 10036

EPA ID: NYP004268504

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8049 (Continued)

1016144063

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055459007

Environmental Interest/Information System

**AC179
NW
1/8-1/4
0.137 mi.
721 ft.**

**CON EDISON
587 10TH AVE
NEW YORK, NY 10036**

**NY MANIFEST S112210663
N/A**

Site 11 of 11 in cluster AC

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYP004268496
Country: USA

**Actual:
22 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268496
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457024JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210663

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268496
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457024JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AD180
NE
1/8-1/4
0.138 mi.
727 ft.

CHATSWORTH LLC
405 WEST 45TH STREET
NEW YORK, NY 10036
Site 6 of 6 in cluster AD

NY AST A100168842
N/A

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-216763
Program Type: PBS
UTM X: 585166.72409000003
UTM Y: 4512669.4309200002
Expiration Date: 07/07/2015
Site Type: Apartment Building/Office Building

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHATSWORTH LLC (Continued)

A100168842

Affiliation Records:

Site Id: 8168
Affiliation Type: Facility Owner
Company Name: CHATSWORTH LLC
Contact Type: MEMBER
Contact Name: LARRY D. GOLDSTEIN
Address1: 144 E. 44TH ST., 5TH FL.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (646) 201-9698
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 6/11/2010

Site Id: 8168
Affiliation Type: Mail Contact
Company Name: CHATSWORTH, LLC
Contact Type: Not reported
Contact Name: LARRY D. GOLDSTEIN
Address1: C/O VESTA REALTY SERVICES, INC.
Address2: 144 EAST 44TH STREET, 5TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (646) 201-9698
EMail: LARRYG@1370.GMAIL.COM
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 6/11/2010

Site Id: 8168
Affiliation Type: On-Site Operator
Company Name: CHATSWORTH LLC
Contact Type: Not reported
Contact Name: GREGORY MCNALLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-8973
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8168
Affiliation Type: Emergency Contact
Company Name: CHATSWORTH LLC
Contact Type: Not reported
Contact Name: LARRY D. GOLDSTEIN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHATSWORTH LLC (Continued)

A100168842

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 201-9698
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2005

Tank Info:

Tank Number: #1
Tank Id: 22417
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/08/2001
Capacity Gallons: 3500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 06/11/2010
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AE181
NW
1/8-1/4
0.138 mi.
728 ft.

CON EDISON - GM 16 INCH
10TH AVE WEST 42 /WEST 43
NEW YORK, NY 10009

RCRA NonGen / NLR
NY MANIFEST

1008195513
NYP004106860

Site 1 of 11 in cluster AE

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 02/27/2004

Facility name: CON EDISON - GM 16 INCH

Facility address: 10TH AVE WEST 42 /WEST 43

NEW YORK, NY 10009

EPA ID: NYP004106860

Mailing address: 4 IRVING PLACE

NEW YORK, NY 10003

Contact: ANTHONY DRUMMINGS

Contact address: 4 IRVING PLACE

NEW YORK, NY 10003

Contact country: US

Contact telephone: (212) 460-3770

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
23 ft.

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: Not reported

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: 02/04/2003

Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.

Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US

Owner/operator telephone: Not reported

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: 02/04/2003

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - GM 16 INCH (Continued)

1008195513

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/26/2004
Site name: CON EDISON - GM 16 INCH
Classification: Not a generator, verified

Date form received by agency: 02/25/2004
Site name: CON EDISON - GM 16 INCH
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004106860
Country: USA

Mailing Info:

Name: CON ED
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE1322307
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/04/2003
Trans1 Recv Date: 02/04/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/05/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004106860
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSD ID: 46690JM
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

Y182
SSW
1/8-1/4
0.138 mi.
730 ft.

HPD
534 9TH AVE
MANHATTAN, NY 10018

Site 7 of 8 in cluster Y

NY AST
NY HIST AST

U003396148
N/A

Relative:
Higher

AST:

Actual:
32 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-601370
Program Type: PBS
UTM X: 584976.83765999996
UTM Y: 4512259.3612200003
Expiration Date: 04/25/2015
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 23337
Affiliation Type: Mail Contact
Company Name: 534 9TH AVE HDFC
Contact Type: Not reported
Contact Name: ETHAN ROZENBLATT
Address1: 221 WEST 38TH ST
Address2: STE 300
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 974-0044
EMail: ECMANAG@AOL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/9/2013

Site Id: 23337
Affiliation Type: On-Site Operator
Company Name: HPD
Contact Type: Not reported
Contact Name: 534 9TH AVE HDFC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 974-0044
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/9/2013

Site Id: 23337
Affiliation Type: Emergency Contact
Company Name: 534 9TH AVE HDFC
Contact Type: Not reported
Contact Name: MANUEL LOPEZ
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HPD (Continued)

U003396148

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 392-3983
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/9/2013

Site Id: 23337
Affiliation Type: Facility Owner
Company Name: 534 9TH AVE HDFC
Contact Type: MANAGING AGENT
Contact Name: ETHAN ROSENBLATT
Address1: 221 WEST 38TH ST STE 300
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 974-0044
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/9/2013

Tank Info:

Tank Number: 1
Tank Id: 45782
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1901
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 07/09/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HPD (Continued)

U003396148

HIST AST:

PBS Number: 2-601370
SWIS Code: 6201
Operator: LETICIA MACHADO
Facility Phone: (212) 695-6961
Facility Addr2: 534 9TH AVE
Facility Type: APARTMENT BUILDING
Emergency: JOSEPH ROSSI
Emergency Tel: (212) 268-3414
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: HPD/T.I.L. PROGRAM
Owner Address: 150 WILLIAM STREET,5TH FLOOR
Owner City,St,Zip: NEW YORK, NY 10038
Federal ID: Not reported
Owner Tel: (212) 240-5643
Owner Type: Local Government
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: HPD/T.I.L. PROGRAM
Mailing Address: 150 WILLIAM STREET
Mailing Address 2: 5TH FLOOR
Mailing City,St,Zip: NEW YORK, NY 10038
Mailing Telephone: (212) 240-5643
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 03/05/1993
Expiration: 03/04/1998
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 1
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 0
Pipe Location: Aboveground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HPD (Continued)

U003396148

Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 0
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 6
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

AE183
NW
1/8-1/4
0.138 mi.
731 ft.

CON EDISON MANHOLE: 43279
W 43RD ST & 10TH AVE NE COR
NEW YORK, NY 10036

RCRA-CESQG

1016149258
NYP004279212

Site 2 of 11 in cluster AE

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 11/29/2012

Facility name: CON EDISON MANHOLE: 43279
Facility address: W 43RD ST & 10TH AVE NE COR
NEW YORK, NY 10036

EPA ID: NYP004279212
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported

Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported

EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 43279 (Continued)

1016149258

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AE184
NW
1/8-1/4
0.139 mi.
733 ft.

500 W 43RD ST
NEW YORK, NY 10036

Site 3 of 11 in cluster AE

EDR US Hist Cleaners 1015068153
N/A

Relative:
Lower

EDR Historical Cleaners:

Name: STRAND HONGS CLEANER INC
Year: 2010
Address: 500 W 43RD ST

Actual:
23 ft.

Name: STRAND HONGS CLEANER INC
Year: 2011
Address: 500 W 43RD ST

Name: STRAND HONGS CLEANER INC
Year: 2012
Address: 500 W 43RD ST

AE185
NW
1/8-1/4
0.139 mi.
733 ft.

THE STRAND CONDOMINIUM
500 WEST 43RD STREET
NEW YORK, NY 10036

Site 4 of 11 in cluster AE

NY AST U004078423
N/A

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-601661
Program Type: PBS
UTM X: 584856.73736999999
UTM Y: 4512639.4491299996
Expiration Date: 12/14/2013
Site Type: Apartment Building/Office Building

Actual:
23 ft.

Affiliation Records:

Site Id: 23623
Affiliation Type: Facility Owner
Company Name: THE STRAND
Contact Type: Not reported
Contact Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STRAND CONDOMINIUM (Continued)

U004078423

Address1: 500 WEST 43RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 634-8900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/23/2009

Site Id: 23623
Affiliation Type: Mail Contact
Company Name: COOPER SQUARE REALTY
Contact Type: Not reported
Contact Name: BENJAMIN HAWKINS
Address1: 6 EAST 43RD STREET
Address2: 14TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 634-8988
EMail: ZOE.MAGID@COOPERSQUARE.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/6/2010

Site Id: 23623
Affiliation Type: On-Site Operator
Company Name: THE STRAND CONDOMINIUM
Contact Type: Not reported
Contact Name: LUIS RUIZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-1632
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/23/2009

Site Id: 23623
Affiliation Type: Emergency Contact
Company Name: THE STRAND
Contact Type: Not reported
Contact Name: JENNIFER GRANDA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STRAND CONDOMINIUM (Continued)

U004078423

Phone: (212) 634-8900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/23/2009

Tank Info:

Tank Number: 001
Tank Id: 47380
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1988
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 03/31/2009
Material Name: #6 Fuel Oil (On-Site Consumption)

AE186
NW
1/8-1/4
0.139 mi.
733 ft.
TEN STAR CORP.
501 WEST 43RD STREET
NEW YORK, NY 10036
Site 5 of 11 in cluster AE

NY AST **A100177765**
N/A

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-212318
Program Type: PBS
UTM X: 584861.16579999996
UTM Y: 4512650.8239399996
Expiration Date: 07/03/2016
Site Type: Apartment Building/Office Building

Actual:
23 ft.

Affiliation Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TEN STAR CORP. (Continued)

A100177765

Site Id: 7781
Affiliation Type: Facility Owner
Company Name: TEN STAR CORP.
Contact Type: SEC. OF CORP
Contact Name: SOLOMON GOTTLIEB
Address1: 5210 16TH AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 435-5360
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 5/22/2006

Site Id: 7781
Affiliation Type: Mail Contact
Company Name: NOAM CORPORATION
Contact Type: Not reported
Contact Name: SOLOMON GOTTLIEB
Address1: 5210 16TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 435-5360
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 5/22/2006

Site Id: 7781
Affiliation Type: On-Site Operator
Company Name: TEN STAR CORP.
Contact Type: Not reported
Contact Name: CRUZ MITRE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 626-6523
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 5/22/2006

Site Id: 7781
Affiliation Type: Emergency Contact
Company Name: TEN STAR CORP.
Contact Type: Not reported
Contact Name: G. BAUER INC.
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TEN STAR CORP. (Continued)

A100177765

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 299-1650
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 18744
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/18/1927
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 06/23/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

AF187 WEST 45TH STREET ASSOCIATES
NNE 425 W. 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.139 mi.
733 ft. Site 1 of 5 in cluster AF

NY AST A100183061
N/A

Relative: AST:
Higher Region: STATE
DEC Region: 2
Actual: Site Status: Active
35 ft. Facility Id: 2-606415

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 45TH STREET ASSOCIATES (Continued)

A100183061

Program Type: PBS
UTM X: 585086.33536000003
UTM Y: 4512683.1052400004
Expiration Date: 07/18/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 28278
Affiliation Type: Facility Owner
Company Name: WEST 45TH STREET ASSOCIATES
Contact Type: MANAGING AGENT
Contact Name: MARTIN HOLLANDER
Address1: 425 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 213-0123
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 6/27/2006

Site Id: 28278
Affiliation Type: Mail Contact
Company Name: MARTIN MANAGEMENT
Contact Type: Not reported
Contact Name: MARTIN HOLLANDER
Address1: 114 EAST 39TH STREET
Address2: Not reported
City: NEW YORK,
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 213-0123
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28278
Affiliation Type: On-Site Operator
Company Name: WEST 45TH STREET ASSOCIATES
Contact Type: Not reported
Contact Name: MOHAMMED KAWOYA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 645-7834
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/14/2011

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 45TH STREET ASSOCIATES (Continued)

A100183061

Site Id: 28278
Affiliation Type: Emergency Contact
Company Name: WEST 45TH STREET ASSOCIATES
Contact Type: Not reported
Contact Name: MARTIN HOLLANDER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 213-0123
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 61401
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/10/1950
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 06/14/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AE188
NW
1/8-1/4
0.139 mi.
734 ft.

CONSOLIDATED EDISON
W 43 ST & 10TH AVE
NEW YORK, NY 10020

Site 6 of 11 in cluster AE

NY MANIFEST **S109064866**
N/A

Relative: NY MANIFEST:
Lower EPA ID: NYP001157954
Country: USA

Actual: Mailing Info:
23 ft. Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

NY MANIFEST:
No Manifest Records Available

AG189
NE
1/8-1/4
0.139 mi.
736 ft.

401 W 45TH ST
NEW YORK, NY 10036

Site 1 of 12 in cluster AG

EDR US Hist Auto Stat **1015471281**
N/A

Relative: EDR Historical Auto Stations:
Higher Name: BAIRS COLLISION REPAIR
Year: 2010
Address: 401 W 45TH ST

Name: BAIRS COLLISION REPAIR
Year: 2011
Address: 401 W 45TH ST

Name: BAIRS COLLISION REPAIR
Year: 2012
Address: 401 W 45TH ST

AG190
NE
1/8-1/4
0.140 mi.
738 ft.

CON EDISON - MH M39899
9TH AVE & W. 45TH STREET
NEW YORK, NY 10036

Site 2 of 12 in cluster AG

RCRA NonGen / NLR **1008195696**
NY MANIFEST **NYP004112843**

Relative: RCRA NonGen / NLR:
Higher Date form received by agency: 02/27/2004
Facility name: CON EDISON - MH M39899
Facility address: 9TH AVE & W. 45TH STREET
NEW YORK, NY 10036

EPA ID: NYP004112843
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003

Contact: ANTHONY DRUMMINGS
Contact address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MH M39899 (Continued)

1008195696

Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/09/2003
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/09/2003
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/26/2004
Site name: CON EDISON - MH M39899
Classification: Not a generator, verified

Date form received by agency: 02/25/2004
Site name: CON EDISON - MH M39899
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MH M39899 (Continued)

1008195696

EPA ID: NYP004112843
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NJA4115607
Manifest Status: Not reported
Trans1 State ID: NJD003812097
Trans2 State ID: NJD003812047
Generator Ship Date: 07/09/2003
Trans1 Recv Date: 07/09/2003
Trans2 Recv Date: 07/15/2003
TSD Site Recv Date: 07/15/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004112843
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: H10376
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Document ID: NJA4118278
Manifest Status: Not reported
Trans1 State ID: NJD003812097
Trans2 State ID: Not reported
Generator Ship Date: 07/09/2003
Trans1 Recv Date: 07/09/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004112843
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: H10376
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00658
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MH M39899 (Continued)

1008195696

EPA ID: NYT004112843
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NJA4115607
Manifest Status: Not reported
Trans1 State ID: NJD003812097
Trans2 State ID: NJD003812047
Generator Ship Date: 07/09/2003
Trans1 Recv Date: 07/09/2003
Trans2 Recv Date: 07/15/2003
TSD Site Recv Date: 07/15/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004112843
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: H10376
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Document ID: NJA4118278
Manifest Status: Not reported
Trans1 State ID: NJD003812097
Trans2 State ID: Not reported
Generator Ship Date: 07/09/2003
Trans1 Recv Date: 07/09/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004112843
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: H10376
Waste Code: D005 - BARIUM 100.0 MG/L TCLP
Quantity: 00658
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AF191
NNE
1/8-1/4
0.140 mi.
739 ft.
427 WEST 45ST C/O B. HAVIV ASSOCIATES
427 WEST 45 TH ST
MANHATTAN, NY 10036
Site 2 of 5 in cluster AF

NY AST
NY HIST AST
U003388149
N/A

Relative:
Higher

AST:

Actual:
35 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-257974
Program Type: PBS
UTM X: 585115.84779000003
UTM Y: 4512696.2679099999
Expiration Date: 07/10/2012
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 10663
Affiliation Type: Facility Owner
Company Name: BARUCH HAVIV
Contact Type: OWNER-MANAGER
Contact Name: BARUCH HAVIV
Address1: PO BOX 10
Address2: Not reported
City: CRESSKILL
State: NJ
Zip Code: 07626
Country Code: 001
Phone: (212) 307-1994
EMail: BOUKI379@AOL.COM
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/3/2007

Site Id: 10663
Affiliation Type: Mail Contact
Company Name: BARUCH HAVIV
Contact Type: OWNER-MANAGER
Contact Name: BARUCH HAVIV
Address1: PO BOX 10
Address2: Not reported
City: CRESSKILL
State: NJ
Zip Code: 07626
Country Code: 001
Phone: (212) 307-1994
EMail: BOUKI379@AOL.COM
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/3/2007

Site Id: 10663
Affiliation Type: On-Site Operator
Company Name: 427 WEST 45ST C/O B. HAVIV ASSOCIATES
Contact Type: Not reported
Contact Name: BARUCH HAVIV
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

427 WEST 45ST C/O B. HAVIV ASSOCIATES (Continued)

U003388149

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-1994
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 10663
Affiliation Type: Emergency Contact
Company Name: 427 WEST 45TH ST C/O B. HAVIV ASSOCIATES
Contact Type: Not reported
Contact Name: RON HAVIV
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 315-3047
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 13250
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H99 - Tank Leak Detection - Other

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1976
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/2008
Register: True
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

427 WEST 45TH ST C/O B. HAVIV ASSOCIATES (Continued)

U003388149

Last Modified: 05/10/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-257974
SWIS Code: 6201
Operator: BARUCH HAVIV
Facility Phone: (212) 307-1994
Facility Addr2: 427 WEST 45 TH ST
Facility Type: APARTMENT BUILDING
Emergency: RON HAVIV
Emergency Tel: (212) 315-3047
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 427 WEST 45TH ST C/O B. HAVIV ASSOCIATES
Owner Address: PO BOX 10
Owner City,St,Zip: CRESSKILL, NJ 07626
Federal ID: Not reported
Owner Tel: (212) 307-1994
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: BARUCH HAVIV
Mailing Name: 427 WEST 45TH ST ASSOCIATES
Mailing Address: PO BOX 10
Mailing Address 2: Not reported
Mailing City,St,Zip: CRESSKILL, NJ 07626
Mailing Telephone: (212) 307-1994
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 07/10/1997
Expiration: 07/10/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

427 WEST 45TH C/O B. HAVIV ASSOCIATES (Continued)

U003388149

Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

AF192
NNE
1/8-1/4
0.140 mi.
739 ft.

427 W 45TH ST
NEW YORK, NY 10036
Site 3 of 5 in cluster AF

EDR US Hist Auto Stat 1015490483
N/A

Relative:
Higher

EDR Historical Auto Stations:
Name: A GEICO AUTOMOTIVE INC
Year: 2003
Address: 427 W 45TH ST

Actual:
35 ft.

AG193
NE
1/8-1/4
0.140 mi.
740 ft.

CON EDISION - MH39899
45TH ST & 9TH AVENUE 45TH ST &
NEW YORK, NY 10003
Site 3 of 12 in cluster AG

RCRA NonGen / NLR 1007207747
NY MANIFEST NYP004074506

Relative:
Higher

RCRA NonGen / NLR:
Date form received by agency: 06/02/2002
Facility name: CON EDISION - MH39899
Facility address: 45TH ST & 9TH AVENUE 45TH ST &
NEW YORK, NY 10003
EPA ID: NYP004074506
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
37 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - MH39899 (Continued)

1007207747

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 06/01/2002
Site name: CON EDISION - MH39899
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - MH39899
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004074506
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: CTF0833905
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 02/14/2001
Trans1 Recv Date: 02/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/16/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004074506
Trans1 EPA ID: CTD000604488
Trans2 EPA ID: Not reported
TSD ID: 18014MA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - MH39899 (Continued)

1007207747

Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: CTF0833947
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 02/14/2001
Trans1 Recv Date: 02/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/15/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004074506
Trans1 EPA ID: CTD000604488
Trans2 EPA ID: Not reported
TSD ID: 51440MASS
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00003
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

AF194
North
1/8-1/4
0.140 mi.
741 ft.
BARUCH HAVIV
431 W 45TH ST
MANHATTAN, NY 10036
Site 4 of 5 in cluster AF

NY AST
NY HIST AST
U003389823
N/A

Relative:
Higher

AST:

Actual:
34 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-286141
Program Type: PBS
UTM X: 585106.58852999995
UTM Y: 4512701.26841
Expiration Date: 07/20/2012
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 12751
Affiliation Type: Facility Owner
Company Name: SUZANNE AND BARUCH HAVIV
Contact Type: OWNER - MANAGER
Contact Name: BARUCH HAVIV
Address1: P.O. BOX 10
Address2: Not reported
City: CRESSKILL
State: NJ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BARUCH HAVIV (Continued)

U003389823

Zip Code: 07626
Country Code: 001
Phone: (212) 307-1994
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/3/2012

Site Id: 12751
Affiliation Type: Mail Contact
Company Name: BARUCH HAVIV
Contact Type: Not reported
Contact Name: SUPER/ FACILITY MANAGER
Address1: 431 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 307-1994
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12751
Affiliation Type: On-Site Operator
Company Name: BARUCH HAVIV
Contact Type: Not reported
Contact Name: BARUCH HAVIV
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-1994
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/3/2012

Site Id: 12751
Affiliation Type: Emergency Contact
Company Name: SUZANNE AND BARUCH HAVIV
Contact Type: Not reported
Contact Name: RON HAVIV
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 315-3047
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BARUCH HAVIV (Continued)

U003389823

Date Last Modified: 7/3/2012

Tank Info:

Tank Number: 001
Tank Id: 17663
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 02/01/1978
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/10/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 07/03/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-286141
SWIS Code: 6201
Operator: BARUCH HAVIV
Facility Phone: (212) 307-1994
Facility Addr2: 431 W 45TH ST
Facility Type: APARTMENT BUILDING
Emergency: RON HAVIV
Emergency Tel: (212) 315-3047
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: SUZANNE&BARUCH HAVIV
Owner Address: P O BOX 10
Owner City,St,Zip: CRESSKILL, NJ 07626
Federal ID: Not reported
Owner Tel: (212) 307-1994
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BARUCH HAVIV (Continued)

U003389823

Mailing Name: SUZANNE&BARUCH HAVIV
Mailing Address: P O BOX 10
Mailing Address 2: Not reported
Mailing City,St,Zip: CRESSKILL, NJ 07626
Mailing Telephone: (212) 307-1994
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 07/10/1997
Expiration: 07/20/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AH195
WNW
1/8-1/4
0.141 mi.
744 ft.

NEW YORK TRANSIT AUTH
565 TENTH AVE
NEW YORK, NY 10036

Site 1 of 5 in cluster AH

RCRA NonGen / NLR

1007449208
NYR000126235

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: NEW YORK TRANSIT AUTH

Facility address: 565 TENTH AVE
NEW YORK, NY 10036

EPA ID: NYR000126235

Mailing address: BROADWAY
NEW YORK, NY 10004

Contact: THOMAS ABDALLAH

Contact address: BROADWAY
NEW YORK, NY 10004

Contact country: US

Contact telephone: (646) 252-3500

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NO NAME FOUND

Owner/operator address: Not reported
Not reported

Owner/operator country: US

Owner/operator telephone: Not reported

Legal status: Municipal

Owner/Operator Type: Owner

Owner/Op start date: 07/30/2004

Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND

Owner/operator address: Not reported
Not reported

Owner/operator country: US

Owner/operator telephone: Not reported

Legal status: Municipal

Owner/Operator Type: Operator

Owner/Op start date: 07/30/2004

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TRANSIT AUTH (Continued)

1007449208

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Site name: NEW YORK TRANSIT AUTH

Classification: Not a generator, verified

Date form received by agency: 08/03/2004

Site name: NEW YORK TRANSIT AUTH

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

AF196 432 WEST 45TH STREET
NNE 432 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.141 mi.
745 ft. Site 5 of 5 in cluster AF

NY AST U004078697
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-607273
Program Type: PBS
UTM X: 585063.21806999994
UTM Y: 4512681.9515199997
Expiration Date: 01/03/2017
Site Type: Other

Actual:
34 ft.

Affiliation Records:

Site Id: 29126
Affiliation Type: Facility Owner
Company Name: REISS REALTY CORP.
Contact Type: PRES
Contact Name: NEAL PILZER
Address1: 432 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 245-0969
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 12/19/2006

Site Id: 29126
Affiliation Type: Mail Contact
Company Name: REISS REALTY CORP.
Contact Type: PRES
Contact Name: NEAL PILZER
Address1: 432 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

432 WEST 45TH STREET (Continued)

U004078697

Zip Code: 10036
Country Code: 001
Phone: (212) 245-0969
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 12/19/2006

Site Id: 29126
Affiliation Type: On-Site Operator
Company Name: 432 WEST 45TH STREET
Contact Type: Not reported
Contact Name: NEAL PILZER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-0969
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29126
Affiliation Type: Emergency Contact
Company Name: REISS REALTY CORP.
Contact Type: Not reported
Contact Name: NEAL PILZER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 261-9000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 1
Tank Id: 62652
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

432 WEST 45TH STREET (Continued)

U004078697

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/18/1957
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 12/05/2011
Material Name: #4 Fuel Oil (On-Site Consumption)

AI197
East
1/8-1/4
0.141 mi.
746 ft.

CON EDISON SERVICE BOX: 8491
357 W 44TH ST
NEW YORK, NY 10036
Site 1 of 8 in cluster AI

RCRA-CESQG 1016148567
FINDS NYP004271458

Relative:
Higher

RCRA-CESQG:

Actual:
37 ft.

Date form received by agency: 10/01/2012
Facility name: CON EDISON SERVICE BOX: 8491
Facility address: 357 W 44TH ST
NEW YORK, NY 10036
EPA ID: NYP004271458
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: RICARDO CARTY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 643-3044
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8491 (Continued)

1016148567

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055467276

Environmental Interest/Information System

Y198 536 9TH AVE
SSW 536 NINTH AVENUE
1/8-1/4 NEW YORK, NY 10018
0.141 mi.
747 ft. Site 8 of 8 in cluster Y

NY AST **A100354002**
N/A

Relative:
Higher

AST:

Actual:
32 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-042927
Program Type: PBS
UTM X: 584980.31302999996
UTM Y: 4512265.5071999999
Expiration Date: 06/12/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 364
Affiliation Type: Mail Contact
Company Name: TPEC MANAGEMENT
Contact Type: Not reported
Contact Name: ANTONINO PECORA
Address1: 506 9TH AVENUE
Address2: SUITE 2FN
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 643-2616
EMail: TPECNY@YAHOO.COM
Fax Number: Not reported
Modified By: KAKYER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

536 9TH AVE (Continued)

A100354002

Date Last Modified: 6/6/2013

Site Id: 364
Affiliation Type: On-Site Operator
Company Name: 536 9TH AVE
Contact Type: Not reported
Contact Name: 536 NINTH LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-2616
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 6/26/2009

Site Id: 364
Affiliation Type: Emergency Contact
Company Name: 536 NINTH LLC
Contact Type: Not reported
Contact Name: ANTONINO PECORA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 643-2616
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 6/26/2009

Site Id: 364
Affiliation Type: Facility Owner
Company Name: 536 NINTH LLC
Contact Type: OWNER
Contact Name: ANTONINO PECORA
Address1: 506 9TH AVE., SUITE 2FN
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 643-2616
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 6/6/2013

Tank Info:

Tank Number: 001
Tank Id: 1963

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

536 9TH AVE (Continued)

A100354002

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H04 - Tank Leak Detection - Groundwater Well
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1920
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 06/06/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

AG199
NE
1/8-1/4
0.142 mi.
748 ft.

CON EDISON
642 NINTH AVE
NEW YORK, NY 10036
Site 4 of 12 in cluster AG

NY MANIFEST S112210735
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269254
Country: USA

Actual:
37 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210735

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269254
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457223JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269254
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457223JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210735

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

**AG200
NE
1/8-1/4
0.142 mi.
748 ft.**

**CON EDISON SERVICE BOX: 8519
642 9TH AVE
NEW YORK, NY 10036**

RCRA-CESQG

**1016144136
NYP004269247**

Site 5 of 12 in cluster AG

**Relative:
Higher**

RCRA-CESQG:

Date form received by agency: 09/18/2012

Facility name: CON EDISON SERVICE BOX: 8519

Facility address: 642 9TH AVE
NEW YORK, NY 10036

EPA ID: NYP004269247

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8519 (Continued)

1016144136

Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

**AE201
NW
1/8-1/4
0.142 mi.
749 ft.**

**595 10TH AVE
NEW YORK, NY 10036**

Site 7 of 11 in cluster AE

**EDR US Hist Cleaners 1015078323
N/A**

**Relative:
Lower**

EDR Historical Cleaners:

Name: OMNI DRY CLEANERS
Year: 2001
Address: 595 10TH AVE

**Actual:
23 ft.**

Name: OMNI DRY CLEANERS
Year: 2003
Address: 595 10TH AVE

Name: OMNI DRY CLEANERS
Year: 2004
Address: 595 10TH AVE

Name: OMNI DRY CLEANERS
Year: 2005
Address: 595 10TH AVE

Name: OMNI DRY CLEANERS
Year: 2006
Address: 595 10TH AVE

Name: OMNI DRY CLEANERS INC
Year: 2007
Address: 595 10TH AVE

Name: OMNI DRY CLEANERS CORPORATE
Year: 2008
Address: 595 10TH AVE

**AE202
NW
1/8-1/4
0.142 mi.
749 ft.**

**OMNI CLEANERS CORP
595 10TH AVE
NEW YORK, NY 10036**

Site 8 of 11 in cluster AE

**RCRA-SQG 1004759351
NYR000007757**

**Relative:
Lower**

RCRA-SQG:

Date form received by agency: 01/01/2007
Facility name: OMNI CLEANERS CORP
Facility address: 595 10TH AVE

**Actual:
23 ft.**

NEW YORK, NY 10036
EPA ID: NYR000007757
Mailing address: 10TH AVE

NEW YORK, NY 10036
Contact: WON BOK RHEE
Contact address: 10TH AVE
NEW YORK, NY 10036

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

OMNI CLEANERS CORP (Continued)

1004759351

Contact country: US
Contact telephone: (212) 244-0328
Contact email: Not reported
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: OMNI CLEANERS CORP
Owner/operator address: 595 10TH AVE
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: (212) 244-0328
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: OMNI CLEANERS CORP
Owner/operator address: 595 10TH AVE
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: (212) 244-0328
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: OMNI CLEANERS CORP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/07/1995
Site name: OMNI CLEANERS CORP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

OMNI CLEANERS CORP (Continued)

1004759351

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

**AE203
NW
1/8-1/4
0.142 mi.
749 ft.**

**OMNI CLEANERS
595 10TH AVENUE
NEW YORK, NY 10036

Site 9 of 11 in cluster AE**

**NY MANIFEST
NY DRYCLEANERS**

**S110247515
N/A**

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYR000007757
Country: USA

**Actual:
23 ft.**

Mailing Info:
Name: OMNI CLEANERS
Contact: RHEE WON BOK
Address: 608 10TH AVENUE
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-244-0328

NY MANIFEST:
No Manifest Records Available

DRYCLEANERS:
Facility ID: 2-6202-00652
Phone Number: 212-244-0328
Region: Not reported
Registration Effective Date: 5/11/1999 10:26:28:616
Inspection Date: 08JUL25
Install Date: 95/98/08
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

**AH204
West
1/8-1/4
0.143 mi.
754 ft.**

**CON EDISON
563 10TH AVE
NEW YORK, NY 10036

Site 2 of 5 in cluster AH**

NY MANIFEST

**S112210628
N/A**

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYP004268140
Country: USA

**Actual:
23 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210628

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268140
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457014JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268140
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210628

Manifest Tracking Num: 010457014JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AH205
West
1/8-1/4
0.145 mi.
766 ft.

CON EDISON
OPP 561 10TH AVE
NEW YORK, NY 10036

NY MANIFEST

S112210627
N/A

Site 3 of 5 in cluster AH

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268132
Country: USA

Actual:
23 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268132
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457013JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210627

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268132
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457013JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AH206
West
1/8-1/4
0.145 mi.
766 ft.

501 WEST 41ST STREET ASSOCIATES, LLC
561 10TH AVENUE
NEW YORK, NY 10036
Site 4 of 5 in cluster AH

NY AST A100292466
N/A

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609788
Program Type: PBS
UTM X: 584758.23528000002

Actual:
23 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

501 WEST 41ST STREET ASSOCIATES, LLC (Continued)

A100292466

UTM Y: 4512510.5898200003
Expiration Date: 12/16/2014
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 335214
Affiliation Type: Facility Owner
Company Name: 501 WEST 41ST STREET ASSOCIATES, LLC
Contact Type: VP
Contact Name: DANIELA LUCCHETTO
Address1: ONE BRYANT PARK,48TH FLR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 427-9700
EMail: DLUCCHETTO@FETNER.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/13/2012

Site Id: 335214
Affiliation Type: Mail Contact
Company Name: 501 WEST 41ST STREET ASSOCIATES, LLC
Contact Type: VP
Contact Name: DANIELA LUCCHETTO
Address1: ONE BRYANT PARK,48TH FLR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 427-9700
EMail: DLUCCHETTO@FETNER.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/13/2012

Site Id: 335214
Affiliation Type: On-Site Operator
Company Name: 501 WEST 41ST STREET ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: NESTOR CERALLOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-5142
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/13/2012

Site Id: 335214
Affiliation Type: Emergency Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

501 WEST 41ST STREET ASSOCIATES, LLC (Continued)

A100292466

Company Name: 501 WEST 41ST STREET ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: DANIELA LUCCHETTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 742-9700
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/13/2012

Tank Info:

Tank Number: 001
Tank Id: 181139
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2002
Capacity Gallons: 15000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 01/13/2012
Material Name: #4 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AH207
West
1/8-1/4
0.145 mi.
766 ft.

CON EDISON SERVICE BOX: 43260
561 10TH AVE OPPOSITE OF
NEW YORK, NY 10036
Site 5 of 5 in cluster AH

RCRA-CESQG
FINDS
1016144026
NYP004268132

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 43260

Facility address: 561 10TH AVE OPPOSITE OF

NEW YORK, NY 10036

EPA ID: NYP004268132

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055424642

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43260 (Continued)

1016144026

Environmental Interest/Information System

**AJ208
SE
1/8-1/4
0.146 mi.
769 ft.**

**CON EDISON
336 W 42ND ST
NEW YORK, NY 10036

Site 1 of 10 in cluster AJ**

**NY MANIFEST S112210641
N/A**

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004268272
Country: USA

**Actual:
39 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456579JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210641

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268272
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456579JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AJ209 **CON EDISON SERVICE BOX: 8125**
SE **336 W 42ND ST**
1/8-1/4 **NEW YORK, NY 10036**
0.146 mi.
769 ft. **Site 2 of 10 in cluster AJ**

RCRA-CESQG **1016144040**
FINDS **NYP004268272**

Relative:
Higher

RCRA-CESQG:

Actual:
39 ft.

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 8125
Facility address: 336 W 42ND ST
NEW YORK, NY 10036
EPA ID: NYP004268272
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8125 (Continued)

1016144040

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428149

Environmental Interest/Information System

AB210
WSW
1/8-1/4
0.146 mi.
773 ft.

CON EDISON
OPP 461 W 40TH ST
NEW YORK, NY 10018

NY MANIFEST **S112210337**
N/A

Site 3 of 4 in cluster AB

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265070
Country: USA

Actual:
29 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210337

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265070
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456117JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265070
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210337

Manifest Tracking Num: 010456117JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AG211
NE
1/8-1/4
0.147 mi.
774 ft.

644 NINTH AVE
644 NINTH AVENUE
NEW YORK, NY 10036

NY AST **U003385308**
NY HIST AST **N/A**

Site 6 of 12 in cluster AG

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-112682
Program Type: PBS
UTM X: 585195.76607000001
UTM Y: 4512669.3209300004
Expiration Date: 06/05/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 3582
Affiliation Type: Facility Owner
Company Name: T J MANAGEMENT CORP
Contact Type: REGISTERED AGENT
Contact Name: ERIC GULLY
Address1: 939 ONDERDONK AVENUE
Address2: Not reported
City: RIDGEWOOD
State: NY
Zip Code: 11385
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 6/28/2007

Site Id: 3582
Affiliation Type: Mail Contact
Company Name: T J MANAGEMENT CORP
Contact Type: REGISTERED AGENT
Contact Name: ERIC GULLY
Address1: 939 ONDERDONK AVENUE
Address2: Not reported
City: RIDGEWOOD
State: NY
Zip Code: 11385

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

644 NINTH AVE (Continued)

U003385308

Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 6/28/2007

Site Id: 3582
Affiliation Type: On-Site Operator
Company Name: 644 NINTH AVE
Contact Type: Not reported
Contact Name: ERIC GULLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 3582
Affiliation Type: Emergency Contact
Company Name: T J MANAGEMENT CORP
Contact Type: Not reported
Contact Name: ERIC GULLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 5536
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

644 NINTH AVE (Continued)

U003385308

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/18/1980
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUD
Last Modified: 07/03/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-112682
SWIS Code: 6201
Operator: MULLEN & WOODS INC
Facility Phone: (212) 265-5790
Facility Addr2: 644 9TH AVENUE
Facility Type: APARTMENT BUILDING
Emergency: ROY UHL
Emergency Tel: (212) 265-5790
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: T J MANAGEMENT CORP
Owner Address: 40J GULLY 5954 WOODBINE ST
Owner City,St,Zip: RIDGEWOOD, NY 11385
Federal ID: Not reported
Owner Tel: (212) 456-5233
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: JOHN GULLY
Mailing Name: T J MANAGEMENT CORP
Mailing Address: 5954 WOODBINE STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: RIDGEWOOD, NY 11385
Mailing Telephone: (212) 265-5790
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 07/17/1997
Expiration: 06/05/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

644 NINTH AVE (Continued)

U003385308

Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

AB212 **COVENANT HOUSE**
WSW **460 W 41ST STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.148 mi.
779 ft. **Site 4 of 4 in cluster AB**

NY UST **U004122182**
N/A

Relative:
Lower

UST:

Actual:
27 ft.

Id/Status: 2-610819 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 01/01/2011
UTM X: 584801.69819000002
UTM Y: 4512454.3664100002
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 396458
Affiliation Type: Facility Owner
Company Name: COVENANT HOUSE
Contact Type: DIRECTOR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COVENANT HOUSE (Continued)

U004122182

Contact Name: DAVID L. GREGORIO
Address1: 5 PENN PLAZA
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 727-4000
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/16/2008

Site Id: 396458
Affiliation Type: Mail Contact
Company Name: COVENANT HOUSE
Contact Type: Not reported
Contact Name: DAVID L. GREGORIO
Address1: 460 W. 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 330-0547
EMail: DGREGORIO@COVENANTHOUSE.ORG
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/16/2008

Site Id: 396458
Affiliation Type: On-Site Operator
Company Name: COVENANT HOUSE
Contact Type: Not reported
Contact Name: LENNOX EDWARDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 613-0300
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/16/2008

Site Id: 396458
Affiliation Type: Emergency Contact
Company Name: COVENANT HOUSE
Contact Type: Not reported
Contact Name: LENNOX EDWARDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COVENANT HOUSE (Continued)

U004122182

Country Code: 001
Phone: (212) 613-0300
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/16/2008

Tank Info:

Tank Number: ONE
Tank ID: 222479
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 01/01/1996
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: 01/01/2006
Pipe Model: Not reported
Modified By: msbaptis
Last Modified: 06/23/2008

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)

AI213
East
1/8-1/4
0.149 mi.
786 ft.
CON EDISON SERVICE BOX: 8492
351 W 44TH ST
NEW YORK, NY 10036
Site 2 of 8 in cluster AI

RCRA-CESQG
FINDS
1016144129
NYP004269171

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 09/18/2012
Facility name: CON EDISON SERVICE BOX: 8492
Facility address: 351 W 44TH ST
NEW YORK, NY 10036
EPA ID: NYP004269171
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ

Actual:
38 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8492 (Continued)

1016144129

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461209

Environmental Interest/Information System

AI214
East
1/8-1/4
0.149 mi.
787 ft.
CON EDISON
351 W 44
NEW YORK, NY 10036
Site 3 of 8 in cluster AI

NY MANIFEST **S112210727**
N/A

Relative: NY MANIFEST:
Higher EPA ID: NYP004269171
Country: USA
Actual: Mailing Info:
38 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210727

Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269171
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457101JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269171
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210727

TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457101JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AG215
NE
1/8-1/4
0.150 mi.
794 ft.

647 9TH AVE
NEW YORK, NY 10036
Site 7 of 12 in cluster AG

EDR US Hist Cleaners 1015084483
N/A

Relative:
Higher

EDR Historical Cleaners:

Name: O K CLEANERS
Year: 2000
Address: 647 9TH AVE

Actual:
38 ft.

Name: OK CLEANERS INC
Year: 2011
Address: 647 9TH AVE

Name: OK CLEANERS INC
Year: 2012
Address: 647 9TH AVE

AG216
NE
1/8-1/4
0.150 mi.
794 ft.

OK CLEANERS INCORPORATED
647 9TH AVENUE
NEW YORK, NY 10036
Site 8 of 12 in cluster AG

NY MANIFEST S110247504
NY DRYCLEANERS N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYD986889764
Country: USA

Actual:
38 ft.

Mailing Info:
Name: OK CLEANERS INCORPORATED
Contact: OK CLEANERS INCORPORATED
Address: 647 9TH AVENUE
City/State/Zip: NEW YORK, NY 10036
Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

OK CLEANERS INCORPORATED (Continued)

S110247504

Phone: 212-664-9637

NY MANIFEST:

No Manifest Records Available

DRYCLEANERS:

Facility ID: 2-6202-00650
Phone Number: 212-664-9637
Region: Not reported
Registration Effective Date: 5/11/1999 10:16:34:883
Inspection Date: 04MAR9
Install Date: 98
Drop Shop: Y
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

**AG217
NE
1/8-1/4
0.150 mi.
794 ft.**

**O K CLEANERS
647 9TH AVE
NEW YORK, NY 10036**

**RCRA NonGen / NLR 1000107358
FINDS NYD986889764**

Site 9 of 12 in cluster AG

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: O K CLEANERS INC
Facility address: 647 9TH AVE
NEW YORK, NY 10036
EPA ID: NYD986889764
Mailing address: 9TH AVE
NEW YORK, NY 10036
Contact: Not reported
Contact address: 9TH AVE
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

**Actual:
38 ft.**

Owner/Operator Summary:

Owner/operator name: O K CLEANERS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: O K CLEANERS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

O K CLEANERS (Continued)

1000107358

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: O K CLEANERS INC
Classification: Not a generator, verified

Date form received by agency: 03/20/1995
Site name: O K CLEANERS INC
Classification: Not a generator, verified

Date form received by agency: 03/26/1990
Site name: O K CLEANERS INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004441925

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AE218
NW
1/8-1/4
0.151 mi.
798 ft.
CON EDISON SERVICE BOX: 8301
503 W 43RD ST
NEW YORK, NY 10036
Site 10 of 11 in cluster AE

RCRA-CESQG
FINDS
1016144029
NYP004268165

Relative:
Lower

RCRA-CESQG:

Actual:
21 ft.

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 8301
Facility address: 503 W 43RD ST
NEW YORK, NY 10036
EPA ID: NYP004268165
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055424651

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8301 (Continued)

1016144029

Environmental Interest/Information System

AE219
NW
1/8-1/4
0.151 mi.
798 ft.

CON EDISON
503 W 43RD ST
NEW YORK, NY 10036

Site 11 of 11 in cluster AE

NY MANIFEST **S112210630**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268165
Country: USA

Actual:
21 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268165
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457015JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210630

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268165
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457015JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AK220
NNW
1/8-1/4
0.152 mi.
800 ft.

608 10TH AVE
NEW YORK, NY 10036

Site 1 of 5 in cluster AK

EDR US Hist Cleaners 1015080231
N/A

Relative:
Lower

EDR Historical Cleaners:

Name: OMNI DRY CLEANERS
Year: 2009
Address: 608 10TH AVE

Actual:
25 ft.

Name: OMNI DRY CLEANERS
Year: 2010
Address: 608 10TH AVE

Name: OMNI DRY CLEANERS
Year: 2011
Address: 608 10TH AVE

Name: OMNI DRY CLEANERS
Year: 2012
Address: 608 10TH AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AK221 OMNI DRY CLEANERS
NNW 608 10TH AVE
1/8-1/4 NEW YORK, NY 10036
0.152 mi.
800 ft. Site 2 of 5 in cluster AK

NY DRYCLEANERS S110247516
N/A

Relative:
Lower

DRYCLEANERS:

Facility ID: ---
Phone Number: Not reported
Region: 2
Registration Effective Date: Not reported
Inspection Date: Not reported
Install Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: ???

Actual:
25 ft.

AG222 AMETHYST WEST HDFC
NE 646 9TH AVENUE
1/8-1/4 NEW YORK, NY 10036
0.152 mi.
802 ft. Site 10 of 12 in cluster AG

NY AST A100178325
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606112
Program Type: PBS
UTM X: 585164.63641000004
UTM Y: 4512664.4653099999
Expiration Date: 06/26/2016
Site Type: Apartment Building/Office Building

Actual:
38 ft.

Affiliation Records:

Site Id: 27977
Affiliation Type: Facility Owner
Company Name: AMETHYST WEST HDFC % SPARK PROPERTIES
Contact Type: MANAGING AGENT
Contact Name: ZOHAR HALFON
Address1: 347 WEST 44TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 265-6500
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 5/9/2006

Site Id: 27977
Affiliation Type: Mail Contact
Company Name: AMETHYST WEST HDFC
Contact Type: Not reported
Contact Name: Z. HALFON
Address1: % SPARK PROPERTIES
Address2: 347 WEST 44TH STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMETHYST WEST HDFC (Continued)

A100178325

City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 265-6500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27977
Affiliation Type: On-Site Operator
Company Name: AMETHYST WEST HDFC
Contact Type: Not reported
Contact Name: THOMAS TAUSEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 977-8489
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27977
Affiliation Type: Emergency Contact
Company Name: AMETHYST WEST HDFC % SPARK PROPERTIES
Contact Type: Not reported
Contact Name: ZOHAR HALFON, MANAGING AGENT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-6500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 60972
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D02 - Pipe Type - Galvanized Steel
G01 - Tank Secondary Containment - Diking (Aboveground)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMETHYST WEST HDFC (Continued)

A100178325

I05 - Overfill - Vent Whistle
J00 - Dispenser - None
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
E02 - Piping Secondary Containment - Vault (with Access)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1978
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 03/16/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

AJ223
SE
1/8-1/4
0.152 mi.
804 ft.

CHURCH OF THE HOLY CROSS & SCH
332 WEST 42ND STREET
NEW YORK, NY 10036
Site 3 of 10 in cluster AJ

NY AST **U003385248**
N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-061336
Program Type: PBS
UTM X: 585224.57435999997
UTM Y: 4512344.5851299996
Expiration Date: 06/05/2017
Site Type: School

Actual:
39 ft.

Affiliation Records:
Site Id: 1077
Affiliation Type: Facility Owner
Company Name: CHURCH OF THE HOLY CROSS
Contact Type: ADM
Contact Name: GERARD MULVEY
Address1: 329 WEST 42ND ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-4732
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 5/14/2014

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHURCH OF THE HOLY CROSS & SCH (Continued)

U003385248

Site Id:	1077
Affiliation Type:	Mail Contact
Company Name:	CHURCH OF THE HOLY CROSS
Contact Type:	Not reported
Contact Name:	REV. GERARD MULVEY
Address1:	329 WEST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 246-4732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	5/14/2014
Site Id:	1077
Affiliation Type:	On-Site Operator
Company Name:	CHURCH OF THE HOLY CROSS & SCH
Contact Type:	Not reported
Contact Name:	CARLOS CORREA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 246-4732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	1077
Affiliation Type:	Emergency Contact
Company Name:	CHURCH OF THE HOLY CROSS
Contact Type:	Not reported
Contact Name:	CARLOS CORREA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 246-4732
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	5397
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CHURCH OF THE HOLY CROSS & SCH (Continued)

U003385248

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1940
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 05/14/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

AL224 **CON EDISON SERVICE BOX: 43254**
West **548 10TH AVE**
1/8-1/4 **NEW YORK, NY 10036**
0.153 mi.
806 ft. **Site 1 of 9 in cluster AL**

RCRA-CESQG **1016144043**
FINDS **NYP004268306**

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 43254
Facility address: 548 10TH AVE
NEW YORK, NY 10036

EPA ID: NYP004268306
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported

Contact country: Not reported
Contact telephone: (347) 865-5931

Contact email: Not reported
EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43254 (Continued)

1016144043

hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458892

Environmental Interest/Information System

225
WNW
1/8-1/4
0.154 mi.
812 ft.

10TH AVE DEVELOPMENT CORP
506 W 42ND ST
NEW YORK, NY 10036

NY AST
NY HIST AST
U003389581
N/A

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-202282
Program Type: PBS
UTM X: 584805.47791000002
UTM Y: 4512574.4702099999
Expiration Date: 07/20/1992
Site Type: Unknown

Actual:
21 ft.

Affiliation Records:

Site Id: 6918
Affiliation Type: Facility Owner
Company Name: 10TH AVE DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: JH TAYLOR MGT CO 330 W 42ND ST
Address2: Not reported
City: NEW YORK
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

10TH AVE DEVELOPMENT CORP (Continued)

U003389581

Zip Code: 10036
Country Code: 001
Phone: (212) 502-8200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6918
Affiliation Type: Mail Contact
Company Name: 10TH AVE DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: JH TAYLOR MGT CO 330 W 42ND ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 502-8200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6918
Affiliation Type: On-Site Operator
Company Name: 10TH AVE DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: GILBERT SANDOVAL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-8377
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6918
Affiliation Type: Emergency Contact
Company Name: 10TH AVE DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: J H TAYLOR MANAGEMENT CO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 502-8200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

10TH AVE DEVELOPMENT CORP (Continued)

U003389581

Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 16948
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-202282
SWIS Code: 6201
Operator: GILBERT SANDOVAL
Facility Phone: (212) 695-8377
Facility Addr2: 506 W 42ND ST
Facility Type: Not reported
Emergency: J H TAYLOR MANAGEMENT CO
Emergency Tel: (212) 502-8200
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 10TH AVE DEVELOPMENT CORP
Owner Address: JH TAYLOR MGT CO 330 W 42ND ST
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 502-8200
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

10TH AVE DEVELOPMENT CORP (Continued)

U003389581

Mailing Name: 10TH AVE DEVELOPMENT CORP
Mailing Address: JH TAYLOR MGT CO 330 W 42ND ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 502-8200
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 07/20/1987
Expiration: 07/20/1992
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AI226
East
1/8-1/4
0.154 mi.
815 ft.
347-349 W. 44 ST.
347-349 WEST 44TH STREET
NEW YORK, NY 10036
Site 4 of 8 in cluster AI

NY AST U004045449
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-609299
Program Type: PBS
UTM X: 585239.85407
UTM Y: 4512510.3437200002
Expiration Date: 10/16/2008
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 31144
Affiliation Type: Facility Owner
Company Name: LATHAM FORTY-FOUR APT. CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 347-349 W. 44TH ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31144
Affiliation Type: Mail Contact
Company Name: TURF COMPANY
Contact Type: Not reported
Contact Name: JOHN TOUHEY
Address1: 397 BRIDGE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31144
Affiliation Type: On-Site Operator
Company Name: 347-349 W. 44 ST.
Contact Type: Not reported
Contact Name: JOHN TOUHEY
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

347-349 W. 44 ST. (Continued)

U004045449

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 852-3323
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31144
Affiliation Type: Emergency Contact
Company Name: LATHAM FORTY-FOUR APT. CORP.
Contact Type: Not reported
Contact Name: ZOHAR HALFON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-6500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 67059
Material Code: 0000
Common Name of Substance: Empty

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/13/2003
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

347-349 W. 44 ST. (Continued)

U004045449

Material Name: Empty

AI227
East
1/8-1/4
0.154 mi.
815 ft.

347 W 44TH ST
NEW YORK, NY 10036

EDR US Hist Cleaners **1015047275**
N/A

Site 5 of 8 in cluster AI

Relative:
Higher

EDR Historical Cleaners:

Name: K S LAUNDRY & CLEANERS
Year: 1999

Actual:
38 ft.

Address: 347 W 44TH ST

Name: K S LAUNDRY & CLEANERS
Year: 2000
Address: 347 W 44TH ST

Name: TIMES ONE LAUNDRY & DRY CLEANERS
Year: 2009
Address: 347 W 44TH ST

Name: TIMES ONE LAUNDRY & DRY
Year: 2010
Address: 347 W 44TH ST

Name: TIMES ONE LAUNDRY & DRY CLEANERS
Year: 2011
Address: 347 W 44TH ST

Name: TIMES ONE LAUNDRY & DRY CLEANERS
Year: 2012
Address: 347 W 44TH ST

AG228
NE
1/8-1/4
0.155 mi.
819 ft.

649-9TH AVE
649 NINTH AVENUE
NEW YORK, NY 10036

NY AST **U003387741**
NY HIST AST **N/A**

Site 11 of 12 in cluster AG

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-233749
Program Type: PBS
UTM X: 585191.43853000004
UTM Y: 4512685.9241899997
Expiration Date: 06/30/2019
Site Type: Apartment Building/Office Building

Actual:
38 ft.

Affiliation Records:

Site Id: 8521
Affiliation Type: Mail Contact
Company Name: THREE HAND REALTY LLC
Contact Type: OWNER
Contact Name: ELMADANI SADEK
Address1: 829 6TH AVE, 2ND FLOOR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

649-9TH AVE (Continued)

U003387741

Address2: Not reported
City: NY
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 564-1414
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/30/2014

Site Id: 8521
Affiliation Type: On-Site Operator
Company Name: 649 LLC
Contact Type: Not reported
Contact Name: PEREZ P. GILBERTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 716-0270
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/30/2014

Site Id: 8521
Affiliation Type: Emergency Contact
Company Name: THREE HAND REALTY LLC
Contact Type: Not reported
Contact Name: PEREZ P. GILBERTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 716-0270
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/30/2014

Site Id: 8521
Affiliation Type: Facility Owner
Company Name: THREE HAND REALTY LLC
Contact Type: OWNER
Contact Name: ELMADANI SADEK
Address1: 829 6TH AVE, 2ND FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 564-1414

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

649-9TH AVE (Continued)

U003387741

Email: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/30/2014

Tank Info:

Tank Number: 001
Tank Id: 12502
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/2010
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 06/30/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-233749
SWIS Code: 6201
Operator: 649-51 9TH AVE CORP % A CLARKE
Facility Phone: (212) 265-0004
Facility Addr2: 649 9TH AVENUE
Facility Type: APARTMENT BUILDING
Emergency: VALERIE RUSSO
Emergency Tel: (212) 265-0004
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 649-51 9TH AVE CORP % A CLARKE
Owner Address: 1881 BROADWAY
Owner City,St,Zip: NEW YORK, NY 10023

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

649-9TH AVE (Continued)

U003387741

Federal ID: Not reported
Owner Tel: (212) 541-4477
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: STEPHEN DENARRO
Mailing Name: 649-51 9TH AVE CORP % A CLARKE
Mailing Address: 1881 BROADWAY
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10023
Mailing Telephone: (212) 541-4477
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 07/10/1997
Expiration: 07/10/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AJ229
SE
1/8-1/4
0.155 mi.
820 ft.

HOLY CROSS CHURCH
331 WEST 42ND STREET
NEW YORK, NY 10036

Site 4 of 10 in cluster AJ

NY MANIFEST **S110047050**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYR000164921
Country: USA

Actual:
40 ft.

Mailing Info:
Name: HOLY CROSS CHURCH
Contact: HOLY CROSS CHURCH
Address: 329 W 42ND ST
City/State/Zip: MANHATTAN, NY 10036
Country: USA
Phone: 212-246-4732

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2009-05-28
Trans1 Recv Date: 2009-05-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-01
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164921
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 2400.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000201299WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2009-05-22

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLY CROSS CHURCH (Continued)

S110047050

Trans1 Recv Date: 2009-05-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-05-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164921
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 1600.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000201265WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2009-05-22
Trans1 Recv Date: 2009-05-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-05-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164921
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 1600.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000201265WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLY CROSS CHURCH (Continued)

S110047050

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2009-05-28
Trans1 Recv Date: 2009-05-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-01
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000164921
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 2400.0
Units: P - Pounds
Number of Containers: 4.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000201299WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AL230
West
1/8-1/4
0.156 mi.
823 ft.

551 10TH AVE
NEW YORK, NY 10018
Site 2 of 9 in cluster AL

EDR US Hist Auto Stat 1015550568
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: NEW YORK TOWING & AUTO CARE
Year: 2011
Address: 551 10TH AVE

Actual:
23 ft.

Name: NEW YORK TOWING & AUTO CARE
Year: 2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015550568

Address: 551 10TH AVE

AI231
East
1/8-1/4
0.156 mi.
823 ft.

CON EDISON
344 W 44 ST
NEW YORK, NY 10036
Site 6 of 8 in cluster AI

NY MANIFEST S112210731
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269213
Country: USA

Actual:
38 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269213
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457100JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210731

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269213
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457100JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AI232
East
1/8-1/4
0.156 mi.
823 ft.

CON EDISON MANHOLE: 8504
344 W 44TH
NEW YORK, NY 10036
Site 7 of 8 in cluster AI

RCRA-CESQG 1016144133
FINDS NYP004269213

Relative:
Higher

RCRA-CESQG:

Actual:
38 ft.

Date form received by agency: 09/18/2012
Facility name: CON EDISON MANHOLE: 8504
Facility address: 344 W 44TH
NEW YORK, NY 10036
EPA ID: NYP004269213
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 8504 (Continued)

1016144133

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461227

Environmental Interest/Information System

AM233 **445 W 45 DEVELOPMENT CORP**
North **445 W 45TH ST**
1/8-1/4 **NEW YORK, NY 10036**
0.157 mi.
829 ft. **Site 1 of 3 in cluster AM**

NY UST **U001836276**
NY AST **N/A**
NY HIST AST

Relative:
Higher

UST:
Id/Status: 2-482986 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 11/16/1995
UTM X: 585074.14410999999
UTM Y: 4512718.3257400002
Site Type: Unknown

Actual:
32 ft.

Affiliation Records:
Site Id: 21662
Affiliation Type: Facility Owner
Company Name: ARTHUR GOODMAN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001836276

Contact Type: Not reported
Contact Name: Not reported
Address1: 445 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21662
Affiliation Type: Mail Contact
Company Name: ARTHUR GOODMAN
Contact Type: Not reported
Contact Name: Not reported
Address1: 350 5TH AVENUE
Address2: SUITE 3304
City: NEW YORK
State: NY
Zip Code: 10118
Country Code: 001
Phone: (212) 736-8072
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21662
Affiliation Type: On-Site Operator
Company Name: 445 W 45 DEVELOPMENT CORP
Contact Type: Not reported
Contact Name: ARTHUR GOODMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 21662
Affiliation Type: Emergency Contact
Company Name: ARTHUR GOODMAN
Contact Type: Not reported
Contact Name: ARTHUR GOODMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001836276

Zip Code: Not reported
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 32302
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 11/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None

AST:

Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-240273
Program Type: PBS
UTM X: 585074.14410999999
UTM Y: 4512718.3257400002
Expiration Date: 08/17/1997
Site Type: Other

Affiliation Records:

Site Id: 9094
Affiliation Type: Facility Owner
Company Name: MR ARTHUR GOODMAN
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001836276

Contact Name: Not reported
Address1: 445 W 45TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 9094
Affiliation Type: Mail Contact
Company Name: MR ARTHUR GOODMAN
Contact Type: Not reported
Contact Name: Not reported
Address1: 445 W 45TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 9094
Affiliation Type: On-Site Operator
Company Name: 445 W 45 DEVELOPERS PARTNERSHP
Contact Type: Not reported
Contact Name: ARTHUR GOODMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 9094
Affiliation Type: Emergency Contact
Company Name: MR ARTHUR GOODMAN
Contact Type: Not reported
Contact Name: ARTHUR GOODMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001836276

Country Code: 001
Phone: (212) 245-3800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 17982
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1498
Tightness Test Method: 01
Date Test: 11/01/1990
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 09/28/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-240273
SWIS Code: 6201
Operator: ARTHUR GOODMAN
Facility Phone: (212) 245-3800
Facility Addr2: 445 W 45TH ST
Facility Type: OTHER
Emergency: ARTHUR GOODMAN
Emergency Tel: (212) 245-3800
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MR ARTHUR GOODMAN
Owner Address: 445 W 45TH ST
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 245-3800

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001836276

Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: MR ARTHUR GOODMAN
Mailing Address: 445 W 45TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 245-3800
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/19/1992
Expiration: 08/17/1997
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1498
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1498
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 4
Overfill Protection: 4
Dispenser Method: Gravity
Date Tested: 11/01/1990
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Petro-Tite
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AM234
North
1/8-1/4
0.157 mi.
829 ft.

445 W 45TH ST
NEW YORK, NY 10036

Site 2 of 3 in cluster AM

EDR US Hist Auto Stat

1015499862
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: A & K AUTO SERVICE INC
Year: 2001
Address: 445 W 45TH ST

Actual:
32 ft.

AM235
North
1/8-1/4
0.157 mi.
829 ft.

445 W 45 DEVELOPMENT CORP
445 W 45TH ST
NEW YORK, NY 10036

Site 3 of 3 in cluster AM

NY HIST UST

U001839416
N/A

Relative:
Higher

HIST UST:

PBS Number: 2-482986
SPDES Number: Not reported
Emergency Contact: ARTHUR GOODMAN
Emergency Telephone: (212) 245-3800
Operator: ARTHUR GOODMAN
Operator Telephone: (212) 245-3800
Owner Name: ARTHUR GOODMAN
Owner Address: 445 WEST 45TH STREET
Owner City,St,Zip: NEW YORK, NY 10036
Owner Telephone: (212) 245-3800
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: ARTHUR GOODMAN
Mailing Address: 350 5TH AVENUE
Mailing Address 2: SUITE 3304
Mailing City,St,Zip: NEW YORK, NY 10118
Mailing Contact: Not reported
Mailing Telephone: (212) 736-8072
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)
and Subpart 360-14.
Facility Addr2: 445 W 45TH ST
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 11/16/1990
Expiration Date: 11/16/1995
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

445 W 45 DEVELOPMENT CORP (Continued)

U001839416

County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 11/01/1994
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AG236
NE
1/8-1/4
0.157 mi.
829 ft.
648 NINTH AVE
648 NINTH AVENUE
NEW YORK, NY 10036
Site 12 of 12 in cluster AG

NY AST
NY HIST AST
U003385309
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-112690
Program Type: PBS
UTM X: 585202.30547999998
UTM Y: 4512680.6092299996
Expiration Date: 06/05/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 3583
Affiliation Type: Facility Owner
Company Name: T J MANAGEMENT CORP
Contact Type: REGISTERED AGENT
Contact Name: ERIC GULLY
Address1: 939 ONDERDONK AVENUE
Address2: Not reported
City: RIDGEWOOD
State: NY
Zip Code: 11385

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

648 NINTH AVE (Continued)

U003385309

Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 6/28/2007

Site Id: 3583
Affiliation Type: Mail Contact
Company Name: T J MANAGEMENT CORP
Contact Type: REGISTERED AGENT
Contact Name: ERIC GULLY
Address1: 939 ONDERDONK AVENUE
Address2: Not reported
City: RIDGEWOOD
State: NY
Zip Code: 11385
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 6/28/2007

Site Id: 3583
Affiliation Type: On-Site Operator
Company Name: 648 NINTH AVE
Contact Type: Not reported
Contact Name: ERIC GULLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 3583
Affiliation Type: Emergency Contact
Company Name: T J MANAGEMENT CORP
Contact Type: Not reported
Contact Name: ERIC GULLY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 456-5233
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

648 NINTH AVE (Continued)

U003385309

Tank Info:

Tank Number: 001
Tank Id: 5537
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/18/1980
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUR
Last Modified: 07/03/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-112690
SWIS Code: 6201
Operator: MULLEN & WOODS INC
Facility Phone: (212) 265-5790
Facility Addr2: 648 9TH AVENUE
Facility Type: APARTMENT BUILDING
Emergency: ROY UHL C/O MULLEN & WOODS
Emergency Tel: (212) 265-5790
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: T J MANAGEMENT CORP
Owner Address: 59-54 WOODBINE STREET
Owner City,St,Zip: NEW YORK, NY 11385
Federal ID: Not reported
Owner Tel: (718) 456-5233
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: JOHN GULLY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

648 NINTH AVE (Continued)

U003385309

Mailing Name: T J MANAGEMENT CORP
Mailing Address: 59-54 WOODBINE STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: RIDGEWOOD, NY 11385
Mailing Telephone: (718) 366-6059
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 07/07/1997
Expiration: 06/05/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AL237
West
1/8-1/4
0.157 mi.
831 ft.

CON EDISON SERVICE BOX: 43253
544 10TH AVE
NEW YORK, NY 10036
Site 3 of 9 in cluster AL

RCRA-CESQG
FINDS

1016144044
NYP004268314

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 43253

Facility address: 544 10TH AVE
NEW YORK, NY 10036

EPA ID: NYP004268314

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428167

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43253 (Continued)

1016144044

Environmental Interest/Information System

AL238
West
1/8-1/4
0.158 mi.
832 ft.

CON EDISON
548 10TH AVE
NEW YORK, NY 10036

Site 4 of 9 in cluster AL

NY MANIFEST **S112210644**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268306
Country: USA

Actual:
24 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268306
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457012JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210644

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268306
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457012JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AN239 330 WEST 43RD STREET
ESE 330 WEST 43RD STREET
1/8-1/4 MANHATTAN, NY
0.158 mi.
832 ft. Site 1 of 2 in cluster AN

NY LTANKS S102660676
N/A

Relative:
Higher

LTANKS:

Actual:
39 ft.

Site ID: 107700
Spill Number/Closed Date: 9512825 / 1/16/1996
Spill Date: 1/15/1996
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1/15/1996
CID: 282
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

330 WEST 43RD STREET (Continued)

S102660676

Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/15/1996
Spill Record Last Update: 1/27/1998
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller County: 999
Spiller Contact: N/A
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 94700
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"20-30 GALLONS SPILLED TANK REPAIR. SPEEDI DRY AND OIL REMOVED
BY OIL CO.

Remarks: TANK HAS FAILED IN THE APARTMENT COMPLEX.UNKNOWN THE NAME OF THE
APARTMENT COMPLEX OR THE OWNER.FIRE DEPT IS STILL ON THE
SCENE.QUANTITY OF THE TANK IS UNKNOWN ALSO OR HOW MUCH HAS LEAKED OUT

Material:
Site ID: 107700
Operable Unit ID: 1023913
Operable Unit: 01
Material ID: 356566
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: 20
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AK240
NNW
1/8-1/4
0.158 mi.
834 ft.

**614 10TH AVE
NEW YORK, NY 10036**

Site 3 of 5 in cluster AK

**EDR US Hist Auto Stat 1015576749
N/A**

**Relative:
Lower**

EDR Historical Auto Stations:
Name: 10 AVENUE TOWING & REPAIR
Year: 2003
Address: 614 10TH AVE

**Actual:
29 ft.**

Name: 10TH AVENUE TOWING & REPAIR
Year: 2010
Address: 614 10TH AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AK241
NNW
1/8-1/4
0.158 mi.
834 ft.

SERVICE STATION
624 10TH AVE
MANHATTAN, NY

NY LTANKS

S103037879
N/A

Site 4 of 5 in cluster AK

Relative:
Lower

LTANKS:

Actual:
29 ft.

Site ID: 118089
Spill Number/Closed Date: 9713164 / 12/22/1998
Spill Date: 2/25/1998
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 2/25/1998
CID: 257
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 2/25/1998
Spill Record Last Update: 2/25/1999
Spiller Name: JP YOUNG
Spiller Company: JP YOUNG
Spiller Address: 408 8TH AVE SUITE 206
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: FLORA GANDELMAN
Spiller Phone: (212) 582-5790
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 102645
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MULQUEEN"CONTAMINATED SOILS EXCAVATED DOWN TO BEDROCK SURFACE.
BEDROCK INSPECTED BY MULQUEEN. BEDROCK SURFACE HAD CHANNELS CUT IN IT
AND GROUNDWATER WAS DIRECTED TO SEWER SYSTEM. NO FURTHER ACTIONS
REQUIRED.
Remarks: pulling tanks vapor complaints from neighbors

Material:

Site ID: 118089
Operable Unit ID: 1059246
Operable Unit: 01
Material ID: 324191
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SERVICE STATION (Continued)

S103037879

Oxygenate: False

Tank Test:

AL242
West
1/8-1/4
0.158 mi.
836 ft.

CON EDISON
547 10TH AVE
NEW YORK, NY 10036
Site 5 of 9 in cluster AL

NY MANIFEST **S112210639**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268256
Country: USA

Actual:
24 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268256
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457010JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210639

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268256
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457010JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AJ243
SE
1/8-1/4
0.159 mi.
837 ft.

HOLY CROSS CHURCH
331 WEST 42ND STREET
NEW YORK, NY 10036

RCRA-LQG 1012186630
NYR000164921

Site 5 of 10 in cluster AJ

Relative:
Higher

RCRA-LQG:

Date form received by agency: 05/13/2010

Facility name: HOLY CROSS CHURCH

Facility address: 331 WEST 42ND STREET

NEW YORK, NY 10036

EPA ID: NYR000164921

Mailing address: WEST 42ND STREET

NEW YORK, NY 10036

Contact: PETER COLAPIETRO

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (212) 246-4732

Contact email: HOLYCROSSNYC@AOL.COM

EPA Region: 02

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any

Actual:
40 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLY CROSS CHURCH (Continued)

1012186630

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: FATHER PETER COLAPIETRO
Owner/operator address: WEST 42ND STREET
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1995
Owner/Op end date: Not reported

Owner/operator name: HOLY CROSS CHURCH
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: 06/05/1854
Owner/Op end date: Not reported

Owner/operator name: FATHER PETER COLAPIETRO
Owner/operator address: WEST 42ND STREET
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1995
Owner/Op end date: Not reported

Owner/operator name: ARCHDIOCESE OF NEW YORK
Owner/operator address: FIRST AVE 16TH FLOOR
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: 06/05/1854
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLY CROSS CHURCH (Continued)

1012186630

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 05/12/2009
Site name: HOLY CROSS CHURCH
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D004
Waste name: ARSENIC

Waste code: D005
Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D010
Waste name: SELENIUM

Waste code: D011
Waste name: SILVER

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D008
Waste name: LEAD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HOLY CROSS CHURCH (Continued)

1012186630

Violation Status: No violations found

**AJ244
SE
1/8-1/4
0.159 mi.
837 ft.**

**CONSOLIDATED EDISON
329 W 42 ST MH56654
NEW YORK, NY 10027**

**NY MANIFEST 1009241742
N/A**

Site 6 of 10 in cluster AJ

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004102596
Country: USA

**Actual:
40 ft.**

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE1296198
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/13/2002
Trans1 Recv Date: 09/13/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/16/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004102596
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 17741AV
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00226
Units: K - Kilograms (2.2 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2002

Document ID: NYE0460305
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/13/2002
Trans1 Recv Date: 09/13/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/13/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004102596
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: 80416AB

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009241742

Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 02255
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

AI245
East
1/8-1/4
0.159 mi.
838 ft.

CON EDISON
342 W 44 ST
NEW YORK, NY 10036
Site 8 of 8 in cluster AI

NY MANIFEST **S112210725**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269155
Country: USA

Actual:
38 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269155
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457099JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210725

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269155
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457099JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AL246
West
1/8-1/4
0.161 mi.
848 ft.

FAST TOWING & AUTO REPAIR
547 10TH ST
NEW YORK, NY 10018
Site 6 of 9 in cluster AL

RCRA NonGen / NLR 1001028742
NY MANIFEST NYR000009746

Relative:
Lower

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: FAST TOWING & AUTO REPAIR
Facility address: 547 10TH ST
NEW YORK, NY 100181119
EPA ID: NYR000009746
Mailing address: FIFTH AVE
NEW YORK, NY 10019
Contact: Not reported
Contact address: FIFTH AVE
NEW YORK, NY 10019

Actual:
24 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FAST TOWING & AUTO REPAIR (Continued)

1001028742

Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: SOLIL MANAGEMENT
Owner/operator address: 640 FIFTH AVE
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 265-2280
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SOLIL MANAGEMENT
Owner/operator address: 640 FIFTH AVE
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 265-2280
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: FAST TOWING & AUTO REPAIR
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: FAST TOWING & AUTO REPAIR
Classification: Not a generator, verified

Date form received by agency: 07/27/1995
Site name: FAST TOWING & AUTO REPAIR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FAST TOWING & AUTO REPAIR (Continued)

1001028742

Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYR000009746

Country: USA

Mailing Info:

Name: SOLIL MGMT

Contact: JED MYERS

Address: 640 5TH AVE

City/State/Zip: NEW YORK, NY 10019

Country: USA

Phone: 212-265-2280

Document ID: NYB4126383

Manifest Status: Completed copy

Trans1 State ID: Not reported

Trans2 State ID: Not reported

Generator Ship Date: 950811

Trans1 Recv Date: 950811

Trans2 Recv Date: Not reported

TSD Site Recv Date: 950811

Part A Recv Date: 950927

Part B Recv Date: 950822

Generator EPA ID: NYR000009746

Trans1 EPA ID: NYD986910222

Trans2 EPA ID: Not reported

TSDF ID: NYD082785429

Waste Code: D001 - NON-LISTED IGNITABLE WASTES

Quantity: 00165

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 003

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 100

Year: 95

AL247
West
1/8-1/4
0.161 mi.
848 ft.

CON EDISON SERVICE BOX: 43249
547 10TH AVE
NEW YORK, NY 10036
Site 7 of 9 in cluster AL

RCRA-CESQG
FINDS

1016144038
NYP004268256

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 43249

Facility address: 547 10TH AVE

NEW YORK, NY 10036

EPA ID: NYP004268256

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Actual:
24 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43249 (Continued)

1016144038

Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110004516275

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AL248
West
1/8-1/4
0.161 mi.
848 ft.

547 10TH AVE
NEW YORK, NY 10018

Site 8 of 9 in cluster AL

EDR US Hist Auto Stat

1015548653
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: N Y C AUTO REPAIR
Year: 1999
Address: 547 10TH AVE

Actual:
24 ft.

Name: N Y C AUTO REPAIR
Year: 2000
Address: 547 10TH AVE

Name: AUTO REPAIR & TOWING
Year: 2001
Address: 547 10TH AVE

Name: AUTO REPAIR & TOWING
Year: 2002
Address: 547 10TH AVE

Name: CALL TRANSMISSION REPAIR HR
Year: 2003
Address: 547 10TH AVE

Name: CALL TRANSMISSION REPAIR HR
Year: 2004
Address: 547 10TH AVE

Name: CALL TRANSMISSION REPAIR 24 HR
Year: 2010
Address: 547 10TH AVE

Name: MEINEKI TOWING TRANSMISSION
Year: 2011
Address: 547 10TH AVE

Name: MEINEKI TOWING TRANSMISSION
Year: 2012
Address: 547 10TH AVE

AJ249
SE
1/8-1/4
0.162 mi.
855 ft.

CON EDISON
327 W 42ND ST
NEW YORK, NY 10036

Site 7 of 10 in cluster AJ

NY MANIFEST

S112210638
N/A

Relative:
Higher

NY MANIFEST:

EPA ID: NYP004268249
Country: USA

Actual:
40 ft.

Mailing Info:

Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210638

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268249
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456577JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268249
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210638

Year: 2012
Manifest Tracking Num: 010456577JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AJ250
SE
1/8-1/4
0.162 mi.
855 ft.

CON EDISON SERVICE BOX: 8122
327 W 42ND ST
NEW YORK, NY 10036

RCRA-CESQG 1016144037
FINDS NYP004268249

Site 8 of 10 in cluster AJ

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON SERVICE BOX: 8122

Facility address: 327 W 42ND ST
NEW YORK, NY 10036

EPA ID: NYP004268249

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8122 (Continued)

1016144037

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458865

Environmental Interest/Information System

**AK251
NNW
1/8-1/4
0.163 mi.
860 ft.**

**615 10TH AVE
NEW YORK, NY 10036**

Site 5 of 5 in cluster AK

**EDR US Hist Auto Stat 1015577165
N/A**

**Relative:
Lower**

EDR Historical Auto Stations:

Name: DANICIS I CONSTA CO
Year: 2010
Address: 615 10TH AVE

**Actual:
27 ft.**

Name: DANICIS I CONSTA CO
Year: 2011
Address: 615 10TH AVE

Name: DANICIS I CONSTA COMPANY
Year: 2012
Address: 615 10TH AVE

**AO252
SSW
1/8-1/4
0.164 mi.
864 ft.**

**525 9TH AVE
NEW YORK, NY 10018**

Site 1 of 16 in cluster AO

**EDR US Hist Cleaners 1015072016
N/A**

**Relative:
Higher**

EDR Historical Cleaners:

Name: BKM LAUNDROMAT CORP
Year: 2002
Address: 525 9TH AVE

**Actual:
32 ft.**

Name: BKM LAUNDROMAT CORP
Year: 2003
Address: 525 9TH AVE

Name: D & P LAUNDROMAT INC
Year: 2005
Address: 525 9TH AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AL253
West
1/8-1/4
0.165 mi.
870 ft.
CON EDISON
544 10TH AVE
NEW YORK, NY 10036
Site 9 of 9 in cluster AL

NY MANIFEST **S112210645**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268314
Country: USA

Actual:
24 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268314
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457011JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210645

Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268314
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457011JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AP254 **339 W. 44 REALTY LLC**
East **339 W. 44TH STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.165 mi.
873 ft. **Site 1 of 4 in cluster AP**

NY AST **U004079630**
N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606042
Program Type: PBS
UTM X: 585258.45845000003
UTM Y: 4512500.2327899998
Expiration Date: 11/16/2014
Site Type: Apartment Building/Office Building

Actual:
38 ft.

Affiliation Records:
Site Id: 27907
Affiliation Type: Mail Contact
Company Name: C/O S. W. MGT LLC
Contact Type: Not reported
Contact Name: 339 W. 44 REALTY LLC
Address1: 145 HUGUENOT STREET
Address2: SUITE 503
City: NEW ROCHELLE
State: NY
Zip Code: 10801

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

339 W. 44 REALTY LLC (Continued)

U004079630

Country Code: 001
Phone: (914) 637-6200
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/16/2009

Site Id: 27907
Affiliation Type: On-Site Operator
Company Name: 339 W. 44 REALTY LLC
Contact Type: Not reported
Contact Name: ANGEL SANTIAGO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 879-8453
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/16/2009

Site Id: 27907
Affiliation Type: Emergency Contact
Company Name: 339 W. 44 REALTY LLC
Contact Type: Not reported
Contact Name: ROCKWAY FUEL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 585-8300
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/16/2009

Site Id: 27907
Affiliation Type: Facility Owner
Company Name: 339 W. 44 REALTY LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 339 W. 44TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (914) 637-6200
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/16/2009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

339 W. 44 REALTY LLC (Continued)

U004079630

Tank Info:

Tank Number: 001
Tank Id: 60878
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G05 - Tank Secondary Containment - Synthetic Liner
F06 - Pipe External Protection - Wrapped
I05 - Overfill - Vent Whistle
J00 - Dispenser - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/2000
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 11/16/2009
Material Name: #2 Fuel Oil (On-Site Consumption)

AJ255
SE
1/8-1/4
0.165 mi.
873 ft.

**CON EDISON SERVICE BOX: 8128
324 W 42ND ST
NEW YORK, NY 10036**

**RCRA-CESQG 1016144046
FINDS NYP004268330**

Site 9 of 10 in cluster AJ

**Relative:
Higher**

RCRA-CESQG:

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 8128
Facility address: 324 W 42ND ST
NEW YORK, NY 10036
EPA ID: NYP004268330
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator

**Actual:
40 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8128 (Continued)

1016144046

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458918

Environmental Interest/Information System

AJ256
SE
1/8-1/4
0.165 mi.
873 ft.

CON EDISON
324 W 42ND ST
NEW YORK, NY 10036
Site 10 of 10 in cluster AJ

NY MANIFEST S112210647
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004268330
Country: USA

Actual:
40 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210647

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268330
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456580JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268330
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210647

Year: 2012
Manifest Tracking Num: 010456580JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AQ257 650 NINTH AVENUE
NE 650 NINTH AVENUE
1/8-1/4 NEW YORK, NY 10036
0.168 mi.
888 ft.

NY AST U003397157
NY HIST AST N/A

Site 1 of 7 in cluster AQ

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603422
Program Type: PBS
UTM X: 585205.61802000005
UTM Y: 4512686.1983599998
Expiration Date: 06/28/2018
Site Type: Apartment Building/Office Building

Actual:
39 ft.

Affiliation Records:

Site Id: 25339
Affiliation Type: Mail Contact
Company Name: SR GROUP
Contact Type: Not reported
Contact Name: SUDHAKAR RAYAPUDI
Address1: PO BOX 6356
Address2: Not reported
City: HILLBOROUGH
State: NJ
Zip Code: 08844
Country Code: 001
Phone: (732) 301-2833
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/10/2013

Site Id: 25339
Affiliation Type: On-Site Operator
Company Name: 650-50 NINTH AVENUE
Contact Type: Not reported
Contact Name: FRANK ARMENDI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

650 NINTH AVENUE (Continued)

U003397157

Zip Code: Not reported
Country Code: 001
Phone: (212) 926-9661
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25339
Affiliation Type: Emergency Contact
Company Name: SUDHAKAR RAYAPUDI
Contact Type: Not reported
Contact Name: SUDHAKAR RAYAPUDI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (973) 886-1071
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/10/2013

Site Id: 25339
Affiliation Type: Facility Owner
Company Name: SUDHAKAR RAYAPUDI
Contact Type: OWNER
Contact Name: SUDHAKAR RAYAPUDI
Address1: 767 9TH AVE, BASEMENT UNIT
Address2: Not reported
City: NY
State: NY
Zip Code: 10019
Country Code: 001
Phone: (973) 886-1071
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/10/2013

Tank Info:

Tank Number: 001
Tank Id: 54221
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

650 NINTH AVENUE (Continued)

U003397157

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/15/1998
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 10/10/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-603422
SWIS Code: 6201
Operator: FRANK ARMENDI
Facility Phone: (212) 579-0318
Facility Addr2: Not reported
Facility Type: Not reported
Emergency: FRNK ARMENDI
Emergency Tel: (212) 581-5331
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: RONALD DEMILT
Owner Address: 150 WEST 84TH STREET
Owner City,St,Zip: NEW YORK, NY 10024
Federal ID: Not reported
Owner Tel: (212) 579-0318
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: RONALD DEMILT
Mailing Address: 150 WEST 84TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10024
Mailing Telephone: (212) 579-0318
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 04/21/1998
Expiration: 04/14/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: Minor Data Missing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

650 NINTH AVENUE (Continued)

U003397157

Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 01
Tank Containment: None
Leak Detection: 00
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

**AQ258
NE
1/8-1/4
0.168 mi.
888 ft.**

**652 9TH AVE
NEW YORK, NY 10036**

Site 2 of 7 in cluster AQ

**Relative:
Higher**

EDR Historical Cleaners:

Name: WASHLAND
Year: 2001
Address: 652 9TH AVE

**Actual:
39 ft.**

Name: WASHLAND
Year: 2002
Address: 652 9TH AVE

Name: WASHLAND
Year: 2003
Address: 652 9TH AVE

Name: WASHLAND
Year: 2004
Address: 652 9TH AVE

**EDR US Hist Cleaners 1015084985
N/A**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015084985

Name: WASHLAND
Year: 2005
Address: 652 9TH AVE

Name: WASHLAND
Year: 2006
Address: 652 9TH AVE

Name: WASHLAND
Year: 2007
Address: 652 9TH AVE

AO259
SSW
1/8-1/4
0.169 mi.
890 ft.

408 WEST 39TH ST
408 WEST 39TH ST
MANHATTAN, NY

NY LTANKS

S102662822
N/A

Site 2 of 16 in cluster AO

Relative:
Lower

LTANKS:

Actual:
31 ft.

Site ID: 183559
Spill Number/Closed Date: 9612460 / 2/13/1997
Spill Date: 1/18/1997
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1/18/1997
CID: 369
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/18/1997
Spill Record Last Update: 2/13/1997
Spiller Name: CHARLIE BOETTIGER
Spiller Company: Not reported
Spiller Address: 408 WEST 39TH ST
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller County: 001
Spiller Contact: CHARLIE BOETTIGER
Spiller Phone: (718) 932-9075
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 153687
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MULQUEEN"
Remarks: CLEANUP IN PROGRESS

Material:

Site ID: 183559

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408 WEST 39TH ST (Continued)

S102662822

Operable Unit ID: 1043976
Operable Unit: 01
Material ID: 341103
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AO260
SSW
1/8-1/4
0.169 mi.
891 ft.

CON EDISON SERVICE BOX: 7392
405 W 39TH ST
NEW YORK, NY 10018

RCRA-CESQG
FINDS

1016143755
NYP004265385

Site 3 of 16 in cluster AO

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 08/28/2012

Facility name: CON EDISON SERVICE BOX: 7392

Facility address: 405 W 39TH ST
NEW YORK, NY 10018

EPA ID: NYP004265385
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported

Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931

Contact email: Not reported
EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7392 (Continued)

1016143755

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055424955

Environmental Interest/Information System

**AR261
NNW
1/8-1/4
0.169 mi.
892 ft.**

**PHIL'S WEST 44TH ST SERV/STA
614/626 TENTH AVENUE
NEW YORK, NY 10036**

**NY UST U001840299
N/A**

Site 1 of 9 in cluster AR

**Relative:
Lower**

UST:

Id/Status: 2-456713 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/02/2003
UTM X: 584857.92790000001
UTM Y: 4512702.9805399999
Site Type: Retail Gasoline Sales

**Actual:
29 ft.**

Affiliation Records:

Site Id: 20148
Affiliation Type: Facility Owner
Company Name: 626 ENMUT PROPERTIES LTD.
Contact Type: Not reported
Contact Name: Not reported
Address1: 408 EIGHTH AVENUE, SUITE 206
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 707-8993
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20148
Affiliation Type: Mail Contact
Company Name: 626 ENMUT PROPERTIES LTD.
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PHIL'S WEST 44TH ST SERV/STA (Continued)

U001840299

Contact Name: Not reported
Address1: 408 EIGHT AVENUE, SUITE 206
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 707-8993
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20148
Affiliation Type: On-Site Operator
Company Name: PHILS WEST 44TH ST SERV/STA
Contact Type: Not reported
Contact Name: JOHN P. YOUNG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 707-8993
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20148
Affiliation Type: Emergency Contact
Company Name: 626 ENMUT PROPERTIES LTD.
Contact Type: Not reported
Contact Name: JOHN P. YOUNG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 707-8993
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 36702
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PHIL'S WEST 44TH ST SERV/STA (Continued)

U001840299

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 06/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 36703
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 06/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 36704

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PHIL'S WEST 44TH ST SERV/STA (Continued)

U001840299

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 06/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 004
Tank ID: 36705
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 06/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PHIL'S WEST 44TH ST SERV/STA (Continued)

U001840299

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 005
Tank ID: 36706
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 06/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 006
Tank ID: 53962
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 02/01/1998
Date Tank Closed: 02/01/1998
Registered: True
Tank Location: Underground
Tank Type: Z
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PHIL'S WEST 44TH ST SERV/STA (Continued)

U001840299

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

AR262
NNW
1/8-1/4
0.169 mi.
892 ft.

CONSOLIDATED EDISON
626 10TH AVE 44TH & 45TH ST
NEW YORK, NY
Site 2 of 9 in cluster AR

NY MANIFEST S109155605
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004160453
Country: USA

Actual:
29 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PL RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-08-13
Trans1 Recv Date: 2008-08-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-08-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004160453
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 135.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001433538FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109155605

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-08-13
Trans1 Recv Date: 2008-08-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-08-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004160453
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: Not reported
Quantity: 135.0
Units: K - Kilograms (2.2 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001433538FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

AR263
NNW
1/8-1/4
0.169 mi.
892 ft.

CON EDISON
626 10TH AVE
NEW YORK, NY 10036

Site 3 of 9 in cluster AR

RCRA-CESQG 1012185242
NYP004160453

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 08/12/2008
Facility name: CON EDISON
Facility address: 626 10TH AVE
NEW YORK, NY 10036
EPA ID: NYP004160453
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: HERMAN BAKER
Contact address: Not reported
Not reported

Actual:
29 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185242

Contact country: Not reported
Contact telephone: (718) 267-3853
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AP264
East
1/8-1/4
0.170 mi.
895 ft.

CON EDISON
337 W 44
NEW YORK, NY 10036
Site 2 of 4 in cluster AP

NY MANIFEST **S112210722**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269122
Country: USA

Actual:
39 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210722

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269122
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457098JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269122
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210722

Manifest Tracking Num: 010457098JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AO265
SSW
1/8-1/4
0.170 mi.
896 ft.

524 9TH AVE
NEW YORK, NY 10018

EDR US Hist Cleaners 1015071932
N/A

Site 4 of 16 in cluster AO

Relative:
Higher

EDR Historical Cleaners:
Name: YEES EXCELLENT CLEANERS
Year: 2006

Actual:
32 ft.

Address: 524 9TH AVE

AO266
SSW
1/8-1/4
0.170 mi.
896 ft.

408 W 39 ST
408 WEST 39TH STREET
NEW YORK, NY 10018

NY AST U004045524
N/A

Site 5 of 16 in cluster AO

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-347264
Program Type: PBS
UTM X: 584919.20053000003
UTM Y: 4512235.0527799996
Expiration Date: 04/19/2003
Site Type: Apartment Building/Office Building

Actual:
31 ft.

Affiliation Records:
Site Id: 17010
Affiliation Type: Facility Owner
Company Name: 408 WEST 39 LP
Contact Type: Not reported
Contact Name: Not reported
Address1: PO BOX 2600
Address2: Not reported
City: BALA CYNWYD
State: PA
Zip Code: 19004
Country Code: 001
Phone: (610) 260-8325
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408 W 39 ST (Continued)

U004045524

Date Last Modified: 3/4/2004

Site Id: 17010
Affiliation Type: Mail Contact
Company Name: 408 WEST 39 LP
Contact Type: Not reported
Contact Name: Not reported
Address1: PO BOX 2600
Address2: Not reported
City: BALA CYNWYD
State: PA
Zip Code: 19004
Country Code: 001
Phone: (610) 260-8325
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 17010
Affiliation Type: On-Site Operator
Company Name: 408 W 39 ST
Contact Type: Not reported
Contact Name: ISAAC TAPIERO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 388-9914
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 17010
Affiliation Type: Emergency Contact
Company Name: 408 WEST 39 LP
Contact Type: Not reported
Contact Name: ISAAC TAPIERO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 388-9914
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 33075

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

408 W 39 ST (Continued)

U004045524

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/2002
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AO267
SSW
1/8-1/4
0.170 mi.
898 ft.

**406 WEST 39TH STREET
406 WEST 39TH STREET
NEW YORK, NY 10018**

Site 6 of 16 in cluster AO

**NY AST U003383805
NY HIST AST N/A**

**Relative:
Lower**

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-063207
Program Type: PBS
UTM X: 584924.89064999996
UTM Y: 4512232.1204899997
Expiration Date: 01/14/2017
Site Type: Apartment Building/Office Building

**Actual:
31 ft.**

Affiliation Records:

Site Id: 1239
Affiliation Type: Facility Owner
Company Name: GIOVANNI QUARTUCCIA
Contact Type: OWNER
Contact Name: GIOVANNI QUARTUCCIA
Address1: 406 WEST 39TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 594-8587

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 39TH STREET (Continued)

U003383805

EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 11/22/2006

Site Id: 1239
Affiliation Type: Mail Contact
Company Name: GIOVANNI QUARTUCCIA
Contact Type: Not reported
Contact Name: Not reported
Address1: 406 WEST 39TH STREET
Address2: APT 2R
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 594-8587
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1239
Affiliation Type: On-Site Operator
Company Name: 406 WEST 39TH STREET
Contact Type: Not reported
Contact Name: GIOVANNI QUARTUCCIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 594-8587
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1239
Affiliation Type: Emergency Contact
Company Name: GIOVANNI QUARTUCCIA
Contact Type: Not reported
Contact Name: ANGELO QUARTUCCIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 562-5101
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 39TH STREET (Continued)

U003383805

Tank Info:

Tank Number: 001
Tank Id: 2285
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B99 - Tank External Protection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1900
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DXLIVING
Last Modified: 11/22/2006
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-063207
SWIS Code: 6201
Operator: GIOVANNI QUARTUCCIA
Facility Phone: (212) 594-8587
Facility Addr2: 406 WEST 39TH STREET
Facility Type: APARTMENT BUILDING
Emergency: ANGELO QUARTUCCIA
Emergency Tel: (212) 562-5101
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: GIOVANNI QUARTUCCIA
Owner Address: 406 WEST 39TH STREET
Owner City,St,Zip: NEW YORK, NY 10018
Federal ID: Not reported
Owner Tel: (212) 594-8587
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: GIOVANNI QUARTUCCIA
Mailing Address: 406 WEST 39TH STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 39TH STREET (Continued)

U003383805

Mailing Address 2: APT 2R
Mailing City,St,Zip: NEW YORK, NY 10018
Mailing Telephone: (212) 594-8587
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 11/05/2001
Expiration: 01/14/2007
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 9
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: Epoxy Liner
Pipe External: 0
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AN268
ESE
1/8-1/4
0.170 mi.
898 ft.

CON EDISON
F/O 323 WEST 43RD ST.
NEW YORK, NY 10036

Site 2 of 2 in cluster AN

NY MANIFEST S112209906
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004260543
Country: USA

Actual:
40 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-30
Trans1 Recv Date: 2012-07-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004260543
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010464041JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-07-30

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112209906

Trans1 Recv Date: 2012-07-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-02
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004260543
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010464041JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AO269
SSW
1/8-1/4
0.170 mi.
900 ft.

**CON EDISON SERVICE BOX 39834
W 39TH ST & 9TH AVE NW COR
NEW YORK, NY 10018**

**RCRA NonGen / NLR 1014926348
NYP004241030**

Site 7 of 16 in cluster AO

**Relative:
Higher**

RCRA NonGen / NLR:

**Actual:
32 ft.**

Date form received by agency: 09/29/2011
Facility name: CON EDISON SERVICE BOX 39834
Facility address: W 39TH ST & 9TH AVE NW COR
NEW YORK, NY 10018
EPA ID: NYP004241030
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX 39834 (Continued)

1014926348

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 08/30/2011
Site name: CON EDISON SERVICE BOX 39834
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

AO270
SSW
1/8-1/4
0.171 mi.
901 ft.

CON EDISON
W 39TH ST & 9TH AVE
NEW YORK, NY 10019

Site 8 of 16 in cluster AO

RCRA-CESQG 1012185836
NYP004166716

Relative:
Higher

RCRA-CESQG:

Actual:
32 ft.

Date form received by agency: 04/11/2009
Facility name: CON EDISON
Facility address: W 39TH ST & 9TH AVE
NEW YORK, NY 10019
EPA ID: NYP004166716
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS MICHAELIDES
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (718) 204-4297
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185836

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AO271
SSW
1/8-1/4
0.171 mi.
901 ft.

**PORT AUTH OF NY & NJ 9TH AVE & 38-39
9TH AVE BETW 38TH & 39TH ST
NEW YORK, NY 10018**

**RCRA NonGen / NLR 1000390994
NY MANIFEST NYD981483324**

Site 9 of 16 in cluster AO

**Relative:
Higher**

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: PORT AUTH OF NY & NJ 9TH AVE & 38-39
Facility address: 9TH AVE BETW 38TH & 39TH ST
NEW YORK, NY 10018
EPA ID: NYD981483324
Mailing address: BLVD EAST
WEEHAWKEN, NY 07087
Contact: HCONFIRST CALO
Contact address: BLVD EAST
WEEHAWKEN, NY 07087
Contact country: US
Contact telephone: (201) 348-3573
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

**Actual:
32 ft.**

Owner/Operator Summary:

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: District
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38-39 (Continued)

1000390994

Owner/operator telephone: (212) 555-1212
Legal status: District
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: PORT AUTH OF NY & NJ 9TH AVE & 38-39
Classification: Not a generator, verified

Date form received by agency: 04/25/1986
Site name: PORT AUTH OF NY & NJ 9TH AVE & 38-39
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD981483324
Country: USA

Mailing Info:

Name: PORT AUTHORITY OF NEW YORK & NEW JERSEY
Contact: PORT AUTHORITY OF NEW YORK & NEW JERSEY
Address: 500 BLVD EAST
City/State/Zip: WEEHAWKEN, NJ 07087
Country: USA
Phone: 201-867-9095

Document ID: NYA3481514
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: H10PC708
Trans2 State ID: Not reported
Generator Ship Date: 860715
Trans1 Recv Date: 860715
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860716
Part A Recv Date: 860826
Part B Recv Date: 860801

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38-39 (Continued)

1000390994

Generator EPA ID: NYD981483324
Trans1 EPA ID: ARD069748192
Trans2 EPA ID: Not reported
TSDF ID: TND980729305
Waste Code: X727 - NJ ONLY UNKNOWN
Quantity: 00825
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 86

AO272
SSW
1/8-1/4
0.171 mi.
902 ft.

CONSOLIDATED EDISON
WEST 39 ST & 9TH AVE
NEW YORK, NY 10020
Site 10 of 16 in cluster AO

NY MANIFEST **S109584422**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004166716
Country: USA

Actual:
32 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: CONSOLIDATED EDISON
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 40.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584422

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584422

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 40.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584422

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 40.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584422

Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 40.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H135

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584422

Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-11
Trans1 Recv Date: 2009-04-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004166716
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001440599FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

AO273 BELL ATLANTIC-NY
SSW W 39TH ST/9 AVE
1/8-1/4 NEW YORK, NY 10018
0.171 mi.
902 ft. Site 11 of 16 in cluster AO

FINDS 1007252030
NY MANIFEST N/A

Relative:
Higher

FINDS:

Registry ID: 110017243721

Actual:
32 ft.

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYP000935932
Country: USA

Mailing Info:

Name: BELL ATLANTIC-NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BELL ATLANTIC-NY (Continued)

1007252030

Contact: Not reported
Address: Not reported
City/State/Zip: Not reported
Country: Not reported
Phone: Not reported

NY MANIFEST:

No Manifest Records Available

AO274
SSW
1/8-1/4
0.171 mi.
903 ft.

BELL ATLANTIC-NY
W 39TH ST/9 AVE
MANHATTAN, NY 00000

RCRA NonGen / NLR

1007205565
NYP000935932

Site 12 of 16 in cluster AO

Relative:
Higher

RCRA NonGen / NLR:

Actual:
32 ft.

Date form received by agency: 03/01/1998
Facility name: BELL ATLANTIC-NY
Facility address: W 39TH ST/9 AVE
MANHATTAN, NY 000000000
EPA ID: NYP000935932
Mailing address: BELL ATLANTIC ENV AFFAIRS
221 E 37TH ST 4TH FL
NEW YORK, NY 100160000
Contact: JOHN QUATRALE
Contact address: BELL ATLANTIC ENV AFFAIRS
NEW YORK, NY 100160000
Contact country: US
Contact telephone: (212) 338-7141
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/28/1998
Site name: BELL ATLANTIC-NY
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BELL ATLANTIC-NY (Continued)

1007205565

Date form received by agency: 02/27/1998
Site name: BELL ATLANTIC-NY
Classification: Large Quantity Generator

Violation Status: No violations found

**AO275
SSW
1/8-1/4
0.171 mi.
905 ft.**

**CON EDISON
400 W 39TH ST
NEW YORK, NY 10018

Site 13 of 16 in cluster AO**

**NY MANIFEST S112210362
N/A**

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004265336
Country: USA

**Actual:
32 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-18
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265336
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456244JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210362

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-18
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265336
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456244JJJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AO276
SSW
1/8-1/4
0.171 mi.
905 ft.

CON EDISON MANHOLE: 7401
400 W 39TH ST
NEW YORK, NY 10018
Site 14 of 16 in cluster AO

RCRA-CESQG 1016143750
FINDS NYP004265336

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 08/28/2012
Facility name: CON EDISON MANHOLE: 7401
Facility address: 400 W 39TH ST
NEW YORK, NY 10018

Actual:
32 ft.

EPA ID: NYP004265336
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 7401 (Continued)

1016143750

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468097

Environmental Interest/Information System

AS277
SE
1/8-1/4
0.172 mi.
907 ft.
THERA REALTY, LLC
321-325 WEST 42ND STREET
NEW YORK, NY 10036
Site 1 of 2 in cluster AS

NY AST A100296349
N/A

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610192
Program Type: PBS
UTM X: 585222.67154000001
UTM Y: 4512330.8453099998
Expiration Date: 11/02/2014
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 363130

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THERA REALTY, LLC (Continued)

A100296349

Affiliation Type: Facility Owner
Company Name: THERA REALTY, LLC
Contact Type: PROPERTY MANAGER
Contact Name: NICK CONWAY
Address1: 46 TRINITY PLACE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10006
Country Code: 001
Phone: (718) 267-0300
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2006

Site Id: 363130
Affiliation Type: Mail Contact
Company Name: THERA REALTY LLC
Contact Type: Not reported
Contact Name: ANGELO ZOUMAS
Address1: 31-10 37TH STREET
Address2: SUITE500
City: LIC
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 267-0300
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/29/2009

Site Id: 363130
Affiliation Type: On-Site Operator
Company Name: THERA REALTY, LLC
Contact Type: Not reported
Contact Name: ALBERTO MORALES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 749-6853
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2006

Site Id: 363130
Affiliation Type: Emergency Contact
Company Name: THERA REALTY, LLC
Contact Type: Not reported
Contact Name: ALBERTO MORALES
Address1: Not reported
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THERA REALTY, LLC (Continued)

A100296349

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 749-6853
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2006

Tank Info:

Tank Number: 001
Tank Id: 211386
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None

Tank Location: 3
Tank Type: Steel Tank in Concrete
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/26/1997
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 03/01/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

AT278
ENE
1/8-1/4
0.174 mi.
919 ft.

INVESTMENT DEV CO WEST NINTH CO BLDG
359 W 45TH ST
NEW YORK, NY 10031
Site 1 of 7 in cluster AT

RCRA NonGen / NLR 1001029197
NY0000302638

Relative:
Higher

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: INVESTMENT DEV CO WEST NINTH CO BLDG
Facility address: 359 W 45TH ST
NEW YORK, NY 10031

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INVESTMENT DEV CO WEST NINTH CO BLDG (Continued)

1001029197

EPA ID: NY0000302638
Mailing address: W 45TH ST
NEW YORK, NY 10031
Contact: Not reported
Contact address: W 45TH ST
NEW YORK, NY 10031
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: INVESTMENT DEVELOPMENT CO
Owner/operator address: 2121 BROADWAY
NEW YORK, NY 10038
Owner/operator country: US
Owner/operator telephone: (212) 875-9132
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: INVESTMENT DEVELOPMENT CO
Owner/operator address: 2121 BROADWAY
NEW YORK, NY 10038
Owner/operator country: US
Owner/operator telephone: (212) 875-9132
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: INVESTMENT DEV CO WEST NINTH CO BLDG
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

INVESTMENT DEV CO WEST NINTH CO BLDG (Continued)

1001029197

Date form received by agency: 07/08/1999
Site name: INVESTMENT DEV CO WEST NINTH CO BLDG
Classification: Not a generator, verified

Date form received by agency: 05/19/1994
Site name: INVESTMENT DEV CO WEST NINTH CO BLDG
Classification: Large Quantity Generator

Violation Status: No violations found

AT279
ENE
1/8-1/4
0.174 mi.
919 ft.

359 W 45TH ST
NEW YORK, NY 10036
Site 2 of 7 in cluster AT

EDR US Hist Cleaners 1015048936
N/A

Relative:
Higher

Actual:
39 ft.

EDR Historical Cleaners:
Name: 9TH CORNER CLEANERS
Year: 2001
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANER
Year: 2003
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANER
Year: 2004
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANERS
Year: 2005
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANERS
Year: 2006
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANERS
Year: 2008
Address: 359 W 45TH ST

Name: 9TH CORNER CLEANERS
Year: 2010
Address: 359 W 45TH ST

AT280
ENE
1/8-1/4
0.175 mi.
923 ft.

356 W 45 ST
356 WEST 45TH STREET
NEW YORK, NY 10036
Site 3 of 7 in cluster AT

NY AST U003384234
N/A

Relative:
Higher

Actual:
39 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-085782
Program Type: PBS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

356 W 45 ST (Continued)

U003384234

UTM X: 585283.61129000003
UTM Y: 4512591.8408399997
Expiration Date: 03/16/2014
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2080
Affiliation Type: Mail Contact
Company Name: DAJ LLC
Contact Type: Not reported
Contact Name: JOSEPH FRANCO
Address1: 101 WEST 69TH STREET
Address2: SUITE 1C
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 874-3401 102
EMail: JFRANCO@FRANCOMANAGEMENT.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/29/2014

Site Id: 2080
Affiliation Type: On-Site Operator
Company Name: 356 WEST 45 STREET
Contact Type: Not reported
Contact Name: DAJ LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 874-3401
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/3/2007

Site Id: 2080
Affiliation Type: Emergency Contact
Company Name: DAJ LLC
Contact Type: Not reported
Contact Name: JOSEPH FRANCO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 874-3401
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/3/2007

Site Id: 2080

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

356 W 45 ST (Continued)

U003384234

Affiliation Type: Facility Owner
Company Name: DAJ LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 101 WEST 69TH ST., 1C
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 874-3401
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/29/2014

Tank Info:

Tank Number: 001
Tank Id: 3349
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
E99 - Piping Secondary Containment - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1941
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/2014
Register: True
Modified By: NRLOMBAR
Last Modified: 01/29/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AS281
SE
1/8-1/4
0.175 mi.
924 ft.
319 WEST 42ND STREET
319 WEST 42ND STREET
NEW YORK, NY 10036
Site 2 of 2 in cluster AS

NY AST
NY HIST AST
U003384179
N/A

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-084638
Program Type: PBS
UTM X: 585261.80175999994
UTM Y: 4512337.5752999997
Expiration Date: 10/07/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 1975
Affiliation Type: Facility Owner
Company Name: JNK - 42 LLC % ABC REALTY
Contact Type: AGENT
Contact Name: WILLIAM D. HARRA
Address1: 152 WEST 57TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 307-0500
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 8/16/2007

Site Id: 1975
Affiliation Type: Mail Contact
Company Name: % ABC REALTY
Contact Type: Not reported
Contact Name: WILLIAM D. HARRA
Address1: 152 WEST 57TH STREET
Address2: 12TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 307-0500
EMail: BHARRA@ABCMGMT.NET
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 8/16/2007

Site Id: 1975
Affiliation Type: On-Site Operator
Company Name: 319 WEST 42ND STREET
Contact Type: Not reported
Contact Name: J. KORN
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

319 WEST 42ND STREET (Continued)

U003384179

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 757-5670
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1975
Affiliation Type: Emergency Contact
Company Name: JNK - 42 LLC % ABC REALTY
Contact Type: Not reported
Contact Name: WILLIAM HARRA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-0500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 3222
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/02/1984
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

319 WEST 42ND STREET (Continued)

U003384179

Register: True
Modified By: MSBAPTIS
Last Modified: 10/23/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-084638
SWIS Code: 6201
Operator: ABC REALTY
Facility Phone: (212) 307-0500
Facility Addr2: 319 WEST 42ND STREET
Facility Type: APARTMENT BUILDING
Emergency: WILLIAM D. HARRA
Emergency Tel: (212) 307-0500
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: NATHAN Z. & JAMES A. KORN
Owner Address: 101 WEST 12TH STREET
Owner City,St,Zip: NEW YORK, NY 10011
Federal ID: Not reported
Owner Tel: (212) 675-6668
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: JAMES A. KORN
Mailing Address: 101 WEST 12TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10011
Mailing Telephone: (212) 675-6668
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 03/27/1997
Expiration: 02/28/2002
Renew Flag: False
Renew Date: 10/30/2001
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

319 WEST 42ND STREET (Continued)

U003384179

Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 05
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: Diking
Leak Detection: 00
Overfill Protection: 04
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

AU282
WSW
1/8-1/4
0.176 mi.
928 ft.

538 10TH AVE
NEW YORK, NY 10018
Site 1 of 5 in cluster AU

EDR US Hist Auto Stat 1015545068
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: ACC CAR CARE CTR
Year: 2003
Address: 538 10TH AVE

Actual:
25 ft.

AR283
NNW
1/8-1/4
0.177 mi.
932 ft.

CON EDISON SERVICE BOX: 43286
628 10TH AVE OPPOSITE
NEW YORK, NY 10036

RCRA-CESQG 1016144111
FINDS NYP004268991

Site 4 of 9 in cluster AR

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 09/17/2012
Facility name: CON EDISON SERVICE BOX: 43286
Facility address: 628 10TH AVE OPPOSITE
NEW YORK, NY 10036
EPA ID: NYP004268991
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar

Actual:
30 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43286 (Continued)

1016144111

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461094

Environmental Interest/Information System

AR284
NNW
1/8-1/4
0.177 mi.
932 ft.

CON EDISON
OPP 628 10TH AVE
NEW YORK, NY 10036
Site 5 of 9 in cluster AR

NY MANIFEST S112210709
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268991
Country: USA

Actual:
30 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210709

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268991
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457041JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268991
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210709

Year: 2012
Manifest Tracking Num: 010457041JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AT285
ENE
1/8-1/4
0.177 mi.
934 ft.

CON EDISON
F/O 354 W45 ST & 8TH AVE
NEW YORK, NY 10036

NY MANIFEST

S112210721
N/A

Site 4 of 7 in cluster AT

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269114
Country: USA

Actual:
39 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269114
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457221JJK
Import Ind: N
Export Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210721

Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269114
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 3000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457221JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AQ286
NE
1/8-1/4
0.178 mi.
939 ft.

CONSOLIDATED EDISON
656 9TH AVE
NEW YORK, NY 10036
Site 3 of 7 in cluster AQ

NY MANIFEST S111157718
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004230843
Country: USA

Actual:
40 ft.

Mailing Info:
Name: CONSOLIDATED EDISON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S111157718

Contact: TOM TEELING
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2011-03-14
Trans1 Recv Date: 2011-03-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-03-16
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004230843
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 750.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 007660091JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AU287
WSW
1/8-1/4
0.178 mi.
940 ft.

CON EDISON MANHOLE: 43247
W 40TH ST &10TH AVE NW COR
NEW YORK, NY 10018

RCRA-CESQG 1016143767
NYP004265500

Site 2 of 5 in cluster AU

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 08/29/2012
Facility name: CON EDISON MANHOLE: 43247
Facility address: W 40TH ST &10TH AVE NW COR
NEW YORK, NY 10018
EPA ID: NYP004265500
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported

Actual:
25 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 43247 (Continued)

1016143767

Contact country: Not reported
Contact telephone: Not reported
Contact email: (347) 865-5931
EPA Region: Not reported
Classification: 02
Description: Conditionally Exempt Small Quantity Generator
Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AT288
ENE
1/8-1/4
0.178 mi.
942 ft.

**WEST 45TH ST VENTURE LLC
355 WEST 45 STREET
NEW YORK, NY 10036**

**NY AST U003383726
N/A**

Site 5 of 7 in cluster AT

**Relative:
Higher**

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-061484
Program Type: PBS
UTM X: 585292.96686000004
UTM Y: 4512600.4971599998
Expiration Date: 01/23/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 1091

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 45TH ST VENTURE LLC (Continued)

U003383726

Affiliation Type: Mail Contact
Company Name: DALAN MGMT.
Contact Type: Not reported
Contact Name: ANDREW WRUBLIN
Address1: 134 WEST 25TH ST. 2ND FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 929-0510
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/19/2012

Site Id: 1091
Affiliation Type: On-Site Operator
Company Name: WEST 45TH ST VENTURE LLC
Contact Type: Not reported
Contact Name: ARVIN STEVENS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 514-2446
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/19/2012

Site Id: 1091
Affiliation Type: Emergency Contact
Company Name: WEST 45TH STREET VENTURE LLC
Contact Type: Not reported
Contact Name: ANDREW WRUBLIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 929-0510
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/19/2012

Site Id: 1091
Affiliation Type: Facility Owner
Company Name: WEST 45TH STREET VENTURE LLC
Contact Type: MGR.
Contact Name: ANDREW WRUBLIN
Address1: 134 WEST 25TH ST
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 45TH ST VENTURE LLC (Continued)

U003383726

City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 929-0510
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/19/2012

Tank Info:

Tank Number: 001
Tank Id: 2131
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/1959
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AP289
East
1/8-1/4
0.178 mi.
942 ft.
VITO SACCHETTI
328 WEST 44TH STREET
NEW YORK, NY 10036
Site 3 of 4 in cluster AP

NY AST **A100159777**
N/A

Relative:
Higher

AST:

Actual:
39 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-604396
Program Type: PBS
UTM X: 585312.9444999998
UTM Y: 4512485.8213
Expiration Date: 01/12/2015

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VITO SACCHETTI (Continued)

A100159777

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 26270
Affiliation Type: Facility Owner
Company Name: VITO SACCHETTI
Contact Type: OWNER
Contact Name: VITO SACCHETTI
Address1: 1466 ST PETERS AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10461
Country Code: 001
Phone: (718) 828-1111
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 12/10/2007

Site Id: 26270
Affiliation Type: Mail Contact
Company Name: T.M.S. MANAGEMENT COMPANY
Contact Type: Not reported
Contact Name: VITO SACCHETTI
Address1: 1466 ST. PETERS AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10461
Country Code: 001
Phone: (718) 828-1111
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 1/6/2005

Site Id: 26270
Affiliation Type: On-Site Operator
Company Name: VITO SACCHETTI
Contact Type: Not reported
Contact Name: VITO SACCHETTI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 828-1111
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/9/2004

Site Id: 26270
Affiliation Type: Emergency Contact
Company Name: VITO SACCHETTI
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VITO SACCHETTI (Continued)

A100159777

Contact Name: VITO SACCHETTI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 828-1111
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/9/2004

Tank Info:

Tank Number: 01
Tank Id: 57573
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/2000
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 02
Tank Id: 181323
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VITO SACCHETTI (Continued)

A100159777

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B05 - Tank External Protection - Jacketed
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2000
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KXTANG
Last Modified: 01/06/2005
Material Name: #2 Fuel Oil (On-Site Consumption)

AQ290
NE
1/8-1/4
0.178 mi.
942 ft.

DRY CLEANERS
659 9TH AVE
NEW YORK, NY 10036

RCRA NonGen / NLR
FINDS
NY MANIFEST

1000148423
NYD048340095

Site 4 of 7 in cluster AQ

Relative:
Higher

RCRA NonGen / NLR:

Actual:
40 ft.

Date form received by agency: 01/01/2007
Facility name: DRY CLEANERS
Facility address: 659 9TH AVE
NEW YORK, NY 10010
EPA ID: NYD048340095
Mailing address: WORRALL AVE - ECOSYSTEM
POUGHKEEPSIE, NY 12603
Contact: PAUL CIMINELLO
Contact address: WORRALL AVE - ECOSYSTEM
POUGHKEEPSIE, NY 12603
Contact country: US
Contact telephone: (914) 452-1658
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: E H & L PROPERTIES C-O ARNOLD SPIEGEL ES
Owner/operator address: 50 E 42ND ST
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: (212) 972-4037
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Owner/operator name: E H & L PROPERTIES C-O ARNOLD SPIEGEL ES
Owner/operator address: 50 E 42ND ST
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: (212) 972-4037
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: DRY CLEANERS
Classification: Not a generator, verified

Date form received by agency: 11/03/1998
Site name: DRY CLEANERS
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110019587204

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Registry ID: 110004357071

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

NY MANIFEST:

EPA ID: NYD048340095
Country: USA

Mailing Info:

Name: REGAL
Contact: REGAL
Address: 659-9TH AVENUE
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-247-7608

Document ID: NJA0216530
Manifest Status: Completed after the designated time period for a TSDf to get a copy to the DEC
Trans1 State ID: NJSWAS284
Trans2 State ID: Not reported
Generator Ship Date: 860709
Trans1 Recv Date: 860709
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860709
Part A Recv Date: 860807
Part B Recv Date: 860716
Generator EPA ID: NYD048340095
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSDf ID: NJD002200046
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00608
Units: P - Pounds
Number of Containers: 032
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 86

Document ID: NJA0439526
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880421
Trans1 Recv Date: 880421
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880421
Part A Recv Date: 880427
Part B Recv Date: 880429
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00160
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0432598
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880616
Trans1 Recv Date: 880616
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880616
Part A Recv Date: 880621
Part B Recv Date: 880628
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NYA8813384
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880325
Trans1 Recv Date: 880325
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880325
Part A Recv Date: 880405
Part B Recv Date: 880404
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0443918
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880518
Trans1 Recv Date: 880518
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880518
Part A Recv Date: 880524
Part B Recv Date: 880602
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA1333880
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911028
Trans1 Recv Date: 911028
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911028
Part A Recv Date: Not reported
Part B Recv Date: 911112

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA2173700
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950620
Trans1 Recv Date: 950620
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950620
Part A Recv Date: 950628
Part B Recv Date: 950629
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2047010
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 941207
Trans1 Recv Date: 941207
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941207
Part A Recv Date: Not reported
Part B Recv Date: 941223
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA2041924
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950106
Trans1 Recv Date: 950106
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950106
Part A Recv Date: 950112
Part B Recv Date: 950126
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2157099
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950713
Trans1 Recv Date: 950713
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950713
Part A Recv Date: 950720
Part B Recv Date: 950725
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYC4627124
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: DER000000273

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Generator Ship Date: 05/05/1998
Trans1 Recv Date: 05/05/1998
Trans2 Recv Date: 05/12/1998
TSD Site Recv Date: 05/13/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD048340095
Trans1 EPA ID: OHD980587364
Trans2 EPA ID: Not reported
TSD ID: 85433
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00585
Units: P - Pounds
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: MNA5025571
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 861125
Trans1 Recv Date: 861125
Trans2 Recv Date: Not reported
TSD Site Recv Date: 861125
Part A Recv Date: 861209
Part B Recv Date: 861209
Generator EPA ID: NYD048340095
Trans1 EPA ID: NJD000768093
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00120
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 86

Document ID: NJA0497752
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880907
Trans1 Recv Date: 880907
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880907
Part A Recv Date: 880912
Part B Recv Date: 880920
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0512329
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 881201
Trans1 Recv Date: 881201
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881201
Part A Recv Date: 881208
Part B Recv Date: 881220
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0510150
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 881005
Trans1 Recv Date: 881005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881005
Part A Recv Date: 881013
Part B Recv Date: 881025
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Quantity: 00160
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0498550
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 881103
Trans1 Recv Date: 881103
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881103
Part A Recv Date: 881109
Part B Recv Date: 881125
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0620268
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 890515
Trans1 Recv Date: 890515
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890515
Part A Recv Date: 890518
Part B Recv Date: 890525
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00160
Units: P - Pounds
Number of Containers: 002
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NJA1423036
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920324
Trans1 Recv Date: 920324
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920324
Part A Recv Date: 920403
Part B Recv Date: 920406
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA1332257
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911126
Trans1 Recv Date: 911126
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911126
Part A Recv Date: Not reported
Part B Recv Date: 911206
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DRY CLEANERS (Continued)

1000148423

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1328147
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920219
Trans1 Recv Date: 920219
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920219
Part A Recv Date: 920227
Part B Recv Date: 920302
Generator EPA ID: NYD048340095
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00135
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

[Click this hyperlink](#) while viewing on your computer to access
106 additional NY_MANIFEST: record(s) in the EDR Site Report.

AQ291
NE
1/8-1/4
0.178 mi.
942 ft.

REGAL TAILORS CLEANERS
659 9TH AVE
NEW YORK, NY 10036
Site 5 of 7 in cluster AQ

NY DRYCLEANERS **S110247759**
N/A

Relative:
Higher

DRYCLEANERS:
Facility ID: 2-6202-00174
Phone Number: 212-262-7757
Region: Not reported
Registration Effective Date: N/A
Inspection Date: 03OCT22
Install Date: Not reported
Drop Shop: Not reported
Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

Actual:
40 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AU292
WSW
1/8-1/4
0.179 mi.
943 ft.

500 W 40TH ST
NEW YORK, NY 10018

Site 3 of 5 in cluster AU

EDR US Hist Auto Stat 1015522977
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: A NUMBER 1 ABWAYS CAR COLLISION REPA
Year: 2011
Address: 500 W 40TH ST

Actual:
25 ft.

Name: A NUMBER 1 ABWAYS CAR COLLISION REPA
Year: 2012
Address: 500 W 40TH ST

AV293
NNE
1/8-1/4
0.179 mi.
944 ft.

426-428 W. 46TH OWNER'S CORP.
428 WEST 46TH STREET
NEW YORK, NY 10036

Site 1 of 10 in cluster AV

NY AST A100183114
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606490
Program Type: PBS
UTM X: 585111.90871999995
UTM Y: 4512749.6792799998
Expiration Date: 07/25/2016
Site Type: Apartment Building/Office Building

Actual:
37 ft.

Affiliation Records:

Site Id: 28351
Affiliation Type: Facility Owner
Company Name: 426-428 WEST 46TH ST. OWNERS CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: % KYROUS REALTY GROUP, 263 W 38TH ST STE 15E
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 302-1500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/16/2013

Site Id: 28351
Affiliation Type: Mail Contact
Company Name: KYROUS REALTY GROUP, INC.
Contact Type: Not reported
Contact Name: HARRIET KYROUS
Address1: 263 WEST 38TH STREET
Address2: SUITE 15E
City: NEW YORK
State: NY
Zip Code: 10018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

426-428 W. 46TH OWNER'S CORP. (Continued)

A100183114

Country Code: 001
Phone: (212) 302-1500
EMail: HARRIET@KYROUSREALTYGROUP.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 10/29/2013

Site Id: 28351
Affiliation Type: On-Site Operator
Company Name: 426-428 W. 46TH OWNERS CORP.
Contact Type: Not reported
Contact Name: JOSE MARIMON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-7590
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28351
Affiliation Type: Emergency Contact
Company Name: 426-428 WEST 46TH ST. OWNERS CORP.
Contact Type: Not reported
Contact Name: JOSE MARIMON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 307-7590
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 01
Tank Id: 61502
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

426-428 W. 46TH OWNER'S CORP. (Continued)

A100183114

K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/18/1974
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 05/16/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

AW294 TRAVEL INN HOTEL
WNW 515 WEST 42ND STREET
1/8-1/4 NEW YORK, NY 10036
0.180 mi.
952 ft. Site 1 of 4 in cluster AW

NY AST U004067824
N/A

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-055239
Program Type: PBS
UTM X: 584792.93417999998
UTM Y: 4512593.5330299996
Expiration Date: 12/30/2006
Site Type: Other

Actual:
19 ft.

Affiliation Records:
Site Id: 819
Affiliation Type: Facility Owner
Company Name: FICO REALTY
Contact Type: Not reported
Contact Name: Not reported
Address1: 515 WEST 42ND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 695-7171
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 819
Affiliation Type: Mail Contact
Company Name: FICO REALTY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRAVEL INN HOTEL (Continued)

U004067824

Contact Type: Not reported
Contact Name: RONALD DOMB
Address1: 515 WEST 42ND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 695-7171
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 819
Affiliation Type: On-Site Operator
Company Name: TRAVEL INN HOTEL
Contact Type: Not reported
Contact Name: ALVIN WIDEMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-7171
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 819
Affiliation Type: Emergency Contact
Company Name: FICO REALTY
Contact Type: Not reported
Contact Name: ANTONIO LAHOZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 594-4923
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 1762
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRAVEL INN HOTEL (Continued)

U004067824

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 12000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/16/2006
Register: True
Modified By: DXLIVING
Last Modified: 10/03/2006
Material Name: #6 Fuel Oil (On-Site Consumption)

AU295
West
1/8-1/4
0.182 mi.
959 ft.

CON EDISON
OPP 503 W 40TH ST
NEW YORK, NY 10018

NY MANIFEST S112210343
N/A

Site 4 of 5 in cluster AU

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265138
Country: USA

Actual:
24 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265138
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210343

Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456242JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265138
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456242JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AX296
SSE
1/8-1/4
0.182 mi.
960 ft.
STAGING ASSOCIATES LTD
342 WEST 40TH STREET
NEW YORK, NY 10018
Site 1 of 3 in cluster AX

NY AST **A100178264**
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606036
Program Type: PBS
UTM X: 585088.78896999999
UTM Y: 4512204.9614800001
Expiration Date: 06/21/2006
Site Type: Other

Actual:
36 ft.

Affiliation Records:

Site Id: 27901
Affiliation Type: Facility Owner
Company Name: RANDY WILL
Contact Type: Not reported
Contact Name: Not reported
Address1: 342 WEST 40TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 736-5727
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27901
Affiliation Type: Mail Contact
Company Name: STAGING ASSOCIATES LTD
Contact Type: Not reported
Contact Name: PATRICK O'LEARY
Address1: 342 WEST 40TH STREET
Address2: Not reported
City: NEW YORK,
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 736-5727
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27901
Affiliation Type: On-Site Operator
Company Name: STAGING ASSOCIATES LTD
Contact Type: Not reported
Contact Name: STAGING ASSOCIATES
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STAGING ASSOCIATES LTD (Continued)

A100178264

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-5727
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27901
Affiliation Type: Emergency Contact
Company Name: RANDY WILL
Contact Type: Not reported
Contact Name: STAGING ASSOCIATES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-5727
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 01
Tank Id: 60872
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
B01 - Tank External Protection - Painted/Asphalt Coating
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STAGING ASSOCIATES LTD (Continued)

A100178264

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AQ297
NE
1/8-1/4
0.183 mi.
967 ft.

CON EDISON
661 9TH AVE
NEW YORK, NY 10036

NY MANIFEST S112210728
N/A

Site 6 of 7 in cluster AQ

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269189
Country: USA

Actual:
40 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269189
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457222JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210728

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269189
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457222JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AT298
ENE
1/8-1/4
0.183 mi.
968 ft.

BROADWAY & ELLWOOD REALTY, LLC.
348 WEST 45TH STREET
NEW YORK, NY 10036

NY AST A100178517
N/A

Site 6 of 7 in cluster AT

Relative:
Higher

AST:

Actual:
39 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606345
Program Type: PBS
UTM X: 585268.35027000005
UTM Y: 4512572.2890100004
Expiration Date: 01/04/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 28208
Affiliation Type: Mail Contact
Company Name: C/O S.W. MGT LLC
Contact Type: Not reported
Contact Name: BROADWAY & ELLWOOD REALTY, LLC.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROADWAY & ELLWOOD REALTY, LLC. (Continued)

A100178517

Address1: 145 HUGUENOT STREET,SUITE 503
Address2: Not reported
City: NEW ROCHELLE
State: NY
Zip Code: 10801
Country Code: 001
Phone: (914) 637-6200
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/3/2013

Site Id: 28208
Affiliation Type: On-Site Operator
Company Name: BROADWAY & ELLWOOD REALTY, LLC.
Contact Type: Not reported
Contact Name: ED BAEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 470-7118
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/3/2013

Site Id: 28208
Affiliation Type: Emergency Contact
Company Name: 348 WEST 45 EQUITIES
Contact Type: Not reported
Contact Name: ROCKWAY BOILER COMPANY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 585-8300
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 3/7/2008

Site Id: 28208
Affiliation Type: Facility Owner
Company Name: BROADWAY & ELLWOOD REALTY, LLC.
Contact Type: MGR
Contact Name: MARTIN BLUM
Address1: 348 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BROADWAY & ELLWOOD REALTY, LLC. (Continued)

A100178517

Phone: (914) 637-6200
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/3/2013

Tank Info:

Tank Number: 001
Tank Id: 61291
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other
I05 - Overfill - Vent Whistle
E02 - Piping Secondary Containment - Vault (with Access)
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating

3
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/29/1940
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 04/03/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

AR299
NNW
1/8-1/4
0.183 mi.
968 ft.

HESS CORPORATION
502 W 45TH ST
NEW YORK, NY 10036

Site 6 of 9 in cluster AR

RCRA NonGen / NLR 1004570577
NY MANIFEST NYD982722043
US AIRS

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: HESS CORPORATION
Facility address: 502 W 45TH ST
NEW YORK, NY 10036
EPA ID: NYD982722043
Mailing address: HESS PLAZA
WOODBIDGE, NJ 07095
Contact: JOHN GEITNER
Contact address: HESS PLAZA
WOODBIDGE, NJ 07095

Actual:
29 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Contact country: US
Contact telephone: (732) 750-7105
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: HESS CORPORATION
Owner/operator address: HESS PLAZA
WOODBRIDGE, NY 07095
Owner/operator country: US
Owner/operator telephone: (732) 750-6000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/2006
Owner/Op end date: Not reported

Owner/operator name: HESS CORPORATION
Owner/operator address: Not reported
Not reported

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Yes

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Yes

Historical Generators:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Date form received by agency: 08/01/2006
Site name: HESS CORPORATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/31/2006
Site name: HESS CORPORATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/28/1998
Site name: AMERADA HESS STATION 32215
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD982722043
Country: USA

Mailing Info:

Name: AMARADA HESS
Contact: AMARADA HESS
Address: 1 HESS PLAZA
City/State/Zip: WOODBRIDGE, NJ 07095
Country: USA
Phone: 201-656-9500

Document ID: NJA2195057
Manifest Status: Completed copy
Trans1 State ID: 006815
Trans2 State ID: Not reported
Generator Ship Date: 951026
Trans1 Recv Date: 951026
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951027
Part A Recv Date: 951122
Part B Recv Date: 951110
Generator EPA ID: NYD982722043
Trans1 EPA ID: PAD014146179
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: CTF0022357
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 920717
Trans1 Recv Date: 920717
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

TSD Site Recv Date: 920717
Part A Recv Date: Not reported
Part B Recv Date: 920803
Generator EPA ID: NYD982722043
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSD ID: CTD002593887
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: L Landfill.
Specific Gravity: 100
Year: 92

Document ID: NJA2195006
Manifest Status: Completed copy
Trans1 State ID: 06815
Trans2 State ID: Not reported
Generator Ship Date: 950919
Trans1 Recv Date: 950919
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950921
Part A Recv Date: 951020
Part B Recv Date: 951005
Generator EPA ID: NYD982722043
Trans1 EPA ID: PAD014146179
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: CTF0149785
Manifest Status: Completed copy
Trans1 State ID: PD4214NY
Trans2 State ID: Not reported
Generator Ship Date: 920827
Trans1 Recv Date: 920827
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920827
Part A Recv Date: Not reported
Part B Recv Date: 920908
Generator EPA ID: NYD982722043
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSD ID: CTD002593887
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00225

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: CTF0149792
Manifest Status: Completed copy
Trans1 State ID: NYPD4214
Trans2 State ID: Not reported
Generator Ship Date: 920727
Trans1 Recv Date: 920727
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920727
Part A Recv Date: Not reported
Part B Recv Date: 920804
Generator EPA ID: NYD982722043
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: CTD002593887
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00400
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA2560108
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 06815
Trans2 State ID: Not reported
Generator Ship Date: 960726
Trans1 Recv Date: 960726
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960801
Part A Recv Date: 960822
Part B Recv Date: 960909
Generator EPA ID: NYD982722043
Trans1 EPA ID: PAD014146179
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00050
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00100
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NYA7038999
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 890912
Trans1 Recv Date: 890912
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890913
Part A Recv Date: 890928
Part B Recv Date: 890920
Generator EPA ID: NYD982722043
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89

Document ID: CTF0149789
Manifest Status: Completed copy
Trans1 State ID: NYPD4214
Trans2 State ID: Not reported
Generator Ship Date: 920819
Trans1 Recv Date: 920819
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920819
Part A Recv Date: Not reported
Part B Recv Date: 920901
Generator EPA ID: NYD982722043
Trans1 EPA ID: NYD980761191
Trans2 EPA ID: Not reported
TSDF ID: CTD002593887
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA2726975
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 006815

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Trans2 State ID: 06815
Generator Ship Date: 970422
Trans1 Recv Date: 970422
Trans2 Recv Date: 970425
TSD Site Recv Date: 970425
Part A Recv Date: 970513
Part B Recv Date: 970520
Generator EPA ID: NYD982722043
Trans1 EPA ID: PAD014146179
Trans2 EPA ID: PAD014146179
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02000
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 97

AIRS (AFS):

Airs Minor Details:

EPA plant ID: 110001576429
Plant name: HESS S/S #32215
Plant address: 502 W 45TH STREET
NEW YORK, NY 10036
County: NEW YORK
Region code: 02
Dunn & Bradst #: Not reported
Air quality cntrl region: 043
Sic code: 5541
Sic code desc: GASOLINE SERVICE STATIONS
North Am. industrial classf: Not reported
NAIC code description: Not reported
Default compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR
LOCAL GOVERNMENT
Current HPV: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1004
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS CORPORATION (Continued)

1004570577

Hist compliance date:	1203
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1302
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1101
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1103
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1104
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1202
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1204
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1301
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1303
Air prog code hist file:	SIP SOURCE

Compliance & Violation Data by Minor Sources:

Air program code:	SIP SOURCE
Plant air program pollutant:	Not reported
Default pollutant classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt:	ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date:	Not reported
Turnover compliance:	Not reported
Air program code:	SIP SOURCE
Plant air program pollutant:	VOLATILE ORGANIC COMPOUNDS
Default pollutant classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt:	Not reported
Repeat violator date:	Not reported
Turnover compliance:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AR300 HESS #32215
NNW 502 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.183 mi.
968 ft. Site 7 of 9 in cluster AR

NY LTANKS U003178494
NY UST N/A

Relative:
Lower

LTANKS:

Actual:
29 ft.

Site ID: 81935
Spill Number/Closed Date: 8807538 / 10/18/2004
Spill Date: 12/13/1988
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: WXSUN
Referred To: Not reported
Reported to Dept: 12/13/1988
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 12/21/1988
Spill Record Last Update: 11/2/2004
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 75663
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SUN"11/06/01: MF-R9 OTHER SPILLS AT SITE 9314775, 8807198,CLOSED 9516313,CLOSED, 9604842, CLOSED, 9415731, CLOSED.02/18/2004- AUSTIN - REASSIGNED TO SUN10/15/04-On 10/15/04 Sun sent a letter to Michael Matri of Hess requiring by 11/30/04 to submit the following information: 1)Tank Closure Report, 2)Locations of tank and/or line test failure, 3)Subsurface investigation report, including current and historical soil and groundwater analysis, and 4)A surrounding property sketch including property layout and usage.10/18/04-On 10/15/04 Sun received from Micael Matri of Hess a Revised Spill Closure Report, prepared by EnviroTrac, dated December 2002. The report indicated that Hess removed 2,150 tons of soil from the site. Out of 20 soil samples collected following the UST removal, VOCs were detected in excess of their respective TAGM guidelines in only 3 (SP-2, SP-3 ans SP-10). Semi-VOCs were detected above their respective TAGM guidelines in only 2 of the samples (SP-14 and SP-20). Since there are no potable water supply well within a 1/4-mile radius of the site and this spill occurred prior to the removal of the 2,150 tons of soil that Hess removed during the UST removal, and only few VOC and SVOC concentrations higher than the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Remarks: NYSDEC standards, this spill is closed.
2 4K TANKS SYPHONED TOGETHER FAILED PETRO. L R = -0.554 GPH. ORIG.
INVESTIGATED BY GRATHWOL

Material:

Site ID: 81935
Operable Unit ID: 923009
Operable Unit: 01
Material ID: 455870
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 81935
Spill Tank Test: 1534998
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

UST:

Id/Status: 2-338613 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/29/2017
UTM X: 584926.34404999996
UTM Y: 4512782.90809
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 16281
Affiliation Type: Facility Owner
Company Name: HESS CORP
Contact Type: LICENSE COORDINATOR
Contact Name: JANICE FLAHERTY
Address1: 1 HESS PLAZA
Address2: Not reported
City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (732) 750-6000
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 1/22/2014

Site Id: 16281
Affiliation Type: Mail Contact
Company Name: HESS CORP
Contact Type: Not reported
Contact Name: JANICE FLAHERTY
Address1: 1 HESS PLAZA
Address2: Not reported
City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (732) 750-6350
EMail: JFLAHERTY@HESS.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/1/2011

Site Id: 16281
Affiliation Type: On-Site Operator
Company Name: HESS #32215
Contact Type: Not reported
Contact Name: SITE MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-6594
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/8/2009

Site Id: 16281
Affiliation Type: Emergency Contact
Company Name: HESS CORP
Contact Type: Not reported
Contact Name: HESS CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (732) 750-6000
EMail: Not reported
Fax Number: Not reported
Modified By: KCKEMP
Date Last Modified: 7/23/2012

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Tank Number: 001
Tank ID: 27848
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 002
Tank ID: 27849
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 003
Tank ID: 27850
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 004
Tank ID: 27851
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Number: 005
Tank ID: 27852
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 006
Tank ID: 27853
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 007
Tank ID: 27854
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 008
Tank ID: 27855
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 009
Tank ID: 27856
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 010
Tank ID: 27857
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1980
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 11/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Number: 11
Tank ID: 52311
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 04/01/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/08/2009

Equipment Records:

I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

Tank Number: 12
Tank ID: 52312
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 04/01/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/01/2011

Equipment Records:

I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)

Tank Number: 13
Tank ID: 52314
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 04/01/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/01/2011

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HESS #32215 (Continued)

U003178494

I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double-Walled (Underground)

Tank Number: 14
Tank ID: 52313
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 04/01/1997
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 10/08/2009

Equipment Records:

I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AR301
NNW
1/8-1/4
0.183 mi.
968 ft.

502 W 45TH ST
NEW YORK, NY 10036

Site 8 of 9 in cluster AR

EDR US Hist Auto Stat

1015525594
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: AMERADA HESS CORP
Year: 2001
Address: 502 W 45TH ST

Actual:
29 ft.

Name: AMERADA HESS CORP
Year: 2003
Address: 502 W 45TH ST

Name: AMERADA HESS CORP
Year: 2004
Address: 502 W 45TH ST

Name: AMERADA HESS
Year: 2005
Address: 502 W 45TH ST

Name: AMERADA HESS CORP
Year: 2007
Address: 502 W 45TH ST

Name: AMERADA HESS CORP
Year: 2008
Address: 502 W 45TH ST

Name: AMERADA HESS CORP
Year: 2009
Address: 502 W 45TH ST

Name: AMERADA HESS CORP
Year: 2010
Address: 502 W 45TH ST

Name: HESS CORPORATION
Year: 2011
Address: 502 W 45TH ST

Name: HESS CORPORATION
Year: 2012
Address: 502 W 45TH ST

AR302
NNW
1/8-1/4
0.183 mi.
968 ft.

502 WEST 45TH ST/HESS
502 WEST 45TH STREET
MANHATTAN, NY

Site 9 of 9 in cluster AR

NY LTANKS
NY Spills

S104501430
N/A

Relative:
Lower

LTANKS:

Site ID: 104613
Spill Number/Closed Date: 8807198 / 3/19/2003

Actual:
29 ft.

Spill Date: 11/30/1988
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates a file or hazard. DEC Response. Willing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

Responsible Party: Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 12/1/1988
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 12/1/1988
Spill Record Last Update: 7/19/2005
Spiller Name: Not reported
Spiller Company: HESS OIL
Spiller Address: 502 WEST 45TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 295954
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"
Remarks: Not reported

Material:

Site ID: 104613
Operable Unit ID: 923860
Operable Unit: 01
Material ID: 455543
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 104613
Spill Tank Test: 1534949
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

SPILLS:

Facility ID: 9606129
Facility Type: ER
DER Facility ID: 295954
Site ID: 102777
DEC Region: 2
Spill Date: 8/13/1996
Spill Number/Closed Date: 9606129 / 12/31/1997
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 8/13/1996
CID: 297
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/13/1996
Spill Record Last Update: 6/14/2002
Spiller Name: Not reported
Spiller Company: HESS GAS
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: UNKNOWN
Contact Phone: (000) 000-0000
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks: "MULQUEEN" MULQUEEN INSPECTED. ACTIVE UNDER PREVIOUS SPILL #'S.
SUBJECT WAS WALKING ON THE 45TH ST SIDE BY A SUBWAY AND NOTICE GAS
LEAKING OUT OF THE STONE WALL - SUBJ ALSO NOTICE GAS VAPORS COMING
FROM THE MANHOLES

Material:

Site ID: 102777
Operable Unit ID: 1033661
Operable Unit: 01
Material ID: 348863
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

Facility ID: 1004718
Facility Type: ER
DER Facility ID: 295954
Site ID: 438001
DEC Region: 2
Spill Date: 7/26/2010
Spill Number/Closed Date: 1004718 / 7/29/2010
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 7/26/2010
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/26/2010
Spill Record Last Update: 7/29/2010
Spiller Name: Not reported
Spiller Company: HESS CORP
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: MICHAEL MATRI
Contact Phone: (732) 841-1377
DEC Memo: 5 gal spill to pavement from broken nozzle. Cleaned , closed. See edocs if warranted.

Remarks: HOSE DETACHED FROM NOZZLE, SPILL TO PAVEMENT. CLEANUP IN PROGRESS, SPILL RESPONSE CONTRACTOR EN ROUTE.

Material:
Site ID: 438001
Operable Unit ID: 1188660
Operable Unit: 01
Material ID: 2183594
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

Facility ID: 9604842
Facility Type: ER
DER Facility ID: 295954
Site ID: 255885
DEC Region: 2
Spill Date: 7/14/1996
Spill Number/Closed Date: 9604842 / 7/15/1996
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)

SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 7/14/1996
CID: 211
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 7/14/1996
Spill Record Last Update: 7/19/2005
Spiller Name: Not reported
Spiller Company: HESS GAS STATION
Spiller Address: 502 WEST 45 ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: caller reports there was some type of malfunction with gas
pumpcausing spill - fire dept is on scene trying to contain it -
someproduct has entered storm dran

Material:

Site ID: 255885
Operable Unit ID: 1032482
Operable Unit: 01
Material ID: 347596
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9415731

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

Facility Type: ER
DER Facility ID: 295954
Site ID: 62560
DEC Region: 2
Spill Date: 3/5/1995
Spill Number/Closed Date: 9415731 / 3/5/1995
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 3/5/1995
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: 3/5/1995
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 4/12/1995
Spill Record Last Update: 7/19/2005
Spiller Name: Not reported
Spiller Company: ISLAND TRANSPORTATION
Spiller Address: 5700 47TH ST
Spiller City,St,Zip: MASPETH, NY 11378
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: APPEARS SPILL CAME UP THRU FILL LINE - CALLED BACK AT 9:30 TO UPDATE QUANTITY.

Material:
Site ID: 62560
Operable Unit ID: 1012908
Operable Unit: 01
Material ID: 370903
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 4
Units: Gallons
Recovered: 4
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9516313
Facility Type: ER
DER Facility ID: 295954

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

502 WEST 45TH ST/HESS (Continued)

S104501430

Site ID: 102776
DEC Region: 2
Spill Date: 3/19/1996
Spill Number/Closed Date: 9516313 / 3/19/2003
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/19/1996
CID: 312
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/19/1996
Spill Record Last Update: 7/19/2005
Spiller Name: Not reported
Spiller Company: HESS #32215
Spiller Address: 502 WEST 45TH ST
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: (212) 245-6594
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"SANGESLAND"Closed file filed under Spill #88-07198
Remarks: soil borings found contaminated soil in readings of 1156 ppm

Material:
Site ID: 102776
Operable Unit ID: 1027284
Operable Unit: 01
Material ID: 352833
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

[Click this hyperlink](#) while viewing on your computer to access
additional NY_SPILL: detail in the EDR Site Report.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

303
SW
1/8-1/4
0.184 mi.
969 ft.

CON EDISON
465 W 39 ST.
NEW YORK, NY 10018

NY MANIFEST

S112210367
N/A

Relative:
Lower

NY MANIFEST:

EPA ID: NYP004265385
Country: USA

Actual:
29 ft.

Mailing Info:

Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265385
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210367

Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265385
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456248JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AX304
SSE
1/8-1/4
0.184 mi.
969 ft.
THE STAY BRIDGE
334-340 WEST 40TH STREET
NEW YORK, NY 10018
Site 2 of 3 in cluster AX

NY UST **U004109451**
N/A

Relative:
Higher

UST:
Id/Status: 2-610618 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/20/2011
UTM X: 585106.88765000005
UTM Y: 4512195.1896200003
Site Type: Other

Actual:
37 ft.

Affiliation Records:
Site Id: 384959
Affiliation Type: Facility Owner
Company Name: MEHTA FAMILY LLC
Contact Type: OWNER
Contact Name: KK MEHTA
Address1: 100 GARDEN CITY PLAZA, STE 220
Address2: Not reported
City: GARDEN CITY
State: NY
Zip Code: 11530
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAY BRIDGE (Continued)

U004109451

Phone: (516) 663-5990
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/27/2007

Site Id: 384959
Affiliation Type: Mail Contact
Company Name: MEHTA FAMILY LLC
Contact Type: Not reported
Contact Name: KK MEHTA
Address1: 100 GARDEN CITY PLAZA
Address2: SUITE 220
City: GARDEN CITY
State: NY
Zip Code: 11530
Country Code: 001
Phone: (516) 663-5990
EMail: KKMEHTACPA@HOTMAIL.COM
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/27/2007

Site Id: 384959
Affiliation Type: On-Site Operator
Company Name: THE STAY BRIDGE
Contact Type: Not reported
Contact Name: MEHTA FAMILY LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 663-5990
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/27/2007

Site Id: 384959
Affiliation Type: Emergency Contact
Company Name: MEHTA FAMILY LLC
Contact Type: Not reported
Contact Name: KK MEHTA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 663-5990
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 7/27/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAY BRIDGE (Continued)

U004109451

Tank Info:

Tank Number: 01
Tank ID: 218548
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/11/2007
Date Tank Closed: 07/11/2007
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 07/27/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None

Tank Number: 02
Tank ID: 218549
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/11/2007
Date Tank Closed: 07/11/2007
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 07/27/2007

Equipment Records:

F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAY BRIDGE (Continued)

U004109451

I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

Tank Number: 03
Tank ID: 218550
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/11/2007
Date Tank Closed: 07/11/2007
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 07/27/2007

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 04
Tank ID: 218551
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/11/2007
Date Tank Closed: 07/11/2007
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAY BRIDGE (Continued)

U004109451

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 07/27/2007

Equipment Records:

C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None

Tank Number: 05
Tank ID: 232548
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 700
Install Date: Not reported
Date Tank Closed: 08/16/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 01/22/2010

Equipment Records:

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AX305
SSE
1/8-1/4
0.184 mi.
969 ft.

THE STAYBRIDGE
334 -340 WEST 40TH STREET
MANHATTAN, NY 10018

RCRA-LQG **1010329057**
NY MANIFEST **NYR000146787**

Site 3 of 3 in cluster AX

Relative:
Higher

RCRA-LQG:

Actual:
37 ft.

Date form received by agency: 04/14/2008
Facility name: THE STAYBRIDGE
Facility address: 334 -340 WEST 40TH STREET
MANHATTAN, NY 10018
EPA ID: NYR000146787
Mailing address: GARDEN CITY PLAZA
SUITE 220
GARDEN CITY, NY 11530
Contact: ALEXANDRA JANELLI
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 967-2753
Contact email: eceaaalex@aol.com
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: MEHTA FAMILY, LLC
Owner/operator address: GARDEN CITY PLAZA
GARDEN CITY, NY 11530
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/19/2007
Owner/Op end date: Not reported
Owner/operator name: MEHTA FAMILY, LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/19/2007
Owner/Op end date: Not reported
Owner/operator name: MEHTA FAMILY LLC
Owner/operator address: GARDEN CITY PLAZA SUITE 200

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

GARDEN CITY, NY 11530

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/19/2007
Owner/Op end date: Not reported

Owner/operator name: MEHTA FAMILY LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/19/2007
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 05/03/2007
Site name: STAYBRIDGE THE
Classification: Large Quantity Generator

Date form received by agency: 05/02/2007
Site name: STAYBRIDGE THE
Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYR000146787
Country: USA

Mailing Info:

Name: METHA FAMILY LLC
Contact: ALEXANDRA JANELLI

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Address: 100 GARDEN CITY PLAZA
City/State/Zip: GARDEN CITY, NY 11530
Country: USA
Phone: 212-967-2745

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 59160
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121878JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Quantity: 53800
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121879JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54180
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121880JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 39220
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121882JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 55120
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Year: 2007
Manifest Tracking Num: 003121883JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54000
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121884JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 58900
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121885JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 49580
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121886JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 8/20/2007
Trans1 Recv Date: 8/20/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/20/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54720
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121887JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 59160.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121878JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 53800.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121879JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54180.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121880JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 39220.0
Units: P - Pounds
Number of Containers: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121882JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 55120.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121883JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121884JJJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 58900.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121885JJJK
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 49580.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121886JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-20
Trans1 Recv Date: 2007-08-20
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-20
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE STAYBRIDGE (Continued)

1010329057

Part B Recv Date: Not reported
Generator EPA ID: NYR000146787
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 54720.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 003121887JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AY306 416 WEST 46TH LLC
NNE 416 WEST 46TH STREET
1/8-1/4 NEW YORK, NY 10036
0.184 mi.
974 ft. Site 1 of 6 in cluster AY

NY AST A100292337
N/A

Relative:
Higher

AST:

Actual:
39 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-607792
Program Type: PBS
UTM X: 585139.77260000003
UTM Y: 4512734.4564500004
Expiration Date: 05/28/2007
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 29644
Affiliation Type: Facility Owner
Company Name: 416 W 46TH LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 1374 FIRST AVE., 2B
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 249-6818
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

416 WEST 46TH LLC (Continued)

A100292337

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29644
Affiliation Type: Mail Contact
Company Name: 416 W 46TH LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 1372 FIRST AVENUE
Address2: 2B
City: NEW YORK
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 249-6818
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29644
Affiliation Type: On-Site Operator
Company Name: 416 WEST 46TH LLC
Contact Type: Not reported
Contact Name: SIMON GRETCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 669-4895
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 29644
Affiliation Type: Emergency Contact
Company Name: 416 W 46TH LLC
Contact Type: Not reported
Contact Name: SIMON GRETCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 669-4895
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

416 WEST 46TH LLC (Continued)

A100292337

Tank Id: 63522
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AU307
West
1/8-1/4
0.185 mi.
975 ft.

CON EDISON
OPP 509 W 40TH ST
NEW YORK, NY 10018
Site 5 of 5 in cluster AU

NY MANIFEST S112210341
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265112
Country: USA

Actual:
24 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210341

Part B Recv Date: Not reported
Generator EPA ID: NYP004265112
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456241JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265112
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456241JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210341

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AT308
ENE
1/8-1/4
0.185 mi.
976 ft.

349 W 45TH ST
NEW YORK, NY 10036
Site 7 of 7 in cluster AT

EDR US Hist Auto Stat 1015441350
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: ZYZY AUTO REPAIR
Year: 2010
Address: 349 W 45TH ST

Actual:
39 ft.

Name: ZYZY AUTO REPAIR
Year: 2011
Address: 349 W 45TH ST

Name: ZYZY AUTO REPAIR
Year: 2012
Address: 349 W 45TH ST

AY309
NNE
1/8-1/4
0.185 mi.
976 ft.

HIGHPOINT ASSOCIATES XII, LLC
410-412 WEST 46TH STREET
NEW YORK, NY 10036

NY AST U004077711
N/A

Site 2 of 6 in cluster AY

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-279153
Program Type: PBS
UTM X: 585142.65645000001
UTM Y: 4512733.5622500004
Expiration Date: 12/01/2018
Site Type: Apartment Building/Office Building

Actual:
40 ft.

Affiliation Records:

Site Id: 12137
Affiliation Type: Facility Owner
Company Name: HIGHPOINT ASSOCIATES XII, LLC
Contact Type: MANAGING AGENT
Contact Name: RICHARD LAGANA
Address1: 15165 VENTURA BLVD, SUITE 140
Address2: Not reported
City: SHERMAN OAKS
State: CA
Zip Code: 91403
Country Code: 001
Phone: (212) 684-4141
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HIGHPOINT ASSOCIATES XII, LLC (Continued)

U004077711

Date Last Modified: 11/6/2013

Site Id: 12137
Affiliation Type: Mail Contact
Company Name: % KEYSTONE MANAGEMENT, INC.
Contact Type: Not reported
Contact Name: HIGHPOINT ASSOCS XII, LLC
Address1: 15165 VENTURA BOULEVARD
Address2: SUITE 140
City: SHERMAN OAKS
State: CA
Zip Code: 91403
Country Code: 001
Phone: (212) 684-4141
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 11/6/2013

Site Id: 12137
Affiliation Type: On-Site Operator
Company Name: HIGHPOINT ASSOCIATES XII, LLC
Contact Type: Not reported
Contact Name: RICHARD LAGANA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 684-4141 309
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 11/6/2013

Site Id: 12137
Affiliation Type: Emergency Contact
Company Name: HIGHPOINT ASSOCIATES XII, LLC
Contact Type: Not reported
Contact Name: RICHARD LAGANA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 684-4141 309
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 11/6/2013

Tank Info:

Tank Number: 001
Tank Id: 28073

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HIGHPOINT ASSOCIATES XII, LLC (Continued)

U004077711

Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1989
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 10/03/2013
Material Name: #6 Fuel Oil (On-Site Consumption)

AZ310 **CON EDISON SERVICE BOX: 7873**
West **510 W 41ST ST**
1/8-1/4 **NEW YORK, NY 10036**
0.185 mi.
979 ft. **Site 1 of 4 in cluster AZ**

RCRA-CESQG **1016144045**
FINDS **NYP004268322**

Relative:
Lower

RCRA-CESQG:

Actual:
20 ft.

Date form received by agency: 09/13/2012
Facility name: CON EDISON SERVICE BOX: 7873
Facility address: 510 W 41ST ST
NEW YORK, NY 10036
EPA ID: NYP004268322
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7873 (Continued)

1016144045

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055458909

Environmental Interest/Information System

AZ311
West
1/8-1/4
0.185 mi.
979 ft.

CON EDISON
510 W 41ST ST
NEW YORK, NY 10036

Site 2 of 4 in cluster AZ

NY MANIFEST **S112210646**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268322
Country: USA

Actual:
20 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210646

Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268322
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457017JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-13
Trans1 Recv Date: 2012-09-13
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268322
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457017JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210646

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AV312 424 WEST OWNERS LTD.
NNE 424 WEST 46TH STREET
1/8-1/4 NEW YORK, NY 10046
0.185 mi.
979 ft. Site 2 of 10 in cluster AV

NY AST U004045546
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-315192
Program Type: PBS
UTM X: 585155.64309000003
UTM Y: 4512752.1245900001
Expiration Date: 10/15/1997
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 14397
Affiliation Type: Facility Owner
Company Name: 424 WEST OWNERS LTD.
Contact Type: Not reported
Contact Name: Not reported
Address1: 424 WEST 46TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10046
Country Code: 001
Phone: (212) 769-3706
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14397
Affiliation Type: Mail Contact
Company Name: C/O MARBROSE REALTY
Contact Type: Not reported
Contact Name: RANFI BOCHNER
Address1: 43 WEST 75TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 769-3706
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

424 WEST OWNERS LTD. (Continued)

U004045546

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14397
Affiliation Type: On-Site Operator
Company Name: 424 WEST OWNERS LTD.
Contact Type: Not reported
Contact Name: ARNOLD HERRERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 924-5354
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14397
Affiliation Type: Emergency Contact
Company Name: 424 WEST OWNERS LTD.
Contact Type: Not reported
Contact Name: RANDI BOCHNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 769-3706
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 24686
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

424 WEST OWNERS LTD. (Continued)

U004045546

Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AY313 **406 WEST 46TH STREET CORP.**
NE **406 WEST 46TH STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.186 mi.
980 ft. **Site 3 of 6 in cluster AY**

NY TANKS **S110772154**
N/A

Relative:
Higher

TANKS:
Facility Id: 2-610671
Region: STATE
DEC Region: 2
Site Status: Inactive
Program Type: PBS
Expiration Date: Not reported
UTM X: 585156.42293
UTM Y: 4512724.97963

Actual:
40 ft.

AO314 **CON EDISON SERVICE BOX: 39829**
SSW **515 9TH AVE**
1/8-1/4 **NEW YORK, NY 10018**
0.186 mi.
981 ft. **Site 15 of 16 in cluster AO**

RCRA-CESQG **1016143756**
FINDS **NYP004265393**

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 08/28/2012
Facility name: CON EDISON SERVICE BOX: 39829
Facility address: 515 9TH AVE
NEW YORK, NY 10018
EPA ID: NYP004265393
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

Actual:
32 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39829 (Continued)

1016143756

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468131

Environmental Interest/Information System

AO315
SSW
1/8-1/4
0.186 mi.
981 ft.

**CON EDISON
515 9TH AVE
NEW YORK, NY 10018
Site 16 of 16 in cluster AO**

**NY MANIFEST S112210368
N/A**

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004265393
Country: USA

**Actual:
32 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210368

Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265393
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456078JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265393
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456078JJK
Import Ind: N
Export Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210368

Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

AW316
WNW
1/8-1/4
0.186 mi.
981 ft.

CON EDISON SERVICE BOX: 8068
519 W 42ND ST
NEW YORK, NY 10036
Site 2 of 4 in cluster AW

RCRA-CESQG 1016144067
FINDS NYP004268546

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/14/2012
Facility name: CON EDISON SERVICE BOX: 8068
Facility address: 519 W 42ND ST
NEW YORK, NY 10036

Actual:
19 ft.

EPA ID: NYP004268546
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8068 (Continued)

1016144067

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055459025

Environmental Interest/Information System

**AW317
WNW
1/8-1/4
0.186 mi.
981 ft.**

**CON EDISON
519 W 42ND ST
NEW YORK, NY 10036**

**NY MANIFEST S112210668
N/A**

Site 3 of 4 in cluster AW

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYP004268546
Country: USA

**Actual:
19 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268546
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456583JJK
Import Ind: N
Export Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210668

Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268546
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456583JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BA318
NE
1/8-1/4
0.186 mi.
983 ft.

404 W 46TH ST
NEW YORK, NY 10036
Site 1 of 3 in cluster BA

EDR US Hist Cleaners 1015055754
N/A

Relative:
Higher

EDR Historical Cleaners:
Name: SPEEDY CLEANERS
Year: 2010

Actual:
40 ft.

Address: 404 W 46TH ST

Name: SPEEDY CLEANERS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015055754

Year: 2011
Address: 404 W 46TH ST

Name: SPEEDY CLEANERS
Year: 2012
Address: 404 W 46TH ST

AY319 HARTLEY HOUSE
NNE 413 WEST 46TH ST
1/8-1/4 NEW YORK, NY 10036
0.187 mi.
985 ft. Site 4 of 6 in cluster AY

NY AST U003384062
NY HIST AST N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-081280
Program Type: PBS
UTM X: 585188.35387999995
UTM Y: 4512748.6151599996
Expiration Date: 03/24/2007
Site Type: Other

Actual:
40 ft.

Affiliation Records:

Site Id: 1689
Affiliation Type: Facility Owner
Company Name: HARTLEY HOUSE INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 413 WEST 46TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-9885
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1689
Affiliation Type: Mail Contact
Company Name: HARTLEY HOUSE INC
Contact Type: Not reported
Contact Name: MARY FOLLETT
Address1: 413 WEST 46TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-9885
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HARTLEY HOUSE (Continued)

U003384062

Site Id: 1689
Affiliation Type: On-Site Operator
Company Name: HARTLEY HOUSE
Contact Type: Not reported
Contact Name: HARTLEY HOUSE INC (TE-501C3)
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-9885
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 1689
Affiliation Type: Emergency Contact
Company Name: HARTLEY HOUSE INC
Contact Type: Not reported
Contact Name: JULIO GODOY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 315-4344
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 2900
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HARTLEY HOUSE (Continued)

U003384062

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-081280
SWIS Code: 6201
Operator: HARTLEY HOUSE INC (TE-501C3)
Facility Phone: (212) 246-9885
Facility Addr2: 413 WEST 46TH ST
Facility Type: OTHER
Emergency: HARTLEY HOUSE-BH KINZER EX DIR
Emergency Tel: (212) 246-9885
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: HARTLEY HOUSE INC
Owner Address: 413 WEST 46TH ST
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 246-9885
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: HARTLEY HOUSE INC
Mailing Address: 413 WEST 46TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 246-9885
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 02/28/1997
Expiration: 03/24/2002
Renew Flag: False
Renew Date: 11/13/2001
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HARTLEY HOUSE (Continued)

U003384062

Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: Not reported
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

AY320 ST CLEMENTS CHURCH
NNE 423 W 46TH ST
1/8-1/4 NEW YORK, NY 10036
0.187 mi.
985 ft. Site 5 of 6 in cluster AY

NY AST U003391968
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-404772
Program Type: PBS
UTM X: 585164.82721999998
UTM Y: 4512761.0008300003
Expiration Date: 08/23/1998
Site Type: Other

Affiliation Records:
Site Id: 19485
Affiliation Type: Facility Owner
Company Name: BOARD OF MGRS EPISCOPAL DIOCES
Contact Type: Not reported
Contact Name: Not reported
Address1: 104 AMSTERDAM AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10025
Country Code: 001
Phone: (212) 246-7277
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST CLEMENTS CHURCH (Continued)

U003391968

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19485
Affiliation Type: Mail Contact
Company Name: BOARD OF MGRS EPISCOPAL DIOCES
Contact Type: Not reported
Contact Name: Not reported
Address1: 104 AMSTERDAM AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10025
Country Code: 001
Phone: (212) 246-7277
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19485
Affiliation Type: On-Site Operator
Company Name: ST CLEMENTS CHURCH
Contact Type: Not reported
Contact Name: DOUGLAS WILLIAMS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-7277
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19485
Affiliation Type: Emergency Contact
Company Name: BOARD OF MGRS EPISCOPAL DIOCES
Contact Type: Not reported
Contact Name: EMORY EDWARDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 586-3977
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST CLEMENTS CHURCH (Continued)

U003391968

Tank Id: 23023
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-404772
SWIS Code: 6201
Operator: DOUGLAS WILLIAMS
Facility Phone: (212) 246-7277
Facility Addr2: 423 W 46TH ST
Facility Type: OTHER
Emergency: EMORY EDWARDS
Emergency Tel: (212) 586-3977
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: BOARD OF MGRS EPISCOPAL DIOCES
Owner Address: 104 AMSTERDAM AVE
Owner City,St,Zip: NEW YORK, NY 10025
Federal ID: Not reported
Owner Tel: (212) 246-7277
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: BOARD OF MGRS EPISCOPAL DIOCES
Mailing Address: 104 AMSTERDAM AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10025
Mailing Telephone: (212) 246-7277

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST CLEMENTS CHURCH (Continued)

U003391968

Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 11/29/1993
Expiration: 08/23/1998
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BB321
ESE
1/8-1/4
0.187 mi.
986 ft.

EMPIRE EFFECTS INC
214 E 21ST ST
NEW YORK, NY 10010
Site 1 of 5 in cluster BB

RCRA NonGen / NLR
FINDS **1000551517**
NYD986938595

Relative:
Higher

RCRA NonGen / NLR:

Actual:
41 ft.

Date form received by agency: 01/01/2007
Facility name: EMPIRE EFFECTS INC
Facility address: 214 E 21ST ST
NEW YORK, NY 100107460
EPA ID: NYD986938595
Mailing address: E 21ST ST
NEW YORK, NY 10010
Contact: Not reported
Contact address: E 21ST ST
NEW YORK, NY 10010
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: DANILO SALAI & JOHN LEWIS
Owner/operator address: 214 E 21 ST
NEW YORK, NY 10010
Owner/operator country: US
Owner/operator telephone: (212) 477-4776
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DANILO SALAI & JOHN LEWIS
Owner/operator address: 214 E 21 ST
NEW YORK, NY 10010
Owner/operator country: US
Owner/operator telephone: (212) 477-4776
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIREFFECTS INC (Continued)

1000551517

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: EMPIREFFECTS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: EMPIREFFECTS INC
Classification: Not a generator, verified

Date form received by agency: 02/05/1991
Site name: EMPIREFFECTS INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004459808

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

BB322 **EMPIREFFECTS INCORPORATED**
ESE **311 WEST 43RD STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.187 mi.
986 ft. **Site 2 of 5 in cluster BB**

NY AST **U003393531**
NY MANIFEST **N/A**

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-032638
Program Type: PBS
UTM X: 585320.83392999996
UTM Y: 4512401.8698399998
Expiration Date: 12/21/2017
Site Type: Other

Actual:
41 ft.

Affiliation Records:
Site Id: 230
Affiliation Type: Facility Owner
Company Name: JUNIPER ASSOCIATES
Contact Type: MEMBER
Contact Name: F. ANTHONY ZUNINO
Address1: 311 WEST 43RD ST
Address2: Not reported
City: NEW YORK

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE EFFECTS INCORPORATED (Continued)

U003393531

State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 307-7890
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 12/11/2007

Site Id: 230
Affiliation Type: Mail Contact
Company Name: JUNIPER ASSOCIATES
Contact Type: Not reported
Contact Name: F. ANTHONY ZUNINO
Address1: 311 WEST 43RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 307-7890
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 230
Affiliation Type: On-Site Operator
Company Name: 311 WEST 43RD ST
Contact Type: Not reported
Contact Name: TERRY DWORJAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-6469
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 230
Affiliation Type: Emergency Contact
Company Name: JUNIPER ASSOCIATES
Contact Type: Not reported
Contact Name: TERRY DWORJAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 728-0233
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE EFFECTS INCORPORATED (Continued)

U003393531

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 30491
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/1955
Capacity Gallons: 6000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 08/13/2013
Material Name: #6 Fuel Oil (On-Site Consumption)

NY MANIFEST:

EPA ID: NYD986938595
Country: USA

Mailing Info:

Name: EMPIRE EFFECTS INCORPORATED
Contact: JEAN PREECE
Address: 311 WEST 43RD STREET
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-477-4776

NY MANIFEST:

No Manifest Records Available

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BB323
ESE
1/8-1/4
0.187 mi.
986 ft.

T V C LABORATORIES INC C/O CIT
311 W 43RD ST - 10TH & 11TH FL
NEW YORK, NY 10036

RCRA NonGen / NLR
FINDS

1000790573
NYD987020575

Site 3 of 5 in cluster BB

Relative:
Higher

RCRA NonGen / NLR:

Actual:
41 ft.

Date form received by agency: 01/01/2007
Facility name: T V C LABORATORIES INC C/O CIT
Facility address: 311 W 43RD ST - 10TH & 11TH FL
NEW YORK, NY 10036
EPA ID: NYD987020575
Mailing address: 7TH AVE - 19TH FL
NEW YORK, NY 10019
Contact: Not reported
Contact address: 7TH AVE - 19TH FL
NEW YORK, NY 10019
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: THE CIT GROUP CREDIT FINANCE
Owner/operator address: 810 7TH AVE
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 974-7400
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE CIT GROUP CREDIT FINANCE
Owner/operator address: 810 7TH AVE
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 974-7400
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

T V C LABORATORIES INC C/O CIT (Continued)

1000790573

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: T V C LABORATORIES INC C/O CIT
Classification: Not a generator, verified

Date form received by agency: 02/11/1997
Site name: T V C LABORATORIES INC C/O CIT
Classification: Not a generator, verified

Date form received by agency: 11/10/1992
Site name: T V C LABORATORIES INC C/O CIT
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 03/06/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110008081930

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AY324
NNE
1/8-1/4
0.187 mi.
986 ft.

**ST CLEMENTS
423 WEST 46TH ST
MANHATTAN, NY**

**NY LTANKS S106124300
N/A**

Site 6 of 6 in cluster AY

**Relative:
Higher**

LTANKS:

Site ID: 97790
Spill Number/Closed Date: 0308286 / 4/12/2006
Spill Date: 11/5/2003
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101

**Actual:
38 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST CLEMENTS (Continued)

S106124300

Investigator: GWHEITZM
Referred To: Not reported
Reported to Dept: 11/5/2003
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/5/2003
Spill Record Last Update: 4/12/2006
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: SETH
Spiller Phone: (212) 246-7277
Spiller Extention: 0
DEC Region: 2
DER Facility ID: 87080
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND" send tank test letter PBS 2-404772 indicates that the 2000 gal tank is above ground with suction piping and exempt from testing. 6/15/05 Heitzman: Sent letter to church requesting additional documentation on repairs to line and possible re-test. 4/12/06 - No response received from property owner. However, based on judgement and the spills closure guidance, this appears to be one that can be closed out. They will have a higher authority to answer to.
Remarks: Tank test failure at above location. Repairs to line to be made and tank retested.

Material:

Site ID: 97790
Operable Unit ID: 874549
Operable Unit: 01
Material ID: 501796
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 97790
Spill Tank Test: 1528790
Tank Number: 1
Tank Size: 2000
Test Method: 03
Leak Rate: 0
Gross Fail: F

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST CLEMENTS (Continued)

S106124300

Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

AZ325
West
1/8-1/4
0.188 mi.
993 ft.

MERCEDES-BENZ MANHATTAN INC.
536 WEST 41TH ST.
MANHATTAN, NY 10036

NY AST **S107782842**
N/A

Site 3 of 4 in cluster AZ

Relative:
Lower

AST:

Actual:
19 ft.

Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-601492
Program Type: PBS
UTM X: 584692.55870000005
UTM Y: 4512534.3207900003
Expiration Date: 05/19/1998
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 23454
Affiliation Type: Facility Owner
Company Name: QUAKER STATE CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: P.O. BOX 989
Address2: Not reported
City: OIL CITY
State: PA
Zip Code: 16301
Country Code: 001
Phone: (814) 676-7676
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23454
Affiliation Type: Mail Contact
Company Name: QUAKER STATE CORPORATION
Contact Type: Not reported
Contact Name: MIKE HEIL
Address1: 255 ELM ST.
Address2: P.O. BOX 989
City: OIL CITY
State: PA
Zip Code: 16301
Country Code: 001
Phone: (814) 676-7676
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23454

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC. (Continued)

S107782842

Affiliation Type: On-Site Operator
Company Name: MERCEDES-BENZ MANHATTAN INC.
Contact Type: Not reported
Contact Name: QUAKER STATE CORP.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 760-0600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23454
Affiliation Type: Emergency Contact
Company Name: QUAKER STATE CORP.
Contact Type: Not reported
Contact Name: QUAKER STATE CORP.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (814) 676-7676
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 46428
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/01/1991
Capacity Gallons: 500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC. (Continued)

S107782842

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Lube Oil

Tank Number: 002
Tank Id: 46429
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/01/1991
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Lube Oil

Tank Number: 003
Tank Id: 46430
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC. (Continued)

S107782842

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/01/1991
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Lube Oil

AP326
East
1/8-1/4
0.189 mi.
997 ft.

CINERIC INC
321 W 44TH ST - 4TH FL
NEW YORK, NY 10036

RCRA-CESQG
FINDS
NJ MANIFEST

1000555821
NYD986983666

Site 4 of 4 in cluster AP

Relative:
Higher

RCRA-CESQG:

Actual:
40 ft.

Date form received by agency: 01/01/2007
Facility name: CINERIC INC
Facility address: 321 W 44TH ST - 4TH FL
NEW YORK, NY 100365404
EPA ID: NYD986983666
Mailing address: W 44TH ST - 4TH FL
NEW YORK, NY 10036
Contact: Not reported
Contact address: W 44TH ST - 4TH FL
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: CINERIC INC
Owner/operator address: 321 W 44TH ST
NEW YORK, NY 10036
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CINERIC INC (Continued)

1000555821

Owner/operator telephone: (212) 586-4822
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CINERIC INC
Owner/operator address: 321 W 44TH ST
NEW YORK, NY 10036

Owner/operator country: US
Owner/operator telephone: (212) 586-4822
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: CINERIC INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: CINERIC INC
Classification: Not a generator, verified

Date form received by agency: 12/11/1991
Site name: CINERIC INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004481178

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CINERIC INC (Continued)

1000555821

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

Manifest Code:	NJA5117089
EPA ID:	NYD986983666
Date Shipped:	07/01/2005
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/01/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/01/2005
Transporter 1 Decal:	Not reported
Transporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	07280521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CINERIC INC (Continued)

1000555821

Hand Code:	Not reported
Manifest Code:	000888173JJK
EPA ID:	NYD986983666
Date Shipped:	06/08/2007
TSDf EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/08/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	06/08/2007
Transporter 1 Decal:	Not reported
Transporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	F002
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	50
Unit:	G
Hand Code:	H02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AV327 433 W 46TH HDFC ASSOC.
NNE 433 WEST 46TH STREET
1/8-1/4 NEW YORK, NY 10036
0.189 mi.
998 ft. Site 3 of 10 in cluster AV

NY AST A100078005
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-374806
Program Type: PBS
UTM X: 585141.38632000005
UTM Y: 4512773.27654
Expiration Date: 01/05/2019
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18869
Affiliation Type: Facility Owner
Company Name: 433 W 46 ST HDFC
Contact Type: PRES
Contact Name: RICHARD ROBERTS
Address1: 433 W 46TH ST, #3R
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 929-3780
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 12/5/2013

Site Id: 18869
Affiliation Type: Mail Contact
Company Name: 433 W 46 ST CORP
Contact Type: Not reported
Contact Name: RICHARD ROBERTS
Address1: 433 WEST 46TH HDFC ASSOC.
Address2: 433 WEST 46TH STREET #3R
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 929-3780
EMail: RICHARDROBERTSHYC@GMAIL.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 12/5/2013

Site Id: 18869
Affiliation Type: On-Site Operator
Company Name: 433 W 46TH HDFC ASSOC.
Contact Type: Not reported
Contact Name: RICHARD ROBERTS
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

433 W 46TH HDFC ASSOC. (Continued)

A100078005

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-3780
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18869
Affiliation Type: Emergency Contact
Company Name: 433 W 46 ST CORP
Contact Type: Not reported
Contact Name: RICHARD ROBERTS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 929-3780
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 8/4/2011

Tank Info:

Tank Number: 001
Tank Id: 21176
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1955
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

433 W 46TH HDFC ASSOC. (Continued)

A100078005

Last Modified: 12/05/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

**BA328
NE
1/8-1/4
0.189 mi.
1000 ft.**

**CON EDISON SERVICE BOX: 39914
W 46TH ST & 9TH AVE NE COR
NEW YORK, NY 10036**

RCRA-CESQG

**1016144128
NYP004269163**

Site 2 of 3 in cluster BA

**Relative:
Higher**

RCRA-CESQG:

**Actual:
41 ft.**

Date form received by agency: 09/18/2012
Facility name: CON EDISON SERVICE BOX: 39914
Facility address: W 46TH ST & 9TH AVE NE COR
NEW YORK, NY 10036
EPA ID: NYP004269163
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JOSE MONTALVO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 427-1331
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39914 (Continued)

1016144128

Violation Status: No violations found

AQ329 665-7-9 9TH AVE
NE 665-7-9 9TH AVE
1/8-1/4 NEW YORK, NY 10036
0.189 mi.
1000 ft. Site 7 of 7 in cluster AQ

NY AST U003392559
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-200190
Program Type: PBS
UTM X: 585172.5718499995
UTM Y: 4512719.6929099998
Expiration Date: 10/23/2007
Site Type: Unknown

Affiliation Records:

Site Id: 6731
Affiliation Type: Facility Owner
Company Name: LEONARD FRANZBLAU-PIONEER MGT
Contact Type: Not reported
Contact Name: Not reported
Address1: 27 WEST 72ND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 874-1882
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6731
Affiliation Type: Mail Contact
Company Name: LEONARD FRANZBLAU-PIONEER MGT
Contact Type: Not reported
Contact Name: Not reported
Address1: 27 WEST 72ND STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 874-1882
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6731
Affiliation Type: On-Site Operator
Company Name: 665-7-9 9TH AVE
Contact Type: Not reported
Contact Name: MANNY CAPPAS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

665-7-9 9TH AVE (Continued)

U003392559

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 874-1882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004
Site Id:	6731
Affiliation Type:	Emergency Contact
Company Name:	LEONARD FRANZBLAU-PIONEER MGT
Contact Type:	Not reported
Contact Name:	LEONARD FRANZBLAU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 874-1882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank Id:	24867
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	D00 - Pipe Type - No Piping
	G00 - Tank Secondary Containment - None
	A00 - Tank Internal Protection - None
	H00 - Tank Leak Detection - None
	B00 - Tank External Protection - None
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

665-7-9 9TH AVE (Continued)

U003392559

Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-200190
SWIS Code: 6201
Operator: MANNY CAPPAS
Facility Phone: (212) 874-1882
Facility Addr2: 665 9TH AVE
Facility Type: Not reported
Emergency: LEONARD FRANZBLAU
Emergency Tel: (212) 874-1882
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: LEONARD FRANZBLAU-PIONEER MGT
Owner Address: 27 WEST 72ND STREET
Owner City,St,Zip: NEW YORK, NY 10023
Federal ID: Not reported
Owner Tel: (212) 874-1882
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: LEONARD FRANZBLAU-PIONEER MGT
Mailing Address: 27 WEST 72ND STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10023
Mailing Telephone: (212) 874-1882
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/10/1997
Expiration: 10/23/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

665-7-9 9TH AVE (Continued)

U003392559

Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BC330
NNW
1/8-1/4
0.190 mi.
1001 ft.

WEST 45TH ST & 10TH AVE
WEST 45TH ST & 10TH AVE
NEW YORK, NY
Site 1 of 4 in cluster BC

NY LTANKS **S100167849**
N/A

Relative:
Lower

LTANKS:

Actual:
30 ft.

Site ID: 199072
Spill Number/Closed Date: 9000492 / 8/2/1993
Spill Date: 4/14/1990
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates a file or hazard. DEC Response. Unknown
Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 8/2/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 4/14/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 5/11/1990
Spill Record Last Update: 8/2/1993
Spiller Name: Not reported
Spiller Company: HESS
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 45TH ST & 10TH AVE (Continued)

S100167849

DEC Region: 2
DER Facility ID: 165686
DEC Memo: Not reported
Remarks: TANK LEAKING, GAS ODOR IN WATER, LEAKING TO TRACKS BELOW, SAMPLE
TAKEN OF WATER, DEC TO INVESTIGATE FURTHER.

Material:
Site ID: 199072
Operable Unit ID: 938840
Operable Unit: 01
Material ID: 438876
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

BA331
NE
1/8-1/4
0.190 mi.
1001 ft.

VERIZON LOG 32912 NAHOLE R320
W 46TH ST & 9TH AVE
NEW YORK, NY 10036
Site 3 of 3 in cluster BA

RCRA NonGen / NLR

1014917858
NYP000963058

Relative:
Higher

RCRA NonGen / NLR:

Actual:
41 ft.

Date form received by agency: 04/27/2008
Facility name: VERIZON LOG 32912 NAHOLE R320
Facility address: W 46TH ST & 9TH AVE
NEW YORK, NY 10036
EPA ID: NYP000963058
Mailing address: E 37TH ST 4TH FL
NEW YORK, NY 10016
Contact: MIKE ANGELONE
Contact address: E 37TH ST 4TH FL
NEW YORK, NY 10016
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VERIZON LOG 32912 NAHOLE R320 (Continued)

1014917858

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AV332 L&F REALTY CO
NNE 435 WEST 46TH STREET
1/8-1/4 NEW YORK, NY 10036
0.190 mi.
1002 ft. Site 4 of 10 in cluster AV

NY AST U003389207
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-297054
Program Type: PBS
UTM X: 585136.63011999999
UTM Y: 4512775.7753100004
Expiration Date: 07/14/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 13701
Affiliation Type: Facility Owner
Company Name: L&F REALTY CO
Contact Type: PRESIDENT
Contact Name: ADAM STRYKER
Address1: 225 W 34TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10122
Country Code: 001
Phone: (212) 736-6888
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 6/19/2012

Site Id: 13701
Affiliation Type: Mail Contact
Company Name: L&F REALTY CO
Contact Type: Not reported
Contact Name: Not reported
Address1: 225 W 34TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10122
Country Code: 001
Phone: (212) 736-6888
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L&F REALTY CO (Continued)

U003389207

Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 6/19/2012

Site Id: 13701
Affiliation Type: On-Site Operator
Company Name: L&F REALTY CO
Contact Type: Not reported
Contact Name: ISMET KOLENOVIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-8789
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13701
Affiliation Type: Emergency Contact
Company Name: L&F REALTY CO
Contact Type: Not reported
Contact Name: ALFRED S FRIEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-6888
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 15433
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L&F REALTY CO (Continued)

U003389207

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1901
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 06/07/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-297054
SWIS Code: 6201
Operator: ISMET KOLENOVIC
Facility Phone: (212) 265-8789
Facility Addr2: 435 WEST 46TH STREET
Facility Type: APARTMENT BUILDING
Emergency: ALFRED S FRIEDMAN
Emergency Tel: (212) 736-6888
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: L&F REALTY CO
Owner Address: 225 W 34TH STREET
Owner City,St,Zip: NEW YORK, NY 10001
Federal ID: Not reported
Owner Tel: (212) 736-6888
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: L&F REALTY CO
Mailing Address: 225 W 34TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10001
Mailing Telephone: (212) 736-6888
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 07/10/1997
Expiration: 07/14/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L&F REALTY CO (Continued)

U003389207

Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BD333
ENE
1/8-1/4
0.190 mi.
1004 ft.
CON EDISON
342 W 45 ST
NEW YORK, NY 10036
Site 1 of 6 in cluster BD

NY MANIFEST **S112210720**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269106
Country: USA

Actual:
40 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210720

Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269106
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457220JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269106
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457220JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210720

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BC334
NNW
1/8-1/4
0.191 mi.
1009 ft.

637 10TH AVE
NEW YORK, NY 10036
Site 2 of 4 in cluster BC

EDR US Hist Auto Stat 1015586295
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: CALL 24 HR TOW & REPAIR
Year: 2011
Address: 637 10TH AVE

Actual:
30 ft.

AV335
NNE
1/8-1/4
0.191 mi.
1011 ft.

439 WEST 46TH ST
439 WEST 46TH ST
NEW YORK, NY 10036
Site 5 of 10 in cluster AV

NY AST U003384415
NY HIST AST N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-100080
Program Type: PBS
UTM X: 585127.28653000004
UTM Y: 4512780.7748100003
Expiration Date: 03/11/2017
Site Type: Apartment Building/Office Building

Actual:
38 ft.

Affiliation Records:

Site Id: 3018
Affiliation Type: Facility Owner
Company Name: GONEDES FAMILY&LIMITED PARTNER% KIZNER ASSOC. INC.
Contact Type: MANAGING AGENT
Contact Name: JOSEPH KIZNER
Address1: 133 W. 72ND ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 873-0368
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 10/4/2012

Site Id: 3018
Affiliation Type: Mail Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

439 WEST 46TH ST (Continued)

U003384415

Company Name: KIZNER MGMT
Contact Type: Not reported
Contact Name: JOSPEH KIZNER
Address1: 133 W. 72ND ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 873-0368
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 10/4/2012

Site Id: 3018
Affiliation Type: On-Site Operator
Company Name: 439 WEST 46TH ST
Contact Type: Not reported
Contact Name: TED GONEDES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 265-5790
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 3018
Affiliation Type: Emergency Contact
Company Name: GONEDES FAMILY&LIMITED PARTNER% KIZNER ASSOC. INC.
Contact Type: Not reported
Contact Name: JOSEPH KIZNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 873-0368
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 10/4/2012

Tank Info:

Tank Number: 001
Tank Id: 3742
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

439 WEST 46TH ST (Continued)

U003384415

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1910
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 10/04/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-100080
SWIS Code: 6201
Operator: MULLEN & WOODS INC
Facility Phone: (212) 265-5790
Facility Addr2: 439 WEST 46TH ST
Facility Type: APARTMENT BUILDING
Emergency: M. UHL C/O MULLEN & WOODS
Emergency Tel: (212) 265-5790
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: THEODORE GONEDES
Owner Address: 86-15 PALOALTO STREET
Owner City,St,Zip: HOLLIS, NY 11423
Federal ID: Not reported
Owner Tel: (718) 465-6333
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: MARILYN UHL
Mailing Name: MULLEN & WOODS INC.
Mailing Address: 449 WEST 51ST STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10019
Mailing Telephone: (212) 265-5790
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

439 WEST 46TH ST (Continued)

U003384415

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 02/06/1997
Expiration: 03/24/2002
Renew Flag: False
Renew Date: 11/13/2001
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BE336 **AVIS RENT A CAR SYSTEM LLC**
NW **515 WEST 43RD STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.192 mi.
1012 ft. **Site 1 of 5 in cluster BE**

NY UST **U004046057**
N/A

Relative: UST:
Lower Id/Status: 2-609962 / Active
Program Type: PBS
Actual: Region: STATE
19 ft. DEC Region: 2
Expiration Date: 06/15/2015

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM LLC (Continued)

U004046057

UTM X: 584753.59065999999
UTM Y: 4512680.4002400003
Site Type: Other

Affiliation Records:

Site Id: 347728
Affiliation Type: Facility Owner
Company Name: NKM PROSCIA LLC % NICHOLAS PROSCIA
Contact Type: SENIOR VICE PRESIDENT
Contact Name: ROBERT BOUTA
Address1: 785 TOTOWA RD., SUITE 2
Address2: Not reported
City: TOTOWA
State: NJ
Zip Code: 07512
Country Code: 001
Phone: (999) 999-9999
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/14/2013

Site Id: 347728
Affiliation Type: Mail Contact
Company Name: AVIS RENT A CAR SYSTEM LLC
Contact Type: Not reported
Contact Name: MICHAEL FEELEY
Address1: 6 SYLVAN WAY
Address2: DEPT. 29-C93-36
City: PARSIPPANY
State: NJ
Zip Code: 07054
Country Code: 001
Phone: (973) 496-3467
EMail: MICHAEL.FEELEY@AVISBUDET.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/14/2013

Site Id: 347728
Affiliation Type: On-Site Operator
Company Name: AVIS RENT A CAR SYSTEM LLC
Contact Type: Not reported
Contact Name: JOHN BORUCINSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 593-8469
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/14/2013

Site Id: 347728
Affiliation Type: Emergency Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS RENT A CAR SYSTEM LLC (Continued)

U004046057

Company Name: NKM PROSCIA LLC % NICHOLAS PROSCIA
Contact Type: Not reported
Contact Name: ROSE PELINO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (866) 305-7750
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/14/2013

Tank Info:

Tank Number: 1
Tank ID: 206856
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 06/01/2005
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 06/18/2013

Equipment Records:

A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
L99 - Piping Leak Detection - Other
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BB337 **309 W 43 ST**
ESE **309 W 43RD ST**
1/8-1/4 **NYC, NY 10036**
0.192 mi.
1015 ft. **Site 4 of 5 in cluster BB**

NY AST **U003392170**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-218502
Program Type: PBS
UTM X: 585325.42289000005
UTM Y: 4512399.2582200002
Expiration Date: 08/23/2013
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 8326
Affiliation Type: Facility Owner
Company Name: FASHION WEAR REALTY CO
Contact Type: VICE PRESIDENT
Contact Name: MICHAEL J. COLANDRA
Address1: 70 E 55TH ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 755-6556
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/25/2008

Site Id: 8326
Affiliation Type: Mail Contact
Company Name: FASHION WEAR REALTY CO
Contact Type: Not reported
Contact Name: MICHAEL J. COLANDRA
Address1: 70 E. 55TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 755-6556
EMail: THM@THMNY.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 7/18/2013

Site Id: 8326
Affiliation Type: On-Site Operator
Company Name: 309 W 43 ST
Contact Type: Not reported
Contact Name: BEATRICE ROSADO
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

309 W 43 ST (Continued)

U003392170

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 581-5902
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8326
Affiliation Type: Emergency Contact
Company Name: FASHION WEAR REALTY CO
Contact Type: Not reported
Contact Name: BAYSIDE FUEL OIL CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 946-4000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 23960
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1920
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/24/2011
Register: True
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

309 W 43 ST (Continued)

U003392170

Last Modified: 07/18/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-218502
SWIS Code: 6201
Operator: BEATRICE ROSADO
Facility Phone: (212) 581-5902
Facility Addr2: 309 W 43RD ST
Facility Type: APARTMENT BUILDING
Emergency: BAYSIDE FUEL OIL CORP
Emergency Tel: (718) 946-4000
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: FASHION WEAR REALTY CO
Owner Address: 432 EAST 87TH STREET
Owner City,St,Zip: NYC, NY 10128
Federal ID: Not reported
Owner Tel: (212) 722-3313
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: FASHION WEAR REALTY CO
Mailing Address: 435 EAST 86TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10028
Mailing Telephone: (212) 722-3313
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 06/29/1998
Expiration: 08/23/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

309 W 43 ST (Continued)

U003392170

Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BD338
ENE
1/8-1/4
0.194 mi.
1023 ft.

TANK TEST FAILURE TTF
341 W 45TH ST
NEW YORK, NY
Site 2 of 6 in cluster BD

NY LTANKS **S110762231**
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:
Site ID: 443215
Spill Number/Closed Date: 1009654 / 1/13/2011
Spill Date: 12/10/2010
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: BKFALVEY
Referred To: Not reported
Reported to Dept: 12/10/2010
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/10/2010
Spill Record Last Update: 1/13/2011
Spiller Name: Not reported
Spiller Company: SHERRINGTON HOLDINGS LLC
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: SOFIA RUSZCZYK
Spiller Phone: 212 686 5588
Spiller Extention: Not reported
DEC Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TANK TEST FAILURE TTF (Continued)

S110762231

DER Facility ID: 398165
DEC Memo: 1/13/11 Received letter from Protest. Tank failed because of vent line. Repairs made. No contamination found. Passing ttt report dated 1/4/11 was attached. bf
Remarks: Tank test Failure. Caller advised it is a dry leak.

Material:
Site ID: 443215
Operable Unit ID: 1193687
Operable Unit: 01
Material ID: 2189150
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

BD339 341 WEST 45TH STREET
ENE 341 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.194 mi.
1023 ft. Site 3 of 6 in cluster BD

NY AST U003397165
NY HIST AST N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603432
Program Type: PBS
UTM X: 585325.93027999997
UTM Y: 4512582.4475600002
Expiration Date: 11/07/2017
Site Type: Apartment Building/Office Building

Actual:
40 ft.

Affiliation Records:
Site Id: 25349
Affiliation Type: Mail Contact
Company Name: GATSBY ENTERPRISES, LLC
Contact Type: Not reported
Contact Name: STEPHANIE SUAZO
Address1: 347 FIFTH AVENUE
Address2: SUITE 300
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-5588
EMail: MAINTENANCE@GATSBY.NET
Fax Number: Not reported
Modified By: KAKYER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

341 WEST 45TH STREET (Continued)

U003397165

Date Last Modified: 3/12/2013

Site Id: 25349
Affiliation Type: On-Site Operator
Company Name: SHERRINGTON HOLDING, LLC
Contact Type: Not reported
Contact Name: SAMMY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 996-7513
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/15/2005

Site Id: 25349
Affiliation Type: Emergency Contact
Company Name: SHERRINGTON HOLDINGS, LLC
Contact Type: Not reported
Contact Name: ALEX CRUZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 392-0251
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 9/24/2007

Site Id: 25349
Affiliation Type: Facility Owner
Company Name: SHERRINGTON HOLDINGS, LLC
Contact Type: MEMBER
Contact Name: LISA SHALOM
Address1: 347 FIFTH AVENUE SUITE 300
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 686-5588
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 9/24/2007

Tank Info:

Tank Number: 001
Tank Id: 54254

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

341 WEST 45TH STREET (Continued)

U003397165

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/01/1990
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 03/12/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-603432
SWIS Code: 6201
Operator: SAMMY MEZA
Facility Phone: (212) 262-6576
Facility Addr2: 341 WEST 45TH STREET
Facility Type: Not reported
Emergency: SAMMY MEZA
Emergency Tel: (212) 262-6576
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: WEST 45TH ASSOCIATES L.P.
Owner Address: 130 EAST 57TH STREET
Owner City,St,Zip: NEW YORK, NY 10022
Federal ID: Not reported
Owner Tel: (212) 610-2800
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: P.M.G.
Mailing Name: P.M.G MANAGEMENT
Mailing Address: 130 EAST 57TH STREET
Mailing Address 2: 5TH FLOOR
Mailing City,St,Zip: NEW YORK, NY 10022

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

341 WEST 45TH STREET (Continued)

U003397165

Mailing Telephone: (212) 610-2800
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/27/1999
Expiration: 04/15/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Not reported
Leak Detection: 00
Overfill Protection: Not reported
Dispenser Method: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BC340 **640 10TH ASSOC**
NNW **642 10TH AVE**
1/8-1/4 **NEW YORK, NY 10036**
0.196 mi.
1036 ft. **Site 3 of 4 in cluster BC**

NY AST **U003388742**
NY HIST AST **N/A**

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-279897
Program Type: PBS
UTM X: 584967.43871999998
UTM Y: 4512821.23744999999
Expiration Date: 07/14/1997
Site Type: Apartment Building/Office Building

Actual:
29 ft.

Affiliation Records:

Site Id: 12203
Affiliation Type: Facility Owner
Company Name: 640 TENTH AVENUE ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 425 E 61TH STREET - 5TH FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 249-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12203
Affiliation Type: Mail Contact
Company Name: 640 TENTH AVENUE ASSOCIATES
Contact Type: Not reported
Contact Name: ELAINE DE GUZMAN
Address1: 425 E 61TH STREET - 5TH FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 308-0030
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12203
Affiliation Type: On-Site Operator
Company Name: 640 10TH ASSOC
Contact Type: Not reported
Contact Name: KAYVAN HAKIM
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

640 10TH ASSOC (Continued)

U003388742

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 750-8200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 12203
Affiliation Type: Emergency Contact
Company Name: 640 TENTH AVENUE ASSOCIATES
Contact Type: Not reported
Contact Name: KAYVAN HAKIM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 750-8200
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 14536
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

640 10TH ASSOC (Continued)

U003388742

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-279897
SWIS Code: 6201
Operator: KAYVAN HAKIM
Facility Phone: (212) 750-8200
Facility Addr2: 642 10TH AVE
Facility Type: APARTMENT BUILDING
Emergency: KAYVAN HAKIM
Emergency Tel: (212) 750-8200
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 640 TENTH AVENUE ASSOCIATES
Owner Address: 425 E 61TH STREET - 5TH FLOOR
Owner City,St,Zip: NY, NY 10021
Federal ID: Not reported
Owner Tel: (212) 249-9500
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: ELAINE DE GUZMAN
Mailing Name: 640 TENTH AVENUE ASSOCIATES
Mailing Address: 425 E 61TH STREET - 5TH FLOOR
Mailing Address 2: Not reported
Mailing City,St,Zip: NY, NY 10021
Mailing Telephone: (212) 308-0030
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/10/1993
Expiration: 07/14/1997
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

640 10TH ASSOC (Continued)

U003388742

Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

AV341 LEERO REALTY, LLC
NNE 425 WEST 46TH STREET
1/8-1/4 NEW YORK, NY 10036
0.197 mi.
1038 ft. Site 6 of 10 in cluster AV

NY AST A100173565
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-604786
Program Type: PBS
UTM X: 585160.15668000001
UTM Y: 4512763.3895500004
Expiration Date: 11/06/2015
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 26655
Affiliation Type: Facility Owner
Company Name: LEERO REALTY, LLC
Contact Type: AGENT
Contact Name: ARTHUR LEEDS
Address1: 215 WEST 83RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 9/22/2005

Site Id: 26655
Affiliation Type: Mail Contact
Company Name: LEERO REALTY, LLC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEERO REALTY, LLC (Continued)

A100173565

Contact Type: Not reported
Contact Name: Not reported
Address1: 215 WEST 83RD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 26655
Affiliation Type: On-Site Operator
Company Name: LEERO REALTY, LLC
Contact Type: Not reported
Contact Name: RAMON SORIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 26655
Affiliation Type: Emergency Contact
Company Name: LEERO REALTY, LLC
Contact Type: Not reported
Contact Name: ARTHUR LEEDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 58879
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEERO REALTY, LLC (Continued)

A100173565

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/1967
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AV342 **LEERO REALTY CO**
NNE **425 W 46TH ST**
1/8-1/4 **NEW YORK, NY 10036**
0.197 mi.
1038 ft. **Site 7 of 10 in cluster AV**

NY AST **U004047402**
N/A

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-235687
Program Type: PBS
UTM X: 585160.15668000001
UTM Y: 4512763.3895500004
Expiration Date: 07/10/1992
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 8695
Affiliation Type: Facility Owner
Company Name: LEERO REALTY CO
Contact Type: Not reported
Contact Name: Not reported
Address1: 215 W 83RD ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEERO REALTY CO (Continued)

U004047402

Date Last Modified: 3/4/2004

Site Id: 8695
Affiliation Type: Mail Contact
Company Name: LEERO REALTY CO
Contact Type: Not reported
Contact Name: Not reported
Address1: 215 W 83RD ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8695
Affiliation Type: On-Site Operator
Company Name: LEERO REALTY CO
Contact Type: Not reported
Contact Name: RAMON SORIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8695
Affiliation Type: Emergency Contact
Company Name: LEERO REALTY CO
Contact Type: Not reported
Contact Name: ARTHUR LEEDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 874-6400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 12642

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEERO REALTY CO (Continued)

U004047402

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 07/01/1967
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

AV343
NNE
1/8-1/4
0.197 mi.
1038 ft.

CON EDISON
F/O 425 WEST 46TH ST
NEW YORK, NY 10036

Site 8 of 10 in cluster AV

NY MANIFEST S116292663
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004437752
Country: USA

Actual:
38 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PLACE
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 2014-02-08
Trans1 Recv Date: 2014-02-08
Trans2 Recv Date: 2014-02-10
TSD Site Recv Date: 2014-02-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116292663

Generator EPA ID: NYP004437752
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002329851GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

AV344
NNE
1/8-1/4
0.197 mi.
1038 ft.
CON EDISON
F/O 425 W 46 ST & 9TH AVE
NEW YORK, NY 10036
Site 9 of 10 in cluster AV

NY MANIFEST **S112210719**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269098
Country: USA

Actual:
38 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269098
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210719

Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457177JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269098
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457177JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AV345
NNE
1/8-1/4
0.197 mi.
1038 ft.

CON EDISON SERVICE BOX: 8863
425 W 46TH & 9TH AVE FRONT OF
NEW YORK, NY 10036
Site 10 of 10 in cluster AV

RCRA-CESQG
FINDS
1016144121
NYP004269098

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/18/2012

Facility name: CON EDISON SERVICE BOX: 8863

Facility address: 425 W 46TH & 9TH AVE FRONT OF

NEW YORK, NY 10036

EPA ID: NYP004269098

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JOSE MONTALVO

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (212) 427-1331

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461156

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8863 (Continued)

1016144121

Environmental Interest/Information System

BF346
NW
1/8-1/4
0.197 mi.
1041 ft.

514 W 44TH ST
NEW YORK, NY 10036

EDR US Hist Auto Stat **1015533673**
N/A

Site 1 of 10 in cluster BF

Relative:
Lower

EDR Historical Auto Stations:

Name: KOTLER AUTO SPRINGS INCORPORATED
Year: 1999

Actual:
19 ft.

Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS INCORPORATED
Year: 2000
Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS
Year: 2003
Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS INC
Year: 2004
Address: 514 W 44TH ST

Name: I ROSENBERG AUTO REPAIRS INC
Year: 2006
Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS INC
Year: 2007
Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS INC
Year: 2008
Address: 514 W 44TH ST

Name: ROSENBERG IRVING AUTO REPAIR INC
Year: 2009
Address: 514 W 44TH ST

Name: KOTLER AUTO SPRINGS INC
Year: 2010
Address: 514 W 44TH ST

BF347
NW
1/8-1/4
0.197 mi.
1041 ft.

STYLE MGMT CO
514-518 WEST 44TH STREET
NEW YORK, NY 10036

NY AST **A100361250**
N/A

Site 2 of 10 in cluster BF

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611830

Actual:
19 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STYLE MGMT CO (Continued)

A100361250

Program Type: PBS
UTM X: Not reported
UTM Y: Not reported
Expiration Date: 05/29/2017
Site Type: Other

Affiliation Records:

Site Id: 464698
Affiliation Type: Facility Owner
Company Name: ANDREW ROSENBERG
Contact Type: Not reported
Contact Name: Not reported
Address1: 7 RIDGEVIEW CIRCLE
Address2: Not reported
City: ARMONK
State: NY
Zip Code: 10504
Country Code: 001
Phone: (917) 434-4277
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/29/2012

Site Id: 464698
Affiliation Type: Mail Contact
Company Name: STYLE MGMT CO
Contact Type: Not reported
Contact Name: ANDREW ROSENBERG
Address1: 514-518 WEST 44TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 279-3166
EMail: STYLEMGMT@AOL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/29/2012

Site Id: 464698
Affiliation Type: On-Site Operator
Company Name: STYLE MGMT CO
Contact Type: Not reported
Contact Name: ANDREW ROSENBERG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 279-3166
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/29/2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STYLE MGMT CO (Continued)

A100361250

Site Id: 464698
Affiliation Type: Emergency Contact
Company Name: ANDREW ROSENBERG
Contact Type: Not reported
Contact Name: ANDREW ROSENBERG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 434-4277
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/29/2012

Tank Info:

Tank Number: 001
Tank Id: 244239
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E01 - Piping Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/02/2010
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 05/29/2012
Material Name: Waste Oil/Used Oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
BG348 South 1/8-1/4 0.197 mi. 1042 ft.	359 W 39TH ST NEW YORK, NY 10018 Site 1 of 3 in cluster BG	EDR US Hist Cleaners	1015048935 N/A
Relative: Higher	EDR Historical Cleaners: Name: YEES EXCELLENT CLEANERS Year: 2005 Address: 359 W 39TH ST Name: YEES EXCELLENT CLEANERS Year: 2010 Address: 359 W 39TH ST Name: YEES EXCELLENT CLEANERS Year: 2011 Address: 359 W 39TH ST Name: YEES EXCELLENT CLEANERS Year: 2012 Address: 359 W 39TH ST		
Actual: 35 ft.			
BF349 NW 1/8-1/4 0.198 mi. 1043 ft.	NYC DEPT OF ED - PUBLIC SCHOOL 51M 515-533 WEST 44TH STREET NEW YORK, NY 11101 Site 3 of 10 in cluster BF	NY MANIFEST	S112141318 N/A
Relative: Lower	NY MANIFEST: EPA ID: NYR000182394 Country: USA		
Actual: 19 ft.	Mailing Info: Name: NYC DEPT OF ED - PUBLIC SCHOOL 51M Contact: NATHANEIL UMANA Address: 30-30 THOMSON AVE City/State/Zip: LONG ISLAND CITY, NY 11101 Country: USA Phone: 908-322-3000		
	NY MANIFEST: No Manifest Records Available		
BF350 NW 1/8-1/4 0.198 mi. 1046 ft.	PUBLIC SCHOOL 51M 515-533 W 44TH ST NEW YORK, NY 11101 Site 4 of 10 in cluster BF	RCRA-LQG	1014473127 NYR000182394
Relative: Lower	RCRA-LQG: Date form received by agency: 02/17/2012 Facility name: PUBLIC SCHOOL 51M Facility address: 515-533 W 44TH ST NEW YORK, NY 11101 EPA ID: NYR000182394 Mailing address: THOMSON AVE LONG ISLAND CITY, NY 11101		
Actual: 19 ft.			

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC SCHOOL 51M (Continued)

1014473127

Contact: ALEXANDER LEMPert
Contact address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (718) 472-8501
Contact email: ALEMPERT@NYCSCA.ORG
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: NEW YORK CITY DEPT OF SCHOOL FACILITIES
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 07/23/2010
Owner/Op end date: Not reported

Owner/operator name: NYC DEPT OF ED
Owner/operator address: VERNON BLVD
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2011
Owner/Op end date: Not reported

Owner/operator name: NYC DEPT OF ED
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2011
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY DEPT OF EDUCATION
Owner/operator address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 472-8501

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC SCHOOL 51M (Continued)

1014473127

Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 07/23/2010
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 05/16/2011
Site name: NYC DEPT OF ED - PUBLIC SCHOOL 51M
Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Waste code: D008
Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 6781600

Violation Status: No violations found

AZ351 **AMERICAN RED CROSS EMERGENCY FAM. CENTER**
West **515 WEST 41ST STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.198 mi.
1048 ft. **Site 4 of 4 in cluster AZ**

NY AST **U004078086**
N/A

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-407216
Program Type: PBS

Actual:
19 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERICAN RED CROSS EMERGENCY FAM. CENTER (Continued)

U004078086

UTM X: 584748.71872
UTM Y: 4512517.8662400004
Expiration Date: 12/14/2007
Site Type: Other

Affiliation Records:

Site Id: 19703
Affiliation Type: Facility Owner
Company Name: FICO REALTY
Contact Type: Not reported
Contact Name: Not reported
Address1: C/O WELLINGTON HOTEL 871 7TH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 714-2870
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19703
Affiliation Type: Mail Contact
Company Name: AMERICAN RED CROSS
Contact Type: Not reported
Contact Name: CHAPTER DIRECTOR
Address1: 515 WEST 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 714-2870
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19703
Affiliation Type: On-Site Operator
Company Name: AMERICAN RED CROSS EMERGENCY FAM. CENTER
Contact Type: Not reported
Contact Name: AMERICAN RED CROSS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 714-2870
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19703

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERICAN RED CROSS EMERGENCY FAM. CENTER (Continued)

U004078086

Affiliation Type: Emergency Contact
Company Name: FICO REALTY
Contact Type: Not reported
Contact Name: HERMINE E. BOWENS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 714-2870
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 23251
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H04 - Tank Leak Detection - Groundwater Well

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BH352
SSW
1/8-1/4
0.199 mi.
1053 ft.
509 9TH AVE
509 NINTH AVENUE
NEW YORK, NY 10018
Site 1 of 8 in cluster BH

NY TANKS
S116349302
N/A

Relative:
Higher
Actual:
32 ft.
TANKS:
Facility Id: 2-607712
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2017-04-29
UTM X: 584881.56834
UTM Y: 4512164.7255699998

BI353
East
1/8-1/4
0.199 mi.
1053 ft.
CON ED - V 0989
315 W 44 ST
NEW YORK, NY 10036
Site 1 of 8 in cluster BI

RCRA NonGen / NLR
NY MANIFEST
1007206147
NYP004004511

Relative:
Higher
Actual:
41 ft.
RCRA NonGen / NLR:
Date form received by agency: 02/28/1998
Facility name: CON ED - V 0989
Facility address: 315 W 44 ST
NEW YORK, NY 100360000
EPA ID: NYP004004511
Mailing address: CONSOLIDATED EDISON INC
4 IRVING PL RM 310
NEW YORK, NY 100030000
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 100030000
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 0989 (Continued)

1007206147

Historical Generators:

Date form received by agency: 02/27/1998
Site name: CON ED - V 0989
Classification: Not a generator, verified

Date form received by agency: 02/26/1998
Site name: CON ED - V 0989
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004004511
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYB8467407
Manifest Status: Completed copy
Trans1 State ID: 6X3216
Trans2 State ID: Not reported
Generator Ship Date: 970130
Trans1 Recv Date: 970130
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970130
Part A Recv Date: 970219
Part B Recv Date: 970211
Generator EPA ID: NYP004004511
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSD ID: NYD980593636
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 01287
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

BE354 **NY PUBLIC LIBRARY - 43RD ST ANNEX**
NW **521 W 43RD ST**
1/8-1/4 **NEW YORK, NY 10036**
0.199 mi.
1053 ft. **Site 2 of 5 in cluster BE**

RCRA-SQG **1005417374**
FINDS **NYR000105007**
NY MANIFEST

Relative:
Lower

RCRA-SQG:
Date form received by agency: 02/01/2013
Facility name: NYC DEPT OF EDUCATION - BEACON HS M912
Facility address: 521 W 43RD ST
NEW YORK, NY 10036

Actual:
19 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

EPA ID: NYR000105007
Mailing address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact: ALEXANDER LEMPERT
Contact address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Contact country: US
Contact telephone: (718) 472-8501
Contact email: ALEMPERT@NYCSCA.ORG
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: NYC DEPT OF SCHOOL FACILITIES
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 08/17/2011
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW YORK
Owner/operator address: UNKNOWN
NEW YORK, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: CITY OF NEW YORK
Owner/operator address: UNKNOWN
NEW YORK, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: NYC DEPT OF EDUCATION
Owner/operator address: THOMSON AVE
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: (718) 472-8501
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 08/17/2011
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2007
Site name: NEW YORK PUBLIC LIBRARY ANNEX
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: NEW YORK PUBLIC LIBRARY ANNEX
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/28/2002
Site name: NEW YORK PUBLIC LIBRARY ANNEX
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: B004
Waste name: B004

Waste code: B007
Waste name: B007

Violation Status: No violations found

FINDS:

Registry ID: 110019739675

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID: NYR000105007
Country: USA

Mailing Info:

Name: NEW YORK PUBLIC LIBRARY
Contact: TOM NOLAN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Address: 188 MADISON AVE
City/State/Zip: NEW YORK, NY 10016
Country: USA
Phone: 212-592-7360

Document ID: 06
Manifest Status: CTF1030318
Trans1 State ID: NYR000105007
Trans2 State ID: Not reported
Generator Ship Date: CT5000001495
Trans1 Recv Date: Not reported
Trans2 Recv Date: CT5000001495
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DM
Container Type: 1031
Handling Method: P
Specific Gravity: 1
Waste Code: R
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 100002465CTN
Trans1 State ID: NYR000105007
Trans2 State ID: Not reported
Generator Ship Date: CT5000001495
Trans1 Recv Date: Not reported
Trans2 Recv Date: CT5000001495
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DM
Container Type: 800
Handling Method: P

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Specific Gravity: 1
Waste Code: R
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: CTF1030253
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 06/29/2005
Trans1 Recv Date: 06/29/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/30/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 01031
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2005

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-08
Trans1 Recv Date: 2009-04-08
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Manifest Tracking Num: 100016178CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 8/7/2007
Trans1 Recv Date: 8/7/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/7/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 700
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 100002436CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 6/6/2007
Trans1 Recv Date: 6/6/2007
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

TSD Site Recv Date: 6/7/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: CT5000001495
Waste Code: Not reported
Quantity: 800
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 100002465CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-08
Trans1 Recv Date: 2009-04-08
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: CT5000001495
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 100016178CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2008-04-15
Trans1 Recv Date: 2008-04-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-04-16
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 100002354CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-08
Trans1 Recv Date: 2009-04-08
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

TSD ID: CT5000001495
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 100016178CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2010-04-15
Trans1 Recv Date: 2010-04-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: CT5000001495
Waste Code: Not reported
Quantity: 600.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006572587JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Document ID: CTF1030318
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 01/12/2006
Trans1 Recv Date: 01/12/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/12/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: CT232492
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 01031
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2006

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2008-04-15
Trans1 Recv Date: 2008-04-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-04-16
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 1200.0
Units: P - Pounds
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 100002354CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2011-08-30
Trans1 Recv Date: 2011-08-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-08-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 527.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 006572875JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: CTF1030253
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 06/29/2005
Trans1 Recv Date: 06/29/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/30/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 01031
Units: P - Pounds
Number of Containers: 002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYH0241866
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 04/14/2002
Trans1 Recv Date: 04/14/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: 23138PA
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00012
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYH0268875
Manifest Status: Not reported
Trans1 State ID: NYD082785429
Trans2 State ID: Not reported
Generator Ship Date: 04/14/2002
Trans1 Recv Date: 04/14/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: 23138PA
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2007-08-07
Trans1 Recv Date: 2007-08-07
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-08-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 700.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 100002436CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Trans2 State ID: Not reported
Generator Ship Date: 2007-06-06
Trans1 Recv Date: 2007-06-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-06-07
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 800.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 100002465CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

Document ID: CTF1030318
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 01/12/2006
Trans1 Recv Date: 01/12/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/12/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: CT232492
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 01031
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NY PUBLIC LIBRARY - 43RD ST ANNEX (Continued)

1005417374

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CT5000001495
Trans2 State ID: Not reported
Generator Ship Date: 2009-09-30
Trans1 Recv Date: 2009-09-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-09-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000105007
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CT5000001495
Waste Code: Not reported
Quantity: 700.0
Units: P - Pounds
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 100016489CTN
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H010

[Click this hyperlink](#) while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

BE355 **BEACON HIGH SCHOOL**
NW **521 WEST 43RD STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.199 mi.
1053 ft.

NY AST **U004077851**
N/A

Site 3 of 5 in cluster BE

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-456985
Program Type: PBS
UTM X: 584824.31339999998
UTM Y: 4512669.4971399996
Expiration Date: 08/17/2016
Site Type: Other

Actual:
19 ft.

Affiliation Records:
Site Id: 20171
Affiliation Type: Mail Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEACON HIGH SCHOOL (Continued)

U004077851

Company Name: NYC SCHOOL CONSTRUCTION AUTHORITY
Contact Type: Not reported
Contact Name: ALEXANDER LEMPERT
Address1: IEH DIVISION
Address2: 30-30 THOMSON AVENUE
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 472-8502
EMail: ALEMPERT@NYCSCA.ORG
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/14/2013

Site Id: 20171
Affiliation Type: On-Site Operator
Company Name: BEASON HIGH SCHOOL
Contact Type: Not reported
Contact Name: N Y P L
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 714-8519
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/2/2013

Site Id: 20171
Affiliation Type: Emergency Contact
Company Name: NYC SCHOOLS CONSTR. AUTHORITY
Contact Type: Not reported
Contact Name: SECURITY-N Y P L
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 930-0513
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/2/2013

Site Id: 20171
Affiliation Type: Facility Owner
Company Name: NYC SCHOOL CONSTRUCTION AUTHORITY
Contact Type: Not reported
Contact Name: Not reported
Address1: 30-30 THOMSON AVE
Address2: Not reported
City: LONG ISLAND CITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEACON HIGH SCHOOL (Continued)

U004077851

State: NY
Zip Code: 11101
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/2/2013

Tank Info:

Tank Number: 001
Tank Id: 36770
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1988
Capacity Gallons: 1400
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/05/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 11/14/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 57978
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BEACON HIGH SCHOOL (Continued)

U004077851

L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1988
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/05/2012
Register: True
Modified By: NRLOMBAR
Last Modified: 11/14/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

**AW356
WNW
1/8-1/4
0.200 mi.
1054 ft.**

**THE ARMORY OWNERS, INC.
529-543 WEST 42 STREET
NEW YORK, NY 10036
Site 4 of 4 in cluster AW**

**NY AST U004048472
N/A**

**Relative:
Lower**

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608680
Program Type: PBS
UTM X: 584724.11085000006
UTM Y: 4512600.7932900004
Expiration Date: 03/27/2018
Site Type: Private Residence

Affiliation Records:

Site Id: 30532
Affiliation Type: Facility Owner
Company Name: THE ARMORY OWNERS, INC.
Contact Type: PROPERTY MGR
Contact Name: BRIAN RAFFERTY
Address1: 529-543 WEST 42 STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 268-0952
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/25/2013

Site Id: 30532
Affiliation Type: Mail Contact
Company Name: CENTURY OPERATING CORP.
Contact Type: Not reported
Contact Name: BRIAN RAFFERTY

**Actual:
19 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE ARMORY OWNERS, INC. (Continued)

U004048472

Address1: 7 PENN PLAZA, SUITE 1400
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 560-6400
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 10/15/2008

Site Id: 30532
Affiliation Type: On-Site Operator
Company Name: THE ARMORY OWNERS, INC.
Contact Type: Not reported
Contact Name: FRANCIS MC LOUGHLIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 594-0817
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/25/2013

Site Id: 30532
Affiliation Type: Emergency Contact
Company Name: THE ARMORY OWNERS, INC.
Contact Type: Not reported
Contact Name: BRIAN RAFFERTY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 771-2722
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 10/15/2008

Tank Info:

Tank Number: 001
Tank Id: 65515
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE ARMORY OWNERS, INC. (Continued)

U004048472

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/31/2003
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 65516
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None

1
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/30/2003
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE ARMORY OWNERS, INC. (Continued)

U004048472

Tank Id: 225642
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
G09 - Tank Secondary Containment - Modified Double-Walled
(Aboveground)
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2006
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 08/14/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 004
Tank Id: 225643
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled
(Aboveground)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
I00 - Overfill - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

THE ARMORY OWNERS, INC. (Continued)

U004048472

Pipe Model: Not reported
Install Date: 01/01/2006
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 08/14/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

BH357
SSW
1/8-1/4
0.200 mi.
1057 ft.
506-508 NINTH AVENUE
506/508 NINTH AVENUE
NEW YORK, NY 10018
Site 2 of 8 in cluster BH

NY AST
U003392404
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-365661
Program Type: PBS
UTM X: 584879.37233000004
UTM Y: 4512170.0749700004
Expiration Date: 03/27/2018
Site Type: Apartment Building/Office Building

Actual:
33 ft.

Affiliation Records:

Site Id: 18581
Affiliation Type: Mail Contact
Company Name: TPEC MGMT
Contact Type: Not reported
Contact Name: ANTONINO PECORA
Address1: 506 NINTH AVE., STE #2FN
Address2: Not reported
City: NY
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 643-2616
Email: TPECNY@YAHOO.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2013

Site Id: 18581
Affiliation Type: On-Site Operator
Company Name: 506-508 NINTH AVENUE
Contact Type: Not reported
Contact Name: PEC LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

506-508 NINTH AVENUE (Continued)

U003392404

Phone: (212) 643-2616
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2013

Site Id: 18581
Affiliation Type: Emergency Contact
Company Name: PEC LLC
Contact Type: Not reported
Contact Name: ANTONINO PECORA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 607-4444
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2013

Site Id: 18581
Affiliation Type: Facility Owner
Company Name: PEC LLC
Contact Type: MEMBER
Contact Name: ANTONINO PECORA
Address1: 506 NINTH AVE., STE #2FN
Address2: Not reported
City: NY
State: NY
Zip Code: 10018
Country Code: 001
Phone: (516) 607-4444
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2013

Tank Info:

Tank Number: 001
Tank Id: 24521
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

506-508 NINTH AVENUE (Continued)

U003392404

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1955
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 08/27/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

BJ358
North
1/8-1/4
0.200 mi.
1058 ft.

453 W 46TH ST
NEW YORK, NY 10036

EDR US Hist Cleaners 1015063286
N/A

Site 1 of 6 in cluster BJ

Relative:
Higher

EDR Historical Cleaners:

Name: RAINBOW CLEANERS INC
Year: 2005
Address: 453 W 46TH ST

Actual:
36 ft.

Name: RAINBOW CLEANERS INC
Year: 2007
Address: 453 W 46TH ST

Name: RAINBOW CLEANERS INC
Year: 2008
Address: 453 W 46TH ST

BC359
NNW
1/8-1/4
0.201 mi.
1061 ft.

641 10TH AVE
641 TENTH AVE
NEW YORK, NY 10036

NY AST U003384813
NY HIST AST N/A

Site 4 of 4 in cluster BC

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-095257
Program Type: PBS
UTM X: 584953.68026000005
UTM Y: 4512821.0795799997
Expiration Date: 12/28/2018
Site Type: Apartment Building/Office Building

Actual:
28 ft.

Affiliation Records:

Site Id: 2628

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

641 10TH AVE (Continued)

U003384813

Affiliation Type: Mail Contact
Company Name: 641 TENTH AVENUE LLC
Contact Type: Not reported
Contact Name: PETER GIAIMO
Address1: 643 TENTH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 757-8888
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 10/22/2013

Site Id: 2628
Affiliation Type: On-Site Operator
Company Name: 641 10TH AVE
Contact Type: Not reported
Contact Name: 641 TENTH AVENUE LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 757-8888
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/23/2012

Site Id: 2628
Affiliation Type: Emergency Contact
Company Name: 641 TENTH AVENUE LLC
Contact Type: Not reported
Contact Name: J NIEVES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 489-4854
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/23/2012

Site Id: 2628
Affiliation Type: Facility Owner
Company Name: 641 TENTH AVENUE LLC
Contact Type: PRESIDENT
Contact Name: PETER GIAIMO
Address1: 643 TENTH AVENUE
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

641 10TH AVE (Continued)

U003384813

City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 757-8888
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 10/22/2013

Tank Info:

Tank Number: 001
Tank Id: 4512
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
L00 - Piping Leak Detection - None

3
Tank Location: Steel/Carbon Steel/Iron
Tank Type: In Service
Tank Status: Not reported
Pipe Model: 10/05/1950
Install Date: 2000
Capacity Gallons: NN
Tightness Test Method: Not reported
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 10/22/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-095257
SWIS Code: 6201
Operator: 794 DIST CORP
Facility Phone: (212) 757-8888
Facility Addr2: 641 10TH AVE
Facility Type: APARTMENT BUILDING
Emergency: J NIEVES
Emergency Tel: (212) 489-4854
Old PBSNO: Not reported
Date Inspected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

641 10TH AVE (Continued)

U003384813

Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 794 DIST CORP
Owner Address: 643 10TH AVE
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 757-8888
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: 794 DIST CORP
Mailing Address: 643 10TH AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 757-8888
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/13/1997
Expiration: 05/07/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Vault (w/access)
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

641 10TH AVE (Continued)

U003384813

Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BJ360
North
1/8-1/4
0.201 mi.
1061 ft.

449 W46TH STREET
449 W46TH STREET
NEW YORK, NY 10036

NY AST A100307817
N/A

Site 2 of 6 in cluster BJ

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610650
Program Type: PBS
UTM X: 585041.26144999999
UTM Y: 4512800.2709600003
Expiration Date: 08/30/2016
Site Type: Apartment Building/Office Building

Actual:
37 ft.

Affiliation Records:

Site Id: 387154
Affiliation Type: Facility Owner
Company Name: 449 W46TH STREET LLC
Contact Type: AGENT
Contact Name: MARK SCHARFMAN
Address1: 280 N CENTRAL PRWY SUITE 210
Address2: Not reported
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 9/13/2007

Site Id: 387154
Affiliation Type: Mail Contact
Company Name: BEACH LANE MGT
Contact Type: Not reported
Contact Name: MARK SCHARFMAN
Address1: 280 N CENTRAL PARK AVE
Address2: SUITE 210
City: HARTSDALE
State: NY
Zip Code: 10530
Country Code: 001
Phone: (914) 517-8800
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 9/13/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

449 W46TH STREET (Continued)

A100307817

Site Id: 387154
Affiliation Type: On-Site Operator
Company Name: 449 W46TH STREET
Contact Type: Not reported
Contact Name: NELSON MOJICA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 438-6943
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 9/13/2007

Site Id: 387154
Affiliation Type: Emergency Contact
Company Name: 449 W46TH STREET LLC
Contact Type: Not reported
Contact Name: NELSON MOJICA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 438-6943
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 9/13/2007

Tank Info:

Tank Number: 001A
Tank Id: 219406
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
B05 - Tank External Protection - Jacketed
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

449 W46TH STREET (Continued)

A100307817

Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/1980
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: msbaptis
Last Modified: 09/13/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

BJ361 448-450 WEST 46TH STREET
North 448-450 WEST 46TH ST
1/8-1/4 NEW YORK, NY 10036
0.201 mi.
1062 ft. Site 3 of 6 in cluster BJ

NY AST U003392119
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
35 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-214779
Program Type: PBS
UTM X: 585055.41784000001
UTM Y: 4512780.7369499998
Expiration Date: 10/15/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 7993
Affiliation Type: Facility Owner
Company Name: 46 ST.SKY,LLC C/O YAGHOOB BARADERIAN
Contact Type: MEMBER
Contact Name: YAGHOOB BARADARIAN
Address1: P.O. BOX 203
Address2: Not reported
City: ALPINE
State: NJ
Zip Code: 07620
Country Code: 001
Phone: (201) 767-0366
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 8/13/2007

Site Id: 7993
Affiliation Type: Mail Contact
Company Name: 46 WEST. SKY, LLC.
Contact Type: Not reported
Contact Name: YAGHOOB BARADARIAN
Address1: 560 SYLVAN AVE.
Address2: SUITE 2150
City: ENGLEWOOD CLIFFS
State: NJ
Zip Code: 07632

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

448-450 WEST 46TH STREET (Continued)

U003392119

Country Code: 001
Phone: (201) 894-5588
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 11/6/2012

Site Id: 7993
Affiliation Type: On-Site Operator
Company Name: 448-450 WEST 46TH STREET
Contact Type: Not reported
Contact Name: GILERMO MEGRA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 823-8141
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 8/13/2007

Site Id: 7993
Affiliation Type: Emergency Contact
Company Name: 46 ST.SKY,LLC C/O YAGHOOB BARADERIAN
Contact Type: Not reported
Contact Name: JACK BARADARIAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 281-6445
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 8/13/2007

Tank Info:

Tank Number: 001
Tank Id: 23526
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

448-450 WEST 46TH STREET (Continued)

U003392119

K00 - Spill Prevention - None
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1905
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 11/06/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-214779
SWIS Code: 6201
Operator: DOUGLAS CROMIN
Facility Phone: (201) 581-6483
Facility Addr2: Not reported
Facility Type: APARTMENT BUILDING
Emergency: BAYSIDE FUEL OIL
Emergency Tel: (718) 946-4000
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: YAGHOOB BARADERIAN
Owner Address: P.O. BOX 203
Owner City,St,Zip: ALPINE, NJ 07620
Federal ID: Not reported
Owner Tel: (201) 767-0366
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: YAGHOOB BARADERIAN
Mailing Address: P.O. BOX 203
Mailing Address 2: Not reported
Mailing City,St,Zip: ALPINE, NJ 07620
Mailing Telephone: (201) 767-0366
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 10/06/1997
Expiration: 10/15/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

448-450 WEST 46TH STREET (Continued)

U003392119

Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BH362 510
SSW 510 9TH AVE
1/8-1/4 NEW YORK, NY 10018
0.203 mi.
1071 ft. Site 3 of 8 in cluster BH

NY AST U003387938
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
33 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-315184
Program Type: PBS
UTM X: 584934.07605999999
UTM Y: 4512182.0447500004
Expiration Date: 07/10/2017
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 14396
Affiliation Type: Facility Owner
Company Name: EAST WEST ASSOC MGMT CO INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

510 (Continued)

U003387938

Contact Type: MANAGER
Contact Name: SILVIA MIGHTY
Address1: 510 9TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 643-2978
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/13/2012

Site Id: 14396
Affiliation Type: Mail Contact
Company Name: EAST WEST ASSOC MGMT CO INC
Contact Type: Not reported
Contact Name: EAST WEST ASSOC MGMT CO
Address1: 510 9TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 643-2978
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/13/2012

Site Id: 14396
Affiliation Type: On-Site Operator
Company Name: 510
Contact Type: Not reported
Contact Name: TANYA GIBBS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-2978
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 14396
Affiliation Type: Emergency Contact
Company Name: EAST WEST ASSOC MGMT CO INC
Contact Type: Not reported
Contact Name: TANYA GIBBS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

510 (Continued)

U003387938

Zip Code: Not reported
Country Code: 001
Phone: (212) 643-2978
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 12847
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/15/1950
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DXLIVING
Last Modified: 07/06/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-315184
SWIS Code: 6201
Operator: TANYA GIBBS
Facility Phone: (212) 643-2978
Facility Addr2: 510 9TH AVE
Facility Type: APARTMENT BUILDING
Emergency: TANYA GIBBS
Emergency Tel: (212) 643-2978
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: EAST WEST ASSOC MGMT CO INC
Owner Address: 510 9TH AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

510 (Continued)

U003387938

Owner City,St,Zip: NEW YORK, NY 10018
Federal ID: Not reported
Owner Tel: (212) 643-2978
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: EAST WEST ASSOC MGMT CO
Mailing Name: EAST WEST ASSOC MGMT CO INC
Mailing Address: 510 9TH AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10018
Mailing Telephone: (212) 736-2376
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/01/1997
Expiration: 07/10/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: Not reported
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

510 (Continued)

U003387938

Lat/Long: Not reported

BF363
NW
1/8-1/4
0.203 mi.
1072 ft.

518 W 44TH ST
NEW YORK, NY 10036

EDR US Hist Auto Stat 1015535737
N/A

Site 5 of 10 in cluster BF

Relative:
Lower

EDR Historical Auto Stations:

Name: KOTLER AUTO SPRINGS INCORPORATED
Year: 1999

Actual:
19 ft.

Address: 518 W 44TH ST

Name: KOTLER AUTO SPRINGS INCORPORATED
Year: 2000
Address: 518 W 44TH ST

Name: KOTLER AUTO SPRINGS INC
Year: 2001
Address: 518 W 44TH ST

Name: KOTLER AUTO SPRINGS
Year: 2002
Address: 518 W 44TH ST

BF364
NW
1/8-1/4
0.203 mi.
1072 ft.

STYLE MANG & CO
518 W 44TH ST
NEW YORK, NY 10036

RCRA NonGen / NLR 1000554300
FINDS NYD986967610

Site 6 of 10 in cluster BF

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007
Facility name: STYLE MANG & CO
Facility address: 518 W 44TH ST
NEW YORK, NY 100363425

Actual:
19 ft.

EPA ID: NYD986967610
Mailing address: W 44TH ST
NEW YORK, NY 10036

Contact: Not reported
Contact address: W 44TH ST
NEW YORK, NY 10036

Contact country: US
Contact telephone: Not reported
Contact email: Not reported

EPA Region: 02
Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: STYLE MANG & CO
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STYLE MANG & CO (Continued)

1000554300

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: STYLE MANG & CO
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: STYLE MANG & CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: STYLE MANG & CO
Classification: Not a generator, verified

Date form received by agency: 07/18/1991
Site name: STYLE MANG & CO
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004474854

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BH365
SSW
1/8-1/4
0.203 mi.
1072 ft.
CON EDISON
506 9TH AVE
NEW YORK, NY 10018
Site 4 of 8 in cluster BH

NY MANIFEST
S112210363
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004265344
Country: USA

Actual:
33 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265344
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456245JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210363

Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265344
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456245JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BD366
ENE
1/8-1/4
0.205 mi.
1080 ft.

TOWN HOUSE MANAGEMENT
330 WEST 45TH STREET
NEW YORK, NY 10036
Site 4 of 6 in cluster BD

NY UST U004079249
N/A

Relative:
Higher

UST:
Id/Status: 2-602688 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 05/16/2016
UTM X: 585344.69750000001
UTM Y: 4512558.2393800002
Site Type: Apartment Building/Office Building

Actual:
41 ft.

Affiliation Records:
Site Id: 24644
Affiliation Type: Facility Owner
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: AGENT
Contact Name: DAVIS SCHWARTZ
Address1: 330 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN HOUSE MANAGEMENT (Continued)

U004079249

Phone: (212) 247-3450
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/13/2012

Site Id: 24644
Affiliation Type: Mail Contact
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: MANAGING AGENT
Contact Name: DAVID SCHWARTZ
Address1: 330 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 247-3450
EMail: DAVID.TOWNHOUSE@GMAIL.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/13/2012

Site Id: 24644
Affiliation Type: On-Site Operator
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: Not reported
Contact Name: FELIX TEJERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 247-3450
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/14/2010

Site Id: 24644
Affiliation Type: Emergency Contact
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: Not reported
Contact Name: FELIX TEJERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 417-3984
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/14/2010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN HOUSE MANAGEMENT (Continued)

U004079249

Tank Info:

Tank Number: 001
Tank ID: 51142
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 15000
Install Date: Not reported
Date Tank Closed: 03/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

BD367
ENE
1/8-1/4
0.205 mi.
1080 ft.

TOWN HOUSE MANAGEMENT
330 WEST 45TH STREET
NEW YORK, NY 10036
Site 5 of 6 in cluster BD

NY HIST UST
NY AST

U003107179
N/A

Relative:
Higher

HIST UST:
PBS Number: 2-602688
SPDES Number: Not reported
Emergency Contact: URBANDO VASQUEZ
Emergency Telephone: (212) 307-0976
Operator: NILES SCHWARTZ
Operator Telephone: (212) 247-3450
Owner Name: TOWN HOUSE MANAGEMENT
Owner Address: 330 WEST 45TH STREET
Owner City,St,Zip: NEW YORK, NY 10036
Owner Telephone: (212) 247-3450
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: TOWN HOUSE MANAGEMENT
Mailing Address: 330 WEST 45TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Contact: Not reported
Mailing Telephone: (212) 247-3450

Actual:
41 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN HOUSE MANAGEMENT (Continued)

U003107179

Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: Not reported
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: APARTMENT BUILDING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 10/26/2001
Expiration Date: 05/16/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 12000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-In Place
Install Date: Not reported
Capacity (gals): 15000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 03/01/1996
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:

Region: STATE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN HOUSE MANAGEMENT (Continued)

U003107179

DEC Region: 2
Site Status: Active
Facility Id: 2-602688
Program Type: PBS
UTM X: 585344.69750000001
UTM Y: 4512558.2393800002
Expiration Date: 05/16/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 24644
Affiliation Type: Facility Owner
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: AGENT
Contact Name: DAVIS SCHWARTZ
Address1: 330 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 247-3450
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/13/2012

Site Id: 24644
Affiliation Type: Mail Contact
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: MANAGING AGENT
Contact Name: DAVID SCHWARTZ
Address1: 330 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 247-3450
EMail: DAVID.TOWNHOUSE@GMAIL.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 3/13/2012

Site Id: 24644
Affiliation Type: On-Site Operator
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: Not reported
Contact Name: FELIX TEJERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 247-3450
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN HOUSE MANAGEMENT (Continued)

U003107179

Modified By: NRLOMBAR
Date Last Modified: 5/14/2010

Site Id: 24644
Affiliation Type: Emergency Contact
Company Name: TOWN HOUSE MANAGEMENT
Contact Type: Not reported
Contact Name: FELIX TEJERA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 417-3984
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/14/2010

Tank Info:

Tank Number: 002
Tank Id: 51143
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

F04 - Pipe External Protection - Fiberglass
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
H05 - Tank Leak Detection - In-Tank System (ATG)
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
B09 - Tank External Protection - Urethane
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1996
Capacity Gallons: 12000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 05/14/2010
Material Name: #6 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BG368
South
1/8-1/4
0.205 mi.
1081 ft.

R GREENBURG ASSOCIATES
350 W 39TH ST
NEW YORK, NY 10018
Site 2 of 3 in cluster BG

RCRA NonGen / NLR
FINDS
NY MANIFEST

1000355378
NYD083063248

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: R GREENBURG ASSOCIATES

Facility address: 350 W 39TH ST
NEW YORK, NY 10018

EPA ID: NYD083063248

Mailing address: W 39TH ST
NEW YORK, NY 10018

Contact: Not reported

Contact address: W 39TH ST
NEW YORK, NY 10018

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Land type: Private

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ROBERT GREENBERG

Owner/operator address: 350 W 39TH ST
NEW YORK, NY 10018

Owner/operator country: US

Owner/operator telephone: (212) 239-6767

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: ROBERT GREENBERG

Owner/operator address: 350 W 39TH ST
NEW YORK, NY 10018

Owner/operator country: US

Owner/operator telephone: (212) 239-6767

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

R GREENBURG ASSOCIATES (Continued)

1000355378

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: R GREENBURG ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 11/09/1993
Site name: R GREENBURG ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 07/29/1993
Site name: R GREENBURG ASSOCIATES
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 11/09/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

FINDS:

Registry ID: 110004372241

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD083063248
Country: USA

Mailing Info:

Name: GREENBURG RASSOCIATES
Contact: GREENBURG RASSOCIATES
Address: 351 W 39TH STREET
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-239-6767

Document ID: NYA7190721
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

R GREENBURG ASSOCIATES (Continued)

1000355378

Generator Ship Date: 890509
Trans1 Recv Date: 890509
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890511
Part A Recv Date: 890516
Part B Recv Date: 890526
Generator EPA ID: NYD083063248
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NYB5213232
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 930914
Trans1 Recv Date: 930914
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930914
Part A Recv Date: 931025
Part B Recv Date: 930930
Generator EPA ID: NYD083063248
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: U228 - TRICHLOROETHENE
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 125
Year: 93

Document ID: NYB2092698
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PA6703
Trans2 State ID: Not reported
Generator Ship Date: 910206
Trans1 Recv Date: 910206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910208
Part A Recv Date: 910509
Part B Recv Date: 910228
Generator EPA ID: NYD083063248
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

R GREENBURG ASSOCIATES (Continued)

1000355378

TSD ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 133
Year: 91

BE369
NW
1/8-1/4
0.205 mi.
1081 ft.

520 W 43RD ST
NEW YORK, NY 10036
Site 4 of 5 in cluster BE

EDR US Hist Cleaners 1015071445
N/A

Relative:
Lower

EDR Historical Cleaners:

Name: D K VALET CLEANERS
Year: 2008
Address: 520 W 43RD ST

Actual:
19 ft.

Name: D K VALET CLEANERS
Year: 2010
Address: 520 W 43RD ST

Name: D K VALET CLEANERS
Year: 2011
Address: 520 W 43RD ST

Name: D K VALET CLEANERS
Year: 2012
Address: 520 W 43RD ST

BE370
NW
1/8-1/4
0.205 mi.
1081 ft.

NEW GOTHAM
520 WEST 43RD STREET
NEW YORK, NY 10036
Site 5 of 5 in cluster BE

NY AST A100175479
N/A

Relative:
Lower

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605188
Program Type: PBS
UTM X: 584819.96932999999
UTM Y: 4512658.1233200002
Expiration Date: 02/12/2016
Site Type: Apartment Building/Office Building

Actual:
19 ft.

Affiliation Records:

Site Id: 27057
Affiliation Type: Facility Owner
Company Name: 520 WEST 43RD STREET PARTNERS LLC % ROSE ASSOC, IN
Contact Type: Not reported
Contact Name: Not reported
Address1: 200 MADISON AVENUE, 5TH FL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW GOTHAM (Continued)

A100175479

Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 210-6666
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2012

Site Id: 27057
Affiliation Type: Mail Contact
Company Name: ROSE ASSOCIATES, INC.
Contact Type: Not reported
Contact Name: COMPLIANCE DEPT.
Address1: 200 MADISON AVENUE, 5TH FL
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 210-6666
EMail: TMIDDLEBROOKS@ROSENYC.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2012

Site Id: 27057
Affiliation Type: On-Site Operator
Company Name: NEW GOTHAM
Contact Type: Not reported
Contact Name: CHARLES BROWN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 868-2042
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2012

Site Id: 27057
Affiliation Type: Emergency Contact
Company Name: 520 WEST 43RD STREET PARTNERS LLC % ROSE ASSOC, IN
Contact Type: Not reported
Contact Name: ANDREW DISCHINO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 563-4158

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW GOTHAM (Continued)

A100175479

Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/20/2012

Tank Info:

Tank Number: #1
Tank Id: 59552
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
G03 - Tank Secondary Containment - Vault (w/o access)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/01/1996
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 11/20/2012
Material Name: #4 Fuel Oil (On-Site Consumption)

BB371 **300 W 43RD STREET**
ESE **300 W 43RD STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.205 mi.
1082 ft. **Site 5 of 5 in cluster BB**

NY AST **U004076786**
 N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-235903
Program Type: PBS
UTM X: 585339.26263999997
UTM Y: 4512377.7687499998
Expiration Date: 11/01/2017
Site Type: Apartment Building/Office Building

Actual:
42 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

300 W 43RD STREET (Continued)

U004076786

Affiliation Records:

Site Id: 8715
Affiliation Type: Mail Contact
Company Name: 300 WEST 43 STREET, LLC.
Contact Type: Not reported
Contact Name: THOMAS J. SIMMONDS, JR
Address1: 300 W 43RD ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 247-4910
EMail: TSIMMONDS@REALTY42.COM
Fax Number: Not reported
Modified By: kakyer
Date Last Modified: 1/7/2008

Site Id: 8715
Affiliation Type: On-Site Operator
Company Name: 300 W 43RD STREET
Contact Type: Not reported
Contact Name: A. BRAITH WHITE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 247-4910
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8715
Affiliation Type: Emergency Contact
Company Name: RICHARD BASCIANO DBA 303
Contact Type: Not reported
Contact Name: T. SIMMONDS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 247-6643
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8715
Affiliation Type: Facility Owner
Company Name: 300 WEST 43 STREET, LLC.
Contact Type: REGISTERED AGENT
Contact Name: THOMAS J. SIMMONDS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

300 W 43RD STREET (Continued)

U004076786

Address1: 300 WEST 43RD ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 247-4910
EMail: Not reported
Fax Number: Not reported
Modified By: kakyer
Date Last Modified: 1/7/2008

Tank Info:

Tank Number: 001
Tank Id: 12661
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1950
Capacity Gallons: 4000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

BJ372 **CON EDISON**
North **459 W 46 ST**
1/8-1/4 **NEW YORK, NY 10036**
0.205 mi.
1083 ft. **Site 4 of 6 in cluster BJ**

NY MANIFEST **S112210711**
N/A

Relative: NY MANIFEST:
Higher EPA ID: NYP004269015
Country: USA
Actual: Mailing Info:
34 ft. Name: CON EDISON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210711

Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269015
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456595JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-17
Trans1 Recv Date: 2012-09-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269015
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210711

Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456595JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BJ373
North
1/8-1/4
0.205 mi.
1083 ft.

CON EDISON SERVICE BOX: 8858
459 W 46TH ST
NEW YORK, NY 10036
Site 5 of 6 in cluster BJ

RCRA-CESQG 1016144113
FINDS NYP004269015

Relative:
Higher

RCRA-CESQG:

Actual:
34 ft.

Date form received by agency: 09/17/2012
Facility name: CON EDISON SERVICE BOX: 8858
Facility address: 459 W 46TH ST
NEW YORK, NY 10036
EPA ID: NYP004269015
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8858 (Continued)

1016144113

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461110

Environmental Interest/Information System

**BF374
NW
1/8-1/4
0.206 mi.
1087 ft.**

**ORSAP TAXI CORPORATION
520 WEST 44TH ST
NEW YORK, NY 10036
Site 7 of 10 in cluster BF**

**NY AST A100362296
N/A**

**Relative:
Lower**

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611844
Program Type: PBS
UTM X: 584768.43380999996
UTM Y: 4512754.11130999996
Expiration Date: 03/01/2018
Site Type: Apartment Building/Office Building

**Actual:
19 ft.**

Affiliation Records:

Site Id: 466407
Affiliation Type: Facility Owner
Company Name: MICHAEL SINDER
Contact Type: PRESIDENT
Contact Name: MICHAEL SINDER
Address1: 200 RIVERSIDE BLVD
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10069
Country Code: 001
Phone: (516) 316-4728
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOULOG

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ORSAP TAXI CORPORATION (Continued)

A100362296

Date Last Modified: 4/1/2013

Site Id: 466407
Affiliation Type: Mail Contact
Company Name: ORSAP TAXI REPAIR
Contact Type: Not reported
Contact Name: MICHAEL SINDER
Address1: 520 WEST 44TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 967-7577
EMail: ELISHEVA556@AOL.COM
Fax Number: Not reported
Modified By: DMMOLOUD
Date Last Modified: 4/1/2013

Site Id: 466407
Affiliation Type: On-Site Operator
Company Name: ORSAP TAXI CORPORATION
Contact Type: Not reported
Contact Name: MICHAEL SINDER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 967-7577
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/12/2012

Site Id: 466407
Affiliation Type: Emergency Contact
Company Name: MICHAEL SINDER
Contact Type: Not reported
Contact Name: MICHAEL SINDER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 316-4728
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/12/2012

Tank Info:

Tank Number: 001
Tank Id: 244744

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ORSAP TAXI CORPORATION (Continued)

A100362296

Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/2008
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUR
Last Modified: 04/01/2013
Material Name: Lube Oil

Tank Number: 002
Tank Id: 244745
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/2008
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ORSAP TAXI CORPORATION (Continued)

A100362296

Register: True
Modified By: DMMOLOUG
Last Modified: 04/01/2013
Material Name: Waste Oil/Used Oil

**BF375
NW
1/8-1/4
0.206 mi.
1087 ft.**

**520 W 44TH ST
NEW YORK, NY 10036**

**EDR US Hist Auto Stat 1015537058
N/A**

Site 8 of 10 in cluster BF

**Relative:
Lower**

EDR Historical Auto Stations:

Name: FUJII AUTO REPAIR INCORPORATED
Year: 2000
Address: 520 W 44TH ST

**Actual:
19 ft.**

Name: FUJII AUTO REPAIR INC
Year: 2001
Address: 520 W 44TH ST

Name: FUJII AUTO REPAIR INC
Year: 2003
Address: 520 W 44TH ST

Name: FUJII AUTO REPAIR INC
Year: 2004
Address: 520 W 44TH ST

Name: FUJII AUTO REPAIR INC
Year: 2007
Address: 520 W 44TH ST

Name: FUJII AUTO REPAIR INC
Year: 2008
Address: 520 W 44TH ST

Name: FUJII AUTO REPAIR INC
Year: 2009
Address: 520 W 44TH ST

Name: 24 HOUR TOWING SVC BY VANESSA
Year: 2010
Address: 520 W 44TH ST

Name: NYC TOWING & AUTO CARE
Year: 2011
Address: 520 W 44TH ST

Name: NYC TOWING & AUTO CARE
Year: 2012
Address: 520 W 44TH ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BK376 **MARTIN BECK THEATRE CORP**
East **302 WEST 45TH STREET**
1/8-1/4 **MANHATTAN, NY 10036**
0.206 mi.
1090 ft. **Site 1 of 4 in cluster BK**

NY AST **U003391197**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-335134
Program Type: PBS
UTM X: 585410.54073999997
UTM Y: 4512522.1398
Expiration Date: 11/16/2002
Site Type: Other

Affiliation Records:

Site Id: 15968
Affiliation Type: Facility Owner
Company Name: JUJAMCYN THEATERS CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 246 WEST 44TH STREET
Address2: Not reported
City: MANHATTAN
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 840-8181
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15968
Affiliation Type: Mail Contact
Company Name: JUJAMCYN THEATERS CORP
Contact Type: DIRECTOR OF OPERATIONS
Contact Name: JENNIFER HERSHEY
Address1: 246 WEST 44TH STREET
Address2: Not reported
City: MANHATTAN
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 840-8181
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 11/20/2007

Site Id: 15968
Affiliation Type: On-Site Operator
Company Name: MARTIN BECK THEATRE CORP
Contact Type: Not reported
Contact Name: JOSEPH RICCIO
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARTIN BECK THEATRE CORP (Continued)

U003391197

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 840-8181
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15968
Affiliation Type: Emergency Contact
Company Name: JUJAMCYN THEATERS CORP
Contact Type: Not reported
Contact Name: JENNIFER HERSHEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 673-0190
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 045
Tank Id: 20939
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A02 - Tank Internal Protection - Rubber Liner
I05 - Overfill - Vent Whistle
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 3500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/11/2002
Register: True
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARTIN BECK THEATRE CORP (Continued)

U003391197

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-335134
SWIS Code: 6201
Operator: JOSEPH RICCIO
Facility Phone: (212) 840-8181
Facility Addr2: 302 WEST 45TH STREET
Facility Type: OTHER
Emergency: JENNIFER HERSHEY
Emergency Tel: (212) 673-0190
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: JUJAMCYN THEATERS CORP
Owner Address: 246 WEST 44TH STREET
Owner City,St,Zip: MANHATTAN, NY 10036
Federal ID: Not reported
Owner Tel: (212) 840-8181
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: JENNIFER HERSHEY
Mailing Name: JUJAMCYN THEATERS CORP
Mailing Address: 246 WEST 44TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 840-8181
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 11/13/1997
Expiration: 11/16/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 3028
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 045
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 3028
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARTIN BECK THEATRE CORP (Continued)

U003391197

Tank Internal: 2
Tank External: 0
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 0
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 46
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

BK377
East
1/8-1/4
0.206 mi.
1090 ft.

MARTIN BECK THEATRE
302 W 45TH ST
NEW YORK, NY 10036

RCRA NonGen / NLR 1000446199
FINDS NYD986908879

Site 2 of 4 in cluster BK

Relative:
Higher

RCRA NonGen / NLR:

Actual:
41 ft.

Date form received by agency: 01/01/2007
Facility name: MARTIN BECK THEATRE
Facility address: 302 W 45TH ST
NEW YORK, NY 100363802
EPA ID: NYD986908879
Mailing address: W 45TH ST
NEW YORK, NY 10036
Contact: Not reported
Contact address: W 45TH ST
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: JUJAMCYN THEATRES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JUJAMCYN THEATRES
Owner/operator address: NOT REQUIRED

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARTIN BECK THEATRE (Continued)

1000446199

NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MARTIN BECK THEATRE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MARTIN BECK THEATRE
Classification: Not a generator, verified

Date form received by agency: 08/06/1990
Site name: MARTIN BECK THEATRE
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004450987

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BL378
ESE
1/8-1/4
0.207 mi.
1091 ft.
661 8TH AVE
NEW YORK, NY 10036
Site 1 of 7 in cluster BL

EDR US Hist Auto Stat **1015593968**
N/A

Relative:
Higher

Actual:
43 ft.

EDR Historical Auto Stations:

Name: FAST LANE TRANS REPAIR
Year: 2011
Address: 661 8TH AVE

Name: FAST LANE TRANSPORTATION REPAIR
Year: 2012
Address: 661 8TH AVE

BF379
NW
1/8-1/4
0.207 mi.
1091 ft.
CON ED - V 3685
522 W 44 ST
NEW YORK, NY 10036
Site 9 of 10 in cluster BF

RCRA NonGen / NLR **1007205266**
NY LTANKS **NYP000928358**
NY MANIFEST
NY Spills

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 02/28/1998

Facility name: CON ED - V 3685

Facility address: 522 W 44 ST
NEW YORK, NY 100360000

EPA ID: NYP000928358

Mailing address: CONSOLIDATED EDISON INC
4 IRVING PLACE - ROOM 300
NEW YORK, NY 100030000

Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 100030000

Contact country: US

Contact telephone: (212) 460-3770

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/27/1998

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

Site name: CON ED - V 3685
Classification: Not a generator, verified

Date form received by agency: 02/26/1998
Site name: CON ED - V 3685
Classification: Large Quantity Generator

Violation Status: No violations found

LTANKS:

Site ID: 90896
Spill Number/Closed Date: 8901904 / Not Reported
Spill Date: 5/24/1989
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 4/28/2005
Cleanup Meets Standard: False
SWIS: 2401
Investigator: RJFENG
Referred To: 080613 CASE TRANSFERRED TO SPILLS UNIT
Reported to Dept: 5/24/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 2/28/2008
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 4
Date Entered In Computer: 5/25/1989
Spill Record Last Update: 8/6/2013
Spiller Name: Not reported
Spiller Company: AMOCO
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 82010
DEC Memo: 3/14/03 REASSIGNED FROM SULLIVAN TO VOUGHT. 10/27/03 Also see spill # 0307900.11/25/03 Reassigned from Vought to Foley.11/25/03 Received Delta Dispenser Upgrade Report dated 11/10/03 on 11/17/03. Lab analysis of post-ex soil samples collected from beneath four dispensers identified VOC concentrations in excess of TAGM 4046 soil cleanup objectives in three dispenser locations (D-1, D-2, D-3). Delta will delineate the soil impacts beneath the product dispensers. 4/19/04 Received SHAR. On 3/17/04, four borings were advanced by Geoprobe in the vicinity of the dispensers. DTW 13-20'bgs. Nine soil samples were collected at the depth interval exhibiting the highest PID reading or immediately above the water table. SB-1 (3.5-4.5'), SB-1 (17-18'), SB-2(19-20'), SB-3(2.5-3.5'), SB-3 (12-13'), SB-4(2.5-3.5'), SB-4(7-8'), SB-4(12-13'). Analysis by 8260 showed hits for VOCs above cleanup levels in five of nine soil samples in all four borings. Total BTEX conc ranged from ND (SB-1, 3.5-4.5' and SB-2, 3.5-4.5') to 1,076,900ppb in SB-4(12-13').The four borings were

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

converted to 1" temporary wells. Four groundwater samples were collected and analyzed for VOCs. DTW 18-24'bgs. MWs were advanced to 23-26'bgs. Temporary wells were removed. No LNAPL was detected. Total BTEX ranged from 3,732ppb (MW-1) to 45,380ppb(MW-4). Total VOC range from 17,061ppb(MW-2) to 69,062ppb(MW-1). MTBE ranged from 9,050ppb(MW-4) to 64,600ppb(MW-1). 12/21/04 4Q04 report received(samples collected 11/23/04). BTEX ranged from 38ppb(MW-5) to 38810ppb(MW-4). MTBE ranged from 33ppb(MW-5) to 174000ppb(MW-1). DTW approx 12-15'bgs.6/28/04 Investigation report received. On 4/23/04, one 1" well(MW-3) was installed through existing soil boring SB-3 and one 2" well(MW-4) was installed through previously advanced soil boring SB-4. Wells were advanced to 25.5 and 26.5' respectively. GW was encountered at 17.15'bgs in MW-3 and 17'bgs in MW-4. No soil samples collected due to previous investigation.On 5/24/04, three 2" wells (MW-1, MW-2, MW-5) were installed to 24', 20', and 20' respectively. GW encountered at 11.7' and 16.8'bgs. Four soil samples were collected. Hits for VOCs in SB-5/MW-2(10-11'), SB-5/MW-2(12-13'). On 5/28/04, five GW samples were collected. GW was identified at 11'-14.5'bgs. Flow was interpreted as NW. BTEX ranged from 74ppb(MW-5) to 45550ppb(MW-4). MTBE from 19ppb(MW-5) to 192000ppb(MW-1).9/30/04 3Q04 monitoring report received. BTEX from 57ppb(MW-5) to 39150ppb(MW-4). MTBE from 17ppb(MW-5) to 164000ppb(MW-1). DTW 11-14'bgs. Need to delineate downgradient and sidegradient.3/10/05 Received 1Q05 monitoring report. BTEX ranged from 65ppb(MW-5) to 38730ppb(MW-4). MTBE from 12ppb(MW-5) to 204000ppb(MW-1).3/15/05 Issued sidewalk permit letter to install three MWs along the west sidewalk of 4th Ave.3/15/05 Stip issued. Due 4/29/05.4/21/05 Received stip signed by C. Wein on 4/19/05.4/27/05 Portfolio meeting- Vadose and saturated soil impacts at northern border and SW portion of property. PS #51 300' NW. Impacts across street(total BTEX 100ppb). Service station and taxi stand on Sanborns for property across street.4/28/05 Stip executed by T. Kunkel. An Investigation Summary report is due 6/27/05. RAP due 8/26/05.6/13/05 Received subsurface hydrocarbon assessment report dated 6/7/05. MW-6,7,8 installed off-site. Soil results show impacts at MW-7(11-12'bgs & 15-16'bgs). Adjacent to U-Haul and Taxi Stand with garage. Total BTEX in GW was 1ppb(MW-6), 272ppb(MW-7) and ND(MW-8). MTBE concentrations were 2ppb(MW-6), 3ppb(MW-7) and 13ppb(MW-8).6/24/05 Received Investigation summary report dated 6/22/05. On-site vadose zone soil impacts in and around dispensers are from historical release. Elevated MTBE concentrations in MW-1 and MW-2 may be related to more recent release. This is also supported by analysis of BTEX ratios. Off-site soil and GW impacts were detected across 4th Ave at MW-7 and MW-8, which appear to be from U-Haul or taxi stand(impacts as shallow as 11'bgs).9/6/05 Received well installation report documenting installation of EW-1, MW-9 and MW-10. MPE pilot conducted 8/16/05. Pilot test feasibility report to be submitted.12/30/05 Received 3Q05 monitoring report. DTW 11.37-14.90'bgs. BTEX ranged from ND(MW-8) to 50320ppb(MW-4). MTBE ranged from 5.1ppb(MW-6) to 170000ppb(MW-1).2/23/06 Received letter from Delta requesting extension to stip and summarizing MPE pilot test results which was conducted in 8/05. Since 8/05, Delta has tried to identify an appropriate remedial alternative to address site impacts within the vadose, smear and saturated zones on-site. On 11/4/05, Delta sampled on and off-site wells for geochemical parameters and stable carbon isotope ratio analysis. Delta is currently reviewing the results as they relate to the potential use

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

of aerobic stimulation(sparging). Request extension to submit RAP by 5/14/06.3/9/06 4Q05- DTW 11.96-14.63' bgs. BTEX ranged from ND(MW-8) to 44200ppb(MW-4). MTBE ranged from 1ppb(MW-8) to 81900ppb(MW-10).3/16/06 Met with BP and Delta. MW-6,7,8 installed in 4/05. Pilot for MPE completed in 8/05 which determined it is not an option. Geochemical sampling completed 10/05 which showed no degradation. DTW 11.5-14.5' bgs. Very high MTBE concentrations. Sensitive receptors include utility vaults along 4th Ave. Delta was planning to submit biosparge proposal. Vic Kremesec, BP, requested Delta look into something more aggressive.5/9/06 Received feasibility pilot testing and analysis report for Multi-Phase Extraction and a Remedial Action Plan.6/8/2006 - Feng - project reassigned to RJFeng. (RJF)7/28/2006 - Feng - Quarterly Monitoring Report, 1Q2006, 6/6/2006, submitted by Delta. As of sampling on 3/6/2006, groundwater flows to northwest at the depth of 10.89' to 15.17' bg. 11 monitoring wells. W-1, 9,350 ppb BTEX (3,410 ppb B, 1,050 ppb T, 1,480 ppb E, 3,410 ppb X), 21,100 ppb MTBE. W-2, 2,840 ppb BTEX (1,170 ppb B, 163 ppb T, 811 ppb E, 696 ppb X), 3,330 ppb MTBE. W-3, 20,990 ppb BTEX (3,070 ppb B, 6,800 ppb T, 2,120 ppb E, 9,000 ppb X), 10,400 ppb MTBE. W-4, 38,920 ppb BTEX (4,400 ppb B, 17,300 ppb T, 3,220 ppb E, 14,000 ppb X), 33,500 ppb MTBE. W-5, 35.4 ppb BTEX, 4.6 ppb MTBE. W-6, 1.42 ppb BTEX, 4.6 ppb MTBE. W-7, 677 ppb BTEX (22.8 ppb B, 8.9 ppb T, 304 ppb E, 341 ppb X), 8.1 ppb MTBE. W-8, ND. W-9, 16,780 ppb BTEX (2,180 ppb B, 1,890 ppb T, 2,210 ppb E, 10,500 ppb X), 14,200 ppb MTBE. W-10, 17,760 ppb BTEX (3,810 ppb B, 3,180 ppb T, 2,890 ppb E, 7,880 ppb X), 44,900 ppb MTBE. EW-1, 12,180 ppb BTEX (2,110 ppb B, 1,780 ppb T, 1,940 ppb E, 6,350 ppb X), 8,260 ppb MTBE. (RJF)8/1/2006 - Feng - Remedial Action Plan, 5/8/2006, submitted by Delta Environmental. Delta proposed MultiPhase Extraction System to be installed to address FP, soil vapor and gw contamination. Delta conducted pilot test twice. The 1st time it was concluded that "The results of this MPE pilot event conflicted with the expected response from the site's lithology". During the 2nd pilot test, 5 air samples collected at specific intervals to quantify specific vapor VOC concentration being removed. The recovery rates are 0.19 lb/hr BTEX, 0.091 lbs/hr MTBE, 4.89 lbs/hr TPH. For the groundwater drawdown reading, W-9 at 0.28' which located 5 feet away from EW-1. Delta explained that "The limited groundwater drawdown ROI from extraction well EW-1 is likely due to the more transmissive subsurface soils which allow more significant groundwater recharge into the cone of depression generated by MPE operation at the extraction well EW-1". The system components included 4 extraction wells, phase separator, liquid ring pump, system control panel, for vapor and liquid treatment are being designed. System flow chart is provided. By running the MPE, there is better hydraulic control and source removal. RAP is approved conditionally: 1) add the air exhaust in the system flow chart. 2) reinstall the MW-1, MW-3 and MW-4 due to their screen interval starts at the water table or below the water table. 3) Investigate the impact to the subway tunnel right next to the station (N, R and F trains run along 4th Ave). (RJF)8/2/2006 - Feng - Approval of MPE letter sent to BP and cc to Delta. (RJF)9/26/2006 - Feng - Quarterly Monitoring Report, 2Q2006, 9/7/2006, by Delta. Sampled and monitored on 6/19/2006. DTW 10.60' to 14.42' bg, flows to northwest. 10 of 11 monitoring wells were sampled. MW-2 was not accessible. MW-1, 8,012 ppb BTEX, 28,200 ppb MTBE. MW-3, 16,430 ppb BTEX, 8,540 ppb MTBE. MW-4, 37,250 ppb BTEX, 32,400 ppb MTBE. MW-5, 59.1 ppb BTEX, 5.4 ppb MTBE. MW-6, 0.25 ppb BTEX, 2.8 ppb MTBE. MW-7,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

569 ppb BTEX, 6.1 ppb MTBE. MW-8, BTEX ND, 0.71 ppb MTBE. MW-9, 10,688 ppb BTEX, 4,620 ppb MTBE. MW-10, 21,300 ppb BTEX, 63,500 ppb MTBE. EW-1, 8,055 ppb BTEX, 5,250 ppb MTBE. (RJF) 9/28/2006 - Feng - Portfolio meeting with BP and Delta. Plan changed for this site. On 8/2006, Delta had the plan in place for redevelopment and construction of high rise building. There will be multi-story basement, USTs will be pulled and additional soil will be removed. Construction schedule will be confirmed and remedial plan will start from the groundwater quality after tanks removal. (RJF)3/6/3007 - Feng - 3Q2006, 12/21/2006. Groundwater sampled and gauged 9/13/2006. 11 monitoring wells were sampled. DTW 10.68' to 14.36' bg. Flows northwest. LNAPL in MW-9 (0.12'). MW-1, 9,350 ppb BTEX, 21,100 ppb MTBE. MW-2, 2,840 ppb BTEX, 3,330 ppb MTBE. MW-3, 20,990 ppb BTEX, 10,400 ppb MTBE. MW-4, 38,920 ppb BTEX, 33,500 ppb MTBE. MW-5, 35.4 ppb BTEX, 4.6 ppb MTBE. MW-6, 1.42 ppb BTEX, 4.6 ppb MTBE. MW-7, 677 ppb BTEX, 8.1 ppb MTBE. MW-8, ND. MW-9, 16,780 ppb BTEX, 14,200 ppb MTBE. MW-10, 17,760 ppb BTEX, 44,900 ppb MTBE. EW-1, 12,180 ppb BTEX, 8,260 ppb MTBE. Email Delta for status on tank pull, site development and RAP. (RJF)3/6/3007 - Feng - Updates from D. Greffenius (Delta), the USTs, piping, and dispenser removals will begin on Monday, March 12, 2007. Alvin Petroleum is the contractor. 3/6/2007 - Feng - email from D. Taylor (Delta), USTs will be removed and endpoint samples will be taken and Closure report will be submitted. Delta are currently in touch with the site owner who hasn't yet provided the development schedule. (RJF)7/24/2007 - Feng - 4Q2006, 4/30/2007. Groundwater sampled 12/7/2006. All 11 monitoring wells were sampled. DTW 10.42' to 14.17' bg. Flows to northwest. No LNAPL. MW-1, 7,750 ppb BTEX, 9,800 ppb MTBE. MW-2, 2,754 ppb BTEX, 1,340 ppb MTBE. MW-3, 10,370 ppb BTEX, 5,350 ppb MTBE. MW-4, 31,030 ppb BTEX, 14,300 ppb MTBE. MW-5, 47.7 ppb BTEX, 4.4 ppb MTBE. MW-6, 1.94 ppb BTEX, 4 ppb MTBE. MW-7, 650 ppb BTEX, 4.7 ppb MTBE. MW-8, BTEX ND, less than 1 ppb MTBE. MW-9, 9,510 ppb BTEX, 3,630 ppb MTBE. MW-10, 17,180 ppb BTEX, 15,900 ppb MTBE. EW-1, 9,850 ppb BTEX, 3,640 ppb MTBE. (RJF)7/27/2007 - Feng - 1Q2007, 5/7/2007. Groundwater sampled 3/7/2007. 9/11 monitoring wells were sampled. DTW 11.51' to 14.6' bg. Flows to north-northwest. No LNAPL. MW-1, 6,936 ppb BTEX, 4,930 ppb MTBE. MW-2, 2,820 ppb BTEX, 632 ppb MTBE. MW-3, not accessible. MW-4, 40,800 ppb BTEX, 34,800 ppb MTBE. MW-5, well not located. MW-6, ND. MW-7, 468 ppb BTEX, 3.1 ppb MTBE. MW-8, ND. MW-9, 9,160 ppb BTEX, 2,230 ppb MTBE. MW-10, 24,490 ppb BTEX, 7,960 ppb MTBE. EW-1, 10,430 ppb BTEX, 2,460 ppb MTBE. (RJF)7/31/2007 - Feng - Underground Storage Tank Excavation Assessment Report, 4/26/2007, by Delta. Between 3/12/2007 and 3/15/2007, 4 (4,000-gallon) double-walled steel gasoline USTs and 1 (4,000-gallon) double walled steel abandoned UST from a single tank cavity on the central portion of the site were excavated. The abandoned UST was filled with concrete slurry. Upon excavation, the tanks were observed to be in good condition with no visible holes or areas of pitting. Between 3/16/2007 to 3/20/2007, 4 pump island dispensers and the associated product piping were excavated and removed. On 3/12/2007, 1 hydraulic lift was removed. 25 over-excavation soil samples were collected. High contamination detected in soil samples. For USTs excavation, the total BTEX range from ND (SW-17) to 1,796,700 ug/kg in SW-5 (9'), the total VOCs ranged from 205 ug/kg in SW-14 (9') to 2,828,170 ug/kg in SW-5 (9'). For the pump islands and piping excavation, total BTEX concentration ranged from ND in B-13 (12-12.5') to 327,700 ug/kg in B-2 (12-12.5'), the total VOCs concentration ranged from ND in B-3 to 659,890 ug/kg

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

in B2 (12-12.5'). For the hydraulic lift excavation, no SVOCs exceedance. Groundwater encountered at a depth of 13' bg. 1 groundwater sample was taken from MW-4, 40,800 ppb ug/L BTEX, 34,800 ug/L MTBE. On 3/28-29/2007, 795.24 tons of soil was generated during the over excavation activities. The soil was transported and disposed at the Clean Earth of Philadelphia (CEP). The excavations were backfilled with the Certified Clean Fill. 8/1/2007 - Feng - Letter to Kevin Endriss (BP) requiring RAP and the construction details. Due 10/1/2007. (RJF)10/10/2007 - Feng - Portfolio meeting with BP and Delta. Potentially developing the site. Tanks closure done and soil over-excavated. Drill at the side near the subway to inspect for impact on the subway tunnel. The new development may need to excavate down to 30 feet bg. Development schedule is unknown at this point. Delta will submit a work plan for proposing MPE events on 2" wells for short term remediation. (RJF)12/10/2007 - Feng - Call from potential buyer and inquired about the site status. DEC stated the requirement of gw and soil remediation, plus the soil vapor mitigation. Buying is in process. (RJF)1/11/2008 - Feng - Reviewed various documents submitted by HydroTech. 1) Phase I Environmental Site Assessment Report, dated 10/12/2007. Some Recognized Environmental Concerns were identified: the "E" Designation listing of the site for HAZMAT; historical utilization of the site as an auto repair facility and a gasoline station; presence of an open NYSDEC spill at the site; presence of elevated levels of VOCs in the soil and groundwater at the site at concentrations exceeding regulatory standards; inconsistent PBS information. 2) Investigation Work Plan, dated 11/27/2007. Investigation were proposed to be conducted in addressing the "E" Designation. HydroTech proposed GPR Survey to scan for any subsurface anomalies such as unknown tanks; to install 12 soil borings and 2 soil samples will be taken from each soil boring; and 3 groundwater probes will be installed for groundwater sampling. Site plan with proposed soil boring location is provided.3) Site Investigation Report, dated 12/20/2007. The GPR Survey did not identify any significant anomalies. Gasoline contaminated soil is present in the shallow soil in the northern and northwestern portions of the site. The gasoline contamination extends vertically to the deeper depths of the soil and horizontally to the northwestern boundary and western portion of the site. Soil samples collected from HTE-SP-2, 662,600 ppb VOCs at 2'-4', 934,900 ppb VOCs at 10'-12'. Groundwater was encountered at 12 feet bg and flows to northwest. The compounds detected in the groundwater plume are mainly gasoline compounds, range ND to 79,300 ug/L.4) Remedial Action Plan, 12/14/2007. HydroTech proposed to have 1) soil excavation, down to 12'; 2) installation vapor barrier and sub-slab venting system; 3) RAP for groundwater will be submitted to NYSDEC. 5) Floor Plans for the new building. The new building will be occupied the whole site. Called Yash Saha (HydroTech). The excavation will cover the whole site and down to 12'-14', no dewatering is planned. DEC required the vapor barrier and sub-slab venting system design, groundwater remediation. HydroTech will submit a RAP including the soil excavation, groundwater remediation, and soil vapor mitigation shortly. (RJF)2/7/2008 - Feng - Reviewed the Revised RAP, 1/31/2008, by HydroTech. HydroTech proposed: 1) soil excavation; 2) installation of vapor barrier and sub-slab venting system; 3) RegenOx and ORC injections for groundwater remediation. Reviewed also the 3Q2007 quarterly report. During the tank excavation activities in 3/2007, monitoring wells MW-1, MW-5, MW-9 and EW-1 were destroyed. 7/11 wells

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

were sampled. BTEX range 73 ppb (MW-6) to 15,260 ppb (MW-4). MTBE range 18 ppb (MW-6) to 47,200 ppb (MW-4). Emailed HydroTech the comments and questions. (RJF)2/15/2008 - Feng - Stipulation Agreement to Katan Group. Due back 3/7/2008. (RJF)2/27/2008 - Feng - Received signed Stipulation Agreement. Sent for RD's signature. (RJF)3/3/2008 - Feng - Reviewed the Revised RAP, 2/13/2008, by HydroTech. Addressed the comments provided on 2/7/2008. Approval letter to Katan Group and cc to HydroTech. DEC require the vapor barrier to be extended vertically to the surface grade through the foundation walls and more RegenOx injection points to be installed. Revised the vapor barrier design and the injection diagram will be submitted within 10 days. (RJF)3/7/2008 - Feng - Spoke to D. Greffenius (Delta). BP will also oversee the remediation progress occurring onsite. An addendum letter/plan will be submitted for post-excavation sampling, dewatering plan in case dewatering is needed, and monitoring plan after the construction. BP will still continue to comply with the Stipulation between BP and DEC. (RJF)3/13/2008 - Feng - Stipulation Agreement executed 2/28/2008. (RJF)4/17/2008 - Feng - Email to HydroTech regarding the notification of chemox injection to EPA UIC program. HydroTech contacted EPA and it may take 30 days to have EPA review the details of the injections. Letter for offsite soil vapor point to HydroTech. 4/18/2008 - Feng - Call from HydroTech (Yash). HydroTech will inject the ORC while installing the soil vapor points. ORC will be injected at the sidewalk across the 4th Ave and some onsite injection points. (RJF)4/24/2008 - Feng - email from Yash Saha (HydroTech). HydroTech has finished the onsite ORC injection and the soil gas implants offsite. (RJF)5/1/2008 - Feng - Site visit. Met with Carlos Quinonez from HydroTech. The tech team was late. The work will be rescheduled. 5/2/2008 - Feng - Site visit and met with Yash Saha. Started RegenOx injection using GeoProbe. The intended injection points were marked. It will be drilled down to 25 feet and the RegenOx will be injected into the 25 feet to 16 feet. Planned to finish 10 point today. Offsite soil vapor sampling also ongoing. According to Yash, there will be some dewatering activities along with the development. Dewatering water will need to be treated. Met with D. Greffenius (Delta) in DEC office. Received the IRAP. (RJF)5/9/2008 - Feng - cc-d the EPA Underground Injection Control section's letter to Katan group for authorization to inject RegenOx and ORC. (RJF)6/12/2008 - Feng - Called from Yash (HydroTech). All the RegenOx injections are completed at this time. They started the site excavation on 6/4/2008, so far at 8 feet bg, and had some foundation pillars installed. The elevator shaft part has not worked on yet. At this time, no work on site, but may excavate deeper later on. DEC still requires groundwater samples to confirm the effectiveness of the RegenOx, taken gw samples from the previous baseline sampling points. 6/16/2008 - Feng - 4Q2008, 3/18/2008, by Delta. The monitoring well network was gauged and sampled on 1/17/2008. 7 wells. DTW 11.01' to 14.88' bg. Flows to northwest. BTEX range ND to 18,500 ppb (MW-10). MTBE range ND to 21,000 ppb (MW-4). 6/18/2008 - Feng - Portfolio meeting with BP and Delta. In 6/2008, soil removal is about 4,600 tons. Delta is submitting the final version of IRAP. The exhaust blowers planned for building's lower parking levels will control vapors. No sub slab venting system might be installed since the basement is so close to water table. Conference call with BP/Delta, Katan/HydroTech will be scheduled. (RJF)7/28/2008 - Conference call with Delta (D. Greffenius and G. Hinshalwood) and HydroTech (Rachel). Delta and HydroTech will be

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

sending the brief summary of the site status. (RJF)9/17/2008 - Vapor complaint from the resident across the street. DEC has contacted and required the developer (Perry Soskin from Katan Group) and the RP (BP) to immediately mitigate the vapor by today. Mr. Soskin from Katan Group and David Greffenius from Delta called back. Delta and EnviroTrac will be onsite and lay the plastic sheeting on the area today. They will there around 4:30pm. Tomorrow they will cover with a few loads of fills and more plastic sheeting on top of the fills if necessary. Called the resident David Simonoff and informed him that the responsible party will be onsite start taking of the odor today and DEC will continue to monitor the situation. (RJF)9/17/2008 - Site visit and met with Delta and EnviroTrac. The north portion of property near the 5th Street is filled with water, half foot to one foot deep. Delta and EnviroTrac lay the plastic sheeting on the watery area with some product, next to 4th Ave and east portion. A vac truck will be mobilized tomorrow morning and remove the water before the backfills. (RJF)10/16/2008 - Letter to Katan Group and BP requiring the developer/RP to submit a Revised RAP which include monitoring wells installation around the property to access the current and during construction groundwater condition, dewatering plan, post construction remediation plan if necessary, and post construction groundwater monitoring plan. Revised RAP due 11/17/2008. The Department notifies the city agencies, DOB, DEP, and DOH on the site status and its intended development. (RJF)10/29/2008 - 1Q2008, 7/25/2008, by Delta. Vacant. The monitoring well network was gauged and sampled on 3/6/2008. During tank excavation activities in 3/2007, MW-1, MW-5, MW-9, and EW-1 were destroyed. Due to construction onsite during first quarter 2008, all onsite wells are covered with soil and gravel and are suspected to be destroyed. 3 were were gauged (offsite wells). No LNAPL. DTW 14.04' to 14.78' bg. Flows to northwest. 3 were sampled. BTEX range ND to 407 ug/L (MW-7). MTBE range ND to 2.8 ug/L (MW-6). 2Q2008, 9/29/2008, by Delta. Vacant. The monitoring wells were gauged and sampled 6/30/2008. 3 offsite wells were gauged. No LNAPL. DTW 13.48' to 14.12' bg. flows to northwest. 3 wells were sampled. BTEX range ND to 486 ug/L (MW-7). MTBE range ND to 1.9 ug/L (MW-6). (RJF)11/10/2008 - Vapor complaint received from resident adjacent to the site. Visited the site, no access because the site was locked. Walked around the site and did not observe odor. No PID reading. Water retained in the open excavation again. (RJF)11/10/2008 - Email to Bill Bogdon approving the 60 days extension for RAP. (RJF)11/12/2008 - Delta and EnviroTrac were onsite to mitigate the vapor. A vac truck was mobilized and vac out the product in the property line area and water. Delta and EnviroTrac will then cover the area with product and rest of the water. They will come back tomorrow to see if water level rise again. Soil backfill may be done if necessary. (RJF)12/10/2008 - Email from David Greffenius (Delta)"Please note that Delta and EnviroTrac, on behalf of Atlantic Richfield, will be transporting additional backfill to the 363 4th Avenue, Brooklynsite this Friday, December 12, 2008, in order to fill-in the remainingstanding (ground) water at this site for the purpose of preventinganother vapor complaint by the residents in this neighborhood. Our plan will be identical to our last effort: we will cover thestanding water with plastic (where it is safe to do so), and then coverthe plastic/water with between 4 and 6 loads of recycled concreteaggregate (RCA) backfill."12/17/2008 - Spoke with David Greffenius (Delta). The excavation where been with water is backfilled. The product seems coming back again. Might need to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

investigate the adjacent parking lot. (RJF)12/18/2008 - Visited the site and met with David Greffenius. The site is backfilled in most of the area with water. Some water is still retained near the back apartment building. No product was seen this time. David will stop by regularly to check if there is any recharge of the product. SanBorn maps may be reviewed for the parking lot next door. (RJF)1/20/2009 - Met with Domenick Tonacchia (Tona Development), Bill Bogdon (Tona Development), Kevin Kleaka (Impact Environmental), and phone conference with David Greffenius (Delta). There will no dewatering. The building will be covered the entire site with cellar, no subcellar. There will be changes for the new building since they are trying to avoid dewatering process. DEC required an investigation work plan for both onsite and offsite by 2/2009. (RJF)3/20/2009 - Reviewed Investigation Work Plan, dated 3/3/2009, by Delta. Delta proposes to install 7 monitoring wells at the sidewalks around the perimeter of the site. Work to be scheduled and RI report to be due within 90 days, 6/19/2009. Work Plan is approved. Letter to BP and cc to Delta. (RJF) 3/23/2009 - Reviewed the Investigation Work Plan, dated 2/2009, by Leggette, Brashears & Graham, Inc (LBG). LBG proposes to install 4 monitoring wells onsite within the perimeter. Comments to LBG and Tona Development via email. see comments in eDoc. (RJF)3/24/2009 - Reviewed LBG's responses to the comments on the IWP, uploaded in eDocs. Additional comments on the responses were sent to LBG and Tona Development, in eDocs. (RJF)4/3/2009 - Reviewed the Updated IWP, via email on 3/25/2009, by LBG. Previous comments are addressed. Work plan to be approved. Letter to Tona Development and LBG. 4/3/2009 - Conference call with BP, Delta, Tona Development and LBG. The offsite wells installation will be started within 2 weeks. The onstie will be within 1 week. Tona Development will advance some test pits to verify the real water table and will notify BP 2 days in advance so BP could send a field technician to the site. Changes to the development plan will be made, the basement slab will be above water table. DEC require the RAP should include the vapor barrier and SSDS. Stipulation agreement will be sent to Tona Development. (RJF)4/6/2009 - Stipulation Agreement to 267 Sixth Street, LLC. eDocs. (RJF)4/28/2009 - Conference call with Tona Development and Delta. The onsite wells are installed and the report will be sent to DEC and Delta. Sewer line is identified beneath the sidewalk. A Con Ed oil line is also identified between the sidewalk and the site and might be extended into the site. Hand clearance will be made during the installation of the offsite wells. The test pits were advanced down to 9-10 feet below current grade, and found groundwater at 5 feet in one of them. Construction excavation will be above/at water table. Tona will be moving the soil around this week to make the ramp for the machines entrance. A plan to suppress the possible odor shall be in place before the excavation. And soil shall be tested for disposal and this enable the soil to be disposed immediated when being generated. Delta will review the Tona's recent investigation report to come up the IRAP, remedy to be proposed depend on the current site condition, soil and groundwater residual. Next updates call will be held upon the submission of IRAP. (RJF) 7/7/2009 - Reviewed Subsurface Investigation Report, dated 5/13/2009, by Leggette, Brashears & Graham, Inc. On April 9, 2009, the groundwater monitoring wells were installed onsite. Soil samples were collected continuously through the boring from the excavation grade to approximately 15 feet below the excavation grade. The final boring depth is approximately 20 feet below the historical grade of the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

site. The wells were surveyed. DTW 4.54' to 10.55'. no product was encountered, but film was observed. Soil samples run for VOCs and SVOCs. VOCs and SVOCs exceedances were detected, unit in ug/kg. MW-21, 10-15 feet, 920 benzene, 770 toluene, 30,000 ethylbenzene, 22,700 xylenes. MW-22, 5-10 feet, 6,200 benzene, 100,000 toluene,, 120,000 ethylbenzene, 400,000 xylene, 1,100 MTBE. MW-25, 10-15 feet, 1,500 benzene, 11,000 toluene, 43,000 ethylbenzene, 183,000 xylene. Groundwater samples were run for VOCs and SVOCs. Exceedances were detected, unit in ug/L. MW-21, 360 benzene, 300 toluene, 1,300 ethylbenzene, 1,480 xylene, 610 MTBE. MW-22, 230 benzene, 3,700 toluene, 2,300 ethylbenzene, 7,900 xylene, 28 MTBE. MW-25, 1,200 benzene, 620 toluene, 3,500 ethylbenzene, 6,200 xylene, 1,100 MTBE. And SVOCs were also detected in these wells. Compared to the historical soil and groundwater concentration levels, data show down trend for most of the wells. The data gained from this investigation will be used in preparing of the IRAP. Email BP and Delta for the status of the IRAP. (RJF)7/14/2009 - Conference call with Tona Development, BP and Delta. Delta is putting together the LBG's report data and the new building plan, the IRAP will be submitted next week. Delta is also going through the MTA permitting process to have the wells installed at the sidewalk along 4th Ave. There are probably 3-4 feet of soil to be removed, no dewatering. Film = sheet in LBG's report. DEC required there are shall be wells being able to monitor the effectiveness of Delta's proposed remedy. BP will gauge and sample the onsite wells after the perimeter wells are in. (RJF)1/4/2010 - Reviewed Work Plan for Offsite Monitoring Wells Abandonment, dated October 12, 2009, by Delta. Delta will abandon the three monitoring wells across 4th Ave, MW-6, MW-7 and MW-8. (RJF)1/12/2010 - Reviewed Subsurface Hydrocarbon Assessment Report Addendum, dated October 29, 2009, by Delta. On June 19, 2009, EnviroTrac, on behalf of Atlantic Richfield and under the direction of Delta, installed one permanent two-inch monitoring well (MW-13) at the northeast sidewalk of 6th Street using Geoprobe 6610 hollow-stem auger drill rig with direct push, macro-core sampling capability. MW-13 was drilled to 18 feet and groundwater was encountered at 12 feet. 2 soil samples were collected. MW-13 (11.5-12'), VOCs ND. MW-13 (19.5-20'), VOCs ND. On September 21, 2009, MW-13 as well as the monitoring wells onsite MW-20, MW-21, MW-22, MW-23, MW-24 and MW-15 were gauged and sampled. DTW 6.31' to 12.63' bg. NO LNAPL. unit in ug/L. MW-13, ND. MW-20, 7.6 benzene, 26 MTBE, 6 isopropylbenzene, 9.4 n-propylbenzene, 61 total VOCs. MW-21, 350 benzene, 290 toluene, 1,250 ethylbenzene, 860 xylene, 2,750 BTEX, 430 MTBE, 34 n-butylbenzene, 18 sec-butylbenzene, 87 isopropylbenzene, 10 p-isopropylbenzene, 520 naphthalene, 240 n-propylbenzene, 590 1,2,4-trimethylbenzene, 140 1,3,5-trimethylbenzene, 4,819 total VOCs. MW-22, 140 benzene, 810 toluene, 1,450 ethylbenzene, 420 xylene, 2,820 BTEX, 76 MTBE, 11 n-butylbenzene, 32 isopropylbenzene, 7.1 p-isopropylbenzene, 260 naphthalene, 60 n-propylbenzene, 250 1,2,4-trimethylbenzene, 100 1,3,5-trimethylbenzene, 3,621 total VOCs. MW-23, ND. MW-24, 21 MTBE, 27 total VOCs. MW-25, 1,100 benzene, 440 toluene, 2,790 ethylbenzene, 2,600 xylene, 6,930 BTEX, 390 MTBE, 25 n-butylbenzene, 15J sec-butylbenzene, 170 isopropylbenzene, 14J p-isopropylbenzene, 280 naphthalene, 300 n-propylbenzene, 830 1,2,4-trimethylbenzene, 400 1,3,5-trimethylbenzene, 9,354 total VOCs. Off-site Monitoring Well Abandonment Report, dated December 30, 2009, by Delta. On October 21, 2009, EnviroTrac, on behalf of Atlantic Richfield, abandoned offsite wells MW-6, MW-7 and MW-8 by 1)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

removing the bolt-down cover and riser cap from each well; 2) tremmie-filling each well screen and riser pipe with Portland cement/bentonite slurry from the bottom of the well to 5 feet bg using a grout pump; and 3) filling the top 5 feet of riser pipe and the flush-mount cover of the each well with Portland cement to the groundwater surface. (RJF)3/10/2010 - Neil Steven (646-542-4312) from Law Enforcement Region 2 called. Odor complaint from the residents. He went to the site yesterday, there was strong odor and dark product. Email to Nick Onufrak (BP), Bill Bogdon (Tona Development) and David Greffenius (Delta)."Bill and Nick,DEC received a odor complaint from the nearby residents for this site. Our ECO went to the site yesterday and he said there was strong odor and dark product was witnessed. You MUST send someone out there TODAY, to take pictures, sample the product, remove the product and mitigate the odor. If nobody is there today, we will send contractor out tomorrow and bill everybody. " Called and spoke with Nick Onufrak. He will call EnviroTrac and see what they can do, and give us an update by the end of today. Call Domenick (Tona Construction), he will send out someone to check out. Forwarded him the email since Bill is no longer with Tona. (RJF)3/10/2010 - email from Gordon Hinshalwood (Delta). "We investigated SS 13397 today in response to your email below. Some soil staining was identified in the rear area of the site, but free-phase NAPL was not identified on the standing water in the excavation, nor were hydrocarbon odors identified.We plan on delivering a frac tank to the property tomorrow afternoon and pumping the standing water out of the excavation (the volume of water is reportedly too large for a vac truck to handle). We will store the water in the tank on-site until we can arrange for it's proper disposal. We also intend to backfill the excavation to prevent further water accumulation on-site, which will likely happen on Friday, or early on next week."3/11/2010 - closed the spill 09-12838 opened for receiving the odor complain from Cynthia Simonoff and refer to spill 89-01904. Called Ms. Simonoff and told her that BP will be there this afternoon to vac the water out and will do some backfill by Friday. (RJF)3/11/2010 - NYCDEP called and claimed there was odor and product onsite. DEC Tibbe visited the site and met Dave Greffenius (Delta) and EnviroTrac. There was a petroleum odor but it was not significant. There was some floating product and sheen on the water in the excavation, and there was stained soil most of the way around the excavation, at water level. Delta was directed to sample the oil and excavate the stained soil. DEC also required addressing any floating product, if there is any, during the monthly gauging event. DEC emailed to Delta and required the submittal of RAP to address the soil and groundwater, regardless of the potential development, because the schedule is unknown. Draft prposal or a review of alternatives by 3/2010. (RJF)3/17/2010 - email from Nick Onufrak (BP). They will be onsite to pump out more water and backfill some of the excavation Wednesday and Thursday. Domenick (Tona Development) is aware of the work. DEC responded to the Yvonne Schmitz's inquiry. (RJF)4/7/2010 - received complaint and spill 1000269 was opened. DEC Spill staff visited the site. The responder did not detect any petroleum odors and from his vantage point outside the fence, could not see floating product, but he did see standing water in the excavation. DEC email to BP and Tona Development requiring that the issue of standing water in the excavation must be rectified in order to prevent future impacts to the area residents as well as reduce and/or eliminate future complaints. The only way could

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

be pumping out the water and completely fill the excavation to grade. DEC requires arrangements to complete this task immediately. Email from David Greffenius and attached with LNAPL Forensic Analysis Letter Report. Based on the fingerprinting forensic analysis of the sample collected from the top of the standing water, the floating oil was determined to be a relatively "fresh" diesel/fuel oil product probably released within the last two years. Based on BP's underground storage tank (UST) registration records, no diesel or fuel oil USTs were registered at the subject site from 1990 forward. 4/8/2010 - email from David Greffenius. EnviroTrac will begin water pumping operation tomorrow and site backfilling is scheduled for next week. 4/9/2010 - Letter from BP committing to address the odor complaint issue in a timely fashion and the spill remediation. 4/12/2010 - letter to NYC DOB, DOH, DEP notifying the open excavation issue at the site. 4/13/2010 - email from David Greffenius. Additional water pumping and removal, and site backfilling activities are scheduled to begin on Thursday, April 15. They are planning to bring in 1,000-1,500 yards of additional backfill material to the site (1,500-2,500 tons) over a 2-3 days period. checked spill 97-05330 at 278 6th Street. No investigation has been done at this site. PBS record 2-603857 at 383-393 4th Ave 278 6th Street show one 550-gallon kerosene (#1 fuel oil), one 275-gallon #2 fuel oil, one 4,000-gallon diesel, and one 4,000-gallon gasoline were removed in 3/2008. But no tanks closure report in file. 4/14/2010 - DEC Zhune called the owner of 278 6th Street. The property is sold already and he will call the consultant who did the closure to send the report in. 6/8/2010 - DEC responds to the Dailey News inquiry. Documentation of the backfill of the excavation including 3 photos taken after the backfill on 4/19/2010 were received from Delta. As seen from the photos, the backfill is up to the street level, and the monitoring wells are still in place. 6/9/2010 - DEC inspected the site around 9am and took some photos. No petroleum odors noticed. NO sign of contaminated soil was found. 4Q2009, 3/2/2010, by EnviroTrac. Currently a vacant lot. The monitoring well network was gauged and sampled on 12/28/2009. Due to site flooding several wells were inaccessible during the 12/2009 event (MW-21, MW-22, MW-23, MW-24 were under water) and were subsequently gauged and sampled on 1/22/2010. 6 wells were gauged. No LNAPL. DTW 3.76 - 12.82 (below existing grade?). Flows to northwest. historic flows to south. 6 wells were sampled. MW-24 was under water, not sampled. Max benzene 490 ug/L (MW-25). Max BTEX 2,820 ug/L (MW-25). Max MTBE 120 ug/L (MW-25). 1Q2010, 5/17/2010, by EnviroTrac. The monitoring well network was gauged and monitored on 3/25/2010. 7 wells were gauged. NO LNAPL. DTW 2.19 - 10.23' (below existing grade?). Flows to northwest. 7 wells were sampled. Max benzene 9.1 ug/L (MW-22). Max BTEX 248.6 ug/L (MW-21). Max MTBE 10 ug/L (MW-24). 7/20/2010 - Reviewed Remediation Work Plan for Chemical Oxidation Solution Pilot Application, dated July 12, 2010, by Delta. During the week of June 21, 2010, Delta installed 6 soil borings in the portion near the 4th Ave. SB-8 (12-13'), 1,302,600 ug/kg total VOCs. SB-8 (20-21'), 12,568 total VOCs. SB-9 (8-10'), 1,884 total VOCs. SB-9 (19-20'), 525 VOCs. SB-10 (7.5-10'), 828,240 VOCs. SB-10 (15-16'), 217 total VOCs. MW-14 (11-12'), 167,549 total VOCs. MW-14 (17-18'), 15,788 total VOCs. MW-15 (7.5-10'), 318,470 total VOCs. MW-15 (14-15'), 15,908 total VOCs. 3 soil borings turned into MW-14, MW-15 and MW-16. soil sample was not recovered and therefore no sample was collected for MW-16. Delta proposes to inject iron activated sodium persulfate and a pilot

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

will be conducted first. 2 application wells AW-1 and AW-2 will be installed in the northwest portion of the site. The application wells will be installed to 15 feet bg with 10 feet 4-inch diameter screen. 500 gallon of sodium persulfate/EDTA-chelated Fe(II) solution (0.50 kg/gal/0.01 kg/gal EDTA-Fe(II) as Fe) will be added into the two application wells. Surrounding wells MW-15, MW-16 and MW-22 will be monitored. Pre-application sampling will be included BTEX/MTBE, sulfate, DO, pH, ORP, and alkalinity. Sampling will be also conducted the day of the application, following day, and weekly for 2 weeks. Anticipated the pilot to be conducted the final week of 7/2010. ChemOx pilot work plan is approved. Report due 8/2010.10/26/10 The site is temporarily reassigned to Alex Zhitomirsky as per V. Brevdo and M. Tibbe. I went to the site today. There is some standing water and some residential garbage at the site. I could not smell any odor. An e-mail with my findings was sent to V. Brevdo and M. Tibbe. AZ 4/11/2011 - Spill transferred back to JFeng.6/24/2011 - On June 24, 2011, DEC reviewed the work plan proposing full scale ChemOx injection. Then DEC was also notified by the developer that they have financing coming into place and plan again to develop the site. A conference call was held on June 28th with BP, its consultant, and the property developer. The developer is planning to construct a building with a full basement that will cover the entire footprint of the property; with the basement only to a depth at which dewatering will not be needed. As such, BP will need to change plans - the developer agreed to provide us with their construction drawings, and BP agreed to provide a work plan for a focused investigation to determine whether they could over-excavate to remove remaining impacts; we also spoke about the need for continued gw monitoring which would likely need to include wells in the basement.8/1/2011 - Reviewed Soil Investigation Work Plan, dated 7/14/2011, by Antea Group. 8 soil borings were proposed in order to identify remaining soil contamination. Comments: the drilling should be beyond the historical contamination depth until hitting clean soil; sewer information in the sidewalk of 4th Ave; the 1997 misfiled oil burner replacement Block 987 Lot 11, but address 363 4th Ave; and if this site is a e-designated site under NYC DEP. 8/9/2011 - meeting with BP and Antea Group. Discussed the submitted IWP. DEC required the drilling down to the clean depth in order to vertically profile of the soil and identify remaining soil contamination. Revised IWP will be submitted. 9/9/2011 - reviewed additional revision of the IWP submitted via email by Antea Group on 9/5/2011. "reduced" PID reading is defined as immeasurable reading. So soil samples from the water table interface, highest PID reading, reduced PID reading, and 3 feet below reduced PID reading will be taken. 9/9/2011 - approved IWP for installing 8 soil borings to assess the current soil condition. Report due 12/2011. 10/27/2011 - 2Q2011, 9/7/2011, by Antea Group. The groundwater samples were collected on June 6, 2011. 10 wells were sampled. NO LNAPL. BTEX concentration increased from the last quarterly sampling results. MW-14, 36,320 ug/L BTEX, less than 25 ug/L MTBE. MW-15, 8,230 ug/L BTEX, less than 5.0 ug/L MTBE. MW-21, 1,060 ug/L BTEX, 97 ug/L MTBE. MW-25, 195 ug/L BTEX, 21 ug/L MTBE. 11/22/11 - Raphael Ketani. Arnie Fleming of Fleming-Lee-Shue (212) 675-3225 called me today about the case. He said that FLS is the consultant for the new developer. The site has an "E" designation. He said that BP is moving slowly on remediating the site. However, the site was excavated and oil flowed out from the east wall. Mr. Fleming stated that there is a yard area that belongs to the condominium

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

building next door and that this would be a good place to do the investigation. However, the condominium has not been cooperative about letting BP's crew on the neighboring property. I told Mr. Fleming to send DEC the contact information for the condominium and we will pursue acquiring access for an investigation on their property. He said that he will. 11/22/2011 - As per Ketani, spill 11-10410 was generated for the offsite issue. 11/23/2011 - sent via email to Naftali Group LLC the stipulation agreement along with corrective action plan. As per DEC Ketani, sent letter notifying petroleum contamination at 270 Fifth Street and required investigation. Response is required within 15 days in receipt of the letter. Letter was sent to: 270 Fifth Street Corp. 270 Fifth Street Brooklyn, NY 11215BPC Management 84 Livingston Street Brooklyn, NY 1120111/29/2011 - Reviewed Investigation Summary Report, dated October 28, 2011, by Antea Group. 6 soil borings were installed in the central portion and western portion along 4th Ave of the site. The borings were advanced to 20 to 30 feet bgs where a peat layer was encountered. Very high total VOCs and SVOCs were detected in various location. For total VOCs in soil samples ug/kg, SB-26 (7.5-9) 54,300, (15-16) dark NAPL stain 17,801, (20-21), 30.2. SB-29 (10-11) 155,380, (13.75-14.25) odd staining 236,111, (27-28) 26.19. SB-30 (7.25-8.25) staining 251,429, (22.33-22.66) stain with product 18,287, (25-26.33) 23,781. SB-31 (3.5-4) 108,609, (9-10) odor sheen on acetate 1,017,620, (29-30) 8,217. SB-32 (3.5-4) 2,990, (10-15) 17,024, (20-22) 334.7. For SVOCs, SB-26 (15-16) 1,907,400. SB-30 (22.33-22.66) 1,653,800. Antea concluded that soil contamination were identified in the central area of the site and along western border by 4th Ave. Varied depth 3.5 to greater than 20' and soil staining showed visible evidence of a heavier than gasoline grade of hydrocarbon in some location. Excavation alone may not be possible to remediate. Will propose vapor barrier and SSDS and development of a post construction remediation strategy to address the impacts. 11/30/2011 - letter to BP and requiring a RAWP to be submitted by 1/2012. DEC require the contaminated soil to be excavated, install hydraulic barrier to prevent site recontamination by the seeping oil, and vapor barrier + SSDS for the future building. The letter which was sent to the apartment building was attached as per DEC Paul John's request. 12/9/11 - Raphael Ketani. Today there was a conference call with Arnie Fleming of Fleming Lee Shue, Hassan Hussein, head of the Hazardous Materials Unit, June Feng, project manager, and myself. Mr. Fleming commented about the oil seep that was coming in from the east side of the property. I told him that the DEC wanted BP to excavate down about 16 feet at each location that showed excessive contamination (above CP-51 standards). Mr. Fleming said that BP had made a determination that these locations were too deep to excavate. Wells would be put in the sidewalk. Mr. Fleming also stated that he had bad experiences with installing wells through a vapor barrier. Once you open the wells to sample them, then the vapors come out and the VOCs are suddenly high in the building. He added that his client, the latest developer, was willing to install a 150 foot long curtain to prevent the oil from seeping onto the property. They would excavate to 10 feet below grade, the foundation level, and drive sheeting along the east border. He suggested ordering a STIP for his client to hold him as responsible for installing the 150 foot long curtain wall. He said that he believed that chemical oxidation can work. The soil is sandy. He can use pressure pulse technology to treat the contamination. Mr. Fleming went on to describe how this

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

technology works and the benefits. After this, the conference ended.12/15/11 - Raphael Ketani. Today I received a response letter from Mr. Onufrak of Atlantic Richfield Company (ARCO). In the letter, Mr. Onufrak states that he is responding to DEC's 11/30/11 letter requesting a RAWP describing the excavation of the contaminated soil and the construction of a barrier in order to prevent the oil from the neighboring condo building from migrating onto the subject former BP property. Mr. Onufrak writes that ARCO disagrees with taking any responsibility for any off site oil that is migrating onto the property. However, he also wrote that the site owner, 267 Sixth Street LLC, is willing to pay for the barrier. ARCO will submit a RAWP for only excavating the contaminated soil at the site.12/16/11 - Raphael Ketani. I sent a response letter stating that ARCO should submit a RAWP just for the excavation. However, I added that the containment and cleanup of the off site oil should be worked out between 267 Sixth Street LLC, 267 Development LLC and the owners of the neighboring condo building (270 5th Street).responsible party: ARCO (BP #13397)owner of site: 267 Sixth Street LLCdeveloper: 267 Development LLCneighbor: 270 5th Street (condo)12/27/11 - Raphael Ketani. Kevin McGuinness (developer's consultant) (212) 675-3225 called. He said that the developer and BP have reached an agreement regarding the retaining wall for holding back the oil on the east side of the property. BP will submit a work plan for only the west side excavation and the developer will submit a work plan for only the retaining wall construction. This was being done because the developer is under a short time constraint whereby he has to start work by a certain date. I told Mr. McGuinness that the submission of two work plans was fine. Mr. McGuinness responded that the DEC should receive the wall work plan by January 9, 2012. I asked him who was the owner of the site. He said that it was still BP.1/5/12 - Raphael Ketani. I received the 1/4/12 Hydraulic Barrier RAP from Flemng Lee Shue for preventing the seepage of oil onto the site from the property to the east. I found the RAP to be acceptable for installing the steel sheet piling wall. I sent a letter to Mr. McGuinness stating this and an e-mail. I also had received the 1/3/12 Remedial Action Plan - Chemical Oxidation from the Antea Group. The basis of the plan was to use chemical oxidation and soil vapor intrusion to remove the contamination from the soil and the groundwater. Within the plan, there were diagrams showing the installation of piping for accessing the wells remotely after the site is developed and a building is constructed. The idea was that remediation would continue after site development. This I did not believe was a good plan. The reason being that if the treatment methods didn't perform as expected, then there would be no other options for the remediation, except natural attenuation. From the 9/28/-29/11 sample data in the work plan, the locations of concern for the soil contamination were SB-26 and SB-29 to SB-32. SB-26 = 7.5'-9' 54,300 ppb total VOCs; 15'-16' 17,801 ppb total VOCs and 1,907,400 ppb total SVOCsSB-29 = 10'-11' 155,380 ppb total VOCs; 13.75'-14.25' 236,111 ppb total VOCsSB-30 = 7.25'-8.25' 251,429 ppb total VOCs; 22.33'-22.56' 18,287 ppb total VOCs and 1,653,800 ppb total SVOCs; 25'-26.33' 23,781 ppb total VOCsSB-31 = 1.5'-4' 108,609 ppb total VOCs; 9'-10' 1,017,620 ppb total VOCs; 29.65'-30' 8,217 ppb total VOCsSB-32 = 10'15' 17,024 ppb total VOCs The locations of concern for the groundwater contamination were MW-14 (3/10/11 NAPL; 9/6/11 34,880 ppb total VOCs) and MW-15 (9/6/11 3,022 ppb total VOCs).I sent a letter approving the 1/3/12 RAP - Chemical Oxidation for conducting the work before the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

property construction. I disapproved the installation of the remote conduit piping before the building construction. In the letter, I also let the Antea Group know that they have to come up with an alternative method of remediation in the event that the treatment methods fail to achieve a level of remediation that is at or below the standards. 1/10/12 - Raphael Ketani. I sent an addendum letter to my 1/9/12 letter regarding the Chemical Oxidation RAP. In this letter, I stated that Atlantic Richfield has to delineate the off site groundwater contamination, as depicted in the last diagram in the 1/3/12 Chemical Oxidation RAP. The diagram shows a hot spot of 16,385 ppb of total BTEX that abuts the fencing on the northwest side (4th Avenue). In the letter, I added that if the chemical treatments don't reduce the soil and groundwater contamination to or below the CP-51 standards, then they should consider excavation. Mr. Fleming (212) 675-3225 called in the morning. He tried to convince me to let the building be constructed first and have the piping for the solution treatment wells installed at the same time before the remediation takes place. I told him that my experience has shown me that this method doesn't usually work. I added that if the treatment solutions don't work, then everyone is stuck with high contamination below the new building. Mr. Fleming said that the developer is under a deadline to start the construction or else he will lose the money. I told Mr. Fleming that the idea of treating the soil and groundwater after the construction was unacceptable. Later in the morning Mr. Fleming called again. He said that the sheet piles could be made to go down more than 10 feet. He also stated that they could excavate the site generally down to 14 feet with no problems, excavate some small hot spots to 16 feet, and, if necessary, then drive the piling deeper and excavate further down. I told him this sounded alright. Mr. Fleming closed the conversation by stating that he will have a conference call with his client and Atlantic Richfield in a few minutes to discuss the plan. 1/19/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called today. We had a 30 minute phone conversation regarding the site. He argued for having DEC give a verbal approval to allow the construction company to put in piles and excavate generally to 10 feet down. He said that, at that point, they would dig out the contaminated soil in places down to 13 feet (this was 3 feet shallower than he had told me before). Then BP would inject lots of treatment solution into the soil in order to break down the contamination. After this, access piping would be installed for possible future injections and groundwater monitoring. Then the building would be built. I told Mr. Fleming that with the building constructed, you can't take confirmatory soil samples in order to see whether the treatment solutions did the job of reducing the contamination. Mr. Fleming stated that we would know whether the contamination has been sufficiently reduced by monitoring the groundwater. If the groundwater concentrations are low, then the treatments are being successful. He added that more treatments would be able to take place if needed. I told Mr. Fleming that all of the hot spots should be dug out. That's the best way to deal with this. Mr. Fleming said that the edge of the property is right up against an 8 foot NYC sewer main and this main is between the site and the subway. I told Mr. Fleming that he had never stated this before. He said that he found this out yesterday when the owner sent him the building drawings. I asked him how deep this sewer was. He said that being 8 feet, it's one of Brooklyn's main sewers. So it must be at least 15 below grade. Mr. Fleming added that he had spoken to the NYC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

OER and had asked them what would satisfy their requirements for remediation of the site. He said that they told him "Whatever DEC wants." I told Mr. Fleming that this was not an answer and that we always want the contamination cleaned up first. Mr. Fleming said that his client was willing to wait several months for the injected solutions to do their work and then build. However, if this is going to drag on for a year or two, then his client will just walk away from the project. I told Mr. Fleming to send the DEC a letter describing what he is proposing with lots of pictures, diagrams and drawings showing the sewer and I will take a look at his proposal. However, I stated, "I will not promise him anything over the phone." He said that this didn't sound good, but he will send me the plan. 1/20/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me today. He said that he had spoken to his client and had worked out a plan whereby treatment solution injection and confirmatory soil sampling would be possible even with the foundation in place. I asked him how he would accomplish this. He said that 12 inch access ports would be built into the foundation so that drilling can take place in order to inject treatment solutions and take confirmatory samples. Then I asked him how additional treatment solution injections would take place. Mr. Fleming stated that special wells would be installed into the sidewalk that would have very long risers which would curve under the foundation and go into the water table. I told him to send me plans showing the access ports, the 8 foot sewer and the groundwater sampling wells. Mr. Fleming said that he will. Later in the day, Mr. Fleming sent me the plans (4/2/09 foundation plan and 1/29/12 groundwater well sampling plan). 1/23/12 - Raphael Ketani. I reviewed the plans and my notes from my conversations with Mr. Fleming on 1/19/12 and 1/20/12 and before. I sent Mr. Onufrak of ARCO, Mr. Hinshalwood of Antea and Mr. McGuinness of Fleming Lee Shue a letter approving the plan to construct the 12 inch diameter access ports and the groundwater monitoring wells with the very long risers. I stated in the letter that they should try to dig out as much of the contamination as is possible before embarking on the foundation construction. I included copies of the boring and well locations for every boring and well that had elevated VOCs and SVOCs since the project had begun. I also included copies of the DEC 1/9/12 letter warning of possible damage to the subway tunnel walls if they use sodium persulfate, and that they should include a work schedule for each step of the access port and well construction, and foundation construction. 1/30/12 - Raphael Ketani. Dan Cole of the NYC Office of Environmental Remediation (212) 341-0964 called regarding the site. He said that he wanted to have the owner install a much thicker vapor barrier that would be impervious to product, also. I asked him how thick a barrier. He said 20 MILS. I told him to send a letter to the owners with a "c-c" to me (after the owners agree to this) stating that the barrier will be 20 MILS. Mr. Cole said that he will. I received an e-mail from Mr. Cole as a "c-c." The e-mail was sent to Toni Finger of Kramer Levin (presumably the developer's lawyer). It stated that the OER needed several things in order to close out its review for the site: notarized affidavit from the buyer stating that the previously issued DOB job number will be used for development of the project; information about how the 20 MIL vapor barrier will be installed; a signed and stamped letter from Karl Fischer summarizing the full project description. Upon receipt of the above information, the OER will issue a Notice of No Objection. 2/1/12 - Raphael Ketani. On 1/31/12 and 2/1/12, the Naftali 1/31/12 OER Notice to Proceed, the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

Witek 1/30/12 Affidavit, the KFA Architects 1/30/12 Affidavit and the 1/1/12 Grace Letter were sent to Mr. Cole. On 1/31/12, Mr. Cole sent a Notice of No Objection to Mr. Finger for DOB Job No. NB-310071294.2/21/12 - Raphael Ketani. Peter Helseth of Fleming-Lee Shue sent an e-mail containing a document describing the use of steel sheet piling in combination with a sealant. This barrier system would be used to prevent oil from seeping onto the site. I responded back by stating that it was the responsibility of the consultant and the developer to make sure that the barrier is appropriate and efficaceous.2/24/12 - Raphael Ketani. Today, I received a letter from Gordon Hinshalwood, PhD. of Antea Group. In the letter Dr. Hinshalwood stated that the 1/3/12 Remedial Action Plan - Chemical Oxidation was being implemented. Excavation will take place generally to 13 feet below grade, and deeper where it is feasible to remove more contaminated soil. The additional soil impacts and the historical groundwater impacts were expected to be addressed by the actions described in the Remedial Action Plan. In addition, redevelopment is scheduled for 2/20/12. Once the basement level excavation is complete, then the ISCO application wells, associated piping and monitoring wells will be installed within 30 days. Also, during this time, the SSDS, vapor barrier and soil sampling access ports will be installed. Redevelopment will be completed in 12 to 24 months. After this time, the soil sampling ports will be sealed and the ability to evaluate the treatments will be very limited. The remedial activities schedule was included in the letter. The first round of solution applications will take place within 14 days of installing the wells. Three additional rounds of solution application are indicated (if this many will be necessary to treat the contamination). Post application soil and groundwater sampling will take place one month after each application. So Dr. Hinshalwood expects the entire remediation process to take no more than 12 months following the initial phase of construction.2/27/12 - Raphael Ketani. I sent an e-mail to Dr. Hinshalwood again warning him about the use of sodium persulfate near a subway structure and to contact the NYCT about its use at the site. I also again asked for the soil descriptions and calculations that were used to determine how much treatment solution would be necessary to remediate the contamination. I contacted the NYCT about the intended use of sodium persulfate by Antea Group, but I could only leave a message. Later, Dr. Hinshalwood called me in response to my e-mail. He said that Antea had contacted the NYCT regarding the proposed treatment solution injections and they are in the process for getting a permit to do the injections. Also, we discussed what type of information the DEC wanted in order to understand whether the solution injections will proceed as planned. Dr. Hinshalwood will send an addendum letter with the information.3/1/12 - Raphael Ketani. Peter Helseth, P.E. of Fleming-Lee Shue sent me an e-mail with an attachment showing an alternative product for use as a hydraulic barrier. 3/2/12 - Raphael Ketani. Dr. Hinshalwood sent me an e-mail today. He stated that Clean Earth of Carteret, NJ will be the destination for the contaminated soil that will be excavated. No soil will leave the site until he has an acceptance letter from Clean Earth.3/12/12 - Raphael Ketani. Dr. Hinshalwood sent me the "Addendum to Proposed Schedule for Implementation of Remedial Action Plan" dated 3/12/12 and produced by Antea Group. In the RAP, Dr. Hinshalwood explained that a permit application to use sodium persulfate was submitted to the NYCT on 2/22/12. Boring logs and Rockware software were used to create cross

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

sections of the site. The soils are predominantly sand and silty sand with peat in the central portion of the site. Soil porosity varies from 25% to 30%. Permeability is from 10-2 to 10-4 darcys, but is highly variable. Cross sectional diagrams were provided which depicted the lateral distribution of the sand, silty sand and peat in the subsurface. He also explained that a pilot test was conducted in the northwest corner of the property in the vicinity of MW-15 and MW-16. The treatment solution was injected into the 4' to 14' interval. It was found that AW-2 would only accept 150 gals. of solution over the course of a day. While AW-1 would accept up to 280 gals. of solution per day. Dr. Hinshalwood stated that, given the limited reagent volume to be used, it will not affect the subway. The volumes to be used per injection well will likely be 150 to 300 gals. per day. The solution density will be no more than 0.5 kg/gal. The total mass to be injected will be 2500 gals. for this round. This means that each injection well will receive about 75 gals. I responded back to Dr. Hinshalwood by e-mail that the DEC had accepted the RAP without comment, but that no work should proceed until the NYCT sends the permit for using the solution. Also, I stated in the e-mail that the DEC should receive a copy of this permit. 3/23/12 - Raphael Ketani. I called up Mr. Fleming (212) 675-3225 today. He said that the removal of the fill material will start April 1. The contaminated fill has been delineated. It will be disposed of. Test piles have been done for the foundation. The foundation plan calls for 14 or 16 soil sampling ports in the foundation floor. The barrier sheeting has been ordered. Fleming-Lee Shue will have someone on site everyday for air monitoring and construction - it is an OER requirement. 4/10/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called today. He said that they had wanted to drive the steel sheet piling between the neighboring condo building and the site. However, they found out that the building had already been damaged from vibrations caused by the previous demolition and excavation work to remove the old gas station. The condo building was built in 1911 and can't take any vibrations. The NYC Dept of Buildings has required that seismometers be placed next to the building in order to measure the vibrations. If there are significant vibrations, then all work will have to stop. Mr. Fleming said that this would make it impossible to install the steel sheeting as originally planned. However, he had an alternative method in mind. As the water table is about 20 feet down, he told me that after they have removed the cover soil down to 10 feet below grade, the construction company can dig a trench that extends 10 feet deeper along the property boundary with the condo property. Once this trench is constructed they will hand install, not drive, steel sheeting such that they will have a wall that is 20 feet high. The base of the steel wall will be below the water table and will be keyed into the future building foundation. The wall will be deep enough to stop the migration of the oil from the condo property which is appearing at 10 to 13 feet below grade. I told Mr. Fleming that this would be fine and to send me a new work plan. Mr. Fleming said that they are anxious to start the work and the DEC will receive the plan very soon. 4/25/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called to say that a UST was discovered below the neighboring condo property (spill #1110410 and #1200737). The contractors for Mr. Fleming were installing the required sheeting when they found free product running into the site from the neighbor's soil. They also saw that the neighbor's parking lot was sinking a couple of inches. They looked at the parking lot east of the building and found an old fill pipe. They

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

stuck a rebar down the pipe and came up with 2 feet of oil. The condo was contacted and they hired YU Associates to do a GPR survey. One 550 gal. tank was found. The tank was emptied and cleaned out and the oil stopped seeping onto the site. The tank will be removed. Mr. Fleming asked whether DEC would allow 267 Sixth Street LLC (alternate address for 363 4th Avenue) to not put in the steel sheeting - as it was intended to prevent oil from seeping onto the site. I told him that since the oil is not moving onto the site, there is no need for the sheeting and it can be left out of the development of the site. I asked Mr. Fleming whether the condo was going to dig out the contamination. Mr. Fleming said that they were talking about it, but they weren't moving. I told Mr. Fleming to suggest to Mr. Naftali that he let his contractor do the excavation and back bill the condo. Mr. Fleming said that this was presently being discussed as he already has his equipment and trucks on site. After this, the conversation ended. 5/2/12 - Raphael Ketani. Arnie Fleming of Fleming Lee Shue called. He is the consultant for the developer of the neighboring site to the west (363 4th Avenue; #8901904). He said that he was at the co-op site yesterday and the contractors had emptied and cleaned out the tank. Because of this, the oil seepage onto 363 4th Avenue had stopped. The tank on the co-op property was a 1,000 gals. and was 2 feet away from the border between the two properties. No piping was found associated with the tank. Mr. Fleming said that he was dewatering his client's property and no oil was flowing in. However, he told Mr. Yu of Yu & Associates that he should start digging out the contaminated soil around the tank as he will stop dewatering and then Yu & Associates will have to do their own dewatering in order to remove the contaminated soil. Mr. Yu said that he was waiting for the co-op board to meet in order to give him a decision regarding whether he can proceed with the remediation work. Mr. Yu also stated that an oil sample was sent off for fingerprinting. So everyone is waiting for the results. Mr. Fleming said that he emphasized to Mr. Yu that he should take advantage of the present dewatering because it will save him some money. Also, I sent an e-mail to Mr. Fleming stating that the steel sheeting didn't need to be installed as no oil was seeping onto the property and because the only purpose for installing the sheeting was to prevent the seepage. Later today, Rodney Rivera from the Regional Direction office of Region 2 came to the DER floor. He said that there had been a dust and petroleum odor complaint by someone from the co-op next door to Channel 11 News. Mr. Rivera was trying to find out what was happening at the site. I spoke to him and told him that this was the first time that I had been told there were dust and odor problems at the site. I also explained that excavation work was supposed to take place as part of the remediation of the site. However, I also told Mr. Rivera that the UST under the co-op property had just been cleaned out and had leaked oil into the ground. So this may also be a source of odors. Next, I spoke to one of the supervisors in the Spills Unit and he ordered a person in his unit to go and investigate the complaint. Next, I contacted Mr. Fleming (212) 675-3225. He said that he is aware that there are odors, but there isn't a significant problem with the dust. However, they are usually mild. However, there are instances of strong odors when they dig in the site to put the pile caps for the foundation. These odors usually affect a resident in the first floor of the co-op as his apartment is right next to the digging. Mr. Fleming also stated that this person's apartment is 5 feet from the newly discovered UST which was just cleaned out. So

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

there will be odors when the soil is dug out in this location. A consultant from PAL Environmental is walking around the site with a PID meter and checking the odor levels. The first floor apartment was investigated for odors, but they are mild. I told Mr. Fleming that he will have to come up with a solution to the odor problem in order to alleviate the issue for this resident. Mr. Fleming said that he will send the DEC a plan in writing, but they will first try sealing the person's windows with plastic and caulk so that there are no air leaks. Maybe this will solve the problem. I asked Mr. Fleming what he and his crew are doing about the odors. Mr. Fleming said that the odors only happen with the initial dig into a location and then they quickly dissipate. However, he is using biosolve (a masking agent). Also, Fleming Lee Shue is now starting to dig out the hot spots. I asked Mr. Fleming to keep me informed. He said that he will. The Spill investigator contacted DER from the site and reported back that presently there were no odors.5/7/12 - Raphael Ketani. Vanessa Meer of Yu & Associates (201) 791-0075, 116 called today and left a message. I tried to return her call, but could only leave a responding message.5/8/12 - Raphael Ketani. I spoke to Mr. Fleming (212) 675-3225 today. I told him that there had been another odor complaint and the EPA was now involved. He said that the neighbor who had been complaining was moved into a hotel across the street from his apartment building. I told him that was fine and I asked who had arranged this. He said that it was the contractor. I asked Mr. Fleming to find out the name of the person who was affected by the odors. Mr. Fleming said that he will. Mr. Fleming added that the odors are of gasoline, not fuel oil. So everytime they dig, some odors appear. He said that he has a guy walking around the site with a PID meter and checking that there are no exceedences of the 10 ppm standard. However, if there are, then the work stops to let the odors disipate. An odor suppressing material was put down, but it's not very effective.Mr. Fleming added that the NYC DOB came by and stopped the work. There's a stop work order. He doesn't know why this happened, but they usually don't get involved in odor complaints. On another note, Mr. Fleming said that they are presently dewatering the site and the water table has been depressed 3 feet. So, if the contractors from Yu & Associates want to, now is the time to dig out the soil contamination. I told Mr. Fleming that the co-op may not be ready to remediate the spill.5/9/12 - Raphael Ketani. I spoke to Ryan Piper, EG I of the Region Spills Unit, about the latest odor incident. He said that the odor incident was called into the Spills Hotline by the NYC DEP. The incident was assigned spill number 1200916. Mr. Piper told me that he went to the site, but didn't find any odors. I told him that the citizen who had been complaining about odors in his apartment had been moved to a hotel. I asked him whether he knew the name of the citizen. Mr. Piper said that he didn't. However, he said that the spill case had been closed and referred back to this one. Tona Construction and Management, 615 Baltic Street, Brooklyn, 11217 is the construction company. The contact is Michael Izzo, General Superintendent, at (718) 399-3800/cell (718) 825-9309.5/11/12 - Raphael Ketani. Steve Sangesland, Duty Desk Officer for the Region 2 Spills Unit, gave me a note that Matt Law (718) 593-9028 had tried to contact someone at the DEC regarding odors from the former BP station. I spoke to Mr. Law at length about the site, about the nature of the contamination (that is was just gasoline) and about the procedures for monitoring and managing the vapors and odors. He said that he was concerned that something else

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

had contaminated the site, other than gasoline. I asked him whether he was the resident who had been moved to the hotel. Mr. Law said that he was not and that he lives on the other side of the building from the site. He stated that he was glad that the DEC was aware of the situation and that the contractors were managing the odors. I explained that they are working to get rid of the contamination as fast as possible in order to alleviate the odors and that the building that will be built will have a vapor barrier and a passive vapor venting system. So this building will be safe to live in. With that, Mr. Law thanked me for all of the information and the conversation ended. 5/18/12 - Raphael Ketani. I received a copy of a letter today by e-mail from Antea Group. The letter was dated 5/16/12 and was sent by Antea Group in response to comments by the NYCT regarding the use of sodium persulfate to treat the contamination and the extent of the contamination. I reviewed the letter. From its contents, I determined that Antea Group had adequately responded to the NYCT's comments and concerns. 5/30/12 - Raphael Ketani. I received an e-mail today from Peter Helseth of Fleming Lee Shue. He stated that most of the foundation elements have been constructed on the site and the area for the foundation walls has been capped with clean stone. There is no more exposed soil, nor excavating taking place. So air monitoring has been stopped. 6/7/12 - Raphael Ketani. I received a call from Jay Solomon (212) 661-9400, the attorney for the Shepherd family that had been moved out of apartment 1G at 270 5th Street. He said that when the foundation was laid at the construction site next door, lots of oil vapors entered the apartment and the parents and two kids had to be moved into a hotel temporarily. However, he added that the foundation work has been finished. I told Mr. Solomon to contact the company responsible for the air monitoring and have them do a followup indoor air inspection just to be sure everything is alright. He said that the vapors had come from the construction site. I told him that the vapors would more likely come from the 1,080 gal. UST site because there is lots of contaminated soil there and this location is much closer to apartment 1G. Mr. Solomon didn't comment on this. I added that once the tank is removed, the contamination in the soil is exposed and the oil will vaporize. In any event, I said, it would be good to have a followup indoor air survey done of the apartment. I told him that Fleming Lee Shue was the consultant in charge of setting up the air monitoring and he should contact them. With that, the conversation ended. I tried to contact Mr. Fleming (212) 675-3225 regarding the attorney's request for another indoor air inspection, but I could only leave a message. Mr. Helseth from Fleming Lee Shue called in response to my message. He said that Mr. Fleming was out today, but he will take care of anything that's an issue. I explained that Mr. Solomon had called and wanted a vapor survey performed in his client's apartment. Mr. Helseth said that this will be done. I added that a vapor survey should also be done in the hallway outside the apartment, outside the building itself and next to the excavation area for the 1,080 UST. Mr. Helseth said that this will be done. Later, Mr. Fleming called. We discussed the issue of doing a PID survey in the Shepherd's apartment. I told him that the DEC also wanted a survey inside the building's hallway, just outside the apartment, just outside the apartment in order to get the ambient air concentrations, then next to the UST removal site and finally next to the border of the two concerned properties (condo and excavation site). Mr. Fleming said that he will talk to his client about this. Some time later, Mr. Fleming left a phone message that all

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

parties had agreed to do the vapor surveying. The co-op board was being contacted and it was hoped that the surveying will take place tomorrow, 6/8/12. Mr. Fleming stated that he will keep me posted. 6/8/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me regarding doing the vapor testing inside apartment 1G at the co-op and outside at the UST excavation location. Mr. Fleming told me that the lawyer told him not to enter the property and that Yu & Associates will do the work. I told Mr. Fleming that it didn't matter who was going to do the testing, just that the DEC gets the data. Later, I contacted Mr. Leung (201) 791-0075/cell (201) 310-2501 and explained that I wanted Yu & Associates to do the vapor survey. Mr. Leung said that more than one resident had been complaining about vapors from the BP site a while ago. I asked him whether they still were complaining. He said "No." Mr. Leung added that nothing is happening right now as he was told the DEC wanted to take a look at the soil delineation results first before more excavating takes place. I told him that was not true. I told him that the DEC wants Yu & Associates to move as quickly as possible to excavate the contaminated soil, then submit the end point results once all of the soil is removed, and then go forward with installing groundwater wells. Mr. Leung said that he thought this was what the DEC wanted. So he will mobilize his crew. 6/14/12 - Raphael Ketani. Mr. Fleming left me a message today. He said that one of his workers did a PID survey of the neighborhood. The only vapor detections were about 8 ppm just across the property fence with 270 5th Street. The detections were at the location of the open tank grave. Mr. Fleming added that the tank is sitting on the ground and hasn't been removed and the tank grave is uncovered. His worker was not able to do a PID survey of the Shepherd's apartment as he was not allowed access. 6/18/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called me regarding doing the neighborhood vapor survey. He said that the only detections were at the location of the tank removal next door. However, there is another construction site to the south across the street and they are doing dewatering. There is a 20,000 gal. Baker Tank for storing the recovered water on site before disposal. Mr. Fleming didn't know what the site used to be. He did state that the groundwater level always was a little lower than expected on the southern side of the site. Now he understands why. Lastly, he said that the developer is going to pour the concrete floor very soon. However, BP and Antea Group have not done the first round of treatment solution injections. By way of the timing for letting the treatment solutions do their work, they will miss the opportunity to do a second round of treatment (if necessary) if BP and Antea don't move quickly. Mr. Fleming said that he will keep me informed. I tried to contact Mr. Onufrak (410) 825-8213 regarding having the first round of treatment injections performed. However, I could only leave a message. Next, I contacted Dr. Hinshalwood at Antea (914) 495-9950. I told him that the developer was going to install the floor for the new building very soon and that BP and Antea should do the solution injections very soon. Otherwise, they may not have the opportunity to do them. Dr. Hinshalwood said that Antea has been in touch with the developer on a daily basis in order to know when there is a pause in the construction and they can do the injections. He said that the injections will take place in wells that will be installed at two depths throughout the site - as had been agreed upon. I told Dr. Hinshalwood that was correct, but Mr. Fleming had lead me to believe that doing the injections would not be possible as the floor would be

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

completed. Dr. Hinshalwood said that they would bore through the floor to install the needed wells. He added that he was not the project manager anymore. He said that the new project manager is Tim Fisher (914) 495-9935. He said that he will have Mr. Fisher call me regarding the project and the solution injecting. I told him that would be fine. As an alternate, Dr. Hinshalwood said, I could also talk to Chris Meyer (914) 495-9937, the portfolio manager, about the project. With this, the conversation ended. 6/19/12 - Raphael Ketani. Chris Meyer of Antea Group sent me the following e-mail: As a follow-up to the conversation you had yesterday with Gordon Hinshalwood, I thought this update was appropriate. I realize it's been a little while since we discussed this project. In accordance with the RAP that was approved by the NYSDEC on March 15th, last Friday (June 15), we completed the installation of the ISCO application wells and ground water monitoring wells along the western property boundary. Installation of the sub slab depressurization piping and soil vapor barrier was also completed last Friday by the developer. Per the email approval you provided to the developer on May 2, the steel sheeting was not installed by the developer. Yesterday (June 18), the developer poured the concrete slab for the building. Today, we are collecting baseline readings from the newly installed monitoring wells present along the western property boundary, as requested by the Transit Authority (TA). At this time we are in the process of coordinating the first ISCO application. We do not have a definitive schedule of when the first application will occur, but we expect it will be in July. 6/25/12 - Raphael Ketani. Mr. Meyer sent me an e-mail stating that the first ISCO is scheduled for Thursday, 6/28/12. 7/9/12 - Raphael Ketani. Mr. Fleming (212) 675-3225 called to say that the first injections took place about a week ago. 8/16/12 - Raphael Ketani. Mr. Fleming sent me an e-mail stating that BP installed the groundwater treatment injection pipes and performed the first injection about two weeks ago. However, they were not keeping him in the loop. The building is progressing and is well above grade. 8/22/12 - Raphael Ketani. I responded to Mr. Fleming's last e-mail and stated that there was a meeting with staff from BP yesterday. They had indicated that the building construction is moving forward and that 3 rounds of injections had already taken place. They were concerned that groundwater injection and confirmatory soil sampling access could be lost as the construction was moving so quickly that the access portals will be closed soon. I added that the groundwater samples to be taken after the treatment injections must be at or close to GA standards. If they are not, then more treatment will have to take place. If the foundation portals are closed up before the groundwater is sufficiently remediated, then the DEC will contact the NYC DOB and the NYC OER and tell them to hold off on issuing the Certificate of Occupancy. Mr. Fleming called me. He said that the soil confirmation access ports will remain open until next summer. The holes will be closed only just before the owner goes for his Certificate of Occupancy. 10/15/12 - Raphael Ketani. I tried to contact Tim Fisher (914) 495-9935 and Chris Meyer (914) 495-9937 of Antea Group, and Nick Onufrak (410) 825-8213 of BP regarding progress at the site and whether confirmatory soil borings had been taken and whether groundwater samples had been taken. However, I could only leave voice messages. Mr. Meyer called me back. The last injection was completed. All 8 applications have been completed. The sodium persulfate solutions and EDTA chelated iron are in the ground. On October 22, Antea is going out to do groundwater

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

and soil confirmatory sampling.10/18/12 - Raphael Ketani. Mr. Meyer called. He said that due to the crane still being in place for constructing the building, the sampling date has been pushed back to October 24.10/22/12 - Raphael Ketani. Mr. Meyer (914) 495-9937 called. He said that the soil and groundwater confirmatory sampling has been pushed back to November 5, 2012. The sampling will take 5 to 6 days.11/12/12 - Raphael Ketani. Mr. Fisher left me the following e-mail message today: Today we are beginning the process of collecting confirmation soil and grab ground water samples from below the building slab at former BP station 13397 to determine if impacts remain following the completion of ISCO applications. We expect site activities to last through this Thursday.1/9/2013 - Raphael Ketani. A conference call took place today between Nick Onufrak of BP-ARCO(410) 825-8213, Chris Meyer (914) 495-9937 and Gordon Hinshalwood (914) 495-9950 of Antea Group and myself. The subjects of the call were the groundwater and soil sample results and the Certificate of Occupancy for the building. Mr. Onufrak stated that they had received the soil and groundwater results after 8 rounds of solution injections had taken place. The results were not good. There wasn't much improvement. They wanted to know whether this would affect the ability of the building's owner to get the Certificate of Occupancy. I told him that the poor results will. I added that you can't have a building sitting over a pool of oil. The vapors will travel up the footings and into the concrete walls of the basement - bypassing the vapor barrier - and then into the building. Mr. Meyer stated that the building will have a vapor barrier and a passive venting system. I told everyone that another way to reduce the contamination has to be found. I added that I had another case with the same problem and they can't get a permanent C of O as they have oil seeping under the property. Their contamination was known, but the owner built his building anyway. I also said that the DEC would have to contact the NYC OER and they would let the NYC DOB know that someone has built on top of contamination that still exists. I asked whether the groundwater could be extracted. Mr. Meyer said that the wells can't pass a pump down the pipe. I asked whether just pushing a hose down each well would suffice. Mr. Onufrak and Mr. Meyer said that they will have to consider what can be done. They will send the DEC the report with the analytical results.Later, I talked to Dan Cole of the NYC OER and passed the above case notes to him via e-mail. He responded back by e-mail.1/10/13 - Raphael Ketani. I responded to Mr. Cole's 1/9/13 e-mail (see the e-docs). I stated in the e-mail that a meeting needed to be held with all parties in order to make everyone aware of the continuing existence of the oil and contamination below the site. We would also have to discuss what can be done to resolve this problem.1/24/13 - Raphael Ketani. The meeting took place as planned. In attendance were representatives from the owner's consulting company, the lawyer for the owner, BP, BP's consultants, BP's lawyer, Dan Cole from the NYC OER and myself. I brought up the issue that despite the numerous rounds of solution injections, the Department was informed that the contamination was still about as concentrated as before. I stated that an alternative means of remediation needed to be found and employed. Mr. Hinshalwood stated that only a 5% solution was used for the rounds of injections. As the site is next to the subway tunnel, this was the strength limit of the solution that the MTA would approve. I told Mr. Hinshalwood that this explained why the contamination hadn't been broken down. I again insisted that a remediation method be found to reduce or remove the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

soil contamination. I also stated that there was product on the water table. Mr. Onufrak and Mr. Meyer stated that they will start using a vacuum truck to collect the product from one well where they have seen free oil. I told them to submit a work plan and I gave them 30 days from today to do so. Mr. Onufrak said that this was enough time. Mr. Onufrak stated that two wells were destroyed during the building construction. I told him that the re-installation of the wells must be part of the work plan. I asked them when I will receive the soil confirmatory sampling data report. Mr. Meyer said that it was still going through internal review, but the DEC should receive it soon. The meeting ended with an agreement to present an alternative means of remediation. 2/1/13 - Raphael Ketani. Mr. Meyer (914) 495-9937 sent me an e-mail stating that a site visit was made on January 30 to see whether it was possible to position a vacuum truck near some of the wells in order to collect the groundwater. A location was found where the vacuum truck could park. So the first vacuum event will take place the week of February 11. Stingers will be used to collect groundwater from the observation wells. 2/7/13 - Raphael Ketani. Mr. Meyer sent me the following e-mail: The first VEFR event is scheduled to take place on Wednesday, February 13th. Six consecutive weekly VEFR events are planned. 2/15/13 - Raphael Ketani. I received the following e-mail from Mr. Meyer: The first VEFR event took place this past Wednesday, February 13th. The next VEFR event is scheduled for Wednesday, February 20th to gain additional information. We will also be submitting a VEFR work plan to you next week. I've also attached the report we've prepared to summarize a number of activities that were implemented as proposed in the Remedial Action Plan - Chemical Oxidation, dated January 3, 2012, the Proposed Schedule for Implementation of Remedial Action Plan addendum, dated February 22, 2012, and the Addendum to Proposed Schedule for Implementation of Remedial Action Plan, dated March 12, 2012. As such, the post-application sampling results we discussed during our meeting in January, are also presented. 2/19/13 - Raphael Ketani. I finished my review of the Antea Group 2/13/13 Remedial Action Summary Report. From 4/11/12 to 5/25/12, 7386 tons of contaminated soil were excavated and taken to Clean Earth of Carteret, NJ. Between 4/26/12 and 6/19/12, 75,297 gals. of groundwater accumulated on site and this was taken to Lorco Petroleum Services in Elizabeth, NJ as non-hazardous waste. The SSDS system was installed prior to construction of the foundation. It consisted of 4 inch schedule 40 PVC piping with 0.020 slots beneath the concrete basement slab. The piping was laid down in a layer of 3/4 inch crushed stone that is 4 feet thick with 3 risers extending through the slab, which will be extended to the roof. A Grace Preprufe 300R and 160R/Bithuthene 4000 vapor barrier was installed. Eight (8) soil borings were performed from 5/24/12 to 6/12/12. These borings were turned into wells OW-1A to OW-4A and OW-1B to OW-4B. The borings were started at the excavation floor, which was 10 feet bgs. OW-1A to OW-4A were drilled to 30 feet bgs. OW-1B to OW-4B were drilled to 20 feet bgs. The wells were installed along the western boundary of the property which is along 4th Avenue in order to monitor the sodium persulfate concentrations and the groundwater. During the same time interval, 16 soil borings were performed and were turned into wells for the purpose of injecting the treatment solutions. These wells were AW-1A to AW-8A and AW-1B to AW-8B. The borings started at the excavation floor. AW-1A were finished at 16 to 19 feet bgs and AW-1B to AW-8B were finished at 24 to 28 feet bgs. Each well was connected with a 2 inch diameter PVC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

hose.AW-1 (A,B) to AW-4 (A,B) and AW-7(A,B) were used to treat the soil and the groundwater under the western portion of the site. AW-3 (A,B), AW-6 (A,B) and AW-8 (A,B) were installed to treat the soil and groundwater under the central portion of the site. AW-5 (A,B) were installed in order to treat the soil and groundwater under the southwestern portion of the site. Soil samples were only taken from the deep B series of borings due to the proximity to the shallow A series of borings. No soil samples were taken from AW-1B or AW-7B. The analytical results showed exceedences at AW-2B to AW-4B, AW-6B, AW-8B, OW-1B to OW-4B. On 2/21/12 (dated as 2/21/13 in the report), groundwater samples were collected from MW-13, MW-15, MW-16, MW-20, MW-22 and MW-24. The VOC results for MW-13 were all non-detect. Those for MW-15 were extremely high. MW-16 had VOC results from just a little above the TOGS standards to below the standards. The results for MW-20 were all a little above the standards. MW-22 had 2 high VOC hits with the rest being low to moderate hits. MW-24 had hits from below to 3 a little above the standards. Pre-injection groundwater samples were taken on 6/19/12 from OW-1A to OW-4A and OW-1B to OW-4B. Each of the samples had exceedences for almost all of the TOGS 1.1.1 standards. All of the samples, except for OW-4B, had very high exceedences for total xylenes and ethylbenzene. OW-1A, OW-2A, OW-1B and OW-2B had very high exceedences for 1,2,4-trimethylbenzene. OW-2A, OW-2B, OW-3A and OW-3B had very high benzene exceedences. OW-1A, OW-2A, OW-2B, OW-3A and OW-3B had very high toluene exceedences. OW-1A, OW-1B, OW-2A and OW-2B had very high naphthalene and 1,3,5-trimethylbenzene exceedences. OW-1A, OW-1B and OW-2A had very high n-propylbenzene exceedences. Eight applications were performed from 6/28/12 to 9/20/12. The sodium persulfate solutions were applied over several rounds at a concentration of 50,000 mg/l for each individual injection. This concentration was required by the NYCT as they were concerned that stronger concentrations would affect the subway tunnel bordering the property under 4th Avenue. About 12,800 gals. of 50,000 mg/l solution was injected with ferrous iron as an activation chemical. Staff at Antea Group calculated that an injected concentration of 130,000 mg/l would degrade to 5,000 mg/l at the property boundary, which would further degrade to 15 mg/l at the tunnel. Post injection, 6 borings were performed from 11/12/12 to 11/14/12 to 26.5 to 38.5 feet bgs. These were SB-33 to SB-38. A seventh boring, SB-39, hit refusal at 17 feet bgs and SB-40 hit a void below ground and could not be completed. The analytical results for the soil samples from the 6 borings all had exceedences. SB-33 had extremely high VOC exceedences and many SVOC exceedences. SB-34 was tested only for VOCs and had high hits. The SB-35 results were a little above standards to non-detect. SB-36 had low to high VOCs and SVOCs exceedences. SB-37 had low VOC hits, but extremely high SVOC exceedences. SB-38 had extremely high VOC hits and low to moderate SVOC exceedences. The median soil contamination total concentrations increased after the injections from 12,330 ppb total VOCs to 22,869 ppb. The mean total soil SVOC concentrations decreased from 14,691 ppb to 3914 ppb. Groundwater samples were taken from 11/12/12 to 11/14/12. SB-33 had many very high VOCs, and SVOC exceedences. SB-34 and SB-35 had high to very high VOCs. The water sample from SB-36 had 5 high VOCs and many high SVOC hits. SB-37 had high to very high VOC hits and low to high SVOC hits. SB-38 had many very high VOCs and also SVOC exceedences. Later, groundwater was sampled on 1/8/13 from OW-1A, OW-1B to OW-4A, OW-4B. The groundwater samples from OW-1B, OW-2A, OW-2B and OW-3B had many very high VOC hits and SVOCs which

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

were mostly non-detect to low hits below TOGS with a few low exceedences. The sample from OW-4A had VOC hits from below the standards to 4 very high exceedences. OW-4B had VOC hits from below the standards to several moderate exceedences. I approved the data in the report as it gave a reasonable picture of the degree of soil and groundwater contamination below the site. However, it will remain to be seen how effective the VEFR events are in reducing the groundwater contamination. 2/21/13 - Raphael Ketani. I sent Mr. Hinshalwood (914) 495-9950, Mr. Meyer (914) 495-9937 and Mr. Onufrak (410) 825-8213 an e-mail stating that the DEC wanted groundwater to be sampled from the MW, AW and OW series of wells. Mr. Hinshalwood (914) 495-9950 responded back by e-mail stating that the MW series of wells were destroyed by the foundation construction, except for MW-13 which will be used to monitor the groundwater when the construction ends. Also, he stated that the AW series of wells were not accessible and wells OW-1A and OW-1B had been destroyed, but will be reinstalled. So only 9 wells will be available for monitoring. The OW series are all along 4th Avenue. MW-13 is along 6th Street along the southern border of the property. 2/25/13 - Raphael Ketani. I received the 2/22/13 Antea Group Vacuum Enhanced Fluid Recovery Work Plan. The purpose of the plan is to extract NAPL and contaminated groundwater. VEFR events will take place weekly. Wells OW-1A to OW-3A will be used for VEFRing. Stinger devices will be used in the wells to collect the total liquids. Vacuuming using a vacuum truck will be undertaken for a single well. During the vacuuming event, the radius of influence (ROI) will be determined. Vacuuming will be conducted for 2 hours at each observation well. At the end of each VEFR event, product and groundwater levels will be gauged. The volume of NAPL and groundwater collected will be measured and recorded. The vacuum will be measured every 30 minutes. Vapor concentrations will be measured every 15 minutes using a PID meter. Before any future solution injection applications are performed, it will be determined whether the ROI extends under the western border of the property. Data from the ROI and the VEFR events will be used to determine whether more extraction wells are needed. 2/26/13 - Raphael Ketani. I found the Vacuum Enhanced Fluid Recovery Work Plan to be acceptable with the comment that the product and groundwater gauging must take place before the VEFR or vacuum events take place. I added that monthly progress update reports must be submitted to the DEC by the third week of the month following the VEFR and vacuum events and gauging. The progress reports must include the NAPL and groundwater elevations, the amount of product recovered and the groundwater flow map. I also added that quarterly groundwater analytical reports must be submitted no later than 30 days following the date of sample collection. The sampling must be for the expanded lists of VOCs and SVOCs. I drafted a letter for the review of Mr. Hussein with the above approval and requirements. Mr. Hussein approved the letter and it was sent out. 3/1/13 - Raphael Ketani. Mr. Meyer (914) 495-9937 sent me the below e-mail today: Three vacuum enhanced fluid recovery events were conducted at former service station 13397 on February 13th, February 20th, and February 27th, 2013. The objective of these events was to recover any NAPL that may have been present (as was evident from a sampling event in one of the observation wells along Fourth Avenue in January), and to explore the potential for ground water recovery using this technology on the existing wells (OW-1 through 3), which are located under the newly-constructed building with remote access ports for sampling located in the sidewalk as proposed in the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

approved Vacuum Enhanced Fluid Recovery Work Plan dated February 22, 2013. Ground water samples were collected from Observation Wells OW-1A, OW-1B, OW-2B and OW-3B on February 27th and will be compared to the "baseline" ground water samples collected from the observation wells in January 2013 (before the VEFR events) to see if there is any significant change in VOC concentrations. Monitoring well MW-13 is located beneath some temporary infrastructure that is being used as part of the building construction. As such, it could not be sampled. To date, minimal water (115 gallons) and no measurable NAPL was recovered during the three extraction events, indicating that the practical application of this technology for hydraulic control is limited. Additionally, no significant vacuum influence was observed in surrounding wells during any of the extraction events, and vapor recovery was minimal as well, indicating that insufficient air flow was induced to mobilize significant vapor mass. Given these results, it is unlikely that this remedial approach will recover significant contaminant mass from the subsurface. At this point, no additional extraction events are planned, pending a review of the results of the ground water samples that were collected. Per your approval letter, we will be providing a more formal summary of these results in the third week of March. As I mentioned in my email on 2/21/13, efforts are also underway for Naftali to replace the two sidewalk wells that were destroyed during their construction activities (OW-1 and OW-3A).

-----I responded by e-mail stating that the Atlantic Richfield Company and Antea Group had to find a way of recovering the contaminated groundwater, even if this meant installing larger diameter wells or more wells. 3/6/13 - Raphael Ketani. Mr. Meyer sent me the contact information for the person at the MTA who approved the sodium persulfate treatment plan. This person is Rajen Udeshi (646) 252-3673. 3/7/13 - Raphael Ketani. I spoke Mr. Udeshi. He said that he didn't do the analysis to determine that a 5% solution was required. He added that he is a Principal Engineer and a structural engineer. However, he is only involved in coordinating the treatment solution application process. Mr. Udeshi told me that Emil Dul (dool), Principal Engineer, MTA Environmental Group, at (646) 252-2405 is the person who calculated what the treatment solution concentration should be. I spoke to Mr. Dul. Mr. Dul said that whenever a treatment project is proposed within 200 feet of an MTA tunnel or such, then the Six Agency rule comes into play. He said that the six agencies include the Fire Department, the NYC DOB and a few others. The rule is administered by the NYC DOB. The engineer or architectural drawings need the approval of the six agencies. He said that some time ago, a meeting took place between the consultants from Antea Group and staff from the MTA to discuss the proposed sodium persulfate treatment plan. Mr. Dul added that the MTA was concerned that the treatment solution not leave the site - in other words, be completely used up - so that the subway tunnel would not be affected. Mr. Dul said that once they had all of the information, then they considered the treatment plan, which included drawings showing the locations of the injections points. Staff from the MTA went over the calculations for obtaining the solution mixture that Antea Group wanted to use and what the expected concentration would be at the property boundary. However, Mr. Dul said, he was not sure of all of the details regarding what had transpired. So he wanted to call me back with the rest of his staff to discuss the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

matter. I told him that would be fine, but that I still wanted to know who in MTA had decided that a 5% solution was the correct concentration. Mr. Dul responded that Antea Group had proposed this in order to make sure the solution would be used up and to prevent its escape from the site. With that, the conversation ended. Later, Mr. Dul called me back and started a conference call with Derrick Braithwaite and Mary Kong, engineers from the MTA. Mr. Dul lead the conversation. He said that the MTA met with Antea Group on 3/27/12. They discussed the proposed treatment plan. On 5/16/12, the MTA sent Antea Group a letter with many questions regarding the injection plan. Antea Group later responded back. Mr. Dul was emphatic that the MTA never asked Antea Group why they were going to use a 5% solution. He added that they never challenged what Antea Group was proposing. The MTA's only concern was that the treatment solutions not contact the subway tunnel. Ms. Kong stated that they wanted sentinel wells installed (which Antea Group did). Antea Group told them that they modeled the injections and had confidence in the model. Mr. Braithwaite said that he went to the site twice to witness the injections. Mr. Dul stated that the MTA simply doesn't want anything getting near the concrete. As long as the groundwater is non-detect for persulfate, then they are happy. He added that the MTA doesn't approve the outside consultant's plans. They only accept them. With that, the conversation ended. 3/12/13 - Raphael Ketani. Mr. Meyer (consultant to BP) sent me an e-mail stating that wells OW-4A and OW-4B will be replaced today. 3/29/13 - Raphael Ketani. Mr. Meyer sent me the 3/22/13 Antea Group Progress Update Report. VEFR events took place on 2/13, 2/20 and 2/27. The wells used were OW-1A, OW-2A and OW-3A. OW-4A was not used as it had been destroyed. No NAPL was recovered during any of the events. Vapor concentrations in the wells were typically less than 100 ppm during each of the VEFR events. Groundwater was sampled on 2/27 and 3/7 from OW-1A, OW-1B, OW-2B and OW-3B. BTEX was very high in all of the samples and was up to 9840 ppb. Total VOCs ranged up to 11,321 ppb. The SVOCs were only slightly elevated. On 3/12/13, OW-4A-R and OW-4B-R were installed. 5/9/13 - Raphael Ketani. I spoke to Mr. Meyer (914) 495-9937 today regarding progress at the site. He said that Mr. Naftali, the owner, had replaced two wells that his construction crew had damaged. Presently, Antea is working on a work plan to install 6 new wells for groundwater monitoring and product/groundwater recovery. He said that these new wells will be straight instead of curved and so they will be able to do VEFRing. All of the wells will be installed along 4th Avenue. From the excavation along the sidewalk which took place in the past, Antea now knows where the utilities are. So they will be able to hand clear past the utilities and install the wells. Mr. Meyer said that he had the draft work plan on his desk. The final plan will be sent to the DEC soon. 6/24/13 - Raphael Ketani. I reviewed the 6/20/13 Well Installation Work Plan Notification. Antea Group plans to install up to 11 wells. Five of the wells will be installed in the existing 12 inch diameter sampling ports in the basement, SB-33 to SB-37. Three additional dual nested well clusters are also proposed along 4th Avenue. Each cluster will have a shallow screen from 5 to 20 bgs and a deep screen from 20 to 30 feet bgs. The wells will be 4 inches in diameter. The work is scheduled to start in late July. I approved the work plan with one comment. This regarded the nested pairs of wells that will be installed along 4th Avenue. The figure enclosed in this document shows that the wells in each pair will be closely spaced laterally. The Department is concerned

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

that this arrangement will allow for groundwater cross communication between each well. The construction must be modified in order to prevent this from happening. 8/6/13 - Raphael Ketani. As per the order of Paul John, Environmental Engineer IV/Regional Remediation Engineer, this BP spill case is being transferred to Jeff Vought in Region 2 Spills. Mr. Vought will be the new case manager effective today.

Remarks: TWO 4K TANKS FAILED PETRO. (1) LR = -0.448 GPH, (2) LR = GROSS.

Material:

Site ID: 90896
Operable Unit ID: 929176
Operable Unit: 01
Material ID: 2106611
Material Code: 1213A
Material Name: MTBE (METHYL-TERT-BUTYL ETHER)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True
Site ID: 90896
Operable Unit ID: 929176
Operable Unit: 01
Material ID: 449628
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: True

Tank Test:

Site ID: 90896
Spill Tank Test: 1535513
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

NY MANIFEST:

EPA ID: NYP000928358
Country: USA

Mailing Info:

Name: AMOCO SS C/O ISLAND TRANSPORTATION CORP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

Contact: HERBERT E LAUTH
Address: 299 EDISON AVENUE
City/State/Zip: WEST BABYLON, NY 11704
Country: USA
Phone: 516-694-4800

Document ID: NYB7846155
Manifest Status: Completed copy
Trans1 State ID: PD3678
Trans2 State ID: Not reported
Generator Ship Date: 960905
Trans1 Recv Date: 960905
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960905
Part A Recv Date: 961224
Part B Recv Date: 960923
Generator EPA ID: NYP000928358
Trans1 EPA ID: NYD986908085
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00500
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96

Document ID: NYG0123795
Manifest Status: Completed copy
Trans1 State ID: GX3213
Trans2 State ID: Not reported
Generator Ship Date: 970313
Trans1 Recv Date: 970313
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970317
Part A Recv Date: 970325
Part B Recv Date: 970325
Generator EPA ID: NYP000928358
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID: NYD980593636
Waste Code: B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity: 01326
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

SPILLS:
Facility ID: 0307900
Facility Type: ER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON ED - V 3685 (Continued)

1007205266

DER Facility ID: 82010
Site ID: 90895
DEC Region: 2
Spill Date: 10/27/2003
Spill Number/Closed Date: 0307900 / 10/27/2003
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 2401
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 10/27/2003
CID: 204
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/27/2003
Spill Record Last Update: 7/26/2004
Spiller Name: BRAD FISHER
Spiller Company: BP SERVICE STATION 13397
Spiller Address: 363 4TH AVENUE
Spiller City,St,Zip: BROOKLYN, NY
Spiller Company: 001
Contact Name: BRAD FISHER
Contact Phone: (914) 765-8198
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"VOUGHT"10/27/03. Ref. to spill # 8901904. YK.

Remarks: STILL UNDER INVESTIGATION

Material:
Site ID: 90895
Operable Unit ID: 874291
Operable Unit: 01
Material ID: 501426
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BF380
NW
1/8-1/4
0.207 mi.
1091 ft.
CON EDISON
522 WEST 44TH ST
NEW YORK, NY 10001
Site 10 of 10 in cluster BF

NY MANIFEST
S116293872
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004450615
Country: USA

Actual:
19 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL
Address 2: 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 2014-02-27
Trans1 Recv Date: 2014-02-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2014-03-10
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004450615
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 1136
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002327947GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S116293872

Generator Ship Date: 2014-02-24
Trans1 Recv Date: 2014-02-24
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2014-03-05
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004450615
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 455
Units: K - Kilograms (2.2 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 002327946GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

BD381 **CON EDISON SILO: 8693**
ENE **328 W 45TH ST**
1/8-1/4 **NEW YORK, NY 10036**
0.207 mi.
1093 ft. **Site 6 of 6 in cluster BD**

RCRA-CESQG **1016144144**
FINDS **NYP004269320**

Relative:
Higher

RCRA-CESQG:

Actual:
41 ft.

Date form received by agency: 09/19/2012
Facility name: CON EDISON SILO: 8693
Facility address: 328 W 45TH ST
NEW YORK, NY 10036
EPA ID: NYP004269320
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SILO: 8693 (Continued)

1016144144

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055461281

Environmental Interest/Information System

BL382
ESE
1/8-1/4
0.208 mi.
1096 ft.

CON EDISON
W 42 ST & 8TH AVE
NEW YORK, NY 10002

RCRA NonGen / NLR

1014398120
NYP004204715

Site 2 of 7 in cluster BL

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 03/23/2010
Facility name: CON EDISON
Facility address: W 42 ST & 8TH AVE
NEW YORK, NY 10002
EPA ID: NYP004204715
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: PATRICK HANLEY
Contact address: Not reported
Contact country: Not reported
Contact telephone: (347) 203-1475
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
43 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1014398120

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

BL383
ESE
1/8-1/4
0.208 mi.
1096 ft.

CON EDISON
W 42ND ST & 8TH AVE
NEW YORK, NY 10036
Site 3 of 7 in cluster BL

RCRA-CESQG 1012185054
NYP004158564

Relative:
Higher

RCRA-CESQG:

Actual:
43 ft.

Date form received by agency: 05/15/2008
Facility name: CON EDISON
Facility address: W 42ND ST & 8TH AVE
NEW YORK, NY 10036
EPA ID: NYP004158564
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: THOMAS COLUMBIA
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (646) 235-1328
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

1012185054

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

BL384
ESE
1/8-1/4
0.208 mi.
1096 ft.

CON EDISON - MANHOLE 32350
W 42 ST. & 8 AVE.
NEW YORK, NY 10008
Site 4 of 7 in cluster BL

RCRA-LQG **1014397061**
NYP004193785

Relative:
Higher

RCRA-LQG:

Actual:
43 ft.

Date form received by agency: 03/23/2010
Facility name: CON EDISON - MANHOLE 32350
Facility address: W 42 ST. & 8 AVE.
NEW YORK, NY 10008
EPA ID: NYP004193785
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: FRANKLYN MURRAY
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (212) 460-2808
Contact email: MURRAYFR@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON - MANHOLE 32350 (Continued)

1014397061

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/15/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/15/2009
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 09/06/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

BL385
ESE
1/8-1/4
0.208 mi.
1096 ft.

NYCTA - W 42ND ST & 8TH AVE STATION
W 42ND ST & 8TH AVE
NEW YORK, NY 10019
Site 5 of 7 in cluster BL

RCRA-CESQG **1001124767**
NY MANIFEST **NYR000030429**

Relative:
Higher

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: NYCTA - W 42ND ST & 8TH AVE STATION
Facility address: W 42ND ST & 8TH AVE
NEW YORK, NY 10019
EPA ID: NYR000030429
Mailing address: AVE OF THE AMERICAS NYCTA
NEW YORK, NY 10019

Actual:
43 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Contact: Not reported
Contact address: AVE OF THE AMERICAS NYCTA
NEW YORK, NY 10019
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: NEW YORK CITY TRANSIT AUTH
Owner/operator address: 1550 AVE OF AMERICAS
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 424-4668
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY TRANSIT AUTH
Owner/operator address: 1550 AVE OF AMERICAS
NEW YORK, NY 10019
Owner/operator country: US
Owner/operator telephone: (212) 424-4668
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: NYCTA - W 42ND ST & 8TH AVE STATION
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: NYCTA - W 42ND ST & 8TH AVE STATION
Classification: Not a generator, verified

Date form received by agency: 10/07/1996
Site name: NYCTA - W 42ND ST & 8TH AVE STATION
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYR000030429
Country: USA

Mailing Info:

Name: NYCTA
Contact: NEW YORK CITY TRANSIT AUTH
Address: 2 BROADWAY
Address 2: ROOM A27.64
City/State/Zip: NEW YORK, NY 10004
Country: USA
Phone: 646-463-1949

Document ID: 07
Manifest Status: 001875453JJK
Trans1 State ID: NYR000030429
Trans2 State ID: Not reported
Generator Ship Date: NJD991291105
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD980772768
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 20
Handling Method: P
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 7/3/2007
Trans1 Recv Date: 7/3/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 7/3/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 20
Units: P - Pounds
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 001875453JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2010-01-06
Trans1 Recv Date: 2010-01-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-01-06
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Waste Code: Not reported
Quantity: 80.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 001056933GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 106.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 98.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 160.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: NYG2972952
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 10/04/2001
Trans1 Recv Date: 10/04/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/18/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 0440375ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00300
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG3206457
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 12/05/2001
Trans1 Recv Date: 12/05/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/13/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 0440375ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00500
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG2973249
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 08/24/2001
Trans1 Recv Date: 08/24/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/12/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 0448290ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 01600
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 2008-07-09
Trans1 Recv Date: 2008-07-09
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-07-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NYD049836679
Waste Code: Not reported
Quantity: 100.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 003711955JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H132

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 2008-07-12
Trans1 Recv Date: 2008-07-12
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-07-23
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: Not reported
Quantity: 550.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 003553726JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H132

Document ID: NYG3318066
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 05/07/2002
Trans1 Recv Date: 05/07/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/15/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Trans2 EPA ID: Not reported
TSDF ID: 0440375ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00100
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3318615
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 03/08/2002
Trans1 Recv Date: 03/08/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/25/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 0440375MA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00400
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2002

Document ID: NYG3544371
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 11/08/2002
Trans1 Recv Date: 11/08/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/11/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: 0440375ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Year: 2002

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2011-02-04
Trans1 Recv Date: 2011-02-04
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-02-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 110.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 001056755GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 2007-07-03
Trans1 Recv Date: 2007-07-03
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2007-07-03
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 20.0
Units: P - Pounds
Number of Containers: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2007
Manifest Tracking Num: 001875453JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 160.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 106.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-07-17
Trans1 Recv Date: 2009-07-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-07-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 98.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 000958689GBF
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NYCTA - W 42ND ST & 8TH AVE STATION (Continued)

1001124767

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: NYG2773899
Manifest Status: Not reported
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 05/05/2003
Trans1 Recv Date: 05/05/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/13/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030429
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSD ID: 0440465ME
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00150
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

[Click this hyperlink](#) while viewing on your computer to access
5 additional NY_MANIFEST: record(s) in the EDR Site Report.

**BL386
ESE
1/8-1/4
0.208 mi.
1096 ft.**

**CONSOLDATED EDISON
W 42ND ST & 8TH AVE
NEW YORK, NY**

**NY MANIFEST S109155561
N/A**

Site 6 of 7 in cluster BL

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004158564
Country: USA

**Actual:
43 ft.**

Mailing Info:
Name: CONSOLDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PL RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109155561

Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2008-05-15
Trans1 Recv Date:	2008-05-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-05-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004158564
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001450793FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2008-05-15
Trans1 Recv Date:	2008-05-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-05-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004158564
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NYD077444263
Waste Code:	Not reported
Quantity:	80.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109155561

Manifest Tracking Num: 001450793FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-05-15
Trans1 Recv Date: 2008-05-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-05-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004158564
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 80.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 2.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001450793FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-05-15
Trans1 Recv Date: 2008-05-15
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109155561

TSD Site Recv Date:	2008-05-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004158564
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NYD077444263
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001450793FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	2008-05-15
Trans1 Recv Date:	2008-05-15
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-05-20
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004158564
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NYD077444263
Waste Code:	Not reported
Quantity:	80.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	001450793FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109155561

Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 2008-05-15
Trans1 Recv Date: 2008-05-15
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2008-05-20
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004158564
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: Not reported
Quantity: 50.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1.0
Year: 2008
Manifest Tracking Num: 001450793FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

BL387
ESE
1/8-1/4
0.208 mi.
1096 ft.
CONSOLIDATED EDISON
W 42 ST. & 8 AVE.
NEW YORK, NY 10008
Site 7 of 7 in cluster BL

NY MANIFEST **S110045768**
N/A

Relative: NY MANIFEST:
Higher EPA ID: NYP004193785
Country: USA

Actual:
43 ft. Mailing Info:
Name: CONSOLIDATED EDISON
Contact: CONSOLIDATED EDISON
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S110045768

Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-09-06
Trans1 Recv Date: 2009-09-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-09-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004193785
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 5500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001031293JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: Y
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-09-06
Trans1 Recv Date: 2009-09-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-09-08
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004193785
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 5500.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S110045768

Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001031293JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: Y
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

**BM388
ESE
1/8-1/4
0.209 mi.
1102 ft.**

**CON EDISON SERVICE BOX: 32367
672 8TH AVE
NEW YORK, NY 10017**

**RCRA-CESQG 1016144005
FINDS NYP004267928**

Site 1 of 2 in cluster BM

**Relative:
Higher**

RCRA-CESQG:

Date form received by agency: 09/12/2012

Facility name: CON EDISON SERVICE BOX: 32367

Facility address: 672 8TH AVE
NEW YORK, NY 10017

EPA ID: NYP004267928

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 32367 (Continued)

1016144005

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055457820

Environmental Interest/Information System

**BM389
ESE
1/8-1/4
0.209 mi.
1102 ft.**

**CON EDISON
672 8TH AVE
NEW YORK, NY 10017**

**NY MANIFEST S112210606
N/A**

Site 2 of 2 in cluster BM

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004267928
Country: USA

**Actual:
43 ft.**

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-11
Trans1 Recv Date: 2012-09-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004267928
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210606

Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456621JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-11
Trans1 Recv Date: 2012-09-11
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-13
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004267928
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456621JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BH390
SSW
1/8-1/4
0.209 mi.
1102 ft.

CON ED
505 9 AVE
NEW YORK, NY 10018
Site 5 of 8 in cluster BH

NY MANIFEST
S116295786
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004470431
Country: USA

Actual:
33 ft.

Mailing Info:
Name: CON ED
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2014-03-18
Trans1 Recv Date: 2014-03-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2014-03-19
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004470431
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 012354086JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BG391
South
1/8-1/4
0.209 mi.
1102 ft.
WEST SIDE LOFTS LTD
347 WEST 39TH STREET
NEW YORK, NY 10018
Site 3 of 3 in cluster BG

NY AST
U004077665
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-360554
Program Type: PBS
UTM X: 585081.96267000004
UTM Y: 4512162.4264500001
Expiration Date: 10/14/2018
Site Type: Apartment Building/Office Building

Actual:
35 ft.

Affiliation Records:

Site Id: 18168
Affiliation Type: Facility Owner
Company Name: WEST SIDE LOFTS LTD
Contact Type: WEST SIDE LOFTS
Contact Name: EILEEN ALUSKA
Address1: 1740 BROADWAY, 2ND FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 247-2603
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/23/2013

Site Id: 18168
Affiliation Type: Mail Contact
Company Name: ORSID REALTY CORP
Contact Type: Not reported
Contact Name: COMPLIANCE DEPARTMENT
Address1: 1740 BROADWAY
Address2: 2ND FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 247-2603
EMail: ZMAGID@ORSIDR.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 9/23/2013

Site Id: 18168
Affiliation Type: On-Site Operator
Company Name: WEST SIDE LOFTS LTD
Contact Type: Not reported
Contact Name: CHRIS CLOTTIN
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST SIDE LOFTS LTD (Continued)

U004077665

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 563-2827
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18168
Affiliation Type: Emergency Contact
Company Name: WEST SIDE LOFTS LTD % ORSID REALTY CORP.
Contact Type: Not reported
Contact Name: EILEEN ALUSKA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 247-2603
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/20/2008

Tank Info:

Tank Number: 001
Tank Id: 10440
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
L00 - Piping Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1928
Capacity Gallons: 6000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST SIDE LOFTS LTD (Continued)

U004077665

Register: True
Modified By: MSBAPTIS
Last Modified: 09/23/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

BN392
SSE
1/8-1/4
0.209 mi.
1103 ft.

DIVISION OF PAROLE
314 WEST 40TH STREET
NEW YORK, NY 10018
Site 1 of 7 in cluster BN

NY UST **U004076229**
N/A

Relative:
Higher

UST:

Actual:
38 ft.

Id/Status: 2-056502 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/28/2015
UTM X: 585189.99927000003
UTM Y: 4512179.6553499997
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 929
Affiliation Type: Mail Contact
Company Name: GOULD 40TH ST LLC
Contact Type: VICE PRESIDENT
Contact Name: DANIEL LEMBO
Address1: 60 CUTTERMILL RD SUITE 303
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 466-3100
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2/28/2013

Site Id: 929
Affiliation Type: On-Site Operator
Company Name: DIVISION OF PAROLE
Contact Type: Not reported
Contact Name: ALAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 594-3360
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/30/2007

Site Id: 929
Affiliation Type: Emergency Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIVISION OF PAROLE (Continued)

U004076229

Company Name: GOULD 49TH ST LLC
Contact Type: Not reported
Contact Name: ALAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 807-3992
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/30/2007

Site Id: 929
Affiliation Type: Facility Owner
Company Name: GOULD 40TH ST LLC
Contact Type: VICE PRESIDENT
Contact Name: DANIEL LEMBO
Address1: 60 CUTTERMILL RD SUITE 303
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 466-3100
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2/28/2013

Tank Info:

Tank Number: 001
Tank ID: 1902
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIVISION OF PAROLE (Continued)

U004076229

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I00 - Overfill - None

BN393 **DIVISION OF PAROLE**
SSE **314 WEST 40TH STREET**
1/8-1/4 **NEW YORK, NY 10018**
0.209 mi.
1103 ft. **Site 2 of 7 in cluster BN**

NY HIST UST **U003074301**
NY AST **N/A**

Relative:
Higher

HIST UST:

Actual:
38 ft.

PBS Number: 2-056502
SPDES Number: Not reported
Emergency Contact: VINCENT MATTEO
Emergency Telephone: (718) 951-9397
Operator: DANIEL LEMBO
Operator Telephone: (212) 594-3360
Owner Name: MAJESTIC PROPERTIES-DAN LEMBO
Owner Address: 60 CUTTER MILL ROAD
Owner City,St,Zip: GREAT NECK, NY 11021
Owner Telephone: (516) 466-3100
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Name: MAJESTIC PROPERTIES-DAN LEMBO
Mailing Address: 60 CUTTER MILL ROAD
Mailing Address 2: Not reported
Mailing City,St,Zip: GREAT NECK, NY 11021
Mailing Contact: Not reported
Mailing Telephone: (516) 466-3100
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: 314 WEST 40TH STREET
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 10/05/2001
Expiration Date: 12/02/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIVISION OF PAROLE (Continued)

U003074301

County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed Before April 1, 1991
Install Date: Not reported
Capacity (gals): 3000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Not reported
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
Lat/long: Not reported

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-056502
Program Type: PBS
UTM X: 585189.99927000003
UTM Y: 4512179.6553499997
Expiration Date: 12/28/2015
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 929
Affiliation Type: Mail Contact
Company Name: GOULD 40TH ST LLC
Contact Type: VICE PRESIDENT
Contact Name: DANIEL LEMBO
Address1: 60 CUTTERMILL RD SUITE 303
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 466-3100
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIVISION OF PAROLE (Continued)

U003074301

Date Last Modified: 2/28/2013

Site Id: 929
Affiliation Type: On-Site Operator
Company Name: DIVISION OF PAROLE
Contact Type: Not reported
Contact Name: ALAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 594-3360
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/30/2007

Site Id: 929
Affiliation Type: Emergency Contact
Company Name: GOULD 49TH ST LLC
Contact Type: Not reported
Contact Name: ALAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 807-3992
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 8/30/2007

Site Id: 929
Affiliation Type: Facility Owner
Company Name: GOULD 40TH ST LLC
Contact Type: VICE PRESIDENT
Contact Name: DANIEL LEMBO
Address1: 60 CUTTERMILL RD SUITE 303
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 466-3100
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2/28/2013

Tank Info:

Tank Number: 101
Tank Id: 1903

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIVISION OF PAROLE (Continued)

U003074301

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/1989
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

BN394 **V1056**
SSE **314 W. 40TH STREET**
1/8-1/4 **NEW YORK CITY, NY 10018**
0.209 mi.
1103 ft. **Site 3 of 7 in cluster BN**

RCRA NonGen / NLR **1007206916**
NY MANIFEST **NYP004033809**

Relative:
Higher

RCRA NonGen / NLR:

Actual:
38 ft.

Date form received by agency: 01/03/2001
Facility name: V1056
Facility address: 314 W. 40TH STREET
NEW YORK CITY, NY 10018
EPA ID: NYP004033809
Mailing address: CONSOLIDATED EDISON INC.
4 IRVING PLACE -- ROOM 300
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC.
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V1056 (Continued)

1007206916

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/02/2001
Site name: V1056
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V1056
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004033809
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0213715
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 04/07/1999
Trans1 Recv Date: 04/07/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/07/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004033809
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSDF ID: GX3213
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 01833
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

V1056 (Continued)

1007206916

Specific Gravity: 01.00
Year: 99

BO395
West
1/8-1/4
0.209 mi.
1106 ft.

CON EDISON SERVICE BOX: 7623
535 W 40TH ST
NEW YORK, NY 10018

RCRA-CESQG

1016143727
NYP004265096

Site 1 of 4 in cluster BO

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 08/27/2012

Facility name: CON EDISON SERVICE BOX: 7623

Facility address: 535 W 40TH ST
NEW YORK, NY 10018

EPA ID: NYP004265096

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

Used oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7623 (Continued)

1016143727

Violation Status: No violations found

BO396
West
1/8-1/4
0.209 mi.
1106 ft.

CON EDISON
535 W 40TH ST
NEW YORK, NY 10018

Site 2 of 4 in cluster BO

NY MANIFEST S112210339
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265096
Country: USA

Actual:
21 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265096
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456239JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210339

Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265096
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456239JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BO397
West
1/8-1/4
0.209 mi.
1106 ft.

CON EDISON
OPP 535 W 40TH ST
NEW YORK, NY 10018
Site 3 of 4 in cluster BO

NY MANIFEST **S112210336**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265062
Country: USA

Actual:
21 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210336

Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265062
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1600.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456240JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265062
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1600.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456240JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210336

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BP398
WSW
1/8-1/4
0.209 mi.
1106 ft.

CON EDISON
OPP 519 10TH AVE
NEW YORK, NY 10018
Site 1 of 7 in cluster BP

NY MANIFEST **S112210334**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265047
Country: USA

Actual:
27 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265047
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456238JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210334

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265047
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456238JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BP399
WSW
1/8-1/4
0.209 mi.
1106 ft.

CON EDISON SERVICE BOX: 43239
519 10TH AVE OPPOSITE
NEW YORK, NY 10018
Site 2 of 7 in cluster BP

RCRA-CESQG 1016143722
FINDS NYP004265047

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 08/27/2012
Facility name: CON EDISON SERVICE BOX: 43239
Facility address: 519 10TH AVE OPPOSITE
NEW YORK, NY 10018
EPA ID: NYP004265047
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported

Actual:
27 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 43239 (Continued)

1016143722

Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055421789

Environmental Interest/Information System

BI400 321 W 44 ST
East 321 WEST 44TH STREET
1/8-1/4 NEW YORK, NY 10036
0.210 mi.
1108 ft. Site 2 of 8 in cluster BI

NY AST U004048458
N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-192309
Program Type: PBS
UTM X: 585336.23315999995
UTM Y: 4512486.8667900003

Actual:
41 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

321 W 44 ST (Continued)

U004048458

Expiration Date: 12/28/2017
Site Type: Other

Affiliation Records:

Site Id: 6039
Affiliation Type: Mail Contact
Company Name: EAST END CAPITAL PARTNERS LLC
Contact Type: Not reported
Contact Name: NICK POLITO
Address1: 600 MADISON AVE. 11TH FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 600-2117
EMail: NYPOLITO@EASTENDMANAGER.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2013

Site Id: 6039
Affiliation Type: On-Site Operator
Company Name: 321 W 44 ST
Contact Type: Not reported
Contact Name: JASON CAMILLERI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 757-7420
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2013

Site Id: 6039
Affiliation Type: Emergency Contact
Company Name: EEGO WEST 44 OWNER LLC C/O EAST END CAPITAL PART
Contact Type: Not reported
Contact Name: JASON CAMILLERI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 757-7420
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2013

Site Id: 6039
Affiliation Type: Facility Owner
Company Name: EEGO WEST 44 OWNER LLC C/O EAST END CAPITAL PART

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

321 W 44 ST (Continued)

U004048458

Contact Type: OWNER
Contact Name: NICK POLITO
Address1: 600 MADISON AVE. 11TH FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 600-2117
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2013

Tank Info:

Tank Number: 002
Tank Id: 235942
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1960
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/19/2013
Register: True
Modified By: MSBAPTIS
Last Modified: 10/21/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 01
Tank Id: 11298
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

321 W 44 ST (Continued)

U004048458

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
G03 - Tank Secondary Containment - Vault (w/o access)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: 03
Date Test: 03/28/2000
Next Test Date: Not reported
Date Tank Closed: 06/28/2005
Register: True
Modified By: MSBAPTIS
Last Modified: 10/21/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 01A
Tank Id: 249984

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J01 - Dispenser - Pressurized Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/19/2013
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

321 W 44 ST (Continued)

U004048458

Modified By: MSBAPTIS
Last Modified: 10/21/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

BI401
East
1/8-1/4
0.210 mi.
1108 ft.

TECHNICOLOR
321 W 44TH ST
NEW YORK, NY 10036

Site 3 of 8 in cluster BI

RCRA-CESQG **1000243016**
NY MANIFEST **NYD092653831**
NY Spills

Relative:
Higher

RCRA-CESQG:

Actual:
41 ft.

Date form received by agency: 01/01/2007
Facility name: TECHNICOLOR
Facility address: 321 W 44TH ST
NEW YORK, NY 100365481
EPA ID: NYD092653831
Mailing address: W 44TH ST
NEW YORK, NY 10036
Contact: Not reported
Contact address: W 44TH ST
NEW YORK, NY 10036
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: TECHNICOLOR
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TECHNICOLOR
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: TECHNICOLOR
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: TECHNICOLOR
Classification: Not a generator, verified

Date form received by agency: 04/09/1992
Site name: TECHNICOLOR EAST COAST INC.
Classification: Large Quantity Generator

Date form received by agency: 12/18/1980
Site name: TECHNICOLOR
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 12/06/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

NY MANIFEST:

EPA ID: NYD092653831
Country: USA

Mailing Info:

Name: TECHNICOLOR
Contact: PELL LUZ CHEMIST
Address: 321 WEST 44 ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-582-7310

Document ID: NJO0216546
Manifest Status: Completed copy
Trans1 State ID: S8158AA
Trans2 State ID: Not reported
Generator Ship Date: 840516
Trans1 Recv Date: 840516
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840516
Part A Recv Date: 840530
Part B Recv Date: 840522
Generator EPA ID: NYD092653831
Trans1 EPA ID: NJD980525844
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00400
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 84

Document ID: NJA0173223
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: JA-195NJD
Trans2 State ID: NJDEP#S06
Generator Ship Date: 860130
Trans1 Recv Date: 860130
Trans2 Recv Date: 860131
TSD Site Recv Date: 860131
Part A Recv Date: 860227
Part B Recv Date: 860207
Generator EPA ID: NYD092653831
Trans1 EPA ID: NJD981138324
Trans2 EPA ID: NJD981138324
TSDF ID: NJD002454544
Waste Code: F001 - UNKNOWN
Quantity: 00383
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: U210 - TETRACHLOROETHYLENE
Quantity: 00580
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00610
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00230
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00087
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00017
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00009
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00068
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00235
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	Not reported
Year:	2005
Document ID:	NYG5055012
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	04/06/2005
Trans1 Recv Date:	04/06/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/11/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD092653831
Trans1 EPA ID:	56703PANY
Trans2 EPA ID:	Not reported
TSDF ID:	NYD077444263
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00028
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00008
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	Not reported
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00078
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	U122 - FORMALDEHYDE
Quantity:	00011
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: U044 - CHLOROFORM
Quantity: 00062
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: U210 - TETRACHLOROETHYLENE
Quantity: 00580
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00610
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00230
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00087
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00017
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYG2531016
Manifest Status: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 08/15/2001
Trans1 Recv Date: 08/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/23/2001
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: AZD982441263
Trans2 EPA ID: Not reported
TSD ID: Not reported
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00400
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG2513187
Manifest Status: Not reported
Trans1 State ID: PAD196717878
Trans2 State ID: PAR000501577
Generator Ship Date: 03/27/2006
Trans1 Recv Date: 03/27/2006
Trans2 Recv Date: 03/27/2006
TSD Site Recv Date: 04/06/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: PA263
Trans2 EPA ID: PA354
TSD ID: AZD982441263
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2006

Document ID: NJA0000158
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: NJSWAS284
Trans2 State ID: Not reported
Generator Ship Date: 841004
Trans1 Recv Date: 841004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 841004
Part A Recv Date: 851029
Part B Recv Date: 841109
Generator EPA ID: NYD092653831
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D000 - NON-LISTED TOXIC WASTES
Quantity: 00450
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 84

Document ID: NYB2078352
Manifest Status: Completed copy
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 900104
Trans1 Recv Date: 900104
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900109
Part A Recv Date: 900123
Part B Recv Date: 900119
Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NYB2092104
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 901127
Trans1 Recv Date: 901127
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901129
Part A Recv Date: 910409
Part B Recv Date: 910104
Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 130
Year: 90

Document ID: NJA1212014
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Trans2 State ID: Not reported
Generator Ship Date: 910522
Trans1 Recv Date: 910522
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910523
Part A Recv Date: 910703
Part B Recv Date: 910614
Generator EPA ID: NYD092653831
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00737
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 02452
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NYG2513187
Manifest Status: Not reported
Trans1 State ID: PAD196717878
Trans2 State ID: PAR000501577
Generator Ship Date: 03/27/2006
Trans1 Recv Date: 03/27/2006
Trans2 Recv Date: 03/27/2006
TSD Site Recv Date: 04/06/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: PA263
Trans2 EPA ID: PA354
TSDF ID: AZD982441263
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2006

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00009
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00068
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00235
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00028
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00078
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: U122 - FORMALDEHYDE
Quantity: 00011
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: U044 - CHLOROFORM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Quantity: 00062
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYB2092725
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PA6703
Trans2 State ID: Not reported
Generator Ship Date: 910206
Trans1 Recv Date: 910206
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910208
Part A Recv Date: 910403
Part B Recv Date: 910228
Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 130
Year: 91

[Click this hyperlink](#) while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID: NYD986983666
Country: USA

Mailing Info:
Name: CINERIC INCORPORATED
Contact: BALAZS NYARI
Address: 630 NINTH AVE
City/State/Zip: NEW YORK, NY 10036 3708
Country: USA
Phone: 212-586-4822

Document ID: NJO0216546
Manifest Status: Completed copy
Trans1 State ID: S8158AA
Trans2 State ID: Not reported
Generator Ship Date: 840516
Trans1 Recv Date: 840516
Trans2 Recv Date: Not reported
TSD Site Recv Date: 840516
Part A Recv Date: 840530
Part B Recv Date: 840522
Generator EPA ID: NYD092653831

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Trans1 EPA ID: NJD980525844
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00400
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 84

Document ID: NJA0173223
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: JA-195NJD
Trans2 State ID: NJDEP#S06
Generator Ship Date: 860130
Trans1 Recv Date: 860130
Trans2 Recv Date: 860131
TSD Site Recv Date: 860131
Part A Recv Date: 860227
Part B Recv Date: 860207
Generator EPA ID: NYD092653831
Trans1 EPA ID: NJD981138324
Trans2 EPA ID: NJD981138324
TSDF ID: NJD002454544
Waste Code: F001 - UNKNOWN
Quantity: 00383
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: U210 - TETRACHLOROETHYLENE
Quantity: 00580
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Specific Gravity: 01.00
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00610
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00230
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00087
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00017
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: NYG5055012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSD ID: NYD077444263
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00009
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00068
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00235
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00028
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00078
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: U122 - FORMALDEHYDE
Quantity: 00011
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: U044 - CHLOROFORM
Quantity: 00062
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: U210 - TETRACHLOROETHYLENE
Quantity: 00580
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00610
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00230
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00087
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG4651272
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/11/2005
Trans1 Recv Date: 04/11/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00017
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYG2531016
Manifest Status: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 08/15/2001
Trans1 Recv Date: 08/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/23/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: AZD982441263
Trans2 EPA ID: Not reported
TSDF ID: Not reported
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00400
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: NYG2513187

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Manifest Status: Not reported
Trans1 State ID: PAD196717878
Trans2 State ID: PAR000501577
Generator Ship Date: 03/27/2006
Trans1 Recv Date: 03/27/2006
Trans2 Recv Date: 03/27/2006
TSD Site Recv Date: 04/06/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: PA263
Trans2 EPA ID: PA354
TSD ID: AZD982441263
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2006

Document ID: NJA0000158
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: NJSWAS284
Trans2 State ID: Not reported
Generator Ship Date: 841004
Trans1 Recv Date: 841004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 841004
Part A Recv Date: 851029
Part B Recv Date: 841109
Generator EPA ID: NYD092653831
Trans1 EPA ID: NJD002200046
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D000 - NON-LISTED TOXIC WASTES
Quantity: 00450
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 100
Year: 84

Document ID: NYB2078352
Manifest Status: Completed copy
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 900104
Trans1 Recv Date: 900104
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900109
Part A Recv Date: 900123
Part B Recv Date: 900119

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NYB2092104
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: IA7667
Trans2 State ID: Not reported
Generator Ship Date: 901127
Trans1 Recv Date: 901127
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901129
Part A Recv Date: 910409
Part B Recv Date: 910104
Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSDF ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 130
Year: 90

Document ID: NJA1212014
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910522
Trans1 Recv Date: 910522
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910523
Part A Recv Date: 910703
Part B Recv Date: 910614
Generator EPA ID: NYD092653831
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00737
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 02452
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NYG2513187
Manifest Status: Not reported
Trans1 State ID: PAD196717878
Trans2 State ID: PAR000501577
Generator Ship Date: 03/27/2006
Trans1 Recv Date: 03/27/2006
Trans2 Recv Date: 03/27/2006
TSD Site Recv Date: 04/06/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: PA263
Trans2 EPA ID: PA354
TSDF ID: AZD982441263
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00600
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2006

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00009
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00068
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00235
Units: P - Pounds
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00028
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00008
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00078
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: U122 - FORMALDEHYDE
Quantity: 00011
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NYG5055012
Manifest Status: Not reported
Trans1 State ID: MAD985286988
Trans2 State ID: Not reported
Generator Ship Date: 04/06/2005
Trans1 Recv Date: 04/06/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/11/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD092653831
Trans1 EPA ID: 56703PANY
Trans2 EPA ID: Not reported
TSDF ID: NYD077444263
Waste Code: U044 - CHLOROFORM
Quantity: 00062
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: Not reported

Document ID: NYB2092725
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PA6703
Trans2 State ID: Not reported
Generator Ship Date: 910206
Trans1 Recv Date: 910206
Trans2 Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

TSD Site Recv Date: 910208
Part A Recv Date: 910403
Part B Recv Date: 910228
Generator EPA ID: NYD092653831
Trans1 EPA ID: NYD057722258
Trans2 EPA ID: Not reported
TSD ID: NYD057722258
Waste Code: F001 - UNKNOWN
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 130
Year: 91

[Click this hyperlink](#) while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

SPILLS:

Facility ID: 0503745
Facility Type: ER
DER Facility ID: 6032
Site ID: 348421
DEC Region: 2
Spill Date: 6/28/2005
Spill Number/Closed Date: 0503745 / 9/7/2006
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: qxabidi
Referred To: Not reported
Reported to Dept: 6/28/2005
CID: 406
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/28/2005
Spill Record Last Update: 9/7/2006
Spiller Name: UNKNOWN NAME
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 999
Contact Name: JACK DICKINSON
Contact Phone: (631) 586-5900
DEC Memo: 6/29/05 Tipple responded to site, #2FO covered floor in basement room, Demolition contractor appeared to have cut hole in tank while working in room, the 5000 gal. tank must be registered for removal. Building houses many recording studios and a club on the first floor,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

preventing olfactory impact to the populated areas is of upmost importance. Arco Env. finally arrived with the Vac truck for product removal and began cleanup. Product to be removed, final power wash may be completed Wed AM. 10/21/05 - Raphael Ketani. The associated PBS case is #2-192309. The 5,000 gal. tank has been closed and removed. I left messages for Jack Dickinson of ARCO Environmental ((631) 586-5900) and Henry Harde of GTO Construction ((914) 665-3600) asking them to call me back with information regarding the spill. 10/25/05 - Raphael Ketani. Henry Harde of GTO Construction called me back to say that his company was just the contractor for the cleanup. He said that the environmental company overseeing the work was Sextant Projects and that the person in charge was Walter Mystkowski ((631) 663-3144 cell). I called up Mr. Mystkowski and he said his company was in charge of the project. He asked for my e-mail address so that he could electronically send me the remediation report (wmyst@optonline.net). 12/21/05 - Raphael Ketani. I called Mr. Mystkowski and he said the submission of the remediation/cleanup report was being held up by a billing dispute between ARCO Environmental and Sextant Projects. I called up Mr. Dickinson of ARCO and he said he would send the report to me. 1/4/06 - Raphael Ketani. I left a message for Mr. Dickinson requesting the remediation/cleanup report. 07/20/06: This spill is transferred from Mr. Koon Tang to Q. Abidi. Contacted to Mr. Jack Dickinson (631) 586-5900 he said he will find out about the spill report and he will fax it to me at the earliest. -QA 07/24/06: Called Mr. Jack Dickinson regarding report of spill and left message to call me back. -QA 07/25/06: Contacted Mr. Jack Dickinson on phone (631) 586-5900 he said he didn't take any soil sample he will send me waste manifest report and closing confirmation letter by fax today. -QA 08/09/06: Called Mr. Jack Dickinson and asked to find out if there are any cracks in the basement floor or not. He said he will find out about it and he will fax me the letter very shortly. -QA 08/18/06: Called Jack Dickensen for closing confirmation letter. He was not there left message to call me back. -QA 08/21/06: Called Jack Dickinson (AARCO) at (718) 586-5900 He said that he will send letter for closing the spill at the earliest. Called Mr. Walter Mystkowski at (631) 663-3144 (cell) for sending report. He said he will talk to contractor GPL Construction then he will call me back. -QA 08/25/06: Called Mr. Walter Mystkowski to remind him to send report and left message to call me back. -QA 09/07/06: GTL Construction notified #2 fuel oil in office building basement. GTL contacted to AARCO to respond emergency clean up. According to the letter of operational manager (GTL Construction) Liquid vacuum truck recover 1,805 gallons of #2 Fuel oil/water. The load transported and disposed at N.Y. oil recovery under manifest. On the basis of information DEC Staff closed this spill. -QA
Caller estimates spill is a few hundred gallons. Material covers the entire floor to a 20 x 20 room. Looks like the breather valve broke (that is a guess) GTO Construction is on site. Spill is contained in the room (subfloor 12ft down). Unknown if spill is ongoing. No clean up at this time. Clean up crew ETA is 30min.

Remarks:

Material:

Site ID: 348421
Operable Unit ID: 1106075
Operable Unit: 01
Material ID: 1968568
Material Code: 0001A
Material Name: #2 Fuel Oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TECHNICOLOR (Continued)

1000243016

Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

BI402 WEST 44TH STREE HOTEL
East 306 WEST 44TH STREET
1/8-1/4 NEW YORK, NY 10036
0.210 mi.
1111 ft. Site 4 of 8 in cluster BI

NY UST U004118647
N/A

Relative:
Higher

UST:
Id/Status: 2-610785 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 07/18/2012
UTM X: 585327.36078999995
UTM Y: 4512448.9246500004
Site Type: Other

Actual:
41 ft.

Affiliation Records:
Site Id: 394825
Affiliation Type: Facility Owner
Company Name: WEST 44TH STREET HOTEL, LLC
Contact Type: SVP
Contact Name: MEL RUFFIN
Address1: 666 FIFTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10103
Country Code: 001
Phone: (212) 399-3600
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/12/2008

Site Id: 394825
Affiliation Type: Mail Contact
Company Name: WEST 44TH STREET HOTEL, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 666 FIFTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10103
Country Code: 001
Phone: (212) 399-3600
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 44TH STREE HOTEL (Continued)

U004118647

Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/12/2008

Site Id: 394825
Affiliation Type: On-Site Operator
Company Name: WEST 44TH STREE HOTEL
Contact Type: Not reported
Contact Name: TISHMAN CONSTRUCTION CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 399-3600
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/12/2008

Site Id: 394825
Affiliation Type: Emergency Contact
Company Name: WEST 44TH STREET HOTEL, LLC
Contact Type: Not reported
Contact Name: PETER HARDECKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 237-3498
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/12/2008

Tank Info:

Tank Number: 001
Tank ID: 221984
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1500
Install Date: Not reported
Date Tank Closed: 02/29/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 44TH STREE HOTEL (Continued)

U004118647

Modified By: dxliving
Last Modified: 03/12/2008

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

BJ403
North
1/8-1/4
0.211 mi.
1112 ft.
CLINTON 510 OWNERS H.D.F.C.
465 W. 46 ST.
NEW YORK, NY 10036
Site 6 of 6 in cluster BJ

NY AST **A100139083**
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-604030
Program Type: PBS
UTM X: 585066.22098999994
UTM Y: 4512812.8239599997
Expiration Date: 03/29/2019
Site Type: Apartment Building/Office Building

Actual:
32 ft.

Affiliation Records:

Site Id: 25918
Affiliation Type: Facility Owner
Company Name: CLINTON 510 OWNERS H.D.F.C. C/O R.F.STEWART REAL E
Contact Type: AGENT
Contact Name: ROBERT KAYE
Address1: 192 LEXINGTON AVE. #504
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 481-5080
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/11/2014

Site Id: 25918
Affiliation Type: Mail Contact
Company Name: RF STUART REAL ESTATE
Contact Type: Not reported
Contact Name: ROBERT KAYE
Address1: 192 LEXINGTON AVE
Address2: SUITE 504

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLINTON 510 OWNERS H.D.F.C. (Continued)

A100139083

City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 418-5080
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/11/2014

Site Id: 25918
Affiliation Type: On-Site Operator
Company Name: CLINTON 510 OWNERS H.D.F.C.
Contact Type: Not reported
Contact Name: MAS COTTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 991-2635
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/10/2013

Site Id: 25918
Affiliation Type: Emergency Contact
Company Name: CLINTON 510 OWNERS H.D.F.C. C/O SUNFLOWER MGMT
Contact Type: Not reported
Contact Name: MAS COTTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 991-2635
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/10/2013

Tank Info:

Tank Number: 01
Tank Id: 56431
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLINTON 510 OWNERS H.D.F.C. (Continued)

A100139083

I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/26/1982
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 07/10/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

BQ404
NE
1/8-1/4
0.211 mi.
1115 ft.

670 9TH AVE
NEW YORK, NY 10036

Site 1 of 6 in cluster BQ

EDR US Hist Cleaners 1015086180
N/A

Relative:
Higher

EDR Historical Cleaners:

Name: 670 WASH & DRYEXPRESS INC
Year: 2004
Address: 670 9TH AVE

Name: 670 WASH DRY EXPRESS INC
Year: 2005
Address: 670 9TH AVE

Name: BEST WASH & DRY INC
Year: 2006
Address: 670 9TH AVE

Name: 670 WASH & DRY EXPRESS INC
Year: 2006
Address: 670 9TH AVE

Name: BEST WASH & DRY INC
Year: 2007
Address: 670 9TH AVE

Name: 670 WASH & DRY INC
Year: 2007
Address: 670 9TH AVE

Name: 670 WASH DRY EXPRESS INC
Year: 2008
Address: 670 9TH AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015086180

Name: PEST WASH & DRY INC
Year: 2009
Address: 670 9TH AVE

Name: BEST WASH & DRY INC
Year: 2010
Address: 670 9TH AVE

Name: 670 WASH & DRY EXPRESS INC
Year: 2011
Address: 670 9TH AVE

Name: 670 WASH & DRY EXPRESS INC
Year: 2012
Address: 670 9TH AVE

BR405
SSE
1/8-1/4
0.211 mi.
1115 ft.

HAP ENGRAVING OF NY LTD
323 W 39TH ST
NEW YORK, NY 10018
Site 1 of 10 in cluster BR

RCRA NonGen / NLR
FINDS
NY MANIFEST

1000336624
NYD981561731

Relative:
Higher

RCRA NonGen / NLR:

Actual:
36 ft.

Date form received by agency: 01/01/2007
Facility name: HAP ENGRAVING OF NY LTD
Facility address: 323 W 39TH ST
NEW YORK, NY 100181411
EPA ID: NYD981561731
Mailing address: W 39TH ST
NEW YORK, NY 100181411
Contact: Not reported
Contact address: W 39TH ST
NEW YORK, NY 100181411
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: WINOKER REALTY CO
Owner/operator address: 1410 BROADWAY ROOM 2203
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: (212) 764-7666
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: WINOKER REALTY CO
Owner/operator address: 1410 BROADWAY ROOM 2203
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: (212) 764-7666

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: HAP ENGRAVING OF NY LTD
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: HAP ENGRAVING OF NY LTD
Classification: Not a generator, verified

Date form received by agency: 08/31/1994
Site name: HAP ENGRAVING OF NY LTD
Classification: Small Quantity Generator

Date form received by agency: 09/11/1992
Site name: ALCON ENGRAVERS
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/26/1991
Date achieved compliance: 05/28/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/10/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Evaluation date: 04/24/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/26/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/28/1991
Evaluation lead agency: State

FINDS:

Registry ID: 110004409248

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD981561731
Country: USA

Mailing Info:

Name: ALCON
Contact: ALCON
Address: 323 WEST 39TH STREET
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-239-9170

Document ID: NYA5688378
Manifest Status: Completed copy
Trans1 State ID: NYIA8036
Trans2 State ID: Not reported
Generator Ship Date: 880225
Trans1 Recv Date: 880225
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880225
Part A Recv Date: 880317
Part B Recv Date: 880303
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Specific Gravity: 130
Year: 88

Document ID: NYA3027003
Manifest Status: Completed copy
Trans1 State ID: NY8385RW
Trans2 State ID: Not reported
Generator Ship Date: 861211
Trans1 Recv Date: 861211
Trans2 Recv Date: Not reported
TSD Site Recv Date: 861212
Part A Recv Date: 861217
Part B Recv Date: 861217
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 86

Document ID: NYA7173225
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890406
Trans1 Recv Date: 890406
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890406
Part A Recv Date: 890412
Part B Recv Date: 890411
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 000
Year: 89

Document ID: NYB5582745
Manifest Status: Completed copy
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 920512

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Trans1 Recv Date: 920512
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920512
Part A Recv Date: Not reported
Part B Recv Date: 920526
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 92

Document ID: NYB6912702
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 950601
Trans1 Recv Date: 950601
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950601
Part A Recv Date: Not reported
Part B Recv Date: 950615
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 95

Document ID: NYA7027218
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890110
Trans1 Recv Date: 890110
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890110
Part A Recv Date: 890117
Part B Recv Date: 890119
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 89

Document ID: NYA7039026
Manifest Status: Completed copy
Trans1 State ID: MV6352
Trans2 State ID: Not reported
Generator Ship Date: 890912
Trans1 Recv Date: 890912
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890913
Part A Recv Date: 890918
Part B Recv Date: 890919
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 89

Document ID: NYB5721039
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 921001
Trans1 Recv Date: 921001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921001
Part A Recv Date: Not reported
Part B Recv Date: 921021
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 92

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Document ID: NYB5411367
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 930107
Trans1 Recv Date: 930107
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930107
Part A Recv Date: 930126
Part B Recv Date: 930115
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 93

Document ID: NYB2105712
Manifest Status: Completed copy
Trans1 State ID: IA8036
Trans2 State ID: Not reported
Generator Ship Date: 900214
Trans1 Recv Date: 900214
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900214
Part A Recv Date: 900301
Part B Recv Date: 900302
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 90

Document ID: NYB2775726
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 901129
Trans1 Recv Date: 901129
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901129
Part A Recv Date: 910102

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Part B Recv Date: 910107
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 90

Document ID: NYB2138913
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 900710
Trans1 Recv Date: 900710
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900710
Part A Recv Date: 900809
Part B Recv Date: 900813
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 90

Document ID: NYB5177061
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 931020
Trans1 Recv Date: 931020
Trans2 Recv Date: Not reported
TSD Site Recv Date: 931020
Part A Recv Date: Not reported
Part B Recv Date: 931103
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 93

Document ID: NYA6258807
Manifest Status: Completed copy
Trans1 State ID: NY8385RW
Trans2 State ID: Not reported
Generator Ship Date: 870421
Trans1 Recv Date: 870421
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870421
Part A Recv Date: 870424
Part B Recv Date: 870427
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 87

Document ID: NYA5348349
Manifest Status: Completed copy
Trans1 State ID: NY1A8036
Trans2 State ID: Not reported
Generator Ship Date: 880525
Trans1 Recv Date: 880525
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880531
Part A Recv Date: 880527
Part B Recv Date: 880607
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 88

Document ID: NYA5217489
Manifest Status: Completed copy
Trans1 State ID: NY8385-RW

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Trans2 State ID: Not reported
Generator Ship Date: 870929
Trans1 Recv Date: 870929
Trans2 Recv Date: Not reported
TSD Site Recv Date: 870930
Part A Recv Date: 871001
Part B Recv Date: 871005
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 130
Year: 87

Document ID: NYA7098048
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 880914
Trans1 Recv Date: 880914
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880914
Part A Recv Date: 880920
Part B Recv Date: 880921
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NYB2379852
Manifest Status: Completed copy
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 910611
Trans1 Recv Date: 910611
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910611
Part A Recv Date: 910618
Part B Recv Date: 910619
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 91

Document ID: NYB2417130
Manifest Status: Completed copy
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 911203
Trans1 Recv Date: 911203
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911203
Part A Recv Date: Not reported
Part B Recv Date: 911210
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134
Year: 91

Document ID: NYB6613209
Manifest Status: Completed copy
Trans1 State ID: PD9938
Trans2 State ID: Not reported
Generator Ship Date: 940922
Trans1 Recv Date: 940922
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940922
Part A Recv Date: 941003
Part B Recv Date: 941003
Generator EPA ID: NYD981561731
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSD ID: NYD082785429
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 134

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HAP ENGRAVING OF NY LTD (Continued)

1000336624

Year: 94

[Click this hyperlink](#) while viewing on your computer to access additional NY_MANIFEST: detail in the EDR Site Report.

BP406
WSW
1/8-1/4
0.212 mi.
1117 ft.

510 10TH AVE
NEW YORK, NY 10018
Site 3 of 7 in cluster BP

EDR US Hist Auto Stat 1015530418
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: TOWING & REPAIR
Year: 2007
Address: 510 10TH AVE

Actual:
27 ft.

Name: TOWING & REPAIR
Year: 2011
Address: 510 10TH AVE

Name: TOWING & REPAIR
Year: 2012
Address: 510 10TH AVE

BP407
WSW
1/8-1/4
0.212 mi.
1117 ft.

CON EDISION - MH43240
W39TH ST & 10TH AVE W39TH ST &
NEW YORK, NY 10003
Site 4 of 7 in cluster BP

RCRA NonGen / NLR 1007208120
NY MANIFEST NYP004082525

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 06/02/2002
Facility name: CON EDISION - MH43240
Facility address: W39TH ST & 10TH AVE W39TH ST &
NEW YORK, NY 10003
EPA ID: NYP004082525
Mailing address: IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: (212) 460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
27 ft.

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISION - MH43240 (Continued)

1007208120

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 06/01/2002
Site name: CON EDISION - MH43240
Classification: Not a generator, verified

Date form received by agency: 05/31/2002
Site name: CON EDISION - MH43240
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYP004082525
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0709767
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/14/2001
Trans1 Recv Date: 05/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/14/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004082525
Trans1 EPA ID: NYD980593636
Trans2 EPA ID: Not reported
TSD ID: 20854AD
Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Quantity: 03909
Units: K - Kilograms (2.2 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
408 North 1/8-1/4 0.212 mi. 1119 ft.	460 W 46TH ST NEW YORK, NY 10036	EDR US Hist Cleaners	1015063930 N/A
Relative: Lower	EDR Historical Cleaners: Name: W 46 CLEANERS Year: 2006 Address: 460 W 46TH ST Name: W 46 CLEANERS Year: 2007 Address: 460 W 46TH ST Name: W 46 CLEANER Year: 2010 Address: 460 W 46TH ST Name: W FORTY SIX CLEANER Year: 2011 Address: 460 W 46TH ST		
Actual: 30 ft.			
BS409 ENE 1/8-1/4 0.212 mi. 1119 ft.	CON EDISON SERVICE BOX: 8879 363 W 46TH ST NEW YORK, NY 10036 Site 1 of 4 in cluster BS	RCRA-CESQG FINDS	1016144178 NYP004269676
Relative: Higher	RCRA-CESQG: Date form received by agency: 09/20/2012 Facility name: CON EDISON SERVICE BOX: 8879 Facility address: 363 W 46TH ST NEW YORK, NY 10036 EPA ID: NYP004269676 Mailing address: IRVING PL, RM 828 NEW YORK, NY 10003 Contact: RICARDO CARTY Contact address: Not reported Not reported Contact country: Not reported Contact telephone: (212) 643-3044 Contact email: Not reported EPA Region: 02 Classification: Conditionally Exempt Small Quantity Generator Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste		
Actual: 43 ft.			

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8879 (Continued)

1016144178

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055462342

Environmental Interest/Information System

BP410
WSW
1/8-1/4
0.212 mi.
1121 ft.

**PORT AUTH OF NY & NJ 10TH AVE & 38-39
10TH AVE BETW 38TH & 39TH ST
NEW YORK, NY 10018**

**RCRA NonGen / NLR 1000390993
NY MANIFEST NYD981483316**

Site 5 of 7 in cluster BP

**Relative:
Lower**

RCRA NonGen / NLR:

**Actual:
27 ft.**

Date form received by agency: 01/01/2007
Facility name: PORT AUTH OF NY & NJ 10TH AVE & 38-39
Facility address: 10TH AVE BETW 38TH & 39TH ST
NEW YORK, NY 10018
EPA ID: NYD981483316
Mailing address: BLVD EAST
WEEHAWKEN, NY 07087
Contact: HCONTFIRST CALO
Contact address: BLVD EAST
WEEHAWKEN, NY 07087
Contact country: US
Contact telephone: (201) 348-3573
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: District
Owner/Operator Type: Operator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 10TH AVE & 38-39 (Continued)

1000390993

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: District
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: PORT AUTH OF NY & NJ 10TH AVE & 38-39
Classification: Not a generator, verified

Date form received by agency: 04/25/1986
Site name: PORT AUTH OF NY & NJ 10TH AVE & 38-39
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD981483316
Country: USA

Mailing Info:

Name: PORT AUTHORITY OF NY & NJ
Contact: PORT AUTHORITY OF NY & NJ
Address: 25 JOURNAL SQUARE 4TH FLOOR
City/State/Zip: JERSEY CITY, NJ 07306
Country: USA
Phone: 201-589-0900

Document ID: NYB1794078
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: (NJ)XK81X

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 10TH AVE & 38-39 (Continued)

1000390993

Trans2 State ID: T691KWNJ
Generator Ship Date: 900214
Trans1 Recv Date: 900214
Trans2 Recv Date: 900215
TSD Site Recv Date: 900216
Part A Recv Date: 900309
Part B Recv Date: 900314
Generator EPA ID: NYD981483316
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: NJD054126164
TSDF ID: NYD057770109
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00550
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 90

BP411 **CONSOLIDATED EDISON**
WSW **#43240 W 39TH ST & 10TH AVE**
1/8-1/4 **NEW YORK, NY 10020**
0.212 mi.
1121 ft. **Site 6 of 7 in cluster BP**

NY MANIFEST **1009240650**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004083525
Country: USA

Actual:
27 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0664101
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/14/2001
Trans1 Recv Date: 05/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/15/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004083525
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: 60913AX
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity: 00217
Units: K - Kilograms (2.2 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

1009240650

Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

BP412 NEW YORK CITY DEP
WSW 39TH ST BET 11TH&10
1/8-1/4 NEW YORK, NY
0.213 mi.
1123 ft. Site 7 of 7 in cluster BP

NY MANIFEST 1009244242
N/A

Relative: NY MANIFEST:
Lower EPA ID: NYP010000743
Country: USA

Actual: Mailing Info:
27 ft. Name: NEW YORK CITY DEP
Contact: STANLEY SIEBENBERG
Address: 59-17 JUNCTION BLVD
City/State/Zip: FLUSHING, NY 11373
Country: USA
Phone: 718-595-4654

Document ID: NJA1471180
Manifest Status: Completed copy
Trans1 State ID: NJDEPS581
Trans2 State ID: Not reported
Generator Ship Date: 920605
Trans1 Recv Date: 920605
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920605
Part A Recv Date: Not reported
Part B Recv Date: 920619
Generator EPA ID: NYP010000743
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92

BK413 325 W 45 ST
East 325 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.213 mi.
1126 ft. Site 3 of 4 in cluster BK

NY AST A100320253
N/A

Relative: AST:
Higher Region: STATE
DEC Region: 2
Actual: Site Status: Active
41 ft. Facility Id: 2-292834

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

325 W 45 ST (Continued)

A100320253

Program Type: PBS
UTM X: 585363.48274000001
UTM Y: 4512561.7865199996
Expiration Date: 07/14/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 13335
Affiliation Type: Facility Owner
Company Name: 325 WEST 45TH STREET OWNERS CORPORATION
Contact Type: PROPERTY MGR
Contact Name: MARY MARINO
Address1: 325 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-0430
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/17/2013

Site Id: 13335
Affiliation Type: Mail Contact
Company Name: 325 WEST 45TH STREET OWNERS CORP.
Contact Type: Not reported
Contact Name: MARY MARIANO
Address1: 325 WEST 45TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-0430
EMail: THEWHITBY1@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/17/2013

Site Id: 13335
Affiliation Type: On-Site Operator
Company Name: 325 W 45 ST
Contact Type: Not reported
Contact Name: SYLEJMAN NIVOKAZI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-0403
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/17/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

325 W 45 ST (Continued)

A100320253

Site Id: 13335
Affiliation Type: Emergency Contact
Company Name: 325 WEST 45TH STREET OWNERS CORPORATION
Contact Type: Not reported
Contact Name: SYLEJMAN NIVOKAZI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 246-0430
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 4/17/2013

Tank Info:

Tank Number: 046
Tank Id: 15206
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/10/1990
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 04/17/2013
Material Name: #6 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BH414 **CON EDISON SERVICE BOX: 39821**
SSW **503 9TH AVE**
1/8-1/4 **NEW YORK, NY 10018**
0.213 mi.
1126 ft. **Site 6 of 8 in cluster BH**

RCRA-CESQG **1016143751**
FINDS **NYP004265344**

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/28/2012

Facility name: CON EDISON SERVICE BOX: 39821

Facility address: 503 9TH AVE

NEW YORK, NY 10018

EPA ID: NYP004265344

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468104

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39821 (Continued)

1016143751

Environmental Interest/Information System

BI415 **CON EDISON SERVICE BOX: 8500**
East **305 W 44TH ST**
1/8-1/4 **NEW YORK, NY 10036**
0.214 mi.
1131 ft. **Site 5 of 8 in cluster BI**

RCRA-CESQG **1016144154**
FINDS **NYP004269429**

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/19/2012

Facility name: CON EDISON SERVICE BOX: 8500

Facility address: 305 W 44TH ST
NEW YORK, NY 10036

EPA ID: NYP004269429

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. Importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8500 (Continued)

1016144154

FINDS:

Registry ID: 110055462191

Environmental Interest/Information System

BI416
East
1/8-1/4
0.214 mi.
1131 ft.
HACELS, INC
305 W 44TH ST
NEW YORK, NY 10036
Site 6 of 8 in cluster BI

NY AST
NY HIST AST
U003391902
N/A

Relative:
Higher

AST:

Actual:
42 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-364916
Program Type: PBS
UTM X: 585373.44336000003
UTM Y: 4512466.64592
Expiration Date: 12/14/2017
Site Type: Private Residence

Affiliation Records:

Site Id: 18514
Affiliation Type: Facility Owner
Company Name: HACELS INC
Contact Type: BLDG MGR
Contact Name: JOSEPH HYNES
Address1: 709 8TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 957-8000
EMail: Not reported
Fax Number: Not reported
Modified By: msbaptis
Date Last Modified: 10/11/2007

Site Id: 18514
Affiliation Type: Mail Contact
Company Name: HACELS INC
Contact Type: Not reported
Contact Name: CARMEN VUOTTO
Address1: 709 8TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 957-8000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HACELS, INC (Continued)

U003391902

Site Id: 18514
Affiliation Type: On-Site Operator
Company Name: HACELS, INC
Contact Type: Not reported
Contact Name: JOE HYNES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 957-8000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18514
Affiliation Type: Emergency Contact
Company Name: HACELS INC
Contact Type: Not reported
Contact Name: JOE HYNES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 245-8100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 22663
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
3
Tank Location: Steel/Carbon Steel/Iron
Tank Type: In Service
Tank Status: Not reported
Pipe Model:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HACELS, INC (Continued)

U003391902

Install Date: 03/07/1990
Capacity Gallons: 2500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: msbaptis
Last Modified: 10/11/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-364916
SWIS Code: 6201
Operator: RUPERT POWELL
Facility Phone: (212) 957-8000
Facility Addr2: 305 W 44TH ST
Facility Type: OTHER
Emergency: JOE HYNES
Emergency Tel: (212) 245-8100
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: HACELS INC
Owner Address: 709 8TH AVE
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 957-8000
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: PATRICK J. MONACHINO, JR.
Mailing Name: HACELS INC
Mailing Address: 709 8TH AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 957-8000
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 11/03/1997
Expiration: 12/14/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HACELS, INC (Continued)

U003391902

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BQ417
NE
1/8-1/4
0.216 mi.
1141 ft.
672 NINTH AVE.,LLC
672 9TH AVENUE
NEW YORK, NY 10036
Site 2 of 6 in cluster BQ

NY AST A100177952
N/A

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605647
Program Type: PBS
UTM X: 585248.38393999997
UTM Y: 4512762.6284999996
Expiration Date: 04/13/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 27514
Affiliation Type: Facility Owner
Company Name: 672 NINTH AVE.,LLC
Contact Type: AGENT
Contact Name: JONATHAN RUHL
Address1: P.O.BOX 3582
Address2: Not reported
City: NEW HYDE PARK
State: NY
Zip Code: 11040
Country Code: 001
Phone: (718) 597-0808
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

672 NINTH AVE.,LLC (Continued)

A100177952

Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2/8/2006

Site Id: 27514
Affiliation Type: Mail Contact
Company Name: 672 NINTH AVE.,LLC
Contact Type: Not reported
Contact Name: J.RUHL
Address1: P.O.BOX 1847
Address2: Not reported
City: PARAMUS
State: NJ
Zip Code: 07653
Country Code: 001
Phone: (201) 363-1448
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2/8/2006

Site Id: 27514
Affiliation Type: On-Site Operator
Company Name: 672 NINTH AVE.,LLC
Contact Type: Not reported
Contact Name: KEMAL CARI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 929-9119
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2/8/2006

Site Id: 27514
Affiliation Type: Emergency Contact
Company Name: 672 NINTH AVE.,LLC
Contact Type: Not reported
Contact Name: J.RUHL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 363-1448
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2/8/2006

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

672 NINTH AVE.,LLC (Continued)

A100177952

Tank Number: 001
Tank Id: 60193
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
K01 - Spill Prevention - Catch Basin
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other
E07 - Piping Secondary Containment - Trench Liner

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/31/1961
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 01/27/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

BT418
NW
1/8-1/4
0.216 mi.
1141 ft.
F.D.N.Y.-RESCUE CO. 1
530 WEST 43RD STREET
NEW YORK, NY 10036
Site 1 of 9 in cluster BT

NY AST **U003178521**
N/A

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-600574
Program Type: PBS
UTM X: 584789.39512999996
UTM Y: 4512674.0931099998
Expiration Date: 12/27/1996
Site Type: Other

Actual:
19 ft.

Affiliation Records:
Site Id: 22555
Affiliation Type: Facility Owner
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 250 LIVINGSTON STREET
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F.D.N.Y.-RESCUE CO. 1 (Continued)

U003178521

City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: Mail Contact
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 250 LIVINGSTON STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: On-Site Operator
Company Name: F.D.N.Y.-RESCUE CO. 1
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 570-4204
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: Emergency Contact
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: F.D.N.Y.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F.D.N.Y.-RESCUE CO. 1 (Continued)

U003178521

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 003
Tank Id: 52596
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1996
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Diesel

Tank Number: 004
Tank Id: 52597
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
G99 - Tank Secondary Containment - Other

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F.D.N.Y.-RESCUE CO. 1 (Continued)

U003178521

Install Date: 12/01/1996
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Diesel

**BT419
NW
1/8-1/4
0.216 mi.
1141 ft.**

**F.D.N.Y.-RESCUE CO. 1
530 WEST 43RD STREET
NEW YORK, NY 10036**

**NY UST U004077941
N/A**

Site 2 of 9 in cluster BT

**Relative:
Lower**

UST:

**Actual:
19 ft.**

Id/Status: 2-600574 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/27/1996
UTM X: 584789.39512999996
UTM Y: 4512674.0931099998
Site Type: Other

Affiliation Records:

Site Id: 22555
Affiliation Type: Facility Owner
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 250 LIVINGSTON STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: Mail Contact
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 250 LIVINGSTON STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F.D.N.Y.-RESCUE CO. 1 (Continued)

U004077941

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: On-Site Operator
Company Name: F.D.N.Y.-RESCUE CO. 1
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 570-4204
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 22555
Affiliation Type: Emergency Contact
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: F.D.N.Y.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 403-1580
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 43025
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: 12/01/1989
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F.D.N.Y.-RESCUE CO. 1 (Continued)

U004077941

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
F05 - Pipe External Protection - Jacketed
I05 - Overfill - Vent Whistle

Tank Number: 002
Tank ID: 43026
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: 12/01/1989
Date Tank Closed: 11/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
F05 - Pipe External Protection - Jacketed
C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BS420
ENE
1/8-1/4
0.217 mi.
1144 ft.

CON EDISON SERVICE BOX: 8880
357 W 46TH ST
NEW YORK, NY 10036
Site 2 of 4 in cluster BS

RCRA-CESQG
FINDS
1016144180
NYP004269692

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/20/2012

Facility name: CON EDISON SERVICE BOX: 8880

Facility address: 357 W 46TH ST
NEW YORK, NY 10036

EPA ID: NYP004269692

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: RICARDO CARTY

Contact address: Not reported

Contact country: Not reported

Contact telephone: (212) 643-3044

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055462351

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8880 (Continued)

1016144180

Environmental Interest/Information System

BN421
SSE
1/8-1/4
0.218 mi.
1152 ft.

CON EDISON
312 W 40TH ST
NEW YORK, NY 10018

Site 4 of 7 in cluster BN

NY MANIFEST **S112210425**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004265997
Country: USA

Actual:
39 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-31
Trans1 Recv Date: 2012-08-31
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265997
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456300JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210425

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-31
Trans1 Recv Date: 2012-08-31
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265997
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456300JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BN422 **CON EDISON SERVICE BOX: 7671**
SSE **312 W 40TH ST**
1/8-1/4 **NEW YORK, NY 10018**
0.218 mi.
1152 ft. **Site 5 of 7 in cluster BN**

RCRA-CESQG **1016143815**
FINDS **NYP004265997**

Relative:
Higher

RCRA-CESQG:

Actual:
39 ft.

Date form received by agency: 08/31/2012
Facility name: CON EDISON SERVICE BOX: 7671
Facility address: 312 W 40TH ST
NEW YORK, NY 10018
EPA ID: NYP004265997
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7671 (Continued)

1016143815

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428568

Environmental Interest/Information System

BR423 **338-340 WEST 39 ST**
South **338 WEST 39TH ST**
1/8-1/4 **NEW YORK, NY 10018**
0.218 mi.
1152 ft. **Site 2 of 10 in cluster BR**

NY AST **U003383310**
NY HIST AST **N/A**

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-035009
Program Type: PBS
UTM X: 585096.22164
UTM Y: 4512141.1633900004
Expiration Date: 12/02/2016
Site Type: Apartment Building/Office Building

Actual:
36 ft.

Affiliation Records:

Site Id: 322
Affiliation Type: Facility Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

338-340 WEST 39 ST (Continued)

U003383310

Company Name: THE CAPORAL COMPANY
Contact Type: OWNERS AGENT
Contact Name: ROBERT AUSTIN
Address1: 1251 AVE OF THE AMERICAS
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10020
Country Code: 001
Phone: (212) 408-2900
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 1/9/2013

Site Id: 322
Affiliation Type: Mail Contact
Company Name: THE CAPORAL CO % SENTINEL R.E. CORP
Contact Type: Not reported
Contact Name: ROBERT AUSTIN
Address1: 1251 AVENUE OF THE AMERICAS
Address2: 35TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10020
Country Code: 001
Phone: (212) 408-2951
EMail: AUSTINR@SENTINELCORP.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 1/9/2013

Site Id: 322
Affiliation Type: On-Site Operator
Company Name: 338-340 W 39 ST
Contact Type: Not reported
Contact Name: THE CAPORAL COMPANY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 603-4976
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/2/2008

Site Id: 322
Affiliation Type: Emergency Contact
Company Name: THE CAPORAL COMPANY
Contact Type: Not reported
Contact Name: ROBERT AUSTIN
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

338-340 WEST 39 ST (Continued)

U003383310

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 408-2951
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 1/9/2013

Tank Info:

Tank Number: 001
Tank Id: 961
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1920
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 12/02/2008
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-035009
SWIS Code: 6201
Operator: THE CAPORAL COMPANY
Facility Phone: (212) 695-1968
Facility Addr2: 338 WEST 39TH ST
Facility Type: OTHER
Emergency: MR AHMED NUR
Emergency Tel: (212) 408-2900
Old PBSNO: Not reported
Date Inspected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

338-340 WEST 39 ST (Continued)

U003383310

Inspector: Not reported
Result of Inspection: Not reported
Owner Name: THE CAPORAL COMPANY
Owner Address: 888 SEVENTH AVE 4500
Owner City,St,Zip: NEW YORK, NY 10106
Federal ID: Not reported
Owner Tel: (212) 408-2900
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: SUPER FACILITY MANAGER
Mailing Name: 338-340 WEST 39TH STREET
Mailing Address: 338-340 WEST 39TH STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10018
Mailing Telephone: (212) 695-1968
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/21/1998
Expiration: 12/02/2001
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

338-340 WEST 39 ST (Continued)

U003383310

Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

BS424
ENE
1/8-1/4
0.218 mi.
1153 ft.

352 WEST 46TH STREET
352 WEST 46TH STREET
NEW YORK, NY 10036

NY AST
NY HIST AST

U003388992
N/A

Site 3 of 4 in cluster BS

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-256951
Program Type: PBS
UTM X: 585330.74578999996
UTM Y: 4512655.4434099998
Expiration Date: 09/16/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 10573
Affiliation Type: Facility Owner
Company Name: PRIME 352 WEST 46 LLC
Contact Type: AGENT
Contact Name: RALPH ABECASSIS
Address1: 60 MADISON AVENUE, SUITE 1111
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 673-2300
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/30/2013

Site Id: 10573
Affiliation Type: Mail Contact
Company Name: DSA MANAGEMENT CO, INC.
Contact Type: Not reported
Contact Name: RALPH ABECASSIS
Address1: 60 MADISON AVENUE
Address2: SUITE 1111
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 673-2300
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/30/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

352 WEST 46TH STREET (Continued)

U003388992

Site Id: 10573
Affiliation Type: On-Site Operator
Company Name: 352 WEST 46TH STREET
Contact Type: Not reported
Contact Name: LEONEL CHAPARO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 460-5218
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/30/2013

Site Id: 10573
Affiliation Type: Emergency Contact
Company Name: PRIME 352 WEST 46 LLC
Contact Type: Not reported
Contact Name: LEONEL CHAPARO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 460-5218
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 7/30/2013

Tank Info:

Tank Number: 001
Tank Id: 15020
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

352 WEST 46TH STREET (Continued)

U003388992

Install Date: 12/01/1979
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 07/30/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-256951
SWIS Code: 6201
Operator: EMILIO BRIALES
Facility Phone: (212) 541-9419
Facility Addr2: 352 WEST 46TH STREET
Facility Type: APARTMENT BUILDING
Emergency: HOWARD SORKIN
Emergency Tel: (914) 993-0300
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: LEWIS KAYE (GATES EQUITIES)
Owner Address: 6 BRUCE RD BOX 146
Owner City,St,Zip: MAMARONECK, NY 10543
Federal ID: Not reported
Owner Tel: (914) 698-7570
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: SIERRA ASSETS GROUP
Mailing Address: 30 GLENN STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: WHITE PLAINS, NY 10603
Mailing Telephone: () -
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/07/1997
Expiration: 10/02/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

352 WEST 46TH STREET (Continued)

U003388992

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

BU425 **765-8TH AVENUE**
SE **765 8TH AVENUE**
1/8-1/4 **NEW YORK, NY 10018**
0.219 mi.
1154 ft. **Site 1 of 2 in cluster BU**

NY AST **U004045759**
N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-214787
Program Type: PBS
UTM X: 585485.60569
UTM Y: 4512652.6778199999
Expiration Date: 01/07/1993
Site Type: Unknown

Actual:
41 ft.

Affiliation Records:
Site Id: 7994
Affiliation Type: Facility Owner
Company Name: YAGHOOB BARADARIAN
Contact Type: Not reported
Contact Name: Not reported
Address1: BOX 203
Address2: Not reported
City: ALPINE
State: NJ
Zip Code: 10036
Country Code: 001
Phone: (201) 767-0366
Email: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

765-8TH AVENUE (Continued)

U004045759

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 7994
Affiliation Type: Mail Contact
Company Name: YAGHOOB BARADARIAN
Contact Type: Not reported
Contact Name: Not reported
Address1: BOX 203
Address2: Not reported
City: ALPINE
State: NJ
Zip Code: 10036
Country Code: 001
Phone: (201) 767-0366
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 7994
Affiliation Type: On-Site Operator
Company Name: 765-8TH AVENUE
Contact Type: Not reported
Contact Name: EDUARDO VELEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 767-0366
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 7994
Affiliation Type: Emergency Contact
Company Name: YAGHOOB BARADARIAN
Contact Type: Not reported
Contact Name: BAYSIDE FUEL OIL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 946-4000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

765-8TH AVENUE (Continued)

U004045759

Tank Number: 001
Tank Id: 23527
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/01/1993
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

BR426 **315 ASSOCIATES LLC**
SSE **315 WEST 39TH STREET**
1/8-1/4 **NEW YORK, NY 10018**
0.219 mi.
1156 ft. **Site 3 of 10 in cluster BR**

NY AST **A100353016**
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-482056
Program Type: PBS
UTM X: 585157.13838000002
UTM Y: 4512122.5460999999
Expiration Date: 10/17/2015
Site Type: Apartment Building/Office Building

Actual:
36 ft.

Affiliation Records:

Site Id: 21583
Affiliation Type: Facility Owner
Company Name: 315 ASSOCIATES LLC, C/O HANDRO MGMT
Contact Type: MANAGING AGENT
Contact Name: SCOTT HANDLER
Address1: 561 SEVENTH AVENUE, 15TH FL.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC (Continued)

A100353016

Country Code: 001
Phone: (212) 398-1888
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 8/31/2010

Site Id: 21583
Affiliation Type: Mail Contact
Company Name: 315 ASSOCIATES LLC, C/O HANDRO MGMT
Contact Type: Not reported
Contact Name: SCOTT HANDLER
Address1: 561 SEVENTH AVENUE
Address2: 15TH FL
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 398-1888
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 8/31/2010

Site Id: 21583
Affiliation Type: On-Site Operator
Company Name: 315 ASSOCIATES LLC
Contact Type: Not reported
Contact Name: BILL CIRCUI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-1101
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 8/31/2010

Site Id: 21583
Affiliation Type: Emergency Contact
Company Name: 315 ASSOCIATES LLC, C/O HANDRO MGMT
Contact Type: Not reported
Contact Name: SCOTT HANDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 398-1888
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 8/31/2010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC (Continued)

A100353016

Tank Info:

Tank Number: 001
Tank Id: 39241
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
C01 - Pipe Location - Aboveground

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/05/1973
Capacity Gallons: 5500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: CGFREEDM
Last Modified: 08/31/2010
Material Name: #6 Fuel Oil (On-Site Consumption)

**BR427
SSE
1/8-1/4
0.219 mi.
1156 ft.**

**315 ASSOCIATES
315 W 39TH ST
NEW YORK, NY 10018**

**RCRA-SQG 1010566529
FINDS NYR000151761**

Site 4 of 10 in cluster BR

**Relative:
Higher**

RCRA-SQG:

Date form received by agency: 11/13/2007
Facility name: 315 ASSOCIATES LLC
Facility address: 315 W 39TH ST
NEW YORK, NY 100181412
EPA ID: NYR000151761
Mailing address: 7TH AVE
C/O HANDRO MANAGEMENT CORP
NEW YORK, NY 10018
Contact: WILLIAM CIURCIU
Contact address: 7TH AVE C/O HANDRO MANAGEMENT CORP
NEW YORK, NY 10018
Contact country: US
Contact telephone: (212) 736-1101
Contact email: Not reported
EPA Region: 02

**Actual:
36 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES (Continued)

1010566529

Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: 315 ASSOCIATES FLLC
Owner/operator address: 7TH AVE C/O HANDRO MGMT CORP
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1950
Owner/Op end date: Not reported

Owner/operator name: HANDRO MANAGEMENT CORP
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/1979
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 11/12/2007
Site name: 315 ASSOCIATES LLC
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES (Continued)

1010566529

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110019825698

Environmental Interest/Information System

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

**BR428
SSE
1/8-1/4
0.219 mi.
1156 ft.**

**315 ASSOCIATES LLC/HANDRO MANGMT
315 W 39TH ST
NEW YORK, NY 10018**

**NY MANIFEST S108980780
N/A**

Site 5 of 10 in cluster BR

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYR000151761
Country: USA

**Actual:
36 ft.**

Mailing Info:
Name: 315 ASSOCIATES LLC/HANDRO MANGMT
Contact: SAL TOVER
Address: 561 7TH AVE
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-391-2240

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000151761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 15
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003535113JJK

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC/HANDRO MANGMT (Continued)

S108980780

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000151761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 55
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003535113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC/HANDRO MANGMT (Continued)

S108980780

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000151761
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NJD002200046
Waste Code:	Not reported
Quantity:	5
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	003535113JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/29/2007
Trans1 Recv Date:	11/29/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/29/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000151761
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID:	NJD002200046
Waste Code:	Not reported
Quantity:	15
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	003535113JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC/HANDRO MANGMT (Continued)

S108980780

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000151761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 15
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003535113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000151761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

315 ASSOCIATES LLC/HANDRO MANGMT (Continued)

S108980780

Waste Code: Not reported
Quantity: 5
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003535113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2007
Trans1 Recv Date: 11/29/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/29/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000151761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 5
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003535113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
BV429 North 1/8-1/4 0.219 mi. 1157 ft.	656 10TH AVE NEW YORK, NY 10036 Site 1 of 2 in cluster BV	EDR US Hist Cleaners	1015085255 N/A
Relative: Lower	EDR Historical Cleaners: Name: BKI COIN LAUNDRY INC Year: 2002 Address: 656 10TH AVE		
Actual: 25 ft.	Name: BKI COIN LAUNDRY INC Year: 2003 Address: 656 10TH AVE		
	Name: BKI COIN LAUNDRY Year: 2006 Address: 656 10TH AVE		
	Name: BKI COIN LAUNDRY Year: 2007 Address: 656 10TH AVE		
	Name: BKI COIN LAUNDRY Year: 2009 Address: 656 10TH AVE		
	Name: BKI COIN LAUNDRY Year: 2010 Address: 656 10TH AVE		
	Name: BI LAUNDRY CORP Year: 2011 Address: 656 10TH AVE		
	Name: BI LAUNDRY CORP Year: 2012 Address: 656 10TH AVE		
BU430 SE 1/8-1/4 0.219 mi. 1157 ft.	CON EDISON MANHOLE 60250 W 41 ST 336' WW COR 8 AVE NEW YORK, NY 10036 Site 2 of 2 in cluster BU	RCRA NonGen / NLR	1014918987 NYP004226066
Relative: Higher	RCRA NonGen / NLR: Date form received by agency: 03/06/2012 Facility name: CON EDISON MANHOLE 60250 Site name: CON EDISON - MANHOLE 60250 Facility address: W 41 ST 336' WW COR 8 AVE NEW YORK, NY 10036		
Actual: 42 ft.	EPA ID: NYP004226066 Mailing address: IRVING PL NEW YORK, NY 10003 Contact: DENNIS HUACON Contact address: Not reported Not reported Contact country: US Contact telephone: (212) 460-2757 Contact email: Not reported		

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE 60250 (Continued)

1014918987

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CON EDISON CO OF NY INC
Owner/operator address: IRVING PL 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/30/2011
Owner/Op end date: Not reported

Owner/operator name: CON EDISON CO OF NY INC
Owner/operator address: IRVING PL 15TH FL
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/30/2011
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 03/01/2011
Site name: CON EDISON MANHOLE 60250
Classification: Not a generator, verified

Date form received by agency: 01/30/2011
Site name: CON EDISON MANHOLE 60250
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE 60250 (Continued)

1014918987

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 5000

Violation Status: No violations found

**431
SW
1/8-1/4
0.219 mi.
1157 ft.**

**PORT AUTH NY&NJ-LINC TUN NY EMER GARAGE
WEST 38TH ST / DYER AVE (WEST 39TH ST)
NEW YORK, NY 10018**

**NY UST U001839293
N/A**

**Relative:
Lower**

UST:

Id/Status: 2-340340 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/14/1992
UTM X: 584762.15752000001
UTM Y: 4512212.0968000004
Site Type: Unknown

**Actual:
31 ft.**

Affiliation Records:

Site Id: 16433
Affiliation Type: Facility Owner
Company Name: PORT AUTHORITY OF NY&NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 WORLD TRADE CENTER
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10048
Country Code: 001
Phone: (212) 466-7000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 16433
Affiliation Type: Mail Contact
Company Name: PORT AUTHORITY OF NY&NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 1 WORLD TRADE CENTER
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10048
Country Code: 001
Phone: (212) 466-7000
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH NY&NJ-LINC TUN NY EMER GARAGE (Continued)

U001839293

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 16433
Affiliation Type: On-Site Operator
Company Name: PORT AUTH NY&NJ-LINC TUN NY EMER GARAGE
Contact Type: Not reported
Contact Name: PORT AUTHORITY OF NY&NJ-LINCOL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 348-1994
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 16433
Affiliation Type: Emergency Contact
Company Name: PORT AUTHORITY OF NY&NJ
Contact Type: Not reported
Contact Name: LINCOLN TUNNEL-COMM CTR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (201) 348-3634
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 31590
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/01/1961
Date Tank Closed: 08/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH NY&NJ-LINC TUN NY EMER GARAGE (Continued)

U001839293

Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
I00 - Overfill - None
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 31591
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 03/01/1961
Date Tank Closed: 08/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

BH432 METRO
SSW 9TH AVE 38TH STREET
1/8-1/4 BROOKLYN, NY
0.219 mi.
1158 ft. Site 7 of 8 in cluster BH

NY LTANKS S109064186
N/A

Relative:
Higher

LTANKS:

Site ID: 395024
Spill Number/Closed Date: 0713297 / 6/19/2008
Spill Date: 3/17/2008
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Actual:
36 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METRO (Continued)

S109064186

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: bkfalvey
Referred To: Not reported
Reported to Dept: 3/17/2008
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/17/2008
Spill Record Last Update: 6/19/2008
Spiller Name: JOE EWALD
Spiller Company: METRO
Spiller Address: 9TH AVE 38TH STREET
Spiller City,St,Zip: BROOKLYN, NY
Spiller County: 001
Spiller Contact: JOE EWALD
Spiller Phone: (718) 694-5231
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 271825
DEC Memo: 3/28/08 Called George Cunningham of NYCT (646)252-3607 today [I was on VL from 3/17 to 3/25]. Left message on machine to call me back. Sent ttf letter to:George CunninghamNYCT2 broadway, 2nd Fl.New york, NY 10004 bf6/19/08 On 4/28/08, received letter from jennifer Woutinen of NYCT in response to ttf letter. Supply pump on suction side lost prime, so line was tested. Track crew working near line broke pipe. Soil samples taken. All parameters are non-detect and line was replaced. NFA. bf
Remarks: PBS No: 2-190047LINE FAILURE: ISOLATE AND REDO

Material:

Site ID: 395024
Operable Unit ID: 1151970
Operable Unit: 01
Material ID: 2142740
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 395024
Spill Tank Test: 2384852
Tank Number: 38S-1
Tank Size: 4000
Test Method: 03

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METRO (Continued)

S109064186

Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 3/17/2008
Test Method: Horner EZ Check I or II

BI433 **CON EDISON SERVICE BOX: 8510**
East **300 W 44TH**
1/8-1/4 **NEW YORK, NY 10036**
0.220 mi.
1159 ft. **Site 7 of 8 in cluster BI**

RCRA-CESQG **1016144149**
FINDS **NYP004269379**

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/19/2012

Facility name: CON EDISON SERVICE BOX: 8510

Facility address: 300 W 44TH
NEW YORK, NY 10036

EPA ID: NYP004269379

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8510 (Continued)

1016144149

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055435676

Environmental Interest/Information System

BI434
East
1/8-1/4
0.220 mi.
1159 ft.

GLOBE AFFILIATES
300 WEST 44TH STREET
NEW YORK, NY 10036
Site 8 of 8 in cluster BI

NY AST A100166422
N/A

Relative:
Higher

AST:

Actual:
42 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-090573
Program Type: PBS
UTM X: 585378.10650999995
UTM Y: 4512450.2686799997
Expiration Date: 03/24/2007
Site Type: Other

Affiliation Records:

Site Id: 2217
Affiliation Type: Facility Owner
Company Name: GLOBE AFFILIATES C/O APPLECORE HOTELS
Contact Type: Not reported
Contact Name: Not reported
Address1: 15 WEST 29TH STREET, 15TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 790-2700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2217
Affiliation Type: Mail Contact
Company Name: GLOBE AFFILITES INC % APPLECORE HOTELS
Contact Type: Not reported
Contact Name: DAVE MILLER
Address1: 15 W 39TH ST
Address2: 15TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 790-2700

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GLOBE AFFILIATES (Continued)

A100166422

Email: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/1/2004

Site Id: 2217
Affiliation Type: On-Site Operator
Company Name: GLOBE AFFILIATES
Contact Type: Not reported
Contact Name: GLOBE AFFILIATES, INC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 719-2300
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 2217
Affiliation Type: Emergency Contact
Company Name: GLOBE AFFILIATES C/O APPLECORE HOTELS
Contact Type: Not reported
Contact Name: ALBERT FERNANDEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 790-2700
Email: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 3519
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
H00 - Tank Leak Detection - None

Tank Location: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GLOBE AFFILIATES (Continued)

A100166422

Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1969
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Gasoline

BH435
SSW
1/8-1/4
0.220 mi.
1159 ft.

PORT AUTH OF NY & NJ 9TH AVE & 38
38TH ST & 9TH AVE
NEW YORK, NY 10018

RCRA NonGen / NLR 1000390992
NY MANIFEST NYD981483308

Site 8 of 8 in cluster BH

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: PORT AUTH OF NY & NJ 9TH AVE & 38

Facility address: 38TH ST & 9TH AVE
NEW YORK, NY 10018

EPA ID: NYD981483308

Mailing address: BLVD EAST
WEEHAWKEN, NY 07087

Contact: HCONTFIRST CALO
Contact address: BLVD EAST
WEEHAWKEN, NY 07087

Contact country: US

Contact telephone: (201) 348-3573

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: PORT AUTHORITY OF NY & NJ

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: District

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: District

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38 (Continued)

1000390992

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: PORT AUTH OF NY & NJ 9TH AVE & 38
Classification: Not a generator, verified

Date form received by agency: 04/25/1986
Site name: PORT AUTH OF NY & NJ 9TH AVE & 38
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:

EPA ID: NYD981483308
Country: USA

Mailing Info:

Name: PORT AUTHORITY OF NEW YORK & NEW JERSEY
Contact: PORT AUTHORITY OF NEW YORK & NEW JERSEY
Address: 500 BLVD EAST
City/State/Zip: WEEHAWKEN, NJ 07087
Country: USA
Phone: 201-867-9095

Document ID: NJA0333737
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 880921
Trans1 Recv Date: 880921
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880921
Part A Recv Date: 880927
Part B Recv Date: 880928
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38 (Continued)

1000390992

Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 88

Document ID: NJA0333749
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 880901
Trans1 Recv Date: 880901
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880901
Part A Recv Date: 880908
Part B Recv Date: 880913
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00008
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NJA0361158
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 21410-NJD
Trans2 State ID: Not reported
Generator Ship Date: 881028
Trans1 Recv Date: 881028
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881028
Part A Recv Date: 881122
Part B Recv Date: 881107
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00012
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38 (Continued)

1000390992

Document ID: NJA0361160
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 881118
Trans1 Recv Date: 881118
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881118
Part A Recv Date: 881122
Part B Recv Date: 881129
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00015
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NJA0333738
Manifest Status: Completed copy
Trans1 State ID: 000000000
Trans2 State ID: Not reported
Generator Ship Date: 881012
Trans1 Recv Date: 881012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881012
Part A Recv Date: 881102
Part B Recv Date: 881019
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00012
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NJA0333739
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 881004
Trans1 Recv Date: 881004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881004
Part A Recv Date: 881014

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38 (Continued)

1000390992

Part B Recv Date: 881013
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00010
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NJA0361157
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 881011
Trans1 Recv Date: 881011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881011
Part A Recv Date: 881018
Part B Recv Date: 881019
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00010
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

Document ID: NYA3481593
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: H10R708
Trans2 State ID: Not reported
Generator Ship Date: 860715
Trans1 Recv Date: 860715
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860716
Part A Recv Date: 860813
Part B Recv Date: 860801
Generator EPA ID: NYD981483308
Trans1 EPA ID: ARD069748192
Trans2 EPA ID: Not reported
TSDF ID: TND980729305
Waste Code: X727 - NJ ONLY UNKNOWN
Quantity: 00825
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTH OF NY & NJ 9TH AVE & 38 (Continued)

1000390992

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 86

Document ID: NJA0361156
Manifest Status: Completed copy
Trans1 State ID: NJSWAS300
Trans2 State ID: Not reported
Generator Ship Date: 880923
Trans1 Recv Date: 880923
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880923
Part A Recv Date: 880928
Part B Recv Date: 880930
Generator EPA ID: NYD981483308
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00020
Units: Y - Cubic yards* (.85 tons)
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 88

BS436
ENE
1/8-1/4
0.220 mi.
1162 ft.

CON EDISON SERVICE BOX: 8881
353 W 46TH ST
NEW YORK, NY 10036
Site 4 of 4 in cluster BS

RCRA-CESQG **1016144181**
FINDS **NYP004269700**

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/20/2012

Facility name: CON EDISON SERVICE BOX: 8881

Facility address: 353 W 46TH ST
NEW YORK, NY 10036

EPA ID: NYP004269700

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: RICARDO CARTY

Contact address: Not reported

Contact country: Not reported

Contact telephone: (212) 643-3044

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8881 (Continued)

1016144181

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055421734

Environmental Interest/Information System

**BQ437
NE
1/8-1/4
0.221 mi.
1167 ft.**

**EMPIRE CLEANERS
674 9TH AVE.
NEW YORK, NY 10036**

Site 3 of 6 in cluster BQ

**RCRA-CESQG
FINDS
NY MANIFEST
US AIRS**

**1000261171
NYD982719064**

**Relative:
Higher**

RCRA-CESQG:

**Actual:
44 ft.**

Date form received by agency: 01/01/2007
Facility name: EMPIRE TAILORS & CLEANERS
Facility address: 674 9TH AVE
NEW YORK, NY 10036
EPA ID: NYD982719064
Mailing address: 9TH AVE
NEW YORK, NY 10036
Contact: SUK JUN LEE
Contact address: 9TH AVE
NEW YORK, NY 10036
Contact country: US
Contact telephone: (212) 586-0122
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: S J CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: S J CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: EMPIRE TAILORS & CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/23/1988

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Site name: EMPIRE TAILORS & CLEANERS
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001606566

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

NY MANIFEST:

EPA ID: NYD982719064
Country: USA

Mailing Info:

Name: EMPIRE TAILOR & CLEANER
Contact: EMPIRE TAILOR & CLEANER
Address: 674 9TH AVENUE
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-586-0122

Document ID: NJA1333881
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911028
Trans1 Recv Date: 911028
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911028
Part A Recv Date: Not reported
Part B Recv Date: 911112
Generator EPA ID: NYD982719064

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA2172078
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950526
Trans1 Recv Date: 950526
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950526
Part A Recv Date: 950605
Part B Recv Date: 950613
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA1943087
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 941109
Trans1 Recv Date: 941109
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941109
Part A Recv Date: 941117
Part B Recv Date: 941128
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Specific Gravity: 100
Year: 94

Document ID: NJA1953079
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940707
Trans1 Recv Date: 940707
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940707
Part A Recv Date: 940714
Part B Recv Date: 940722
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA1935642
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940927
Trans1 Recv Date: 940927
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940927
Part A Recv Date: 941006
Part B Recv Date: 941007
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA2093567
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950912

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Trans1 Recv Date: 950912
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950912
Part A Recv Date: 950921
Part B Recv Date: 950927
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: 07
Manifest Status: 001305995JJK
Trans1 State ID: NYD982719064
Trans2 State ID: Not reported
Generator Ship Date: CDX107000000
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD000564906
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DM
Container Type: 260
Handling Method: P
Specific Gravity: 1
Waste Code: R
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 001305995JJK
Trans1 State ID: NYD982719064
Trans2 State ID: Not reported
Generator Ship Date: CDX107000000
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD000564906

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSD ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 80
Handling Method: P
Specific Gravity: 1
Waste Code: R
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD000564906
Trans2 State ID: Not reported
Generator Ship Date: 6/13/2007
Trans1 Recv Date: 6/13/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 6/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982719064
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: CDX107000000
Waste Code: Not reported
Quantity: 80
Units: P - Pounds
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 001305995JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Mgmt Method Type Code: H020

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD000564906
Trans2 State ID: Not reported
Generator Ship Date: 6/13/2007
Trans1 Recv Date: 6/13/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 6/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982719064
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: CDX107000000
Waste Code: Not reported
Quantity: 260
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 001305995JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: NJA0620269
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 890515
Trans1 Recv Date: 890515
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890515
Part A Recv Date: 890518
Part B Recv Date: 890525
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00080
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NJA1119107
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911003
Trans1 Recv Date: 911003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911003
Part A Recv Date: Not reported
Part B Recv Date: 911018
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1326313
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911218
Trans1 Recv Date: 911218
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911218
Part A Recv Date: Not reported
Part B Recv Date: 920109
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1423037
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Trans2 State ID: Not reported
Generator Ship Date: 920324
Trans1 Recv Date: 920324
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920324
Part A Recv Date: 920403
Part B Recv Date: 920406
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA1432756
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920413
Trans1 Recv Date: 920413
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920413
Part A Recv Date: 920427
Part B Recv Date: 920422
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA1440906
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920514
Trans1 Recv Date: 920514
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920514
Part A Recv Date: Not reported
Part B Recv Date: 920603
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA1328148
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920219
Trans1 Recv Date: 920219
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920219
Part A Recv Date: 920227
Part B Recv Date: 920302
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA2096989
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950421
Trans1 Recv Date: 950421
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950421
Part A Recv Date: 950501
Part B Recv Date: 950505
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Year: 95

Document ID: NJA2041923
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950106
Trans1 Recv Date: 950106
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950106
Part A Recv Date: 950113
Part B Recv Date: 950126
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00195
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2080482
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950307
Trans1 Recv Date: 950307
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950307
Part A Recv Date: 950330
Part B Recv Date: 950316
Generator EPA ID: NYD982719064
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00060
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

[Click this hyperlink](#) while viewing on your computer to access
105 additional NY_MANIFEST: record(s) in the EDR Site Report.

AIRS (AFS):

Airs Minor Details:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

EPA plant ID: 110001607663
Plant name: EMPIRE CLEANERS
Plant address: 674 9TH AVE
NEW YORK, NY 100363602
County: NEW YORK
Region code: 02
Dunn & Bradst #: Not reported
Air quality cntrl region: 043
Sic code: 7216
Sic code desc: DRYCLEANING PLANTS, EXCEPT RUG
North Am. industrial classf: 812320
NAIC code description: Drycleaning and Laundry Services (except Coin-Operated)
Default compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR
LOCAL GOVERNMENT
Current HPV: Not reported

Compliance and Enforcement Major Issues:

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: Not reported
National action type: Not reported
Date achieved: Not reported
Penalty amount: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1204
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1301
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1303
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1004
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1004
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1101
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1101
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1102
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1102
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1103
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1104
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1201
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1201
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1202
Air prog code hist file:	MACT (SECTION 63 NESHAPS)
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMPIRE CLEANERS (Continued)

1000261171

Hist compliance date: 1203
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: MACT (SECTION 63 NESHAPS)

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: MACT (SECTION 63 NESHAPS)

Compliance & Violation Data by Minor Sources:

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: SIP SOURCE
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT
Repeat violator date: Not reported
Turnover compliance: Not reported

Air program code: MACT (SECTION 63 NESHAPS)
Plant air program pollutant: Not reported
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: UNCLASSIFIED
Repeat violator date: Not reported
Turnover compliance: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BQ438
NE
1/8-1/4
0.221 mi.
1167 ft.

674 9TH AVE
NEW YORK, NY 10036

Site 4 of 6 in cluster BQ

EDR US Hist Cleaners

1015086527
N/A

Relative:
Higher

EDR Historical Cleaners:

Name: EMPIRE TAILORS & CLEANERS INC
Year: 2001
Address: 674 9TH AVE

Actual:
44 ft.

Name: EMPIRE TAILORS & CLEANERS INC
Year: 2003
Address: 674 9TH AVE

Name: EMPIRE TAILORS & CLEANERS
Year: 2007
Address: 674 9TH AVE

Name: EMPIRE TAILORS & CLEANERS
Year: 2008
Address: 674 9TH AVE

Name: EMPIRE TAILORS & CLEANERS INC
Year: 2010
Address: 674 9TH AVE

Name: EMPIRE TAILORS & CLEANERS
Year: 2011
Address: 674 9TH AVE

Name: EMPIRE TAILORS & CLEANERS
Year: 2012
Address: 674 9TH AVE

BQ439
NE
1/8-1/4
0.221 mi.
1167 ft.

EMPIRE CLEANER
674 NINTH AVE.
NEW YORK, NY 10036

Site 5 of 6 in cluster BQ

NY DRYCLEANERS

S109527357
N/A

Relative:
Higher

DRYCLEANERS:

Facility ID: 2-6202-00226
Phone Number: 212-586-0122
Region: Not reported
Registration Effective Date: 9/6/2001 13:50:07:886
Inspection Date: 07MAY21
Install Date: 01
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Actual:
44 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BT440
NW
1/8-1/4
0.221 mi.
1169 ft.

FDNY RESCUE 1
530 WEST 43RD ST
MANHATTAN, NY
Site 3 of 9 in cluster BT

NY LTANKS
NY Spills
S102660118
N/A

Relative:
Lower

Actual:
19 ft.

LTANKS:

Site ID: 176798
Spill Number/Closed Date: 9706580 / 7/6/1999
Spill Date: 9/2/1997
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 9/2/1997
CID: 312
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 9/2/1997
Spill Record Last Update: 8/6/1999
Spiller Name: TONY MARINO
Spiller Company: NYC DEPT OF DESIGN/CONSTR
Spiller Address: 30-30 THOMPSON AV 5TH FL
Spiller City,St,Zip: LONG ISLAND CITY, NY 11101-001
Spiller County: 001
Spiller Contact: TONY MARINO
Spiller Phone: (718) 391-1062
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 148576
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD"URS performed investigation. No further action required.
Remarks: SAMPLES FOUND CONTAMINATED SOIL ON SITE

Material:

Site ID: 176798
Operable Unit ID: 1049933
Operable Unit: 01
Material ID: 332168
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FDNY RESCUE 1 (Continued)

S102660118

Tank Test:

SPILLS:

Facility ID: 9613779
Facility Type: ER
DER Facility ID: 272467
Site ID: 176797
DEC Region: 2
Spill Date: 2/24/1997
Spill Number/Closed Date: 9613779 / 3/23/2006
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 2/24/1997
CID: 297
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/24/1997
Spill Record Last Update: 3/23/2006
Spiller Name: TONY MARINO
Spiller Company: NEW YORK CITY FD
Spiller Address: 530 WEST 43RD ST
Spiller City,St,Zip: MANHATTEN, NY
Spiller Company: 001
Contact Name: TONY MARINO
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"ZHITOMIRSKY"URS PERFORMED INVESTIGATION. NO FURTHER ACTION REQUIRED.
10/11/2005 According to Jane Staten (URS)URS submitted ISRP on
10/18/1999. Contamination was a result of fire in 1987 and not from
the former UST.ISRP recommended NFA for the site. On August 17, 1999
AZ approved this recommendation. On October 18, 1999, NFA letter was
issued. AZ
Remarks: CALLER COMPANY TESTED SOIL FOR AN UNDERGROUND FUEL TANK CLOSURE AND
THEY JUST RECEIVED THE RESULTS TODAY THAT THE SOIL IS CONTAMINATED

Material:

Site ID: 176797
Operable Unit ID: 1045207
Operable Unit: 01
Material ID: 338883
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FDNY RESCUE 1 (Continued)

S102660118

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

BW441
WNW
1/8-1/4
0.221 mi.
1169 ft.

545 W 42ND ST
NEW YORK, NY 10036

EDR US Hist Auto Stat 1015548239
N/A

Site 1 of 7 in cluster BW

Relative:
Lower

EDR Historical Auto Stations:

Name: AJAX AUTO TECH COLLISION
Year: 2004
Address: 545 W 42ND ST

Actual:
19 ft.

Name: AJAX AUTO TECH COLLISION
Year: 2010
Address: 545 W 42ND ST

Name: AJAX AUTO TECH COLLISION
Year: 2011
Address: 545 W 42ND ST

Name: AJAX AUTO TECH COLLISION
Year: 2012
Address: 545 W 42ND ST

BX442
ENE
1/8-1/4
0.222 mi.
1170 ft.

CON EDISON
F/O 346 W 46 & 9TH AVE
NEW YORK, NY 10036

NY MANIFEST S112210733
N/A

Site 1 of 2 in cluster BX

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004269239
Country: USA

Actual:
42 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210733

Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269239
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456232JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-18
Trans1 Recv Date: 2012-09-18
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-18
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004269239
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456232JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210733

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BX443 **CON EDISON SERVICE BOX: 8892**
ENE **346 W 46TH & 8TH AVE FRONT OF**
1/8-1/4 **NEW YORK, NY 10036**
0.222 mi.
1170 ft. **Site 2 of 2 in cluster BX**

RCRA-CESQG **1016144135**
FINDS **NYP004269239**

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 09/18/2012

Actual:
42 ft.

Facility name: CON EDISON SERVICE BOX: 8892
Facility address: 346 W 46TH & 8TH AVE FRONT OF
NEW YORK, NY 10036

EPA ID: NYP004269239
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JOSE MONTALVO
Contact address: Not reported
Not reported

Contact country: Not reported
Contact telephone: (212) 427-1331
Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8892 (Continued)

1016144135

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055435621

Environmental Interest/Information System

BO444
West
1/8-1/4
0.222 mi.
1171 ft.

CON EDISON
OPP 543 W 40TH ST
NEW YORK, NY 10018
Site 4 of 4 in cluster BO

NY MANIFEST S112210338
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265088
Country: USA

Actual:
20 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-27
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265088
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 750.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210338

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-27
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265088
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 750.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456113JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BR445 333 WEST 39TH ST
SSE 333 WEST 39TH ST
1/8-1/4 NEW YORK, NY 10018
0.223 mi.
1179 ft. Site 6 of 10 in cluster BR

NY AST U003386445
N/A

Relative: AST:
Higher Region: STATE
DEC Region: 2
Actual: Site Status: Active
36 ft. Facility Id: 2-241652
Program Type: PBS
UTM X: 585114.83539000002
UTM Y: 4512145.040959999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

333 WEST 39TH ST (Continued)

U003386445

Expiration Date: 10/15/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 9216
Affiliation Type: Facility Owner
Company Name: JOFFEE-333 W. 39 REALTY LLC C/O NEIL JOFFEE
Contact Type: PROPERTY MANAGER
Contact Name: EDWARD CAMUZO
Address1: 125 PARK AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017
Country Code: 001
Phone: (212) 564-8275
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Site Id: 9216
Affiliation Type: Mail Contact
Company Name: NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: EDWARD CAMUZO
Address1: 589 EIGHTH AVENUE
Address2: 12TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 244-9400
EMail: ECAMUZO@NGKF.COM
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Site Id: 9216
Affiliation Type: On-Site Operator
Company Name: 333 WEST 39TH ST
Contact Type: Not reported
Contact Name: JOHN PORMIGIANO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 564-8275
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Site Id: 9216
Affiliation Type: Emergency Contact
Company Name: JOFFEE-333 W. 39 REALTY LLC C/O NEIL JOFFEE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

333 WEST 39TH ST (Continued)

U003386445

Contact Type: Not reported
Contact Name: EDWARD CAMUZO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 244-9400
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 1/17/2013

Tank Info:

Tank Number: 001
Tank Id: 9957
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/01/1925
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DMMOLOUG
Last Modified: 01/17/2013
Material Name: #4 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BW446 **CON EDISON SERVICE BOX: 8074**
WNW **546 W 42ND ST**
1/8-1/4 **NEW YORK, NY 10036**
0.223 mi.
1179 ft. **Site 2 of 7 in cluster BW**

RCRA-CESQG **1016144068**
FINDS **NYP004268553**

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/14/2012

Facility name: CON EDISON SERVICE BOX: 8074

Facility address: 546 W 42ND ST

NEW YORK, NY 10036

EPA ID: NYP004268553

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055429264

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8074 (Continued)

1016144068

Environmental Interest/Information System

BW447
WNW
1/8-1/4
0.223 mi.
1179 ft.

CON EDISON
546 W 42ND ST
NEW YORK, NY 10036

Site 3 of 7 in cluster BW

NY MANIFEST **S112210669**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268553
Country: USA

Actual:
19 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268553
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456584JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210669

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268553
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456584JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BK448 **CON EDISON SERVICE BOX: 4158**
East **557 W 23RD ST**
1/8-1/4 **NEW YORK, NY 10014**
0.223 mi.
1179 ft. **Site 4 of 4 in cluster BK**

RCRA NonGen / NLR **1016144148**
FINDS **NYP004269361**

Relative: RCRA NonGen / NLR:
Higher Date form received by agency: 03/22/2013
Facility name: CON EDISON SERVICE BOX: 4158
Actual: Facility address: 557 W 23RD ST
42 ft. NEW YORK, NY 10014
EPA ID: NYP004269361
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 4158 (Continued)

1016144148

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 02/22/2013
Site name: CON EDISON SERVICE BOX: 4158
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055461307

Environmental Interest/Information System

BY449
SSW
1/8-1/4
0.225 mi.
1189 ft.

CON EDISON SERVICE BOX: 7173
350 W 38TH ST
NEW YORK, NY 10018
Site 1 of 8 in cluster BY

RCRA-CESQG **1016143753**
FINDS **NYP004265369**

Relative:
Higher

RCRA-CESQG:

Actual:
38 ft.

Date form received by agency: 08/28/2012
Facility name: CON EDISON SERVICE BOX: 7173
Facility address: 350 W 38TH ST
NEW YORK, NY 10018
EPA ID: NYP004265369
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7173 (Continued)

1016143753

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055424946

Environmental Interest/Information System

BT450 **43RD PARKING CORP**
NW **541 W 43 ST**
1/8-1/4 **NY, NY 10036**
0.226 mi.
1192 ft. **Site 4 of 9 in cluster BT**

NY UST **U000399370**
NY HIST UST **N/A**

Relative:
Lower

UST:
Id/Status: 2-296473 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 07/07/2002
UTM X: 584770.20799000002
UTM Y: 4512698.2978400001
Site Type: Unknown

Actual:
19 ft.

Affiliation Records:
Site Id: 13653
Affiliation Type: Facility Owner
Company Name: 43RD PARKING CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 541 W 43 ST
Address2: Not reported
City: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

43RD PARKING CORP (Continued)

U000399370

State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 643-2062
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13653
Affiliation Type: Mail Contact
Company Name: 43RD PARKING CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 541 W 43 ST
Address2: Not reported
City: NY
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 643-2062
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13653
Affiliation Type: On-Site Operator
Company Name: 43RD PARKING CORP
Contact Type: Not reported
Contact Name: 43-44 MGT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-2062
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13653
Affiliation Type: Emergency Contact
Company Name: 43RD PARKING CORP
Contact Type: Not reported
Contact Name: GAUY SPINDLA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-8631
EMail: Not reported
Fax Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

43RD PARKING CORP (Continued)

U000399370

Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 12166
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 04/23/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 12167
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 04/23/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

43RD PARKING CORP (Continued)

U000399370

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-296473
SPDES Number: Not reported
Emergency Contact: GAUY SPINDLA
Emergency Telephone: (212) 643-8631
Operator: 43-44 MGT
Operator Telephone: (212) 643-2062
Owner Name: 43RD PARKING CORP
Owner Address: 541 W 43 ST
Owner City,St,Zip: NY, NY 10036
Owner Telephone: (212) 643-2062
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: 43RD PARKING CORP
Mailing Address: 541 W 43 ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NY, NY 10036
Mailing Contact: Not reported
Mailing Telephone: (212) 643-2062
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Facility Addr2: 541 W 43 ST
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 12/01/2000
Expiration Date: 07/07/2002
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 8000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

43RD PARKING CORP (Continued)

U000399370

Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Temporarily Out Of Service
Install Date: Not reported
Capacity (gals): 4000
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Other
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Temporarily Out Of Service
Install Date: Not reported
Capacity (gals): 4000
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Other
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BT451 **CON EDISON MANHOLE: 8295**
NW **541 W 43RD ST**
1/8-1/4 **NEW YORK, NY 10036**
0.226 mi.
1192 ft. **Site 5 of 9 in cluster BT**

RCRA-CESQG **1016144054**
FINDS **NYP004268413**

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/13/2012

Facility name: CON EDISON MANHOLE: 8295

Facility address: 541 W 43RD ST

NEW YORK, NY 10036

EPA ID: NYP004268413

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055428201

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON MANHOLE: 8295 (Continued)

1016144054

Environmental Interest/Information System

BT452
NW
1/8-1/4
0.226 mi.
1192 ft.

CON EDISON
541 W 43RD ST
NEW YORK, NY 10036

Site 6 of 9 in cluster BT

NY MANIFEST **S112210655**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004268413
Country: USA

Actual:
19 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268413
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457023JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210655

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268413
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457023JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BT453 MARVIN MITHELL
NW 541 WEST 43RD STREET
1/8-1/4 NEW YORK, NY 10036
0.226 mi.
1192 ft. Site 7 of 9 in cluster BT

NY UST U003418632
NY HIST UST N/A

Relative: UST:
Lower Id/Status: 2-603858 / Unregulated/Closed
Program Type: PBS
Actual: Region: STATE
19 ft. DEC Region: 2
Expiration Date: 12/29/2003
UTM X: 584770.20799000002
UTM Y: 4512698.2978400001
Site Type: Unknown
Affiliation Records:
Site Id: 25757
Affiliation Type: Facility Owner
Company Name: MARVIN MITCHELL
Contact Type: Not reported
Contact Name: Not reported
Address1: 157 CONGRESS STREET
Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARVIN MITHELL (Continued)

U003418632

City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 624-3859
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25757
Affiliation Type: Mail Contact
Company Name: MARVIN MITCHELL
Contact Type: Not reported
Contact Name: MARVIN MITCHELL
Address1: 2112 BROADWAY #413
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 362-4455
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25757
Affiliation Type: On-Site Operator
Company Name: MARVIN MITHELL
Contact Type: Not reported
Contact Name: GARY SPINDLER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-2062
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 25757
Affiliation Type: Emergency Contact
Company Name: MARVIN MITCHELL
Contact Type: Not reported
Contact Name: MARVIN MITCHELL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 362-4455
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARVIN MITHELL (Continued)

U003418632

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank ID: 55790
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 55791
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARVIN MITHELL (Continued)

U003418632

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

HIST UST:

PBS Number: 2-603858
SPDES Number: Not reported
Emergency Contact: MARVIN MITCHEL
Emergency Telephone: (212) 362-4455
Operator: GARY SPINDLER
Operator Telephone: (212) 643-2062
Owner Name: MARVIN MITCHELL
Owner Address: 157 CONGRESS STREET
Owner City,St,Zip: BROOKLYN, NY 11201
Owner Telephone: (718) 624-3859
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Name: MARVIN MITCHELL
Mailing Address: 2112 BROADWAY #413
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10023
Mailing Contact: MARVIN MITCHELL
Mailing Telephone: (212) 362-4455
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons)
and Subpart 360-14.
Facility Addr2: 541 WEST 43RD STREET
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: Not reported
Expiration Date: 12/29/2003
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MARVIN MITHELL (Continued)

U003418632

Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 4000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 01/01/1999
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 4000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 01/01/1999
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BT454
NW
1/8-1/4
0.226 mi.
1192 ft.
541 W 43RD ST
NEW YORK, NY 10036
Site 8 of 9 in cluster BT

EDR US Hist Auto Stat **1015546735**
N/A

Relative: EDR Historical Auto Stations:
Lower Name: ALLSTATE LEASING & CAR RENTAL
 Year: 2002
Actual: Address: 541 W 43RD ST
19 ft.

BQ455
NE
1/8-1/4
0.226 mi.
1193 ft.
676 9TH AVE
NEW YORK, NY 10036
Site 6 of 6 in cluster BQ

EDR US Hist Cleaners **1015086666**
N/A

Relative: EDR Historical Cleaners:
Higher Name: CARILLIS CARPET CLEANING INC
 Year: 2006
Actual: Address: 676 9TH AVE
44 ft.

 Name: CARILLIS CARPET CLEANING INC
 Year: 2008
 Address: 676 9TH AVE

 Name: CARILLIS CARPET CLEANING INC
 Year: 2009
 Address: 676 9TH AVE

 Name: CARILLIS CARPET CLEANING INC
 Year: 2009
 Address: 676 9TH AVE

 Name: ACTION CARPET CLEANERS
 Year: 2009
 Address: 676 9TH AVE

BY456
South
1/8-1/4
0.226 mi.
1194 ft.
341-343 WEST 38TH STREET
341-343 WEST 38TH STREET
NEW YORK, NY 10002
Site 2 of 8 in cluster BY

NY AST **A100173490**
N/A

Relative: **AST:**
Higher Region: STATE
 DEC Region: 2
Actual: Site Status: Active
38 ft. Facility Id: 2-601279
 Program Type: PBS
 UTM X: 585010.589000000004
 UTM Y: 4512083.22869999999
 Expiration Date: 11/14/2005
 Site Type: Other

Affiliation Records:
 Site Id: 23246
 Affiliation Type: Facility Owner
 Company Name: CENTRAL PROPERTIES LLC % ELK INVESTORS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

341-343 WEST 38TH STREET (Continued)

A100173490

Contact Type: Not reported
Contact Name: Not reported
Address1: 641 LEXINGTON AVENUE, 23RD FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 371-5050
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23246
Affiliation Type: Mail Contact
Company Name: CENTRAL PROPERTIES LLC
Contact Type: Not reported
Contact Name: ABNER OHEBSHALOM
Address1: % ELK INVESTORS
Address2: 641 LEXINGTON AVENUE, 23RD FLOOR
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 371-5050
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23246
Affiliation Type: On-Site Operator
Company Name: 341-343 WEST 38TH STREET
Contact Type: Not reported
Contact Name: CARLOS PLATERO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 279-2383
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23246
Affiliation Type: Emergency Contact
Company Name: CENTRAL PROPERTIES LLC % ELK INVESTORS
Contact Type: Not reported
Contact Name: MARIO ESPINOZA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

341-343 WEST 38TH STREET (Continued)

A100173490

Zip Code: Not reported
Country Code: 001
Phone: (212) 670-5468
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 45184
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F04 - Pipe External Protection - Fiberglass
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 4750
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

**BR457
SSE
1/8-1/4
0.227 mi.
1198 ft.**

**WEST 39TH STREET DEVELOPMENT
328-339 WEST 39TH STREET AND
NEW YORK, NY 10018**

**NY UST U004159792
N/A**

Site 7 of 10 in cluster BR

**Relative:
Higher**

UST:
Id/Status: 2-611490 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/16/2015
UTM X: 585083.55374
UTM Y: 4512118.4961799998
Site Type: Other

**Actual:
36 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

U004159792

Affiliation Records:

Site Id:	443466
Affiliation Type:	Facility Owner
Company Name:	WEST 39TH STREET LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1200 UNION TURNPIKE
Address2:	Not reported
City:	NEW HYDE PARK
State:	NY
Zip Code:	11040
Country Code:	001
Phone:	(718) 343-6400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/16/2010
Site Id:	443466
Affiliation Type:	Mail Contact
Company Name:	CNS MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	CHARLES POWERS
Address1:	208 NEWTOWN ROAD
Address2:	Not reported
City:	PLAINVIEW
State:	NY
Zip Code:	11803
Country Code:	001
Phone:	(516) 932-3228
EMail:	CPOWERS@CNSMANAGEMENT.NET
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/16/2010
Site Id:	443466
Affiliation Type:	On-Site Operator
Company Name:	WEST 39TH STREET DEVELOPMENT
Contact Type:	Not reported
Contact Name:	STEVE GRISWOLD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 643-6777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	12/16/2010
Site Id:	443466
Affiliation Type:	Emergency Contact
Company Name:	WEST 39TH STREET LLC
Contact Type:	Not reported
Contact Name:	CHARLES POWERS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

U004159792

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 932-3228
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/16/2010

Tank Info:

Tank Number: 001
Tank ID: 237383
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/09/2010
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 12/16/2010

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
J03 - Dispenser - Gravity
F00 - Pipe External Protection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 237384
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/09/2010
Registered: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

U004159792

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 12/16/2010

Equipment Records:

J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

BR458
SSE
1/8-1/4
0.227 mi.
1198 ft.

WEST 39TH STREET DEVELOPMENT
328-339 WEST 39TH STREET AND
NEW YORK, NY 10018

NY AST **A100354128**
N/A

Site 8 of 10 in cluster BR

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-611490
Program Type: PBS
UTM X: 585083.55374
UTM Y: 4512118.4961799998
Expiration Date: 12/16/2015
Site Type: Other

Actual:
36 ft.

Affiliation Records:

Site Id: 443466
Affiliation Type: Facility Owner
Company Name: WEST 39TH STREET LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 1200 UNION TURNPIKE
Address2: Not reported
City: NEW HYDE PARK
State: NY
Zip Code: 11040
Country Code: 001
Phone: (718) 343-6400
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

A100354128

Date Last Modified: 12/16/2010

Site Id: 443466
Affiliation Type: Mail Contact
Company Name: CNS MANAGEMENT CORP.
Contact Type: Not reported
Contact Name: CHARLES POWERS
Address1: 208 NEWTOWN ROAD
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 932-3228
EMail: CPOWERS@CNSMANAGEMENT.NET
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/16/2010

Site Id: 443466
Affiliation Type: On-Site Operator
Company Name: WEST 39TH STREET DEVELOPMENT
Contact Type: Not reported
Contact Name: STEVE GRISWOLD
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 643-6777
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/16/2010

Site Id: 443466
Affiliation Type: Emergency Contact
Company Name: WEST 39TH STREET LLC
Contact Type: Not reported
Contact Name: CHARLES POWERS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 932-3228
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/16/2010

Tank Info:

Tank Number: 003
Tank Id: 237385

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

A100354128

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
J03 - Dispenser - Gravity
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled
(Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/03/2010
Register: True
Modified By: NRLOMBAR
Last Modified: 12/16/2010
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 004
Tank Id: 237386
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
G09 - Tank Secondary Containment - Modified Double-Walled
(Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET DEVELOPMENT (Continued)

A100354128

Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/03/2010
Register: True
Modified By: NRLOMBAR
Last Modified: 12/16/2010
Material Name: #2 Fuel Oil (On-Site Consumption)

**BR459
SSE
1/8-1/4
0.227 mi.
1198 ft.**

**WEST 39TH STREET LLC
328-336 W 39TH ST
NEW YORK, NY 10018**

RCRA-LQG

**1014399877
NYR000179671**

Site 9 of 10 in cluster BR

**Relative:
Higher**

RCRA-LQG:

Date form received by agency: 01/31/2012

Facility name: WEST 39TH STREET LLC

Facility address: 328-336 W 39TH ST
NEW YORK, NY 10018

EPA ID: NYR000179671

Mailing address: UNION TNPK
NEW HYDE PARK, NY 11040

Contact: CHARLES POWERS

Contact address: NEWTOWN RD
PLAINVIEW, NY 11803

Contact country: US

Contact telephone: (516) 932-3228

Contact email: CPOWERS@CNSMANAGEMENT.NET

EPA Region: 02

Land type: Private

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: WEST 39TH STREET LLC

Owner/operator address: Not reported
Not reported

Owner/operator country: US

Owner/operator telephone: Not reported

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: 12/17/2009

Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

1014399877

Owner/operator name: WEST 39TH STREET LLC

Owner/operator address: Not reported

Owner/operator country: Not reported

Owner/operator telephone: Not reported

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: 12/17/2009

Owner/Op end date: Not reported

Owner/operator name: WEST 39TH STREET LLC

Owner/operator address: UNION TNPK

NEW HYDE PARK, NY 11040

Owner/operator country: US

Owner/operator telephone: (718) 343-6400

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: 12/17/2009

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Used oil Specification marketer: No

Used oil transfer facility: No

Used oil transporter: No

Historical Generators:

Date form received by agency: 09/14/2011

Site name: WEST 39TH STREET LLC

Classification: Not a generator, verified

Date form received by agency: 12/21/2010

Site name: WEST 39TH STREET LLC

Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D008

Waste name: LEAD

Waste code: D008

Waste name: LEAD

Waste code: D008

Waste name: LEAD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

1014399877

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D008
Waste name: LEAD
Amount (Lbs): 20426000

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 10/10/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

BY460
SSW
1/8-1/4
0.227 mi.
1199 ft.

CON EDISON SERVICE BOX: 39820
497 9TH AVE
NEW YORK, NY 10018

RCRA-CESQG
FINDS
1016143752
NYP004265351

Site 3 of 8 in cluster BY

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/28/2012
Facility name: CON EDISON SERVICE BOX: 39820
Facility address: 497 9TH AVE
NEW YORK, NY 10018

EPA ID: NYP004265351
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported

Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported

EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39820 (Continued)

1016143752

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468113

Environmental Interest/Information System

**BY461
SSW
1/8-1/4
0.227 mi.
1199 ft.**

**CON EDISON
497 9TH AVE
NEW YORK, NY 10018

Site 4 of 8 in cluster BY**

**NY MANIFEST S112210364
N/A**

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004265351
Country: USA

**Actual:
38 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265351
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210364

Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456246JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265351
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456246JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BZ462
WNW
1/8-1/4
0.227 mi.
1199 ft.

MERCEDES-BENZ MANHATTAN INC
528 W 41ST ST
NEW YORK, NY 10036

RCRA-CESQG
NY MANIFEST
NY BROWNFIELDS

1000168670
NYD981138472

Site 1 of 8 in cluster BZ

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 01/01/2007

Facility name: MERCEDES-BENZ MANHATTAN INC

Facility address: 528 W 41ST ST
NEW YORK, NY 10036

EPA ID: NYD981138472

Mailing address: W 41ST ST
NEW YORK, NY 10036

Contact: Not reported

Contact address: W 41ST ST
NEW YORK, NY 10036

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: Not reported

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: Not reported

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MERCEDES-BENZ MANHATTAN INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/14/1999
Site name: MERCEDES-BENZ MANHATTAN INC
Classification: Small Quantity Generator

Date form received by agency: 03/22/1994
Site name: MERCEDES-BENZ MANHATTAN
Classification: Large Quantity Generator

Date form received by agency: 02/29/1992
Site name: MERCEDES-BENZ MANHATTAN
Classification: Large Quantity Generator

Date form received by agency: 10/15/1985
Site name: MERCEDES-BENZ MANHATTAN INC
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 08/26/1994
Date achieved compliance: 10/11/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/26/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/26/1994

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Date achieved compliance: 10/11/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/26/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 06/15/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 10/11/1994
Evaluation lead agency: State

Evaluation date: 06/15/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/11/1994
Evaluation lead agency: State

Evaluation date: 10/13/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA Contractor/Grantee

NY MANIFEST:

EPA ID: NYD981138472
Country: USA

Mailing Info:

Name: MERCEDES BENZ MANHATTAN INCORPORATED
Contact: LEAH LANE
Address: 536 WEST 41ST STREET
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 212-760-0606

Document ID: NJA0139649
Manifest Status: Completed copy
Trans1 State ID: NJDEPDECA
Trans2 State ID: Not reported
Generator Ship Date: 860218
Trans1 Recv Date: 860218
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860219
Part A Recv Date: 860226
Part B Recv Date: 860226
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Quantity: 00051
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NJA0298962
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880518
Trans1 Recv Date: 880518
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880519
Part A Recv Date: 880615
Part B Recv Date: 880531
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00050
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 88

Document ID: NJA0331318
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 880517
Trans1 Recv Date: 880517
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880518
Part A Recv Date: 880526
Part B Recv Date: 880523
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768101
Waste Code: F003 - UNKNOWN
Quantity: 00360
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Document ID: NJA0381538
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880118
Trans1 Recv Date: 880118
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880119
Part A Recv Date: 880216
Part B Recv Date: 880128
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00145
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0297679
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 880720
Trans1 Recv Date: 880720
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880720
Part A Recv Date: 880808
Part B Recv Date: 880728
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: F005 - UNKNOWN
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 88

Document ID: NJA1346260
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911023
Trans1 Recv Date: 911023
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911023
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Part B Recv Date: 911115
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00344
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA0919244
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910904
Trans1 Recv Date: 910904
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910905
Part A Recv Date: 910923
Part B Recv Date: 910923
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01098
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1333142
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911217
Trans1 Recv Date: 911217
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911217
Part A Recv Date: Not reported
Part B Recv Date: 920109
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00344
Units: P - Pounds
Number of Containers: 004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: PAC6531571
Manifest Status: Completed copy
Trans1 State ID: PAAH0172
Trans2 State ID: Not reported
Generator Ship Date: 920110
Trans1 Recv Date: 920110
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920114
Part A Recv Date: 920127
Part B Recv Date: 920128
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: PAD987266715
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92

Document ID: NJA1924610
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940930
Trans1 Recv Date: 940930
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940930
Part A Recv Date: 941026
Part B Recv Date: 941019
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00060
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 94

Document ID: NJA1820963
Manifest Status: Completed copy
Trans1 State ID: NJDEPE086

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Trans2 State ID: 00602
Generator Ship Date: 940830
Trans1 Recv Date: 940830
Trans2 Recv Date: 940913
TSD Site Recv Date: 940913
Part A Recv Date: Not reported
Part B Recv Date: 940923
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: NYD980769947
TSD ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00330
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA1949703
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 941123
Trans1 Recv Date: 941123
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941123
Part A Recv Date: 941222
Part B Recv Date: 941208
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00063
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 94

Document ID: NJA2060213
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950120
Trans1 Recv Date: 950120
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950120
Part A Recv Date: 950206
Part B Recv Date: 950207
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD984908202

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00065
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 95

Document ID: CTB0032299
Manifest Status: Completed copy
Trans1 State ID: XH54TR/NJ
Trans2 State ID: Not reported
Generator Ship Date: 860421
Trans1 Recv Date: 860421
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860422
Part A Recv Date: 860429
Part B Recv Date: 860429
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSD ID: CTD072138969
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00052
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NJA0236462
Manifest Status: Completed copy
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 861020
Trans1 Recv Date: 861020
Trans2 Recv Date: Not reported
TSD Site Recv Date: 861020
Part A Recv Date: 861024
Part B Recv Date: 861030
Generator EPA ID: NYD981138472
Trans1 EPA ID: NJD980787147
Trans2 EPA ID: Not reported
TSD ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00175
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Year: 86

Document ID: NJA0327116
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 881130
Trans1 Recv Date: 881130
Trans2 Recv Date: Not reported
TSD Site Recv Date: 881207
Part A Recv Date: 890109
Part B Recv Date: 881213
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768101
Waste Code: F003 - UNKNOWN
Quantity: 00576
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 88

Document ID: NJA0619090
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 890321
Trans1 Recv Date: 890321
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890321
Part A Recv Date: 890412
Part B Recv Date: 890328
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768101
Waste Code: F003 - UNKNOWN
Quantity: 00360
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NJA0635201
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 890524
Trans1 Recv Date: 890524

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Trans2 Recv Date: Not reported
TSD Site Recv Date: 890531
Part A Recv Date: 890612
Part B Recv Date: 890607
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768101
Waste Code: F003 - UNKNOWN
Quantity: 00411
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 89

Document ID: NJA1460462
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920406
Trans1 Recv Date: 920406
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920406
Part A Recv Date: 920416
Part B Recv Date: 920416
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00344
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

Document ID: NJA1357342
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 921116
Trans1 Recv Date: 921116
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921116
Part A Recv Date: 921201
Part B Recv Date: 921203
Generator EPA ID: NYD981138472
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

Quantity: 00344
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 92

[Click this hyperlink](#) while viewing on your computer to access
97 additional NY_MANIFEST: record(s) in the EDR Site Report.

BROWNFIELDS:

Program: BCP
Site Code: 460494

Site Description: Site Location: The site is located at 536 West 41st Street in New York City, New York County and consists of one tax parcel. Historically this was a number of lots which recently consolidated into one lot which is 2.296 acres in size and is in the Hell's Kitchen neighborhood. Site Features: The site has a one to two story brick and concrete building with a partial basement and an asphalt-paved parking lot. Unused Amtrak tunnels and the No.7 train extension tunnels are located approximately 25 to 30 feet beneath the ground surface. It is bordered by a utility building to the north, a church and abandoned gas station to the east, bus parking to the south, and a NYC Transit Authority bus depot to the west. Current Zoning/Uses: The site is currently vacant and is zoned C6-4 which is a mixed commercial/residential zone. Mixed use residential/commercial sites are located to the west of the site. Commercial buildings are located to the north while to the east are two churches and an abandoned commercial site. North east of the site are condominiums and a police station. Historical Uses: The site has included a bottling company and warehouse, an auto repair station, and a filling station in the past. Site Geography and Geology: The surface topography slopes down to the east and is approximately 20 feet above mean sea level. Due to the topography, it is expected that groundwater would flow from the southwest towards the Hudson River. However, the groundwater flow can be affected by factors such as bedrock, fill and other factors. Depth to bedrock ranges from 4 feet on the west side of the site to 19 feet on the east side. Bedrock consists of schist with granite intrusions.

Env Problem: Nature and Extent of Contamination - There have been three reported spills on the Site since 1996, including diesel and hydraulic oil. Soil - The BCP investigation soil sampling results indicate seven SVOCs exceed the NYSDEC Unrestricted Soil Cleanup Objectives (SCOs). Most notable of the SVOCs was benzo(a) pyrene, which slightly exceeded the commercial SCO of 1 ppm at two location with a maximum concentration of 1.33 ppm. Metals exceeding unrestricted SCOs were detected in 10 of 11 locations sampled during the RI. The primary metal contaminant was lead, found above unrestricted SCOs in 8 of the original 11 samples and all 14 supplemental lead samples. Maximum lead concentration was 6590 ppm, which exceeded both the unrestricted SCO of 63 ppm as well as the commercial SCO of 1000 ppm. PCBs also exceed the unrestricted SCO of 0.1 ppm at two location, with a maximum concentration of 0.348 ppm. The pesticide 4,4'-DDT exceeded the unrestricted SCO of 0.0033 ppm at 6 locations with a maximum concentration of 0.0826 ppm. 4,4'-DDD and 4,4' DDE also exceeded unrestricted SCOs in one location. Groundwater - Groundwater impacts

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN INC (Continued)

1000168670

are limited to slight exceedances of groundwater standards by one SVOC (2,4-dichlorophenol at a concentration of 8 ppb compared to the standard of 5 ppb) and several common metals. Soil Vapor - Tetrachloroethene at a maximum concentration of 120 ug/m3.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

BZ463 **MERCEDES/BENZ MANHATTAN INC**
WNW **536 W 41 ST**
1/8-1/4 **NEW YORK, NY 10036**
0.227 mi.
1199 ft. **Site 2 of 8 in cluster BZ**

NY UST **U004078087**
N/A

Relative:
Lower

UST:
Id/Status: 2-426962 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 12/14/2007
UTM X: 584692.55870000005
UTM Y: 4512534.3207900003
Site Type: Other Wholesale/Retail Sales

Actual:
19 ft.

Affiliation Records:
Site Id: 19741
Affiliation Type: Facility Owner
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 536 WEST 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19741
Affiliation Type: Mail Contact
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 536 WEST 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U004078087

Site Id: 19741
Affiliation Type: On-Site Operator
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: MR. RALPH FISHER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19741
Affiliation Type: Emergency Contact
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: MR.MICHEAL KEENAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001-A
Tank ID: 77998
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1100
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U004078087

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

BZ464 **MERCEDES/BENZ MANHATTAN INC**
WNW **536 W 41 ST**
1/8-1/4 **NEW YORK, NY 10036**
0.227 mi.
1199 ft. **Site 3 of 8 in cluster BZ**

NY HIST UST **U003074760**
NY AST **N/A**
NY HIST AST

Relative:
Lower

HIST UST:

Actual:
19 ft.

PBS Number: 2-426962
SPDES Number: Not reported
Emergency Contact: MR. MICHAEL KEENAN
Emergency Telephone: (212) 629-1600
Operator: MR. STEPHAN ALTRICHTER
Operator Telephone: (212) 629-1606
Owner Name: MERCEDES/BENZ MANHATTAN INC
Owner Address: 536 WEST 41ST STREET
Owner City,St,Zip: NEW YORK, NY 10036
Owner Telephone: (212) 760-0600
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: MERCEDES/BENZ MANHATTAN INC
Mailing Address: 536 WEST 41ST STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Contact: MR. THOM LOPEZ
Mailing Telephone: (212) 629-1612
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 536 W 41 ST
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 10/15/1999
Expiration Date: 12/14/2002
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 4500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 1100
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Diking
Leak Detection: None
Overfill Prot: Product Level Gauge
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-426962
Program Type: PBS
UTM X: 584692.55870000005
UTM Y: 4512534.3207900003
Expiration Date: 12/14/2007
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 19741
Affiliation Type: Facility Owner
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 536 WEST 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19741
Affiliation Type: Mail Contact
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 536 WEST 41ST STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19741
Affiliation Type: On-Site Operator
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: MR. RALPH FISHER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 19741
Affiliation Type: Emergency Contact
Company Name: MERCEDES/BENZ MANHATTAN INC
Contact Type: Not reported
Contact Name: MR.MICHEAL KEENAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 629-1600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Tank Number: 001
Tank Id: 77997
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1991
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Other

Tank Number: 002
Tank Id: 78000
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/1991
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Other

Tank Number: 002-A
Tank Id: 78001
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

6
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Other

Tank Number: 003
Tank Id: 78002
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground

1
Tank Location:
Tank Type: Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/01/1991
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Lube Oil

Tank Number: 003-A
Tank Id: 78003
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G07 - Tank Secondary Containment - Excavation Liner

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Other

Tank Number: 004
Tank Id: 63500
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

H99 - Tank Leak Detection - Other
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2002
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Lube Oil

HIST AST:

PBS Number: 2-426962
SWIS Code: 6201
Operator: MR. STEPHAN ALTRICHTER
Facility Phone: (212) 629-1606
Facility Addr2: 536 W 41 ST
Facility Type: OTHER
Emergency: MR. MICHAEL KEENAN
Emergency Tel: (212) 629-1600
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MERCEDES/BENZ MANHATTAN INC
Owner Address: 536 WEST 41ST STREET
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 760-0600
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: MR. THOM LOPEZ
Mailing Name: MERCEDES/BENZ MANHATTAN INC
Mailing Address: 536 WEST 41ST STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 629-1612
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/15/1999
Expiration: 12/14/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 4500
FAMT: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 002
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 1100
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 003
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (Gal): 1100
Product Stored: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Vault (w/o access)
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES/BENZ MANHATTAN INC (Continued)

U003074760

Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

465
East
1/8-1/4
0.227 mi.
1200 ft.

MILFORD PLAZA HOTEL
700 EIGHTH AVENUE
NEW YORK, NY 10036

NY AST U003387568
N/A

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-296562
Program Type: PBS
UTM X: 585395.69105000002
UTM Y: 4512455.4673600001
Expiration Date: 07/07/2007
Site Type: Other

Actual:
43 ft.

Affiliation Records:

Site Id: 13660
Affiliation Type: Facility Owner
Company Name: MILFORD PLAZA ASSOCIATES
Contact Type: Not reported
Contact Name: Not reported
Address1: 1271 AVE OF THE AMERICAS
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10020
Country Code: 001
Phone: (212) 708-0800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13660
Affiliation Type: Mail Contact
Company Name: MILFORD PLAZA ASSOCIATES
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 700 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 869-3600
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILFORD PLAZA HOTEL (Continued)

U003387568

Date Last Modified: 4/11/2014

Site Id: 13660
Affiliation Type: On-Site Operator
Company Name: MILFORD PLAZA HOTEL
Contact Type: Not reported
Contact Name: COX HOTEL CORPORATION
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 869-3600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13660
Affiliation Type: Emergency Contact
Company Name: MILFORD PLAZA ASSOCIATES
Contact Type: Not reported
Contact Name: LORENZO MELENDEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 869-3600
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 12172
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MILFORD PLAZA HOTEL (Continued)

U003387568

Pipe Model: Not reported
Install Date: 06/01/1980
Capacity Gallons: 18000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Diesel

BV466
North
1/8-1/4
0.228 mi.
1202 ft.

CONSOLIDATED EDISON
46 ST & 10TH AVE
NEW YORK, NY

NY MANIFEST 1009242106
N/A

Site 2 of 2 in cluster BV

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004107785
Country: USA

Actual:
25 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NJA4138518
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/23/2003
Trans1 Recv Date: 02/23/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004107785
Trans1 EPA ID: NJD991291105
Trans2 EPA ID: Not reported
TSDF ID: 10376
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BT467
NW
1/8-1/4
0.228 mi.
1206 ft.
543 W 43RD ST
NEW YORK, NY 10036
Site 9 of 9 in cluster BT

EDR US Hist Cleaners **1015073895**
N/A

Relative: EDR Historical Cleaners:
Lower Name: ACTION CARPET CLEANERS
 Year: 2001
Actual: Address: 543 W 43RD ST
19 ft.

 Name: ACTION CARPET CLEANERS
 Year: 2002
 Address: 543 W 43RD ST

BR468
SSE
1/8-1/4
0.229 mi.
1209 ft.
WEST 39TH STREET LLC
328 -336 W 39TH ST
NEW YORK, NY 10018
Site 10 of 10 in cluster BR

NY MANIFEST **S110824129**
N/A

Relative: NY MANIFEST:
Higher EPA ID: NYR000179671
 Country: USA

Actual: Mailing Info:
36 ft. Name: WEST 39TH STREET LLC
 Contact: CHARLES POWERS
 Address: 328-336 W 39TH ST
 City/State/Zip: NEW YORK, NY 10018
 Country: USA
 Phone: Not reported

 Document ID: Not reported
 Manifest Status: Not reported
 Trans1 State ID: NJR000066803
 Trans2 State ID: Not reported
 Generator Ship Date: 2010-12-22
 Trans1 Recv Date: 2010-12-22
 Trans2 Recv Date: Not reported
 TSD Site Recv Date: 2010-12-22
 Part A Recv Date: Not reported
 Part B Recv Date: Not reported
 Generator EPA ID: NYR000179671
 Trans1 EPA ID: Not reported
 Trans2 EPA ID: Not reported
 TSDF ID: NJD991291105
 Waste Code: Not reported
 Quantity: 54260.0
 Units: P - Pounds
 Number of Containers: 1.0
 Container Type: DT - Dump trucks
 Handling Method: T Chemical, physical, or biological treatment.
 Specific Gravity: 1.0
 Year: 2010
 Manifest Tracking Num: 005972576JJK
 Import Ind: N
 Export Ind: N
 Discr Quantity Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 59320.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006016535JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 53180.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006016536JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 59380.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006016537JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 63300.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006016538JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 65400.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 006016539JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-29
Trans1 Recv Date: 2010-12-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 63240.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007393782JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 66980.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939679JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 64640.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939680JJK

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 70400.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939681JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 55240.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939682JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 62740.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939683JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 71060.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939684JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Waste Code: Not reported
Quantity: 63200.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939685JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 51860.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939686JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 61180.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939687JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 52280.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Year: 2010
Manifest Tracking Num: 007939689JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 64060.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939690JJJ
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 58040.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939693JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000066803
Trans2 State ID: Not reported
Generator Ship Date: 2010-12-22
Trans1 Recv Date: 2010-12-22
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2010-12-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000179671
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 72160.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2010
Manifest Tracking Num: 007939695JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 39TH STREET LLC (Continued)

S110824129

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

[Click this hyperlink](#) while viewing on your computer to access
387 additional NY_MANIFEST: record(s) in the EDR Site Report.

BN469
SSE
1/8-1/4
0.229 mi.
1210 ft.

CON EDISON SERVICE BOX: 7674
304 W 40TH ST
NEW YORK, NY 10018

RCRA-CESQG **1016143816**
FINDS **NYP004266003**

Site 6 of 7 in cluster BN

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/31/2012

Facility name: CON EDISON SERVICE BOX: 7674

Facility address: 304 W 40TH ST
NEW YORK, NY 10018

EPA ID: NYP004266003

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7674 (Continued)

1016143816

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055469210

Environmental Interest/Information System

**BN470
SSE
1/8-1/4
0.229 mi.
1210 ft.**

**CON EDISON
304 W 40TH ST
NEW YORK, NY 10018**

**NY MANIFEST S112210426
N/A**

Site 7 of 7 in cluster BN

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004266003
Country: USA

**Actual:
39 ft.**

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-31
Trans1 Recv Date: 2012-08-31
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004266003
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456301JJK
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210426

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-31
Trans1 Recv Date: 2012-08-31
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004266003
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456301JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BW471
WNW
1/8-1/4
0.229 mi.
1211 ft.
CON EDISON
550 W 42ND ST
NEW YORK, NY 10036
Site 4 of 7 in cluster BW

Relative: NY MANIFEST:
Lower EPA ID: NYP004268561
Country: USA
Actual: Mailing Info:
19 ft.

NY MANIFEST **S112210670**
N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210670

Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268561
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456585JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268561
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210670

TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456585JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BW472
WNW
1/8-1/4
0.229 mi.
1211 ft.

CON EDISON SERVICE BOX: 8073
550 W 42ND ST
NEW YORK, NY 10036
Site 5 of 7 in cluster BW

RCRA-CESQG **1016144069**
FINDS **NYP004268561**

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 09/14/2012

Facility name: CON EDISON SERVICE BOX: 8073

Facility address: 550 W 42ND ST

NEW YORK, NY 10036

EPA ID: NYP004268561

Mailing address: IRVING PL, RM 828

NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 8073 (Continued)

1016144069

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055459034

Environmental Interest/Information System

CA473 **ENGINE CO. 34 / LADDER 21**
SW **440 WEST 38TH STREET**
1/8-1/4 **NEW YORK, NY 10018**
0.230 mi.
1215 ft. **Site 1 of 5 in cluster CA**

NY AST **U003394386**
N/A

Relative:
Higher

AST:

Actual:
32 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-357642
Program Type: PBS
UTM X: 584767.92168999999
UTM Y: 4512226.6584000001
Expiration Date: 07/28/2003
Site Type: Other

Affiliation Records:

Site Id: 17912
Affiliation Type: Facility Owner
Company Name: NYC FIRE DEPARTMENT
Contact Type: ASSISTANT COMMISSIONER
Contact Name: JOSEPH M. MASTROPIETRO
Address1: 9 METROTECH
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 34 / LADDER 21 (Continued)

U003394386

Date Last Modified: 12/1/2005

Site Id: 17912
Affiliation Type: Mail Contact
Company Name: NEW YORK CITY FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: ASSISTANT COMMISSIONER
Address1: BUILDING MAINTENANCE DIVISION
Address2: 48-34 35TH STREET
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 784-6510
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/1/2005

Site Id: 17912
Affiliation Type: On-Site Operator
Company Name: ENGINE CO. 34 / LADDER 21
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 570-4234
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 12/1/2005

Site Id: 17912
Affiliation Type: Emergency Contact
Company Name: NYC FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: EOC/NOTIFICATION DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/1/2011

Tank Info:

Tank Number: 001
Tank Id: 35151

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 34 / LADDER 21 (Continued)

U003394386

Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G99 - Tank Secondary Containment - Other
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1979
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Diesel

Tank Number: 002
Tank Id: 35152
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1970
Capacity Gallons: 2500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/1999
Register: True
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 34 / LADDER 21 (Continued)

U003394386

Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 003
Tank Id: 55110
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B03 - Tank External Protection - Original Impressed Current
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 01/01/1998
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/1998
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Gasoline

Tank Number: 004
Tank Id: 56210
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 34 / LADDER 21 (Continued)

U003394386

Install Date: 01/01/1999
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/2005
Register: True
Modified By: NRLOMBAR
Last Modified: 12/01/2005
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 005
Tank Id: 56211
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1999
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/2005
Register: True
Modified By: NRLOMBAR
Last Modified: 12/01/2005
Material Name: #2 Fuel Oil (On-Site Consumption)

BY474
SSW
1/8-1/4
0.231 mi.
1219 ft.
CON EDISON
498 9TH AVE
NEW YORK, NY 10018
Site 5 of 8 in cluster BY

NY MANIFEST **S112210361**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004265328
Country: USA

Actual:
39 ft.

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210361

City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265328
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456243JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265328
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 2000.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210361

Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456243JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BY475
SSW
1/8-1/4
0.231 mi.
1219 ft.

CON EDISON SERVICE BOX: 39825
498 9TH AVE
NEW YORK, NY 10018

RCRA-CESQG **1016143749**
FINDS **NYP004265328**

Site 6 of 8 in cluster BY

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/28/2012

Facility name: CON EDISON SERVICE BOX: 39825

Facility address: 498 9TH AVE
NEW YORK, NY 10018

EPA ID: NYP004265328

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 39825 (Continued)

1016143749

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468088

Environmental Interest/Information System

CB476
NW
1/8-1/4
0.232 mi.
1224 ft.

UNITED RENTALS (NORTH AMERICA), INC.
540 WEST 44TH STREET
NEW YORK, NY 10036
Site 1 of 2 in cluster CB

NY AST A100320121
N/A

Relative:
Lower

AST:

Actual:
19 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-610875
Program Type: PBS
UTM X: 584746.750800000004
UTM Y: 4512762.84704000004
Expiration Date: 03/31/2013
Site Type: Other

Affiliation Records:

Site Id: 400683
Affiliation Type: Facility Owner
Company Name: UNITED RENTALS (NORTH AMERICA), INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 791 EAST 64TH AVENUE
Address2: Not reported
City: DENVER
State: CO
Zip Code: 80229
Country Code: 001
Phone: (303) 286-4394
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/31/2011

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED RENTALS (NORTH AMERICA), INC. (Continued)

A100320121

Site Id: 400683
Affiliation Type: Mail Contact
Company Name: UNITED RENTALS (NORTH AMERICA), INC.
Contact Type: Not reported
Contact Name: GRANT ZOIDOWSKI
Address1: 791 EAST 64TH AVENUE
Address2: Not reported
City: DENVER
State: CO
Zip Code: 80229
Country Code: 001
Phone: (303) 286-4394
EMail: ENVIRONMENTAL@UR.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/31/2011

Site Id: 400683
Affiliation Type: On-Site Operator
Company Name: UNITED RENTALS (NORTH AMERICA), INC.
Contact Type: Not reported
Contact Name: UNITED RENTALS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-7300
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/31/2011

Site Id: 400683
Affiliation Type: Emergency Contact
Company Name: UNITED RENTALS (NORTH AMERICA), INC.
Contact Type: Not reported
Contact Name: MC CLAIN VIEIRA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 736-7300
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 5/31/2011

Tank Info:

Tank Number: 001
Tank Id: 223985
Material Code: 0008
Common Name of Substance: Diesel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED RENTALS (NORTH AMERICA), INC. (Continued)

A100320121

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
A02 - Tank Internal Protection - Rubber Liner
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F02 - Pipe External Protection - Original Sacrificial Anode
I02 - Overfill - High Level Alarm
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin

Tank Location: 2
Tank Type: Steel Tank in Concrete
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 03/31/2008
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/26/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 05/31/2011
Material Name: Diesel

Tank Number: 002
Tank Id: 223987
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

C01 - Pipe Location - Aboveground
A01 - Tank Internal Protection - Epoxy Liner
D11 - Pipe Type - Flexible Piping
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
K00 - Spill Prevention - None
E04 - Piping Secondary Containment - Double-Walled (Underground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring

2
Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: E
Install Date: 03/31/2008
Capacity Gallons: 180
Tightness Test Method: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED RENTALS (NORTH AMERICA), INC. (Continued)

A100320121

Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/26/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 05/31/2011
Material Name: Waste Oil/Used Oil

Tank Number: 003
Tank Id: 223988
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
D11 - Pipe Type - Flexible Piping
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E04 - Piping Secondary Containment - Double-Walled (Underground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: E
Install Date: 03/31/2008
Capacity Gallons: 180
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/26/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 05/31/2011
Material Name: Lube Oil

Tank Number: 004
Tank Id: 223989
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

C01 - Pipe Location - Aboveground
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
D11 - Pipe Type - Flexible Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED RENTALS (NORTH AMERICA), INC. (Continued)

A100320121

F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
E04 - Piping Secondary Containment - Double-Walled (Underground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: E
Install Date: 03/31/2008
Capacity Gallons: 180
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/26/2011
Register: True
Modified By: NRLOMBAR
Last Modified: 05/31/2011
Material Name: Lube Oil

CC477 **PORT AUTHORITY BUS TERMINAL**
SE **625 EIGHTH AVENUE**
1/8-1/4 **NEW YORK, NY 10018**
0.232 mi.
1225 ft. **Site 1 of 9 in cluster CC**

NY UST **U004078076**
N/A

Relative:
Higher

UST:
Id/Status: 2-600923 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/07/2017
UTM X: 585240.00136999995
UTM Y: 4512192.4429400004
Site Type: Trucking/Transportation/Fleet Operation

Actual:
40 ft.

Affiliation Records:
Site Id: 22893
Affiliation Type: Facility Owner
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 625 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 502-2240
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/13/2013

Site Id: 22893
Affiliation Type: Mail Contact
Company Name: PORT AUTHORITY OF NY AND NJ
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTHORITY BUS TERMINAL (Continued)

U004078076

Contact Name: ERNEST PEART
Address1: 625 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 502-2214
EMail: EPEART@PANYNJ.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/13/2013

Site Id: 22893
Affiliation Type: On-Site Operator
Company Name: PORT AUTHORITY BUS TERMINAL
Contact Type: Not reported
Contact Name: ERNEST PEART
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 502-2214
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 10/17/2012

Site Id: 22893
Affiliation Type: Emergency Contact
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: COMMUNICATIONS DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 502-2245
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/17/2010

Tank Info:

Tank Number: PABT 2
Tank ID: 44605
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 12/01/1981
Date Tank Closed: Not reported
Registered: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTHORITY BUS TERMINAL (Continued)

U004078076

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None

Tank Number: PABT 2A
Tank ID: 52878
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 10/01/1996
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 12/07/2009

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
E04 - Piping Secondary Containment - Double-Walled (Underground)
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C03 - Pipe Location - Aboveground/Underground Combination
K01 - Spill Prevention - Catch Basin
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CC478
SE
1/8-1/4
0.232 mi.
1225 ft.

CON EDISON AT PORT AUTHORITY OF NY & NJ
625 8TH AVE - BASEMENT
NEW YORK, NY 10018

RCRA NonGen / NLR
FINDS
NY MANIFEST

1001968930
NYR000081265

Site 2 of 9 in cluster CC

Relative:
Higher

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: CON EDISON AT PORT AUTHORITY OF NY & NJ

Facility address: 625 8TH AVE - BASEMENT

NEW YORK, NY 10018

EPA ID: NYR000081265

Mailing address: 1ST AVE ROOM 807

NEW YORK, NY 10017

Contact: JUAN TORIBIO

Contact address: 1ST AVE ROOM 807

NEW YORK, NY 10017

Contact country: US

Contact telephone: (212) 338-4721

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Actual:
40 ft.

Owner/Operator Summary:

Owner/operator name: PORT AUTHORITY OF NY & NJ

Owner/operator address: 625 8TH AVE
NEW YORK, NY 10018

Owner/operator country: US

Owner/operator telephone: (212) 502-2455

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ

Owner/operator address: 625 8TH AVE
NEW YORK, NY 10018

Owner/operator country: US

Owner/operator telephone: (212) 502-2455

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Mixed waste (haz. and radioactive): No

Recycler of hazardous waste: No

Transporter of hazardous waste: No

Treater, storer or disposer of HW: No

Underground injection activity: No

On-site burner exemption: No

Furnace exemption: No

Used oil fuel burner: No

Used oil processor: No

User oil refiner: No

Used oil fuel marketer to burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON AT PORT AUTHORITY OF NY & NJ (Continued)

1001968930

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: CON EDISON AT PORT AUTHORITY OF NY & NJ
Classification: Not a generator, verified

Date form received by agency: 04/18/2000
Site name: CON EDISON AT PORT AUTHORITY OF NY & NJ
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004558997

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000081265
Country: USA

Mailing Info:

Name: CONSOLIDATED EDISON
Contact: FRANKLIN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: NYE0482463
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 05/25/2000
Trans1 Recv Date: 05/25/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/26/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000081265
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSD ID: 28192AU
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON AT PORT AUTHORITY OF NY & NJ (Continued)

1001968930

Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00010
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D009 - MERCURY 0.2 MG/L TCLP
Quantity: 00035
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2000

CC479
SE
1/8-1/4
0.232 mi.
1225 ft.
Site 3 of 9 in cluster CC

PABT - PORT AUTHORITY BUS TERMINAL
625 8TH AVE
NEW YORK, NY 10018

Relative:
Higher

RCRA-LQG
FINDS
NY AST
NY HIST AST
NY MANIFEST
NJ MANIFEST
RI MANIFEST
EPA WATCH LIST

Actual:
40 ft.

RCRA-LQG:
Date form received by agency: 02/16/2012
Facility name: PABT - PORT AUTHORITY BUS TERMINAL
Facility address: 625 8TH AVE
NEW YORK, NY 10018
EPA ID: NYD987012689
Mailing address: 8TH AVE
PORT AUTHORITY BUS TERMINAL
NEW YORK, NY 10018
Contact: ERNEST PEART
Contact address: 8TH AVE PORT AUTHORITY BUS TERMINAL
NEW YORK, NY 10018
Contact country: US
Contact telephone: (212) 502-2303
Contact email: EPEART@PANYNJ.GOV
EPA Region: 02
Land type: Municipal
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: PORT AUTHORITY OF NY AND NJ
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 12/01/1937
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY AND NJ
Owner/operator address: 8TH AVE PORT AUTHORITY BUS TERMINAL
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 12/01/1937
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY & NJ
Owner/operator address: ONE WORLD TRADE CENTER
NEW YORK, NY 10048
Owner/operator country: Not reported
Owner/operator telephone: (212) 435-7000
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Used oil transporter: No

Historical Generators:

Date form received by agency: 02/29/2008

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Large Quantity Generator

Date form received by agency: 01/01/2007

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Small Quantity Generator

Date form received by agency: 01/01/2006

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/02/2002

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Large Quantity Generator

Date form received by agency: 07/14/1999

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Small Quantity Generator

Date form received by agency: 03/20/1996

Site name: PORT AUTHORITY OF NY & NJ

Classification: Large Quantity Generator

Date form received by agency: 03/29/1994

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Large Quantity Generator

Date form received by agency: 08/26/1992

Site name: PORT AUTHORITY BUS TERMINAL

Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D008

Waste name: LEAD

Waste code: D018

Waste name: BENZENE

Waste code: D000

Waste name: Not Defined

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D006

Waste name: CADMIUM

Waste code: D007

Waste name: CHROMIUM

Waste code: D008

Waste name: LEAD

Waste code: D018

Waste name: BENZENE

Waste code: X001

Waste name: WASTE OILS

Waste code: X003

Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 686.7

Waste code: D008

Waste name: LEAD

Amount (Lbs): 20040

Waste code: D018

Waste name: BENZENE

Amount (Lbs): 41.7

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/28/2010
Date achieved compliance: 03/19/2012
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/13/2010
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/28/2010
Date achieved compliance: 03/19/2012
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 09/29/2011
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 0
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/28/2010
Date achieved compliance: 03/19/2012
Violation lead agency: EPA
Enforcement action: SINGLE SITE CA/FO
Enforcement action date: 03/19/2012
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: .01
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 03/19/2012
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/16/2011
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Evaluation date: 10/28/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/19/2012
Evaluation lead agency: EPA

Evaluation date: 02/03/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009482176

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Registry ID: 110009488367

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-600923
Program Type: PBS
UTM X: 585240.00136999995
UTM Y: 4512192.4429400004
Expiration Date: 10/07/2017
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 22893
Affiliation Type: Facility Owner
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: Not reported
Address1: 625 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Zip Code: 10018
Country Code: 001
Phone: (212) 502-2240
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/13/2013

Site Id: 22893
Affiliation Type: Mail Contact
Company Name: PORT AUTHORITY OF NY AND NJ
Contact Type: Not reported
Contact Name: ERNEST PEART
Address1: 625 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 502-2214
EMail: EPEART@PANYNJ.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/13/2013

Site Id: 22893
Affiliation Type: On-Site Operator
Company Name: PORT AUTHORITY BUS TERMINAL
Contact Type: Not reported
Contact Name: ERNEST PEART
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 502-2214
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 10/17/2012

Site Id: 22893
Affiliation Type: Emergency Contact
Company Name: PORT AUTHORITY OF NY & NJ
Contact Type: Not reported
Contact Name: COMMUNICATIONS DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 502-2245
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Last Modified: 11/17/2010

Tank Info:

Tank Number: PABT 1
Tank Id: 44604
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
G99 - Tank Secondary Containment - Other
I00 - Overfill - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/15/1950
Capacity Gallons: 300
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/30/2008
Register: True
Modified By: NRLOMBAR
Last Modified: 06/02/2008
Material Name: Diesel

Tank Number: PABT 10
Tank Id: 224335
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J03 - Dispenser - Gravity
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 700
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Other

Tank Number: PABT 11
Tank Id: 219368
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
G99 - Tank Secondary Containment - Other

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/30/2008
Register: True
Modified By: NRLOMBAR
Last Modified: 07/30/2008
Material Name: Diesel

Tank Number: PABT 12
Tank Id: 224336
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K00 - Spill Prevention - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1996
Capacity Gallons: 100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Diesel

Tank Number: PABT 3
Tank Id: 44609
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

E01 - Piping Secondary Containment - Diking (Aboveground)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K00 - Spill Prevention - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 600
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/25/2006
Register: True
Modified By: NRLOMBAR
Last Modified: 11/03/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Material Name: Diesel

Tank Number: PABT 4
Tank Id: 219362
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 50
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/14/2010
Register: True
Modified By: NRLOMBAR
Last Modified: 11/17/2010
Material Name: Other

Tank Number: PABT 5
Tank Id: 219363
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 3

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 12/31/1979
Capacity Gallons: 497
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/21/2010
Material Name: Other

Tank Number: PABT 6
Tank Id: 219364
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
J03 - Dispenser - Gravity

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 750
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Other

Tank Number: PABT 7
Tank Id: 219365
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
J03 - Dispenser - Gravity
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 750
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Other

Tank Number: PABT 8
Tank Id: 219366
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
J03 - Dispenser - Gravity

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 700
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Last Modified: 06/13/2013
Material Name: Other

Tank Number: PABT 9
Tank Id: 219367
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
K99 - Spill Prevention - Other
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J03 - Dispenser - Gravity
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

3
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 700
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Other

Tank Number: PABT10A
Tank Id: 229687
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
F06 - Pipe External Protection - Wrapped
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/09/2009
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: dxliving
Last Modified: 08/03/2009
Material Name: Diesel

Tank Number: PABT1A
Tank Id: 229686
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

F06 - Pipe External Protection - Wrapped
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
I03 - Overfill - Automatic Shut-Off
E12 - Piping Secondary Containment - Double-Wall (Aboveground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

3
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/09/2009
Capacity Gallons: 2200
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: dxliving
Last Modified: 08/03/2009
Material Name: Diesel

Tank Number: PABT3A
Tank Id: 219361
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E01 - Piping Secondary Containment - Diking (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/31/2006
Capacity Gallons: 600
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 06/13/2013
Material Name: Diesel

HIST AST:

PBS Number: 2-600923
SWIS Code: 6201
Operator: LEO M. CLINTRON
Facility Phone: (212) 502-2415
Facility Addr2: 625 8TH AVE.
Facility Type: OTHER
Emergency: 15 EMERGENCY DESK
Emergency Tel: (212) 502-2255
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: KEN PHILMUS, GENERAL MANAGER
Owner Address: 625 EIGHTH AVENUE
Owner City,St,Zip: NEW YORK, NY 10018
Federal ID: Not reported
Owner Tel: (212) 502-2240
Owner Type: State Government
Owner Subtype: 00
Mailing Contact: EDWIN SWANSTON
Mailing Name: PORT AUTHORITY OF NEW YORK AND NEW JERSEY
Mailing Address: 625 EIGHTH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10018
Mailing Telephone: (212) 502-2272
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 11/14/1997
Expiration: 10/07/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1900
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: PABT 1
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 300
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 09
Pipe Location: Aboveground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 00
Tank Containment: None
Leak Detection: 00
Overfill Protection: 00
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: PABT 3
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 600
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 00
Pipe Location: Aboveground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 00
Tank Containment: None
Leak Detection: 00
Overfill Protection: 00
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

NY MANIFEST:

EPA ID: NYD987012689
Country: USA

Mailing Info:

Name: PORT AUTHORITY OF NEW YORK NEW JERSEY
Contact: BRIAN HARRIS
Address: 241 ERIE STREET ROOM 306A
City/State/Zip: JERSEY CITY, NJ 07310
Country: USA
Phone: 212-502-2257

Document ID: NYB6555519
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: PD9796NY
Trans2 State ID: Not reported
Generator Ship Date: 950208
Trans1 Recv Date: 950208
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950210
Part A Recv Date: 950223
Part B Recv Date: 950313
Generator EPA ID: NYD987012689
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID: NYD057770109
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00004
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Waste Code: Not reported
Quantity: 00002
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Specific Gravity: 080
Waste Code: Not reported
Quantity: 00056
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Year: 95

Document ID: NJA1953924
Manifest Status: Completed copy
Trans1 State ID: NJDEPE086
Trans2 State ID: Not reported
Generator Ship Date: 950112
Trans1 Recv Date: 950112
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950112
Part A Recv Date: 950206
Part B Recv Date: 950126
Generator EPA ID: NYD987012689
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00031
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 080
Year: 95

Document ID: 06
Manifest Status: NJA5316454
Trans1 State ID: NYD987012689
Trans2 State ID: Not reported
Generator Ship Date: NJD991291105
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD980772768
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DM
Container Type: 600
Handling Method: P
Specific Gravity: 1
Waste Code: T

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 1/17/2007
Trans1 Recv Date: 1/17/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 1/17/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 250
Units: P - Pounds
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000062123WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: Y
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2/27/2007
Trans1 Recv Date: 2/27/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 3/1/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 600
Units: P - Pounds
Number of Containers: 2
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000067534WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 12/11/2007
Trans1 Recv Date: 12/11/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/13/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 9200
Units: P - Pounds
Number of Containers: 23
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 000069812WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 11/21/2007
Trans1 Recv Date: 11/21/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/21/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 1800
Units: P - Pounds
Number of Containers: 6
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 001871070JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 5
Units: P - Pounds
Number of Containers: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 120
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 24
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 5
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 25
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 5
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 15
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 45
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 9
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 5
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 8/2/2007
Trans1 Recv Date: 8/2/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 8/2/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported
Quantity: 5
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003121776JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 10/25/2007
Trans1 Recv Date: 10/25/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/25/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Quantity: 2000
Units: P - Pounds
Number of Containers: 4
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003122810JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 10/18/2007
Trans1 Recv Date: 10/18/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/18/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 415
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 8
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003122811JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 10/30/2007
Trans1 Recv Date: 10/30/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/30/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 8
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003122878JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 10/30/2007
Trans1 Recv Date: 10/30/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/30/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 72
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 3
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Year: 2007
Manifest Tracking Num: 003122878JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 10/30/2007
Trans1 Recv Date: 10/30/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/30/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987012689
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 4
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 1
Year: 2007
Manifest Tracking Num: 003122878JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

[Click this hyperlink](#) while viewing on your computer to access
136 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:
Manifest Code: 000201076WAS
EPA ID: NYD987012689
Date Shipped: 01/08/2009

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

TSDf EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	01/08/2009
Transporter 1 Decal:	Not reported
Transporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2009 New Jersey Manifest Data
Quantity:	400
Unit:	P
Hand Code:	H111
Manifest Code:	NJA5316454
EPA ID:	NYD987012689
Date Shipped:	03/13/2006
TSDf EPA ID:	NJD991291105

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 03/13/2006
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 03/13/2006
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 05150621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 003121776JJK
EPA ID: NYD987012689
Date Shipped: 08/02/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/02/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	08/02/2007
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	Not reported
Transporter-1 EPA Facility Name:	Not reported
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D002
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	45
Unit:	G
Hand Code:	H14
Waste Code:	D002
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	15
Unit:	G
Hand Code:	H14
Waste Code:	D001
Manifest Year:	2007 New Jersey Manifest Data

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Quantity:	120
Unit:	G
Hand Code:	H06
Waste Code:	D002
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	5
Unit:	G
Hand Code:	H14
Waste Code:	D001
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	5
Unit:	P
Hand Code:	H14
Waste Code:	D002
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	25
Unit:	G
Hand Code:	H14
Manifest Code:	000423247WAS
EPA ID:	NYD987012689
Date Shipped:	10/21/2011
TSDf EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	Not reported
Transporter 1 Decal:	Not reported
Transporter 2 Decal:	Not reported
Generator EPA Facility Name:	PORT AUTHORITY OF NY/NJ
Transporter-1 EPA Facility Name:	PRICE TRUCKING CORP
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	CLEAN EARTH OF NORTH JERSEY INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

QTY Units:	Pounds
Transporter SEQ ID:	1.00
Transporter-1 Date:	10/21/2011
Waste SEQ ID:	1.00
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	10/21/2011
Manifest Discrepancy Type:	Quantity
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	Not reported
Reason Load Was Rejected:	Not reported
Waste Code:	D008
Manifest Year:	2011 New Jersey Manifest Data
Quantity:	9,580.00
Unit:	Pounds
Hand Code:	H111
Manifest Code:	008927138JJK
EPA ID:	NYD987012689
Date Shipped:	12/9/2011
TSDf EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	Not reported
Transporter 1 Decal:	Not reported
Transporter 2 Decal:	Not reported
Generator EPA Facility Name:	PORT AUTHORITY OF NY/NJ
Transporter-1 EPA Facility Name:	AUCHTER INDUSTRIAL VAC SERVICE INC
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	CLEAN EARTH OF NORTH JERSEY INC
QTY Units:	gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter SEQ ID: 1.00
Transporter-1 Date: 12/9/2011
Waste SEQ ID: 1.00
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: 12/9/2011
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): Not reported
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 30.00
Unit: gallons
Hand Code: H141

Manifest Code: 004258122JJK
EPA ID: NYD987012689
Date Shipped: 01/29/2009
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 01/30/2009
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 800
Unit: P
Hand Code: H111

Manifest Code: NJA5027056
EPA ID: NYD987012689
Date Shipped: 08/25/2004
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/25/2004
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/25/2004
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 09200421
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 001871469JJK
EPA ID: NYD987012689
Date Shipped: 01/29/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/29/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 01/29/2008
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	F001
Manifest Year:	2008 New Jersey Manifest Data
Quantity:	165
Unit:	G
Hand Code:	H141
Manifest Code:	008930729JJK
EPA ID:	NYD987012689
Date Shipped:	9/29/2011
TSDf EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDf Received Waste:	Not reported
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Generator EPA Facility Name:	PORT AUTHORITY OF NY/NJ
Transporter-1 EPA Facility Name:	AUCHTER INDUSTRIAL VAC SERVICE INC
Transporter-2 EPA Facility Name:	Not reported
Transporter-3 EPA Facility Name:	Not reported
Transporter-4 EPA Facility Name:	Not reported
Transporter-5 EPA Facility Name:	Not reported
TSDf EPA Facility Name:	CLEAN EARTH OF NORTH JERSEY INC
QTY Units:	gallons
Transporter SEQ ID:	1.00
Transporter-1 Date:	9/29/2011
Waste SEQ ID:	2.00
Waste Type Code 2:	D018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: 9/29/2011
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): Not reported
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 5.00
Unit: gallons
Hand Code: H141

Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 55.00
Unit: gallons
Hand Code: H141

Waste Code: D008
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 20.00
Unit: Pounds
Hand Code: H141

Manifest Code: 008930729JJK
EPA ID: NYD987012689
Date Shipped: 9/29/2011
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: Not reported
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: PORT AUTHORITY OF NY/NJ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter-1 EPA Facility Name: AUCHTER INDUSTRIAL VAC SERVICE INC
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: CLEAN EARTH OF NORTH JERSEY INC
QTY Units: gallons
Transporter SEQ ID: 1.00
Transporter-1 Date: 9/29/2011
Waste SEQ ID: 3.00
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: 9/29/2011
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): Not reported
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 5.00
Unit: gallons
Hand Code: H141

Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 55.00
Unit: gallons
Hand Code: H141

Waste Code: D008
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 20.00
Unit: Pounds
Hand Code: H141

Manifest Code: 003122878JJK
EPA ID: NYD987012689
Date Shipped: 10/30/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/30/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/30/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000062123VES
EPA ID: NYD987012689
Date Shipped: 01/17/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 01/17/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 01/17/2007
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 250
Unit: P
Hand Code: H11

Manifest Code: 003122810JJK
EPA ID: NYD987012689
Date Shipped: 10/25/2007
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/25/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 10/25/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000067534WAS
EPA ID: NYD987012689
Date Shipped: 02/27/2007
TSDf EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 02/27/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 03/01/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 600
Unit: P
Hand Code: H11

Manifest Code: 005974682JJK
EPA ID: NYD987012689
Date Shipped: 08/20/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/20/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 08/20/2009
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 500
Unit: P
Hand Code: H111

Manifest Code: 003122811JJK
EPA ID: NYD987012689
Date Shipped: 10/18/2007
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 10/18/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 10/18/2007
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: F001
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 415
Unit: G
Hand Code: H14

Manifest Code: NJA5226993
EPA ID: NYD987012689
Date Shipped: 05/04/2005
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 05/04/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 05/04/2005
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 06010522
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5270796
EPA ID: NYD987012689
Date Shipped: 11/04/2005
TSDf EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/04/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Date TSDf Received Waste: 11/04/2005
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 01170622
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 000200125WAS
EPA ID: NYD987012689
Date Shipped: 07/26/2010
TSDf EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/26/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 07/26/2010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D008
Manifest Year: 2010 New Jersey Manifest Data
Quantity: 800
Unit: P
Hand Code: H111

Manifest Code: 008930729JJK
EPA ID: NYD987012689
Date Shipped: 9/29/2011
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
Transporter 1 Decal: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter 2 Decal: Not reported
Generator EPA Facility Name: PORT AUTHORITY OF NY/NJ
Transporter-1 EPA Facility Name: AUCHTER INDUSTRIAL VAC SERVICE INC
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: CLEAN EARTH OF NORTH JERSEY INC
QTY Units: Pounds
Transporter SEQ ID: 1.00
Transporter-1 Date: 9/29/2011
Waste SEQ ID: 1.00
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: 9/29/2011
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): Not reported
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 5.00
Unit: gallons
Hand Code: H141

Waste Code: D001
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 55.00
Unit: gallons
Hand Code: H141

Waste Code: D008
Manifest Year: 2011 New Jersey Manifest Data
Quantity: 20.00
Unit: Pounds
Hand Code: H141

RI MANIFEST:

GEN Cert Date: 9/11/2007
Transporter Receipt Date: 9/11/2007
Number Of Containers: 1
Container Type: DM
Waste Code1: D001
Waste Code2: D039
Waste Code3: Not reported
Comment: Not reported
Fee Exempt Code: Not reported
TSDF Name: United Oil Recovery Inc
TSDF ID: RID084802842
TSDF Date: 9/13/2007
Transporter 2 Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PABT - PORT AUTHORITY BUS TERMINAL (Continued)

1000789804

Transporter 2 ID: Not reported
Manifest Docket Number: 000060051UIS
Waste Description: RQ WASTE PETROLEUM DISTILLATES NOS
Quantity: 25
WT/Vol Units: G
Item Number: a
Transporter Name: UNITED INDUSTRIAL SERVICES
Transporter EPA ID: CTD021816889
GEN Cert Date: 9/11/2007
Transporter Recpt Date: 9/11/2007
Transporter 2 Recpt Date: Not reported
TSDF Recpt Date: 9/13/2007
EPA ID: NYD987012689
Transporter 2 ID: Not reported

EPA WATCH LIST:

Facility ID: NYD987012689
Program: RCRA Facilities
List date: November 2012 Watch List

Facility ID: NYD987012689
Program: RCRA Facilities
List date: December 2012 Watch List

CC480
SE
1/8-1/4
0.232 mi.
1225 ft.

L & L PAINTING CO INC
625 8TH AVE - BLOCK 1032 LOT 2
NEW YORK, NY 10018

RCRA NonGen / NLR

1015747108
NYR000184192

Site 4 of 9 in cluster CC

Relative:
Higher

RCRA NonGen / NLR:

Actual:
40 ft.

Date form received by agency: 03/14/2012
Facility name: L & L PAINTING CO INC
Facility address: 625 8TH AVE - BLOCK 1032 LOT 2
NEW YORK, NY 10018
EPA ID: NYR000184192
Mailing address: 8TH AVE - BLOCK 1032 LOT 29
NEW YORK, NY 10018
Contact: SCOTT M EARL
Contact address: S OYSTER BAY RD
HICKSVILLE, NY 11801
Contact country: US
Contact telephone: (516) 349-1900
Contact email: SCOTTMEARL@AOL.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: L&L PAINTING CO INC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L & L PAINTING CO INC (Continued)

1015747108

Owner/Op start date: 06/01/2011
Owner/Op end date: Not reported

Owner/operator name: PORT AUTHORITY OF NY/NJ
Owner/operator address: 8TH AVE
NEW YORK, NY 10018

Owner/operator country: US
Owner/operator telephone: (212) 502-2200
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/15/1950
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 09/12/2011
Site name: L & L PAINTING CO INC
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L & L PAINTING CO INC (Continued)

1015747108

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

CC481
SE
1/8-1/4
0.232 mi.
1225 ft.

PORT AUTHORITY BUS TERMINAL
625 8TH AVE
NEW YORK, NY 10018
Site 5 of 9 in cluster CC

RCRA NonGen / NLR 1001489336
ICIS NYU005001268

Relative:
Higher

RCRA NonGen / NLR:

Actual:
40 ft.

Date form received by agency: 01/01/2007
Facility name: GREYHOUND BUS CO INC
Facility address: 625 8TH AVE
NEW YORK, NY 10018
EPA ID: NYU005001268
Mailing address: 8TH AVE
NEW YORK, NY 10018
Contact: Not reported
Contact address: 8TH AVE
NEW YORK, NY 10018
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTHORITY BUS TERMINAL (Continued)

1001489336

Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: GREYHOUND BUS CO INC
Classification: Not a generator, verified

Date form received by agency: 05/10/1999
Site name: GREYHOUND BUS CO INC
Classification: Not a generator, verified

Date form received by agency: 05/10/1999
Site name: GREYHOUND BUS CO INC
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 09/09/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

ICIS:

Enforcement Action ID: 02-2011-7110
FRS ID: 110009482176
Program ID: FRS 110009482176
Action Name: PORT AUTHORITY OF NEW YORK AND NEW JERSEY
Full Address: 625 8TH AVE NEW YORK NY 10018
State: New York

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PORT AUTHORITY BUS TERMINAL (Continued)

1001489336

Facility Name: PABT - PORT AUTHORITY BUS TERMINAL
Facility Address: 625 8TH AVE
NEW YORK, NY 10018
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: NEW YORK
EPA Region #: 2

Enforcement Action ID: 02-2011-7110
FRS ID: 110009482176
Program ID: RCRAINFO NYD987012689
Action Name: PORT AUTHORITY OF NEW YORK AND NEW JERSEY
Full Address: 625 8TH AVE NEW YORK NY 10018
State: New York
Facility Name: PORT AUTHORITY BUS TERMINAL
Facility Address: 625 8TH AVE
NEW YORK, NY 10018
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: NEW YORK
EPA Region #: 2

Enforcement Action ID: 02-2011-7110
FRS ID: 110009482176
Program ID: BR NYD987012689
Action Name: PORT AUTHORITY OF NEW YORK AND NEW JERSEY
Full Address: 625 8TH AVE NEW YORK NY 10018
State: New York
Facility Name: PORT AUTHORITY BUS TERMINAL
Facility Address: 625 8TH AVE
NEW YORK, NY 10018
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: NEW YORK
EPA Region #: 2

Program ID: BR NYD987012689
Facility Name: PABT - PORT AUTHORITY BUS TERMINAL
Address: 625 8TH AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Program ID: FRS 110009482176
Facility Name: PABT - PORT AUTHORITY BUS TERMINAL
Address: 625 8TH AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Program ID: RCRAINFO NYD987012689
Facility Name: PABT - PORT AUTHORITY BUS TERMINAL
Address: 625 8TH AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CC482
SE
1/8-1/4
0.232 mi.
1225 ft.
L & L PAINTING CO INC
625 8TH AVE - BLOCK 1032 LOT 29
NEW YORK, NY 10018
Site 6 of 9 in cluster CC

NY MANIFEST
S111437899
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYR000184192
Country: USA

Actual:
40 ft.

Mailing Info:
Name: L & L PAINTING CO INC
Contact: L & L PAINTING CO INC
Address: 625 8TH AVE
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-502-2200

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2011-10-17
Trans1 Recv Date: 2011-10-17
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-10-17
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000184192
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 220.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 4.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 000423223WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Trans2 State ID: Not reported
Generator Ship Date: 2011-12-28

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

L & L PAINTING CO INC (Continued)

S111437899

Trans1 Recv Date: 2011-12-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-12-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000184192
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 165.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 2011
Manifest Tracking Num: 000457157WAS
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

CA483
SW
1/8-1/4
0.233 mi.
1228 ft.

450 W 38 AT I 495
NEW YORK, NY 10292
Site 2 of 5 in cluster CA

EDR US Hist Auto Stat 1015501931
N/A

Relative:
Higher

EDR Historical Auto Stations:
Name: MONTERO & CHINO AUTO REPAIR
Year: 2008
Address: 450 W 38 AT I 495

Actual:
32 ft.

CD484
WSW
1/8-1/4
0.233 mi.
1229 ft.

CON EDISON SERVICE BOX: 7384
514 W 39TH ST
NEW YORK, NY 10018
Site 1 of 8 in cluster CD

RCRA-CESQG 1016143790
NYP004265740

Relative:
Lower

RCRA-CESQG:
Date form received by agency: 08/30/2012
Facility name: CON EDISON SERVICE BOX: 7384
Facility address: 514 W 39TH ST
NEW YORK, NY 10018
EPA ID: NYP004265740
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ

Actual:
25 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7384 (Continued)

1016143790

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

CD485
WSW
1/8-1/4
0.233 mi.
1229 ft.

514 W 39TH ST
NEW YORK, NY 10018

Site 2 of 8 in cluster CD

EDR US Hist Auto Stat 1015533672
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: CITYWIDE AUTO GROUP INC
Year: 2003
Address: 514 W 39TH ST

Actual:
25 ft.

Name: CITYWIDE AUTO GROUP INC
Year: 2004
Address: 514 W 39TH ST

Name: BNY AUTO TECH INC
Year: 2010

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015533672

Address: 514 W 39TH ST

Name: WAHLAHS AUTO REPAIR INC
Year: 2011
Address: 514 W 39TH ST

Name: WAHLAHS AUTO REPAIR INC
Year: 2012
Address: 514 W 39TH ST

CD486 CITYWIDE AUTO REPAIR LLC
WSW 514 WEST 39TH STREET
1/8-1/4 NEW YORK, NY 10018
0.233 mi.
1229 ft. Site 3 of 8 in cluster CD

NY AST A100293570
N/A

Relative:
Lower

AST:

Actual:
25 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609402
Program Type: PBS
UTM X: 584656.99658000004
UTM Y: 4512349.7825499997
Expiration Date: 12/22/2008
Site Type: Other

Affiliation Records:

Site Id: 31246
Affiliation Type: Facility Owner
Company Name: RAANAN YAAKOBVITCH
Contact Type: Not reported
Contact Name: Not reported
Address1: 2500 JOHNSON AVE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10463
Country Code: 001
Phone: (212) 244-4420
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31246
Affiliation Type: Mail Contact
Company Name: RAANAN YAAKOBVITCH
Contact Type: Not reported
Contact Name: Not reported
Address1: 2500 JOHNSON AVENUE
Address2: Not reported
City: BRONX
State: NY
Zip Code: 10463
Country Code: 001
Phone: (212) 244-4420
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITYWIDE AUTO REPAIR LLC (Continued)

A100293570

Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31246
Affiliation Type: On-Site Operator
Company Name: CITYWIDE AUTO REPAIR LLC
Contact Type: Not reported
Contact Name: RON TAAKOBVITCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 244-4420
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 31246
Affiliation Type: Emergency Contact
Company Name: RAANAN YAAKOBVITCH
Contact Type: Not reported
Contact Name: JOSH SHIMONI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 494-1306
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 39-001
Tank Id: 67334
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
A99 - Tank Internal Protection - Other
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CITYWIDE AUTO REPAIR LLC (Continued)

A100293570

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 200
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Waste Oil/Used Oil

Tank Number: 39-002
Tank Id: 67335
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
A99 - Tank Internal Protection - Other
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 200
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Waste Oil/Used Oil

CD487 **CON EDISON**
WSW **514 W 39TH ST**
1/8-1/4 **NEW YORK, NY 10018**
0.233 mi.
1229 ft. **Site 4 of 8 in cluster CD**

NY MANIFEST **S112210401**
N/A

Relative: **NY MANIFEST:**
Lower **EPA ID:** **NYP004265740**
Country: **USA**

Actual:
25 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210401

Mailing Info:

Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-30
Trans1 Recv Date: 2012-08-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265740
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456254JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-30
Trans1 Recv Date: 2012-08-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-31
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265740
Trans1 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210401

Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 1500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456254JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

CE488
South
1/8-1/4
0.233 mi.
1230 ft.

335 WEST 38TH ST
335 WEST 38TH ST
NEW YORK, NY 10018

NY AST **U003384418**
NY HIST AST **N/A**

Site 1 of 3 in cluster CE

Relative:
Higher

AST:

Actual:
38 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-100145
Program Type: PBS
UTM X: 585073.44360999996
UTM Y: 4512080.83980000002
Expiration Date: 03/24/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 3024
Affiliation Type: Facility Owner
Company Name: 335 WEST 38TH ST COOPERATIVE CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 335 WEST 38TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 564-6348
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/12/2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

335 WEST 38TH ST (Continued)

U003384418

Site Id: 3024
Affiliation Type: Mail Contact
Company Name: 335 WEST 38 ST COOPERATIVE CORP
Contact Type: Not reported
Contact Name: BOB DONAHUE
Address1: 335 WEST 38TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 564-6348
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/12/2012

Site Id: 3024
Affiliation Type: On-Site Operator
Company Name: 335 WEST 38 STREET COOPERATIVE CORP.
Contact Type: Not reported
Contact Name: RICK BURDA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 971-9455
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/12/2012

Site Id: 3024
Affiliation Type: Emergency Contact
Company Name: 335 WEST 38TH ST COOPERATIVE CORP
Contact Type: Not reported
Contact Name: BOB DONAHUE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 564-6348
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/12/2012

Tank Info:

Tank Number: 001
Tank Id: 3747
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

335 WEST 38TH ST (Continued)

U003384418

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
A01 - Tank Internal Protection - Epoxy Liner
I05 - Overfill - Vent Whistle
L99 - Piping Leak Detection - Other
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1976
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/12/2012
Material Name: #4 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-100145
SWIS Code: 6201
Operator: ASHTON NEWTON
Facility Phone: (212) 736-0554
Facility Addr2: 335 WEST 38TH ST
Facility Type: PRIVATE RESIDENCE
Emergency: ROBERT DONAHUE
Emergency Tel: (212) 564-6348
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 335 WEST 38TH ST COOP CORP
Owner Address: 335 WEST 38TH ST
Owner City,St,Zip: NEW YORK, NY 10018
Federal ID: Not reported
Owner Tel: (212) 564-6348
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: ROBERT DONAHUE SECY./TREA
Mailing Name: 335 WEST 38TH ST COOP CORP
Mailing Address: 335 WEST 38TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10018-2916
Mailing Telephone: (212) 564-6348
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

335 WEST 38TH ST (Continued)

U003384418

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: True
Certification Date: Not reported
Expiration: 03/24/2007
Renew Flag: False
Renew Date: 11/13/2001
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 01
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: 0
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CA489
SW
1/8-1/4
0.233 mi.
1232 ft.

450 W 38TH ST
NEW YORK, NY 10018
Site 3 of 5 in cluster CA

EDR US Hist Auto Stat 1015501932
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: ALL MAGIC AUTOMOTIVE INCORPORATED
Year: 2000
Address: 450 W 38TH ST

Actual:
33 ft.

Name: ALL MAGIC AUTOMOTIVE INC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015501932

Year: 2001
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR
Year: 2002
Address: 450 W 38TH ST

Name: ALL MAGIC AUTOMOTIVE INC
Year: 2003
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR
Year: 2004
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR
Year: 2005
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR
Year: 2006
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR
Year: 2007
Address: 450 W 38TH ST

Name: MONTERO & CHINO AUTO REPAIR SHOP
Year: 2009
Address: 450 W 38TH ST

Name: OREN AUTO REPAIR INC
Year: 2011
Address: 450 W 38TH ST

Name: OREN AUTO REPAIR INC
Year: 2012
Address: 450 W 38TH ST

CF490
NNE
1/8-1/4
0.233 mi.
1232 ft.

416 WEST 47TH STREET
416 WEST 47TH ST
NEW YORK, NY
Site 1 of 8 in cluster CF

NY LTANKS S104278720
N/A

Relative:
Higher

LTANKS:
Site ID: 273048
Spill Number/Closed Date: 9909811 / 6/13/2005
Spill Date: 11/12/1999
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: GWHEITZM
Referred To: Not reported

Actual:
43 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

416 WEST 47TH STREET (Continued)

S104278720

Reported to Dept: 11/12/1999
CID: 211
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/12/1999
Spill Record Last Update: 6/13/2005
Spiller Name: VITO CUTUGNO
Spiller Company: GRL PROPERTY INVESTORS
Spiller Address: 214-57 27TH AVENUE
Spiller City,St,Zip: BAYSIDE, NY
Spiller County: 001
Spiller Contact: VITO CUTUGNO
Spiller Phone: (718) 631-3108
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 222204
DEC Memo: 06/13/05 Heitzman: See PBS 2-602413. 3000-gallon tank closed in place and replaced with unknown, unregulated (<1100 gal) tank.
Remarks: DEC Sigona requested that tank testor report this spill to hotline

Material:

Site ID: 273048
Operable Unit ID: 1088503
Operable Unit: 01
Material ID: 298881
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 273048
Spill Tank Test: 1547841
Tank Number: 1
Tank Size: 2500
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CF491
NNE
1/8-1/4
0.233 mi.
1232 ft.

CON EDISON
416 W 47TH ST
NEW YORK, NY 10036

Site 2 of 8 in cluster CF

RCRA-CESQG **1012185869**
NYP004167045

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 04/14/2009

Facility name: CON EDISON

Facility address: 416 W 47TH ST
NEW YORK, NY 10036

EPA ID: NYP004167045

Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003

Contact: DANIEL PONTECORVO

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 203-2573

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CF492 **416 WEST 47TH STREET ASSOCIATES LTD.**
NNE **416 WEST 47TH STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.233 mi.
1232 ft. **Site 3 of 8 in cluster CF**

NY AST **U004045535**
 N/A

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-602413
Program Type: PBS
UTM X: 585211.77462000004
UTM Y: 4512811.5001100004
Expiration Date: 08/21/2005
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 24370
Affiliation Type: Facility Owner
Company Name: 416 WEST 47 STREET ASSOC LTD % GRL PROP. INV. LTD.
Contact Type: Not reported
Contact Name: Not reported
Address1: 214-57 27TH AVE
Address2: Not reported
City: BAYSIDE
State: NY
Zip Code: 11360
Country Code: 001
Phone: (718) 225-2541
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24370
Affiliation Type: Mail Contact
Company Name: GRL PROPERTY INV. LTD.
Contact Type: Not reported
Contact Name: VITO L. CUTUGNO
Address1: 214-57 27TH AVENUE
Address2: Not reported
City: BAYSIDE
State: NY
Zip Code: 11360
Country Code: 001
Phone: (718) 225-2541
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24370
Affiliation Type: On-Site Operator
Company Name: 416 WEST 47TH STREET ASSOCIATES LTD.
Contact Type: Not reported
Contact Name: VITO L. CUTUGNO
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

416 WEST 47TH STREET ASSOCIATES LTD. (Continued)

U004045535

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 631-3108
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 24370
Affiliation Type: Emergency Contact
Company Name: 416 WEST 47 STREET ASSOC LTD % GRL PROP. INV. LTD.
Contact Type: Not reported
Contact Name: VITO L. CUTUGNO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 631-3108
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 1
Tank Id: 50025
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 3000
Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

416 WEST 47TH STREET ASSOCIATES LTD. (Continued)

U004045535

Material Name: #2 Fuel Oil (On-Site Consumption)

CF493
NNE
1/8-1/4
0.234 mi.
1234 ft.

426 WEST 47TH STREET
426 WEST 47TH STREET
NEW YORK, NY 10036
Site 4 of 8 in cluster CF

NY AST U003397051
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
42 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-603222
Program Type: PBS
UTM X: 585153.31391999999
UTM Y: 4512812.2165700002
Expiration Date: 08/04/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 25155
Affiliation Type: Facility Owner
Company Name: ZADA WEST LLC
Contact Type: PARTNER
Contact Name: DANIEL RAHIMZADA
Address1: 229 WEST 57TH ST
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 441-5116
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/15/2013

Site Id: 25155
Affiliation Type: Mail Contact
Company Name: ZADA WEST LLC
Contact Type: Not reported
Contact Name: DANNY ZADA
Address1: 17 BARSTOW RD. STE 409
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 441-5116
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/15/2013

Site Id: 25155
Affiliation Type: On-Site Operator
Company Name: ZADA WEST LLC
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

426 WEST 47TH STREET (Continued)

U003397051

Contact Name: DANNY ZADA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (516) 441-5116
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/15/2013

Site Id: 25155
Affiliation Type: Emergency Contact
Company Name: ZADA WEST LLC
Contact Type: Not reported
Contact Name: DANNY ZADA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 956-4141
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 53533
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/23/1937
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

426 WEST 47TH STREET (Continued)

U003397051

Register: True
Modified By: MSBAPTIS
Last Modified: 08/08/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-603222
SWIS Code: 6001
Operator: DEMMIS HIMMAN
Facility Phone: (917) 314-7878
Facility Addr2: Not reported
Facility Type: Not reported
Emergency: DEMMIS HIMMAN
Emergency Tel: (917) 314-7878
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 426 WEST 47TH STREET ASSOCIATES L.P
Owner Address: P.O. BOX 298
Owner City,St,Zip: NEW YORK, NY 10024
Federal ID: Not reported
Owner Tel: (212) 724-3161
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: A. KOKOT
Mailing Name: AK REALTY CO.
Mailing Address: P.O. BOX 298
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10024
Mailing Telephone: (212) 274-3161
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 02/25/1998
Expiration: 11/24/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 60
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

426 WEST 47TH STREET (Continued)

U003397051

Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 05
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: 08
Leak Detection: 00
Overfill Protection: 06
Dispenser Method: Gravity
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CG494
NNE
1/8-1/4
0.234 mi.
1235 ft.

432-434 WEST 47TH ST. TENANTS CORP.
432-434 WEST 47TH ST
NEW YORK, NY 10036
Site 1 of 2 in cluster CG

NY AST
NY HIST AST
U003386622
N/A

Relative:
Higher

AST:

Actual:
42 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-243590
Program Type: PBS
UTM X: 585132.43044000003
UTM Y: 4512830.0930300001
Expiration Date: 07/07/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 9390
Affiliation Type: Facility Owner
Company Name: 432-434 WEST 47TH TENANTS CORPORATION
Contact Type: PROPERTY MGR
Contact Name: DARLENE CARUSO
Address1: 2190 BROADWAY, SUITE 300
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 362-9298
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 5/23/2012

Site Id: 9390

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

432-434 WEST 47TH ST. TENANTS CORP. (Continued)

U003386622

Affiliation Type: Mail Contact
Company Name: MERLOT MANAGEMENT
Contact Type: Not reported
Contact Name: DARLENE CARUSO
Address1: 201 WEST 91ST ST
Address2: SUITE #1D
City: NEW YORK
State: NY
Zip Code: 10024
Country Code: 001
Phone: (212) 362-9298
EMail: DARLENE@MERLOTMGMT.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 5/23/2012

Site Id: 9390
Affiliation Type: On-Site Operator
Company Name: 432-434 WEST 47TH STREET TENANTS CORP.
Contact Type: Not reported
Contact Name: SABAHETA KOLOENVIC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 956-6147
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2009

Site Id: 9390
Affiliation Type: Emergency Contact
Company Name: 432-434 WEST 47TH TENANTS CORPORATION
Contact Type: Not reported
Contact Name: GLADYS PAREDES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 362-9298
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 8/27/2009

Tank Info:

Tank Number: 001
Tank Id: 10351
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

432-434 WEST 47TH ST. TENANTS CORP. (Continued)

U003386622

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1984
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 05/23/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-243590
SWIS Code: 6201
Operator: MODESTO MEDINA
Facility Phone: (212) 835-0815
Facility Addr2: 432 WEST 47TH ST
Facility Type: APARTMENT BUILDING
Emergency: MAEN BEREKDAR
Emergency Tel: (212) 397-7828
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 432-434 WEST 47TH TENANTS CORPORATION
Owner Address: P.O. BOX 2229 TIMES SQUARE STATION
Owner City,St,Zip: NEW YORK, NY 10108
Federal ID: Not reported
Owner Tel: (212) 265-1829
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: 432-434 WEST 47TH TENANTS CORPORATION
Mailing Address: P.O. BOX 2299 TIMES SQUARE STATION
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10108-2299
Mailing Telephone: (212) 265-1829
Owner Mark: First Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

432-434 WEST 47TH ST. TENANTS CORP. (Continued)

U003386622

Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/11/1997
Expiration: 07/07/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CD495
WSW
1/8-1/4
0.234 mi.
1236 ft.

516 W 39TH ST
NEW YORK, NY 10018
Site 5 of 8 in cluster CD

EDR US Hist Auto Stat 1015534906
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: VILLAGE AUTOMOTIVE
Year: 2003
Address: 516 W 39TH ST

Actual:
25 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015534906

Name: VILLAGE AUTOMOTIVE
Year: 2004
Address: 516 W 39TH ST

Name: VILLAGE AUTOMOTIVE
Year: 2010
Address: 516 W 39TH ST

CH496 CON EDISON SERVICE BOX: 7621
West 549 W 40TH ST
1/8-1/4 NEW YORK, NY 10018
0.234 mi.
1237 ft. Site 1 of 2 in cluster CH

RCRA-CESQG 1016143747
FINDS NYP004265302

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 08/28/2012

Facility name: CON EDISON SERVICE BOX: 7621

Facility address: 549 W 40TH ST
NEW YORK, NY 10018

EPA ID: NYP004265302

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7621 (Continued)

1016143747

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468060

Environmental Interest/Information System

CH497
West
1/8-1/4
0.234 mi.
1237 ft.

CON EDISON
549 W 40TH ST
NEW YORK, NY 10018

NY MANIFEST S112210359
N/A

Site 2 of 2 in cluster CH

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004265302
Country: USA

Actual:
19 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265302
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456074JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210359

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-28
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265302
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456074JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

CF498 **406 WEST 47TH ST H.D.F.C.**
NE **406 WEST 47TH ST**
1/8-1/4 **NEW YORK, NY 10036**
0.234 mi.
1237 ft. **Site 5 of 8 in cluster CF**

NY AST **U004045520**
 N/A

Relative: **AST:**
Higher Region: STATE
 DEC Region: 2
Actual: Site Status: Inactive
45 ft. Facility Id: 2-295604
 Program Type: PBS
 UTM X: 585235.21678999998
 UTM Y: 4512799.11362

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 47TH ST H.D.F.C. (Continued)

U004045520

Expiration Date: 07/07/1997
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 13575
Affiliation Type: Facility Owner
Company Name: 406 WEST 47TH ST H.D.F.C.
Contact Type: Not reported
Contact Name: Not reported
Address1: 406 WEST 47TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (914) 234-3300
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13575
Affiliation Type: Mail Contact
Company Name: P & L MANAGEMENT & CONSULTING INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 460 OLD POST ROAD
Address2: Not reported
City: BEDFORD
State: NY
Zip Code: 10506
Country Code: 001
Phone: (914) 234-3300
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13575
Affiliation Type: On-Site Operator
Company Name: 406 WEST 47TH ST H.D.F.C.
Contact Type: Not reported
Contact Name: P & L MANAGEMENT & CONSULTING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 234-3300
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13575
Affiliation Type: Emergency Contact
Company Name: 406 WEST 47TH ST H.D.F.C.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 47TH ST H.D.F.C. (Continued)

U004045520

Contact Type: Not reported
Contact Name: P & L MANAGEMENT & CONSULTING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (914) 234-3300
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 37433
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/28/1986
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: msbaptis
Last Modified: 02/01/2008
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 001
Tank Id: 12105
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 47TH ST H.D.F.C. (Continued)

U004045520

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 01/01/1955
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1998
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

Affiliation Records:

Site Id: 20015
Affiliation Type: Mail Contact
Company Name: 406 WEST 47TH STREET HDFC
Contact Type: Not reported
Contact Name: LARRY ROBERTS-TREASURER
Address1: P.O. BOX 2384
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10108
Country Code: 001
Phone: (917) 796-3121
EMail: LARRYMICHAELROBERTS@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 3/21/2013

Site Id: 20015
Affiliation Type: On-Site Operator
Company Name: 406 WEST 47TH STREET, HDFC
Contact Type: Not reported
Contact Name: 406 WEST 47TH ST. HDFC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 315-5425
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 47TH ST H.D.F.C. (Continued)

U004045520

Site Id: 20015
Affiliation Type: Emergency Contact
Company Name: 406 WEST 47TH STREET HDFC
Contact Type: Not reported
Contact Name: LARRY ROBERTS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 315-5425
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 20015
Affiliation Type: Facility Owner
Company Name: 406 WEST 47TH STREET HDFC
Contact Type: TREASURER
Contact Name: LARRY ROBERTS
Address1: 406 W. 47TH ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10108
Country Code: 001
Phone: (917) 796-3121
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 3/21/2013

Tank Info:

Tank Number: 001
Tank Id: 37433
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

406 WEST 47TH ST H.D.F.C. (Continued)

U004045520

Install Date: 07/28/1986
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: msbaptis
Last Modified: 02/01/2008
Material Name: #2 Fuel Oil (On-Site Consumption)

Tank Number: 001
Tank Id: 12105
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 01/01/1955
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1998
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

CC499 **KNICKERBOCKER BIOLOGICALS INC**
SSE **300 W 40TH ST**
1/8-1/4 **NEW YORK, NY 10018**
0.235 mi.
1239 ft. **Site 7 of 9 in cluster CC**

RCRA NonGen / NLR **1000173162**
FINDS **NYD020417317**

Relative:
Higher

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: KNICKERBOCKER BIOLOGICALS INC
Facility address: 300 W 40TH ST
NEW YORK, NY 10018
EPA ID: NYD020417317
Mailing address: W 40TH ST
NEW YORK, NY 10018
Contact: Not reported

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KNICKERBOCKER BIOLOGICALS INC (Continued)

1000173162

Contact address: W 40TH ST
NEW YORK, NY 10018
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: KNICKERBOCKER BIOLOGICALS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: KNICKERBOCKER BIOLOGICALS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: KNICKERBOCKER BIOLOGICALS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: KNICKERBOCKER BIOLOGICALS INC
Classification: Not a generator, verified

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KNICKERBOCKER BIOLOGICALS INC (Continued)

1000173162

Date form received by agency: 08/14/1980
Site name: KNICKERBOCKER BIOLOGICALS INC
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004351013

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CF500
NNE
1/8-1/4
0.235 mi.
1240 ft.

CONSOLIDATED EDISON
416 WEST 47TH STREET
MANHATTAN, NY 10009

NY MANIFEST S109584127
N/A

Site 6 of 8 in cluster CF

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004167045
Country: USA

Actual:
44 ft.

Mailing Info:
Name: CONSOLIDATED EDISON
Contact: FRANKLYN MURRAY
Address: 4 IRVING PLACE RM 828
City/State/Zip: MANHATTAN, NY 10003
Country: USA
Phone: 212-460-2808

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167045
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 425.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584127

Year: 2009
Manifest Tracking Num: 001028348JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167045
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 425.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028348JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584127

Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167045
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 425.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028348JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2009-04-14
Trans1 Recv Date: 2009-04-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-04-15
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004167045
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 425.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2009
Manifest Tracking Num: 001028348JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSOLIDATED EDISON (Continued)

S109584127

Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BY501 498 NINTH AVENUE
SSW 498 NINTH AVENUE
1/8-1/4 NEW YORK, NY 10018
0.235 mi.
1241 ft. Site 7 of 8 in cluster BY

NY AST A100178302
N/A

Relative:
Higher

AST:

Actual:
39 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606084
Program Type: PBS
UTM X: 584876.23147
UTM Y: 4512129.4704700001
Expiration Date: 06/25/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 27949
Affiliation Type: Facility Owner
Company Name: ESPOSITO REALTY LLC
Contact Type: OFFICER
Contact Name: ROBERT ESPOSITO
Address1: 500 NINTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 279-3298
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2006

Site Id: 27949
Affiliation Type: Mail Contact
Company Name: ESPOSITO REALTY LLC
Contact Type: OFFICER
Contact Name: ROBERT ESPOSITO
Address1: 500 NINTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 279-3298
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

498 NINTH AVENUE (Continued)

A100178302

Date Last Modified: 4/26/2006

Site Id: 27949
Affiliation Type: On-Site Operator
Company Name: 498 NINTH AVENUE
Contact Type: Not reported
Contact Name: ROBERT ESPOSITO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 279-3298
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 27949
Affiliation Type: Emergency Contact
Company Name: ESPOSITO REALTY
Contact Type: Not reported
Contact Name: ROBERT ESPOSITO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 279-3298
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 60925
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

498 NINTH AVENUE (Continued)

A100178302

H00 - Tank Leak Detection - None
1
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/15/1962
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: BVCAMPBE
Last Modified: 06/09/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

BW502
WNW
1/8-1/4
0.235 mi.
1242 ft.

555 W 42ND ST
NEW YORK, NY 10036
Site 6 of 7 in cluster BW

EDR US Hist Auto Stat 1015552183
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: A AAAAA AUTOMOTIVE TOWING
Year: 1999
Address: 555 W 42ND ST

Actual:
19 ft.

CF503
NNE
1/8-1/4
0.235 mi.
1243 ft.

415 REALTY ASSOCIATES LLC
415 WEST 47TH STREET
NEW YORK, NY 10036
Site 7 of 8 in cluster CF

NY AST U003391058
NY HIST AST N/A

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-328774
Program Type: PBS
UTM X: 585220.95860000001
UTM Y: 4512820.37641
Expiration Date: 10/02/2017
Site Type: Apartment Building/Office Building

Actual:
44 ft.

Affiliation Records:
Site Id: 15413
Affiliation Type: Facility Owner
Company Name: 415 REALTY ASSOCIATES LLC
Contact Type: MEMBER
Contact Name: LEONARD GLEICH
Address1: 415 WEST 47TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (917) 797-3463

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

415 REALTY ASSOCIATES LLC (Continued)

U003391058

EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/8/2013

Site Id: 15413
Affiliation Type: Mail Contact
Company Name: 415 REALTY ASSOCIATES, LLC
Contact Type: Not reported
Contact Name: LEONARD GLEICH
Address1: 415 WEST 47TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (917) 797-3463
EMail: LENGLEICH@HOTMAIL.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/8/2013

Site Id: 15413
Affiliation Type: On-Site Operator
Company Name: 415 REALTY ASSOCIATES LLC
Contact Type: Not reported
Contact Name: LEONARD GLEICH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 582-3099
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 15413
Affiliation Type: Emergency Contact
Company Name: 415 REALTY ASSOCIATES LLC
Contact Type: Not reported
Contact Name: LEONARD GLEICH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 582-3099
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

415 REALTY ASSOCIATES LLC (Continued)

U003391058

Tank Info:

Tank Number: 001
Tank Id: 20679
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H99 - Tank Leak Detection - Other
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B05 - Tank External Protection - Jacketed

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/20/1987
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KXTANG
Last Modified: 09/04/2007
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-328774
SWIS Code: 6201
Operator: LEONARD GLEICH
Facility Phone: (212) 582-6680
Facility Addr2: 415 W 47TH ST
Facility Type: APARTMENT BUILDING
Emergency: LEONARD GLEICH
Emergency Tel: (212) 582-3099
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 415 REALTY ASSOCIATES LLC
Owner Address: 415 WEST 47TH STREET
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 582-6680
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: LEONARD GLEICH
Mailing Name: 415 REALTY ASSOCIATES, LLC
Mailing Address: 415 WEST 47TH STREET

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

415 REALTY ASSOCIATES LLC (Continued)

U003391058

Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 582-6680
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/10/1997
Expiration: 10/02/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: 05
Pipe Location: Aboveground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 00
Tank Containment: Diking
Leak Detection: 06
Overfill Protection: 06
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CA504
SW
1/8-1/4
0.235 mi.
1243 ft.

CON EDISON SERVICE BOX: 7152
456 W 38TH ST
NEW YORK, NY 10018
Site 4 of 5 in cluster CA

RCRA-CESQG
FINDS
1016143721
NYP004265039

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/27/2012

Facility name: CON EDISON SERVICE BOX: 7152

Facility address: 456 W 38TH ST
NEW YORK, NY 10018

EPA ID: NYP004265039

Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ

Contact address: Not reported
Not reported

Contact country: Not reported

Contact telephone: (347) 865-5931

Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055467132

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7152 (Continued)

1016143721

Environmental Interest/Information System

**CA505
SW
1/8-1/4
0.235 mi.
1243 ft.**

**CON EDISON
456 W 38TH ST
NEW YORK, NY 10018

Site 5 of 5 in cluster CA**

**NY MANIFEST S112210333
N/A**

**Relative:
Higher**

NY MANIFEST:
EPA ID: NYP004265039
Country: USA

**Actual:
33 ft.**

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265039
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456116JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210333

Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-27
Trans1 Recv Date: 2012-08-27
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-28
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265039
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456116JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

CE506
South
1/8-1/4
0.236 mi.
1244 ft.

NEWBRIDGE COMMUNICATIONS
333 E 38TH ST - 8TH FLOOR
NEW YORK, NY 10016

Site 2 of 3 in cluster CE

RCRA NonGen / NLR **1004759848**
FINDS **NYR000023341**
NY MANIFEST

Relative:
Higher

RCRA NonGen / NLR:

Actual:
38 ft.

Date form received by agency: 01/01/2007
Facility name: NEWBRIDGE COMMUNICATIONS
Facility address: 333 E 38TH ST - 8TH FLOOR
NEW YORK, NY 10016
EPA ID: NYR000023341
Mailing address: E 38TH ST - 8TH FLOOR
NEW YORK, NY 10016
Contact: SCOTT TILTON
Contact address: E 38TH ST - 8TH FLOOR
NEW YORK, NY 10016
Contact country: US
Contact telephone: (212) 455-5708
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Owner/Operator Summary:

Owner/operator name: NEWBRIDGE COMMUNICATIONS
Owner/operator address: 333 E 38TH ST
NEW YORK, NY 10016
Owner/operator country: US
Owner/operator telephone: (212) 455-5000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEWBRIDGE COMMUNICATIONS
Owner/operator address: 333 E 38TH ST
NEW YORK, NY 10016
Owner/operator country: US
Owner/operator telephone: (212) 455-5000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: NEWBRIDGE COMMUNICATIONS
Classification: Not a generator, verified

Date form received by agency: 05/02/1996
Site name: NEWBRIDGE COMMUNICATIONS
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004524578

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000023341
Country: USA

Mailing Info:

Name: NEWBRIDGE COMMUNICATIONS
Contact: SCOTT TILTON
Address: 333 EAST 38TH STREET 8TH FLOOR
City/State/Zip: NEW YORK, NY 10016
Country: USA
Phone: 212-455-5708

Document ID: NYG0600597
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 03/23/1998
Trans1 Recv Date: 03/23/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/23/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: Not reported
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00109
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYG0716301
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 07/07/1998
Trans1 Recv Date: 07/07/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/13/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 00.80
Year: 98

Document ID: NYG1376802
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 09/08/1998
Trans1 Recv Date: 09/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/16/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00070
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 00.80
Year: 98

Document ID: NYG0761949
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 05/04/1998
Trans1 Recv Date: 05/04/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/13/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Document ID: NYG0874152
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 01/26/1998
Trans1 Recv Date: 01/26/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/18/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYG0601488
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 02/18/1998
Trans1 Recv Date: 02/18/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYG1379313
Manifest Status: Not reported
Trans1 State ID: NJD046555033
Trans2 State ID: Not reported
Generator Ship Date: 08/03/1998
Trans1 Recv Date: 08/03/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/05/1998
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Part B Recv Date: Not reported
Generator EPA ID: NYR000023341
Trans1 EPA ID: NYD045604964
Trans2 EPA ID: Not reported
TSDF ID: AA106Y
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 00.80
Year: 98

Document ID: NYB7229844
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AA106Y
Trans2 State ID: Not reported
Generator Ship Date: 960820
Trans1 Recv Date: 960820
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960828
Part A Recv Date: Not reported
Part B Recv Date: 960920
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB7229025
Manifest Status: Completed copy
Trans1 State ID: 502TTB
Trans2 State ID: Not reported
Generator Ship Date: 960930
Trans1 Recv Date: 960930
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961008
Part A Recv Date: Not reported
Part B Recv Date: 961024
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB8019684
Manifest Status: Completed copy
Trans1 State ID: AA106YNJ
Trans2 State ID: Not reported
Generator Ship Date: 970122
Trans1 Recv Date: 970122
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970129
Part A Recv Date: Not reported
Part B Recv Date: 970210
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 97

Document ID: NYB8561592
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJAA106Y
Trans2 State ID: Not reported
Generator Ship Date: 961125
Trans1 Recv Date: 961125
Trans2 Recv Date: Not reported
TSD Site Recv Date: 961204
Part A Recv Date: Not reported
Part B Recv Date: 961220
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB7773237
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AA106YNJ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Trans2 State ID: Not reported
Generator Ship Date: 961218
Trans1 Recv Date: 961218
Trans2 Recv Date: 970114
TSD Site Recv Date: 970115
Part A Recv Date: Not reported
Part B Recv Date: 970129
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 96

Document ID: NYB8515872
Manifest Status: Completed copy
Trans1 State ID: AA106Y
Trans2 State ID: Not reported
Generator Ship Date: 970428
Trans1 Recv Date: 970428
Trans2 Recv Date: 970506
TSD Site Recv Date: 970507
Part A Recv Date: Not reported
Part B Recv Date: 970519
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 97

Document ID: NYB8041608
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AA1064
Trans2 State ID: Not reported
Generator Ship Date: 970331
Trans1 Recv Date: 970331
Trans2 Recv Date: 970415
TSD Site Recv Date: 970415
Part A Recv Date: Not reported
Part B Recv Date: 970502
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 97

Document ID: NYB8022384
Manifest Status: Completed copy
Trans1 State ID: AA1064
Trans2 State ID: Not reported
Generator Ship Date: 970520
Trans1 Recv Date: 970520
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970528
Part A Recv Date: Not reported
Part B Recv Date: 970609
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0270693
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 970829
Trans1 Recv Date: 970829
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970908
Part A Recv Date: Not reported
Part B Recv Date: 970925
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Year: 97

Document ID: NYG0776799
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJAA106Y
Trans2 State ID: Not reported
Generator Ship Date: 971229
Trans1 Recv Date: 971229
Trans2 Recv Date: Not reported
TSD Site Recv Date: 980108
Part A Recv Date: Not reported
Part B Recv Date: 980127
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0082215
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 502TTB
Trans2 State ID: Not reported
Generator Ship Date: 970626
Trans1 Recv Date: 970626
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970702
Part A Recv Date: Not reported
Part B Recv Date: 970723
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0150543
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AA106YNJ
Trans2 State ID: Not reported
Generator Ship Date: 971003
Trans1 Recv Date: 971003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEWBRIDGE COMMUNICATIONS (Continued)

1004759848

Trans2 Recv Date: Not reported
TSD Site Recv Date: 971015
Part A Recv Date: Not reported
Part B Recv Date: 971104
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

Document ID: NYG0272655
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: AA106Y
Trans2 State ID: Not reported
Generator Ship Date: 970718
Trans1 Recv Date: 970718
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970805
Part A Recv Date: Not reported
Part B Recv Date: 970826
Generator EPA ID: NYR000023341
Trans1 EPA ID: NJD046555033
Trans2 EPA ID: Not reported
TSDF ID: NYD045604964
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 97

[Click this hyperlink](#) while viewing on your computer to access
2 additional NY_MANIFEST: record(s) in the EDR Site Report.

CF507
NNE
1/8-1/4
0.236 mi.
1246 ft.
GAMO REALTY CO
428 WEST 47TH ST
NEW YORK CITY, NY 10036
Site 8 of 8 in cluster CF

NY AST **U003385544**
NY HIST AST **N/A**

Relative: **AST:**
Higher Region: STATE
DEC Region: 2
Actual: Site Status: Active
42 ft. Facility Id: 2-147877
Program Type: PBS
UTM X: 585183.66073
UTM Y: 4512826.386389997

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385544

Expiration Date: 06/05/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 4373
Affiliation Type: Facility Owner
Company Name: NCR,LLC/AREA CODE MGMT
Contact Type: AREA CODE MGMT
Contact Name: AVIHU GERAFI
Address1: 519 EAST 5TH ST SUITE 17
Address2: Not reported
City: NEW YORK CITY
State: NY
Zip Code: 10009
Country Code: 001
Phone: (646) 330-5520
EMail: LAGERAFI@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Site Id: 4373
Affiliation Type: Mail Contact
Company Name: NCR,LLC/AREA CODE MGMT
Contact Type: AREA CODE MGMT
Contact Name: AVIHU GERAFI
Address1: 519 EAST 5TH ST SUITE 17
Address2: Not reported
City: NEW YORK CITY
State: NY
Zip Code: 10009
Country Code: 001
Phone: (646) 330-5520
EMail: LAGERAFI@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Site Id: 4373
Affiliation Type: On-Site Operator
Company Name: NCR, LLC
Contact Type: Not reported
Contact Name: TRAVIS COKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 972-2506
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Site Id: 4373
Affiliation Type: Emergency Contact
Company Name: NCR,LLC/AREA CODE MGMT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385544

Contact Type: Not reported
Contact Name: AVIHU GERAFI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 330-5520
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Tank Info:

Tank Number: 001
Tank Id: 8000
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1965
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 09/12/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-147877
SWIS Code: 6201
Operator: FRANCISCO RIVERA
Facility Phone: (212) 974-2187
Facility Addr2: 428 WEST 47TH ST
Facility Type: Not reported
Emergency: ISAAC CHINITZ
Emergency Tel: (212) 974-2187

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385544

Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: GAMO REALTY CO
Owner Address: 826 NINTH AVENUE 2FS
Owner City,St,Zip: NEW YORK CITY, NY 10019
Federal ID: Not reported
Owner Tel: (212) 974-2187
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: GAMO REALTY CO
Mailing Address: 826 NINTH AVENUE 2FS
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK CITY, NY 10019
Mailing Telephone: (212) 974-2187
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/08/1997
Expiration: 06/05/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385544

Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CI508 **709 EIGHTH AVENUE**
East **709 8TH AVENUE**
1/8-1/4 **NEW YORK, NY 10036**
0.236 mi.
1247 ft. **Site 1 of 4 in cluster CI**

NY AST **U004045734**
N/A

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-236497
Program Type: PBS
UTM X: 585397.71680000005
UTM Y: 4512484.80009
Expiration Date: 07/10/1992
Site Type: Other

Affiliation Records:

Site Id: 8765
Affiliation Type: Facility Owner
Company Name: HACELS INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 709 8TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 957-8000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8765
Affiliation Type: Mail Contact
Company Name: JOYCE CONTRACTING INC
Contact Type: Not reported
Contact Name: MEL DITHOWICH
Address1: 9201 FLATLANDS AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11236
Country Code: 001
Phone: (718) 257-1070
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

709 EIGHTH AVENUE (Continued)

U004045734

Date Last Modified: 3/4/2004

Site Id: 8765
Affiliation Type: On-Site Operator
Company Name: 709 EIGHTH AVENUE
Contact Type: Not reported
Contact Name: RUPERT POWELL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 957-8000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 8765
Affiliation Type: Emergency Contact
Company Name: HACELS INC
Contact Type: Not reported
Contact Name: RUPERT POWELL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 325-7108
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 12679
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

709 EIGHTH AVENUE (Continued)

U004045734

Pipe Model: Not reported
Install Date: 10/01/1991
Capacity Gallons: 900
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/1996
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

BZ509
WNW
1/8-1/4
0.237 mi.
1251 ft.

TRAILWAYS INC
544 W 41ST ST
NEW YORK, NY 10036

RCRA NonGen / NLR
FINDS
NY MANIFEST

1000254768
NYD981483514

Site 4 of 8 in cluster BZ

Relative:
Lower

RCRA NonGen / NLR:

Actual:
19 ft.

Date form received by agency: 01/01/2007
Facility name: TRAILWAYS INC
Facility address: 544 W 41ST ST
NEW YORK, NY 100366201
EPA ID: NYD981483514
Mailing address: CLINTON ST
HOBOKEN, NY 07030
Contact: Not reported
Contact address: CLINTON ST
HOBOKEN, NY 07030
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: TRAILWAYS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TRAILWAYS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRAILWAYS INC (Continued)

1000254768

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: TRAILWAYS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: TRAILWAYS INC
Classification: Not a generator, verified

Date form received by agency: 04/30/1986
Site name: TRAILWAYS INC
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004404458

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD981483514
Country: USA

Mailing Info:

Name: TRAILWAYS INCORPORATED
Contact: TRAILWAYS INCORPORATED
Address: 825 41ST STREET & 11TH AVENUE
City/State/Zip: NEW YORK, NY 10001
Country: USA
Phone: 201-656-3440

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TRAILWAYS INC (Continued)

1000254768

Document ID: NJA0162512
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS-10
Trans2 State ID: Not reported
Generator Ship Date: 860502
Trans1 Recv Date: 860502
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860502
Part A Recv Date: 860610
Part B Recv Date: 860515
Generator EPA ID: NYD981483514
Trans1 EPA ID: NJD980784649
Trans2 EPA ID: Not reported
TSDF ID: NJD084044064
Waste Code: X721 - WASTE OIL FROM GAS STATION (NJ ONLY)
Quantity: 01321
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

CG510
NNE
1/8-1/4
0.238 mi.
1257 ft.

436-438 WEST 47TH APARTMENT OWNERS CORP
436 WEST 47TH STREET
NEW YORK, NY 10036
Site 2 of 2 in cluster CG

NY AST **A100292366**
N/A

Relative:
Higher

AST:

Actual:
41 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-608785
Program Type: PBS
UTM X: 585130.07982999994
UTM Y: 4512828.6028100001
Expiration Date: 04/03/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30636
Affiliation Type: Facility Owner
Company Name: 436-438 W 47TH APT OWNERS CORP % JORDAN COOPER & A
Contact Type: Not reported
Contact Name: Not reported
Address1: 440 NINTH AVE, 15TH FL
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 888-6100
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/4/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

436-438 WEST 47TH APARTMENT OWNERS CORP (Continued)

A100292366

Site Id: 30636
Affiliation Type: Mail Contact
Company Name: 436-438 WEST 47TH APT OWNERS CORP.
Contact Type: Not reported
Contact Name: PAUL T. BRENSILBER
Address1: % JORDAN, COOPER & ASSOCS
Address2: 440 NINTH AVENUE, 15TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 613-4602
EMail: SBRENSILBER@JORDANCOOPER.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/4/2013

Site Id: 30636
Affiliation Type: On-Site Operator
Company Name: 436-438 WEST 47TH APARTMENT OWNERS CORP
Contact Type: Not reported
Contact Name: GREG KOROW
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 228-4240
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/4/2013

Site Id: 30636
Affiliation Type: Emergency Contact
Company Name: 436-438 W 47TH APT OWNERS CORP % JORDAN COOPER & A
Contact Type: Not reported
Contact Name: PAUL T. BRENSILBER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 544-0025
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/4/2013

Tank Info:

Tank Number: 001
Tank Id: 65645
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

436-438 WEST 47TH APARTMENT OWNERS CORP (Continued)

A100292366

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
B05 - Tank External Protection - Jacketed
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/30/1964
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 10/04/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

CD511
WSW
1/8-1/4
0.238 mi.
1257 ft.

**522 W 39TH ST
NEW YORK, NY 10018**

**EDR US Hist Auto Stat 1015538568
N/A**

Site 6 of 8 in cluster CD

**Relative:
Lower**

EDR Historical Auto Stations:

Name: BAIRS AUTO REPAIRS
Year: 2004
Address: 522 W 39TH ST

**Actual:
24 ft.**

Name: BAIRS AUTO REPAIRS
Year: 2010
Address: 522 W 39TH ST

CE512
South
1/8-1/4
0.238 mi.
1257 ft.

**331- WEST 38TH ST
331 WEST 38TH STREET
NEW YORK, NY 10018**

**NY AST A100183460
N/A**

Site 3 of 3 in cluster CE

**Relative:
Higher**

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606889
Program Type: PBS
UTM X: 585048.45973
UTM Y: 4512063.0563300001

**Actual:
38 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

331- WEST 38TH ST (Continued)

A100183460

Expiration Date: 08/29/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 28744
Affiliation Type: Facility Owner
Company Name: JACK RANDAZZO
Contact Type: OWNER
Contact Name: JACK RANDAZZO
Address1: 1946 78TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11214
Country Code: 001
Phone: (718) 232-0730
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/18/2012

Site Id: 28744
Affiliation Type: Mail Contact
Company Name: RANDAZZO REALTY CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 1946 78TH ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11214
Country Code: 001
Phone: (718) 614-3804
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/18/2012

Site Id: 28744
Affiliation Type: On-Site Operator
Company Name: 331- WEST 38TH ST
Contact Type: Not reported
Contact Name: SALVIO RANDAZZO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 614-3804
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/18/2012

Site Id: 28744
Affiliation Type: Emergency Contact
Company Name: JACK RANDAZZO

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

331- WEST 38TH ST (Continued)

A100183460

Contact Type: Not reported
Contact Name: SALVIO RANDAZZO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 614-3804
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 7/18/2012

Tank Info:

Tank Number: 123
Tank Id: 61998
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

K00 - Spill Prevention - None
B99 - Tank External Protection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
H99 - Tank Leak Detection - Other
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

3
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/20/1963
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 07/18/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BY513
South
1/8-1/4
0.238 mi.
1258 ft.
344 WEST 38TH STREET
344 WEST 38TH STREET
NEW YORK, NY 10018
Site 8 of 8 in cluster BY

NY AST
U003385434
N/A

Relative:
Higher

AST:

Actual:
39 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-189502
Program Type: PBS
UTM X: 585045.40341999999
UTM Y: 4512081.7389700003
Expiration Date: 03/15/2011
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 5796
Affiliation Type: Mail Contact
Company Name: WINOKER REALTY COMPANY
Contact Type: Not reported
Contact Name: KEN BONAL
Address1: 462 SEVENTH AVENUE, 12A
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 519-2015
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/20/2008

Site Id: 5796
Affiliation Type: On-Site Operator
Company Name: 344 WEST 38TH STREET
Contact Type: Not reported
Contact Name: CARLOS PLATERO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 364-5084
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/20/2008

Site Id: 5796
Affiliation Type: Emergency Contact
Company Name: KARMA PROPERTIES, LLC % WINOKER REALTY
Contact Type: Not reported
Contact Name: KEN BONAL
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

344 WEST 38TH STREET (Continued)

U003385434

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 733-1835
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 3/20/2008

Site Id: 5796
Affiliation Type: Facility Owner
Company Name: KARMA PROPERTIES, LLC % WINOKER REALTY
Contact Type: Not reported
Contact Name: Not reported
Address1: 462 SEVENTH AVENUE, 12A
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 519-2015
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 3/18/2011

Tank Info:

Tank Number: 001
Tank Id: 6425
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1912
Capacity Gallons: 7500
Tightness Test Method: 21
Date Test: 04/04/2000
Next Test Date: Not reported
Date Tank Closed: 01/23/2009
Register: True
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

344 WEST 38TH STREET (Continued)

U003385434

Last Modified: 03/18/2011
Material Name: #6 Fuel Oil (On-Site Consumption)

CC514
SSE
1/8-1/4
0.239 mi.
1263 ft.

620 8TH AVE
NEW YORK, NY 10018

EDR US Hist Auto Stat 1015579221
N/A

Site 8 of 9 in cluster CC

Relative:
Higher

EDR Historical Auto Stations:

Name: ACC CAR CARE CTR
Year: 2004
Address: 620 8TH AVE

Actual:
39 ft.

CC515
SSE
1/8-1/4
0.239 mi.
1263 ft.

NEW YORK TIMES BUILDING
620 EIGHTH AVENUE
NEW YORK, NY 10018

NY AST U004138382
N/A

Site 9 of 9 in cluster CC

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-611122
Program Type: PBS
UTM X: 585201.59166000003
UTM Y: 4512152.1713500004
Expiration Date: 03/06/2019
Site Type: Apartment Building/Office Building

Actual:
39 ft.

Affiliation Records:

Site Id: 416075
Affiliation Type: Facility Owner
Company Name: NEW YORK TIMES BUILDING CONDO
Contact Type: BUILDING MANAGER
Contact Name: MICHAEL O'LEARY
Address1: 620 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 938-4710
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 7/6/2009

Site Id: 416075
Affiliation Type: Mail Contact
Company Name: FIRST NEW YORK PARTNERS
Contact Type: Not reported
Contact Name: MICHAEL O'LEARY
Address1: 620 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES BUILDING (Continued)

U004138382

State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 938-4710
EMail: MOLEARY@FCRC.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/7/2014

Site Id: 416075
Affiliation Type: On-Site Operator
Company Name: NEW YORK TIMES BUILDING
Contact Type: Not reported
Contact Name: FIRST NEW YORK PARTNERS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 938-4710
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 7/6/2009

Site Id: 416075
Affiliation Type: Emergency Contact
Company Name: NEW YORK TIMES BUILDING CONDO
Contact Type: Not reported
Contact Name: MICHAEL O'LEARY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 938-4710
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2/7/2014

Tank Info:

Tank Number: CO1
Tank Id: 229234
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
F05 - Pipe External Protection - Jacketed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES BUILDING (Continued)

U004138382

B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
E12 - Piping Secondary Containment - Double-Wall (Aboveground)
H05 - Tank Leak Detection - In-Tank System (ATG)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/01/2006
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 02/07/2014
Material Name: Diesel

CI516 **305 WEST 45TH STREET**
East **305 WEST 45TH STREET**
1/8-1/4 **NEW YORK, NY 10036**
0.239 mi.
1263 ft. **Site 2 of 4 in cluster CI**

NY AST **U003383597**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-055751
Program Type: PBS
UTM X: 585410.54960000003
UTM Y: 4512536.0174500002
Expiration Date: 12/16/2014
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 865
Affiliation Type: Mail Contact
Company Name: BLDG MANAGEMENT CO., INC.
Contact Type: Not reported
Contact Name: ABBY WOLF
Address1: 417 FIFTH AVENUE
Address2: 4TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 624-4300
EMail: ABBY@BLDG.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 1/3/2011

Site Id: 865

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

305 WEST 45TH STREET (Continued)

U003383597

Affiliation Type: On-Site Operator
Company Name: RESIDENTIAL APARTMENT BUILDING
Contact Type: Not reported
Contact Name: JAMES GAFFNEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 416-3463
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/10/2006

Site Id: 865
Affiliation Type: Emergency Contact
Company Name: IG SECOND GENERATION PARTNERS, LP & I BLDG CO, INC
Contact Type: Not reported
Contact Name: JAMES GAFFNEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 416-3463
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/10/2006

Site Id: 865
Affiliation Type: Facility Owner
Company Name: IG SECOND GENERATION PARTNERS, LP & I BLDG CO, INC
Contact Type: VICE PRESIDENT
Contact Name: MICKEY NAPOLITANO
Address1: 417 FIFTH AVENUE, 4TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10016
Country Code: 001
Phone: (212) 624-4300
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 12/11/2006

Tank Info:

Tank Number: 121
Tank Id: 1808
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

305 WEST 45TH STREET (Continued)

U003383597

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
F04 - Pipe External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
B04 - Tank External Protection - Fiberglass
E02 - Piping Secondary Containment - Vault (with Access)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 11/12/2009
Material Name: #6 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-055751
SWIS Code: 6201
Operator: JAMES GAFFNEY
Facility Phone: (212) 586-7648
Facility Addr2: 305 WEST 45TH STREET
Facility Type: APARTMENT BUILDING
Emergency: JAMES GAFFNEY
Emergency Tel: (212) 586-7648
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: WEMBLY MANAGEMENT CO.
Owner Address: 52 VANDERBILT AVE., SUITE 1600
Owner City,St,Zip: NEW YORK, NY 10017
Federal ID: Not reported
Owner Tel: (212) 557-6700
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: JUNE GEE
Mailing Name: BUILDING MANAGEMENT CO., INC.
Mailing Address: SUITE 1600
Mailing Address 2: 52 VANDERBILT AVENUE
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Telephone: (212) 557-6700
Owner Mark: Third Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

305 WEST 45TH STREET (Continued)

U003383597

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 09/07/2001
Expiration: 09/06/2006
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 121
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 4
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 4
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CJ517
NNW
1/8-1/4
0.239 mi.
1263 ft.

509 W 45TH ST
NEW YORK, NY 10036
Site 1 of 7 in cluster CJ

EDR US Hist Auto Stat 1015529906
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: ALI TOW & REPAIR
Year: 2010
Address: 509 W 45TH ST

Actual:
20 ft.

Name: ALI TOW & REPAIR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

1015529906

Year: 2011
Address: 509 W 45TH ST

Name: ALI TOW & REPAIR
Year: 2012
Address: 509 W 45TH ST

518
SSW
1/8-1/4
0.240 mi.
1266 ft.

485-497 NINTH AVE PARTNERS LLC
493 9TH AVE
NY, NY 10018

NY TANKS

S116349338
N/A

Relative:
Higher

TANKS:
Facility Id: 2-611691
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 2019-03-01
UTM X: 584860.20475999999
UTM Y: 4512125.1752800001

Actual:
39 ft.

CK519
NNE
1/8-1/4
0.240 mi.
1268 ft.

GAMO REALTY CO
454 WEST 47TH ST
NEW YORK CITY, NY 10036

NY AST
NY HIST AST

U003385543
N/A

Site 1 of 3 in cluster CK

Relative:
Higher

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-147869
Program Type: PBS
UTM X: 585122.84852999996
UTM Y: 4512858.4379899995
Expiration Date: 06/05/2017
Site Type: Apartment Building/Office Building

Actual:
40 ft.

Affiliation Records:
Site Id: 4372
Affiliation Type: Facility Owner
Company Name: OSI, LLC/AREA CODE MGMT
Contact Type: AREA CODE MGMT
Contact Name: AVIHU GERAFL
Address1: 519 EAST 5TH ST
Address2: Not reported
City: NEW YORK CITY
State: NY
Zip Code: 10009
Country Code: 001
Phone: (646) 330-5520
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385543

Site Id: 4372
Affiliation Type: Mail Contact
Company Name: OSI LLC/AREA CODE MGMT
Contact Type: Not reported
Contact Name: AVIHU GERAFI
Address1: 519 EAST 5TH ST SUITE 17
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10009
Country Code: 001
Phone: (646) 330-5520
EMail: LAGERAFI@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Site Id: 4372
Affiliation Type: On-Site Operator
Company Name: OSI, LLC
Contact Type: Not reported
Contact Name: TRAVIS COKER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 972-2506
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Site Id: 4372
Affiliation Type: Emergency Contact
Company Name: OSI, LLC/AREA CODE MGMT
Contact Type: Not reported
Contact Name: AVIHU GERAFI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 330-5520
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/12/2012

Tank Info:

Tank Number: 001
Tank Id: 7999
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385543

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1970
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER
Last Modified: 09/12/2012
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-147869
SWIS Code: 6201
Operator: J T NERICH
Facility Phone: (212) 974-2187
Facility Addr2: 454 WEST 47TH ST
Facility Type: Not reported
Emergency: ISAAC CHINITZ
Emergency Tel: (212) 974-2187
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: GAMO REALTY CO
Owner Address: 826 NINTH AVENUE 2FS
Owner City,St,Zip: NEW YORK CITY, NY 10019
Federal ID: Not reported
Owner Tel: (212) 877-7778
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: GAMO REALTY CO
Mailing Address: 826 NINTH AVENUE FS
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK CITY, NY 10019
Mailing Telephone: (212) 974-2187
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAMO REALTY CO (Continued)

U003385543

Certification Flag: False
Certification Date: 08/08/1997
Expiration: 06/05/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CL520 318 W 39 ST
SSE 318 WEST 39TH STREET
1/8-1/4 NEW YORK, NY 10018
0.241 mi.
1270 ft. Site 1 of 7 in cluster CL

NY AST U004078229
N/A

Relative: AST:
Higher Region: STATE
DEC Region: 2
Actual: Site Status: Active
37 ft. Facility Id: 2-481866
Program Type: PBS
UTM X: 585143.19551999995
UTM Y: 4512116.2796799997

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

318 W 39 ST (Continued)

U004078229

Expiration Date: 09/11/2015
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 21566
Affiliation Type: Facility Owner
Company Name: QUADRI PLANETARY ASSOCS % NEWMARK GRUBB KNIGHT FRA
Contact Type: Not reported
Contact Name: Not reported
Address1: 520 EIGHTH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 695-1248
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2014

Site Id: 21566
Affiliation Type: Mail Contact
Company Name: NEWMARK GRUBB KNIGHT FRANK
Contact Type: Not reported
Contact Name: BARBARA SIEGEL
Address1: 520 EIGHTH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 695-1248
EMail: BSIEGEL@NGKF.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2014

Site Id: 21566
Affiliation Type: On-Site Operator
Company Name: 318 W 39 ST
Contact Type: Not reported
Contact Name: LUIS GUTIEREZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-1248
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2014

Site Id: 21566
Affiliation Type: Emergency Contact
Company Name: QUADRI PLANETARY ASSOCS % NEWMARK GRUBB KNIGHT FRA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

318 W 39 ST (Continued)

U004078229

Contact Type: Not reported
Contact Name: LUIS GUTIERREZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 695-1248
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2014

Tank Info:

Tank Number: 001
Tank Id: 39224
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
I05 - Overfill - Vent Whistle

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1968
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 01/23/2014
Material Name: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CK521 456 W 47 ST
NNE 456 W 47 ST
1/8-1/4 NEW YORK, NY 10036
0.241 mi.
1272 ft. Site 2 of 3 in cluster CK

NY AST U003387383
NY HIST AST N/A

Relative:
Higher

AST:

Actual:
40 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-251836
Program Type: PBS
UTM X: 585118.09239000001
UTM Y: 4512860.9367699996
Expiration Date: 06/20/2018
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 10121
Affiliation Type: Mail Contact
Company Name: NGSAT WEST LLC
Contact Type: Not reported
Contact Name: DANNY ZADA
Address1: 17 BARSTOW RD
Address2: SUITE 409
City: GREAT NECK
State: NY
Zip Code: 10011
Country Code: 001
Phone: (516) 441-5116
EMail: DANZADA22@GMAIL.COM
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/9/2013

Site Id: 10121
Affiliation Type: On-Site Operator
Company Name: 456 WEST 47 OIL TANK
Contact Type: Not reported
Contact Name: NICK BOECK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 989-3000
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 10/24/2005

Site Id: 10121
Affiliation Type: Emergency Contact
Company Name: NESAT WEST, LLC
Contact Type: Not reported
Contact Name: DANNY ZADA
Address1: Not reported
Address2: Not reported
City: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

456 W 47 ST (Continued)

U003387383

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 476-4534
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/9/2013

Site Id: 10121
Affiliation Type: Facility Owner
Company Name: NESAT WEST, LLC
Contact Type: MANAGING MEMBER
Contact Name: DANNY ZADA
Address1: 17 BARSTOW RD SUITE 409
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 441-5116
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 9/9/2013

Tank Info:

Tank Number: 130
Tank Id: 11796
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/02/1925
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KAKYER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

456 W 47 ST (Continued)

U003387383

Last Modified: 09/09/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-251836
SWIS Code: 6201
Operator: JOE NERICH
Facility Phone: (212) 541-4746
Facility Addr2: 456 W 47 ST
Facility Type: Not reported
Emergency: JOE NERICH
Emergency Tel: (212) 541-4746
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: RENNICK PROPERTIES-WEST 47,LLC
Owner Address: 400 EAST 57TH STREET #12C
Owner City,St,Zip: NEW YORK, NY 10022
Federal ID: Not reported
Owner Tel: (212) 308-6433
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: NICHOLAS BOECK
Mailing Name: RENNICK PROPERTIES-WEST 47, LLC
Mailing Address: 400 EAST 57TH STREET
Mailing Address 2: APT. 12C
Mailing City,St,Zip: NEW YORK, NY 10022-3025
Mailing Telephone: (212) 308-6433
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/29/1998
Expiration: 10/15/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 130
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

456 W 47 ST (Continued)

U003387383

Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CM522
NW
1/8-1/4
0.241 mi.
1275 ft.

MERCHANDISING WORKSHOP INC
550 W 43RD ST
NY, NY 10036

NY AST U000404667
NY HIST AST N/A

Site 1 of 4 in cluster CM

Relative:
Lower

AST:

Actual:
18 ft.

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-370258
Program Type: PBS
UTM X: 584741.74054000003
UTM Y: 4512699.8593300004
Expiration Date: 06/10/2009
Site Type: Other

Affiliation Records:

Site Id: 18693
Affiliation Type: Facility Owner
Company Name: P R C
Contact Type: REPRESENTATIVE
Contact Name: TONY QIU
Address1: 550 WEST 43RD ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 244-9392
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 6/10/2004

Site Id: 18693
Affiliation Type: Mail Contact
Company Name: CHINA CONSTRUCTION AMERICA, INC.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP INC (Continued)

U000404667

Contact Type: Not reported
Contact Name: TONY QIU
Address1: 525 WASHINGTON BLVD
Address2: SUITE 2688
City: JERSEY CITY
State: NJ
Zip Code: 07310
Country Code: 001
Phone: (201) 876-2788
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 6/10/2004

Site Id: 18693
Affiliation Type: On-Site Operator
Company Name: P R C
Contact Type: Not reported
Contact Name: STAFF OF CHINESE CONSULATE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 244-9392
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 6/10/2004

Site Id: 18693
Affiliation Type: Emergency Contact
Company Name: P R C
Contact Type: Not reported
Contact Name: TONY QIU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 470-1261
EMail: Not reported
Fax Number: Not reported
Modified By: kxtang
Date Last Modified: 6/10/2004

Tank Info:

Tank Number: 001
Tank Id: 21390
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP INC (Continued)

U000404667

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 7500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/27/1999
Register: True
Modified By: kxtang
Last Modified: 06/10/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-370258
SWIS Code: 6201
Operator: BARNEY GORGONE
Facility Phone: (212) 239-4646
Facility Addr2: 550 W 43RD ST
Facility Type: OTHER
Emergency: NORMAN ALSHOOLER PRESIDENT
Emergency Tel: (212) 490-1046
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MERCHANDISING WORKSHOP INC
Owner Address: 550 W 43RD ST
Owner City,St,Zip: NY, NY 10036
Federal ID: Not reported
Owner Tel: (212) 239-4646
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: MERCHANDISING WORKSHOP INC
Mailing Address: 550 W 43RD ST
Mailing Address 2: Not reported
Mailing City,St,Zip: NY, NY 10036
Mailing Telephone: (212) 239-4646
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 01/16/1998

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP INC (Continued)

U000404667

Expiration: 02/03/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 7500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 7500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CM523
NW
1/8-1/4
0.241 mi.
1275 ft.

**MERCHANDISING WORKSHOP
550 WEST 43RD ST
NEW YORK, NY 10036**

Site 2 of 4 in cluster CM

**NY MANIFEST 1009226311
NY Spills N/A**

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYD132809997
Country: USA

**Actual:
18 ft.**

Mailing Info:
Name: MERCHANDISING WORKSHOP
Contact: JEANNETTEJACKSON
Address: 550 WEST 43RD ST
City/State/Zip: NEW YORK, NY 10036
Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP (Continued)

1009226311

Phone: 212-239-4646

Document ID: NJA1879559
Manifest Status: Completed copy
Trans1 State ID: NJDEPES22
Trans2 State ID: Not reported
Generator Ship Date: 940701
Trans1 Recv Date: 940701
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940705
Part A Recv Date: Not reported
Part B Recv Date: 940715
Generator EPA ID: NYD132809997
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 94

Document ID: NJA2108199
Manifest Status: Not reported
Trans1 State ID: NJD002454544
Trans2 State ID: Not reported
Generator Ship Date: 12/18/1998
Trans1 Recv Date: 12/18/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/18/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD132809997
Trans1 EPA ID: NJD002454544
Trans2 EPA ID: Not reported
TSDF ID: 2809
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00300
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 98

SPILLS:

Facility ID: 0008570
Facility Type: ER
DER Facility ID: 260227
Site ID: 323029
DEC Region: 2
Spill Date: 10/23/2000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP (Continued)

1009226311

Spill Number/Closed Date: 0008570 / 5/4/2010
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 10/23/2000
CID: 389
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/23/2000
Spill Record Last Update: 5/4/2010
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: 12/30/05 - A letter was sent to the property owner requesting all available information regarding steps taken to address the spill case (J. Moras).4/2/09 - Austin - Transferred from Needs Reassignment to Patel for further work to remediate and close - end04/13/09-Hiralkumar Patel. went to site for inspcion. met with door keeper. he has no idea about tank. there is a 20 story building at the site.04/28/10-Hiralkumar Patel.alternate address: 544-550 West 43rd Streetno other spills.PBS #: 2-370258. as per PBS record, site had 7,500 gal #2 oil AST in vault with access. tank was removed in May 1999.property owner (as per ACRIS):The Government of the People's Republic of China (PRC)520 12th AvenueNew York, NY 1003604/29/10-Hiralkumar Patel.10:24 AM:- spoke with Baolin Guo at China Construction America, construction company who built on-site building about 8-9 years ago. Mr. Guo doesn't know anything about spill case.Baolin GuoChina Construction AmericaPh. (201) 876-2788email: guo_baolin@chinaconstruction.us10:31 AM:- spoke with Zheng Xuan (212-244-9392 Ext. 9006) at Chinese consulate office. he doesn't know anything about spill case.11:20 AM:- after dicussing with DEC Austin, sent email to Mr. Guo with copy of spill report and asked him to send information about spill cleanup and excavation depth for new building foundation.2:56 PM:- received message from Tony Chu (917-470-1261) from China construction.05/04/10-Hiralkumar Patel.11:25 AM:- spoke with Mr. Chu. he mentioned that they demolished old 5 story building with 6 ft deep cellar and then they built new 23 story building with 1 story basement (about 9 ft bg). he mentioned that no bedrock was encountered in excavation and no contamination observed. as per Mr. Chu, they did not removed any tank from the site. new building was finished in 2003. currently, site has small heating oil tank for emergency generator.case closed based on following:- as per PBS record, site had AST in vault with access-

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCHANDISING WORKSHOP (Continued)

1009226311

Remarks: tank removed in 1999- as per caller's remarks, spill happened as contractor hit possible oil line- as per contractor, no soil contamination observed during work and they dug 2-3 ft more that previous basement depth
CALLER REPORTING A SPILL OF MATERIAL FROM A CONTRACTOR DIGGING AND STRUCK A POSSIBLE OIL LINE. EITHER #6 OR #4 OIL NO CLEAN UP AS OF YET AND NO CALLBACK

Material:

Site ID: 323029
Operable Unit ID: 831028
Operable Unit: 01
Material ID: 546074
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CK524
NNE
1/8-1/4
0.242 mi.
1276 ft.

RESIDENCE
454 WEST 47TH ST
MANHATTAN, NY

NY LTANKS S105996937
N/A

Site 3 of 3 in cluster CK

Relative:
Higher

LTANKS:

Actual:
40 ft.

Site ID: 317589
Spill Number/Closed Date: 0206941 / 11/29/2002
Spill Date: 10/4/2002
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 10/4/2002
CID: 398
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/4/2002
Spill Record Last Update: 11/29/2002
Spiller Name: Not reported
Spiller Company: RESIDENCE
Spiller Address: SAME

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE (Continued)

S105996937

Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: DAVID FAZIN
Spiller Phone: (516) 939-2959
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 255984
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"10/7/2002 - Sangesland sent out Tank Test Failure form letter to Ms. Suet Chauc/o Leeds Associates215 West 83rd StNew York, NY 10024PBS # 2-14786911/29/2002 Sangesland received a letter from Frank Segal of Leeds Associates (212-874-6400). Letter states that the tank was "pumped out, squeegee cleaned & welded" The tank was then retested on Oct 29, 2002 and passed. (Copies of test report attached).Spill Closed
Remarks: small patch over leak with eboxy. no call back needed. unk contact info at residence.

Material:
Site ID: 317589
Operable Unit ID: 859607
Operable Unit: 01
Material ID: 517531
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 317589
Spill Tank Test: 1527537
Tank Number: 001
Tank Size: 3000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

BZ525
WNW
1/8-1/4
0.242 mi.
1277 ft.

548 W 41ST ST
NEW YORK, NY 10036
Site 5 of 8 in cluster BZ

EDR US Hist Auto Stat 1015548949
N/A

Relative:
Lower

EDR Historical Auto Stations:
Name: ACC CAR CARE CTR
Year: 2004
Address: 548 W 41ST ST

Actual:
19 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CD526
WSW
1/8-1/4
0.242 mi.
1277 ft.

MERCEDES BENZ MANHATTAN INC
528 W 39TH ST
NEW YORK, NY 10036

Site 7 of 8 in cluster CD

RCRA-CESQG
FINDS
NY HIST AST
NY MANIFEST

1000168671
NYD982739245

Relative:
Lower

RCRA-CESQG:

Date form received by agency: 01/01/2007

Facility name: MERCEDES BENZ MANHATTAN INC

Facility address: 528 W 39TH ST
NEW YORK, NY 10036

EPA ID: NYD982739245

Mailing address: W 41ST ST
NEW YORK, NY 10036

Contact: L LANE

Contact address: W 41ST ST
NEW YORK, NY 10036

Contact country: US

Contact telephone: (212) 629-1608

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: M-B NORTH AMERICA

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: M-B NORTH AMERICA

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MERCEDES BENZ MANHATTAN INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/07/1989
Site name: MERCEDES BENZ MANHATTAN INC
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 09/25/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004431044

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST AST:

PBS Number: 2-016063
SWIS Code: 6201
Operator: STEPHAN ALTRICNTER
Facility Phone: (212) 629-1606
Facility Addr2: 528 W 39 ST
Facility Type: OTHER
Emergency: MICHAEL KEENAN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Emergency Tel: (212) 629-1600
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MERCEDES/BENZ MANHATTAN INC
Owner Address: 536 WEST 41ST STREET
Owner City,St,Zip: NEW YORK, NY 10036
Federal ID: Not reported
Owner Tel: (212) 760-0600
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: MR. TOM LOPEZ
Mailing Name: MERCEDES/BENZ MANHATTAN INC
Mailing Address: 536 WEST 41ST STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10036
Mailing Telephone: (212) 629-1612
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 10/06/1997
Expiration: 10/23/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 7500
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 7500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

NY MANIFEST:

EPA ID: NYD982739245
Country: USA

Mailing Info:

Name: MERCEDES BENZ MANHATTAN
Contact: LEIGH LANE
Address: 528 W 38TH ST
City/State/Zip: NEW YORK, NY 10036
Country: USA
Phone: 201-573-2799

Document ID: NJA1202128
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910710
Trans1 Recv Date: 910710
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910710
Part A Recv Date: 910827
Part B Recv Date: 910722
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00411
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1219335
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910814
Trans1 Recv Date: 910814
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910815
Part A Recv Date: 910827
Part B Recv Date: 910828
Generator EPA ID: NYD982739245

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00614
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA1333325
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911028
Trans1 Recv Date: 911028
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911028
Part A Recv Date: Not reported
Part B Recv Date: 911108
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00507
Units: P - Pounds
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 91

Document ID: NJA2042839
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950209
Trans1 Recv Date: 950209
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950209
Part A Recv Date: 950313
Part B Recv Date: 950227
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00015
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Specific Gravity: 100
Year: 95

Document ID: NJA1933470
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940921
Trans1 Recv Date: 940921
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940921
Part A Recv Date: 941005
Part B Recv Date: 941005
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA1923776
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940713
Trans1 Recv Date: 940713
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940713
Part A Recv Date: 960510
Part B Recv Date: 940728
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA1965127
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 941128
Trans1 Recv Date: 941128
Trans2 Recv Date: Not reported
TSD Site Recv Date: 941128
Part A Recv Date: Not reported
Part B Recv Date: 941208
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA1962835
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 940818
Trans1 Recv Date: 940818
Trans2 Recv Date: Not reported
TSD Site Recv Date: 940818
Part A Recv Date: 940902
Part B Recv Date: 940831
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 94

Document ID: NJA2086668
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 950707
Trans1 Recv Date: 950707
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950707
Part A Recv Date: 950720
Part B Recv Date: 950725
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00086
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00112
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2055850
Manifest Status: Completed copy
Trans1 State ID: NJDEPE086
Trans2 State ID: Not reported
Generator Ship Date: 950830
Trans1 Recv Date: 950830
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950830
Part A Recv Date: 951002
Part B Recv Date: 950915
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD984908202

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYC4626977
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: Not reported
Generator Ship Date: 05/27/1998
Trans1 Recv Date: 05/27/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/04/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: SCD077995488
Trans2 EPA ID: Not reported
TSDF ID: X522TP
Waste Code: D006 - CADMIUM 1.0 MG/L TCLP
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 98

Document ID: NYC4879530
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: Not reported
Generator Ship Date: 02/18/1998
Trans1 Recv Date: 02/18/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/03/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: SCD077995488
Trans2 EPA ID: Not reported
TSDF ID: 85587

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F005 - UNKNOWN
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NJA3006352
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: Not reported
Generator Ship Date: 10/20/1998
Trans1 Recv Date: 10/20/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: NJD000768093
Trans2 EPA ID: Not reported
TSD ID: 08690
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00051
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 98

Document ID: NJA2853919
Manifest Status: Not reported
Trans1 State ID: ILD984908202
Trans2 State ID: Not reported
Generator Ship Date: 06/26/1998
Trans1 Recv Date: 06/26/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/26/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: NJD000768093
Trans2 EPA ID: Not reported
TSD ID: 08690
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00051

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 98

Document ID: ILA9739095
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 07/02/2001
Trans1 Recv Date: 07/02/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/10/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00015
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F005 - UNKNOWN
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: IAL9860824
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 12/17/2001
Trans1 Recv Date: 12/17/2001
Trans2 Recv Date: 12/27/2001
TSD Site Recv Date: 01/07/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F005 - UNKNOWN
Quantity:	00240
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001
Document ID:	ILA9759342
Manifest Status:	Not reported
Trans1 State ID:	SCR000075150
Trans2 State ID:	NJD071629976
Generator Ship Date:	08/09/2001
Trans1 Recv Date:	08/09/2001
Trans2 Recv Date:	08/20/2001
TSD Site Recv Date:	08/21/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982739245
Trans1 EPA ID:	ILD980613913
Trans2 EPA ID:	Not reported
TSD ID:	UPW151288
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Quantity:	00006
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2001
Document ID:	ILA9855193
Manifest Status:	Not reported
Trans1 State ID:	SCR000075150
Trans2 State ID:	Not reported
Generator Ship Date:	11/19/2001
Trans1 Recv Date:	11/19/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/30/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982739245
Trans1 EPA ID:	ILD980613913
Trans2 EPA ID:	Not reported
TSD ID:	UPW151288
Waste Code:	F005 - UNKNOWN
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

Specific Gravity: 01.00
Year: 2001

Document ID: ILA9855198
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 11/15/2001
Trans1 Recv Date: 11/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/30/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSD ID: UPW151288
Waste Code: D006 - CADMIUM 1.0 MG/L TCLP
Quantity: 00006
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9580184
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 01/15/2001
Trans1 Recv Date: 01/15/2001
Trans2 Recv Date: 01/18/2001
TSD Site Recv Date: 01/23/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982739245
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSD ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00026
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F005 - UNKNOWN
Quantity: 00224
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES BENZ MANHATTAN INC (Continued)

1000168671

[Click this hyperlink](#) while viewing on your computer to access
237 additional NY_MANIFEST: record(s) in the EDR Site Report.

CD527 **MERCEDES-BENZ MANHATTAN, INC.**
WSW **537 W 38 ST**
1/8-1/4 **NEW YORK, NY 10036**
0.242 mi.
1277 ft. **Site 8 of 8 in cluster CD**

NY AST **U004076128**
N/A

Relative:
Lower

AST:

Actual:
23 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-016063
Program Type: PBS
UTM X: 584634.35213999997
UTM Y: 4512389.9953699997
Expiration Date: 02/04/2018
Site Type: Other

Affiliation Records:

Site Id: 106
Affiliation Type: Mail Contact
Company Name: MIDTOWN CENTER AUTO REPAIR INC.
Contact Type: Not reported
Contact Name: MR RABA H. ABRAMOV
Address1: 537 W 38TH ST.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 629-1608
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/25/2013

Site Id: 106
Affiliation Type: On-Site Operator
Company Name: MERCEDES-BENZ MANHATTAN, INC.
Contact Type: Not reported
Contact Name: RALPH FISHER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 629-1608
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 106
Affiliation Type: Emergency Contact

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN, INC. (Continued)

U004076128

Company Name: 528-534 WEST 39 L.L.C. C/O ROCKROSE DEV. CORP
Contact Type: Not reported
Contact Name: RABA H. ABRAMOV
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 596-3673
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/10/2013

Site Id: 106
Affiliation Type: Facility Owner
Company Name: 528-534 WEST 39 L.L.C. C/O ROCKROSE DEV. CORP
Contact Type: AGENT
Contact Name: RABA H. ABRAMOV
Address1: 666 FIFTH AVE. 5TH FLOOR
Address2: Not reported
City: NY
State: NY
Zip Code: 10103
Country Code: 001
Phone: (212) 847-3700
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 4/10/2013

Tank Info:

Tank Number: 001
Tank Id: 26928
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: 6
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/28/1993
Capacity Gallons: 7500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN, INC. (Continued)

U004076128

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/10/2013
Material Name: #6 Fuel Oil (On-Site Consumption)

Tank Number: 002
Tank Id: 247840

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F00 - Pipe External Protection - None
G05 - Tank Secondary Containment - Synthetic Liner
K01 - Spill Prevention - Catch Basin
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B04 - Tank External Protection - Fiberglass
I00 - Overfill - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/01/2013
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/10/2013
Material Name: Waste Oil/Used Oil

Tank Number: 003
Tank Id: 247841

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F00 - Pipe External Protection - None
G05 - Tank Secondary Containment - Synthetic Liner
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MERCEDES-BENZ MANHATTAN, INC. (Continued)

U004076128

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 02/01/2013
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/10/2013
Material Name: Waste Oil/Used Oil

CL528 **314-316 WEST 39TH STREET CORP.**
SSE **316 WEST 39TH STREET**
1/8-1/4 **NEW YORK, NY 10018**
0.243 mi.
1282 ft. **Site 2 of 7 in cluster CL**

NY AST **U003390650**
NY HIST AST **N/A**

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-160814
Program Type: PBS
UTM X: 585147.86773000006
UTM Y: 4512113.7799399998
Expiration Date: 08/26/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 5510
Affiliation Type: Facility Owner
Company Name: 314-316 WEST 39TH STREET CORP.
Contact Type: PRES
Contact Name: TERRENCE
Address1: 4718 18TH AVENUE, SUITE 141
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 436-1537
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/25/2011

Site Id: 5510
Affiliation Type: Mail Contact
Company Name: 314-316 WEST 39TH STREET CORP.
Contact Type: PRES
Contact Name: TERRENCE
Address1: 4718 18TH AVENUE, SUITE 141
Address2: Not reported
City: BROOKLYN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

314-316 WEST 39TH STREET CORP. (Continued)

U003390650

State: NY
Zip Code: 11204
Country Code: 001
Phone: (718) 436-1537
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 7/25/2011

Site Id: 5510
Affiliation Type: On-Site Operator
Company Name: 314-316 WEST 39TH STREET CORP.
Contact Type: Not reported
Contact Name: MARIA DIAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-0075
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 5510
Affiliation Type: Emergency Contact
Company Name: 314-316 WEST 39TH STREET CORP.
Contact Type: Not reported
Contact Name: MARIA DIAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-0075
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 19710
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

314-316 WEST 39TH STREET CORP. (Continued)

U003390650

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1985
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 07/25/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-160814
SWIS Code: 6201
Operator: MARIA DIAZ
Facility Phone: (212) 736-0075
Facility Addr2: 316 W 39 ST
Facility Type: APARTMENT BUILDING
Emergency: MARIA DIAZ
Emergency Tel: (212) 736-0075
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 314-316 WEST 39TH STREET CORP.
Owner Address: 4718 18TH AVENUE, SUITE 141
Owner City,St,Zip: BROOKLYN, NY 11204
Federal ID: Not reported
Owner Tel: (718) 436-1537
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: MOSES WOLF
Mailing Name: 314-316 WEST 39TH STREET CORP.
Mailing Address: 314-316 WEST 39TH STREET CORP.
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11204
Mailing Telephone: (718) 436-1537
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Certification Flag: False
Certification Date: 08/07/1997
Expiration: 08/26/2002
Renew Flag: False
Renew Date: Not reported
Total Capacity: 2000
FAMT: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

314-316 WEST 39TH STREET CORP. (Continued)

U003390650

Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 1
Tank External: 00
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 00
Tank Containment: Diking
Leak Detection: 00
Overfill Protection: 04
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CL529
SSE
1/8-1/4
0.243 mi.
1282 ft.
CON EDISON
316 W 39TH ST
NEW YORK, NY 10018
Site 3 of 7 in cluster CL

NY MANIFEST **S112210395**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004265682
Country: USA

Actual:
37 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210395

Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-30
Trans1 Recv Date: 2012-08-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265682
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456079JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265682
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456095JJK

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210395

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-30
Trans1 Recv Date: 2012-08-30
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-30
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265682
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456079JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-28
Trans1 Recv Date: 2012-08-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-29

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210395

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265682
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456095JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

CL530 **CON EDISON SERVICE BOX: 7419**
SSE **316 W 39TH ST**
1/8-1/4 **NEW YORK, NY 10018**
0.243 mi.
1282 ft. **Site 4 of 7 in cluster CL**

RCRA-CESQG **1016143784**
FINDS **NYP004265682**

Relative:
Higher

RCRA-CESQG:

Actual:
37 ft.

Date form received by agency: 08/29/2012
Facility name: CON EDISON SERVICE BOX: 7419
Facility address: 316 W 39TH ST
NEW YORK, NY 10018
EPA ID: NYP004265682
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7419 (Continued)

1016143784

hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055425044

Environmental Interest/Information System

BZ531
WNW 551 W 41ST ST
1/8-1/4 NEW YORK, NY 10036
0.244 mi.
1287 ft. Site 6 of 8 in cluster BZ

EDR US Hist Auto Stat 1015550689
N/A

Relative: EDR Historical Auto Stations:
Lower Name: ACC CAR CARE CTR
Year: 2004
Actual: Address: 551 W 41ST ST
19 ft.

BZ532 CON EDISON
WNW 551 W 41ST ST
1/8-1/4 NEW YORK, NY 10036
0.244 mi.
1287 ft. Site 7 of 8 in cluster BZ

NY MANIFEST S112210666
N/A

Relative: NY MANIFEST:
Lower EPA ID: NYP004268520
Country: USA
Actual: Mailing Info:
19 ft. Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210666

Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268520
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457025JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-09-14
Trans1 Recv Date: 2012-09-14
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-09-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004268520
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210666

Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010457025JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

BZ533
WNW
1/8-1/4
0.244 mi.
1287 ft.

CON EDISON SERVICE BOX: 7871
551 W 41ST ST
NEW YORK, NY 10036

RCRA-CESQG **1016144065**
FINDS **NYP004268520**

Site 8 of 8 in cluster BZ

Relative:
Lower

RCRA-CESQG:

Actual:
19 ft.

Date form received by agency: 09/14/2012
Facility name: CON EDISON SERVICE BOX: 7871
Facility address: 551 W 41ST ST
NEW YORK, NY 10036
EPA ID: NYP004268520
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: JUAN RODRIGUEZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7871 (Continued)

1016144065

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055459016

Environmental Interest/Information System

BW534
WNW
1/8-1/4
0.245 mi.
1291 ft.

FEDERAL EXPRESS CORP
560 W 42ND ST
NEW YORK, NY 10036
Site 7 of 7 in cluster BW

RCRA NonGen / NLR
FINDS
RI MANIFEST
NY MANIFEST

1004756464
NYD097499933

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: FEDERAL EXPRESS CORP

Facility address: 560 W 42ND ST
NEW YORK, NY 10036

EPA ID: NYD097499933

Mailing address: RTE 109
FARMINGDALE, NY 11735

Contact: EDWARD WALDRON

Contact address: RTE 109
FARMINGDALE, NY 11735

Contact country: US

Contact telephone: (516) 249-3150

Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: FEDERAL EXPRESS

Owner/operator address: PO BOX 727
MEMPHIS, TN 38194

Owner/operator country: US

Owner/operator telephone: (901) 395-4789

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1004756464

Owner/operator name: FEDERAL EXPRESS
Owner/operator address: PO BOX 727
MEMPHIS, TN 38194
Owner/operator country: US
Owner/operator telephone: (901) 395-4789
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: FEDERAL EXPRESS CORP
Classification: Not a generator, verified

Date form received by agency: 05/11/1998
Site name: FEDERAL EXPRESS CORP
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004376318

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RI MANIFEST:

GEN Cert Date: 1/16/2006
Transporter Receipt Date: 1/16/2006
Number Of Containers: Not reported
Container Type: NONE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1004756464

Waste Code1: Not reported
Waste Code2: Not reported
Waste Code3: Not reported
Comment: Not reported
Fee Exempt Code: Not reported
TSD Name: Northland Environmental Inc.
TSD ID: rid040098352
TSD Date: 1/16/2006
Transporter 2 Name: Not reported
Transporter 2 ID: Not reported
Manifest Docket Number: RIS0112011
Waste Description: OILY SOLIDS/DEBRIS/SLUDGE
Quantity: 750
WT/Vol Units: P
Item Number: 1033
Transporter Name: CONSOLIDATED RECYCLI
Transporter EPA ID: MA5000002261
GEN Cert Date: 1/16/2006
Transporter Recpt Date: 1/16/2006
Transporter 2 Recpt Date: Not reported
TSD Recpt Date: 1/16/2006
EPA ID: NYD097499933
Transporter 2 ID: Not reported

NY MANIFEST:

EPA ID: NYD097499933
Country: USA

Mailing Info:

Name: FEDERAL EXPRESS
Contact: FEDERAL EXPRESS
Address: 5 PENN PLAZA
City/State/Zip: NEW YORK, NY 10001
Country: USA
Phone: 212-947-5252

Document ID: PAC5121782
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: PAAH0172
Trans2 State ID: Not reported
Generator Ship Date: 920423
Trans1 Recv Date: 920423
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920424
Part A Recv Date: Not reported
Part B Recv Date: 920529
Generator EPA ID: NYD097499933
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: PAD987266715
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1004756464

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92

Document ID: NYA7737705
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 890406
Trans1 Recv Date: 890406
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890406
Part A Recv Date: 890601
Part B Recv Date: 890418
Generator EPA ID: NYD097499933
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: NYD049178296
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02000
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 89

Document ID: NYG0586188
Manifest Status: Not reported
Trans1 State ID: NYD077444263
Trans2 State ID: Not reported
Generator Ship Date: 05/29/1998
Trans1 Recv Date: 05/29/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/29/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD097499933
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID: NYPD1010
Waste Code: D018 - BENZENE 0.5 MG/L TCLP
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 98

Document ID: PAC8432970
Manifest Status: Completed copy
Trans1 State ID: PAAH0172
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1004756464

Generator Ship Date: 921020
Trans1 Recv Date: 921020
Trans2 Recv Date: Not reported
TSD Site Recv Date: 921021
Part A Recv Date: Not reported
Part B Recv Date: 921030
Generator EPA ID: NYD097499933
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: PAD987266715
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92

Document ID: NYB2192724
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: PC4337NY
Trans2 State ID: Not reported
Generator Ship Date: 900918
Trans1 Recv Date: 900918
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900918
Part A Recv Date: 910115
Part B Recv Date: 901022
Generator EPA ID: NYD097499933
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSD ID: NYD049178296
Waste Code: F003 - UNKNOWN
Quantity: 00350
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00350
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 90

Document ID: NJA1773276
Manifest Status: Completed copy
Trans1 State ID: NJDEPS500
Trans2 State ID: Not reported
Generator Ship Date: 931022
Trans1 Recv Date: 931022

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDERAL EXPRESS CORP (Continued)

1004756464

Trans2 Recv Date: Not reported
TSD Site Recv Date: 931022
Part A Recv Date: Not reported
Part B Recv Date: 931105
Generator EPA ID: NYD097499933
Trans1 EPA ID: NYD006801245
Trans2 EPA ID: Not reported
TSD ID: NJD991291105
Waste Code: F001 - UNKNOWN
Quantity: 00220
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 93

CI535
East
1/8-1/4
0.245 mi.
1292 ft.

301 WEST 45TH STREET
301 WEST 45TH STREET
NEW YORK, NY 10036
Site 3 of 4 in cluster CI

NY AST A100320319
N/A

Relative:
Higher

AST:

Actual:
43 ft.

Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-198706
Program Type: PBS
UTM X: 586091.48415999999
UTM Y: 4512145.1170499995
Expiration Date: 10/06/1992
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 6602
Affiliation Type: Facility Owner
Company Name: MELOHN PROPERTIES MGMT
Contact Type: Not reported
Contact Name: Not reported
Address1: 105 W 55 ST
Address2: Not reported
City: NY
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 541-9045
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/5/2008

Site Id: 6602
Affiliation Type: Mail Contact
Company Name: MELOHN PROPERTIES MGMT
Contact Type: Not reported
Contact Name: Not reported
Address1: 105 W 55 ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

301 WEST 45TH STREET (Continued)

A100320319

Address2: Not reported
City: NY
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 541-9045
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/5/2008

Site Id: 6602
Affiliation Type: On-Site Operator
Company Name: 30 WEST 45TH STREET
Contact Type: Not reported
Contact Name: FRANKIE GUZMERN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 757-1902
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 6602
Affiliation Type: Emergency Contact
Company Name: MELOHN PROPERTIES MGMT
Contact Type: Not reported
Contact Name: R & M BAILEN ACO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 991-2300
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 21202
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

301 WEST 45TH STREET (Continued)

A100320319

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
1
Steel/Carbon Steel/Iron
Tank Converted to Non-Regulated Use
Not reported
Not reported
10000
NN
Not reported
Not reported
Not reported
True
NRLOMBAR
06/05/2008
#6 Fuel Oil (On-Site Consumption)

Tank Location:
Tank Type:
Tank Status:
Pipe Model:
Install Date:
Capacity Gallons:
Tightness Test Method:
Date Test:
Next Test Date:
Date Tank Closed:
Register:
Modified By:
Last Modified:
Material Name:

CI536
East
1/8-1/4
0.245 mi.
1292 ft.
CAMELOT
301 W. 45TH STREET
NEW YORK, NY 10036
Site 4 of 4 in cluster CI

NY AST **A100320316**
N/A

Relative:
Higher

Actual:
43 ft.

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-610803
Program Type: PBS
UTM X: 585385.55238999997
UTM Y: 4512523.3442599997
Expiration Date: 12/23/2018
Site Type: Apartment Building/Office Building
Affiliation Records:
Site Id: 395563
Affiliation Type: Facility Owner
Company Name: 301 WEST 45TH ST LLC % MELOHN PROP. INC.
Contact Type: PROPERTY MGR
Contact Name: JOSEPH HIMLEICH
Address1: 1995 BROADWAY
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 787-2500
EMail: R.HAMMER@MELOHNPROP.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/9/2014

Site Id: 395563

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CAMELOT (Continued)

A100320316

Affiliation Type: Mail Contact
Company Name: 301 WEST 45TH ST LLC % MELOHN PROP. INC.
Contact Type: PROPERTY MGR
Contact Name: JOSEPH HIMLEICH
Address1: 1995 BROADWAY
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (212) 787-2500
EMail: R.HAMMER@MELOHNPROP.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/9/2014

Site Id: 395563
Affiliation Type: On-Site Operator
Company Name: CAMELOT
Contact Type: Not reported
Contact Name: DARWIN CEPEDA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 307-0664
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/9/2014

Site Id: 395563
Affiliation Type: Emergency Contact
Company Name: 301 WEST 45TH ST LLC % MELOHN PROP. INC.
Contact Type: Not reported
Contact Name: JOSEPH HIMLEICH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 787-2500
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 6/9/2014

Tank Info:

Tank Number: 96-47
Tank Id: 222246
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CAMELOT (Continued)

A100320316

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G02 - Tank Secondary Containment - Vault (w/access)
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
H05 - Tank Leak Detection - In-Tank System (ATG)
I00 - Overfill - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
3
Tank Location:
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1965
Capacity Gallons: 10000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 06/09/2014
Material Name: #6 Fuel Oil (On-Site Consumption)

CN537
South
1/8-1/4
0.247 mi.
1305 ft.

CORONET BUTTON DYERS INC
325 W 38TH ST
NEW YORK, NY 10018

RCRA NonGen / NLR **1000338663**
FINDS **NYD990836868**

Site 1 of 2 in cluster CN

Relative:
Higher

RCRA NonGen / NLR:

Actual:
37 ft.

Date form received by agency: 01/01/2007
Facility name: CORONET BUTTON DYERS INC
Facility address: 325 W 38TH ST
NEW YORK, NY 10018
EPA ID: NYD990836868
Mailing address: W 38TH ST
NEW YORK, NY 10018
Contact: Not reported
Contact address: W 38TH ST
NEW YORK, NY 10018
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CORONET BUTTON DYERS INC (Continued)

1000338663

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: CORONET BUTTON DYERS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: CORONET BUTTON DYERS INC
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: CORONET BUTTON DYERS INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 12/19/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CORONET BUTTON DYERS INC (Continued)

1000338663

FINDS:

Registry ID: 110004509032

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CN538
South
1/8-1/4
0.247 mi.
1305 ft.

NINHURSAG PROPERTIES N.V. LTD.
325 W. 38TH ST.
NEW YORK, NY 10018
Site 2 of 2 in cluster CN

NY AST A100178359
N/A

Relative:
Higher

AST:

Actual:
37 ft.

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606163
Program Type: PBS
UTM X: 585062.73051000002
UTM Y: 4512055.4486499997
Expiration Date: 07/03/2016
Site Type: Other

Affiliation Records:

Site Id: 28027
Affiliation Type: Facility Owner
Company Name: NINHURSAG PROPERTIES N.V. LTD.
Contact Type: FALCON PROPERTIES, INC AS MANAGING AGENT
Contact Name: DAVID ZAGA
Address1: 500 FIFTH AVE. #2500
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10110
Country Code: 001
Phone: (212) 302-3000
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 4/26/2006

Site Id: 28027
Affiliation Type: Mail Contact
Company Name: FALCON PROPERTIES, INC.
Contact Type: Not reported
Contact Name: DAVID ZAGA
Address1: 500 FIFTH AVE.
Address2: SUITE #2500
City: NEW YORK
State: NY
Zip Code: 10110

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NINHURSAG PROPERTIES N.V. LTD. (Continued)

A100178359

Country Code: 001
Phone: (212) 302-3000
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 11/1/2004

Site Id: 28027
Affiliation Type: On-Site Operator
Company Name: NINHURSAG PROPERTIES N.V. LTD.
Contact Type: Not reported
Contact Name: FERNANDO DA SILVA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-3185
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 28027
Affiliation Type: Emergency Contact
Company Name: NINHURSAG PROPERTIES N.V. LTD.
Contact Type: Not reported
Contact Name: FERNANDO DA SILVA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 736-3185
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 61028
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NINHURSAG PROPERTIES N.V. LTD. (Continued)

A100178359

B01 - Tank External Protection - Painted/Asphalt Coating
I05 - Overfill - Vent Whistle
J00 - Dispenser - None
G03 - Tank Secondary Containment - Vault (w/o access)
K00 - Spill Prevention - None
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1985
Capacity Gallons: 6500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 04/19/2011
Material Name: #2 Fuel Oil (On-Site Consumption)

539
ENE
1/8-1/4
0.247 mi.
1305 ft.

326 W 46TH ST
326 W 46TH ST
MANHATTAN, NY

NY LTANKS **S102672157**
N/A

Relative:
Higher

LTANKS:

Actual:
44 ft.

Site ID: 79565
Spill Number/Closed Date: 9301069 / 4/22/1993
Spill Date: 4/22/1993
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 4/22/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 4/22/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/27/1993
Spill Record Last Update: 7/20/1993
Spiller Name: Not reported
Spiller Company: BAERENKLAU
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

326 W 46TH ST (Continued)

S102672157

DER Facility ID: 73861
DEC Memo: Not reported
Remarks: TANK WAS ALREADY FULL CAME OUT VENT-CONTAINED ON SIDE WALK-CREW DOING CLEAN UP

Material:
Site ID: 79565
Operable Unit ID: 979677
Operable Unit: 01
Material ID: 401800
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CJ540
NNW
1/8-1/4
0.247 mi.
1306 ft.

517-525 WEST 45TH STREET
517-525 WEST 45TH STREET
NEW YORK, NY

NY AST **S106470411**
NY Spills **N/A**

Site 2 of 7 in cluster CJ

Relative:
Lower

AST:
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605827
Program Type: PBS
UTM X: 584897.47698000004
UTM Y: 4512811.9973900001
Expiration Date: 02/15/2012
Site Type: Apartment Building/Office Building

Actual:
21 ft.

Affiliation Records:
Site Id: 27694
Affiliation Type: Mail Contact
Company Name: SHABBAT LLC
Contact Type: Not reported
Contact Name: MR. FRIEDMAN
Address1: 5314 16TH AVE., SUITE #227
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (347) 409-7541
EMail: YONAH22@YAHOO.COM
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

S106470411

Site Id: 27694
Affiliation Type: On-Site Operator
Company Name: 517-525 WEST 45TH STREET
Contact Type: Not reported
Contact Name: GEORGE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 214-3308
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Site Id: 27694
Affiliation Type: Emergency Contact
Company Name: SHABBAT LLC
Contact Type: Not reported
Contact Name: FRIEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 409-7541
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Site Id: 27694
Affiliation Type: Facility Owner
Company Name: SHABBAT LLC
Contact Type: AGENT
Contact Name: YONAH FRIEDMAN
Address1: 5314 16TH AVE., SUITE #227
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (347) 409-9516
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Tank Info:

Tank Number: 002
Tank Id: 180011
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

S106470411

Equipment Records:

A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2003
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: KXTANG
Last Modified: 09/08/2004
Material Name: #4 Fuel Oil (On-Site Consumption)

Tank Number: 003
Tank Id: 180012
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/14/2007
Register: True
Modified By: dxliving
Last Modified: 04/28/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

S106470411

Material Name: Waste Oil/Used Oil

Tank Number: 004

Tank Id: 180013

Material Code: 0022

Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I00 - Overfill - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/14/2007
Register: True
Modified By: dxliving
Last Modified: 04/28/2008
Material Name: Waste Oil/Used Oil

SPILLS:

Facility ID: 0430009
Facility Type: ER
DER Facility ID: 259788
Site ID: 322482
DEC Region: 2
Spill Date: 6/1/2004
Spill Number/Closed Date: 0430009 / 6/25/2004
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 6/25/2004
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

S106470411

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/25/2004
Spill Record Last Update: 6/25/2004
Spiller Name: SAME
Spiller Company: 517-525 WEST 45TH STREET
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: STAVROS PAPAIOANNOU
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"
Remarks: Three Gallons of #2 fuel oil contained in fill box. Building super cleaned spill while DEC was on site.

Material:
Site ID: 322482
Operable Unit ID: 890426
Operable Unit: 01
Material ID: 485387
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 3
Units: Gallons
Recovered: 3
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CJ541
NNW
1/8-1/4
0.247 mi.
1306 ft.

**CON EDISON
FT OF 517 W. 45TH ST
NEW YORK, NY 10036
Site 3 of 7 in cluster CJ**

**NY MANIFEST S113814758
N/A**

**Relative:
Lower**

NY MANIFEST:
EPA ID: NYP004311064
Country: USA

**Actual:
21 ft.**

Mailing Info:
Name: CON EDISON
Contact: CON EDISON
Address: 4 IRVING PL 15TH FL
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S113814758

Generator Ship Date: 2013-05-10
Trans1 Recv Date: 2013-05-10
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2013-05-14
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004311064
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 6000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Year: 2013
Manifest Tracking Num: 010456768JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H110

CJ542 517-525 WEST 45TH STREET
NNW 517 WEST 45TH STREET
1/8-1/4 NEW YORK, NY 10036
0.247 mi.
1306 ft. Site 4 of 7 in cluster CJ

NY HIST UST U003790819
N/A

Relative:
Lower

HIST UST:

Actual:
21 ft.

PBS Number: 2-605827
SPDES Number: Not reported
Emergency Contact: EUGENE MARTE
Emergency Telephone: (718) 446-1464
Operator: EUGENE MARTE
Operator Telephone: (718) 446-1464
Owner Name: 525 W45 ST. ASSOCIATES
Owner Address: 48 PROSPECT PARK SW
Owner City,St,Zip: BROOKLYN, NY 11215
Owner Telephone: (718) 499-6200
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: TOKAY REALTY
Mailing Address: 119 MAIN STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: NANUET, NY 10954
Mailing Contact: SAUL SHENKER
Mailing Telephone: (845) 624-0510
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

U003790819

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist
or not at the facility.

Facility Addr2: Not reported
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: APARTMENT BUILDING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 08/17/2001
Expiration Date: 05/03/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 2000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 001
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Not reported
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Diking
Leak Detection: Not reported
Overfill Prot: Float Vent Valve
Dispenser: Not reported
Date Tested: 04/20/2001
Next Test Date: 04/20/2006
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: 21
Deleted: False
Updated: True
Lat/long: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CJ543
NNW
1/8-1/4
0.247 mi.
1306 ft.
517-525 WEST 45TH STREET
517-525 WEST 45TH STREET
NEW YORK, NY 10036
Site 5 of 7 in cluster CJ

NY UST
U004078427
N/A

Relative:
Lower

UST:

Id/Status: 2-605827 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/15/2012
UTM X: 584897.47698000004
UTM Y: 4512811.9973900001
Site Type: Apartment Building/Office Building

Actual:
21 ft.

Affiliation Records:

Site Id: 27694
Affiliation Type: Mail Contact
Company Name: SHABBAT LLC
Contact Type: Not reported
Contact Name: MR. FRIEDMAN
Address1: 5314 16TH AVE., SUITE #227
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (347) 409-7541
EMail: YONAH22@YAHOO.COM
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Site Id: 27694
Affiliation Type: On-Site Operator
Company Name: 517-525 WEST 45TH STREET
Contact Type: Not reported
Contact Name: GEORGE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 214-3308
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Site Id: 27694
Affiliation Type: Emergency Contact
Company Name: SHABBAT LLC
Contact Type: Not reported
Contact Name: FRIEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

U004078427

Zip Code: Not reported
Country Code: 999
Phone: (347) 409-7541
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Site Id: 27694
Affiliation Type: Facility Owner
Company Name: SHABBAT LLC
Contact Type: AGENT
Contact Name: YONAH FRIEDMAN
Address1: 5314 16TH AVE., SUITE #227
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: (347) 409-9516
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 4/28/2008

Tank Info:

Tank Number: 001
Tank ID: 60531
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 05/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 04/20/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 08/30/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

517-525 WEST 45TH STREET (Continued)

U004078427

G00 - Tank Secondary Containment - None

CJ544
NNW
1/8-1/4
0.247 mi.
1306 ft.

517 W 45TH ST
NEW YORK, NY 10036

Site 6 of 7 in cluster CJ

EDR US Hist Auto Stat 1015535325
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: 45 STREET CLASSIC AUTO
Year: 2001

Actual:
21 ft.

Address: 517 W 45TH ST

Name: 45 STREET CLASSIC AUTO
Year: 2002
Address: 517 W 45TH ST

Name: 45 STREET CLASSIC AUTO
Year: 2004
Address: 517 W 45TH ST

Name: PARS AUTO REPAIR INC
Year: 2009
Address: 517 W 45TH ST

Name: PARS AUTO REPAIR
Year: 2010
Address: 517 W 45TH ST

Name: PARS AUTO REPAIR
Year: 2011
Address: 517 W 45TH ST

Name: PARS AUTO REPAIR
Year: 2012
Address: 517 W 45TH ST

CB545
NW
1/8-1/4
0.248 mi.
1307 ft.

551 W 44TH ST
NEW YORK, NY 10036

Site 2 of 2 in cluster CB

EDR US Hist Auto Stat 1015550690
N/A

Relative:
Lower

EDR Historical Auto Stations:

Name: ALI AUTO TRANSMISSION
Year: 2003
Address: 551 W 44TH ST

Actual:
19 ft.

Name: ALI AUTO TRANSMISSION
Year: 2010
Address: 551 W 44TH ST

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CO546
WSW
1/8-1/4
0.248 mi.
1308 ft.

500 10TH AVE
NEW YORK, NY 10018

Site 1 of 7 in cluster CO

EDR US Hist Auto Stat

1015521952
N/A

Relative:
Higher

EDR Historical Auto Stations:

Name: FIRST VEHICLE SVC INC
Year: 2010
Address: 500 10TH AVE

Actual:
33 ft.

CO547
WSW
1/8-1/4
0.248 mi.
1311 ft.

REMCO MAINTENANCE CORPORATION
10TH AVE
NEW YORK, NY 10018

Site 2 of 7 in cluster CO

RCRA-SQG
NJ MANIFEST
NY MANIFEST

1000154761
NYD001514223

Relative:
Higher

RCRA-SQG:

Date form received by agency: 01/23/2007
Facility name: REMCO MAINTENANCE CORPORATION
Facility address: 10TH AVE
NEW YORK, NY 10018
EPA ID: NYD001514223
Contact: DANIEL J RIVERS
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (516) 924-7873
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Actual:
33 ft.

Owner/Operator Summary:

Owner/operator name: HOWARD INTERNATIONAL
Owner/operator address: TENTH AVE
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1972
Owner/Op end date: Not reported

Owner/operator name: REMCO MAINTENANCE CORPORATION
Owner/operator address: TENTH AVE
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/19/1994
Owner/Op end date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/22/2007
Site name: REMCO MAINTENANCE CORPORATION
Classification: Small Quantity Generator

Date form received by agency: 01/22/2007
Site name: REMCO MAINTENANCE CORPORATION
Classification: Small Quantity Generator

Date form received by agency: 01/06/2004
Site name: REMCO MAINTENANCE CORPORATION
Classification: Small Quantity Generator

Date form received by agency: 01/14/2002
Site name: REMCO MAINTENANCE CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: REMCO MAINTENANCE CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 07/21/1999
Site name: REMCO MAINTENANCE CORP
Classification: Large Quantity Generator

Date form received by agency: 01/07/1998
Site name: REMCO MAINTENANCE CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 01/23/1996
Site name: REMCO MAINTENANCE CORPORATION
Classification: Large Quantity Generator

Date form received by agency: 10/14/1994
Site name: REMCO MAINTENANCE CORP
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/23/1985
Date achieved compliance: 10/24/1985
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/23/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 03/30/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/11/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/26/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/23/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 10/24/1985
Evaluation lead agency: State

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

NJ MANIFEST:

Manifest Code: NJA5287887
EPA ID: NYD001514223
Date Shipped: 03/07/2006
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD982792384
Transporter 2 EPA ID: NJD982792384
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 03/07/2006
Date Trans2 Transported Waste: 03/07/2006
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 03/09/2006
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 05040621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Manifest Code: NJA5241403
EPA ID: NYD001514223
Date Shipped: 08/18/2006
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD982792384
Transporter 2 EPA ID: NJD982792384
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/18/2006
Date Trans2 Transported Waste: 08/21/2006
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/21/2006
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 09220621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5214119

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

EPA ID: NYD001514223
Date Shipped: 05/18/2005
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD982792384
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 05/18/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 05/19/2005
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 06220525
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5214120
EPA ID: NYD001514223

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Date Shipped: 05/18/2005
TSDf EPA ID: NJD002200046
Transporter EPA ID: NJD982792384
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 05/18/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDf Received Waste: 05/19/2005
Transporter 1 Decal: Not reported
Transporter 2 Decal: Not reported
Generator EPA Facility Name: Not reported
Transporter-1 EPA Facility Name: Not reported
Transporter-2 EPA Facility Name: Not reported
Transporter-3 EPA Facility Name: Not reported
Transporter-4 EPA Facility Name: Not reported
Transporter-5 EPA Facility Name: Not reported
TSDf EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 06220525
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

NY MANIFEST:

EPA ID: NYD001514223
Country: USA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Mailing Info:

Name: REMCO MAINTENANCE CORP
Contact: CAROL VAN DER POEL
Address: 500 TENTH AVE
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-695-4000

Document ID: NYG5226705
Manifest Status: Not reported
Trans1 State ID: 31992JENY
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2004
Trans1 Recv Date: 11/29/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/06/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYR000080549
Trans2 EPA ID: Not reported
TSD ID: NYD049178
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG5226705
Manifest Status: Not reported
Trans1 State ID: 31992JENY
Trans2 State ID: Not reported
Generator Ship Date: 11/29/2004
Trans1 Recv Date: 11/29/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/06/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYR000080549
Trans2 EPA ID: Not reported
TSD ID: NYD049178
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02400
Units: P - Pounds
Number of Containers: 003
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00025
Units: P - Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00040
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG4293549
Manifest Status: Not reported
Trans1 State ID: 45347PANY
Trans2 State ID: Not reported
Generator Ship Date: 08/10/2004
Trans1 Recv Date: 08/10/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/10/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: NYD049178
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00050
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00160
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00160
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: NYG4293549
Manifest Status: Not reported
Trans1 State ID: 45347PANY
Trans2 State ID: Not reported
Generator Ship Date: 08/10/2004
Trans1 Recv Date: 08/10/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/10/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: NYD049178
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00120
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00040
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2004

Document ID: PAH0061281
Manifest Status: Not reported
Trans1 State ID: Not reported
Trans2 State ID: PAAH50059
Generator Ship Date: 03/18/2004
Trans1 Recv Date: 03/18/2004
Trans2 Recv Date: 03/18/2004
TSD Site Recv Date: 03/19/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYR000080549
Trans2 EPA ID: Not reported
TSDF ID: PAD067098
Waste Code: U204 - SELENIOS ACID
Quantity: 00060
Units: G - Gallons (liquids only)* (8.3 pounds)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Number of Containers: 002
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00040
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 008
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00025
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2004

Document ID: PAH0061282
Manifest Status: Not reported
Trans1 State ID: Not reported
Trans2 State ID: PAAH50059
Generator Ship Date: 03/18/2004
Trans1 Recv Date: 03/18/2004
Trans2 Recv Date: 03/18/2004
TSD Site Recv Date: 03/19/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYR000080549
Trans2 EPA ID: Not reported
TSD ID: PAD067098
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 02500
Units: P - Pounds
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2004

Document ID: SCA0318040
Manifest Status: Not reported
Trans1 State ID: 50059
Trans2 State ID: 2A419
Generator Ship Date: 03/18/2004
Trans1 Recv Date: 03/18/2004
Trans2 Recv Date: 03/18/2004
TSD Site Recv Date: 04/02/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJD986607380

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Trans2 EPA ID: Not reported
TSD ID: SCD036275
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01200
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 058
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00030
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Waste Code: F005 - UNKNOWN
Quantity: 00045
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 01.00
Year: 2004

Document ID: NJA2170651
Manifest Status: Completed copy
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 950612
Trans1 Recv Date: 950612
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950612
Part A Recv Date: 950622
Part B Recv Date: 950621
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: F003 - UNKNOWN
Quantity: 00825
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 015
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA1916698
Manifest Status: Completed copy
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 950314
Trans1 Recv Date: 950314
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950314
Part A Recv Date: Not reported
Part B Recv Date: 950327
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJD982281016
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F003 - UNKNOWN
Quantity: 01500
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 028
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2171021
Manifest Status: Completed copy
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 950710
Trans1 Recv Date: 950710
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950710
Part A Recv Date: 950719
Part B Recv Date: 950720
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F003 - UNKNOWN
Quantity: 00330
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 006
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 95

Document ID: NYG0434421
Manifest Status: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 02/09/1998
Trans1 Recv Date: 02/09/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/09/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: PD8070
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 02800
Units: P - Pounds
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

Document ID: NYG4293549
Manifest Status: Not reported
Trans1 State ID: 45347PANY
Trans2 State ID: Not reported
Generator Ship Date: 08/10/2004
Trans1 Recv Date: 08/10/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/10/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSDF ID: NYD049178
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00010
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01200
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00800
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 04000
Units: P - Pounds
Number of Containers: 004
Container Type: CF - Fiber or plastic boxes, cartons
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2004

Document ID: NJA5214119
Manifest Status: Not reported
Trans1 State ID: NJD982792384
Trans2 State ID: Not reported
Generator Ship Date: 05/18/2005
Trans1 Recv Date: 05/18/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: 08219
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00800
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00400
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: Not reported
Year: 2005

Document ID: NJA5214120
Manifest Status: Not reported
Trans1 State ID: NJD982792384
Trans2 State ID: Not reported
Generator Ship Date: 05/18/2005
Trans1 Recv Date: 05/18/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: 08219
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00320
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: 2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Document ID: NJA5214119
Manifest Status: Not reported
Trans1 State ID: NJD982792384
Trans2 State ID: Not reported
Generator Ship Date: 05/18/2005
Trans1 Recv Date: 05/18/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: 08219
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00800
Units: P - Pounds
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00400
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00200
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: Not reported
Year: Not reported

Document ID: NJA5214120
Manifest Status: Not reported
Trans1 State ID: NJD982792384
Trans2 State ID: Not reported
Generator Ship Date: 05/18/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Trans1 Recv Date: 05/18/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: 08219
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity: 00320
Units: P - Pounds
Number of Containers: 008
Container Type: DM - Metal drums, barrels
Handling Method: Not reported
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00005
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Waste Code: Not reported
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: Not reported
Year: Not reported

Document ID: NJA0005669
Manifest Status: Completed copy
Trans1 State ID: NYJA207NJ
Trans2 State ID: Not reported
Generator Ship Date: 860724
Trans1 Recv Date: 860724
Trans2 Recv Date: Not reported
TSD Site Recv Date: 860724
Part A Recv Date: 860731
Part B Recv Date: 860731

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Generator EPA ID: NYD001514223
Trans1 EPA ID: NJD000813477
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01045
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 019
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 86

Document ID: NJA2265296
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 951113
Trans1 Recv Date: 951113
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951113
Part A Recv Date: 951127
Part B Recv Date: 951212
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F003 - UNKNOWN
Quantity: 00385
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 007
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NJA2265188
Manifest Status: Completed copy
Trans1 State ID: S5811
Trans2 State ID: Not reported
Generator Ship Date: 951106
Trans1 Recv Date: 951106
Trans2 Recv Date: Not reported
TSD Site Recv Date: 951106
Part A Recv Date: 951115
Part B Recv Date: 951122
Generator EPA ID: NYD001514223
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: F003 - UNKNOWN
Quantity: 00935
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 017
Container Type: DM - Metal drums, barrels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

REMCO MAINTENANCE CORPORATION (Continued)

1000154761

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 95

Document ID: NYG0756126
Manifest Status: Not reported
Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 05/13/1998
Trans1 Recv Date: 05/13/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/13/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001514223
Trans1 EPA ID: NYD049178296
Trans2 EPA ID: Not reported
TSD ID: NYPC4339
Waste Code: F003 - UNKNOWN
Quantity: 03600
Units: P - Pounds
Number of Containers: 009
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 98

[Click this hyperlink](#) while viewing on your computer to access
65 additional NY_MANIFEST: record(s) in the EDR Site Report.

CO548 **A S I SIGN SYSTEMS INC**
WSW **500 10TH AVE 6TH FLOOR**
1/8-1/4 **NEW YORK, NY 10018**
0.248 mi.
1311 ft.

RCRA-SQG **1001223824**
FINDS **NYR000050401**
NY MANIFEST

Relative:
Higher

RCRA-SQG:

Actual:
33 ft.

Date form received by agency: 01/01/2007
Facility name: A S I SIGN SYSTEMS INC
Facility address: 500 10TH AVE 6TH FLOOR
NEW YORK, NY 100181180
EPA ID: NYR000050401
Mailing address: 10TH AVE 6TH FLOOR
NEW YORK, NY 10018
Contact: Not reported
Contact address: 10TH AVE 6TH FLOOR
NEW YORK, NY 10018
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Owner/Operator Summary:

Owner/operator name: NEW YORK SIGN SYSTEMS INC
Owner/operator address: 500 10TH AVE
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: (212) 675-8686
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK SIGN SYSTEMS INC
Owner/operator address: 500 10TH AVE
NEW YORK, NY 10018
Owner/operator country: US
Owner/operator telephone: (212) 675-8686
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: A S I SIGN SYSTEMS INC
Classification: Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: A S I SIGN SYSTEMS INC
Classification: Not a generator, verified

Date form received by agency: 02/11/1998
Site name: A S I SIGN SYSTEMS INC
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004540382

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000126227
Country: USA

Mailing Info:

Name: NYCTA
Contact: THOMAS ABDALLAH
Address: 2 BROADWAY
City/State/Zip: NEW YORK, NY 10004
Country: USA
Phone: 646-252-3500

Document ID: 06
Manifest Status: ILA1983706
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: ILD980613913
Trans1 Recv Date: Not reported
Trans2 Recv Date: TXR000050930
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 8
Handling Method: G
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: ILA2006458
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Generator Ship Date: ILD980613913
Trans1 Recv Date: Not reported
Trans2 Recv Date: TXR000050930
TSD Site Recv Date: Not reported
Part A Recv Date: NJD471629976
Part B Recv Date: 2006-02-01
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 36
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026196JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: MID980991566
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 55
Handling Method: G
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Document ID: 06
Manifest Status: 001026196JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: MID980991566
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DF
Container Type: 110
Handling Method: G
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026195JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 5
Number of Containers: DM
Container Type: 500
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026195JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 55
Handling Method: G
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 001026425JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: MID980991566
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DF
Container Type: 60
Handling Method: G
Specific Gravity: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 001026307JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 4
Number of Containers: DM
Container Type: 400
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 001026424JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Units: 3
Number of Containers: DM
Container Type: 900
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: ILA9741794
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 05/22/2001
Trans1 Recv Date: 05/22/2001
Trans2 Recv Date: 05/30/2001
TSD Site Recv Date: 05/31/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00015
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9859091
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 12/06/2001
Trans1 Recv Date: 12/06/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/17/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9842607
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 10/23/2001
Trans1 Recv Date: 10/23/2001
Trans2 Recv Date: 10/28/2001
TSD Site Recv Date: 10/29/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9588919
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 03/06/2001
Trans1 Recv Date: 03/06/2001
Trans2 Recv Date: 03/08/2001
TSD Site Recv Date: 03/12/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9730634
Manifest Status: Not reported
Trans1 State ID: SCR000075150

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Trans2 State ID: Not reported
Generator Ship Date: 06/20/2001
Trans1 Recv Date: 06/20/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/26/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00015
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9748752
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 08/14/2001
Trans1 Recv Date: 08/14/2001
Trans2 Recv Date: 08/20/2001
TSD Site Recv Date: 08/21/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9600073
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 03/27/2001
Trans1 Recv Date: 03/27/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/03/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Trans2 EPA ID: Not reported
TSD ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA1613666
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 03/08/2005
Trans1 Recv Date: 03/08/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/16/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSD ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: ILA1597723
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 02/10/2005
Trans1 Recv Date: 02/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/23/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSD ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Year: 2005

Document ID: ILA1541604
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 01/10/2005
Trans1 Recv Date: 01/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/20/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: ILA1603016
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 04/26/2005
Trans1 Recv Date: 04/26/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00035
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2005

[Click this hyperlink](#) while viewing on your computer to access
137 additional NY_MANIFEST: record(s) in the EDR Site Report.

EPA ID: NYR000050401
Country: USA

Mailing Info:
Name: VISUAL GRAPHIS SYSTEMS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Contact: JAMES CHAPARRO
Address: 500 10TH AVE
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-563-5600

Document ID: 06
Manifest Status: ILA1983706
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: ILD980613913
Trans1 Recv Date: Not reported
Trans2 Recv Date: TXR000050930
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 8
Handling Method: G
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: ILA2006458
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: ILD980613913
Trans1 Recv Date: Not reported
Trans2 Recv Date: TXR000050930
TSD Site Recv Date: Not reported
Part A Recv Date: NJD471629976
Part B Recv Date: 2006-02-01
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 36

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026196JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: MID980991566
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 55
Handling Method: G
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026196JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: MID980991566
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Waste Code: N
Quantity: Not reported
Units: 2
Number of Containers: DF
Container Type: 110
Handling Method: G
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026195JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 5
Number of Containers: DM
Container Type: 500
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 06
Manifest Status: 001026195JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSD ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DM
Container Type:	55
Handling Method:	G
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Document ID:	07
Manifest Status:	001026425JJK
Trans1 State ID:	NYR000050401
Trans2 State ID:	Not reported
Generator Ship Date:	MID980991566
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	NJD054126164
TSD Site Recv Date:	Not reported
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSD ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	2
Number of Containers:	DF
Container Type:	60
Handling Method:	G
Specific Gravity:	1
Waste Code:	T
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Document ID:	07
Manifest Status:	001026307JJK
Trans1 State ID:	NYR000050401
Trans2 State ID:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 4
Number of Containers: DM
Container Type: 400
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Document ID: 07
Manifest Status: 001026424JJK
Trans1 State ID: NYR000050401
Trans2 State ID: Not reported
Generator Ship Date: SCD036275626
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJD054126164
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 3
Number of Containers: DM
Container Type: 900
Handling Method: P
Specific Gravity: 1
Waste Code: B
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported
Container Type: Not reported
Handling Method: Not reported
Specific Gravity: Not reported
Year: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Document ID: ILA9741794
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 05/22/2001
Trans1 Recv Date: 05/22/2001
Trans2 Recv Date: 05/30/2001
TSD Site Recv Date: 05/31/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00015
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9859091
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 12/06/2001
Trans1 Recv Date: 12/06/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/17/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9842607
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 10/23/2001
Trans1 Recv Date: 10/23/2001
Trans2 Recv Date: 10/28/2001
TSD Site Recv Date: 10/29/2001
Part A Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9588919
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: SCR000074591
Generator Ship Date: 03/06/2001
Trans1 Recv Date: 03/06/2001
Trans2 Recv Date: 03/08/2001
TSD Site Recv Date: 03/12/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00020
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9730634
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 06/20/2001
Trans1 Recv Date: 06/20/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/26/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00015
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9748752
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: NJD071629976
Generator Ship Date: 08/14/2001
Trans1 Recv Date: 08/14/2001
Trans2 Recv Date: 08/20/2001
TSD Site Recv Date: 08/21/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA9600073
Manifest Status: Not reported
Trans1 State ID: SCR000075150
Trans2 State ID: Not reported
Generator Ship Date: 03/27/2001
Trans1 Recv Date: 03/27/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/03/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: ILD980613913
Trans2 EPA ID: Not reported
TSDF ID: UPW151288
Waste Code: F005 - UNKNOWN
Quantity: 00020
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2001

Document ID: ILA1613666
Manifest Status: Not reported
Trans1 State ID: TXR000050930

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Trans2 State ID: Not reported
Generator Ship Date: 03/08/2005
Trans1 Recv Date: 03/08/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/16/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: ILA1597723
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 02/10/2005
Trans1 Recv Date: 02/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/23/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: ILA1541604
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 01/10/2005
Trans1 Recv Date: 01/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/20/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

A S I SIGN SYSTEMS INC (Continued)

1001223824

Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00036
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2005

Document ID: ILA1603016
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Trans2 State ID: Not reported
Generator Ship Date: 04/26/2005
Trans1 Recv Date: 04/26/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000050401
Trans1 EPA ID: UPW151288
Trans2 EPA ID: Not reported
TSDF ID: ILD980613913
Waste Code: F005 - UNKNOWN
Quantity: 00035
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 2005

[Click this hyperlink](#) while viewing on your computer to access
137 additional NY_MANIFEST: record(s) in the EDR Site Report.

CO549 **ASI INC**
WSW **500 10TH AVE 7TH FL**
1/8-1/4 **NEW YORK, NY 10018**
0.248 mi.
1311 ft. **Site 4 of 7 in cluster CO**

NY MANIFEST **1009225488**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYC000232215
Country: USA

Actual:
33 ft.

Mailing Info:
Name: ASI INC
Contact: ABBIS JAFFER
Address: 500 10TH AVE 7TH FL
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-563-5600

Document ID: NYB2793870

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASI INC (Continued)

1009225488

Manifest Status: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 10/05/1998
Trans1 Recv Date: 10/05/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/30/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYC000232215
Trans1 EPA ID: FLD980559728
Trans2 EPA ID: Not reported
TSD ID: NYJA334
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00130
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 98

Document ID: NYB2793852
Manifest Status: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 02/16/1999
Trans1 Recv Date: 02/16/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/15/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYC000232215
Trans1 EPA ID: FLD980559728
Trans2 EPA ID: Not reported
TSD ID: NYJA334
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 00165
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 003
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 99

CO550 **NEW YORK TRANSIT AUTH**
WSW **560 TENTH AVE**
1/8-1/4 **NEW YORK, NY 10036**
0.248 mi.
1311 ft. **Site 5 of 7 in cluster CO**

RCRA-CESQG **1007449207**
NYR000126227

Relative: RCRA-CESQG:
Higher Date form received by agency: 01/01/2007
Facility name: NEW YORK TRANSIT AUTH
Actual: Facility address: 560 TENTH AVE
33 ft. NEW YORK, NY 10036
EPA ID: NYR000126227

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TRANSIT AUTH (Continued)

1007449207

Mailing address: BROADWAY 02-92
NEW YORK, NY 10036
Contact: THOMAS ABDALLAH
Contact address: BROADWAY 02-92
NEW YORK, NY 10036
Contact country: US
Contact telephone: (646) 252-3500
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 07/30/2004
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 07/30/2004
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. Importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TRANSIT AUTH (Continued)

1007449207

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: NEW YORK TRANSIT AUTH
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/03/2004
Site name: NEW YORK TRANSIT AUTH
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

551
WNW
1/8-1/4
0.249 mi.
1313 ft.

CONED
557 W41ST ST
NEW YORK, NY 10036

NY MANIFEST **S111314093**
N/A

Relative:
Lower

NY MANIFEST:
EPA ID: NYP004240305
Country: USA

Actual:
19 ft.

Mailing Info:
Name: CONED
Contact: CONED
Address: 4 IRVING PLACE
City/State/Zip: NEW YORK, NY 10004
Country: USA
Phone: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2011-08-21
Trans1 Recv Date: 2011-08-21
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2011-08-22
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004240305
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 500.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2011

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONED (Continued)

S111314093

Manifest Tracking Num: 007655399JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

552
ESE
1/8-1/4
0.249 mi.
1314 ft.

276 WEST 43 STREET
276 WEST 43 STREET
MANHATTAN, NY 10036

NY AST **U003393305**
NY HIST AST **N/A**

Relative:
Higher

AST:

Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-358738
Program Type: PBS
UTM X: 585403.56111000001
UTM Y: 4512343.9827100001
Expiration Date: 10/23/1997
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18006
Affiliation Type: Facility Owner
Company Name: MID-CITY ASSOCIATES COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 42-40 BELL BLVD
Address2: Not reported
City: BAYSIDE
State: NY
Zip Code: 11361
Country Code: 001
Phone: (718) 423-0700
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18006
Affiliation Type: Mail Contact
Company Name: ABILENE, INC
Contact Type: Not reported
Contact Name: VIRGINIA MARCH
Address1: 2402 NEPTUNE AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11224

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

276 WEST 43 STREET (Continued)

U003393305

Country Code: 001
Phone: (718) 372-4210
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18006
Affiliation Type: On-Site Operator
Company Name: 276 WEST 43 STREET
Contact Type: Not reported
Contact Name: BILL O'CONNOR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 921-9268
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 18006
Affiliation Type: Emergency Contact
Company Name: MID-CITY ASSOCIATES COMPANY
Contact Type: Not reported
Contact Name: RONALD KRIGSMAN PE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 471-4089
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 001
Tank Id: 26710
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

276 WEST 43 STREET (Continued)

U003393305

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/01/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-358738
SWIS Code: 6201
Operator: BILL O'CONNOR
Facility Phone: (212) 921-9268
Facility Addr2: 276 WEST 43 STREET
Facility Type: APARTMENT BUILDING
Emergency: RONALD KRIGSMAN PE
Emergency Tel: (718) 471-4089
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: MID-CITY ASSOCIATES COMPANY
Owner Address: 42-40 BELL BLVD
Owner City,St,Zip: BAYSIDE, NY 11361
Federal ID: Not reported
Owner Tel: (718) 423-0700
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: VIRGINIA MARCH
Mailing Name: ABILENE, INC
Mailing Address: 2402 NEPTUNE AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11224
Mailing Telephone: (718) 372-4210
Owner Mark: First Owner
Facility Status: 3 - Administratively closed (reasons include business is closed and/or mail is undeliverable, and staff cannot check if tanks were removed; or a duplicate registration was generated).
Certification Flag: False
Certification Date: 09/15/1992
Expiration: 10/23/1997
Renew Flag: False
Renew Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing
Tank Screen: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

276 WEST 43 STREET (Continued)

U003393305

Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: Undefined
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 06/01/1999
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CO553 **500 LINCOLN, LLC**
WSW **501 TENTH AVENUE**
1/8-1/4 **NEW YORK, NY 10018**
0.250 mi.
1318 ft. **Site 6 of 7 in cluster CO**

NY UST **U001842110**
NY HIST UST **N/A**
NY AST

Relative:
Higher

UST:

Actual:
32 ft.

Id/Status: 2-601778 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 03/21/2016
UTM X: 584670.10620000004
UTM Y: 4512297.5913699996
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 23740
Affiliation Type: Mail Contact
Company Name: 500 LINCOLN, LLC
Contact Type: Not reported
Contact Name: MITCHELL RUTTER
Address1: % ESSEX CAPITAL PARTNERS
Address2: 635 MADISON AVENUE, FLOOR 12

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 888-0800
EMail: MBR@ESSEXCAPITAL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2013

Site Id: 23740
Affiliation Type: On-Site Operator
Company Name: 500 LINCOLN, LLC
Contact Type: Not reported
Contact Name: 500 LINCOLN LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 279-9639
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 9/7/2007

Site Id: 23740
Affiliation Type: Emergency Contact
Company Name: 500 LINCOLN LLC % ESSEX CAPITAL PARTNERS
Contact Type: Not reported
Contact Name: ANTONIO BASILLO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 277-6926
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/25/2011

Site Id: 23740
Affiliation Type: Facility Owner
Company Name: 500 LINCOLN LLC % ESSEX CAPITAL PARTNERS
Contact Type: Not reported
Contact Name: Not reported
Address1: 635 MADISON AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 888-0800
EMail: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2013

Tank Info:

Tank Number: 001
Tank ID: 47754
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1994
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 47755
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1994
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 47959
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1994
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 47960
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 12/01/1987
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 59738
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 06/22/2005
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 59739
Tank Status: Closed - Removed
Material Name: Closed - Removed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Capacity Gallons: 3500
Install Date: 04/01/1994
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 007
Tank ID: 59740
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3500
Install Date: 04/01/1994
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 008
Tank ID: 219256
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 100
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 009
Tank ID: 219258
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 010
Tank ID: 219259
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 011
Tank ID: 219260
Tank Status: Closed - Removed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 012
Tank ID: 219261
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 013
Tank ID: 219262
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 014
Tank ID: 219263
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None

Tank Number: 015
Tank ID: 219264
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 016
Tank ID: 219265

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 017
Tank ID: 219266
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 018
Tank ID: 219267
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 019
Tank ID: 219268
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 020
Tank ID: 219269
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 021

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank ID: 219270
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None

Tank Number: 022
Tank ID: 219271
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 023
Tank ID: 219272
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 024
Tank ID: 219273
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 025
Tank ID: 219274
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 026

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank ID: 219275
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Number: 027
Tank ID: 219276
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 028
Tank ID: 219277
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None

Tank Number: 029
Tank ID: 219278
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
I00 - Overfill - None

Tank Number: 030
Tank ID: 219279
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 031

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank ID: 219280
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 032
Tank ID: 219281
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 033
Tank ID: 219282
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 034
Tank ID: 219283
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 035
Tank ID: 219284
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 036

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank ID: 219285
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 037
Tank ID: 219286
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 038
Tank ID: 219287
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 039
Tank ID: 219288
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 040
Tank ID: 219289
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None

Tank Number: 041

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Tank ID: 219290
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 09/07/2007

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 2-601778
SPDES Number: Not reported
Emergency Contact: HECTOR SANTANA
Emergency Telephone: (212) 714-6420
Operator: HECTOR SANTANA
Operator Telephone: (212) 695-4000
Owner Name: HOWARD INTERNATIONAL CORP.
Owner Address: 475 TENTH AVENUE
Owner City,St,Zip: NEW YORK, NY 10018
Owner Telephone: (212) 714-6420
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: HOWARD INTERNATIONAL CORP.
Mailing Address: 475 TENTH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10018
Mailing Contact: MR. FRED HOWARD
Mailing Telephone: (212) 714-6420
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 500 10TH AVENUE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: MANUFACTURING
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 03/09/2001
Expiration Date: 03/05/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 14000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 005
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 7000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Containment: None
Leak Detection: None
Overfill Prot: Vent Whistle
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:

Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-601778
Program Type: PBS
UTM X: 584670.10620000004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

UTM Y: 4512297.5913699996
Expiration Date: 03/21/2016
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 23740
Affiliation Type: Mail Contact
Company Name: 500 LINCOLN, LLC
Contact Type: Not reported
Contact Name: MITCHELL RUTTER
Address1: % ESSEX CAPITAL PARTNERS
Address2: 635 MADISON AVENUE, FLOOR 12
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 888-0800
EMail: MBR@ESSEXCAPITAL.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2013

Site Id: 23740
Affiliation Type: On-Site Operator
Company Name: 500 LINCOLN, LLC
Contact Type: Not reported
Contact Name: 500 LINCOLN LLC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 279-9639
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 9/7/2007

Site Id: 23740
Affiliation Type: Emergency Contact
Company Name: 500 LINCOLN LLC % ESSEX CAPITAL PARTNERS
Contact Type: Not reported
Contact Name: ANTONIO BASILLO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 277-6926
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 1/25/2011

Site Id: 23740
Affiliation Type: Facility Owner

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 LINCOLN, LLC (Continued)

U001842110

Company Name: 500 LINCOLN LLC % ESSEX CAPITAL PARTNERS
Contact Type: Not reported
Contact Name: Not reported
Address1: 635 MADISON AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10022
Country Code: 001
Phone: (212) 888-0800
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 1/23/2013

Tank Info:

Tank Number: 042
Tank Id: 219291
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G06 - Tank Secondary Containment - Remote Impounding Area
F06 - Pipe External Protection - Wrapped
I05 - Overfill - Vent Whistle
I02 - Overfill - High Level Alarm
B05 - Tank External Protection - Jacketed
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 08/01/2007
Capacity Gallons: 7000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/04/2013
Register: True
Modified By: NRLOMBAR
Last Modified: 01/23/2013
Material Name: #4 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CL554
SSE
1/8-1/4
0.250 mi.
1319 ft.
CON EDISON
310 W 39TH ST
NEW YORK, NY 10018
Site 5 of 7 in cluster CL

NY MANIFEST **S112210394**
N/A

Relative:
Higher

NY MANIFEST:
EPA ID: NYP004265674
Country: USA

Actual:
37 ft.

Mailing Info:
Name: CON EDISON
Contact: TOM TEELING
Address: 4 IRVING PLACE - 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: 212-460-3770

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-29
Trans1 Recv Date: 2012-08-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265674
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456094JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-08-29

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON (Continued)

S112210394

Trans1 Recv Date: 2012-08-29
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-08-29
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004265674
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD002200046
Waste Code: Not reported
Quantity: 4000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 010456094JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

CL555
SSE
1/8-1/4
0.250 mi.
1319 ft.

CON EDISON SERVICE BOX: 7420
310 W 39TH ST
NEW YORK, NY 10018
Site 6 of 7 in cluster CL

RCRA-CESQG 1016143783
FINDS NYP004265674

Relative:
Higher

RCRA-CESQG:

Date form received by agency: 08/29/2012

Facility name: CON EDISON SERVICE BOX: 7420

Facility address: 310 W 39TH ST
NEW YORK, NY 10018

EPA ID: NYP004265674
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003

Contact: JUAN RODRIGUEZ
Contact address: Not reported

Not reported
Contact country: Not reported
Contact telephone: (347) 865-5931
Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON EDISON SERVICE BOX: 7420 (Continued)

1016143783

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110055468284

Environmental Interest/Information System

CM556
NW
1/4-1/2
0.251 mi.
1324 ft.

APARTMENT COMPLEX
560 W 43RD ST
MANHATTAN, NY
Site 3 of 4 in cluster CM

NY LTANKS S105230508
N/A

Relative:
Lower

LTANKS:

Actual:
18 ft.

Site ID: 240109
Spill Number/Closed Date: 0108944 / 1/13/2006
Spill Date: 12/7/2001
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: VRNATTAN
Referred To: Not reported
Reported to Dept: 12/7/2001
CID: 365
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT COMPLEX (Continued)

S105230508

Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/7/2001
Spill Record Last Update: 1/13/2006
Spiller Name: ANDREW MENCZEL
Spiller Company: APARTMENT COMPLEX
Spiller Address: 560 W 43RD ST
Spiller City,St,Zip: MANHATTAN, NY -
Spiller County: 001
Spiller Contact: ANDREW MENCZEL
Spiller Phone: (212) 265-5900
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 197514
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN"ROSSAN - CALLED DAVE FAZIN 12/10 AND 12/11/01 AND LEFT CALL BACK INFORMATION WITH RECEPTIONIST.Vivek Nattanmai, December 7, 2005A letter was mailed to the property owner on 12/7/05 requesting for information. Vivek Nattanmai, January 13, 2006Received information regarding the repairs done and the tank testing information. The tank tightness testing found no leak. Spill report closed. CLOSED on January 13, 2006.
Remarks: HORNER EZ 3 - GROSS LEAK

Material:

Site ID: 240109
Operable Unit ID: 846334
Operable Unit: 01
Material ID: 530153
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 240109
Spill Tank Test: 1526755
Tank Number: 001
Tank Size: 15000
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CM557 RIVERBANK WEST APARTMENTS
NW 560 WEST 43RD ST
1/4-1/2 MANHATTAN, NY
0.251 mi.
1324 ft. Site 4 of 4 in cluster CM

NY LTANKS S105996888
N/A

Relative:
Lower

Actual:
18 ft.

LTANKS:

Site ID: 179567
Spill Number/Closed Date: 0206678 / 4/28/2003
Spill Date: 9/27/2002
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 9/27/2002
CID: 281
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/27/2002
Spill Record Last Update: 4/28/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: KENNETH MUNIZ
Spiller Phone: (201) 437-1017
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 150700
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"9/27/02 TJDOverfill of UST, product came out of vent and into garden bed. Spoke with Hess Oil who have stated driver spoke to building person prior to delivery and obtained a signature on form indicating tank had available capacity to accept volume of intended delivery. Hess Oil did remain on site and driver assisted in clean-up using spill kit from rig. Builing personnel also worked on cleanup. Soils were reported to be impacted.Demeo spoke with Director of Operations for building (Marney Burke 212 629 5990). Building was directed to retain contractor or have building personnel containerize impacted soils and remove off-site for proper disposal. Manifests have been required prior to spill closure.4/28/03Disposal documents received from Eastmond. No further Action required.

Remarks:

TANK OVERFILL AT ABOVE LOCATION. CLEANUP IS IN PROGRESS AT TIME OF CALL AND ALL MATERIAL IS EXPECTED TO BE RECOVERED. RESPONSIBILITYFOR SPILL IS STILL UNDER INVESTIGATION.

Material:

Site ID: 179567
Operable Unit ID: 858427

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RIVERBANK WEST APARTMENTS (Continued)

S105996888

Operable Unit: 01
Material ID: 517281
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CL558 307 W 39TH ST
SSE 307 W 39TH ST
1/4-1/2 NEW YORK, NY 10018
0.253 mi.
1338 ft. Site 7 of 7 in cluster CL

NY LTANKS **S102673398**
NY AST **N/A**
NY HIST AST

Relative:
Higher

Actual:
37 ft.

LTANKS:
Site ID: 153365
Spill Number/Closed Date: 9602492 / 12/31/1997
Spill Date: 5/21/1996
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 5/21/1996
CID: 196
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/21/1996
Spill Record Last Update: 1/6/1998
Spiller Name: JIM CAREY
Spiller Company: HANDS ON MANAGMENT
Spiller Address: 307 WEST 39TH ST
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: JIM CAREY
Spiller Phone: (718) 579-3414
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 130135
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MULQUEEN"
Remarks: TANK OVER FILL ABOUT 10 GALS. SPILLED ON GROUND. CLEAN UP TEAM ON WAY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 W 39TH ST (Continued)

S102673398

FOR SAME. AT THIS TIME DRIVER HAS LEAK CONTAINED.

Material:

Site ID: 153365
Operable Unit ID: 1033954
Operable Unit: 01
Material ID: 352308
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: 10
Resource Affected: Not reported
Oxygenate: False

Tank Test:

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-274585
Program Type: PBS
UTM X: 585175.91165000002
UTM Y: 4512112.5481399996
Expiration Date: 05/11/2015
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 11736
Affiliation Type: Facility Owner
Company Name: NOVITA LLC
Contact Type: MANAGING AGENT
Contact Name: FRANK PECORA
Address1: 1374 1ST AVE. #1A
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 861-0303
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2010

Site Id: 11736
Affiliation Type: Mail Contact
Company Name: NOVITA LLC
Contact Type: Not reported
Contact Name: FRANK PECORA
Address1: 1374 FIRST AVENUE
Address2: #1A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 W 39TH ST (Continued)

S102673398

City: NEW YORK
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 861-0303
EMail: Not reported
Fax Number: Not reported
Modified By: cgfreedm
Date Last Modified: 5/24/2004

Site Id: 11736
Affiliation Type: On-Site Operator
Company Name: NOVITA LLC
Contact Type: Not reported
Contact Name: HAYDDE CASTELLANO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 861-0303
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2010

Site Id: 11736
Affiliation Type: Emergency Contact
Company Name: NOVITA LLC
Contact Type: Not reported
Contact Name: FRANK PECORA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 861-0303
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 10/21/2010

Tank Info:

Tank Number: 001
Tank Id: 13817
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 W 39TH ST (Continued)

S102673398

L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/1981
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MSBAPTIS
Last Modified: 10/21/2010
Material Name: #2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number: 2-274585
SWIS Code: 6201
Operator: FRANK PECORA
Facility Phone: (917) 730-0007
Facility Addr2: 307 W 39TH ST
Facility Type: APARTMENT BUILDING
Emergency: FRANK PECORA
Emergency Tel: (917) 730-0007
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: NOVITA LLC
Owner Address: P.O. BOX 3614
Owner City,St,Zip: NEW HYDE PARK, NY 11040
Federal ID: Not reported
Owner Tel: (212) 517-2244
Owner Type: Private Resident
Owner Subtype: Not reported
Mailing Contact: FRANK PECORA
Mailing Name: NOVITA LLC
Mailing Address: P.O. BOX 3614
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW HYDE PARK, NY 11040
Mailing Telephone: (212) 517-2244
Owner Mark: Second Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 05/15/2000
Expiration: 05/11/2005
Renew Flag: False
Renew Date: Not reported
Total Capacity: 1500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 W 39TH ST (Continued)

S102673398

FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 1500
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 0
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 0
Tank Containment: Diking
Leak Detection: 5
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

CJ559
NNW
1/4-1/2
0.254 mi.
1339 ft.

SPILL NUMBER 0206999
525 WEST 45TH ST
MANHATTAN, NY
Site 7 of 7 in cluster CJ

NY LTANKS S105996948
N/A

Relative:
Lower

LTANKS:
Site ID: 178935
Spill Number/Closed Date: 0206999 / 6/3/2003
Spill Date: 10/7/2002
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 10/7/2002

Actual:
22 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0206999 (Continued)

S105996948

CID: 270
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/7/2002
Spill Record Last Update: 1/21/2005
Spiller Name: SOL
Spiller Company: SOL
Spiller Address: 525 WEST 45TH ST
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller County: 001
Spiller Contact: SOL
Spiller Phone: (845) 624-0533
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 150200
DEC Memo:
Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO" PBS #2-60582710/7/2002 DeMeo responded to the site and witnessed the tank test failure. 5/8/03 TJDDemeo contacted by Paul Stewart (ACT) who has been retained by Dime Savings Bank to perform an investigation at 525 W45th Street due to tank test failure. Mr. Stewart stated (4) borings were installed soil/groundwater samples taken from each location. He reports no contamination found. Mr. Stewart was not aware the Department is pursuing an enforcement case against registered tank owner for non-compliance. Mr. Stewart will be submitting a work plan to further investigate this property including either removing tank or sampling soils beneath tank and investigating buried fill line. See also spill 02065495/22/03 TJDSite visit. Demeo on site to witness uncovering of 2,000 UST. When manway was accessed tank contained approximately 60 gallons of #2 Fuel Oil. Tank had previously been pumped dry and cleaned by PTC. Unknown how oil reemerged into tank. A small hole was cut into tank bottom and a soil sample was collected. No visual or olfactory indicators or contamination were present in sample. Laboratory analysis subsequently revealed all petroleum constituents are below TAGM. Fill and vent lines were removed from tank and properly disposed. 5/29/03 TJDSite visit. Demeo on site to witness excavation, removal and inspection of feed and return product lines. Action Environmental performing work under supervision of ACT. Product lines were excavated from tank to perimeter of tenant space. A small excavation was opened inside tenant space where product lines penetrate foundation wall (beneath slab) from boiler room. No visible or olfactory indicators of petroleum contamination was identified in area of piping runs. 6/3/03 TJDClosure report submitted by ACT. NFA letter issued. Additional notes: 9/24/02 Amtrack spill reported (0206549) 9/28/02 Letter sent to Tokay Realty requiring tightness test 10/7/02 Tightness test conducted (tank failed) 10/22/02 Letter requiring retest and/or tank closure sent 10/22/02 Tightness test performed (tank failed) 10/28/02 Follow-up letter sent requiring subsurface investigation 10/29/02 Tank taken out of service. Temporary tank installed. 2/21/03 New 1500 gal AST installed (not registered) 6/3/03 NFA issued. Old 2000 gal UST still active in PBS. New 1500 gal AST not registered.
Remarks: no comments

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0206999 (Continued)

S105996948

Material:

Site ID: 178935
Operable Unit ID: 858746
Operable Unit: 01
Material ID: 517590
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 178935
Spill Tank Test: 1527544
Tank Number: 1
Tank Size: 2000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

CO560
WSW
1/4-1/2
0.263 mi.
1391 ft.

509 WEST 38TH ST
509 WEST 38TH ST
MANHATTAN, NY
Site 7 of 7 in cluster CO

NY LTANKS S102672971
N/A

Relative:
Higher

LTANKS:

Actual:
32 ft.

Site ID: 327504
Spill Number/Closed Date: 9505232 / 7/28/1995
Spill Date: 7/27/1995
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 7/28/1995
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 7/28/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/17/1995
Spill Record Last Update: 9/30/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

509 WEST 38TH ST (Continued)

S102672971

Spiller Name: Not reported
Spiller Company: 5 STAR HOSP. INC
Spiller Address: SAME
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 263635
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT"
Remarks: CLEAN UP DONE BY AL EASTMAN/NYCDEP ALREADY ON SCENE - E-W TO 11TH AVE
DEP WAS THERE LAST NIGHT - OVERFILL THRU VENT ONTO SIDEWALK THEN ST.,
RUNNING WEST INTO SEWER.

Material:
Site ID: 327504
Operable Unit ID: 1016198
Operable Unit: 01
Material ID: 363225
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 150
Units: Gallons
Recovered: 150
Resource Affected: Not reported
Oxygenate: False

Tank Test:

561
SW
1/4-1/2
0.266 mi.
1406 ft.

**HUDSON MEWS PROPERTY - MARTY FINE PARCEL
403 WEST 37TH STREET AND 501-505 9TH AVENUE
NEW YORK, NY 10018**

**NY BROWNFIELDS S110487608
N/A**

**Relative:
Higher**

BROWNFIELDS:

**Actual:
43 ft.**

Program: BCP
Site Code: 416201
Site Description: Location: The site is located at 403 West 37th Street and 501-505 9th Avenue in the Borough of Manhattan, New York County.Site Features: Currently, the site is vacant. An entrance roadway to the Lincoln Tunnel beyond the retaining wall shared with the site, is to the west.Current Zoning: The site is currently inactive, and is zoned for commercial use. The surrounding neighborhood is also commercial, with some residential.Historical Uses: A former iron works was identified on the Sanborn maps spanning the years from 1911 to 1930 on the south-west portion of the Site. From approximately 1930 to 1968 the site was home to a plumbing business as well as a painter.Site Geology and Hydrogeology: Groundwater is about 10 to 15 feet below the surface and, because it is diverted by the Lincoln Tunnel's retaining wall, generally flows to the northwest. Soils are mainly historic fill and sand.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HUDSON MEWS PROPERTY - MARTY FINE PARCEL (Continued)

S110487608

Env Problem: Nature and Extent of Contamination: Soil contains elevated SVOCs and metals indicative of historic fill. The depth of the historic fill varies across the site from three to 15 feet deep. SVOCs exceeding Restricted Residential SCGs include benzo-a-anthracene, benzo-a-pyrene, benzo-b-fluoranthene, benzo-k-fluoranthene, chrysene, dibenzo(a,h)anthracene, and Indeno(1,2,3-cd)pyrene. Several were found at levels approaching 50 ppm. Metals exceeding Restricted Residential SCGs include lead (maximum detection 9000 ppm vs Track 2 Restricted Residential Use SCG of 400 ppm) and barium (maximum 615 ppm vs 400 ppm.) Groundwater sampling showed contamination in one well for chlorobenzene (29 ppb) and 1,4-dichlorobenzene (97 ppb.)

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern.

562
SSW
1/4-1/2
0.267 mi.
1409 ft.

37TH & 9TH ST/BKLYN
37TH/9TH STREET
BROOKLYN, NY

NY LTANKS S106703525
N/A

Relative:
Higher

LTANKS:
Site ID: 312388
Spill Number/Closed Date: 9012156 / 3/14/2002
Spill Date: 2/21/1991
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: a3
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2/22/1991
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 3/15/1991
Spill Record Last Update: 10/17/2002
Spiller Name: Not reported
Spiller Company: NYCTA
Spiller Address: Not reported
Spiller City, St, Zip: NY
Spiller County: 999
Spiller Contact: Not reported

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

37TH & 9TH ST/BKLYN (Continued)

S106703525

Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 251891
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE" TANK REPLACED. CLOSURE INVESTIGATION PENDING. SEE FILE.
Remarks: 7.5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.241GPH, NYCFD ON
SCENE.

Material:
Site ID: 312388
Operable Unit ID: 949166
Operable Unit: 01
Material ID: 428659
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 312388
Spill Tank Test: 1538284
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

563
NNW
1/4-1/2
0.267 mi.
1412 ft.

**COACH USA/AMTRAK TUNNEL
520 WEST 46TH STREET
MANHATTAN, NY**

**NY LTANKS
NY Spills**

**S105997011
N/A**

**Relative:
Lower**

LTANKS:
Site ID: 101047
Spill Number/Closed Date: 0207335 / 9/18/2006
Spill Date: 10/15/2002
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: aaobliga
Referred To: Not reported
Reported to Dept: 10/15/2002

**Actual:
26 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

CID: 196
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/15/2002
Spill Record Last Update: 9/18/2006
Spiller Name: RICH VIHONSKI
Spiller Company: GRAYLINE COACH LINE USA
Spiller Address: 524 WEST 46TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: MATTHEW MATCHETTE
Spiller Phone: (800) 646-3161
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 100428
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"10/16/02 SA/OD TTF LETTER SENT.FILE TRANSFERRED FROM VOUGHT TO OBLIGADO1/19/06- Obligado - File review. From spill report, apparently a tank test failure for diesel tank, soil affected. From PBS, number is 2-602720. There are 2 underground storage tanks at the site. The site was inspected on 11/4/04 by DEC Rossan. A NOV letter was subsequently sent. Among violations for USTs was a failure to test tanks and unreconciled inventory records. Check tank tightness records and there is no file for this site. Call number on PBS report, spoke to the President, George Greeve at (201)529-3666 (ext 1306), said they spend \$600,000 to fix the problem and to call Rich Vihonski at (201) 225-7557 who can give all needed information. Called Nich and left message. 2/1/06 - Obligado - received email from Austin. Apparently this site has already been referred to legal for enforcement by Tipple. The text of email read as follows:231032 Coach USA Bus Garage (Tipple)no reference spill # 520 West 46th Street, ManhattanRI end 01/31/06status Notes: RP has failed to perform the required investigation & remediaton. Repeated attempts to obtain required documentation have been unsuccessful. Case has been referred to DEC legal for enforcement.9/18/06 - Obligado - Close and consolidate with open spill number 0206549.
Remarks: tank failed test - retry at later date.

Material:
Site ID: 101047
Operable Unit ID: 860156
Operable Unit: 01
Material ID: 517931
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

Tank Test:

Site ID: 101047
Spill Tank Test: 1527576
Tank Number: Not reported
Tank Size: 4000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

SPILLS:

Facility ID: 0206549
Facility Type: ER
DER Facility ID: 100428
Site ID: 152495
DEC Region: 2
Spill Date: 9/24/2002
Spill Number/Closed Date: 0206549 / 6/29/2009
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: AAOBLIGA
Referred To: NFA, 6/29/09
Reported to Dept: 9/24/2002
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/24/2002
Spill Record Last Update: 6/29/2009
Spiller Name: RICHARD VIHONSKI
Spiller Company: COACH USA
Spiller Address: 160 S. ROUTE 17 NORTH
Spiller City,St,Zip: PARAMUS, NJ 07652
Spiller Company: 999
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"SEE ALSO SPILL # 03300699/24/02 TJDDiesel fuel leaking from tunnel wall from an unknown source. Location of leak is western tunnel wall beneath 45th street between 10th and 11th Ave. Demeo has site meeting 9/25 to investigate spotential source.9/26/02 TJDDemeo inspected site with Patrick Teeter (Amtrack). Inspection consisted of accessing tracks at 38th Street and walking along track to impacted area north of 45th street. Track Bed is approximately 25 feet below street level. Oil was observed dripping slowly from bedrock fractures

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

along west wall. Oil suspected to be either diesel or #2 Oil is running down from rock fracture along rock face and accumulating both on ground surface and in debris lying along the track bed. The petroleum is also impacting a catch basin adjacent to track with an unknown discharge point. Two buildings along 45th Street were inspected as potential sources. The first a bus Company (PBS 2-602720) has (2) Diesel UST's. The second an apartment building (PBS 2-605827) has (1)#2 Oil UST. No obvious sign of a problem at either location and no other obvious sources in immediate vicinity of spill. Both above facilities sent letters requiring owners to test tanks. Awaiting results. 5/8/03 TJDBus Garage passed tank test. Apt. Bldg failed test. See also spill 0206999.4/15/04 TJDInvestigation of the apartment building UST revealed they were not the source of the petroleum discharge which is impacting the Amtrak ROW. Upon completion of the investigation of 525 West 45th Street, DEC again contacted the Bus Garage (Coach USA) to inform their management additional investigation of their property was necessary. Coach USA was given the option of performing the necessary investigation with their contractor of choice or allowing a state contractor access to the property to conduct an investigation on DEC's behalf. Coach USA decided to perform the investigation themselves. Coach USA retained the services of Bristol Contracting to perform the required investigation. The initial investigation by Bristol revealed a loose pipe fitting at the bottom of the remote fill spill bucket. The two UST's at the bus garage were filled via a single remote fill. The remote fill was directly connected to the 2000 gal UST, a crossover line was connected to the 4000 gal UST. This design created significant backpressure during deliveries. Excavation in the vicinity of the remote fill revealed a large volume of contaminated soils. The contaminated soils extended to the south & east beneath the driveway area. Upon excavation of approximately 50 cubic yards of contaminated soils down to bedrock, several fractures were identified as suspected pathways for the product to migrate to the railway cut where diesel fuel was leaching out of the rockface and accumulating along the Amtrak Right Of Way. The connection between the bedrock fractures and the impact area was confirmed by several dye tests. Upon confirmation of the hydraulic connection, Coach USA was informed that the Department requires them to remediate all petroleum contamination both on their property and off-site on the Amtrak property. A field meeting with all involved parties was held on April 1, 2004. A new spill (0330069) was reported following discovery of the contaminated soils beneath the remote fill on 2/23/04. A letter of responsibility, Stipulation Agreement and a corrective action plan was mailed to Coach USA on 4/15/04. 2/23/05 - Austin - Project reassigned from DeMeo to Tipple8/23/05 - Raphael Ketani. Case transferred to Jeff Vought. 9/19/06 - Obligado - Site site was left off the original list of sites to be transferred to Obligado from Vought. Transfer from Vought to Obligado. Was previously researching case under a different spill number 0207355. Closed that spill number and consolidated with this open spill number 0206549. 04/30/07-Vought-After review of notes above including fact that Coach USA was the source as owner of remote fill that was the source of the spill, Coach entered a Stipulation Agreement under spill #0330069 this PIN closed and case referred back to DEC Obligado who reopened spill #0330069. DEC Vought, DEC Obligado, DEC Piper and DEC Urda had meeting and DEC Urda will not close case referral originally submitted by DEC Demeo until follow up is received from Obligado.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

Spill closed by Vought. 10/01/07-Vought-Receieved notice from AGs office that Coach paid NYS amount of 2999.86 for cost of cleanup. Costs were possibly low as per DEC Austin. Vought called DEC Demeo as per Austin to confer that only 2999.86 was incurred by state.11/27/07 - Obligado - After review of the file, this spill should be reopened because Coach USA has not provided documentation that remediation of the Amtrak right of way has been performed as per September 23, 2004 letter from Tim Demeo to Richard Vihonski. This spill number is also listed on the Stipulation Agreement, which Coach signed and agreed to remediate both spill numbers 0206549 and 0330069. This spill number is reopened.I called Richard Vihonski (201)225-7557 to get an update on Demeo's requirements. Left message to call back the DEC.11/30/07 - Obligado - Called Mr. Vihonski again. Left a message.12/12/07 - Obligado - Have not heard from Mr. Vihonski. Called again and left a message to call back DEC. As Mr. Vihonski has not been returning my calls I trided calling the Coach President - George Greeve 201)529-3666 (ext 1306). I left a message to call back the DEC.George Greeves called me back shortly after. I discussed with him the 2 spill numbers and the September 23, 2004 letter from DEC DeMeo. He asked me to fax the letter to him and he would contact the appropriate person. I faxed him the letter.2/27/08 - Obligado - Received a voice mail from Mr. Greeves. He was following up on our previous conversation. He inquired if Mr. Vilhonski had taken care of our requirements3/3/08 - Obligado - Called back Mr. Greeve. I left message saying the DEC requirements have not been met.3/26/08 - Obligado - Had meeting with Richard Vilhonski (Coach USA), Jinesh Sheth (Bristol Contracting), and Dennis Oconner (Bristol Contracting). According to Richard, a package was submitted to the DEC in response to the September 23, 2004 letter. This was submitted to Michelle Tipple after Tim DeMeo left. They said the package addressed most of these comments in the letter and they will resubmit it to me within 4 weeks. 8/19/08 - Obligado - Email from Jinesh. They will submit the report via cd.10/22/08 - Obligado - After review of report emailed Jinesh with following comments: "Please submit a revised and scaled Figure 2 Site Map that shows all of the following: - Entire layout of property between West 45th and 46th St, including adjacent Amtrak property. - Location of existing USTs, dispensers, lines, and fills ports.- Location of former abandoned/removed USTs-Boring/Monitoring Well locations- location/extent of surface spill on Amtrak property- Any other pertinent informationPlease also revise Figure 3 and Figure 4 so that the initial/final extents of excavation and soil sampling locations are overlaid on the new site map.Thank you. Please revise the figures and resubmit them to me as pdf files via email within 30 days. Please call me if you wish to discuss this matter."3/26/09 - Obligado - Still have not received revised maps. Sent email to Jinesh requiring maps within 15 days or case would be referred to legal for enforcement.6/10/09 - Obligado - Reviewed revised Maps submitted by Jinesh on 4/20/09. The maps address the above comments. After review of all documentation I called Jinesh for some follow up questions. 1) Where does the drain pipe on the amtrak property go? According to Dennis Oconor who was also on the call, those pipes were damaged and not functional. 2) Did they broom sweep and inspect the bedrock on the amtrak property for fractures or possible conduits, as they had done on the Coach USA property. They said they did and they did not find any fractures or conduits through which the product could have traveled. The bedrock was previously blasted out in order to build the tunnel and it acted as a basin to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

Remarks: trap the product. 3) Are there walls or foundations north and west of the remote fill that would have prevented migration in those directions. According to Jinesh, yest there were building foundations to the west and north down to bedrock that prevented the movement of product in those directions. They also opened up the tank area to inspect and retrofit tanks and lines. They did not see any signs of leakage and they found no evidence of contamination. 4) Finally, I asked Jinesh to provide a photograph of the amtrak outcrop to show there is no more leakage. 6/29/09 - Obligado - Received photodocumentation of clean outcrop. AFter discussion with DEC Tibbe, sent No Further Action letter to Coach USA, cc to Jinesh. oil on callers property from unk source.

Material:

Site ID: 152495
Operable Unit ID: 858159
Operable Unit: 01
Material ID: 517151
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0330069
Facility Type: ER
DER Facility ID: 100428
Site ID: 115245
DEC Region: 2
Spill Date: 2/23/2004
Spill Number/Closed Date: 0330069 / 6/10/2008
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: AAOBLIGA
Referred To: Not reported
Reported to Dept: 3/8/2004
CID: Not reported
Water Affected: Not reported
Spill Source: Non Major Facility > 1,100 gal
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/8/2004
Spill Record Last Update: 6/10/2008

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COACH USA/AMTRAK TUNNEL (Continued)

S105997011

Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller Company: 999
Contact Name: RICHARD VIHONSKI
Contact Phone: (201) 225-7557
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"4/15/04 TJDSee also spill #02065494/28/04 TJDReceived call from Rich Vihanski @ Coach USA requesting an extension regarding the signing of the Stipulation Agreement and Corrective Action plan dated April 15, 2004. An extension was granted until May 14, 2004 to respond.2/23/05 - Austin - transferred from DeMeo to Tipple3/25/05 - Austin - transferred from Tipple to Vought4/24/06- Transferred to DEC Piper. Piper left message w/ Rich requesting call back and info. There is another spill at address related to this event. See spill 0206549. This spill closed.11/26/07 - Obligado - After review of the file, this spill should be reopened because Coach USA has not fulfilled all the requirements the September 23, 2004 letter from Tim Demeo regarding the Stipulation Agreement, in which Coach USA agreed to investigate and remediate spill #s0330069 and 0206459. This spill number is reopened. Notes for this spill will be entered under spill remarks for 0206459, as this is where Tim Demeo entered most of his remarks. 6/10/08 - Obligado - This spill is closed and consolidated with 0206549 as per Vadim's consolidation initiative.
Remarks: Contaminated soil discovered. Source is from a leaking loose fitting on buried spill bucket (remote fill). Location is being investigated as source of discharge regarding DEC Spill #0206549.

Material:
Site ID: 115245
Operable Unit ID: 880636
Operable Unit: 01
Material ID: 496575
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

564
NNW
1/4-1/2
0.274 mi.
1446 ft.

**APT BUILDING
545 WEST 45TH ST
MANHATTAN, NY**

**NY LTANKS S102560347
NY Spills N/A**

**Relative:
Lower**

LTANKS:
Site ID: 246310
Spill Number/Closed Date: 9711326 / 1/9/1998
Spill Date: 1/9/1998
Spill Cause: Tank Failure

**Actual:
21 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APT BUILDING (Continued)

S102560347

Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 2401
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1/9/1998
CID: 257
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/9/1998
Spill Record Last Update: 1/15/1998
Spiller Name: CHARLIE
Spiller Company: MYSTIC OIL
Spiller Address: 19-01 STEINWAY ST
Spiller City,St,Zip: ASTORIA, ZZ
Spiller County: 001
Spiller Contact: NONE
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202288
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MARTINKAT"
Remarks: DRIVER OVERFILLED TANK ONTO SIDEWALK SPILL IS ALL CONTAINED AND BEING
CLEANED UP

Material:
Site ID: 246310
Operable Unit ID: 1057826
Operable Unit: 01
Material ID: 326005
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:
Facility ID: 9613745
Facility Type: ER
DER Facility ID: 80157
Site ID: 87487

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APT BUILDING (Continued)

S102560347

DEC Region: 2
Spill Date: 2/24/1997
Spill Number/Closed Date: 9613745 / 2/24/1997
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2/24/1997
CID: 297
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/24/1997
Spill Record Last Update: 2/27/1997
Spiller Name: PETER LAPORE
Spiller Company: WHALECO FUEL CO
Spiller Address: 1 COFFEE ST
Spiller City,St,Zip: BROOKLYN, NY 11231-
Spiller Company: 001
Contact Name: 45TH ST ASSOC
Contact Phone: (212) 499-6200
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"KRIMGOLD"
Remarks: CROSSOVER TUBE ON THE FUEL TRUCK LEAKED - SPIL IS BEING CLEANED UP NOW
Not reported

Material:
Site ID: 87487
Operable Unit ID: 1041320
Operable Unit: 01
Material ID: 338849
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

565
NE
1/4-1/2
0.274 mi.
1446 ft.

695 9TH AVE/MANH
695 9TH AVENUE
MANHATTAN, NY

NY LTANKS

S102671615
N/A

Relative:
Higher

Actual:
49 ft.

LTANKS:

Site ID: 309123
Spill Number/Closed Date: 9010299 / 11/16/1994
Spill Date: 12/29/1900
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 11/16/1994
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 12/22/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/8/1991
Spill Record Last Update: 11/16/1994
Spiller Name: Not reported
Spiller Company: PETRO HEAT & POWER
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 249656
DEC Memo: Not reported
Remarks: GAUGE WAS INCORRECT RESULTING IN OVERFILL, CLEAN UP TEAM ENROUTE.

Material:

Site ID: 309123
Operable Unit ID: 950715
Operable Unit: 01
Material ID: 430461
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

566
NNE
1/4-1/2
0.285 mi.
1505 ft.

TERRIFIC TENEMENTS
425 WEST 48TH STREET
NEW YORK, NY 10036

NY LTANKS
NY UST

U001837807
N/A

Relative:
Higher

Actual:
47 ft.

LTANKS:

Site ID: 175024
Spill Number/Closed Date: 0102069 / 4/13/2002
Spill Date: 5/21/2001
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 5/23/2001
CID: 396
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/23/2001
Spill Record Last Update: 4/13/2002
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: PETER HOYLE
Spiller Phone: (212) 521-6404
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 147154
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"3/21/2002 Sangesland received a message from Curt Schmidt (from ATC) (212-353-8280 ext 326). He said he sent in a report in July 2001 and would like closure on the site. Sangesland asked him to resubmit the report, which he will now do.Mr. Schmidt said he believes the tank failed a tank test, ATC did some borings around the tank in the courtyard which came back below STARS. The remote fill was replaced and the tank then passed the tank test. No contaminated soil was found.If the report submitted backs up the summary above, the spill number will be closed out.4/13/2002 Sangesland received another copy of this report. Cover letter from Curt Schmidt (ATC) dated 4/3/2002 states that the tank in question (4,000 gal - #2 oil) has been re-lined; The manway has been rebuild and the UST has passed a pressure test on Aug 10, 2001.UST Tank location is in the courtyard at the rear of the apartment building at 425 West 48th St. In June 2001, ATC advanced 5 borings to a level "just below" the bottom of the tank. 4 on each side of the tank and 1 in the presumed downgradient direction. ATC says "no physical or olfactory evidence of fuel oil was detected..... no groudwater was encountered". Samples were tested for VOC's and SVOC's (Methods 8021 & 8270). Trace levels

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TERRIFIC TENEMENTS (Continued)

U001837807

Remarks: of VOC's were found, but none exceeded the TAGM 4046 Levels. Based on the sampling data presented by ATC and the documentation of the tank being rebuilt and retested, the DEC will close this spill number out.4/13/2002 - Spill Closed.
tank is out of service. other # for caller 917-868-6174 cell

Material:

Site ID: 175024
Operable Unit ID: 840889
Operable Unit: 01
Material ID: 537761
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 175024
Spill Tank Test: 1526323
Tank Number: 1
Tank Size: 4000
Test Method: 99
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Alternate Test per 613.5a2v

UST:

Id/Status: 2-404667 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/15/2012
UTM X: 585235.05339000002
UTM Y: 4512901.3614600003
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 19475
Affiliation Type: Facility Owner
Company Name: CLINTON CRS HOUSING
Contact Type: Not reported
Contact Name: Not reported
Address1: 423 WEST 55TH ST. 9TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TERRIFIC TENEMENTS (Continued)

U001837807

Phone: (212) 319-1200
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/7/2011

Site Id: 19475
Affiliation Type: Mail Contact
Company Name: RELATED MANAGEMENT
Contact Type: Not reported
Contact Name: JONATHAN BENEZRY
Address1: 423 WEST 55TH STREET
Address2: 9TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10019
Country Code: 001
Phone: (212) 506-5897
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/7/2011

Site Id: 19475
Affiliation Type: On-Site Operator
Company Name: TERRIFIC TENEMENTS
Contact Type: Not reported
Contact Name: BENNY RAMOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 693-8449
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/7/2011

Site Id: 19475
Affiliation Type: Emergency Contact
Company Name: CLINTON CRS HOUSING
Contact Type: Not reported
Contact Name: ETHEL MCCULLOUGH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 695-2914
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 6/7/2011

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TERRIFIC TENEMENTS (Continued)

U001837807

Tank Info:

Tank Number: 01
Tank ID: 23004
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 06/01/1982
Date Tank Closed: 03/24/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 03/24/2010
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 06/07/2011

Equipment Records:

B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

567
ESE
1/4-1/2
0.287 mi.
1514 ft.

COMMERCIAL PROPERTY
255 WEST 43RD ST
MANHATTAN, NY

NY LTANKS S102961746
NY Spills N/A

Relative:
Higher

LTANKS:

Actual:
48 ft.

Site ID: 259261
Spill Number/Closed Date: 9707270 / 9/20/1997
Spill Date: 9/19/1997
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 9/19/1997
CID: 370
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL PROPERTY (Continued)

S102961746

Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/19/1997
Spill Record Last Update: 1/23/1998
Spiller Name: GAMAL
Spiller Company: TIMES SQUARE HOTEL
Spiller Address: 255 WEST 43RD ST
Spiller City,St,Zip: MANHATTEN, ZZ
Spiller County: 001
Spiller Contact: GAMAL
Spiller Phone: (212) 768-8989
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 212115
DEC Memo: Not reported
Remarks: SPILL DUE TO EQUIPMENT MALFUNCTION SPILL TO GROUND ON SIDEWALK AND UNDER GRATING TO SUB BASEMENT SPILL CONTAINED CLEANUP SCHEDULED FOR THIS AFTERNOON

Material:

Site ID: 259261
Operable Unit ID: 1053638
Operable Unit: 01
Material ID: 332847
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 0902530
Facility Type: ER
DER Facility ID: 212115
Site ID: 414575
DEC Region: 2
Spill Date: 6/2/2009
Spill Number/Closed Date: 0902530 / 8/17/2009
Spill Cause: Other
Spill Class: Not reported
SWIS: 3101
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 6/2/2009
CID: Not reported
Water Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL PROPERTY (Continued)

S102961746

Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/2/2009
Spill Record Last Update: 2/4/2010
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: DISPATCHER 251
Contact Phone: (212) 628-2900
DEC Memo: 06/02/09- Zhune spoke to Kelvin Brown Director Facility Management 917-558-5183, 212-389-9362He said about a month ago while doing sidewalk and vault repair they discovered a UST. They star the process to remove the tank. They came twice to suck out oil and clean the tank. The tank was rusted and the oil were seeping under the tank over passs years. Today they were cutting the tank in pieces the flame from the torch of the welder and the oil under the tank caused a fire and the smoke. Tomorrow the oil company is coming back to clean the oil and water that were left on the pit. 06/08/09-Zhune spoke to Kelvin. He said oil and soil contaminated is been completly removed from the pit. The tank is completed gone by tomorrow. The engineers from Super Structure will remove the walls contaminated with oil. DEC Requested soil samples. Kelvin will call PTC to request soil samples. 08/17/09-Petroleum Tank Cleaners sent the report dated 08/11/09Bernini Construction Corporation of 37 Wesr 20th street contacted PTC regarding their discovery of an oil tank under the sidewalk at the referenced location. The tank was opened and it was determined that the tank has a small amount of oil at the bottom that appearesd to be #6 fuel oil.PTC cleaned the tank in preparation for dismantling.Bernini's employees were cutting out the tank when a small, but undetermined amount of oil was found on the floor in the concrete vault containing the tank. The floor of the tank vault is tick, sound concrete free of cracks or voids. Upon removal of all contaminated debris, three soil samples were obtained from the remainig rubble and submitted to South Mall Analytical labs for analysis. All analytes in the three samples were found to be not detectable. Case Closed.

Remarks: CALLER STATES THAT THERE WAS A STRUCTURE FIRE THIS MORNING DURING OVERHALL CONTAMINATED SOIL WAS FOUND OUTSIDE THE STRUCTURE UNK SOURCE.
Not reported

Material:
Site ID: 414575
Operable Unit ID: 1170960
Operable Unit: 01
Material ID: 2162743
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL PROPERTY (Continued)

S102961746

Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9708960
Facility Type: ER
DER Facility ID: 251930
Site ID: 312433
DEC Region: 2
Spill Date: 10/31/1997
Spill Number/Closed Date: 9708960 / 10/31/1997
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: LUCE
Referred To: Not reported
Reported to Dept: 10/31/1997
CID: 252
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/31/1997
Spill Record Last Update: 11/3/1997
Spiller Name: GAMAL
Spiller Company: TIMES SQUARE HOTEL
Spiller Address: 255 WEST 43RD ST
Spiller City,St,Zip: MANHATTEN, ZZ
Spiller Company: 001
Contact Name: UNK
Contact Phone: (212) 768-8989
DEC Memo: Not reported
Remarks: SPILL HAS BEEN CONTAINED AND CLEANUP IN PROGRESS-CAUSE WAS ADEFFECTIVE GAUGE

Material:

Site ID: 312433
Operable Unit ID: 1055337
Operable Unit: 01
Material ID: 330899
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL PROPERTY (Continued)

S102961746

Resource Affected: Not reported
Oxygenate: False

Tank Test:

CP568
WNW
1/4-1/2
0.303 mi.
1601 ft.

MOBIL S/S
561 11TH AVENUE
NEW YORK (County), NY
Site 1 of 2 in cluster CP

NY LTANKS **S100168133**
N/A

Relative:
Lower

LTANKS:

Actual:
16 ft.

Site ID: 59245
Spill Number/Closed Date: 9009655 / 7/2/2003
Spill Date: 12/5/1990
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: DKHARRIN
Referred To: Not reported
Reported to Dept: 12/5/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 12/12/1990
Spill Record Last Update: 9/11/2003
Spiller Name: MIKE MEOLA
Spiller Company: EXXONMOBIL CORPORATION
Spiller Address: 464 DOUGHTY BLVD.
Spiller City,St,Zip: INWOOD, NY 11096
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 55859
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HARRINGTON" This spill site has been transferred from DEC Sigona to Remedial Bureau B, on August 4, 2003. This spill site has been consolidated under Spill No. 8806783. reassigned from Sullivan to Sigona on 11/6/00 DEC's comments regarding a proposed Work Plan for On-Site and Off-Site Investigation by Roux Associates, dated April 30, 2003. Based on the results of our site visit on March 7, 2003, and evaluation of the proposal by Roux Associates, the DEC accepts ExxonMobil's Work Plan and Schedule to evaluate the on-site and off-site contamination at this location. Exxon-Mobil must now complete the implementation of the Work Plan according to the proposed schedule. The results of this investigation must be compiled

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL S/S (Continued)

S100168133

Remarks: into a Subsurface Investigation Report prepared in accordance with Section No. 3, paragraph 3.14 of the Division of Environmental Remediation's Draft DER-10 Technical Guidance for Site Investigation and Remediation, dated December 2002. A complete Remedial Investigation Report must be submitted for DEC review and approval according to the proposed implementation scheduled.
LINE TEST, FAILED PETRO TITE, LEAK RATE -.26GPH, GASSERVICE TO REPAIR & RETEST, TONY KHOURY (FIELD ENGINEER) 516-239-0266.

Material:

Site ID: 59245
Operable Unit ID: 946673
Operable Unit: 01
Material ID: 429857
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 59245
Spill Tank Test: 1537996
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

CP569 **MOBIL OIL CORP SS #QDL**
WNW **561 11TH AVE**
1/4-1/2 **NEW YORK, NY 10036**
0.305 mi.
1608 ft. **Site 2 of 2 in cluster CP**

RCRA NonGen / NLR **1000253419**
NY LTANKS **NYD986962322**
NY UST
NY Spills
US AIRS

Relative:
Lower

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MOBIL OIL CORP SS #QDL
Facility address: 561 11TH AVE
NEW YORK, NY 100362105
EPA ID: NYD986962322
Mailing address: GALLOWS RD - MKTG ENVIRON
FAIRFAX, NY 220370001
Contact: Not reported
Contact address: GALLOWS RD - MKTG ENVIRON
FAIRFAX, NY 220370001
Contact country: US
Contact telephone: Not reported
Contact email: Not reported

Actual:
16 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MOBIL OIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: US
Owner/operator telephone: (703) 849-3330
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MOBIL OIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: US
Owner/operator telephone: (703) 849-3330
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MOBIL OIL CORP SS #QDL
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: MOBIL OIL CORP SS #QDL
Classification: Not a generator, verified

Date form received by agency: 04/10/1991
Site name: MOBIL OIL CORP SS #QDL
Classification: Small Quantity Generator

Violation Status: No violations found

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

LTANKS:

Site ID: 162739
Spill Number/Closed Date: 9905507 / 7/2/2003
Spill Date: 8/6/1999
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: DKHARRIN
Referred To: Not reported
Reported to Dept: 8/6/1999
CID: 270
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 8/6/1999
Spill Record Last Update: 1/30/2006
Spiller Name: MARCO
Spiller Company: MOBIL
Spiller Address: 561 11 AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: MARCO
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 137288
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HARRINGTON" This spill site has been transferred from DEC Sigona to RemedialBureau B, on August 4, 2003. This spill site has been consolidated under Spill No. 8806783. Reassigned from O'Dowd on March 1, 2000 DEC's comments regarding a proposed Work Plan for On-Site and Off-Site Investigation by Roux Associates, dated April 30, 2003. Based on the results of our site visit on March 7, 2003, and evaluation of the proposal by Roux Associates, the DEC accepts ExxonMobil's Work Plan and Schedule to evaluate the on-site and off-site contamination at this location. Exxon-Mobil must now complete the implementation of the Work Plan according to the proposed schedule. The results of this investigation must be compiled into a Subsurface Investigation Report prepared in accordance with Section No. 3, paragraph 3.14 of the Division of Environmental Remediation's Draft DER-10 Technical Guidance for Site Investigation and Remediation, dated December 2002. A complete Remedial Investigation Report must be submitted for DEC review and approval according to the proposed implementation scheduled.
Remarks: LEAK IS AT SUBMERSIBLE PUMP

Material:

Site ID: 162739
Operable Unit ID: 1080018

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Operable Unit: 01
Material ID: 301801
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 162739
Spill Tank Test: 1547464
Tank Number: Not reported
Tank Size: 4000
Test Method: 01
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Petro-Tite/Petro Comp

UST:

Id/Status: 2-157937 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/29/2007
UTM X: 584600.19351999997
UTM Y: 4512741.9826100003
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5257
Affiliation Type: Facility Owner
Company Name: EXXONMOBIL OIL CORPORATION
Contact Type: OWNER'S AUTHORIZED AGENT
Contact Name: HEATHER GILMORE
Address1: 3225 GALLOWS RD.
Address2: Not reported
City: FAIRFAX
State: VA
Zip Code: 22037-0001
Country Code: 001
Phone: (703) 846-3000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 10/3/2007

Site Id: 5257
Affiliation Type: Mail Contact
Company Name: EXXONMOBIL OIL CORPORATION
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Contact Name: ERIC M. MCPHEE
Address1: % VEEDER-ROOT
Address2: 12265 W. BAYAUD AVE. #300
City: LAKEWOOD
State: CO
Zip Code: 80228
Country Code: 001
Phone: (303) 986-8011
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/21/2006

Site Id: 5257
Affiliation Type: On-Site Operator
Company Name: MOBIL R/S 12267
Contact Type: Not reported
Contact Name: STATION MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 563-0199
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 11/21/2005

Site Id: 5257
Affiliation Type: Emergency Contact
Company Name: EXXONMOBIL OIL CORPORATION
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HELP DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (800) 662-4567
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2/26/2007

Tank Info:

Tank Number: 001
Tank ID: 30308
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1972
Date Tank Closed: 11/01/1986
Registered: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 30309
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 30310
Tank Status: Closed - Removed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
B00 - Tank External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 30311
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Tank Number: 005
Tank ID: 30312
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

Tank Number: 006
Tank ID: 30313
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 30314
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 008
Tank ID: 30315
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 009
Tank ID: 30316
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 010
Tank ID: 30317
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number: 011
Tank ID: 30318
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 012
Tank ID: 30319
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 013
Tank ID: 30320
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1962
Date Tank Closed: 11/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 014

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Tank ID: 208980
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 11/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None

Tank Number: 100
Tank ID: 42022
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/04/2005
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 08/11/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None

Tank Number: 200
Tank ID: 42023
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/04/2005
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 08/11/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 300
Tank ID: 42024
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/04/2005
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 08/11/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None

Tank Number: 400
Tank ID: 42025
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/04/2005
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 08/11/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None

Tank Number: 500
Tank ID: 42026
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/04/2005
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 08/11/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 11/21/2005

Equipment Records:

K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B04 - Tank External Protection - Fiberglass
F06 - Pipe External Protection - Wrapped
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None

Tank Number: 600
Tank ID: 210102
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 280
Install Date: Not reported
Date Tank Closed: 11/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Last Modified: 02/21/2006

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

SPILLS:

Facility ID: 8806783
Facility Type: ER
DER Facility ID: 293016
Site ID: 59243
DEC Region: 2
Spill Date: 11/3/1988
Spill Number/Closed Date: 8806783 / 8/19/2013
Spill Cause: Housekeeping
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: MJHAGGER
Referred To: Not reported
Reported to Dept: 11/14/1988
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/18/1988
Spill Record Last Update: 11/26/2013
Spiller Name: FRANK MESSINA
Spiller Company: EXXONMOBIL CORP.
Spiller Address: 1545 ROUTE 22 EAST
Spiller City,St,Zip: ANNANDALE, NJ 08801
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo:

This spill site has been consolidated under spill no. 88-06783. PBS records indicate that 12 x 550 gallon and 1 x 4,000 gallon USTs closed or removed from this site. 3/7/2003: DEC's comments regarding a proposed Work Plan for On-Site and Off-Site Investigation by Roux Associates, dated April 30, 2003. Based on the results of our site visit on March 7, 2003, and evaluation of the proposal by Roux Associates, the DEC accepts ExxonMobil's Work Plan and Schedule to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

evaluate the on-site and off-site contamination at this location. Exxon-Mobil must now complete the implementation of the Work Plan according to the proposed schedule. The results of this investigation must be compiled into a Subsurface Investigation Report prepared in accordance with Section No. 3, paragraph 3.14 of the Division of Environmental Remediation's Draft DER-10 Technical Guidance for Site Investigation and Remediation, dated December 2002. A complete Remedial Investigation Report must be submitted for DEC review and approval according to the proposed implementation scheduled. (Sigona)8/4/2003: Site transferred from Sigona to Harrington (central office) for management. (Rommel)3/8/2004: Sent letter to Exxon Mobil approving the FS work plan. (Harrington)8/24/2004: Sent letter to Exxon Mobil approving the FS report and the SVE/AS pilot test report. Requested the submission of a CAP. (Harrington)10/8/2004: Approved CAP. Items included were the initiation of monthly EFR events at monitoring wells exhibiting free product, the submission of an RI work plan to finish delineation of subsurface contamination, submission of a RAP, and completion of quarterly groundwater sampling at all site-related monitoring wells. (Harrington)1/19/2005: Consent order is executed by the Regional Director. (Harrington)5/31/2005: Sent letters to Exxon Mobil approving the supplemental RI work plan and the RAP. RAP calls for installation of SVE/AS system and passive bailers to collect free product. (Harrington)9/12/2005: Sent letter to Exxon Mobil approving SVE/AS plan. Fieldwork for system installation is underway. (Harrington)11/1/2005: Station has been closed as per divestment effort. UST excavation is underway. (Harrington)12/1/2005: Sent letter to Exxon Mobil approving the supplemental RI report. SVE/AS system will be up and running by the spring of 2006. (Harrington)1/31/2006: SVE/AS system has been installed on-site. System is awaiting hook-up to electrical grid by Con-Ed. (Harrington)2/13/2006: Sent e-mail to Exxon Mobil approving the tank excavation assessment report. (Harrington)8/29/2006: Sent e-mail to Exxon Mobil approving the SVE/AS System Start-Up Report. AS system will remain inactive until levels of LPH have been substantially reduced. (Harrington)1/15/2007: Project management assumed by Bureau B. (Harrington)7/24/2007: Project re-assigned to Harrington. (Harrington)8/3/2007: PM visited site with Kleinfelder personnel (Mooney, Meyerhoefer). RAP was approved in Spring of 2007. Sale of property to Moinihan Group set for this Fall. Kleinfelder set to propose dismantling of SVE/AS system due to property transfer and subsequent excavation for new building foundation. (Harrington)8/21/2007: PM approved the shut-down of the SVE/AS system on-site. Construction activities are beginning at the site, which include excavation of the site property and demolition of buildings adjacent to the system compound. (Harrington)3/13/2008: PM conducts site visit with Fleming Lee Shue (FLS) personnel (environmental consultant to the developer - Moinihan Group). Site is to become a 56-story residential unit with basement parking and 1st floor commercial usage. Site takes up the entire block between West 42nd and West 43rd Streets from 11th Avenue west to the existing condo property and the Chinese embassy. Site demolition is complete. Excavation and de-watering activities are on-going. Excavation depth varies throughout the site, but ranges from 8-20' below grade. Contractors are using h-piles with timber stringers and tiebacks for sidewall bracing. Excavation in the area of the former station is @ ~8' bgs. FLS has proposed a modification to the RAP changing the approved excavation depth from 40' bgs to 20' bgs.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

(Harrington)3/14/2008: PM sends an e-mail to Fleming Lee Shue with comments on the proposed RAP modification. The Department is requiring further details regarding the confirmatory sampling program for both the excavation bottom and sidewalls, installation of new monitoring wells for post-remedial groundwater monitoring (as the old ones were demolished during excavation activities), copies of the de-watering plan and NYCDEP discharge permit, a construction schedule, and monthly progress reports with photos.

(Harrington)5/28/2008: PM conducts meeting with Fleming Lee Shue personnel (Matt Carroll). All Department comments regarding the revised RAP as noted above have been addressed to the satisfaction of the PM. PM approves the RAP. (Harrington)12/4/08 - Haggerty: assumed management from Dave Harrington1/16/09 - Haggerty: sent email approval for endpoint sampling results after excavation to the depth of the future building. Some minor semi-volatiles and metals but not enough to warrant further excavation. This is 1 parcel of a large Brownfield project. The remedy for this parcel consists of de-watering to depress the water table enough to excavate any contaminated soils.

April 2010 - Project is on hold while the next phase of work is re-bid

April 2011: spoke with consultant, they will be submitting a work plan to install soil borings on the sidewalk. Soil samples will be considered "excavation sidewall samples" since the previous excavation had sheeting install at the property boundary. MWs will also be installed

May 2011 - approved work plan for off-site MW installation, excavation sidewall samples via geoprobe sampling and collecting soil and gw samples in the area with a reported sheen at the bottom of the excavation

June 2011 - collected bottom samples and sidewall samples (via Geoprobe). Off-site MW's will be installed in July

July 2011 - Off-site wells installed 7/20 - 7/21

November 2011 - Report overdue

December 2011 - Spoke with Consultant, Fleming Lee Shue. RP has agreed to pay for the remainder of the off-site work

February 2012 - PM will contact the Fleming Lee Shue. They need to complete the off-site investigation before closure can be considered

April 2012 - no response from FLS

June 2012 - spoke with Michael Pisem from the Moinian Group who is developing the property. I gave him 60 days to install the off-site wells and provide the Dept. with the report or I would refer the Spill to OGC.

Fleming, Lee, Shue called and said they were authorized by Pisem to complete the investigation

December 2012 - still waiting on the report

May 2013 - Spoke with Arnie Fleming from FLS. They are the consultant and performed the Off-site investigation. The samples are clean he told me but his client, The Moinian Group, has not paid FLS so he will not submit the results

August 19, 2013 - Finally able to review the Off-Site Investigation Report after the consultant was paid. No contamination has migrated off-site. Since on-site was de-watered for several years for excavation and construction of in entire city block, all source material was removed and any residual groundwater contamination was remediated and documented. Spill closed

TANKS BEING REMOVED WHEN CONTAMINATED SOIL WAS DISCOVERED, SOIL BEING STOCKPILED & WILL BE REMOVED.

Remarks:

Material:

Site ID: 59243
Operable Unit ID: 923619
Operable Unit: 01
Material ID: 455126
Material Code: 0009
Material Name: Gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	True
Site ID:	59243
Operable Unit ID:	923619
Operable Unit:	01
Material ID:	2106606
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True

Tank Test:

AIRS (AFS):

Airs Minor Details:

EPA plant ID:	110001576660
Plant name:	MOBIL OIL-#17-QDL
Plant address:	561 11TH STREET NEW YORK, NY 10036
County:	NEW YORK
Region code:	02
Dunn & Bradst #:	Not reported
Air quality cntrl region:	043
Sic code:	5541
Sic code desc:	GASOLINE SERVICE STATIONS
North Am. industrial classf:	Not reported
NAIC code description:	Not reported
Default compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Default classification:	POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Govt facility:	ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR LOCAL GOVERNMENT
Current HPV:	Not reported

Historical Compliance Minor Sources:

State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1004
Air prog code hist file:	SIP SOURCE
State compliance status:	IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date:	1101
Air prog code hist file:	SIP SOURCE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS #QDL (Continued)

1000253419

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1102
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1103
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1104
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1201
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1202
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1203
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1204
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1301
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1302
Air prog code hist file: SIP SOURCE

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Hist compliance date: 1303
Air prog code hist file: SIP SOURCE

Compliance & Violation Data by Minor Sources:

Air program code: SIP SOURCE
Plant air program pollutant: VOLATILE ORGANIC COMPOUNDS
Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR
Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS
Def. attainment/non attnmnt: Not reported
Repeat violator date: Not reported
Turnover compliance: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CQ570
WNW
1/4-1/2
0.307 mi.
1623 ft.

TAX LOT 3
600 WEST 42ND ST
MANHATTAN, NY

NY LTANKS

S106970434
N/A

Site 1 of 3 in cluster CQ

Relative:
Lower

LTANKS:

Actual:
17 ft.

Site ID: 350711
Spill Number/Closed Date: 0505659 / 12/20/2005
Spill Date: 8/8/2005
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3101
Investigator: JMMOLOUD
Referred To: Not reported
Reported to Dept: 8/8/2005
CID: 409
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/8/2005
Spill Record Last Update: 12/20/2005
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN.
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: ARJUN PATNEY
Spiller Phone: (646) 265-3701
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 297186
DEC Memo:

Tanks will be removed as part of the Brownfields Project remediation on this site.Site is in BCP C231012. PBS Number 2-610030 Tanks discovered during remedial action at site with strong petroleum odors. Tanks to be removed during remediation and all soil at site to be removed to 20 feet bgs during MGP remediation. No free product observed in soil. Tanks sampled 8/10/2005 by RP, waiting for results. Moloughney 8/11/05Report submitted 11/10/05. Tanks closed on 8/25/05. 1,625 gallons water and product removed from five tanks. - JMM 8/21/05All impacted soil removed during BCP remediation. Spill closed. 12/20/05 - JMM

Remarks: FOUND TANKS THAT HAS A HYDROCARBON ODOR. THE TANKS ARE BEING REMOVED. FORMER MANUFACTURED GAS SITE. DEC IS ON SITE BUT NOT FOR THIS JOESPH MALOUGHNEY 518-8595335

Material:

Site ID: 350711
Operable Unit ID: 1108266
Operable Unit: 01
Material ID: 2098202
Material Code: 0064A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TAX LOT 3 (Continued)

S106970434

Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CQ571
WNW
1/4-1/2
0.310 mi.
1639 ft.

WEST 42ND STREET REDEVELOPMENT PROJECT
605/615 WEST 42ND STREET DEVELOPMENT
NEW YORK, NY 10036

NY BROWNFIELDS

S108984483
N/A

Site 2 of 3 in cluster CQ

Relative:
Lower

BROWNFIELDS:

Program: BCP
Site Code: 359250

Actual:
16 ft.

Site Description: The site is 0.346 acres, identified as tax Block 1090, Lot 23 and located in New York County (Manhattan). The site includes 605 West 42nd Street and 615 West 42nd Street and lies on the north side of West 42nd Street between 11th and 12th Avenues. The site included in the application consists of a three-story garage which is presently abandoned. It is now owned by the volunteer 605 West 42nd Owner LLC who acquired it from Verizon. Prior uses of the site were a coal and coke yard, a can manufacturer and a metal manufacturer. The Sanitary Automatic Candy Corporation and the New York Telephone Company have also occupied the current buildings. The surrounding parcels are currently used for a combination of commercial and residential purposes, such as United Parcel Service (UPS), the Riverbank West Apartment Tower, Mobil filling station (now closed), street-level parking lot and a New York City mounted patrol unit building. Contaminants which are known or suspected to affect soil, groundwater and/or soil gas are petroleum, petroleum related VOCs, SVOCs and metals. This site poses a significant threat to the public health as determined by NYSDOH. The Remedial Action Work Plan (RAWP) with Stipulations was approved by the Department on November 5, 2007. Remedial Construction started on December 10, 2007. Construction was halted in September 2008 due to contractual issues. Remedial Construction recommenced in October 2009 and was completed in the summer of 2010. Certificate of Completion issued December 17, 2010.

Env Problem: Previous investigations have revealed the following contamination: Elevated levels of volatile organic compounds (VOCs) including numerous exceedances of soil cleanup objectives (SCOs) in the vicinity of three closed in place USTs and the former gasoline dispenser; Elevated levels of semi-volatile organic compounds (SVOCs) including naphthalene were detected in samples in the vicinity of the closed in place USTs; Elevated levels of other SVOCs in shallow soil were attributed to the presence of historic fill; The types and concentrations of VOCs in the groundwater are indicative of petroleum contamination in the area of the USTs. There were exceedances of groundwater standards in samples from wells in the vicinity of the former gasoline dispenser and closed in place USTs; Soil gas analytical results revealed elevated concentrations of VOCs at all 14

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 42ND STREET REDEVELOPMENT PROJECT (Continued)

S108984483

sampling locations. Total VOC concentrations exceeded NYSDOH's background levels by up to 4 orders of magnitude. A Track 1 unrestricted use remedy was implemented on the site beginning in December 2007 and ending in June 2010. The remedial construction conformed with the requirements of a Part 375 track 1 cleanup and consisted of:1. Excavation and removal of soil/fill exceeding Track 1 SCOs; 2. Removal and treatment of contaminated groundwater by way of construction dewatering;3. Appropriate off-site disposal of all material from the site (solid and liquid) in accordance with all Federal, State and Local Rules and Regulations;4. Collection and analysis of end-point samples to ascertain achievement of Track 1 SCOs5. Implementation of a Soil Vapor Intrusion Monitoring Plan to establish a baseline for soil vapor along the southern offsite boundary of the Site to ensure there is no potential for soil vapor intrusion into new development, and post-remedial monitoring of groundwater and soil vapor along the southern (downgradient) Site boundary to evaluate the effectiveness of the remedy as it pertains to these media; 6.Import of materials to be used for backfill in compliance with: (1) chemical limits and other specifications and (2) all Federal, State and local rules and regulations for handling and transport of material; 7.Placement of a concrete cap and waterproofing system over the entire site to prevent recontamination of the site as part of the foundation elements for the proposed structure. 8.All responsibilities associated with the Remedial Action, including permitting requirements and pretreatment requirements, will be addressed in accordance with all applicable Federal, State and local rules and regulations.The draft Final Engineering Report was submitted in June 2010 and was finalized in December 2010. A Certificate of Completion was issued December 17, 2010.

Health Problem: Since contaminated soil at the site has been excavated down to bedrock and cleaned up to NYSDEC Part 375 Unrestricted use soil cleanup objectives, no institutional or engineering controls are necessary or will be implemented.

CQ572
WNW
1/4-1/2
0.310 mi.
1639 ft.

VERIZON
605 WEST 42ND ST
MANHATTAN, NY

NY LTANKS **S105055196**
N/A

Site 3 of 3 in cluster CQ

Relative:
Lower

LTANKS:

Actual:
16 ft.

Site ID: 129026
Spill Number/Closed Date: 0103392 / 6/25/2002
Spill Date: 6/28/2001
Spill Cause: Tank Failure
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 6/28/2001
CID: 211
Water Affected: Not reported
Spill Notifier: Responsible Party

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VERIZON (Continued)

S105055196

Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 6/28/2001
Spill Record Last Update: 6/25/2002
Spiller Name: JOHN QUATRALE
Spiller Company: VERIZON
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller County: 001
Spiller Contact: JOHN QUATRALE
Spiller Phone: (212) 338-7141
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 111264
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"CLEANED BY VERIZON.
Remarks: SOME PRODUCT WASHED DOWN DRAIN THAT LEADS TO SEWER - TANK FAILED ON
VEHICLE - MIROY CONTACTED FOR CLEAN UP

Material:

Site ID: 129026
Operable Unit ID: 842019
Operable Unit: 01
Material ID: 535479
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

573
NE
1/4-1/2
0.311 mi.
1643 ft.

346 WEST 48TH ST
346 WEST 48TH ST
MANHATTAN, NY

NY LTANKS S102672759
N/A

Relative:
Higher

LTANKS:
Site ID: 291396
Spill Number/Closed Date: 9413070 / 12/30/1994
Spill Date: 12/30/1994
Spill Cause: Tank Overfill
Spill Source: Unknown
Spill Class: Not reported
Cleanup Ceased: 12/30/1994
Cleanup Meets Standard: True
SWIS: 3101
Investigator: O'DOWD
Referred To: Not reported

Actual:
50 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

346 WEST 48TH ST (Continued)

S102672759

Reported to Dept: 12/30/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/31/1995
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 235949
DEC Memo: Not reported
Remarks: DRIVER WAS CALLED TO FILL UP TANK, THE TANK HAD ALREADY BEEN FILLED BY ANOTHER COMPANY, (UNKNOWN TO DRIVER)- GEMINI TRUCKING HAS PEOPLE ON THE WAY WITH SPEEDY DRY TO CLEAN UP . NO CALL BACK

Material:

Site ID: 291396
Operable Unit ID: 1010589
Operable Unit: 01
Material ID: 375350
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CR574
SE
1/4-1/2
0.312 mi.
1646 ft.
NATIONAL CAR RENTAL
252 WEST 40TH ST
MANHATTAN, NY
Site 1 of 3 in cluster CR

NY LTANKS **S106123829**
N/A

Relative:
Higher

LTANKS:

Actual:
47 ft.

Site ID: 262504
Spill Number/Closed Date: 9502512 / 9/5/2006
Spill Date: 5/30/1995
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: aaobliga
Referred To: Not reported
Reported to Dept: 5/30/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 6/7/1995
Spill Record Last Update: 9/5/2006
Spiller Name: Not reported
Spiller Company: NATIONAL CAR RENTAL/GM
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 225139
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"09/03/03Reassigned from Tibbe to Rommel.09/11/03Spoke to Chris Lochra EnecoTech. No free product at this time in wells.They have initiated the peroxide injections.A report will be generated toward the end of the year.10/29/03 - ANC Rental Corporation liable for this new spill.6/22/05-Vought-Received call Jed Smith (GES 303-861-2200x196) who is consultant for Realm (consultant for old spill number). GES does not work for national. Two different responsible parties USTs removed in late 2003 and new spill number issued.GM formerly owned National Car Rental prior to the merger with Alamo and Vanguard.See also Spill # 0308028 reported by American Envmtl removing two 1000 gallon tanks. American Environmental contracted by ANS Rental Corporation 200 South Andrews Avenue, 2nd Floor, Ft. Lauderdale, FLA 3330195 spill and 03 spill being handled by diffent RPs and consultants.RommelGM retained liability for this spill prior to merge with Alamo, Vanguard. 02/03/04Drilling scheduled 2/4/04.LBG, Ed DeStepanus 914-694-5711Rommel4/7/05-Vought-Spill transferred from Rommel to Vought as per Tang.6/23/05-Vought-Spoke to Jed Smith (GES 303-861-2200x196) who is consultant for Realm (former ownwer of site). USTs removed in late 2003. Report was sent to DEC on 2/15/05. Peroxide injections peformed in 2002-2003 and report recommended NFA. An additional copy will be sent for review. Sensitive receptor survey performed in 1999. A copy of sensitive receptor report, tank closure report and NFA request will be sent for review.8/1/05-Vought-See also closed spill #0308028. New file review by Vought:Final Results of Soil Investigation at 252 W. 40th Street-October 1995. Installation of sixteen soil borings. Bedrock encountered at 4' below grade in basement. Free phase product was observed in soil sample SB12-2[2-4'] and also in SB15-2[2-4']. Soil analyticals show: 310ppb MTBE(SB7-1 0-2'bg), 3000ppb MTBE(SB9-1 0-2'bg), 460ppb benzene(SB11-1 0-2'bg), 12400ppb xylene(SB11-1 0-2'bg), 7700ppb MTBE(SB12-1 0-2'bg), 980ppb benzene(SB12-2 2-4'bg),

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

4800ppb toluene(SB12-2 2-4'bg), 21400ppb xylene(SB12-2 2-4'bg), 25000ppb MTBE(SB12-2 2-4'bg), 1520ppb xylene(SB15-1 0-2'bg), 550ppb benzene(SB15-2 2-4'bg), 14000ppb ethylbenzene(SB15-2 2-4'bg), 4600ppb toluene(SB15-2 2-4'bg), 72000ppb xylene(SB15-2 2-4'bg). Subsurface Investigation for Underground Storage Tanks (EnecoTech 303-861-2200)-1/10/00. Installation of three soil borings around two (550-gallon) gasoline USTs. Three monitoring wells were advanced into bedrock. "Soil impacts appeared greatest adjacent to and downgradient of the dispenser. "EnecoTech is requesting that the site be closed under risk based corrective action criteria since no complete exposure pathways have been identified". Site is located within a parking garage and two USTs are in basement of garage. USTs were in bedrock. "The results of the survey indicated that none of the thirteen adjoining property occupants had complaints of vapors". Soil analyticals show no TAGM 4046 Required Soil Cleanup Objective exceedences. Groundwater analyticals show: 37ppb benzene(GW1), 18ppb toluene(GW1), 1270ppb ethylbenzene(GW1), 4095ppb xylene(GW1), 8.5ppb toluene(GW2), 91ppb ethylbenzene(GW2), 181ppb xylene(GW2), 109ppb benzene(GW3), 27600ppb MTBE(GW3). Phase I Additional Subsurface Investigation (EnecoTech)-January 2002. Installation of thirteen soil borings. "USTs are filled through street level fill pipes on the west side of the garage". "In its letter of June 11, 2001 the NYSDEC requested further soil and groundwater investigation at the site with emphasis being placed on the two areas where ENSR encountered free product..." Groundwater flow to the west/southwest. "EnecoTech recommends 1)installation of two monitoring wells for downgradient delineation 2)the injection of dilute hydrogen peroxide into the monitoring wells to enhance natural biodegradation". Soil analyticals show: 1655ppb MTBE(GP4), 8800ppb MTBE(GP12), 1540ppb xylene(GP13), 3560ppb xylene(GP13). Groundwater analyticals show: 120ppb benzene(GW1), 735ppb ethylbenzene(GW1), 1360ppb xylene(GW1), 73ppb MTBE(GW1), 1510ppb MTBE(GW3). Underground Storage Tank Closure Report (American Environmental)-November 2003. Removal of two (1000-gallon) gasoline USTs. Two dispenser islands were present (one on basement level and one on the first floor level of the garage). The fill box to the tanks was on West 40th Street. A total of 22 (55-gallon) drums of impacted soil was removed from the site. Soil excavation was limited due to the presence of a sewer line on the east side of the excavation and "the spatial constraints of maintaining an active facility on the north side of the excavation". Five endpoint soil samples were collected. 8/3/05-Continued file review by Vought:Underground Storage Tank Closure Report (American Environmental)-November 2003. Endpoints from UST excavation show: 6600ppb toluene(west wall 5'bg), 13000ppb xylene(West wall 5'bg), 3100ppb benzene(bottom 8'bg), 65000ppb toluene(bottom 8'bg), 38000ppb ethylbenzene(bottom 8'bg), 140000ppb xylene(bottom 8'bg), 10000ppb MTBE(bottom 8'bg).Phase II Investigation and Initial Corrective Action Report(Eneco Tech)-5/2/03. "Eneco Tech is proposing injection of dilute hydrogen peroxide solution at the facility in order to increase dissolved oxygen concentrations...". Installation of six monitoring wells and one injection well. Free product in GW-7. Groundwater flow to the southeast. Soil analyticals show: 1540ppb xylene(GP13), 3560ppb xylene(GP15), 1655ppb MTBE(GP4), 8800ppb MTBE(GP4). Groundwater analyticals show: 237ppb benzene(GW1), 974ppb ethylbenzene(GW1), 935ppb xylene(GW1), 44400ppb MTBE(GW1), 820ppb MTBE(GW3), 4360ppb MTBE(GW4), 9ppb benzene(GW5), 5ppb toluene(GW5), 19ppb ethylbenzene(GW5), 416ppb MTBE(GW5), 325ppb benzene(GW7),

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

1860ppb toluene(GW7), 1700ppb ethylbenzene(GW7), 13300ppb xylene(GW7), 2890ppb MTBE(GW7), 7ppb benzene(GW8), 12ppb ethylbenzene(GW8), 67ppb xylene(GW8), 510ppb MTBE(GW8), 12ppb xylene(GW9).Letter from DEC Sawyer to Roberta Barkman (Paul, Hastings, Janfosky and Walker LLP)-10/30/03. "The NYSDEC has received notification that petroleum contaminated soil was discovered at the above referenced site".Letter from Paul Hastings to DEC Sawyer-11/11/03. "This letter is to confirm our understanding that the Department of Environmental Conservation is flexible on the two week deadline contained in your October 30, 2003 letter to me".Letter from DEC Rommel to ANC Rental Corporation (Paula Rickborn)-12/8/03. Department reviewed UST Closure Report and requires additional investigation both onsite and offsite. Letter also required the installation of two monitoring wells in the "vicinity of the west wall soil sample and in the southwest corner, northwest of the floor drain". Report due to the DEC by 1/31/04. Letter from Leggette, Brashears and Graham(Destefanis) to ANC(Rickborn)-12/11/03. Proposal for installation of ten soil borings in vicinity of former UST location and preparation of a RAP. Letter from Paul Hastings to DEC Rommel-12/23/03. "...this letter is a request for an extension of the January 31, 2004 deadline for investigation and reporting..." Request to extend deadline to 3/31/04. Request due to coordination with General Motors (previous owner of site). General Motor's consultant is EnecoTech.Corrective Action Progress and Groundwater Sampling Report (Eneco Tech)-3/11/04. Application of hydrogen peroxide during six monthly site visits. Eleven monitoring wells onsite. "The dissolved oxygen measurements indicate that a general increase has been effected across the site , in particular in the vicinity of the former UST pit (GW-1) and along the south wall of the garage(W-7) where free product has been detected". "The application of hydrogen peroxide solution at a 10% concentration is scheduled for March and April". Depth to groundwater is 1-3' below grade and flow to the south. Groundwater analyticals show: 59ppb benzene(GW1), 72ppb ethylbenzene(GW1), 27ppb xylene(GW1), 2960ppb MTBE(GW1), 12ppb MTBE(GW3), dry well(GW4), 9ppb ethylbenzene(GW5), 11ppb MTBE(GW5), 13ppb benzene(GW7), 12ppb ethylbenzene(GW7), 726ppb xylene(GW7), 2360ppb MTBE(GW7), 76ppb benzene(GW8), 47ppb ethylbenzene(GW8), 1750ppb MTBE(GW8).Remedial Investigation Report (Leggette, Brashears and Graham)-March 2004. Consultant hired by National Environmental. Installation of two additional monitoring wells. Two samples were collected "for forensic analysis in order to determine approximate aging...". Groundwater flow to the east-southeast. Soil analyticals show:140ppb MTBE(GW10 4-8"). Groundwater analyticals show: 59ppb benzene(GW1), 72ppb ethylbenzene(GW1), 27ppb xylene(GW1), 2960ppb MTBE(GW1), 12ppb MTBE(GW3), 9ppb ethylbenzene(GW5), 11ppb MTBE(GW5), 13ppb benzene(GW7), 12ppb ethylbenzene(GW7), 726ppb xylene(GW7), 2360ppb MTBE(GW7), 76ppb benzene(GW8), 47ppb ethylbenzene(GW8), 1750ppb MTBE(GW8), 19ppb benzene(GW10), 16ppb ethylbenzene(GW10), 76ppb toluene(GW10), 97ppb xylene(GW10), 1700ppb MTBE(GW10), 35ppb benzene(GW11), 23ppb ethylbenzene(GW11), 91ppb toluene(GW11), 198ppb xylene(GW11), 390ppb MTBE(GW11).Corrective Action Progress and Groundwater Sampling Report (EnecoTech)-2/15/05. Application of dilute hydrogen peroxide during monthly site visits. Eleven monitoring wells onsite. Groundwater flow to the south-southeast. "The data show that oxygen levels have generally returned to those observed prior to the hydrogen peroxide treatments". "it would be expected that concentrations of STARS VOCs will continue to show a

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

decline toward the applicable New York Standards. Therefore regulatory closure of this site is requested". Groundwater analyticals show: 1.4ppb benzene(GW1), 15ppb ethylbenzene(GW1), 7ppb xylene(GW1), 55ppb MTBE(GW1), 10ppb benzene(GW7), 6ppb toluene(GW7), 49ppb ethylbenzene(GW7), 121ppb xylene(GW7), 470ppb MTBE(GW7), 36ppb benzene(GW8), 6ppb ethylbenzene(GW8), 908ppb MTBE(GW8), 10ppb benzene(GW10), 96ppb toluene(GW10), 25ppb ethylbenzene(GW10), 192ppb xylene(GW10), 291ppb MTBE(GW8), 40ppb benzene(GW11), 100ppb toluene(GW11), 37ppb ethylbenzene(GW11), 139ppb xylene(GW11), 333ppb MTBE(GW11).Letter from GES Jed Smith to DEC Vought-6/29/05. Sent copies of 2/15/05 sampling report, 5/04 remedial investigation report, 11/03 UST Closure Report and 1/00 request for closure. 8/5/05-Vought-After file review DEC requires: 1)continued monitoring to ensure conditions exist (DO concentrations) Vought called Smith (303-861-2200x196) and application of peroxide was performed in May 2004 and DO levels still capable of supporting MNA. If groundwater concentrations show continued decrease spill be closed.Letter should be sent to:David FaveroFavero Geosciences1210 South 5th StreetSuite 2Springfield, Ill. 62703Fax; 217-522-67278/9/05-Vought-Sent letter with above requirement.9/12/05- Obligado -FILE TRANSFERRED FROM VOUGHT TO OBLIGADO9/14/05- Obligado- Review letter from Paul Hastings Attorneys, dated 9/8/05, which requested that Spill #0308028 be combined with Spill #9502512. Called Roberta Barkman and informed her that the 03 spill number was already closed by DEC Vought on 8/1/05 and consolidated with previous 95 spill number.3/29/06 - Obligado - Called Smith (303-861-2200x196). He no longer works for company. Directed call to Joel Young (ext 144), left message to call DEC. 9/1/06 - Obligado - Review Corrective Action Progress and Ground Water Monitoring Report, dated May 18, 2006. Requests closure based on decreasing trends in most wells, source removal (USTs and dispensers) and sensitive receptor survey which found no complete exposure pathways. Max total VOCs is 3708 ppb in GW5 with 1106 BTEX and 1590 MTBE. 8 of the 11 wells show an overall decreasing trend. 2 of the 11 wells (MW5 and MW2) show increasing trend. 1 well (MW10) shows fluctuating trend. Will discuss closure with Joe Sun.9/5/06 - Obligado - After discussion with DEC Sun, issue NFA. Call Eric Harvey at GES (845) 878-8067, ext 20. Asked him if there were any plans to redevelop the site as residential. He said he was unaware of any redevelopment plans. The site is still a rental facility with a carwash. I Asked thim where to send the NFA letter. He said he will email the information.

Remarks: NOTIFIER DID SOIL TESTING AND FOUND CONTAMINATION 2 550 GAL TANKS BURIED ON SITE

Material:

Site ID: 262504
Operable Unit ID: 1013574
Operable Unit: 01
Material ID: 367572
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

Oxygenate: False

Tank Test:

Site ID: 276927
Spill Number/Closed Date: 0308028 / 8/1/2005
Spill Date: 10/29/2003
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: aaobliga
Referred To: Not reported
Reported to Dept: 10/29/2003
CID: 195
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/29/2003
Spill Record Last Update: 11/15/2005
Spiller Name: PAULA RICKBORN
Spiller Company: ANC RENTAL CORP
Spiller Address: 200 SOUTH ANDREWS AV
Spiller City,St,Zip: FORT LAUDERDALE, FL 33301-
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 225139
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"10/30/03 DDO Sawyer sent contaminated soil letter to:Roberta BarkmanHastings, Janofsky & Walker10th Floor1299 Pennsylvania AvenueWashington, DC 2000412/08/03Letter mailed to:Ms. Paula RickbornANC Rental Corporation200 South Andrews Avenue, 2nd FloorFort Lauderdale, Florida 33301H,J & W copiedAmerican Environmental Assessmen, Eric Meyn 631-586-2000 copiedLetter required that a subsurface investigation be performed to delineate the extent of petroleum contamination in the soil and groundwater, both on and off site. Assuming you will gain access to the existing monitoring well network (associated with Spill 9502512), two additional wells must be installed in the vicinity of the west wall soil sample and in the southwest corner, northwest of the floor drain. If you cannot access the existing wells, your investigation must include the installation of a minimum of three monitoring wells. A report summarizing the findings of the subsurface investigation including boring logs, well installation logs, soil and groundwater sample analyses, site plan, a surrounding property sketch including property layout and usage, and conclusions and recommendations must be submitted to the Department before January 31, 2003. Additional borings/monitoring wells may be

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL CAR RENTAL (Continued)

S106123829

Remarks: required by the Department upon review of the investigation report. Rommel 4/7/05 - Vought - Spill transferred from Rommel to Vought as per Tang. 8/1/05 - Vought - This spill closed and referred to open spill #9502512 at same location. 9/12/05 - File transferred from Vought to Obligado. 9/13/05 - Obligado - Receive fax from Paul Hastings Attorneys requesting spill #0308028 be consolidated with open spill #95020512. Call Roberta Barkman at Paul Hastings to inform her that the #0308028 spill was already closed by Vought on 8/1/05 and consolidated with the #95020512 spill number. Roberta asks for documentation and Obligado will send letter.

COMPANY REMOVING 2 1000 GAL TANKS FROM PROPERTY AND TANKS APPEAR TO HAVE BEEN LEAKING FOR UNDETERMINED AMOUNT OF TIME. CURRENTLY REMOVING CONCRETE ENCASEMENT AND CONCRETE SMELLS OF GASOLINE.

Material:

Site ID: 276927
Operable Unit ID: 876523
Operable Unit: 01
Material ID: 501549
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CR575
SE
1/4-1/2
0.314 mi.
1660 ft.

TANK TEST FAILURE TTF
250 WEST 40TH STREET
NEW YORK, NY

Site 2 of 3 in cluster CR

NY LTANKS S111738855
N/A

Relative:
Higher

Actual:
47 ft.

LTANKS:
Site ID: 461489
Spill Number/Closed Date: 1113493 / 6/21/2012
Spill Date: 3/1/2012
Spill Cause: Tank Test Failure
Spill Source: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/1/2012
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

TANK TEST FAILURE TTF (Continued)

S111738855

UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/1/2012
Spill Record Last Update: 6/21/2012
Spiller Name: NAFSHI REALTORS CORP - MORRIS FRANKEO
Spiller Company: UNKNOWN
Spiller Address: 250 WEST 40TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 999
Spiller Contact: NAFSHI REALTORS CORP - MORRIS FRANKEO
Spiller Phone: (718) 783-0202
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 415935
DEC Memo: 6/21/2012 Sangesland reviewed a letter/report from NYC Tank Testing (718-731-7011)Letter says after TTF, their company replaced the fill line, defective vent line and manhole gasket. There was no visible sign of contamination/spill.System was retested on 3/26/2012 and passed.
Remarks: 3000 g above ground tank pbs-2-606052

Material:

Site ID: 461489
Operable Unit ID: 1211575
Operable Unit: 01
Material ID: 2209389
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

576
WNW
1/4-1/2
0.316 mi.
1667 ft.

CON EDISON - WEST 42ND ST. GAS WORKS MGP
WEST 41ST - WEST 42ND STS.
MANHATTAN, NY 10018

EDR MGP 1008407966
N/A

**Relative:
Lower**

Manufactured Gas Plants:
No additional information available

**Actual:
17 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CS577
SW
1/4-1/2
0.321 mi.
1693 ft.
SPILL NUMBER 9003992
475 10TH AVE
NEW YORK CITY, NY
Site 1 of 2 in cluster CS

NY LTANKS
S100167935
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:

Site ID: 195041
Spill Number/Closed Date: 9003992 / 1/26/1996
Spill Date: 7/11/1990
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 7/11/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 7/11/1990
Spill Record Last Update: 1/12/2004
Spiller Name: Not reported
Spiller Company: GASETERIA
Spiller Address: 466 10TH AVENUE
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 162511
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL"07/11/90: DEC (SIGONA) RESPONDING WITH NYCDEP & NYCDF. Closed and cross referenced to spill #8909614. (JMR)
Remarks: SEEPAGE IN BASEMENT FROM EXISTING GASOLINE STATION LEAK CAUSING PEOPLE TO BECOME SICK.(SIGONA)

Material:

Site ID: 195041
Operable Unit ID: 944181
Operable Unit: 01
Material ID: 435111
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9003992 (Continued)

S100167935

Site ID: 195041
Operable Unit ID: 944181
Operable Unit: 01
Material ID: 435112
Material Code: 1850A
Material Name: VAPORS (PETROLEUM)
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

578
NNW
1/4-1/2
0.324 mi.
1710 ft.

BMW
547 WEST 47TH ST
MANHATTAN, NY

NY LTANKS S102660130
N/A

Relative:
Lower

LTANKS:

Actual:
27 ft.

Site ID: 87490
Spill Number/Closed Date: 9707785 / 10/1/1997
Spill Date: 10/1/1997
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 10/1/1997
CID: 322
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/1/1997
Spill Record Last Update: 1/26/1998
Spiller Name: Not reported
Spiller Company: QUAKER STATE
Spiller Address: 225 EAST JOHN CARPENTER FREEWAY
Spiller City,St,Zip: WAY IRVING, TX 75062
Spiller County: 001
Spiller Contact: ROBERT PORTEESE
Spiller Phone: (212) 586-2269
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 80160
DEC Memo: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BMW (Continued)

S102660130

Remarks: QUAKER STATE FILLING STORAGE TANK AND SEAM IN TANK BROKE CAUSING SPILL INSIDE DEALERSHIP - SPILL CONTAINED INSIDE WITHSPEEDI DRY AND BEING CLEANED UP

Material:

Site ID: 87490
Operable Unit ID: 1051036
Operable Unit: 01
Material ID: 329779
Material Code: 0021
Material Name: Transmission Fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 270
Units: Gallons
Recovered: 270
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CT579
West
1/4-1/2
0.325 mi.
1717 ft.

MICHAEL J QUIL DEPOT
525 11TH AVE
MANHATTAN, NY
Site 1 of 5 in cluster CT

NY LTANKS S104789577
NY Spills N/A

Relative:
Lower

LTANKS:

Actual:
19 ft.

Site ID: 139916
Spill Number/Closed Date: 8700318 / 4/10/1987
Spill Date: 2/27/1987
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 4/10/1987
Cleanup Meets Standard: True
SWIS: 3101
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 4/10/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/15/1987
Spill Record Last Update: 11/20/2003
Spiller Name: Not reported
Spiller Company: GREY HOUND BUS LINES
Spiller Address: 525 11TH AVENUE
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 119505
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "
Not reported
Remarks: REFERED TO FRANK RAMANO (NYCDEP).

Material:
Site ID: 139916
Operable Unit ID: 906199
Operable Unit: 01
Material ID: 470321
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 6
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 0007079
Facility Type: ER
DER Facility ID: 119505
Site ID: 139910
DEC Region: 2
Spill Date: 9/15/2000
Spill Number/Closed Date: 0007079 / 12/28/2000
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 9/15/2000
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/15/2000
Spill Record Last Update: 2/10/2004
Spiller Name: CALLER
Spiller Company: NEW YORK CITY TRANSIT AUT
Spiller Address: 370 JAY STREET
Spiller City,St,Zip: BROOKLYN, NY 11201-

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

Spiller Company: 001
Contact Name: JOSEPHINE BROWN
Contact Phone: (718) 243-4581
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"12/28/00 - ABOUT 50 GALLONS OF ANTIFREEZE SPILLED FROM BOILER
COOLING ROOM. NYCT CONTAINED AND CLEANED.
Remarks: mechanical failure with boiler system caused product to spill - less
than 1 gal of product did enter sewer

Material:
Site ID: 139910
Operable Unit ID: 829881
Operable Unit: 01
Material ID: 568979
Material Code: 0028A
Material Name: ETHYLENE GLYCOL
Case No.: 00107211
Material FA: Hazardous Material
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0205306
Facility Type: ER
DER Facility ID: 119505
Site ID: 139913
DEC Region: 2
Spill Date: 8/19/2002
Spill Number/Closed Date: 0205306 / 3/17/2004
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 8/20/2002
CID: 207
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/20/2002
Spill Record Last Update: 3/19/2004
Spiller Name: SAME
Spiller Company: NYC TRANSIT
Spiller Address: 370 JAY ST
Spiller City,St,Zip: BROOKLYN, ZZ

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

Spiller Company: 001
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE" Flex connector failed on discharge line for diesel tank 4. Product was contained by secondary and sump as confirmed by testing. Flex was replaced, primary and secondary were tested and passed Product was cleaned from sump.
Remarks: 2 oz spilled and cleaned up poss malfunction with #4 tank tank taken o/s
Not reported

Material:
Site ID: 139913
Operable Unit ID: 858009
Operable Unit: 01
Material ID: 519505
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0403977
Facility Type: ER
DER Facility ID: 119505
Site ID: 139915
DEC Region: 2
Spill Date: 7/14/2004
Spill Number/Closed Date: 0403977 / 6/27/2005
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 7/14/2004
CID: 405
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/14/2004
Spill Record Last Update: 6/27/2005
Spiller Name: JOSEPHINE BROWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

Spiller Company: NYCT
Spiller Address: 370 JAY STREET
Spiller City,St,Zip: BROOKLYN, NY 11201-
Spiller Company: 001
Contact Name: LENNY GELDMAN (FAC. MNGR)
Contact Phone: (347) 386-7457
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"06-27-05: 2 inches of product discovered in the piping sump of
diesel tank #2. Failure of a flex connector on the discharge line.
Product was contained in the secondary piping and relayed to the
sump. The line was repaired. Primary and secondary lines were tested
and passed. NYCT person onsite states that no petroleum contamination
was encountered during excavation too repair line.
Remarks: LEAK INTO A SUMP AREA, THINK IT IS A LEAKY PIPE, INVESTIGATING CAUSE,
SUMP BELONGS TO DEISEL NUMBER 2 TANK, SUMP AREA IS CONTAINED AND THEY
ARE GOING TO BE CLEANING IT UP, NOTHING WENT TO ENVIRONMENT

Material:
Site ID: 139915
Operable Unit ID: 887230
Operable Unit: 01
Material ID: 491527
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9902203
Facility Type: ER
DER Facility ID: 119505
Site ID: 139920
DEC Region: 2
Spill Date: 5/26/1999
Spill Number/Closed Date: 9902203 / 3/3/2003
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 5/26/1999
CID: 384
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/26/1999
Spill Record Last Update: 3/3/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: CALLER STATES THEY HAVE NO FURTHER INFORMATION AS TO WHAT HAPPENED.
FIRE DEPT HAS NOT ARRIVED ON SCENE YET.

Material:

Site ID: 139920
Operable Unit ID: 1076972
Operable Unit: 01
Material ID: 305714
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9902204
Facility Type: ER
DER Facility ID: 119505
Site ID: 139921
DEC Region: 2
Spill Date: 5/26/1999
Spill Number/Closed Date: 9902204 / 5/26/1999
Spill Cause: Equipment Failure
Spill Class: Known release that creates a file or hazard. DEC Response. Unknown
Responsible Party. Corrective action taken. (ISR)
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 5/26/1999
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MICHAEL J QUIL DEPOT (Continued)

S104789577

Date Entered In Computer: 5/26/1999
Spill Record Last Update: 5/26/1999
Spiller Name: UNK
Spiller Company: GREY HOUND BUS GARAGE
Spiller Address: 525 11TH AVE
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller Company: 001
Contact Name: UNK
Contact Phone: (000) 000-0000
DEC Memo: Not reported
Remarks: DIESEL FUEL LEAKING FROM A STORAGE TANK-APPROX UP TO 200 GALLONS FIRE
DEPT ON SCENE - REQ CALL BACK*****UPDATED REPORT NOW THAT
MATERIAL IS IN SEWER. See also spill 9902203

Material:

Site ID: 139921
Operable Unit ID: 1076974
Operable Unit: 01
Material ID: 556011
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

[Click this hyperlink](#) while viewing on your computer to access
additional NY_SPILL: detail in the EDR Site Report.

CT580
West
1/4-1/2
0.325 mi.
1717 ft.

MJ QUILL DEPOT -NYCT
523 11TH AVENUE
NEW YORK CITY, NY
Site 2 of 5 in cluster CT

NY LTANKS S101340929
N/A

Relative:
Lower

LTANKS:

Actual:
19 ft.

Site ID: 284908
Spill Number/Closed Date: 8904384 / Not Reported
Spill Date: 8/2/1989
Spill Cause: Tank Test Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: RVKETANI
Referred To: 102312 SSRPRD APPVD APPRVL LTR SENT
Reported to Dept: 8/2/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MJ QUILL DEPOT -NYCT (Continued)

S101340929

Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 5
Date Entered In Computer: 8/3/1989
Spill Record Last Update: 10/24/2012
Spiller Name: Not reported
Spiller Company: GREYHOUND BUS- NYCTA
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 231035
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"01/13/95: SPILL REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 01/13/95. TRANSFERED FROM HALE TO TIBBE ON 12/28/00. INVESTIGATION ONGOING. Formerly Greyhound. see also 9112032.11/12/10 - spill re-assigned from Tibbe to Joe O'Connell 5/19/2011 The spill was reassigned from Joe O'Connell to Linda Ross 2/27/12 - Raphael Ketani. The spill case was transferred to me during February 2012. Monthly progress meetings with the NYCT are taking place. 4/26/12 - Raphael Ketani. Groundwater monitoring and product collection are taking place by URS. 7/26/12 - Raphael Ketani. I was informed today by DER Region 2 staff that there may be comingled spills at the site. During 1983, there was a spill at the site from the USTs under a building. This was when the site was owned by Greyhound Lines Inc. Later, the NYCT bought the property. Then on March 8, 1993, the contractor Warren George was doing some work through the side walk for Con Ed and penetrated a feeder line. The line is right next to the building with the USTs. The loss of dielectric was later determined to be 4,000 gal. The location of the feeder penetration was at MW-3. I told staff that I would contact Gregory Mathelier of NYCT [(646) 252-3470/gregory.mathelier@nyct.com] and tell him to contact Mathew Madsen [(718) 267-3866/madsenm@coned.com] and Barry Cohen [(718) 204-4252/cohenb@coned.com] of Con Ed in order to coordinate the remediation of the spills. I sent an e-mail to Mr. Mathelier today with the above information and asked him to let me know whether he is successful in contacting Con Ed. I also attached the Con Ed feeder drawings and a few pages from the Greyhound report. 10/5/12 - Raphael Ketani. Today I received the Site Specific Remedial Plan and Design for Surfactant Flushing. I began my review. 10/22/12 - Raphael Ketani. I finished my review of the 10/5/12 SSRP/RD. Product was originally seen in wells URSMW-7 and URSMW-9 (southwest corner), which are in the diesel UST vault. Product has most consistently been seen in URS-3 (southwest corner). Product was seen as sheen 11 times at URSMW-11. Product has been present as a sheen to 0.01 feet at URSMW-12. In 2004, URS did 3 one well injections of BioSolve at URS-3 and recovered 33 gals. of product. Three more BioSolve injections into URS-3 during 2005 recovered 27 gals. of product. NYCT had 6 more monthly injections done at once a month from September 2005 to March 2006 and recovered 103 gals. of product. Groundwater sampling showed that there was no significant dissolving of the diesel fuel into the water due to the use of the surfactant. Also, the levels of the product at URS-3 were not significantly reduced. About 540 gals. of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MJ QUILL DEPOT -NYCT (Continued)

S101340929

Remarks:

RegenOx were injected into URSMW-13 as 3 injection events on 10/14/08, 12/17/08 to 12/18/08, and from 2/17/09 to 2/18/09. However, product was still found at URS-3. To determine the feasibility of using excavation as a remedial measure, 4 borings were done. These were GP-16 to GP-19 in the southwestern corner sidewalk. All 4 borings were penetrated fill. Only GP-17 had odors and staining. The petroleum impacts are likely adjacent to the foundation. The foundation goes down 14 feet below grade and has likely kept the product from migrating. The petroleum is in the smear zone and possibly beneath the asphalt at 12th Avenue and 40th Street. The NYCT determined that excavation was not practical for various reasons and the DEC did not require it. The SSRP was designed so reduce the impacts at URSMW-7 and URS-3. URSMW-11 will likely be used for the flushing. Six wells will be used in the program. They will be 4 inch wells. URSMW-15 to 18 will be installed. URSMW-18 will be used as a monitoring well. The other wells and URS-3, URSMW-7 and URSMW-13 will be used for injecting, flushing and extraction. A 3% solution of BioSolve will be injected at 5 gpm. About 133 gals. will be injected per well. URS-3, URSMW-7, URSMW-13 will be used as extraction/hydraulic control wells. The minimum residence time for the solution will be 12 hours following injection. A truck will be used to remove twice the volume injected. Groundwater sampling will take place every two weeks during the flusing program.I found the SSRP/RD to acceptable and drafted a letter for the review of Hassan Hussein, EE III of Unit C in DER Region 2.10/23/12 - Raphael Ketani. Mr. Hussein and I discussed the letter. He told me to send it out and I did.Later, Mr. Mathelier sent me an e-mail stating that the surfactant flushing could not take place this year due to contractural issues. He requested a postponement of the work until May 2013. I responded to his request by approving the postponement. CONTAINED IN CLAY SOIL. OIL IN GROUNDWATER WINSTON CONTRACTOR HIRED TO PUMP OIL OUT OF THE CONTAMINATION. (FACILITY SOLD TO MATA/NYCTA)

Material:

Site ID: 284908
Operable Unit ID: 929653
Operable Unit: 01
Material ID: 448439
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 500
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 284908
Operable Unit ID: 929653
Operable Unit: 01
Material ID: 448438
Material Code: 0015
Material Name: Motor Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MJ QUILL DEPOT -NYCT (Continued)

S101340929

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CT581
West
1/4-1/2
0.325 mi.
1718 ft.

CLOSED-LACKOF RECENT INFO
525 NORTH 11TH AVENUE
NEW YORK CITY, NY
Site 3 of 5 in cluster CT

NY LTANKS
NY Spills

S102144972
N/A

Relative:
Lower

Actual:
19 ft.

LTANKS:

Site ID: 167799
Spill Number/Closed Date: 9101412 / 3/7/2003
Spill Date: 5/3/1991
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported

Cleanup Meets Standard: False

SWIS: 3101

Investigator: ADMIN. CLOSED

Referred To: Not reported

Reported to Dept: 5/3/1991

CID: Not reported

Water Affected: Not reported

Spill Notifier: Tank Tester

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: False

Remediation Phase: 0

Date Entered In Computer: 5/8/1991

Spill Record Last Update: 3/7/2003

Spiller Name: Not reported

Spiller Company: GREYHOUND

Spiller Address: Not reported

Spiller City,St,Zip: ZZ

Spiller County: 001

Spiller Contact: Not reported

Spiller Phone: Not reported

Spiller Extention: Not reported

DEC Region: 2

DER Facility ID: 141361

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ADMIN.CLOSED"03/07/2003 Closed Due To The Nature / Extent Of The
Spill Report

Remarks: 5K TANK FAILED TEST,NO ACTION YET DETERMINED.CLOSED DUE TO LACK OF
ANY RECENT INFO-DOES NOT MEET ANY CLEANUP REQUIREMENTS.

Material:

Site ID: 167799

Operable Unit ID: 952603

Operable Unit: 01

Material ID: 427523

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLOSED-LACKOF RECENT INFO (Continued)

S102144972

Material Code: 0043A
Material Name: ANTIFREEZE
Case No.: Not reported
Material FA: Other
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 167799
Spill Tank Test: 1538529
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

SPILLS:

Facility ID: 8710939
Facility Type: ER
DER Facility ID: 284734
Site ID: 139917
DEC Region: 2
Spill Date: 3/31/1988
Spill Number/Closed Date: 8710939 / 4/4/1988
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 3101
Investigator: JCGRATHW
Referred To: Not reported
Reported to Dept: 3/31/1988
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Federal Government
Cleanup Ceased: 4/4/1988
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/31/1988
Spill Record Last Update: 7/13/1988
Spiller Name: Not reported
Spiller Company: GREYHOUND
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLOSED-LACKOF RECENT INFO (Continued)

S102144972

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GRATHWOL"

Remarks: BUS RAN OVER FUEL PUMP, APPROXIMATELY 700 GALLONS ENTERED SANITARY (STORM) SEWER, USCG MAY SEND TEAM, FIRE DEPT NOTIFIED, SPILLER TO HIRECLEAN UP CONTRACTOR.

Material:

Site ID: 139917

Operable Unit ID: 915699

Operable Unit: 01

Material ID: 568037

Material Code: 0008

Material Name: Diesel

Case No.: Not reported

Material FA: Petroleum

Quantity: 1200

Units: Gallons

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

CT582
West
1/4-1/2
0.325 mi.
1718 ft.

UNITED PARCEL SERVICE
525 11TH AVE
NEW YORK, NY 10018

Site 4 of 5 in cluster CT

NY LTANKS
NY MANIFEST
NY Spills

S107521565
N/A

Relative:
Lower

Actual:
19 ft.

LTANKS:

Site ID: 337568

Spill Number/Closed Date: 0412183 / 2/22/2005

Spill Date: 2/15/2005

Spill Cause: Tank Test Failure

Spill Source: Institutional, Educational, Gov., Other

Spill Class: Not reported

Cleanup Ceased: Not reported

Cleanup Meets Standard: False

SWIS: 3101

Investigator: MCTIBBE

Referred To: Not reported

Reported to Dept: 2/15/2005

CID: 444

Water Affected: Not reported

Spill Notifier: Responsible Party

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: True

Remediation Phase: 0

Date Entered In Computer: 2/15/2005

Spill Record Last Update: 2/22/2005

Spiller Name: JOSEPHINE BROWN

Spiller Company: MICHEAL J QUILL DEPOT

Spiller Address: 525 11TH AVE

Spiller City,St,Zip: NEW YORK, NY

Spiller County: 001

Spiller Contact: JOSEPHINE BROWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

Spiller Phone: (646) 208-0326
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 272897
DEC Memo: 02-22-05: NYCT was performing an overfill test of one of their diesel tanks to ensure that the Veeder-Root probe was operating correctly. When the truck hose was removed from the fill line, approximately 5 gallons spilled in the overfill bucket. The spill was contained by the bucket and clean by NYCT.
Remarks: THEY FOUND PIPE LEAKINGH ABOVE GROUND AT THIS SITE

Material:
Site ID: 337568
Operable Unit ID: 1099521
Operable Unit: 01
Material ID: 579860
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

NY MANIFEST:
EPA ID: NYD986903003
Country: USA

Mailing Info:
Name: UNITED PARCEL SERVICE
Contact: JESUS RIVERA
Address: 525 11TH AVE
City/State/Zip: NEW YORK, NY 10018
Country: USA
Phone: 212-560-6228

NY MANIFEST:
No Manifest Records Available

SPILLS:
Facility ID: 0607248
Facility Type: ER
DER Facility ID: 272897
Site ID: 370792
DEC Region: 2
Spill Date: 9/25/2006
Spill Number/Closed Date: 0607248 / 9/26/2006
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 9/25/2006
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/25/2006
Spill Record Last Update: 9/26/2006
Spiller Name: OLUCHI DUROHA
Spiller Company: MICHEAL J QUILL DEPOT
Spiller Address: 525 11TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: OLUCHI DUROHA
Contact Phone: (646) 252-5777
DEC Memo: minor spill contained in boiler roomall cleaned up
Remarks: IT WAS FOUND IN BOILER ROOM AND IS ALL CLEANED UP: UNSURE WHERE CAME FROM

Material:
Site ID: 370792
Operable Unit ID: 1128579
Operable Unit: 01
Material ID: 2118199
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0204089
Facility Type: ER
DER Facility ID: 275647
Site ID: 139912
DEC Region: 2
Spill Date: 7/19/2002
Spill Number/Closed Date: 0204089 / 3/17/2004
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

Referred To: Not reported
Reported to Dept: 7/19/2002
CID: 365
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/19/2002
Spill Record Last Update: 3/19/2004
Spiller Name: CALLER
Spiller Company: NYC TRANSIT
Spiller Address: 370 JAY ST
Spiller City,St,Zip: BROOKLYN, NY 11201-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: (718) 243-4581
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"Flex connector failed on discharge line for diesel tank 1.
Product was contained in the secondary and sump as confirmed by
testing. Flex was replaced, primary and secondary retested and
passed. Product cleaned from sump.

Remarks: PRIMARY LINE ON TANK 1 HAS FAILED - SPILLED TO SUMP AREA - CLEAN UP
IN PROGRESS

Material:

Site ID: 139912
Operable Unit ID: 856896
Operable Unit: 01
Material ID: 518348
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 3
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0513755
Facility Type: ER
DER Facility ID: 272897
Site ID: 360290
DEC Region: 2
Spill Date: 3/1/2006
Spill Number/Closed Date: 0513755 / 3/2/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 3/1/2006
CID: 444
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/1/2006
Spill Record Last Update: 3/2/2006
Spiller Name: CLAIRE SANNON
Spiller Company: BUS DEPOT
Spiller Address: 525 11TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: CLAIRE SANNON
Contact Phone: (718) 243-4581
DEC Memo: minor spill closed
Remarks: leaked from a bus and has been cleaned up:

Material:

Site ID: 360290
Operable Unit ID: 1117466
Operable Unit: 01
Material ID: 2107978
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9112032
Facility Type: ER
DER Facility ID: 275647
Site ID: 139918
DEC Region: 2
Spill Date: 2/23/1992
Spill Number/Closed Date: 9112032 / 2/3/2004
Spill Cause: Equipment Failure
Spill Class: c4
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2/24/1992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2/28/1992
Spill Record Last Update: 2/10/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"10/10/95: This is additional information about material spilled from the translation of the old spill file: #2 DIESEL.refer to 8904384.
Remarks: CHECK VALVE FAILURE. CONTAINED ON CONCRETE FLOOR OF PUMP ROOM. TANKS-A-LOT VAC TRUCK USED. SORBENT APPLIED. CLEAN VENTURES TO HAUL SORBENT AWAY.

Material:
Site ID: 139918
Operable Unit ID: 962199
Operable Unit: 01
Material ID: 417022
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 700
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0511268
Facility Type: ER
DER Facility ID: 272897
Site ID: 357386
DEC Region: 2
Spill Date: 12/28/2005
Spill Number/Closed Date: 0511268 / 12/30/2005
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED PARCEL SERVICE (Continued)

S107521565

Referred To: Not reported
Reported to Dept: 12/28/2005
CID: 408
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/28/2005
Spill Record Last Update: 12/30/2005
Spiller Name: SHERRY BULKLEY
Spiller Company: NYC TRANSIT YUKON DEPOT
Spiller Address: 2 BROADWAY 27TH FLOOR
Spiller City,St,Zip: NEW YORK CITY, NY 10004
Spiller Company: 001
Contact Name: SHERRY BULKLEY
Contact Phone: (646) 252-5777
DEC Memo: Tibbe says OK to close.All contained in the tank room.
Remarks: DUE TO A MALFUNCTION FOR THE OVERFILL ALARM. ALL IN BASEMENT BUT NONE AT FILL PORTS. CONTAINED, AND CLEANED UP BY DEPOT PERSONNEL.

Material:

Site ID: 357386
Operable Unit ID: 1114660
Operable Unit: 01
Material ID: 2104728
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 24
Units: Gallons
Recovered: 24
Resource Affected: Not reported
Oxygenate: False

Tank Test:

[Click this hyperlink](#) while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

CR583
SE
1/4-1/2
0.328 mi.
1734 ft.
SPILL NUMBER 0008894
236 W. 40TH ST
MANHATTAN, NY
Site 3 of 3 in cluster CR

NY LTANKS **S104877129**
N/A

Relative:
Higher

LTANKS:
Site ID: 134201
Spill Number/Closed Date: 0008894 / 3/18/2003
Spill Date: 10/31/2000
Spill Cause: Tank Overfill
Spill Source: Tank Truck

Actual:
47 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0008894 (Continued)

S104877129

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SACCACIO
Referred To: Not reported
Reported to Dept: 10/31/2000
CID: 233
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/31/2000
Spill Record Last Update: 3/18/2003
Spiller Name: Not reported
Spiller Company: OIL CO. UNK
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 115315
DEC Memo: Not reported
Remarks: appears that oil company overfilled the tank in basement fd is on
scene spill is contained in basement no call back needed

Material:
Site ID: 134201
Operable Unit ID: 831327
Operable Unit: 01
Material ID: 546394
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CU584
ESE
1/4-1/2
0.329 mi.
1735 ft.
NEW YORK TIMES CO
229 W 43 ST
NEW YORK, NY 10036
Site 1 of 2 in cluster CU

CERC-NFRAP
RCRA-SQG
1015735593
NYD001315613

Relative:
Higher

CERC-NFRAP:
Site ID: 0203350
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Actual:
50 ft.

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: NEW YORK TIMES CO
Alias Address: Not reported
NY

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY
Date Started: / /
Date Completed: 08/24/90
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 06/27/91
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: 04/01/91
Date Completed: 06/27/91
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

RCRA-SQG:

Date form received by agency: 08/29/2008
Facility name: TIMES SQUARE BUILDING
Facility address: 229 W 43RD ST 10TH FLOOR
NEW YORK, NY 10036
EPA ID: NYD001315613
Mailing address: W 43RD ST 10TH FLOOR
NEW YORK, NY 10036
Contact: PAZ KASPI
Contact address: W 43RD ST 10TH FLOOR
NEW YORK, NY 10036
Contact country: US
Contact telephone: (212) 205-1400
Contact email: PAZ@AFRICAISRAEL.US
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES CO (Continued)

1015735593

Owner/operator name: NEW YORK TIMES CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AL 229 W 43 ST PROP OWNERS LLC
Owner/operator address: Not reported
Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/26/2008
Owner/Op end date: Not reported

Owner/operator name: NEW YORK TIMES CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AFI USA
Owner/operator address: Not reported
Not reported

Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/26/2008
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: Yes
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
Used oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES CO (Continued)

1015735593

Historical Generators:

Date form received by agency: 01/01/2007
Site name: NEW YORK TIMES CO
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NEW YORK TIMES CO
Classification: Not a generator, verified

Date form received by agency: 03/08/1982
Site name: NEW YORK TIMES CO
Classification: Unverified

Hazardous Waste Summary:

Waste code: D008
Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/23/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

CU585
ESE
1/4-1/2
0.329 mi.
1739 ft.

NEW YORK TIMES CO.
229 W 431ST STREET
NEW YORK, NY 10036
Site 2 of 2 in cluster CU

NY HSWDS **S108146777**
N/A

Relative:
Higher

Actual:
50 ft.

HSWDS:

Facility ID: Not reported
Region: 2
Facility Status: Unknown
Owner Type: Puplic
Owner: New York Times Co.
Owner Address: 229 West 431st St.
Owner Phone: (212)556-1103
Operator Type: Puplic
Operator: Fried George, Newsprint MGR.
Operator: Fried George, Newsprint MGR.
Operator Phone: Unknown
EPA ID: NYD001315613
Registry: Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID: None
RCRA Permitted: Unknown
Site Code: Industrial Site
Owner City State: NYC, NY 10036
Operator City State: Not reported
Quadrangle: Unknown
Latitude: Unknown
Longitude: Unknown
Acres: 0.00
Operator Date: Unknown
Close Date: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES CO. (Continued)

S108146777

Completed:	PA
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Waste
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	EPTox
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Public
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Access:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

NEW YORK TIMES CO. (Continued)

S108146777

Waste: Not reported

586
SSW
1/4-1/2
0.336 mi.
1773 ft.

360 W 36TH ST
360 W 36TH ST
MANHATTAN, NY

NY LTANKS

S102662880
N/A

Relative:
Higher

LTANKS:

Actual:
39 ft.

Site ID: 189809
Spill Number/Closed Date: 9614241 / 3/7/1997
Spill Date: 3/7/1997
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 3/7/1997
CID: 322
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/7/1997
Spill Record Last Update: 3/11/1997
Spiller Name: MIKE HELFONT
Spiller Company: MYSTIC TRANSPORT
Spiller Address: 1901 STEINWAY ST
Spiller City,St,Zip: ASTORIA, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 158391
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MARTINKAT"
Remarks: DRIVER OVERFILLED TANK - SPILL IS CONTAINED AND SPILL CREW ONWAY TO
CLEAN UP -EXPECT TO RECOVER ALL PRODUCT

Material:

Site ID: 189809
Operable Unit ID: 1041746
Operable Unit: 01
Material ID: 339343
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

360 W 36TH ST (Continued)

S102662880

Recovered: 10
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CT587
West
1/4-1/2
0.338 mi.
1783 ft.

608 W 40 ST - MAN
608 W.40TH ST
MANHATTAN, NY
Site 5 of 5 in cluster CT

NY LTANKS **S102671470**
N/A

Relative:
Lower

Actual:
18 ft.

LTANKS:
Site ID: 168315
Spill Number/Closed Date: 8909404 / 10/16/1997
Spill Date: 12/27/1989
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: FINGER
Referred To: Not reported
Reported to Dept: 12/28/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/28/1989
Spill Record Last Update: 1/6/2003
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 141794
DEC Memo: Not reported
Remarks: CUSTOMER ORDERED 2K GALS - TK OVERFILL @ 1.2K - ESCAPE FROM VENT - MY-STIC SENDS CLEANUP CREW, BUT CUSTOMER HAD ALREADY HOSED DOWN SPILL & SPREAD OVER LARGE AREA - NY SANIT PUTS DOWN SAND

Material:
Site ID: 168315
Operable Unit ID: 934328
Operable Unit: 01
Material ID: 564985
Material Code: 0002A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

608 W 40 ST - MAN (Continued)

S102671470

Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CV588
ENE
1/4-1/2
0.338 mi.
1786 ft.

**ENGINE CO. 054 FDNY -DDC
782 8TH AVENUE
MANHATTAN, NY
Site 1 of 2 in cluster CV**

**NY LTANKS
NY Spills**

**S103823997
N/A**

**Relative:
Higher**

LTANKS:

**Actual:
49 ft.**

Site ID: 232355
Spill Number/Closed Date: 9812690 / 6/6/2005
Spill Date: 1/14/1999
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: ADZHITOM
Referred To: Not reported
Reported to Dept: 1/14/1999
CID: 252
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1/14/1999
Spill Record Last Update: 6/6/2005
Spiller Name: UNK
Spiller Company: NYC FIRE DEPT ENG CO 54
Spiller Address: 782 8TH AVE
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller County: 001
Spiller Contact: UNK
Spiller Phone: (000) 000-0000
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 191487
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHITOMIRSKY"INVESTIGATION IS BEING PERFORMED BY LIRO/TYREE 1/15/986-6-2005 Reviewed groundwater monitoring results submitted by URS and received on March 14, 2005. The latest groundwater sampling results showed that there is no dissolved phase groundwater contamination at the site. Spill was closed based on this

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 054 FDNY -DDC (Continued)

S103823997

Remarks: information. AZ
SOIL CONTAMINATION DISCOVERED AFTER BORING SAMPLES WERE TAKENTANKS
HAVE BEEN ABANDONED.

Material:

Site ID: 232355
Operable Unit ID: 1069947
Operable Unit: 01
Material ID: 312972
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 232355
Operable Unit ID: 1069947
Operable Unit: 01
Material ID: 312971
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 1310132
Facility Type: ER
DER Facility ID: 445981
Site ID: 490962
DEC Region: 2
Spill Date: 1/17/2014
Spill Number/Closed Date: 1310132 / 1/21/2014
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3101
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 1/17/2014
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ENGINE CO. 054 FDNY -DDC (Continued)

S103823997

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/17/2014
Spill Record Last Update: 1/24/2014
Spiller Name: DISPATCH 282
Spiller Company: FDNY HAS THE INFO
Spiller Address: 782 8TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 999
Contact Name: DISPATCH 282
Contact Phone: (212) 628-2900
DEC Memo: 01/17/14-Zhune spoke to Victor Gressau from DEP (917-769-4005. He said the fire house had a oil delivery and the tank overfilled. Oil came out by the vent pipe and went onto the sidewalk and approximately 10 gallons into a Con-Ed manhole. Victor also said that the FF did not give him the oil company information and also they did not give him the Fire House pone #. As per Victor the Fire Department cleaned the spill. Spill closed.

Remarks: Spill at the firehouse. Spilled to ConEd manhole. Cleanup pending.

Material:

Site ID: 490962
Operable Unit ID: 1240512
Operable Unit: 01
Material ID: 2240711
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**CS589
SW
1/4-1/2
0.339 mi.
1788 ft.**

**BP AMOCO
466 10TH AVE
NEW YORK, NY**

Site 2 of 2 in cluster CS

**NY LTANKS
NY MANIFEST
NY Spills**

**S100167794
N/A**

**Relative:
Higher**

LTANKS:

Site ID: 205589
Spill Number/Closed Date: 0301220 / 12/17/2003
Spill Date: 5/3/2003
Spill Cause: Tank Overfill
Spill Source: Gasoline Station
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported

**Actual:
40 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Reported to Dept: 5/3/2003
CID: 281
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 5/3/2003
Spill Record Last Update: 12/17/2003
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: PAUL SKRYJA
Spiller Phone: (443) 310-2099
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 170710
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"5/5/2003-Vought-Called Paula Skryja and spill occurred on 5/3 am. Ten gallons came out of fill port and onto concrete surface. No sewers or drains affected due to immediate placement of spill boom. Spill cleaned using speedy dry which was recovered.12/17/2003-Vought-See spill 8909614 at same location. This spill closed due to existing gasoline contamination remediated under 8909614.
Remarks: Tank overfill during delivery at above location. Cleanup is in progress and further investigation into cause is pending.

Material:
Site ID: 205589
Operable Unit ID: 867611
Operable Unit: 01
Material ID: 509276
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

NY MANIFEST:
EPA ID: NYR000126714
Country: USA

Mailing Info:
Name: BP PRODUCTS - AMOCO 48501NY
Contact: N/S

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Address: PO BOX 80249
City/State/Zip: RANCHO SANTA MARGARITA, CA 92688
Country: USA
Phone: 949-460-5200

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID: 0206783
Facility Type: ER
DER Facility ID: 170710
Site ID: 205588
DEC Region: 2
Spill Date: 8/27/2002
Spill Number/Closed Date: 0206783 / 10/17/2003
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 10/1/2002
CID: 198
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/1/2002
Spill Record Last Update: 10/17/2003
Spiller Name: Not reported
Spiller Company: GASETERIA
Spiller Address: 466 10TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: DAVID GREFFENIUS
Contact Phone: (914) 765-8172
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ROMMEL"10/17/2003-Vought-see spill #8909614 at same location. This
spill closed by Vought.

Remarks: SOIL AND GROUNDWATER TESTING RESULTED IN FINDING CONTAMINATION IN
SOIL AND THE GROUNDWATER. OWNER OF STATION NOTIFIED.

Material:

Site ID: 205588
Operable Unit ID: 858549
Operable Unit: 01
Material ID: 517378
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9606785
Facility Type: ER
DER Facility ID: 170710
Site ID: 205592
DEC Region: 2
Spill Date: 8/27/1996
Spill Number/Closed Date: 9606785 / 10/17/2003
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 8/27/1996
CID: 312
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/27/1996
Spill Record Last Update: 10/17/2003
Spiller Name: Not reported
Spiller Company: GASETERIA
Spiller Address: 466 10TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ROMMEL"10/17/2003-Vought-See spill #8909614 at same location. This
spill closed by Vought.

Remarks: same occurrence everyday - gas odor any time of the day

Material:
Site ID: 205592
Operable Unit ID: 1034576
Operable Unit: 01
Material ID: 346056
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0301287
Facility Type: ER
DER Facility ID: 170710
Site ID: 205590
DEC Region: 2
Spill Date: 5/2/2003
Spill Number/Closed Date: 0301287 / 5/6/2003
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 5/5/2003
CID: 266
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/5/2003
Spill Record Last Update: 10/17/2003
Spiller Name: Not reported
Spiller Company: BP PRODUCTS NORTH AMERICA
Spiller Address: 1 W PENNSYLVANIA AVENUE
Spiller City,St,Zip: TOWSON, MD 21204-
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"VOUGHT"5/6/2003-Vought-See spill #0301220 at same location reported
by BP Amoco. This spill closed by Vought.
Remarks: TANK OVERFILL DUE TO DRIVER ERROR. SPILLED ONTO CONCRETE AND ASPHALT.
CLEANED UP BY NEW YORK CITY FIRE DEPARTMENT.

Material:
Site ID: 205590
Operable Unit ID: 867677
Operable Unit: 01
Material ID: 505782
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Units: Gallons
Recovered: 20
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 8909614
Facility Type: ER
DER Facility ID: 170710
Site ID: 205591
DEC Region: 2
Spill Date: 1/4/1990
Spill Number/Closed Date: 8909614 / 6/14/2010
Spill Cause: Unknown
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: aaobliga
Referred To: NFA
Reported to Dept: 1/5/1990
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: DEC
Cleanup Ceased: 11/24/2003
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 1/17/1990
Spill Record Last Update: 6/14/2010
Spiller Name: OSCAR PORCELLI
Spiller Company: GASETERIA OIL CORP
Spiller Address: 364 MASPETH AVENUE
Spiller City,St,Zip: BROOKLYN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"01/05/90: (6) MONITORING WELLS INSTALLED,OIL TANKS BEING TESTED BY CONTRACTORS(TRINITY & FENLEY & NICOL), ALL TANKS PUMPED & CLEANED, REPAIRING WATER MAIN.10/10/2003-Vought-Spoke with LaJuana Smith (works for Clinton Housing-212-967-1644) and she is looking to resolve spill). In Nov 1996 DEC required further work from DEC. Ms Smith will call back on Wed for current site status and will possibly submit FOIL request upon her discussion with bank.10/17/2003-Vought-File review by Vought:Community Board 4 Meeting Notice-2/21/90-Meeting held with DEC, NYFD, NYPD, DCA and NYCDEP to discuss current status and plans of site.Fax to DEC from Gaseteria-2/22/90-Pedneault Associates (516-467-8477)-Groundwater analyticals from six monitoring wells and two soil disposal piles (no site plan in file). Groundwater analyticals show 275ppb benzene(W1), 341ppb benzene(W2), 327ppb benzene(W3), 448ppb benzene(W4), 158ppb benzene(W5) and 128ppb benzene(w6). Disposal samples show 1433ppb

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

benzene(east pile) and 188ppb benzene(west pile).Groundwater analyticals-5/21/90-Pedneault Associates-Groundwater analyticals from six monitoring wells (no site plan in file). Groundwater analyticals show 2308ppb benzene(W1), 1091ppb benzene(W2), 680ppb benzene(W3), 385ppb benzene(W4), 736ppb benzene(W5) and 810ppb benzene(w6). Subsurface Investigation-7/90-Environmental Management Services. "In Jan 1990 a subsurface water line broke beneath 10th avenue near the northwest side of the site. Water entered the basement of the adjoining building along with some gasoline." DEC required installation of six monitoring wells on Gaseteria property. Gasoline vapors detected in sewers in building across 10th Avenue. This subsurface investigation consisted of eight soil borings and installation of two additional monitoring wells. Three pump islands serviced by 12 (550-gallon) gasoline USTs and one (2000-gallon) diesel UST. Local topography slopes to the north. Groundwater at depth of 7-9' below grade. Bedrock is 7-11' below grade and slopes downward toward the northwest and southwest corners of site. Groundwater "suspected to flow northward". All wells onsite were set "firmly on bedrock" and "there is not sufficient information available to determine specific groundwater flow". No free product detected in wells. Groundwater appears to flow from 10th Ave towards the USTs. Report recommends groundwater monitoring with possible additional delineation. No soil samples submitted for analysis nor were screened via PID.Letter from DEC to Gaseteria-7/12/90. Letter from DEC (Sigona) to Gaseteria (Oscar Porcelli) requesting subsurface investigation work plan to be apporoved by the DEC to investigate the presence of gasoline vapors. Plan must be received by the DEC by 7/17/90. Odor complaints in January 1990 and again in July 1990. Sigona performed site visit on 7/13/90.Fax to DEC-7/17/90. Letter from Environmental Management Services to DEC (Sigona) proposing: 1)investigation of subsurface utilities as potential pathways 2)determination of groundwater flow direction 3)groundwater monitoring 4)installation of six soil borings along western margin of station and installation of two additional monitoring wells.Letter from DEC to Gaseteria-1/5/95. Letter from DEC (Sigona) to Gaseteria (Angel Chang) requiring "cleanup and removal of discharge". Letter also required immediate steps to abate seepage into basement of 403 W 40th Street. Response from Gaseteria required to DEC by 1/15/95.Letter from Gaseteria to DEC-1/20/95. Letter from Gaseteria (Chang) to DEC (Sigona) stating that Gaseteria will: 1)"divert the flow of surface water away from the south wall of the building" 2)install a SVE system in the basement alonside of the south wall between the concrete floor and the building foundation. Gaseteria does not believe "there is a need to install new groundwater monitoring wells or to further develop existing wells.....since the problem appears to be surface related".Sample analyticals from basement of 480 10th Ave-8/96. Soil analyticals show 20664ppb ethylbenzene(sample 48334), 59164ppb xylene(sample 48334), 11000ppb naphthalene(sample 48334). Letter from DEC to Gaseteria-9/10/96. Letter from DEC(Rommel) to Gaseteria(George Esayan). "DEC in possession of analyticals from Clinton Housing(403 W. 40th Street)". Gasteria required to sample two of the onsite monitoring wells for 8021/8270/lead.Letter from Clinton Housing Development Company-9/11/96. Letter from Clinton(Joseph Tuana) to DEC(Rommel) with copies of analyticals discussed above.Letter from Carl Sulfaro (attorney for Gaseteria) to DEC (Rommel)-9/20/96. Letter stating that Sulfaro "authorized EMS Environmental Services to take two samples of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

the onsite monitoring wells". Samples will be taken 9/27/96. Groundwater analyticals-10/10/96. Analyticals from MW5 by EMS showing 42.56ppb methylene chloride, 5549ppb benzene, 107.33ppb toluene, 1024.75ppb ethylbenzene, 393.15ppb xylene and Oppb MTBE. Letter from Clinton(Kathy Prioleau) to DEC(Rommel)-11/11/96. On 10/27/96 "strong fumes entered basement of 480 10th Ave". NYFD onsite. Letter requests that DEC relay information on "testing done at Gaseteria and UST inspection of Gaseteria". Letter from DEC(Rommel) to Gaseteria(Sulfaro)-11/25/96. Letter stating that requirements of fax dated 9/10/96 were not met because only one well was sampled and 8270/Lead analyses were not performed. Letter requires: 1) submittal of an investigation plan to delineate soil and groundwater contamination 2) source determination 3) installation of three additional monitoring wells 4) installation of an air sampling port on the exhaust line of the venting system and monthly sampling for benzene and THC. Letter states that "action must be taken within 45 days". Letter from DEC(Rommel) to Prioleau(Clinton)-11/26/96. Letter stated that "DEC was never notified" of odor complaints as 11/11/96 letter stated. Also attached to letter was copy of 11/25/96 letter from DEC to Gaseteria. Letter from Gaseteria(Sulfaro) to DEC(Rommel)-1/15/97. Letter stating that Gaseteria "would prefer to perform site investigation, soil removal and/or remediation as needed concurrent with excavation anticipated as part of Federal EPA UST upgrade mandate" and the work is expected to take place in "Spring 1997". Letter from DEC(Rommel) to Gaseteria(Roberto Porcelli)-7/29/98. Letter "serving as final notification of obligations regarding petroleum contamination and vapor incidents". On 6/28/03 petroleum contaminated groundwater infiltrated basement of 480 10th Ave due to heavy rains. This is the "seventh vapor complaint associated with Gaseteria since Jan 1990". Letter states that the "Department is allotting 30 days for Gaseteria to statisfy all requirements in DEC letter dated 11/25/96". Deadline of 8/31/98 given by DEC. Letter from Gaseteria(Seth Friedland) to DEC(Rommel)-8/13/98. Letter stating that "the June 1998 episode was caused by heavy rains and appears to be an isolated event" and that Gaseteria does not agree with Departments conclusions". Letter stated that the station will be taken out of service on 9/15/98, permanently close the USTs and reinstall upgraded USTs on the northern boundary of the site. Letter from DEC(Rommel) to Gaseteria(Roberto Porcelli)-8/28/98. Letter serving as a "reminder of 8/31/98 deadline". Letter from Gaseteria(Oscar Porcelli) to DEC(Rommel)-8/28/98. Letter stating that new USTs were ordered and that work will start the second week of September. Gaseteria intends to install four monitoring wells to replace those destroyed by station upgrade and will retain Environmental Management services to develop remedial plan. Letter from DEC(Rommel) to Gaseteria(Oscar Porcelli)-8/31/98. Letter confirming phone conversation where an agreement was reached that Gaseteria will comply with following requirements and complete the tank upgrade prior to 9/30/98. Letter also required that a workplan be submitted prior to 9/4/03 which included 1) complete delineation 2) soil and groundwater sampling plan for use during excavation activities 3) sampling of SVE emissions 4) installation of three monitoring wells into bedrock and 5) cleaning and proper disposal of oil in the building floor drains and all associated discharge points. Letter from Camin Cargo Control(Gaseteria's Enviro consultant) to Gaseteria-10/5/98. Letter from Camin(Patricia Badding) stating that a site investigation and report shall be prepared. Investigation with Geoprobe and subsequent

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

insallation of monitoring wells scheduled for 10/16/98. Soil samples will also be collected during excavation for new USTs. Venting system emissions will also be sampled. "Cleaning and proper disposal of any oil in the building floor drains and all associated discharge points is the responsibility of Gaseteria". Letter from DEC(Rommel) to Gaseteria(Oscar Porcelli)-10/8/03. Letter acknowledging receipt of Camin 10/5/98 proposal and requiring the following by 10/13/98:

- 1)Site plan with proposed boring locations
- 2)discussion of locations
- 3)discussion of endpoint sampling locations from UST excavation
- 4)discussion of delineation procedure
- 5)include MTBE with analyticals
- 6)collect groundwater samples from Geoprobe locations.

Letter from Camin(Badding) to DEC(Rommel)-10/13/03. Submission of 1)site plan with ten boring locations 2)Collection of six endpoint soil samples from UST excavation 3)excavation and disposal of contaminated soil encountered during tank installation 4)Inclusion of MTBE analyticals 5)collection of groundwater samples(if encountered). Investigation Results from Camin(Badding) to DEC(Rommel)-11/6/98. Results of eight soil borings peformed. Soil analyticals show 2149ppb MTBE(SB1), 526ppb benzene(SB2), 188ppb benzene(SB4), 212ppb benzene(SB5), 4576ppb MTBE(SB6), 1458ppb benzene(SB7), 29114ppb naphthalene(SB7), 187ppb benzene(SB8). Groundwater analyticals show 1239ppb benzene(SB4), 1975ppb benzene(SB5), 5360ppb benzene(SB6). Subsurface Investigation Report Camin Badding 908-523-0616 10/16/98). Investigation report including results above of eight soil borings performed. "There is approximately 2-4 inches of contaminated soil at the soil/bedrock interface in soil boring locations SB2, SB4, SB5, SB7 and SB8. Bedrock at depths of 6-11.5' below grade". "A sheen was detected on all samples"(groundwater). Venting system was samples on 12/11/98 via a vacuum canister attachment to vent. Removed dispenser island is the proposed location of new USTs. See analyticals above. Venting analyticals show 264ppm TPH and no other volatiles. Baseline Acquisition Assessment Report-10/10/02 Delta Environmental (Brad Fisher). Purpose was to establish baseline conditions prior to proposed lease and raze and rebuild of site by BP. One soil borings peformed in 4/02 to depth of 11.5'. Two borings drilled to 24.5" via air rotary and converted to temporary monitoring wells (MW1 and MW2). Delta recommends 1)gaseteria install permanent monitoring wells to delineate contamination. "It is Delta's understanding that Gaseteria will retain the environmental liability of the subject site until spill closure has been obtained". At time of assessment three USTs on site (two 6000-gallon gasoline USTs and one 6000-gallon diesel UST) and four pump islands with six dispensers. Surrounding area is multiple story apartment buildings. "Groundwater is located within bedrock fractures at depths between approximately 12.5 and 13.5 ft bgs". Former USTS onsite which were CLOSED IN PLACE include two (6000-gallon) gasoline USTs in 1998 , one 6000-gallon diesel in 1999, ten 550-gallon gasoline USTs in 1998, one 550-gallon waste oil in 1998 and one 550-gallon fuel oil in 1996. Soil analyticals show 4570ppb xylenes(SB1) and 3970ppb isopropylbenzene(SB1) from depths of 10-11.5'. Groundwater analyticals show 148ppb benzene(MW1), 24800ppb MTBE(MW1) and 30.7ppb benzene(MW2). 10/21/2003-Vought-Reviewed site with DEC(Rommel). Sent Stipulation Agreement with the following requirements: 1)Groundwater delineation via installation of bedrock monitoring wells at former boring locations SB1, SB4, SB5, SB6, SB7 2)Monitoring of vapors and groundwater intrusion 480 10th Ave 3)current status of SVE system and submittal of historic and current SVE effluent samples for benzene analysis or collection of indoor air

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

samples from 480 10th Ave. 10/24/2003-Vought-Called LuJuana Smith (212-967-1644) and left message and explained requirements of 10/21/03 letter. 10/27/2003-Vought-Received message from Steve Muller will be taking indoor air samples from 480 10th Avenue. Vought returned call to Muller (516-395-5957). 10/28/2003-Vought-returned call to Steve Muller to discuss indoor air samples. Left message to return call to DEC. Left message for LuJuana Smith to call DEC. Vought spoke with Muller and okayed PID and stated that SUMA sample as per NYSDOH guidance was not necessary until 1) closure of SVE system or 2) PID indications of petroleum vapors followed by subsequent remediation. Vought also instructed Muller to check sumps. Vought spoke to LuJuana Smith who will be sending in FOIL Request for continuous updates on site. Vought also called Muller and gave him LuJuana's phone (212-967-1644) for access arrangements. 11/6/2003-Vought-Spoke with Steve Muller who was onsite. No PID readings and no olfactory evidence of petroleum and no groundwater infiltration into basement and no product in sump. Muller will produce summary letter and send to DEC. 11/7/2003-Vought-Received Summary Letter from Applied Geosolutions(Muller). Site visit performed on 11/6/03 and inspection of basement at 480 10th Ave. "AGS observed no olfactory detection of odors or vapors consistent with hydrocarbons related to gasoline". PID readings of 4.8ppm were attributed to moisture in basement. Small amount of standing water present near leaking hose. No signs of product in sump. Vapor abatement system unoperational during site visit. Photos of basement submitted with report show no free product or petroleum impact. 11/24/2003-Vought-Received signed STIP from Adam Good(Gaseteria) with revised Corrective Action Plan. 11/26/2003-Vought-Spill transferred from Rommel to Vought. Vought received call from LuJuana Smith and she requested update. Vought faxed her copy of 11/7/03 report and letter sent to Gaseteria on 10/21/03. Vought submitted STIP for implementation to DEC Kunkel. 12/2/03-Vought-STIP implemented by Kunkel. Copy sent and faxed to Good and Muller. 12/17/2003-Vought-See closed spill 0301220 at same location. 9/14/04-Vought-New file review by Vought: Letter from Applied Geosolutions (Steven Muller 516-395-5957). "On November 6, 2003 Applied Geosolutions inspected the basement of 480 10th Avenue to perform vapor monitoring and to identify the presence of groundwater". "During the inspection AGS observed no olfactory detection of odors or vapors consistent with hydrocarbons related to gasoline. The air space was monitored with a portable PID indicating a measurement of 4.8 ppm... This detection is likely the result of low atmospheric pressure followed from periods of rain causing the basement to be damp." The basement floor did not indicate the presence of groundwater...". Line and Dispenser Upgrade Report (Delta Environmental Brad Fisher 914-765-8180). "This Line and Dispenser Report summarizes the results of pump island and product piping upgrade assessment activities conducted by Delta Environmental and Gasoline Installations on behalf of BP Products North America". Work performed included the removing and installing new spill containment boxes beneath each dispenser, removal and replacement of propduct piping and installation of electronic line leak detection systems. Soil analyticals only show minor TAGM 4046 SVOC exceedences attributable to fill. Subsurface Investigation Workplan (Applied Geosolutions)-July 2004. Bedrock at depth of 10' below grade and groundwater at depth of 12.5-13.5' below grade. Report proposes installation of four wells via air rotary followed by groundwater

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

sampling. Groundwater flow direction not determined as of yet. 9/14/04-Vought-Sent letter to Gaseteria approving of Subsurface Investigation Workplan. Vought received message from Lujanna Smith (212-967-1644) and returned call. Vought spoke to Smith and no indication of vapors was noted. Ms. Smith requested info on the applicability of the BCP program for 480 10th Avenue and Vought replied that was only available if HPD was willing to take responsibility of the spill and that she should call Albany for further information. Vought also suggested that she return the call to DEC on 11/14/04 which is when the workplan results are due to DEC. 9/17/04-Vought-Received fax from Applied Geosolutions (Muller). "466 10th Avenue-AGS is currently getting drilling quotes and will complete the Workplan within the 60 day time frame". 1/6/05-Vought-Reviewed Subsurface Investigation Summary Report (Applied Geosolutions) dated December 2004 and received on 1/3/05. Location north of USTs not possible due to concrete with rebar. Installation of three monitoring wells. Groundwater from 7-11' bgs and flow to the west. Groundwater analyticals show 48ppb xylene(MW1), 13ppb 1,2,4-trimethylbenzene(MW1), 17ppb 1,3,5-trimethylbenzene(MW1), 26ppb naphthalene(MW1), 1400ppb MTBE(MW1), 23ppb MTBE(MW2), and 20ppb MTBE(MW3). "The existing groundwater monitoring wells should be monitored on a monthly schedule and sampled on a quarterly schedule to document changes in groundwater elevation and contaminate concentration trends in order to develop and appropriate remedial strategy". DEC requires: 1) installation of monitoring wells on West 37th Street north northeast of site and downgradient from abandoned tankfield along 10th Avenue. 1/19/05-Vought-Meeting at DEC with ASR Tomasello. Will examine possibility of borings across 10th Avenue (may not be possible due to utilities) and also onsite adjacent to 480 10th Avenue. If onsite boring adjacent to 480 10th Avenue is not possible then boring will be installed on 37th Street. 2/17/05-Vought-Spoke to Muller and site visit scheduled for 2/24 at 10am to discuss possible well installation locations. 2/24/05-Vought-Site meeting with ASR Tomasello and no borings possible across 10th Avenue. Well will be installed onsite under canopy downgradient of abandoned tankfield. Well will also be installed on West 37th Street north northeast of site. Obligado- SITE TRANSFERRED FROM VOUGHT TO OBLIGADO 10/12/05 - Spoke with Tomasello ASR, requests to talk about closure for sp0206783. 10/17/05- Obligado - File Review: Final Subsurface Investigation Report, dated June 2005. 4 monitoring wells installed at the site. Wells were installed into Bedrock down to 25 ft bgs. 3 wells installed in December 2004, one additional well installed in March 2005. Groundwater encountered at approximately 7 to 11 feet. No product encountered. Initial gw samples in Dec. 2004 show ND for Benzene in all wells, 1400 ppb MTBE (MW-1), 23 ppb MTBE (MW@), 20 ppb MTBE (MW-3), 48 ppb Xylene (MW-1). March 2005 gw results show 140 ppb benzene (MW1), 2100 ppb MTBE (MW-1), 26 ppb benzene (MW-3), 16 ppb MTBE (MW-3). June 2005 results show 45 ppb benzene (MW-1), 11 ppb Ethylbenene (MW-1), 750 ppb MTBE (MW-1), 52 ppb benzene (MW4), 10 ppb toluene (MW-4), 170 ppb Naphthalene (MW4), 55 ppb MTBE (MW4), 193 ppb xylenes (MW-4). 4Q05 Monitoring Report, dated 10/15/05. Ground water analyticals at show 20 ppb benzene (MW-1), 580 ppb MTBE (MW1), 23 ppb MTBE (MW-2), 21 ppb benzene (MW-3), 15 ppb MTBE (MW-3), 16 ppb benzene (MW-4), 52 ppb ethylbenzene (MW-4), 140 ppb MTBE (MW-4). 11/14/05 - Obligado - Site visit with ASR Tomasello. Request to see at least 2 more quarters of monitoring at a minimum. 12/8/05 - Obligado - Will do a sensitive

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

receptor survey. Continue monitoring. Only 2 quarters of data at MW4.3/1/06 - Obligado - PHone call with Chris/STeve, ask that site be monitored quarterly not monthly.4/12/06 - Obligado - review 1Q06 monitoring report. BTEX ND to 33 ppb, MTBE ND to 800 ppb. 11/21/06 - Obligado - Reviewed Closure Petition/Sensitive Receptor Survey. Sent email to ASR denying NFA stating the following:"Due to historical vapor issues in the adjacent apartment, and the presence of benzene above guidance levels in ground water, the Department requires laboratory analyzed vapor samples from either the slub slab system (if operational) or indoor air samples to confirm no vapor intrusion. The Department also requires an additional round of ground water monitoring to confirm benzene and MTBE levels are still decreasing. NYSDOH Vapor Intrusion Guidance should be followed when collecting air samples available at http://www.health.state.ny.us/environmental/investigations/soil_gas/svi_guidance/index.html. Please submit the results of the additional investigation by January 21, 2007."12/1/06 - Obligado - Steve Muller will be onsite today to collect additional data.5/19/09 - Obligado - Meeting with DEC, ASR, GASeteria. They conducted a groundwater monitoring event and a vapor intrusion investigation in the adjacent residential building. According to report no Vapor intrusion was occurring. Ground water results found low levels of BTEX in GW, max 23 ppb and MTBE is continuing to decrease from 1400 ppb in 2004 to 250 ppb in 1Q09. They will submit a workplan for a confirmatory soil boring investigation by 7/31/09.11/20/09 - Obligado - Reviewed a revised Investigation Work Plan. The plan proposes to install 3 monitoring wells at the site. 2 wells are proposed in the area of the former abandoned 550 USTs and one is downgradient of the dispenser island. I sent a letter to Gaseteria approving the plan.3/22/10 - Obligado - Review the 4th quarter 2009 monitoring report. Max BTEX is 8 ug/L. Max MTBE is 140 ug/L. No LNAPI present.6/14/10 - Obligado - I reviewed the Remedial Investigation Report. 2 Additional soil boring/monitoring wells were installed. 1 soil boring/well location was not completed due utilities in that area. Soil samples were collected from one of the 2 locations, but the other location had shallow bed rock so no soil sample was collected. No soil impacts were detected at the one location where soil was collected. Ground water results showed 13 ppb total BTEX at newly installed MW5. MW6 had no exceedences of TOGs The existing monitoring wells were sampled as well. MW4 had max MTBE at 150 ppb, and BTEX at 14 ppb, and total VOCs were 174 ppb. MW2 had 15.3 ppb BTEX and 11 ppb MTBE. This site has minimal ground water impacts the 6 wells on the site, and lack of evidence of contaminated source soils. Also a VI investigation was previously performed at the adjacent apartment building and no vapor intrusion was determined to be occurring. After discussion with DEC Tibbe, this spill has been closed.

Remarks: GASOLINE ENTERED BUILDING 478 10TH AVE & SEWER SYSTEM, (3) OFFICE BLDGS (475, 478, 483 10TH AVE) EVACUATED, EXPLOSIVE CONDITIONS IN SEWER, DEC & LOCAL AGENCIES ON SCENE. (SIGONA)

Material:

Site ID: 205591
Operable Unit ID: 934554
Operable Unit: 01
Material ID: 442774
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BP AMOCO (Continued)

S100167794

Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: True
Site ID: 205591
Operable Unit ID: 934554
Operable Unit: 01
Material ID: 572491
Material Code: 1213A
Material Name: MTBE (METHYL-TERT-BUTYL ETHER)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True

Tank Test:

590
South
1/4-1/2
0.341 mi.
1802 ft.

LNF PLATING
535 8 AVE.
NYC, NY 10018

NY LTANKS
NY AST
NY CBS AST
NY HIST AST
NY CBS

S102637730
N/A

Relative:
Higher

Actual:
38 ft.

LTANKS:
Site ID: 209549
Spill Number/Closed Date: 9313545 / 2/18/1994
Spill Date: 1/17/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unknown Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 2/18/1994
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1/17/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2/24/1994
Spill Record Last Update: 1/9/1995
Spiller Name: Not reported
Spiller Company: MYSTIC TRANSPORT.
Spiller Address: 1901 STEINWAY STREET
Spiller City,St,Zip: QUEENS, NY
Spiller County: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 173748
DEC Memo: Not reported
Remarks: DRIVER SAID THEY RECEIVED AN ORDER FOR 3000 GAL, TANK ONLY TOOK 1600 GAL - CLEANED UP PRETTY WELL WITH SPEEDY AND SEND SOMEONE OUT TOMORROW TO MAKE SURE.

Material:
Site ID: 209549
Operable Unit ID: 995581
Operable Unit: 01
Material ID: 558802
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CBS AST:
CBS Number: 2-000018
ICS Number: 2-126644
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: D
Telephone: (201) 792-0511
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 02/17/1997
Total Capacity of All Active Tanks(gal): 0
Operator: M. AROCHO
Emergency Contact: M. AROCHO
Emergency Phone: (201) 792-0511
Owner Name: LNF PLATING
Owner Address: 535 8 AVE.
Owner City,St,Zip: NYC, NY 10018
Owner Telephone: (212) 279-8856
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: LNF PLATING
Mail Contact Addr: 535 8 AVE.
Mail Contact Addr2: Not reported
Mail Contact Contact: M. AROCHO
Mail Contact City,St,Zip: NYC, NY 10018
Mail Phone: (212) 279-8856

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Tank Id: 20250
CAS Number: 13463393
Federal ID: Not reported
Tank Status: 0
Install Date: 02/50
Tank Closed: 02/95
Capacity (Gal): 300
Chemical: Nickel carbonyl
Tank Location: Indoors, Aboveground
Tank Type: Steel/carbon steel
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: Other
Tank Error Status: No Missing Data
Date Entered: 02/17/1989
Certified Date: 04/26/1995
Substance: More than one Hazardous Substance on DEC List
Internal Protection: Rubber Liner
External Protection: None
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 20
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: 11/02/92
Is It There: False
Delinquent: False
Date Expired: 02/17/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 01/31/2000

Tank Id: 10050
CAS Number: 37211055
Federal ID: Not reported
Tank Status: 0
Install Date: 02/50
Tank Closed: 02/95
Capacity (Gal): 300
Chemical: Nickel chloride
Tank Location: Indoors, Aboveground
Tank Type: Steel/carbon steel
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: Other
Tank Error Status: No Missing Data

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Date Entered: 02/17/1989
Certified Date: 04/26/1995
Substance: More than one Hazardous Substance on DEC List
Internal Protection: Rubber Liner
External Protection: None
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 20
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: 11/02/92
Is It There: False
Delinquent: False
Date Expired: 02/17/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 01/31/2000

AST:

Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-289221
Program Type: PBS
UTM X: 585104.08813000005
UTM Y: 4511948.7448800001
Expiration Date: 01/01/2017
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 13016
Affiliation Type: Mail Contact
Company Name: 535 8TH AVE LLC
Contact Type: Not reported
Contact Name: MARK SOLBERG
Address1: % OLMSTEAD PROPERTIES, INC.
Address2: 575 EIGHTH AVENUE, SUITE 2400
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 716-3714
Email: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/5/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Site Id: 13016
Affiliation Type: On-Site Operator
Company Name: 535 8TH AVE
Contact Type: Not reported
Contact Name: ADOLPH VALUERDE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 695-4679
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13016
Affiliation Type: Emergency Contact
Company Name: FRANCES SACHAR C/O W REAL EST
Contact Type: Not reported
Contact Name: ADOLPH VALUERDE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 299-4437
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 13016
Affiliation Type: Facility Owner
Company Name: 535 EIGHTH AVE LLC %OLMSTEAD PROPERTIES INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 575 EIGHTH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 654-6662
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 4/5/2013

Tank Info:

Tank Number: 001
Tank Id: 25662
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Equipment Records:

H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None

Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/06/1926
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/05/2013
Material Name: #2 Fuel Oil (On-Site Consumption)

CBS AST:

CBS Number: 2-000018
ICS Number: 2-126644
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: D
Telephone: (201) 792-0511
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 02/17/1997
Total Capacity of All Active Tanks(gal): 0
Operator: M. AROCHO
Emergency Contact: M. AROCHO
Emergency Phone: (201) 792-0511
Owner Name: LNF PLATING
Owner Address: 535 8 AVE.
Owner City,St,Zip: NYC, NY 10018
Owner Telephone: (212) 279-8856
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: LNF PLATING
Mail Contact Addr: 535 8 AVE.
Mail Contact Addr2: Not reported
Mail Contact Contact: M. AROCHO
Mail Contact City,St,Zip: NYC, NY 10018
Mail Phone: (212) 279-8856

Tank Id: 20250

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

CAS Number: 13463393
Federal ID: Not reported
Tank Status: 0
Install Date: 02/50
Tank Closed: 02/95
Capacity (Gal): 300
Chemical: Nickel carbonyl
Tank Location: Indoors, Aboveground
Tank Type: Steel/carbon steel
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: Other
Tank Error Status: No Missing Data
Date Entered: 02/17/1989
Certified Date: 04/26/1995
Substance: More than one Hazardous Substance on DEC List
Internal Protection: Rubber Liner
External Protection: None
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 20
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: 11/02/92
Is It There: False
Delinquent: False
Date Expired: 02/17/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 01/31/2000

Tank Id: 10050
CAS Number: 37211055
Federal ID: Not reported
Tank Status: 0
Install Date: 02/50
Tank Closed: 02/95
Capacity (Gal): 300
Chemical: Nickel chloride
Tank Location: Indoors, Aboveground
Tank Type: Steel/carbon steel
Total Tanks: 0
Tank Secret: False
Tank Secondary Containment: Other
Tank Error Status: No Missing Data
Date Entered: 02/17/1989

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Certified Date: 04/26/1995
Substance: More than one Hazardous Substance on DEC List
Internal Protection: Rubber Liner
External Protection: None
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 20
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: 11/02/92
Is It There: False
Delinquent: False
Date Expired: 02/17/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 01/31/2000

HIST AST:

PBS Number: 2-289221
SWIS Code: 6201
Operator: JEAN ISAAC
Facility Phone: (212) 594-4728
Facility Addr2: 535 8TH AVE
Facility Type: Not reported
Emergency: JEAN ISAAC
Emergency Tel: (212) 594-4728
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: FRANCES SACHAR C/O W REAL EST
Owner Address: 380 MADISON AVENUE
Owner City,St,Zip: NEW YORK, NY 10017
Federal ID: Not reported
Owner Tel: (212) 716-3721
Owner Type: Not reported
Owner Subtype: Not reported
Mailing Contact: FRAN GOLDIIN
Mailing Name: FRANCES SACHAR C/O W REAL EST
Mailing Address: 380 MADISON AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Telephone: (212) 716-3721
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LNF PLATING (Continued)

S102637730

Certification Flag: False
Certification Date: 11/24/1997
Expiration: 01/07/2003
Renew Flag: False
Renew Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: ABOVEGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 5000
Product Stored: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Not reported
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: None
Leak Detection: 0
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: False
SPDES Number: Not reported
Lat/Long: Not reported

CBS:

CBS Number: 2-000018
Program Type: CBS
Facility Status: Unregulated
Expiration Date: Not reported
Dec Region: 2
UTMX: 585072.41381000
UTMY: 4511939.1154500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CW591
WSW
1/4-1/2
0.344 mi.
1818 ft.

COMMERCIAL BUILDING
541 WEST 37TH STREET
NEW YORK, NY

NY LTANKS S106737471
N/A

Site 1 of 2 in cluster CW

Relative:
Lower

LTANKS:

Actual:
18 ft.

Site ID: 334665
Spill Number/Closed Date: 0409846 / 5/5/2005
Spill Date: 12/3/2004
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 12/3/2004
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/3/2004
Spill Record Last Update: 5/5/2005
Spiller Name: MORTY
Spiller Company: COMMERCIAL BUILDING
Spiller Address: 541 WEST 37TH STREET
Spiller City,St,Zip: NEW YORK, NY 001
Spiller County: 001
Spiller Contact: MORTY
Spiller Phone: (212) 564-2000
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 269881
DEC Memo: ttf ltr sent 1/14/20052/14/2005 Received a letter from Morton Usdan (212-564-2006) saying that he hired a company to work on the tank. If it can be fixed, it will be. If not, it will be abandoned.5/2/2005 Sangesland spoke to Mr. Usdan. He said PTC found a dry leak in the vent line and replaced the line. Tank was retested and passed, no contamination was visible.Sangesland asked Mr. Usdan to submit all of this in writing to DEC.5/5/2005 Sangesland received a letter from Mark Salamack at Petroleum Tank Cleaners.Tank was originally tested and failed by another company. PTC emptied the 1500 gal tank, isolated the lines and the stickline and vent line were found to leak. The gasket was replaced and then the tank was tested alone and passed.All necessary piping was replaced and no contamination was found.Spill Closed
Remarks: PBS No: 2-210420

Material:

Site ID: 334665
Operable Unit ID: 1096791
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106737471

Material ID: 576729
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 334665
Spill Tank Test: 1548373
Tank Number: 0001
Tank Size: 1400
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 12/6/2004
Test Method: Horner EZ Check I or II

**CX592
NW
1/4-1/2
0.345 mi.
1823 ft.**

**609 11TH AVE
609-611 11TH AVE
NEW YORK, NY
Site 1 of 4 in cluster CX**

**NY LTANKS
NY Spills
S103824901
N/A**

**Relative:
Lower**

LTANKS:

**Actual:
16 ft.**

Site ID: 230867
Spill Number/Closed Date: 9900078 / 7/2/2003
Spill Date: 4/2/1999
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: DKHARRIN
Referred To: Not reported
Reported to Dept: 4/2/1999
CID: 382
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 4/2/1999
Spill Record Last Update: 9/11/2003
Spiller Name: MIKE MEOLA
Spiller Company: EXXONMOBIL CORPORATION
Spiller Address: 464 DOUGHTY BLVD.
Spiller City,St,Zip: INWOOD, NY 11096

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 11TH AVE (Continued)

S103824901

Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 190248
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HARRINGTON" This spill site has been transferred from DEC Sigona to RemedialBureau B, on August 4, 2003. This spill site has been consolidated under Spill No. 8806783. Reassigned from O'Dowd to Sigona on 11/6/00 DEC's comments regarding a proposed Work Plan for On-Site and Off-Site Investigation by Roux Associates, dated April 30, 2003. Based on the results of our site visit on March 7, 2003, and evaluation of the proposal by Roux Associates, the DEC accepts ExxonMobil's Work Plan and Schedule to evaluate the on-site and off-site contamination at this location. Exxon-Mobil must now complete the implementation of the Work Plan according to the proposed schedule. The results of this investigation must be compiled into a Subsurface Investigation Report prepared in accordance with Section No. 3, paragraph 3.14 of the Division of Environmental Remediation's Draft DER-10 Technical Guidance for Site Investigation and Remediation, dated December 2002. A complete Remedial Investigation Report must be submitted for DEC review and approval according to the proposed implementation scheduled.

Remarks: DOUBLE WALLED STEEL TANK. LEAK IS FROM INNER TO OUTER WALL.

Material:
Site ID: 230867
Operable Unit ID: 1078859
Operable Unit: 01
Material ID: 307218
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 230867
Spill Tank Test: 1547033
Tank Number: 1
Tank Size: 4000
Test Method: 14
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: VacuTest

SPILLS:
Facility ID: 0002289

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 11TH AVE (Continued)

S103824901

Facility Type: ER
DER Facility ID: 61396
Site ID: 63582
DEC Region: 2
Spill Date: 5/24/2000
Spill Number/Closed Date: 0002289 / 7/2/2003
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 5/24/2000
CID: 312
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/24/2000
Spill Record Last Update: 3/24/2005
Spiller Name: ROBERT GANS
Spiller Company: ZZ
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 999
Contact Name: ROBERT GANS
Contact Phone: Not reported
DEC Memo: Spoke to Dr. Sandoval who represents Whitehouse - the tenant/builder/runner of future club. Swingtime is the owner of the property. According to a report written by Swingtime's consultant, American Envmtl Assessment(AEA), there was no contamination.DEC Saccacio required more work.PDM performed own investigation for Whitehouse and found contamination. Whitehouse's attorney(Michael Perle) will send DEC letter. Reassigned from Saccacio.5/9/03 Reassigned from Rommel to Harrington. 1/5/05 Reassigned from Harrington to Foley. Changed address back to 609-611 11th Avenue. Address was 561 11th Ave and listed ExxonMobil as RP. Two PBS registrations, one at each location. Appeared to have been consolidated under spill #8806783 in error. Cross-reference open #9501693 for 609-611 11th Ave. (KMF)From closed spill file: (KMF, 3/24/05)10/24/00 Letter from PDM Environmental Services addressed to Mr. Oscar Sandoval of The White House. PDM reviewed the American Environmental Assessment Corp Summary Report for Soil Removal. They noted that in some samples the reported values were greater than the guidance values. Also noted that some samples were contaminated and above STARS guidance values. Sample results indicate that soils beneath the 11th Avenue property line show the greatest levels in exceedance of criteria and will probably require further remediation. PDM noted complications with obtaining a certificate of occupancy until contaminants have been removed to below acceptable levels.A letter was issued by S. Saccacio on 11/22/00 which states that the spill number will not be considered for closure until additional

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 11TH AVE (Continued)

S103824901

Remarks: investigation is conducted and the Dept reviews the results. See spill #s 0001837, 0001719, 9501693.
STEVE SACCOCIO IS AWARE

Material:
Site ID: 63582
Operable Unit ID: 824213
Operable Unit: 01
Material ID: 550655
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0001837
Facility Type: ER
DER Facility ID: 281560
Site ID: 230866
DEC Region: 2
Spill Date: 5/12/2000
Spill Number/Closed Date: 0001837 / 3/20/2002
Spill Cause: Housekeeping
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 5/12/2000
CID: 196
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/12/2000
Spill Record Last Update: 3/24/2005
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: This spill site has been transferred from DEC Sigona to Remedial Bureau B, on August 4, 2003. Closed and cross referenced to spill

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609 11TH AVE (Continued)

S103824901

8806783.3/23/05 Spill reassigned from Harrington to Foley. Found address information in closed spill file #0002289. Original spill report shows address as 45th St and 11th Ave. Changed address from ExxonMobil at 561 11th Ave to 609-611 11th Ave. Also see open spill #9501693. (KMF)

Remarks: CONSTRUCTION WORKERS DIGGING FOUNDATION FOUND SOIL WITH GASOLINE.WORKERS WALKED OFF SITE. RQUEST DEC FOR INSPECTION.

Material:

Site ID: 230866
Operable Unit ID: 823755
Operable Unit: 01
Material ID: 290049
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CX593
NW
1/4-1/2
0.345 mi.
1823 ft.

609-611 11TH AVE
609-611 11TH AVENUE
MANHATTAN, NY 10036

NY LTANKS
NY Spills
S104652652
N/A

Site 2 of 4 in cluster CX

Relative:
Lower

LTANKS:

Actual:
16 ft.

Site ID: 264591
Spill Number/Closed Date: 9501693 / 9/16/2005
Spill Date: 5/9/1995
Spill Cause: Tank Failure
Spill Source: Gasoline Station
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 5/10/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 5/18/1995
Spill Record Last Update: 9/16/2005
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609-611 11TH AVE (Continued)

S104652652

Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 215638
DEC Memo: 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel.12/7/04 Reassigned from Rommel to Foley. Issued certified letter (Robert Gans, Swing Time LLC Corp., 1270 Saw Mill River Rd, Yonkers NY 10710) requiring site assessment for ten gas USTs removed 7/99. Report to be submitted by 3/7/05.12/21/04 Certified letter returned as attempted, unknown.12/22/04 Resent certified letter to Robert Gans (617 11th Avenue, NY NY 10036).12/27/04 Spoke to Perry Burkett(same address as R. Gans-617 11th Ave, NY NY 10036 (212-582-1951, 212-246-0856(fax)), general counsel for Robert Gans, Swingtime LLC. Will send correspondence and reports that were previously submitted to Steven Saccaccio. Stated that Saccaccio had approved remediation and subsequent construction of building currently on property.1/4/05 Received reports from P. Burkett. 1) Letter workplan dated 5/22/00.2) Letter and fax from B. Pachmohr dated 6/5/00 including field notes and proposal for an additional monitoring well.3) Fax from S. Saccacio to former tenant, Dr. Oscar Sandoval and his atty M. Perle, indicating the planned building will not interfere with the remaining spill investigation and potential remedial obligations.4) Soil Removal Summary Report from American Environmental Assessment Corp. dated 7/5/00.10 gasoline USTs had been located in the SE corner of the property. They were removed prior to the construction work and the site assessment that was performed at the time did not reveal any contamination around the tank field. American Environmental Assessment Corp.(AEAC) was contracted to further investigate. On 5/24/00, AEAC installed three test pits. Soil around the former tank field had been impacted by gasoline. Between 5/31 and 6/14/00, 860 tons of contaminated soil were removed. GW was encountered at 13'bgs. Two samples at 10'bgs showed elevated concentrations of VOCs (total BTEX at 4133ppb(E-5), and 2525ppb(E-4)). Rock was encountered at a depth of approx 6'bgs which dropped off towards the SE corner to 10-12'bgs.1/6/05 Received copy of tank removal affidavit from Petroleum Technology stating ten 550gal gas tanks were removed on 7/20/99.1/10/05 Issued letter requiring installation of three monitoring wells. Two along 11th Ave (adjacent to soil sample locations E-4 and E-5) and one along 45th St (btwn S-2 and S-3). Report due 4/15/05. See spill #s 0001837, 0001719.3/24/05 Met with M. Roux, Roux Associates. If bedrock is encountered, they will core through bedrock (only at location closest to E-5, highest soil cont.). Will take soil samples at all locations(highest PID and at gw interface). GW samples will be taken if encountered before bedrock. 4/20/05 Met Roux(Marty) and ADT Drilling on-site. Refusal at 9'bgs in first boring on northside of W45th St. Second boring(northernmost) on 11th Ave had some hits on the PID up to 700ppm. Sample from 15-17'bgs was wet. ADT installed monitoring well. Third boring to be drilled later.4/28/05 Spoke to M. Roux. Report expected to be submitted by 5/20/05.6/15/05 Reveived Ltd. Subsurface Investigation Report dated 6/14/05. Attempted to install three wells. Two were successful(MW-2 and MW-3). Soil had some detections of BTEX below TAGM RSCOs. Groundwater showed lower levels of BTEX in MW-2(68ppb benzene, 4ppb toluene, 300ppb

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609-611 11TH AVE (Continued)

S104652652

ethylbenzene, 232ppb xylenes). GW in MW-3 showed one hit for MTBE at 10ppb, with no other VOCs detected. 6/16/05 Letter sent to R. Gans requesting confirmatory GW sample be collected at end of July 2005.8/19/05 Letter from Roux Assoc. with results of gw analysis from 7/27/05. Concentrations of BTEX above GWQS in MW-2 (30ppb benzene, 240ppb ethylbenzene, 182ppb xylenes). Concentrations in MW-3 were below GWQS. This appears to be due to residual soil contamination as indicated by boring logs. Potential for exposure from soil vapor is not expected, however, according to the report, a vapor barrier had been installed beneath the building.

Remarks: ENVIRONMENTAL SITE STUDY DONE - GROUND CONTAMINATION FOUND RESULTING FROM TANK LEAKING. PROPERTY IS ABANDONED GAS STATION. 10TH AVE CORP. OWNER ISAAC GATWEN, 18 WOODHAVEN, NEW YORK CITY

Material:

Site ID: 264591
Operable Unit ID: 1016066
Operable Unit: 01
Material ID: 366768
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: True
Site ID: 264591
Operable Unit ID: 1016066
Operable Unit: 01
Material ID: 1521285
Material Code: 1213A
Material Name: MTBE (METHYL-TERT-BUTYL ETHER)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True
Site ID: 264591
Operable Unit ID: 1016066
Operable Unit: 01
Material ID: 1521286
Material Code: 2645A
Material Name: BTEX
Case No.: Not reported
Material FA: Oxygenates
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: True
Site ID: 264591
Operable Unit ID: 1016066
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609-611 11TH AVE (Continued)

S104652652

Material ID: 366767
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: True

Tank Test:

SPILLS:

Facility ID: 0001719
Facility Type: ER
DER Facility ID: 60765
Site ID: 62715
DEC Region: 2
Spill Date: 5/10/2000
Spill Number/Closed Date: 0001719 / 3/20/2002
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 5/10/2000
CID: 312
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/10/2000
Spill Record Last Update: 3/24/2005
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Closed and cross-referenced to 0001837, 0002289, 9501693.3/24/05
Changed address from W 45th St/ 11th Av to 609-611 11th Ave. (KMF)
Remarks: CALLER STATES SUBJS ARE THERE WORKING AND HIT AN OLD TANK- Nothing FURTHER

Material:

Site ID: 62715
Operable Unit ID: 823532
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

609-611 11TH AVE (Continued)

S104652652

Material ID: 289933
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**CX594
NW
1/4-1/2
0.346 mi.
1826 ft.**

**612 W 45TH ST/UPS
612 W 45TH ST
NYC, NY**

NY LTANKS

**S102671711
N/A**

Site 3 of 4 in cluster CX

**Relative:
Lower**

LTANKS:

**Actual:
15 ft.**

Site ID: 139981
Spill Number/Closed Date: 9104075 / 2/12/2003
Spill Date: 7/15/1991
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release that creates a file or hazard. (Highly Improbable)
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SULLIVAN
Referred To: Not reported
Reported to Dept: 7/16/1991
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 7/17/1991
Spill Record Last Update: 2/12/2003
Spiller Name: Not reported
Spiller Company: UPS
Spiller Address: 643 W 43RD ST
Spiller City,St,Zip: NY, NY 10036
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 119559
DEC Memo: Not reported
Remarks: DISCOVERED CONTAMINATED SOIL WHILE REMOVING 12 550 GAL TANKS. 2 HAD VISIBLE CORROSION & LEAKS. SOIL BEING STOCKPILED AND SAMPLED FOR DISPOSAL SITE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

612 W 45TH ST/UPS (Continued)

S102671711

Material:

Site ID: 139981
Operable Unit ID: 957968
Operable Unit: 01
Material ID: 423174
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

595
WNW
1/4-1/2
0.347 mi.
1831 ft.

MYRON GARFINKEL
627 WEST 42ND STREET
NEW YORK, NY 10036

NY UST
NY HIST UST
NY MANIFEST
NY BROWNFIELDS

U003312878
N/A

Relative:
Lower

UST:

Id/Status: 2-603476 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 08/31/2009
UTM X: 584539.31305
UTM Y: 4512728.4089299999
Site Type: Other

Actual:
16 ft.

Affiliation Records:

Site Id: 25392
Affiliation Type: Mail Contact
Company Name: COBS 42ND LLC
Contact Type: Not reported
Contact Name: EVAN STEIN
Address1: C/O M D CARLISLE
Address2: 352 PARK AVENUE SOUTH
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 689-0639
Email: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/31/2004

Site Id: 25392
Affiliation Type: On-Site Operator
Company Name: MYRON GARFINKEL
Contact Type: Not reported
Contact Name: N/A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MYRON GARFINKEL (Continued)

U003312878

Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 689-0639
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/31/2004

Site Id: 25392
Affiliation Type: Emergency Contact
Company Name: COBS 42ND LLC C/O M D CARLISLE
Contact Type: Not reported
Contact Name: EVAN SPEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (212) 689-0639
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/31/2004

Site Id: 25392
Affiliation Type: Facility Owner
Company Name: COBS 42ND LLC C/O M D CARLISLE
Contact Type: PRESIDENT
Contact Name: JERALD JOHNSON
Address1: 352 PARK AVENUE SOUTH
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10010
Country Code: 001
Phone: (212) 689-0639
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 8/31/2004

Tank Info:

Tank Number: 1
Tank ID: 54495
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 03/19/2000
Registered: True
Tank Location: Underground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MYRON GARFINKEL (Continued)

U003312878

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 08/31/2004

Equipment Records:

G00 - Tank Secondary Containment - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
B01 - Tank External Protection - Painted/Asphalt Coating
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating

HIST UST:

PBS Number: 2-603476
SPDES Number: Not reported
Emergency Contact: MYRON GARFINKLE
Emergency Telephone: (203) 866-2700
Operator: AZTEC METAL CO.
Operator Telephone: (212) 293-2777
Owner Name: MYRON GARFINKLE
Owner Address: 6 POINT ROAD WILSON POINT
Owner City,St,Zip: NORWALK, CT 06854
Owner Telephone: (203) 866-2700
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: MYRON GARFINKLE
Mailing Address: 6 POINT ROAD WILSON POINT
Mailing Address 2: Not reported
Mailing City,St,Zip: NORWALK, CT 06854
Mailing Contact: Not reported
Mailing Telephone: (203) 866-2700
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2: 627 WEST 42ND STREET
SWIS ID: 6201
Old PBS Number: Not reported
Facility Type: Not reported
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 05/21/1998
Expiration Date: 05/12/2003

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MYRON GARFINKEL (Continued)

U003312878

Renew Flag: False
Renewal Date: Not reported
Total Capacity: 5000
FAMT: True
Facility Screen: Minor Data Missing
Owner Screen: Minor Data Missing
Tank Screen: No Missing Data
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City: 01
Region: 2

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: In Service
Install Date: Not reported
Capacity (gals): 5000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: 12/27/1987
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

NY MANIFEST:

EPA ID: NYR000130039
Country: USA

Mailing Info:

Name: CUBS 42ND LLC
Contact: TONY HA
Address: 352 PARK AVENUE SOUTH
City/State/Zip: NEW YORK, NY 10001
Country: USA
Phone: 800-969-3478

NY MANIFEST:

No Manifest Records Available

BROWNFIELDS:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MYRON GARFINKEL (Continued)

U003312878

Program: BCP
Site Code: 359267
Site Description: This BCP Application is to redevelop the site for a mix of residential and retail uses, as well as parking. The site is located at 627 and 647 West 42nd Street, New York, NY 10036, and is approximately 0.82 acres in size. The site was formerly used for a variety of residential and commercial uses. Currently, 627 West 42nd Street is vacant and 647 West 42nd Street is used for commercial purposes. The proposed redevelopment for future use includes a mix of residential and retail uses with parking. Known or suspected contaminants listed are petroleum, chlorinated solvents and other VOCs. These contaminants are impacting the soil and soil gas. This BCP Application is currently under review and the Department of Environmental Conservation will determine the application's approval and eligibility in conjunction with the Department of Health. After careful review, the Department determined that this site was not eligible for the BCP. The site had already been developed including soil excavation and remediation prior to submittal of the application. Not reported
Env Problem: Information submitted with the BCP application regarding the environmental conditions at the site are currently under review and will be revised as additional information becomes available. After careful review, the Department determined that this site was not eligible for the BCP. The site had already been developed including soil excavation and remediation prior to submittal of the application. Not reported
Health Problem: Not reported

596
North
1/4-1/2
0.347 mi.
1832 ft.

527 W 48TH ST
527 W 48TH ST
MANHATTAN, NY

NY LTANKS S102662820
N/A

Relative:
Lower

LTANKS:

Actual:
23 ft.

Site ID: 72219
Spill Number/Closed Date: 9612403 / 1/21/1997
Spill Date: 1/17/1997
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1/17/1997
CID: 322
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/17/1997
Spill Record Last Update: 1/21/1997
Spiller Name: CHARLIE BOETTIGER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

527 W 48TH ST (Continued)

S102662820

Spiller Company: MYSTIC OIL
Spiller Address: 19-01 STEINWAY ST
Spiller City,St,Zip: ASTORIA, NY
Spiller County: 001
Spiller Contact: CHARLIE BOETTIGER
Spiller Phone: (718) 932-9075
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 68199
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN"
Remarks: DRIVER OVERFILLED TANK - SPILL ON CONCRETE BEING CLEANED UP

Material:
Site ID: 72219
Operable Unit ID: 1040265
Operable Unit: 01
Material ID: 341050
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

597
South
1/4-1/2
0.348 mi.
1840 ft.

330 W. 36TH ST
330 W. 36TH ST
MANHATTAN, NY

NY LTANKS **S101341105**
N/A

Relative:
Higher

LTANKS:
Site ID: 76938
Spill Number/Closed Date: 9409495 / 10/17/1994
Spill Date: 10/13/1994
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 10/17/1994
Cleanup Meets Standard: True
SWIS: 3101
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 10/17/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

330 W. 36TH ST (Continued)

S101341105

Remediation Phase: 0
Date Entered In Computer: 11/7/1994
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: BARBOUR HOTEL
Spiller Address: 330 W. 36TH ST
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 71847
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TANG"
Remarks: TANK CORRODED ON TOP-TANK WAS PUMPED PUT-CLEANUP WAS DONE

Material:
Site ID: 76938
Operable Unit ID: 1007261
Operable Unit: 01
Material ID: 378922
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

598
SSE
1/4-1/2
0.349 mi.
1841 ft.

APT BUILDING TTF
256 WEST 38 ST
MANHATTAN, NY

NY LTANKS **S112148825**
N/A

Relative:
Higher

LTANKS:
Site ID: 466230
Spill Number/Closed Date: 1203417 / Not Reported
Spill Date: 7/9/2012
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 7/9/2012
CID: Not reported
Water Affected: Not reported

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APT BUILDING TTF (Continued)

S112148825

Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 1
Date Entered In Computer: 7/9/2012
Spill Record Last Update: 7/9/2012
Spiller Name: Not reported
Spiller Company: APT BUILDING
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: ROB HILL
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 420566
DEC Memo: Not reported
Remarks: 4500 gal tank

Material:

Site ID: 466230
Operable Unit ID: 1216236
Operable Unit: 01
Material ID: 2214402
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

599
SW
1/4-1/2
0.351 mi.
1853 ft.

460 10TH AVE
460 10TH AVENUE
MANHATTAN, NY

NY LTANKS **S102672733**
N/A

Relative:
Higher

LTANKS:
Site ID: 73067
Spill Number/Closed Date: 9412295 / 12/20/1994
Spill Date: 12/14/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 12/20/1994
Cleanup Meets Standard: True
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 12/14/1994

Actual:
40 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

460 10TH AVE (Continued)

S102672733

CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/30/1995
Spill Record Last Update: 10/3/2003
Spiller Name: Not reported
Spiller Company: SIVERSTEIN PROPERTIES
Spiller Address: 5215 5TH AVE
Spiller City,St,Zip: NEW YORK, NY 10175
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 68841
DEC Memo: Not reported
Remarks: CUSTOMER OVERORDERED - SPILL CONTAINED ON ROAD PAVEMENT-SUPER FUEL CONTAINING- ABC TANK AT SITE 718/272-2800

Material:

Site ID: 73067
Operable Unit ID: 1005991
Operable Unit: 01
Material ID: 374617
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 400
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**600
SSW
1/4-1/2
0.352 mi.
1857 ft.**

**454 9TH AVE
454 9TH AVE.
MANHATTAN, NY**

**NY LTANKS S102662578
N/A**

**Relative:
Higher**

LTANKS:

Site ID: 101691
Spill Number/Closed Date: 9401631 / 5/4/1994
Spill Date: 5/4/1994
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

**Actual:
39 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

454 9TH AVE (Continued)

S102662578

SWIS: 3101
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 5/4/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/27/1948
Spill Record Last Update: 7/1/1997
Spiller Name: Not reported
Spiller Company: MYSTIC TRANSPORTATION
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 90098
DEC Memo: Not reported
Remarks: Not reported

Material:

Site ID: 101691
Operable Unit ID: 995313
Operable Unit: 01
Material ID: 385380
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CX601 **METROPOLITAN LUMBER COMPANY**
NNW **617 11TH AVE**
1/4-1/2 **NEW YORK, NY 10036**
0.353 mi.
1865 ft. **Site 4 of 4 in cluster CX**

NY LTANKS **1000791013**
NY UST **N/A**

Relative:
Lower

LTANKS:
Site ID: 257831
Spill Number/Closed Date: 9707347 / 1/8/1998
Spill Date: 9/22/1997
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Actual:
17 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 9/22/1997
CID: 297
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 9/22/1997
Spill Record Last Update: 1/16/1998
Spiller Name: BOB GANS
Spiller Company: METROPOLITAN LUMBER CO
Spiller Address: 617 11TH AV
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: BOB GANS
Spiller Phone: (212) 246-9090
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 211110
DEC Memo: Not reported
Remarks: WORKERS LOCATED 8 550 GALLON UNDERGROUND GAS TANKS AND THERE IS SOIL
CONTAMINATION AROUND THE TANKS - CHRIS TOMESSELO HAS BEEN NOTIFIED
FROM DEC R-2

Material:

Site ID: 257831
Operable Unit ID: 1053727
Operable Unit: 01
Material ID: 332918
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

UST:

Id/Status: 2-601335 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 02/19/1998
UTM X: 584716.98108000006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

UTM Y: 4512960.3622599998
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 23302
Affiliation Type: Facility Owner
Company Name: METROPOLITAN LUMBER COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 617 11TH AVE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 246-9090
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23302
Affiliation Type: Mail Contact
Company Name: METROPOLITAN LUMBER CO.
Contact Type: Not reported
Contact Name: BOB GANS
Address1: 617 11TH AVENUE
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10036
Country Code: 001
Phone: (212) 243-9090
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23302
Affiliation Type: On-Site Operator
Company Name: METROPOLITAN LUMBER COMPANY
Contact Type: Not reported
Contact Name: BOB GANS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-9090
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 23302
Affiliation Type: Emergency Contact
Company Name: METROPOLITAN LUMBER COMPANY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

Contact Type: Not reported
Contact Name: BOB GANS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 246-9090
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 01
Tank ID: 45553
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 02
Tank ID: 45554
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser

Tank Number: 03
Tank ID: 45555
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

Tank Number: 04
Tank ID: 45556
Tank Status: Closed - Removed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 05
Tank ID: 45557
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

C02 - Pipe Location - Underground/On-ground

Tank Number: 06
Tank ID: 45558
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 07
Tank ID: 45559
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
I00 - Overfill - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 08
Tank ID: 45560
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B00 - Tank External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 09
Tank ID: 45561
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1992
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

METROPOLITAN LUMBER COMPANY (Continued)

1000791013

Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground

CV602
ENE
1/4-1/2
0.354 mi.
1869 ft.

DAYS HOTEL
790 8TH AVE
NEW YORK, NY

NY LTANKS
NY Spills

S102402110
N/A

Site 2 of 2 in cluster CV

Relative:
Higher

LTANKS:

Actual:
50 ft.

Site ID: 251968
Spill Number/Closed Date: 9903737 / 2/25/2003
Spill Date: 7/1/1999
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 7/1/1999
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 7/1/1999
Spill Record Last Update: 2/25/2003
Spiller Name: CALLER
Spiller Company: AMERADA HESS
Spiller Address: 238 WEST FORT LEE RD
Spiller City,St,Zip: BOGOTA, NJ -
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 281044
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ENGELHARDT"2/25/2003 - Closed Due To The Nature / Extent Of The
Spill Report
Remarks: driver overfilled tank.cleanup started.*region 2 pager 07:12

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

Material:

Site ID: 251968
Operable Unit ID: 1078270
Operable Unit: 01
Material ID: 303642
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 350813
Spill Number/Closed Date: 0505733 / 3/9/2006
Spill Date: 8/10/2005
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JXZHAO
Referred To: Not reported
Reported to Dept: 8/10/2005
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/10/2005
Spill Record Last Update: 3/9/2006
Spiller Name: SHAWN
Spiller Company: DAYS INN HOTEL
Spiller Address: 790 8TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: SHAWN
Spiller Phone: (718) 967-9424
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 206466
DEC Memo: Sangesland spoke to Vinny at Island Tank (718-967-9424).He said there is a new owner of the Hotel and he was hired to inspect the tank.The tank is in a vault and there is a very minor leak in one corner.Island Tank is in the process of pumping out the tank.Tank will be cleaned and then tested with an ultra sound.Work is already underway, so no TTF letter was sent2/1/2006 - jz: Investigation was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

Remarks: conducted by ATC. Zhao spoke with Mike Marose? 212-353-8280 ext. 345.
today. Report will be prepared and forwarded within next few weeks.
LEAKING IN A CORNER OF TANK AND CAUSING SPILL;

Material:

Site ID: 350813
Operable Unit ID: 1108357
Operable Unit: 01
Material ID: 2098292
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 0501767
Facility Type: ER
DER Facility ID: 206466
Site ID: 345991
DEC Region: 2
Spill Date: 5/13/2005
Spill Number/Closed Date: 0501767 / 5/13/2005
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 5/13/2005
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/13/2005
Spill Record Last Update: 5/13/2005
Spiller Name: VINCENT
Spiller Company: DAYS HOTEL
Spiller Address: 790 8TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: VINCENT
Contact Phone: (212) 581-7000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

DEC Memo: 5/13/05 Tipple spoke with Hess, and Day's Inn engineer, spill all
cleaned from sidewalk, petrometer to be checked/calibrated
Remarks: BAD GAGE, VINCENT TOLD THE DRIVER TO KEEP PUMPING AND IT OVERFLOWED:
CREW IS CLEANING UP:

Material:
Site ID: 345991
Operable Unit ID: 1103720
Operable Unit: 01
Material ID: 583934
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0408732
Facility Type: ER
DER Facility ID: 268701
Site ID: 333468
DEC Region: 2
Spill Date: 11/8/2004
Spill Number/Closed Date: 0408732 / 12/3/2004
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JXZHAO
Referred To: Not reported
Reported to Dept: 11/8/2004
CID: 407
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/8/2004
Spill Record Last Update: 12/3/2004
Spiller Name: RICARDO
Spiller Company: Not reported
Spiller Address: 790 8TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: RICARDO
Contact Phone: (212) 581-7000
DEC Memo: PTC in route to clean the spillSpill on sidewalk, contained,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

Remarks: secured, cleaned up.
 Caller states the tank was overfilled due to the gauge being broken,
 super says its been broken for months.

Material:

Site ID: 333468
Operable Unit ID: 1095623
Operable Unit: 01
Material ID: 575745
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9608400
Facility Type: ER
DER Facility ID: 206466
Site ID: 251967
DEC Region: 2
Spill Date: 10/7/1996
Spill Number/Closed Date: 9608400 / 10/7/1996
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
 Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 10/7/1996
CID: 322
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/7/1996
Spill Record Last Update: 10/18/1996
Spiller Name: Not reported
Spiller Company: HOTEL
Spiller Address: 790 8TH AVE
Spiller City,St,Zip: NY, NY -
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
 "MARTINKAT"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

Remarks: inoperative petrometer caused overfill of tank - being cleaned up

Material:

Site ID: 251967
Operable Unit ID: 1036667
Operable Unit: 01
Material ID: 344138
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: 10
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9909158
Facility Type: ER
DER Facility ID: 281044
Site ID: 251969
DEC Region: 2
Spill Date: 10/28/1999
Spill Number/Closed Date: 9909158 / 4/6/2000
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 10/28/1999
CID: 205
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/28/1999
Spill Record Last Update: 4/6/2000
Spiller Name: Not reported
Spiller Company: HESS OIL
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: CALLER
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"CLEANED BY RP.
Remarks: caller reported spill on sidewalk. cleanup enroute.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DAYS HOTEL (Continued)

S102402110

Material:

Site ID: 251969
Operable Unit ID: 1083763
Operable Unit: 01
Material ID: 298249
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

603
ENE
1/4-1/2
0.360 mi.
1899 ft.

SEE SPILL #04-09483
254 WEST 47TH STREET
NEW YORK, NY

NY LTANKS S106971608
N/A

Relative:
Higher

Actual:
48 ft.

LTANKS:

Site ID: 333832
Spill Number/Closed Date: 0409264 / 11/23/2004
Spill Date: 11/12/2004
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 11/12/2004
CID: 408
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/18/2004
Spill Record Last Update: 9/30/2005
Spiller Name: RICK
Spiller Company: COMMERCIAL BUILDING
Spiller Address: 254 WEST 47TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: RICK
Spiller Phone: (212) 719-2733
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 269071

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SEE SPILL #04-09483 (Continued)

S106971608

DEC Memo: Tipple updating///due to a communication problem with the hotline a new number 09-09483 was generated and is being used by the RP and cleanup company.SEE Spill # 04-09483

Remarks: CLEAN UP IN PROGRESS

Material:

Site ID: 333832
Operable Unit ID: 1095978
Operable Unit: 01
Material ID: 575980
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 334232
Spill Number/Closed Date: 0409483 / 9/30/2005
Spill Date: 11/11/2004
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 11/23/2004
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/23/2004
Spill Record Last Update: 9/30/2005
Spiller Name: RICK
Spiller Company: STUDIO
Spiller Address: 254 WEST 47TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: RICK
Spiller Phone: (212) 719-2733
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 269071
DEC Memo: Hotline generated two spill #'s for this location//See Also Spill #

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SEE SPILL #04-09483 (Continued)

S106971608

04-09264PTC cleaning spill9/30/05 - Raphael Ketani. I received a call on 9/27/05 from Melissa Borg of Laurel Environmental, 52 Elm Street, Huntington, NY 11743, (631) 673-0612 regarding the spill. She said that she wanted to know the status of the case and that she was calling for a bank. She said she was the case manager, but that she didn't know anything about the case. I called up the current owners of the property and spoke to Rick Schussel at (212) 719-2733. He is the artistic director for the non-profit company New Dance Art Center. He told me that the spill took place months ago and involved one of the 2 275 gal. fuel oil tanks. He said it was a very small spill from the bottom of the tank and that PTC came and cleaned up the spill and cleaned out the affected tank. Mr. Schussel added that the spill was on a concrete floor that did not have any holes or cracks. They are not going to use this tank, he said, as the one that is still good is sufficient. He told me that he would FAX the report from PTC. I received the cleanup report and will send a No Further Action letter to New Dance Art Center, 10036.

Remarks:

TANK RUPTURED

Material:

Site ID: 334232
Operable Unit ID: 1096378
Operable Unit: 01
Material ID: 576254
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CW604
WSW
1/4-1/2
0.360 mi.
1902 ft.

GAS STATION
550 WEST 37TH ST
NEW YORK, NY

NY LTANKS **S106702998**
N/A

Site 2 of 2 in cluster CW

Relative:
Lower

LTANKS:

Site ID: 120895
Spill Number/Closed Date: 0010648 / 3/17/2005
Spill Date: 12/22/2000
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 12/22/2000

Actual:
18 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAS STATION (Continued)

S106702998

CID: 281
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 12/22/2000
Spill Record Last Update: 3/17/2005
Spiller Name: PHIL RAZZUTO
Spiller Company: CLASSIC SANATION CO
Spiller Address: 99 RT 3
Spiller City,St,Zip: CLIFTON, NJ 07014-001
Spiller County: 001
Spiller Contact: STAN SUCHARSKI
Spiller Phone: (631) 586-4900
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 104927
DEC Memo:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ROMMEL". This spill case was reassigned from DEC (Sigona) to Rommel on 01/07/2004. On December 22, 2000, DEC (Sigona) observed the excavation and removal of 4 x 550 gallon USTs. The contents of 3 x 550 gallon USTs was found to contain a mixture of gasoline and water. 1 x 550 gallon UST contained water only. The excavation was being performed by Fenely & Nicol for Public Parking, Inc. The project was also supervised by DEC contractor EAR under PIN project for New York Auto Service which was impacting the Jacob Javits Center. Does not appear to be related to New York Auto Service spill or have an impact on the Javits Center. 2/24/05-Vought-Spoke with Phillip Rizzuto (973-470-25510) who is agent for property owners. Rizzuto asked for status of Tank Closure Report review and Vought required that a copy be sent to DEC for review. Spill transferred from Rommel to Vought. 3/16/05-Vought-Reviewed Tank Closure Report (Fenley & Nicol - Angel Ramirez) dated 1/18/01 and received on 3/2/05. Project was prepared for: Mr. Phil Rizzuto Classic Sanitation Corporation 99 Route 3 Clifton, NJ 07014 Removal and closure of one (275-gallon) fuel oil AST and four (550-gallon) gasoline USTs. Subject site is used as a public parking garage. Three (550-gallon) gasoline USTs were removed from the north-east front of the interior of the building (Tank Area 1) and one (550-gallon) gasoline UST was removed from southwest of Tank Area 1. Depth to groundwater at site estimated to be 20 feet below grade and flow to the west. "Inspector Anthony Sigona of the NYSDEC was present at the time of the excavation to inspect the tanks and excavated area". "The bottom and sidewalls of the excavation consisted of Manhattan Schist and bedrock". "...it was discovered that soil above the tanks exhibited evidence of gasoline contamination". All product lines were removed and disposed. Soil were analyzed for 8260/8270 TCLP as per Sigona. Soil analyticals only showed on minor exceedence of naphthalene at 11ug/L (Guidance value is 10ug/L). No PID readings were detected. Report recommends No Further Action. Spill closed by Vought due to one minor TAGM 4046 Soil Cleanup Objective exceedence.

Remarks: DURING TANK REMOVAL SOIL CONTAMINATION HAS BEEN DISCOVERED. CONTAMINATION IS ON TOP OF TANKS. AREA TO BE EXCAVATED AND FURTHER SAMPLING/TESTING TO BE DONE. NO CALL BACK REQUESTED. CALLER HAS BEEN IN CONTACT WITH REGION 2 OFFICE.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

GAS STATION (Continued)

S106702998

Material:

Site ID: 120895
Operable Unit ID: 832683
Operable Unit: 01
Material ID: 544542
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

605
WSW
1/4-1/2
0.364 mi.
1923 ft.

**AD SCHEUMANN LUMBER
524 WEST 36TH STREET
NEW YORK, NY**

NY LTANKS

**S102233238
N/A**

**Relative:
Higher**

LTANKS:

**Actual:
35 ft.**

Site ID: 175887
Spill Number/Closed Date: 9510491 / 1/16/1998
Spill Date: 11/17/1995
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 11/20/1995
CID: 282
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/20/1995
Spill Record Last Update: 11/14/2003
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller County: 999
Spiller Contact: ALAN
Spiller Phone: (212) 594-5555
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 147834

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AD SCHEUMANN LUMBER (Continued)

S102233238

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
Remarks: "MULQUEEN"1/16/98 CROSS REFERENCED TO SPILL NUMBER 9610133. (O'DOWD)
THE TANK POSSIBLY LEAKED.THE TANK IS IN THE GROUND.THEY ARE DOING
TESTS ON THE TANK TO DETERMINE IF IT IS THE TANK OR THE LINE.

Material:

Site ID: 175887
Operable Unit ID: 1024976
Operable Unit: 01
Material ID: 357854
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

606
South
1/4-1/2
0.366 mi.
1933 ft.

307 WEST 36TH STREET
307 WEST 36TH STREET
NEW YORK, NY 10018

NY LTANKS U002222969
NY HIST AST N/A

Relative:
Higher

LTANKS:

Actual:
38 ft.

Site ID: 288307
Spill Number/Closed Date: 9212082 / 7/10/1993
Spill Date: 1/25/1993
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 7/10/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1/25/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/29/1993
Spill Record Last Update: 11/18/1993
Spiller Name: Not reported
Spiller Company: NEW MARK REALTY
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 WEST 36TH STREET (Continued)

U002222969

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 233537
DEC Memo: Not reported
Remarks: 10K A/G BASEMENT TANK IN TANK ROOM CLEANED BY AL EASTMOND ON 1-23-93
STUYVESANT FUEL CO. FILLED TANK APPROX 5 AM 1-25-93 AL EASTMOND
TRUCKS ENROUTE TO PUMP TANK

Material:
Site ID: 288307
Operable Unit ID: 978927
Operable Unit: 01
Material ID: 405458
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

HIST AST:
PBS Number: 2-481858
SWIS Code: 6201
Operator: NEWMARK & CO. REAL ESTATE
Facility Phone: (212) 563-5342
Facility Addr2: 307 WEST 36TH STREET
Facility Type: OTHER
Emergency: FRED WIESENBERG
Emergency Tel: (973) 235-1208
Old PBSNO: Not reported
Date Inspected: Not reported
Inspector: Not reported
Result of Inspection: Not reported
Owner Name: 37TH ARCADE COMPANY, % NEWMARK & COMPANY
Owner Address: 125 PARK AVENUE
Owner City,St,Zip: NEW YORK, NY 10017
Federal ID: Not reported
Owner Tel: (212) 372-2000
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Contact: Not reported
Mailing Name: 37TH ARCADE COMPANY, % NEWMARK & COMPANY
Mailing Address: 125 PARK AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: NEW YORK, NY 10017
Mailing Telephone: (212) 372-2000
Owner Mark: First Owner
Facility Status: 1 - Active PBS facility, i.e. total capacity of the PBS tanks is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

307 WEST 36TH STREET (Continued)

U002222969

greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.

Certification Flag: False
Certification Date: 08/04/2000
Expiration: 09/11/2005
Renew Flag: False
Renew Date: Not reported
Total Capacity: 10000
FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: Minor Data Missing
Dead Letter: False
CBS Number: Not reported
Town or City: NEW YORK CITY
County Code: 62
Town or City Code: 01
Region: 2

Tank ID: 001
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Tank Status: In Service
Install Date: Not reported
Capacity (Gal): 10000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: Not reported
Pipe External: Not reported
Tank Containment: Diking
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

607
NW
1/4-1/2
0.369 mi.
1946 ft.

643 W 43RD ST/UPS
643 W 43RD ST/UPS
NYC, NY

NY LTANKS **S100493387**
N/A

Relative:
Lower

LTANKS:
Site ID: 275410
Spill Number/Closed Date: 9200470 / 8/7/1995
Spill Date: 6/15/1991
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial

Actual:
14 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

643 W 43RD ST/UPS (Continued)

S100493387

Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 8/7/1995

Cleanup Meets Standard: True

SWIS: 3101

Investigator: RWAUSTIN

Referred To: Not reported

Reported to Dept: 4/13/1992

CID: Not reported

Water Affected: Not reported

Spill Notifier: Other

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: True

Remediation Phase: 0

Date Entered In Computer: 4/16/1992

Spill Record Last Update: 8/16/1995

Spiller Name: Not reported

Spiller Company: Not reported

Spiller Address: Not reported

Spiller City,St,Zip: ***Update***, ZZ

Spiller County: 001

Spiller Contact: Not reported

Spiller Phone: Not reported

Spiller Extention: Not reported

DEC Region: 2

DER Facility ID: 223922

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN"

Remarks: HIRED CONTRACTOR TO PULL TANK.

Material:

Site ID: 275410

Operable Unit ID: 967708

Operable Unit: 01

Material ID: 415263

Material Code: 0008

Material Name: Diesel

Case No.: Not reported

Material FA: Petroleum

Quantity: -1

Units: Not reported

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

Site ID: 71800

Spill Number/Closed Date: 9202362 / 3/31/1995

Spill Date: 5/22/1992

Spill Cause: Tank Failure

Spill Source: Commercial/Industrial

Spill Class: Possible release with minimal potential for fire or hazard or Known

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

643 W 43RD ST/UPS (Continued)

S100493387

release with no damage. DEC Response. Willing Responsible Party.
Corrective action taken.

Cleanup Ceased: 3/31/1995
Cleanup Meets Standard: True
SWIS: 3101
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 5/28/1992
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 6/2/1992
Spill Record Last Update: 3/31/1995
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 67897
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"AUSTIN"

Remarks: EXCAVATING CONTAMINATED SOIL TO TANK TOP-25 TANKS TO BE CLOSED.
STOCKPILING SOIL; WILL SAMPLE TEST & DISPOSE. SEE 9200470

Material:

Site ID: 71800
Operable Unit ID: 969639
Operable Unit: 01
Material ID: 413618
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

608
SE
1/4-1/2
0.369 mi.
1948 ft.

570 7TH AVE
570 7TH AVENUE
NEW YORK, NY

NY LTANKS S106703468
N/A

Relative:
Higher

Actual:
52 ft.

LTANKS:

Site ID: 179694
Spill Number/Closed Date: 9006935 / 12/19/2005
Spill Date: 9/25/1990
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unknown Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JAMORAS
Referred To: Not reported
Reported to Dept: 9/25/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/25/1990
Spill Record Last Update: 12/19/2005
Spiller Name: ANGELO PROVVIDO
Spiller Company: SILVERSTEIN PROPERTIES
Spiller Address: 570 SEVENTH AVENUE
Spiller City,St,Zip: NEW YORK, NY 10018-001
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 150810
DEC Memo: 12/19/05 - As noted below, a request was made to Silverstein Properties to provide:1) Copies of all receipts for cleanup work done in Sept 19902) Color photos of the tank room 3) Letter from Silverstein saying what happened to the tank to cause the spill, what was done to fix it, how it was cleaned - Request closure.That information was included in the April 14, 2005 letter from Mr. Angelo Provvido. Relative to point #3, there was not a lot of detail provided relative to how it was cleaned up. I asked Mr. Provvido about that during a telephone conversation; he indicated that current personnel (building manager) was not there in 1990 at the time of the spill. However, the information provided meets the intent of the 4/14/05 request - SPILL CLOSED. (Jim Moras)4/14/2005 Rep from Silverstein Properties called to say the property is being refinanced and needs a closure letter.Sangesland requested:1) Copies of all receipts for cleanup work done in Sept 19902) Color photos of the tank room 3) Letter from Silverstein saying what happened to the tank to cause the spill, what was done to fix it, how it was cleaned - Request closure.

Remarks: PETROLEUM TANK CLEANERS TO DO CLEAN UP, CONTAINED IN TANK ROOM.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

570 7TH AVE (Continued)

S106703468

Material:

Site ID: 179694
Operable Unit ID: 944442
Operable Unit: 01
Material ID: 434370
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5040
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

609
SSE
1/4-1/2
0.370 mi.
1951 ft.

246 WEST 38TH STREET
246 WEST 38TH STREET
MANHATTAN, NY

NY LTANKS

S102672401
N/A

Relative:
Higher

Actual:
42 ft.

LTANKS:

Site ID: 276385
Spill Number/Closed Date: 9313628 / 1/9/1995
Spill Date: 2/20/1994
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 1/9/1995
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2/20/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2/24/1994
Spill Record Last Update: 1/9/1995
Spiller Name: Not reported
Spiller Company: MYSTIC OIL CO.
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 224699

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

246 WEST 38TH STREET (Continued)

S102672401

DEC Memo: Not reported
Remarks: OVERFILLED THE TANK THAT THE CUSTOMER OVER ORDERED.

Material:
Site ID: 276385
Operable Unit ID: 995665
Operable Unit: 01
Material ID: 388999
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CY610
SSW
1/4-1/2
0.371 mi.
1958 ft.

MIDTOWN SOUTH PRECINCT NYPD -DDC
357 WEST 35TH STREET
MANHATTAN, NY
Site 1 of 2 in cluster CY

NY LTANKS **S105054624**
NY Spills **N/A**

Relative:
Higher

Actual:
39 ft.

LTANKS:
Site ID: 79052
Spill Number/Closed Date: 0100463 / 1/10/2005
Spill Date: 3/22/2001
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 4/12/2001
CID: 403
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/12/2001
Spill Record Last Update: 1/10/2005
Spiller Name: SGT MICHAEL SMITH
Spiller Company: NYPD MIDTOWN SOUTH
Spiller Address: 357 WEST 35TH ST
Spiller City,St,Zip: MANHATTAN, NY 10001-
Spiller County: 001
Spiller Contact: SGT MICHAEL SMITH
Spiller Phone: (718) 476-6828

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 270762
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KOLLEENY" TYREE REMOVED A 550-GALLON STEEL SINGLE-WALLED EMERGENCY GENERATOR DIESEL TANK. SOIL HAD PETROLEUM ODOR AND SHEEN. CONTAMINATED SOIL WAS OVER-EXCAVATED AND STOCKPILED; POST-EXCAVATION SAMPLES WERE TAKEN. J. KOLLEENY OF DEC SPOKE WITH LAURIE JODICE OF TYREE ON 4/12/01; SHE WILL FORWARD COPY OF CLOSURE REPORT WHEN AVAILABLE. ACCORDING TO LJ, MOST CONTAMINATION WAS REMOVED AND THE SOIL LEFT IN THE PIT WAS RELATIVELY CLEAN. THE TANK LOCATION WAS VERY CLOSE TO WHERE O'BRIEN-KREITZBERG IS INSTALLING AN SVE SYSTEM TO REMEDIATE GASOLINE CONTAMINATION. KOLLEENY WILL FOLLOW UP TO ENSURE THAT RESIDUAL CONTAMINATION FROM THE EMERG. GEN. TANK (IF ANY) IS ADDRESSED, EITHER BY THE SVE SYSTEM OR IN SOME OTHER WAY. This spill is referred to spill # 9512583 and is closed today by II (01/10/05).
Remarks: WHEN TANK WAS REMOVED THERE WAS AN ODOR OF PETROLEUM. [SEE DEC NOTES.]
Not reported

Material:
Site ID: 79052
Operable Unit ID: 837375
Operable Unit: 01
Material ID: 568852
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:
Facility ID: 0705553
Facility Type: ER
DER Facility ID: 270762
Site ID: 385886
DEC Region: 2
Spill Date: 8/15/2007
Spill Number/Closed Date: 0705553 / 1/4/2008
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 8/15/2007
CID: 444
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/15/2007
Spill Record Last Update:	1/4/2008
Spiller Name:	BILL KILNE
Spiller Company:	MIDTOWN SOUTH POLICE
Spiller Address:	357 WEST 35TH STREET
Spiller City,St,Zip:	NEW YORK, NY
Spiller Company:	001
Contact Name:	BILL KILNE
Contact Phone:	(718) 762-5200
DEC Memo:	Part of a long term recovery operation at the site. See also spill nos. 0702185 and 0702402. 08/16/07: Notified of this spill by Ryan Piper of spill response staff on 8/15/07; sent email to Jane Staten and Harvey Roberts of URS (DDC consultant handling long-term remediation of this site under DDC consent order), with cc to Afsar Samani of DDC, stating: "I've been informed by our Spill Response staff that spills are continuing to occur related to damaged fill line to gasoline UST at Midtown South. Initial spill (0613411) occurred in March '07 when gasoline was found in tank sump and nearby monitoring well. According to URS's system performance reports, Franklin Co. determined that tank's fill line was damaged, and they installed direct fill to tank to bypass damaged line. Do you know if Franklin plugged up old fill port when they installed direct fill? It appears that fuel deliveries continue to be made to old fill line, and product keeps showing up in tank sump and monitoring wells. On May 23rd, spill 0702185 was reported by NYPD because sump was filled with gasoline and Veeder Root alarm was going off. Today, another spill was called in (0705553) because of product in sump. Please take necessary steps to have old fill port blocked so it cannot be used anymore (or repaired so it won't leak) as soon as possible, and please also check out entire tank system to make certain it is damaged fill line that's problem, and that there are no other leaks in system. Please get back to me on this and let me know what actions have been taken to address this situation." Afterwards, spoke again with Ryan Piper, who suggested tank be taken out of service and emptied until problem is solved. Sent email to Afsar Samani of DDC, cc's to Jane Staten & Harvey Roberts of URS: "In light of ongoing problems with gasoline UST at Midtown South Precinct, I strongly suggest that tank be taken out of service and emptied until problem(s) with tank and piping has/have been addressed. If this is not practical because police have no alternative location to fuel their vehicles, then please take whatever steps are necessary to immediately rectify problem(s) with tank system. NYCDDC is conducting remediation at this site using SVE and groundwater extraction & treatment systems, and these ongoing spills of fresh gasoline to subsurface will set back remedial efforts for months, or more likely, years, so it is in DDC's interest to resolve this situation promptly. In addition, these releases are a violation of Environmental Conservation Law, as you are aware, and if they continue to occur, our spill responders may be inclined to call Environmental Conservation Officers to site to issue summons." On 8/16/07, received email from Afsar Samani of DDC: "Harvey informed me that vac-truck is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

scheduled to remove product from sump today. Also, NYPD subcontractor is going to be scheduled to repair fill line. URS is looking into this and will make all necessary action to make sure tank and fill port is tight." Then, received email from Jane Staten of URS: "I just spoke with Lt. Pete Polanco for an update on problems with gasoline tank at Midtown South Precinct. According to Lt. Polanco, NYPD tank contractor inspected fuel fill line this morning and found no problems with integrity of line. Therefore, Lt. Polanco believes that product in tank sump was caused by fuel delivery vendor. NYPD are expecting fuel delivery vendor at site this afternoon to discuss problem and also to remove gasoline currently in sump. I will keep you posted." I then sent email to Afsar Samani, with cc's to Jane Staten & Harvey Roberts of URS, Jerry Aliberti of DDC and Lt. Peter Polanco of NYPD: "Thank you for your response. Please be advised that no fuel deliveries should be made to gasoline tank at Midtown South until tank system has been tested to insure integrity of all elements of system. Documentation of tightness test results, and of any repairs made to fill line since problem was discovered in March 2007, must be submitted to NYSDEC before fuel deliveries can resume. This situation is high priority and NYPD should arrange for tightness testing immediately." Then, received phone call from Lt. Polanco of NYPD, who said repairs to damaged fill line were done in June and fill line was tightness tested and passed, and he believes current problem is due to fuel delivery vendor not hooking up vapor recovery line (truck is parked in street long distance from fill port, so there's long length of delivery hose). He said product will be removed from sump and fill line will be tested again. I asked him to submit documentation of repair work and tightness testing, and sent him email with my address. Then, I was cc'd on email from Afsar Samani of DDC to Lt. Polanco of NYPD: "We were informed by following correspondence from NYSDEC that gasoline tank over at Midtown South Police Precinct should not receive any more deliveries until a tightness test has been scheduled. Please let DDC know when you can arrange for your subcontractor to perform a tightness test on this tank. This is very crucial to remedial effort that URS is performing to clean up site on behalf of DDC." - J. Kolleeny08/21/07: Received fax on 8/20/07 from Lt. Polanco of NYPD fuel control unit, with letter from Energy Tank & Environmental Services dated 7/16/07 describing repairs to and pressure testing of fill line to gasoline UST (in eDocs). Sent same-day email response to Lt. Polanco, cc's to Afsar Samani & Jerry Aliberti (DDC), Jane Staten & Harvey Roberts (URS): "Thank you for faxed description of repair work to fill line of gasoline UST at Midtown South and diagram of site, tank and fill port, provided by Energy Tank & Environmental Services, Inc. However, these items do not completely satisfy my request for documentation of tank repairs and testing of fill line, and they raise additional questions. Page that describes repairs and subsequent pressure testing of line is dated 7/16/07. Is that date when repairs were done? I would like to see dated invoice for repair work in addition to this description. Description states that problem was with primary fill line, and that secondary line was intact, which allowed product to go into containment sump and not into ground. However, in March when this problem was first discovered, URS field personnel reported 5 feet of fresh gasoline in groundwater extraction well that had never had gasoline in it before, so somehow product did get into ground. If repairs were done on 7/16/07, why was gasoline again reported in containment sump on top of tank on August 15th (spill

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

number 0705553)? You mentioned that this was caused by delivery person not hooking up vapor recovery line, yet our Petroleum Bulk Storage staff say this would not result in product appearing in sump. I would greatly appreciate it if you could provide additional documentation of repair work, and if NYPD would schedule a tightness test of all lines going into and out of tank, as well as a hydrostatic test of tank's containment sump. I would like to be informed in advance when these tests have been scheduled, so that I can attend." - J. Kolleeny 09/14/07: Visited site 9/10/07 to observe hydrostatic test of tank sump and tightness test of fill line. Mike Suppe of Fenley & Nichol on hand, said sump held water, more or less (slight drip along electric conduit extending from this sump to next sump at end of tank), for over 2 hours. He said no way to test fill line (it's about 2-3 feet long from "remote" fill port) without physically removing it, but he will test entire tank system. In discussions of how product could turn up in sump, I mentioned that Lt. Polanco said it had to do with delivery person not hooking up vapor recovery line. Mike wasn't clear on how that would cause product to appear in sump. I called Lt. Polanco, who said by not hooking up vapor recovery during delivery, excessive back pressure was created, so when delivery hose was disconnected, product would back up and spill into overfill bucket, then drain to sump. Mike Suppe said this isn't possible, since any fuel spilled into spill bucket would drain back into fill line, then into tank (not sump). Mike suggested that temporary fill, which was used while remote fill line was awaiting repair, had not been properly capped once NYPD switched back to using remote fill, and poor threading on top of direct fill extension cylinder and improperly screwed-on cap for this extension, may have resulted in product spilling out capped off temporary fill, again related to back pressure from not hooking up vapor recovery (see photos in eDocs image folder). NYPD now has on-site a long hose to be used for vapor recovery, and reportedly there have not been any more problems with product appearing in sump after deliveries. Spoke with Mike Suppe on 9/11/07, who said tank system passed test. I discussed whole situation with Jane Staten of URS, who forwarded to me email from Harvey Roberts of URS (in eDocs) indicating temporary direct fill was installed by NYPD, not Franklin Co. as stated in URS's system performance reports for site. While this may explain why product was appearing in sump, none of this adequately explains how product escaped into ground and turned up in groundwater extraction wells and monitoring wells (for site cleanup under spill no. 9512583). Mike Suppe indicated if damaged fill line was unknown for a long time, sump could've filled up with gas during deliveries and overtopped inner rim of sump, and from there it could seep into ground. URS will continue to gauge nearby wells for product levels, and see if they continue to decrease. Harvey Roberts email also calls into question when exactly NYPD had repairs done to fill line. I contact Lt. Polanco again and asked for more detailed documentation of repair work, indicating date(s) and nature of work done. He said he would work on getting me that info. - J. Kolleeny 09/17/07: Received fax from Lt. Polanco, a revised version of earlier fax with statement by Energy Tank & Environmental Services regarding repair work on fuel fill line. Statement is still dated 7/16/07; it now states that they uncovered line on 7/5/07, reconnected and tested line on 7/6/07, reporting that line held pressure during backfilling, they then witnessed a fuel delivery on 7/9/07 with no leaks observed, so they re-surfaced area. - J.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Kolleeny01/04/08: On 12/19/07, sent email to Jane Staten of URS: "I recently asked you to ask your field personnel to check if gasoline is still showing up in tank-top sump after fuel deliveries at this site. Do you know if they've checked on this?" On 12/26/07, received email reply from Jane: "Our field technician checked tank sumps at Midtown South on 11/29/07. One sump was dry and other contained a little water. There was no evidence of gasoline." Based on no new reports of gasoline appearing in tank top sump, it appears problem(s) that caused this and related spills has (have) been addressed; OK to close spill. - J. Kolleeny

Remarks:

PRODUCT IN SUMP

Material:

Site ID: 385886
Operable Unit ID: 1143144
Operable Unit: 01
Material ID: 2133406
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9603073
Facility Type: ER
DER Facility ID: 270762
Site ID: 79053
DEC Region: 2
Spill Date: 6/4/1996
Spill Number/Closed Date: 9603073 / 1/10/2005
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
SWIS: 3101
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 6/4/1996
CID: 351
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/4/1996
Spill Record Last Update: 1/10/2005
Spiller Name: GORDON HEDWIG

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Spiller Company: NYC PD
Spiller Address: 357 WEST 35TH ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: GORDON HEDWIG
Contact Phone: (516) 249-3150
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KOLLEENY" This spill is referred to spill # 9512583 and is closed today by II (01/10/05).

Remarks: caller was removing tanks on site and found contamination

Material:

Site ID: 79053
Operable Unit ID: 1034365
Operable Unit: 01
Material ID: 349311
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0702402
Facility Type: ER
DER Facility ID: 270762
Site ID: 382094
DEC Region: 2
Spill Date: 5/29/2007
Spill Number/Closed Date: 0702402 / 5/29/2007
Spill Cause: Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: jbvought
Referred To: Not reported
Reported to Dept: 5/29/2007
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/29/2007
Spill Record Last Update: 8/15/2007
Spiller Name: BILL KLEINS
Spiller Company: POLICE PRECINT

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Spiller Address: 357 WEST 35TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: BILL KLEINS
Contact Phone: (718) 726-5200
DEC Memo: 05/29/07-Vought-This spill closed and referred to open spill #0702185
at same location.
Remarks: WHILE GAUGING WELLS FOUND CONTAMINATED SOIL

Material:

Site ID: 382094
Operable Unit ID: 1139507
Operable Unit: 01
Material ID: 2129547
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0702185
Facility Type: ER
DER Facility ID: 270762
Site ID: 381862
DEC Region: 2
Spill Date: 5/23/2007
Spill Number/Closed Date: 0702185 / 7/8/2008
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 5/23/2007
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/23/2007
Spill Record Last Update: 7/8/2008
Spiller Name: BOB LARGER
Spiller Company: REMEDIATION SITE
Spiller Address: 357 WEST 35TH STREET
Spiller City,St,Zip: NEW YORK, NY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Spiller Company: 001
Contact Name: BOB LARGER
Contact Phone: (718) 762-5200
DEC Memo: 05/23/07-Vought-Duty desk officer. Vought spoke to Bob Laga(Fax 718-359-7865) and SVE and three groundwater wells onsite with SpillBusters installed and Franklin geologist performing weekly inspections of well and system. Franklin was contacted by NYPD that sump of UST was full of product and alarm for Veeder Root was going off. Franklin performed site visit and approximately 20-50 gallons of gasoline present in sump. Vacuum truck estimated time of arrival in two hours to recover gasoline. As per Franklin field geologist level of product in sump has remained constant (may indicate no loss to subsurface). No product in groundwater monitoring well immediately adjacent to tank with product in sump. Vought discussed site with DEC Krimgold and tightness test letter prepared by Vought and submitted to DEC Falvey for signature. Letter sent with one month due date to owner on PBS and cc to Franklin:NYCPDBuilding Maintenance Section59-06 Brooklyn Queens ExpresswayQueens, NY 1137705/29/07-Vought-See also new closed spill #0702402 for spill caused by delivery to broken fill despite instructions by Franklin to not deliver until fill was repaired. Vought called Franklin and spoke to Bill. Franklin reiterated requirement for no more deliveries. Klein still seeking bids for work.07/08/08: This spill case transferred from J. Vought to J. Kolleeny. Problems with fill port and fuel deliveries have been rectified, any product released to environment will be addressed by remedial system on-site, as there is ongoing remediation under DDC consent order spill 9512583. This spill is closed, see also remarks for spill 0705553. - J. Kolleeny
Remarks: AN ACTIVE REMEDIATION SITE HAS CONTAMINATED SOIL; HAS BEEN SPILL THERE BEFORE: JACOB FROM DEC HAS BEEN THERE BEFORE

Material:
Site ID: 381862
Operable Unit ID: 1139288
Operable Unit: 01
Material ID: 2129312
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0613411
Facility Type: ER
DER Facility ID: 270762
Site ID: 378432
DEC Region: 2
Spill Date: 3/14/2007
Spill Number/Closed Date: 0613411 / 3/14/2007
Spill Cause: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101

Investigator: smsanges

Referred To: Not reported

Reported to Dept: 3/14/2007

CID: 410

Water Affected: Not reported

Spill Source: Unknown

Spill Notifier: Local Agency

Cleanup Ceased: Not reported

Cleanup Meets Std: False

Last Inspection: Not reported

Recommended Penalty: False

UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 3/14/2007

Spill Record Last Update: 3/14/2007

Spiller Name: BILL KLEIN

Spiller Company: NYPD PRECINCT MIDTOWN SOU

Spiller Address: 357 WEST 35TH STREET

Spiller City,St,Zip: MANHATTAN, NY

Spiller Company: 001

Contact Name: BILL KLEIN

Contact Phone: (718) 726-5200

DEC Memo: This site is already an active longterm remediation site - Spill #9512583As part of this remediation effort, there are exisiting monitoring wells on the site that are tested periodically. Today, the geologist found 4 ft of gasoline product floating on the water table in a well that previously had nothing. The manway was checked and found to be full of gasoline as well. This was clearly an overfill from a recent delivery.Franklin and/or URS is working the long term cleanup of the site and has arranged for a vac truck to clear out whatever is possible right now. On a long term basis, the existing remediation system will be used to skim the free product from the water table and remove it from the site.This problem will now be addressed by the contractor through the existing long term spill number on file.

Remarks: MATERIAL IS CONTAINED IN SUMP: POSSIBLY DUE TO OVERFILL, BUT UNCONFIRMED AT THIS TIME:

Material:

Site ID: 378432

Operable Unit ID: 1135936

Operable Unit: 01

Material ID: 2125867

Material Code: 0009

Material Name: Gasoline

Case No.: Not reported

Material FA: Petroleum

Quantity: Not reported

Units: Gallons

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

MIDTOWN SOUTH PRECINCT NYPD -DDC (Continued)

S105054624

[Click this hyperlink](#) while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

CY611 357 W 35TH ST/NYPD
SSW 357 W 35TH ST
1/4-1/2 NYC, NY
0.371 mi.
1958 ft. Site 2 of 2 in cluster CY

NY LTANKS S102671776
N/A

Relative:
Higher

LTANKS:

Actual:
39 ft.

Site ID: 187720
Spill Number/Closed Date: 9109281 / 12/1/1991
Spill Date: 12/1/1991
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 12/1/1991
Cleanup Meets Standard: True
SWIS: 3101
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 12/1/1991
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/6/1991
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: ISLAND TRANS
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 156854
DEC Memo: Not reported
Remarks: FD NOTIFIED.

Material:

Site ID: 187720
Operable Unit ID: 959452
Operable Unit: 01
Material ID: 417918
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

357 W 35TH ST/NYPD (Continued)

S102671776

Resource Affected: Not reported
Oxygenate: False

Tank Test:

612
WNW
1/4-1/2
0.371 mi.
1960 ft.

CE - W. 42ND ST. GAS WORKS
640 W 42ND STREET
NEW YORK, NY 10036

NY ENG CONTROLS
NY INST CONTROL
NY VCP
NY BROWNFIELDS

S106906463
N/A

Relative:
Lower

ENG CONTROLS:

Actual:
16 ft.

Site Code: 57381
HW Code: C231024
Control Code: 15
Control Type: ENG
Date Record Added: 10/31/2006
Date Rec Updated: 06/26/2013
Updated By: SRHEIGEL
Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

INST CONTROL:

Site Code: 57381
Control Name: Environmental Easement
HW Code: C231024
Control Code: J
Control Type: INST
Dt record added: 10/31/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 42ND ST. GAS WORKS (Continued)

S106906463

Dt rec updated: 06/26/2013
Updated By: SRHEIGEL
Site Code: 57381
Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

Site Code: 57381
Control Name: Soil Management Plan
HW Code: C231024
Control Code: 14
Control Type: INST
Dt record added: 10/31/2006
Dt rec updated: 06/26/2013
Updated By: SRHEIGEL
Site Code: 57381
Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 42ND ST. GAS WORKS (Continued)

S106906463

shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

Site Code: 57381

Control Name: Ground Water Use Restriction

HW Code: C231024

Control Code: 08

Control Type: INST

Dt record added: 10/31/2006

Dt rec updated: 06/26/2013

Updated By: SRHEIGEL

Site Code: 57381

Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

Site Code: 57381

Control Name: Landuse Restriction

HW Code: C231024

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 42ND ST. GAS WORKS (Continued)

S106906463

Control Code: 25
Control Type: INST
Dt record added: 10/31/2006
Dt rec updated: 06/26/2013
Updated By: SRHEIGEL
Site Code: 57381
Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

Site Code: 57381
Control Name: Site Management Plan
HW Code: C231024
Control Code: 32
Control Type: INST
Dt record added: 10/31/2006
Dt rec updated: 06/26/2013
Updated By: SRHEIGEL
Site Code: 57381
Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 42ND ST. GAS WORKS (Continued)

S106906463

impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

VCP:

Program Type: VCP
Site Code: 57084
HW Code: V00531
Site Class: A
SWIS: 3101
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 03/05/2002
Date Record Updated: 11/06/2013
Updated By: GWCROSS

Site Description: Location: West 42nd Street Former MGP site is located in an urban area. The site is located on the city block bounded by 41st Street, 42nd St, 11th Ave, and 12th Ave. The former plant also extended west across 12th Ave and into what is now the Hudson River. The main part of the site, bounded by 11th and 12th Avenues has been separated out and has entered the Brownfield Cleanup Program as two separate sites, C231012 and C231024. For the purposes of this description, the site will only refer the remaining portion that was not addressed under the Brownfield clean-up agreements. Site Features: The site is paved with asphalt and concrete. Current Zoning/Uses: The site is not zoned as it is a city right-of-way and is currently in use as 12th Avenue. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. The remaining off-site impacts are also being addressed under this site. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Based upon investigations conducted to date, the site is contaminated with coal tar and its constituents. These constituents include benzene, toluene, ethylbenzene, and xylene (BTEX), and polycyclic aromatic hydrocarbons. The coal tar is found at depths of 10 feet or more

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 42ND ST. GAS WORKS (Continued)

S106906463

below ground surface. It is found at the eastern edge of 12th Avenue and sheens are found at the western edge, implying that coal tar is under the bulk of 12th avenue, between W.41st and W.42nd Streets. Coal tar has also been found under the eastern edge of the building on the south side of W.41st Street. The PAH and BTEX contamination is co-located with the coal tar with the highest concentrations reaching 49,000 ppm for total PAHs and 1,340 ppm for total BTEX. The groundwater plume is mainly confined to the site itself with onsite concentrations as high as 450 ppb for total BTEX and 1,850 ppb for total PAHs.

Health Problem: Not reported

BROWNFIELDS:

Program: BCP

Site Code: 57381

Site Description: Location: The River Place I site is located in Manhattan. It is bounded by 12th Ave., 41st and 42nd Streets, and the River Place II Apartments. Site Features: The site is completely covered by a multi-story apartment building. Current Zoning/Uses: The site is currently in use as an apartment building with commercial space on the ground floor. Historical Uses: The site was used, from the 1860's to the 1920's, as a manufactured gas plant (MGP). Gas was produced through the heating of coal and some petroleum products. This activity led to the contamination of the site. Source areas were the main components of the MGP, including the gas holders. This site was originally to be addressed under the multi-site voluntary cleanup agreement with Con Edison (Site No. V00531) The remaining off-site impacts are being addressed in this manner. Site Geology/ Hydrogeology: The site is underlain by a thick layer of fill, with thin layers of silty and sand underneath that. Bedrock is found as shallow as 20 feet below the ground surface. Groundwater at the site is encountered roughly 7 feet below the ground and generally flows to the south and east.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation the contaminants of concern were benzene, toluene, ethylbenzene, xylene, and polycyclic aromatic hydrocarbons in the soil and groundwater.

Health Problem: Currently direct contact exposure are prevented since the site is covered with a building, pavement and landscaped areas. The proposed remedy calls for the removal of waste from landscaped areas and the continued maintenance of the building and paved areas. Soil gas and indoor air sampling showed no evidence of soil vapor intrusion. Public water is provided to the area, thereby preventing exposures to groundwater.

613
NE
1/4-1/2
0.373 mi.
1972 ft.

**AMERICAN SAVINGS BANK
735 9TH AVENUE
NEW YORK CITY, NY**

**NY LTANKS S102671448
N/A**

**Relative:
Higher**

LTANKS:
Site ID: 107295
Spill Number/Closed Date: 8907585 / 10/31/1989
Spill Date: 10/31/1989
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial

**Actual:
51 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMERICAN SAVINGS BANK (Continued)

S102671448

Spill Class: Not reported
Cleanup Ceased: 10/31/1989
Cleanup Meets Standard: True
SWIS: 3101
Investigator: FINGER
Referred To: Not reported
Reported to Dept: 10/31/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/1/1989
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 94378
DEC Memo: Not reported
Remarks: DRIVER OVER DELIVERED, 5 GALLONS BACKED OUT OF FUEL PIPE ON SIDEWALK,
DRIVER DYKED AREA, OIL CO SENT SPILL TEAM TO CLEAN UP.

Material:

Site ID: 107295
Operable Unit ID: 932533
Operable Unit: 01
Material ID: 444371
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CZ614
NNW
1/4-1/2
0.377 mi.
1990 ft.
639 11TH AVE./MAHATTAN
639 11TH AVE.
NEW YORK CITY, NY
Site 1 of 3 in cluster CZ

NY LTANKS
S100167441
N/A

Relative:
Lower

LTANKS:

Actual:
18 ft.

Site ID: 116097
Spill Number/Closed Date: 8706049 / 7/31/1997
Spill Date: 10/16/1987
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 10/19/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/19/1987
Spill Record Last Update: 8/6/1997
Spiller Name: Not reported
Spiller Company: MR. GUTMAN
Spiller Address: 639 11TH AVE.
Spiller City,St,Zip: N.Y., NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 101059
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN"09/27/95: WAS A BATTISTA SPILL MULQUEEN TOOK OVER IN REF. TO SPILL # 9504912. TRIED TO CONTACT OWNER NUMEROUS TIMES, NO REPLY. AFTER CONSIDERING THE FACT THAT THE SPILL HAS OCCURRED A LONG TIME AGO, AND THE SPILL REMARKS INDICATE NO LONG-TERM FOLLOW-UP IS NEEDED. THIS SPILL HAS BEEN CLOSED.
Remarks: NYCFD WAS AT SIGHT FOR TEST, MR. GUTMAN TO ARRANGE TO UNCOVER AND REPAIR LEAK.

Material:

Site ID: 116097
Operable Unit ID: 909883
Operable Unit: 01
Material ID: 465071
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639 11TH AVE./MAHATTAN (Continued)

S100167441

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 116097
Spill Tank Test: 1531952
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

615
North
1/4-1/2
0.381 mi.
2013 ft.

725 10TH AVENUE
725 10TH AVENUE
MANHATTAN, NY

NY LTANKS
NY Spills

S102672235
N/A

Relative:
Higher

LTANKS:

Actual:
40 ft.

Site ID: 216380
Spill Number/Closed Date: 9308145 / 10/5/1993
Spill Date: 10/5/1993
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 10/5/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 10/5/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/5/1993
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 179143
DEC Memo: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

725 10TH AVENUE (Continued)

S102672235

Remarks: GUAGE MALFUNCTION - GAVE WRONG ON HANDING - SENT SPILL CREW - WILL
APPLY SPEEDY DRY.

Material:

Site ID: 216380
Operable Unit ID: 989670
Operable Unit: 01
Material ID: 394385
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 1010636
Facility Type: ER
DER Facility ID: 399155
Site ID: 444250
DEC Region: 2
Spill Date: 1/14/2011
Spill Number/Closed Date: 1010636 / 1/26/2011
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 1/14/2011
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/14/2011
Spill Record Last Update: 1/26/2011
Spiller Name: Not reported
Spiller Company: THE BUILDING
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: TOMMY - SUPERINTENDENT
Contact Phone: (212) 586-3400
DEC Memo: spill from boiler on floor. approx 500-1000 gallons down drain.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

725 10TH AVENUE (Continued)

S102672235

Remarks: Surface cleanup is relatively small. Drain is believed to go to Amtrak tracks below. I spoke with AMtrak rep who walked the tracks. they found no oil. DEP was informed and surface spill was taken care of. Followup for closure. Release to city sanitary system. Surface cleanup complete and repairs have been made. Spill closed. Tommy reported to Castle Oil over 1000 gallons in basement down the drain - No cleanup noted as of yet - possibly from a boiler malfunction

Material:

Site ID: 444250
Operable Unit ID: 1194693
Operable Unit: 01
Material ID: 2190558
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1000
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DA616 **CON EDISON - WEST 45TH ST. GAS WORKS MGP**
NW **12TH AVE BETWEEN WEST 44TH AND WEST 46TH STS.**
1/4-1/2 **NEW YORK, NY 10019**

EDR MGP **1008407995**
N/A

0.382 mi.
2017 ft.

Site 1 of 2 in cluster DA

Relative: Manufactured Gas Plants:
Lower No additional information available

Actual:
13 ft.

DA617 **CON EDISON - 12TH AVE. WORKS MGP**
NW **12TH AVE BETWEEN W 46TH AND W. 45TH**
1/4-1/2 **NEW YORK, NY 10019**

EDR MGP **1008407975**
N/A

0.382 mi.
2017 ft.

Site 2 of 2 in cluster DA

Relative: Manufactured Gas Plants:
Lower No additional information available

Actual:
13 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

618
NNE
1/4-1/2
0.385 mi.
2033 ft.

442 WEST 50TH ST
442 WEST 50TH ST
MANHATTAN, NY

NY LTANKS

S103517567
N/A

Relative:
Higher

Actual:
44 ft.

LTANKS:

Site ID: 257123
Spill Number/Closed Date: 9711517 / 1/14/1998
Spill Date: 1/14/1998
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1/14/1998
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/14/1998
Spill Record Last Update: 1/15/1998
Spiller Name: CHARLIE
Spiller Company: MYSTIC OIL
Spiller Address: 19-01 STEINWAY ST
Spiller City,St,Zip: ASTORIA, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 210539
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MARTINKAT"
Remarks: CALLER REPORTED TANK OVERFILLED. CLEANUP IN PROGRESS.

Material:

Site ID: 257123
Operable Unit ID: 1054271
Operable Unit: 01
Material ID: 326169
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 8
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

442 WEST 50TH ST (Continued)

S103517567

Tank Test:

619
West
1/4-1/2
0.390 mi.
2058 ft.

EMERGENCY GARAGE
LINCOLN TUNNEL EMERG GARA
MANHATTAN, NY

NY LTANKS **S100167777**
N/A

Relative:
Lower

LTANKS:

Actual:
18 ft.

Site ID: 65500
Spill Number/Closed Date: 8908614 / 2/27/2003
Spill Date: 11/30/1989
Spill Cause: Tank Test Failure
Spill Source: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 11/30/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/10/1990
Spill Record Last Update: 2/27/2003
Spiller Name: Not reported
Spiller Company: PORT AUTH NY
Spiller Address: CATHY ROSTOCK(CONTACT)
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 62886
DEC Memo: Not reported
Remarks: 2K TANK FAILED HONER EZY CECK WITH A GROSS LEAK, WILL PUMP TANK, WILL ISOLATE & RETEST, PROBLEM WITH FRINGED MANHOLE.

Material:

Site ID: 65500
Operable Unit ID: 933662
Operable Unit: 01
Material ID: 445349
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EMERGENCY GARAGE (Continued)

S100167777

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 65500
Spill Tank Test: 1536502
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

**620
SSE
1/4-1/2
0.391 mi.
2062 ft.**

**PRIVATE REISDENCE
252 WEST 37TH STREET
MANHATTAN, NY**

**NY LTANKS
NY Spills**

**S103517615
N/A**

**Relative:
Higher**

LTANKS:

**Actual:
39 ft.**

Site ID: 333697
Spill Number/Closed Date: 0409059 / 8/18/2006
Spill Date: 11/9/2004
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: qxabidi
Referred To: Not reported
Reported to Dept: 11/9/2004
CID: 407
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/16/2004
Spill Record Last Update: 8/18/2006
Spiller Name: CASTLE OIL
Spiller Company: CASTLE OIL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: CASTLE OIL
Spiller Phone: (718) 579-3480
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 268948
DEC Memo: Tipple responded, oil impacted sidewalk, roadway along curb and

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIVATE REISDENCE (Continued)

S103517615

Con-Ed transformer vault. Con-Ed advised of impact, surfaces cleaned, awaiting documentation. PBS# 2-15227707/31/06: This spill is transferred from Mr. Koon Tang to Q. Abidi. Called to Mr. Angelo Solimine (718)499-2900 and talk to Ms. Mili (Secretary) she will find information regarding spill and she will call me back. -QA08/15/06: Called Angelo solimine (T&S Trucking Co.)and talked to Mr. John Bari he said he will find out the report and he will fax me. -QA08/18/06: Recieved a closing confirmation letter from Mr. Eston Clare, Sr. Manager (T & S) Trucking Company in which he mentioned that approximate 10 to 15 gals of #6 oil due to defective gauge caused oil to spill while Delivery was being made. T & S Trucking Company sent their Spill Crew at that private residence same day. The Crew cleaned everything that had been stained. Based on the information DEC staff closed the spill. -QA

Remarks: faulty gauge oil came out of vent: oil went into coned vault and coned was notified: michele tippie was advised from dec:

Material:

Tank Test:

SPILLS:

Facility ID: 9608844
Facility Type: ER
DER Facility ID: 101562
Site ID: 116742
DEC Region: 2
Spill Date: 10/16/1996
Spill Number/Closed Date: 9608844 / 2/9/2005
Spill Cause: Equipment Failure
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 10/16/1996
CID: 233
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/16/1996
Spill Record Last Update: 2/9/2005
Spiller Name: PAT MCHUGH
Spiller Company: CON EDISON
Spiller Address: 128 WEST END AVENUE
Spiller City,St,Zip: NEW YORK, NY 10023
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PRIVATE REISDENCE (Continued)

S103517615

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"2/9/05: Con Ed inspected vault: "Site visit was performed and no oil was found - Also, CINDE database indicates site was visited by a crew after the initial incident and no report of oil was made." Close out. (JHO)

Remarks: transformer failure some material may have gone into sewercrew will be sent as soon as possible not enroute yet at least 5 gallons contained in a vault

Material:

Site ID: 116742

Operable Unit ID: 1036981

Operable Unit: 01

Material ID: 561146

Material Code: 0020A

Material Name: TRANSFORMER OIL

Case No.: Not reported

Material FA: Petroleum

Quantity: 6

Units: Gallons

Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

621
SE
1/4-1/2
0.394 mi.
2079 ft.

VAULT #0708
214 WEST 38TH ST/7TH AV
MANHATTAN, NY

NY LTANKS S102239651
N/A

Relative:
Higher

LTANKS:

Site ID: 326607

Spill Number/Closed Date: 9600319 / 10/1/1998

Spill Date: 4/8/1996

Spill Cause: Tank Overfill

Spill Source: Commercial/Industrial

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported

Cleanup Meets Standard: False

SWIS: 3101

Investigator: MMMULQUE

Referred To: Not reported

Reported to Dept: 4/8/1996

CID: 297

Water Affected: Not reported

Spill Notifier: Affected Persons

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: False

Remediation Phase: 0

Date Entered In Computer: 4/8/1996

Spill Record Last Update: 10/1/1998

Spiller Name: UNKNOWN

Spiller Company: UNKNOWN

Actual:
54 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VAULT #0708 (Continued)

S102239651

Spiller Address: UNKNOWN
Spiller City,St,Zip: UNKNOWN, NY
Spiller County: 999
Spiller Contact: RICHARD ROACH
Spiller Phone: (212) 580-6764
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 263103
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MULQUEEN" PBS INFO NOT CORRECT. SPILL OUT VENT PIPE ABOVE VAULT.
Remarks: CON EDISON FOUND FUEL OIL LEAKING INTO THEIR VAULT FROM AN ADJACENT APARTMENT BUILDING WHICH HAD JUST RECEIVED A SHIPMENT OF OIL, AT THIS POINT IT IS UNKNOWN WHO DELIVERED THE OIL, AND THE OIL IS ALSO ON THE SIDE OF THE BUILDING AND RUNNING INTO THE STREET - MR ROACH WILL NOTIFY NTC DEP AND AT THIS POINT CLEAN UP HAS NOT BEEN STARTED

Material:
Site ID: 326607
Operable Unit ID: 1027999
Operable Unit: 01
Material ID: 353715
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

622
SE
1/4-1/2
0.397 mi.
2096 ft.

**7 TIMES SQUARE
7 TIMES SQUARE
NEW YORK, NY**

**NY LTANKS S107417153
N/A**

**Relative:
Higher**

LTANKS:
Site ID: 354867
Spill Number/Closed Date: 0509142 / 11/1/2005
Spill Date: 10/31/2005
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 10/31/2005
CID: 444
Water Affected: Not reported
Spill Notifier: Other

**Actual:
55 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

7 TIMES SQUARE (Continued)

S107417153

Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/31/2005
Spill Record Last Update: 11/1/2005
Spiller Name: Not reported
Spiller Company: FUEL CO
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: ROCK HARDING
Spiller Phone: (212) 391-0760
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 304878
DEC Memo: Mr. Harding confirmed that the spill was cleaned by the oil company.
Remarks: OVERFILL OF TANK AND IS BEING CLEANED UP AT THIS TIME: IS DIKED AND NO WATER EFFECTED:

Material:

Site ID: 354867
Operable Unit ID: 1112256
Operable Unit: 01
Material ID: 2102298
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**CZ623
NNW
1/4-1/2
0.398 mi.
2103 ft.**

**SPILL NUMBER 0203467
612-614 WEST 47TH ST
MANHATTAN, NY
Site 2 of 3 in cluster CZ**

**NY LTANKS S105996204
N/A**

**Relative:
Lower**

LTANKS:

Site ID: 98434
Spill Number/Closed Date: 0203467 / 3/7/2003
Spill Date: 7/2/2002
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unknown Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: WYNE
Referred To: Not reported

**Actual:
16 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0203467 (Continued)

S105996204

Reported to Dept: 7/2/2002
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 7/2/2002
Spill Record Last Update: 3/7/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller County: 001
Spiller Contact: CARMELLA KORTLANG
Spiller Phone: (631) 419-0913
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 87589
DEC Memo: Not reported
Remarks: caller did environmental assessment of property and soil samples showed contamination

Material:

Site ID: 98434
Operable Unit ID: 854299
Operable Unit: 01
Material ID: 521299
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

CZ624
NNW
1/4-1/2
0.400 mi.
2110 ft.
CONSTRUCTION SITE
617-623 WEST 47TH STREET
MANHATTAN, NY
Site 3 of 3 in cluster CZ

NY LTANKS
NY Spills
S107408696
N/A

Relative:
Lower

LTANKS:
Site ID: 351906
Spill Number/Closed Date: 0506652 / 9/20/2006
Spill Date: 8/30/2005
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported

Actual:
17 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

Cleanup Meets Standard: False
SWIS: 3101
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 8/30/2005
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/30/2005
Spill Record Last Update: 11/10/2006
Spiller Name: JEROME KUNG
Spiller Company: CONSTRUCTION SITE
Spiller Address: 607-611 & 617-623 WEST 47
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: JEROME KUNG
Spiller Phone: (212) 338-6754
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 309155
DEC Memo: Sangesland spoke to rep from Gannet Flemming - no need to send a CSL
- They know the process and will submit a report as soon as the work
is complete9/9/05-Vought-Spoke to Joel Rogers (Gannett Flemming
516-671-8440) and contaminated soil was removed and endpoint samples
were collected. One fuel oil UST and one gasoline UST onsite.
Groundwater was present in the bottom of the excavation. Samples were
also collected from piping runs and remote fills. One groundwater
sample was collected. Active construction going on. Endpoint samples
did show TAGM exceedences. Site is DEP E site and vapor barrier will
be installed. Groundwater at 12' below grade. Groundwater samples
were below TOGS and therefore no passive ventilation system. Site
will be excavated down to bedrock over most of site. Minor PAH
exceedences attributable to fill material. One soil sample had
63000ppb naphthalene. Additional soil excavation required at area of
excavation. After excavation for foundation is complete sidewall
samples and bottom groundwater samples will be collected. Dewatering
will occur for building construction. Groundwater samples show minor
PAH and MTBE exceedence. See also spills 0506800, 0507015. Two
additional 550-gallon USTs discovered. DEC requires: soil endpoint
samples and groundwater samples upon reaching limits of excavation
for foundation.10/18/05-Vought-Site visit by Vought on 10/14/05.
Onsite was Jessica Ferngreem(Gannett Fleming) and Jerome Kung (Verizon
646-483-6554). Also on site were owners of 607 West 47th Street
(Felix Guralnik) See also spill #. Free product coming from under 607
West 47th Street and flowing into groundwater in excavacion of
adjacent Verizon site. Site visit to 607 West 47th street showed
waste oil tanks in very poor condition and numerous puddles of waste
oil on garage floor. DEC required Verizon: 1)collection of one
endpoint soil sample from sidewall under 607 West 47th st 2)submission
of analyticals of free product sample 3)regular intermittent
sampling of dewatering effluent as remedial method 4)submission of
PBS registration. NYCDEP discharge permit obtained by Verizon. Vought
called Joel Rogers and left message that he will be faxed a copy of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

the letter. Vought also faxed copy to Ferngren and emailed to Kung. 11/28/05-Vought-Received message from Rogers that hydraulic line ruptured. Vought returned call and line broke from construction equipment. Spill on perched water on bedrock and will be cleaned using adsorbent pads and boom. No further action on this minor spill required. 05/05/06-Vought-See also closed spill #0507015 at same location.05/17/06-Vought-Spill transferred from DEC Vought to DEC Ketani as per DEC Austin.6/22/06 - Raphael Ketani. I spoke to Ms. Jessica Ferngren ((516) 669-1504)of Gannett Fleming. She said they are almost ready to send DEC the closure report. She said that the wall of the neighboring building was waterproofed. [This spill is downgradient from a garage (605 W. 47 St.) with 2 waste oil tanks and sloppy housekeeping.]7/10/06 - Raphael Ketani. I spoke to Ms. Ferngren. She said the closure report will probably be sent in August. Right now it is being reviewed by the client.8/17/06 - Raphael Ketani. I tried to reach Ms. Ferngren, but could only leave a voice mail.9/6/06 - Raphael Ketani. Ms. Ferngren left me a message requesting my mailing address. I sent her a message back with the correct address.9/15/06 - Raphael Ketani. The following tanks were removed from the site: 3000 gal., 5000 gal., five 550 gal., and a 275 gal. However, there are no PBS records or registrations for the site. I finished reviewing the September 2006 Underground Storage Tank and Spill Closure Report. There were moderate to extremely high concentrations of SVOCs at some of the boring locations. Most of these locations are associated with tanks that have been removed or their piping,though a few are not.9/18/06 - Raphael Ketani. I spoke to Ms. Ferngren about the need to register the tanks and about the very high SVOC concentrations at some of the former tank locations. She said that the soils at the tank locations looked clean, but staff in her office couldn't figure out why the results were so high. She just figures there was urban fill mixed in. I told her that these high sites were at the former locations of the tanks. She said that the soil looked clean and that all of the soil was removed anyway and delivered to a facility that takes very contaminated soil. She said she will send in a PBS registration form. 9/20/06 - Raphael Ketani. Nick Lombardo of the PBS Unit came over to me to discuss the PBS registration for the site. He said that Ms. Ferngren had told him that the site is registered. He showed me a PBS registration for the neighboring property, 610-630 W. 48 Street. He said that Ms. Ferngren told him this was the same property as the new owners had combined both 617-623 and 610-630, and planned to build on both. The registration for 610-630 is #2-344818 and shows all of the tanks listed in the September 2006 Underground Storage Tank and Spill Closure Report as closed and removed, and even lists other tanks not indicated in the report for 617-623. I spoke to Ms. Ferngren and told her DEC would prefer that the form list 617-623 as this is where the majority of the tanks came from. She asked whether both addresses can be listed on the registration form. I spoke to Mr. Lombardo and he said that she should get Verizon to submit a letter to DEC requesting that both addresses be listed. I relayed the message to Ms. Ferngren. She agreed to do this.Based upon the Underground Storage Tank and Spill Closure Report and the PBS registration #2-344818, I am closing the spill case.

Remarks: WHILE EXCAVATING TANK FOUND SOIL CONTAMINATION: TOOK SAMPLPES:

Material:
Site ID:

351906

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

Operable Unit ID: 1109407
Operable Unit: 01
Material ID: 2099436
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 0507015
Facility Type: ER
DER Facility ID: 309155
Site ID: 352334
DEC Region: 2
Spill Date: 9/9/2005
Spill Number/Closed Date: 0507015 / 5/5/2006
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 3101
Investigator: JBOUGHT
Referred To: Not reported
Reported to Dept: 9/9/2005
CID: 408
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/9/2005
Spill Record Last Update: 5/5/2006
Spiller Name: JEROME KUNG
Spiller Company: CONSTRUCTION SITE
Spiller Address: 607*-611 AND 617-623 WEST
Spiller City,St,Zip: MANHATTEN, NY
Spiller Company: 001
Contact Name: JEROME KUNG
Contact Phone: (646) 483-6554
DEC Memo: 9/9/05-Vought-Spoke to Joel Rogers (Gannett Flemming 516-671-8440) and contaminated soil was removed and endpoint samples were collected. One fuel oil UST and one gasoline UST onsite. Groundwater was present in the bottom of the excavation. Samples were also collected from piping runs and remote fills. One groundwater sample was collected. Active construction going on. Endpoint samples did show TAGM exceedences. Site is DEP E site and vapor barrier will be

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

installed. Groundwater at 12' below grade. Groundwater samples were below TOGS and therefore no passive ventilation system. Site will be excavated down to bedrock over most of site. Minor PAH exceedences attributable to fill material. One soil sample had 63000ppb naphthalene. Additional soil excavation required at area of excavation. After excavation for foundation is complete sidewall samples and bottom groundwater samples will be collected. Dewatering will occur for building construction. Groundwater samples show minor PAH and MTBE exceedence. See also spills 0506800, 0507015. Two additional 550-gallon USTs discovered. DEC requires: soil endpoint samples and groundwater samples upon reaching limits of excavation for foundation 10/13/05-Vought-Spoke to Joel Rogers and see also spill #0506652, 0506800, 0507015 and 0508375. All three spill numbers will be addressed in one report. Three spill numbers will be consolidated once bedrock is reached and dewatering begins. 10/18/05-Vought-Site visit by Vought on 10/14/05. Onsite was Jessica Ferngrem (Gannett Fleming) and Jerome Kung (Verizon 646-483-6554). Also on site were owners of 607 West 47th Street (Felix Guralnik) See also spill #. Free product coming from under 607 West 47th Street and flowing into groundwater in excavation of adjacent Verizon site. Site visit to 607 West 47th street showed waste oil tanks in very poor condition and numerous puddles of waste oil on garage floor. DEC required Verizon: 1) collection of one endpoint soil sample from sidewall under 607 West 47th st 2) submission of analyticals of free product sample 3) regular intermittent sampling of dewatering effluent as remedial method 4) submission of PBS registration. NYCDEP discharge permit obtained by Verizon. Vought called Joel Rogers and left message that he will be faxed a copy of the letter. Vought also faxed copy to Ferngrem and emailed to Kung. 10/21/05-Vought-Received call from Greg Earnst (Gannett Fleming). Vought returned call and left message to return call. Vought spoke to Earnst and west side of 607 West 47th Street had product coming from under building. Vought did not require new spill number due to existing spill number 0508375. Product will be vacuumed out and underpinning will be installed. Paint on membrane will be applied to underpinning and voids will be filled with cement slurry. 10/25/05-Vought-ECO will be performing site visit to 607 West 47th Street on 10/24/05. Vought received call from Joel Rogers. Vought returned call and left message to return call. Vought received second call from Rogers. Vought returned call and spoke with Rogers. 11/15/2005-Vought-Spoke with Joel Rogers and he will include tank closure report with above requirements and report will be submitted by 1/15/06. 05/05/06-Vought-This spill closed and referred to open spill #0506652 at same location.

Remarks: DURING EXCAVATION, SOIL CONTAMINATION WAS FOUND, POSSABLY BELEIVED TO BE GASOLINE, UNKNOWN AT THIS TIME. SAMPLES WERE TAKEN

Material:

Site ID: 352334
Operable Unit ID: 1109838
Operable Unit: 01
Material ID: 2099856
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0506800
Facility Type: ER
DER Facility ID: 309155
Site ID: 352082
DEC Region: 2
Spill Date: 9/2/2005
Spill Number/Closed Date: 0506800 / 6/23/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 9/2/2005
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/2/2005
Spill Record Last Update: 6/23/2006
Spiller Name: JEROME KUNG
Spiller Company: 607-611 617-623
Spiller Address: WEST 47TH STREET
Spiller City,St,Zip: MANHATTEN, NY
Spiller Company: 001
Contact Name: JEROME KUNG
Contact Phone: (212) 338-6754
DEC Memo: 9/9/05-Vought-Spoke to Joel Rogers (Gannett Flemming 516-671-8440) and contaminated soil was removed and endpoint samples were collected. One fuel oil UST and one gasoline UST onsite. Groundwater was present in the bottom of the excavation. Samples were also collected from piping runs and remote fills. One groundwater sample was collected. Active construction going on. Endpoint samples did show TAGM exceedences. Site is DEP E site and vapor barrier will be installed. Groundwater at 12' below grade. Groundwater samples were below TOGS and therefore no passive ventilation system. Site will be excavated down to bedrock over most of site. Minor PAH exceedences attributable to fill material. One soil sample had 63000ppb naphthalene. Additional soil excavation required at area of excavation. After excavation for foundation is complete sidewall samples and bottom groundwater samples will be collected. Dewatering will occur for building construction. Groundwater samples show minor PAH and MTBE exceedence. See also spills 0506800, 0507015, 0506652. Two additional 550-gallon USTs discovered. DEC requires: soil endpoint samples and groundwater samples upon reaching limits of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S107408696

excavation for foundation10/18/05-Vought-Site visit by Vought on 10/14/05. Onsite was Jessica Ferngreem(Gannett Fleming) and Jerome Kung (Verizon 646-483-6554). Also on site were owners of 607 West 47th Street (Felix Guralnik) See also spill #. Free product coming from under 607 West 47th Street and flowing into groundwater in excavcation of adjacent Verizon site. Site visit to 607 West 47th street showed waste oil tanks in very poor condition and numerous puddles of waste oil on garage floor. DEC required Verizon:
1)collection of one endpoint soil sample from sidewalk under 607 West 47th st 2)submission of analyticals of free product sample 3)regular intermittent sampling of dewatering effluent as remedial method 4)submission of PBS registration. NYCDEP discharge permit obtained by Verizon. Vought called Joel Rogers and left message that he will be faxed a copy of the letter. Vought also faxed copy to Ferngreem and emailed to Kung. 3/21/06- DEC Piper spoke w/ Joel Rogers.. As per conversation, pbs records in order, he will be collecting endpoint/ sidewalk samples soon. Report to DEC in approx 2 mos.3/26/06- DEC Piper, same spill site as 0506652. Hydraulic oil cleaned up. Petroleum contamination related to sp 0506652. This spill closed. AN OLD HYDRALIC PISTON LEAKED: ALL CLEANED UP;

Remarks:

Material:

Site ID: 352082
Operable Unit ID: 1109596
Operable Unit: 01
Material ID: 2099605
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: 2
Resource Affected: Not reported
Oxygenate: False

Tank Test:

625
SSW
1/4-1/2
0.404 mi.
2135 ft.

BASEMENT OF
333 WEST 34TH ST
MANHATTAN, NY

NY LTANKS
NY Spills

S104502515
N/A

Relative:
Higher

LTANKS:

Site ID: 285598
Spill Number/Closed Date: 0305833 / 11/14/2005
Spill Date: 9/2/2003
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: LJALDEN
Referred To: Not reported

Actual:
39 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BASEMENT OF (Continued)

S104502515

Reported to Dept: 9/2/2003
CID: 199
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/2/2003
Spill Record Last Update: 11/14/2005
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: UDNAUTH MATHURA
Spiller Phone: (212) 615-9365
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 284732
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND" Sent TTF letter to consultant: Maria Ramirez, GZA, 65 Willowbrook Blvd, Wayne, NJ 07470 11/5/2003 Sangesland spoke with Maria Ramirez at GZA. She says the building is converting to natural gas and the 10,000 gal tank will be abandoned in place. Tank is below the basement floor under an electrical utility room. They cleaned out the tank and found holes in the top 1/3 of the tank. They will take borings through the bottom of the tank to determine if the area is contaminated. 12/4/2003 e-mail message from Maria Ramirez said the soil borings through the bottom of the tank would take place around 12/12/03. 12/11/2003 Sangesland reviewed a submittal from Maria Ramirez of GZA dated Nov 19, 2003. This outlined the the work discussed above and stated that 4 holes will be drilled through the bottom of the tank and samples will be collected for testing (if possible-it may be in cement). If the samples are clean, the tank will be abandoned in place with foam. 12/22/2003 Sangesland spoke with Fran Schultz of GZA about this site. They made 4 holes in the bottom and sides of this tank and hit cement. Water is entering the tank. To date approx 700 gal of water has entered the tank. They believe the water is from a broken water main. Sangesland asked GZA to test the water for VOC and SVOC. GZA said they would also test for Floride and Clorine to determine if this water is city tap water or groundwater. If the water samples come back clean, then GZA will prepare an arguement that the tank is in a subbasement vault. All records of the building (blueprints) are gone (they were in 7 World Trade Center). There are lots of utilities nearby. The tank is being abandoned in place. GZA will request closure of the spill number. 3/15/2004 Sangesland reviewed a report from Maria Ramirez of GZA. Based on the description of the tank location (below ConEd electrical equipment), the drilling of holes through the bottom and sides of the tank (all into cement), results of water tests on the water that came into the tank after drilling (no petroleum but did have Floride & Chlorine). Based on all of this information, the DEC will allow GZA to go ahead with abandonment of the tank. After proper abandonment is complete, GZA will submit a final report with a request for spill closure. 11/14/05 - Larry Alden - Reviewed file and concur with assessment of Sangesland (3/15/04). Reviewed PBS#

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BASEMENT OF (Continued)

S104502515

Remarks: 2-606121, which showed that 10,000-gallon tank was closed in-place on 7/8/04. With absence of any contamination, and tank subsequently closed, this spill can be closed.
failed a tightness test but could not isolate a specific pipe - test was performed as part of a closure.

Material:

Site ID: 285598
Operable Unit ID: 872431
Operable Unit: 01
Material ID: 555298
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 285598
Spill Tank Test: 1528632
Tank Number: 1
Tank Size: 10000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

SPILLS:

Facility ID: 9610567
Facility Type: ER
DER Facility ID: 231592
Site ID: 285599
DEC Region: 2
Spill Date: 11/22/1996
Spill Number/Closed Date: 9610567 / 1/10/1997
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 11/22/1996
CID: 323
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BASEMENT OF (Continued)

S104502515

Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 11/22/1996
Spill Record Last Update: 1/10/1997
Spiller Name: DICK MURPHY
Spiller Company: SMITH BARNEY
Spiller Address: 333 WEST 34TH ST
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller Company: 001
Contact Name: DICK MURPHY
Contact Phone: (212) 356-2548
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ENGELHARDT"Spill onto concrete/blacktop. Entered adjacent basement
through doorway affecting steel stairway and cement floor. spill
cleaned with sorbal by Walco.

Remarks: VENT ALARM DOES NOT WORK. WAS REPLACED.

Material:
Site ID: 285599
Operable Unit ID: 1042019
Operable Unit: 01
Material ID: 342779
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 25
Units: Gallons
Recovered: 25
Resource Affected: Not reported
Oxygenate: False

Tank Test:

626
South
1/4-1/2
0.406 mi.
2146 ft.

APRT
505 8TH AVE
NY, NY 10018

NY LTANKS S108131253
N/A

Relative:
Higher

LTANKS:
Site ID: 368946
Spill Number/Closed Date: 0605725 / 3/26/2007
Spill Date: 8/17/2006
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: BKFALVEY
Referred To: Not reported
Reported to Dept: 8/17/2006
CID: 444
Water Affected: Not reported

Actual:
37 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APRT (Continued)

S108131253

Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/17/2006
Spill Record Last Update: 3/26/2007
Spiller Name: MARLIN JOSEPH
Spiller Company: APRT
Spiller Address: 505 8TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: MARLIN JOSEPH
Spiller Phone: (718) 624-4842
Spiller Extention: 109
DEC Region: 2
DER Facility ID: 9237
DEC Memo: 8/31/06 - ttf letter sent. bf.10/16/06 received a letter from Anthony Lara of Petroleum Tank. tank was encased in concrete (#6 fuel oil). tank was pumped out and cleaned. fill line was cemented tank was removed from site. bf11/8/06 spoke to Anthony Lara. needs to send disposal manifests. bf1/31/07 spoke with A. Lara. He will fax manifest for waste tomorrow morning. According to him, there was one drum of material. bf3/14/07 Spoke with A. Lara. He said it was two drums of material. Sent me a copy of invoice to show this. No closure application received. This case can not proceed without closure of the tank. Called A. Lara back and told him this. Faxed PBS closure application to him. fax: (718)858-4268. bf3/26/07 On 3/21/07, received letter and closure application for tank. NFA. bf
Remarks: TANK WAS LEAKING AND HAS BEEN PUMPED OUT

Material:

Site ID: 368946
Operable Unit ID: 1126798
Operable Unit: 01
Material ID: 2116364
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 368946
Spill Tank Test: 1550202
Tank Number: 1
Tank Size: 5000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 8/17/2006

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APRT (Continued)

S108131253

Test Method: Horner EZ Check I or II

627
NNW
1/4-1/2
0.407 mi.
2148 ft.

605 WEST 47TH STREET
605 WEST 47TH STREET
MANHATTAN, NY

NY LTANKS S106471516
N/A

Relative:
Lower

LTANKS:

Actual:
16 ft.

Site ID: 132269
Spill Number/Closed Date: 0400961 / 11/17/2004
Spill Date: 4/28/2004
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 4/28/2004
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/28/2004
Spill Record Last Update: 11/17/2004
Spiller Name: MARK LEVINE
Spiller Company: Not reported
Spiller Address: 605 WEST 47TH STREET
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: MARK LEVINE
Spiller Phone: (212) 925-1950
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 113904
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KRIMGOLD" Contaminated soil letter sent to: Raber Enterprises LLC Attn: Marc Levine 175 Canal St. New York, NY 10013 Mr. Levine says a phase II investigation was done as part of a property sale. The new owner has hired Langan Engineering to remove the tank and any contaminated soil. Contact at Langan Engineering is: Tarek Khouri 212-479-5400 5/6/2004 Sangesland spoke to Mr. Khouri from Langan Engineering. He confirmed that the area will be excavated and the tank removed. They will take photographs of the hole and will take endpoint samples to be tested for VOC's & Sock's. A final report will be prepared and forwarded to Jake Krimgold. 5/11/04. J.Krimgold @ site. Contractor unable to remove the tank due to a structural constraints. Will excavate contaminated soil around tank and close tank in-place. Agreed that at least three post-excavation samples will be taken. J.Krimgold observed excavation and found two more UST partially filled with gasoline and water. Preliminary observation

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

605 WEST 47TH STREET (Continued)

S106471516

suggests that the size of tanks 1080 and 550 gal. The current owner has no knowledge of these tanks. Also no records was found in PBS DB. J.Krimgold requested immediately register all tanks at this site with PBS unit before continuation of tank closure.11/17/04. J.Krimgold has reviewed the report dated June 28, 2004 submitted to the Department by Langan Engineering regarding the above mentioned site. Based on the information provided, the petroleum release which was on this site has been satisfactorily cleaned up and all USTs has been closed in place or removed. PBS application was filed. Therefore, no further investigation or response will be required concerning the petroleum contamination at these specific sites at this time. NFA letter.

Remarks:

WILL BE REMOVING TANK AND SOIL:

Material:

Site ID: 132269
Operable Unit ID: 885138
Operable Unit: 01
Material ID: 492193
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

628
WSW
1/4-1/2
0.414 mi.
2184 ft.

CONSTRUCTION SITE
529 WEST 35TH ST
MANHATTAN, NY

NY LTANKS **S105055174**
N/A

Relative:
Higher

LTANKS:

Actual:
36 ft.

Site ID: 246701
Spill Number/Closed Date: 0103274 / 12/13/2001
Spill Date: 6/25/2001
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 6/25/2001
CID: 382
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CONSTRUCTION SITE (Continued)

S105055174

Remediation Phase: 0
Date Entered In Computer: 6/25/2001
Spill Record Last Update: 12/13/2001
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller County: 001
Spiller Contact: GARY ZAID
Spiller Phone: (212) 736-1626
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 202580
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"8/2001-Tank closure report prepared by Franklin Company Contractors. 6/29/2001-Franklin implemented bioremediation by mixing 240lbs of ORC with surrounding soils and filling in excavation. 500 gallons of Waste stream technologies W-4 bio-blend mixture also injected.. Site was bakcfilled with 3 to 6 feet of clean fill, 6 inches of crushed stone and an 8-mil polyethylene vapor barrier. Area was then covered with 6 inch reinforced concrete slab. Soil VOC pass TAGM, soil SVOC exceed TAGM but are due to fill composition. Site visit by Jacob Krimgold showed no visual evidence of contamination. Groundwater VOC and SVOC also pass TAGM. 12/13/2001 Spill closed as per Mark Tibbe, Jacob Krimgold and myself (all NYSDEC personnel).
Remarks: SOIL SAMPLE RESULTS FROM REMOVAL OF 3 TANKS AT LOCATION. NO VISABLE SIGNS OF CONTAMINATION.

Material:
Site ID: 246701
Operable Unit ID: 841954
Operable Unit: 01
Material ID: 535365
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

629
SSE
1/4-1/2
0.414 mi.
2186 ft.

APARTMENT BUILDING
261 WEST 36TH STREET
MANHATTAN, NY

NY LTANKS S104950889
N/A

Relative:
Higher

LTANKS:
Site ID: 76906
Spill Number/Closed Date: 0011776 / 3/22/2001
Spill Date: 1/31/2001
Spill Cause: Tank Failure

Actual:
38 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BUILDING (Continued)

S104950889

Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 1/31/2001
CID: 282
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/31/2001
Spill Record Last Update: 3/22/2001
Spiller Name: N/A
Spiller Company: NEWMARK AND COMPANY
Spiller Address: N/A
Spiller City,St,Zip: N/A, ZZ
Spiller County: 001
Spiller Contact: ISAAC MUNGRA
Spiller Phone: (718) 624-4842
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 71815
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"KRMINGOLD" PETROLEUM TANK CLEANERS ON SITE. FIXED THE TANK AND CLEANED
UP THE SPILL.
Remarks: THE TANK (5,000 GALLON) LEAKED ABOUT 20 GALLONS WAS SPILLED.

Material:
Site ID: 76906
Operable Unit ID: 833715
Operable Unit: 01
Material ID: 542073
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: 20
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DB630
SW
1/4-1/2
0.424 mi.
2237 ft.
AMOCO
436 TENTH AVE
NEW YORK, NY 10018
Site 1 of 2 in cluster DB

NY LTANKS **S107410233**
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:

Site ID: 250195
Spill Number/Closed Date: 9905246 / 8/27/1999
Spill Date: 8/1/1999
Spill Cause: Tank Overfill
Spill Source: Gasoline Station
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SACCACIO
Referred To: Not reported
Reported to Dept: 8/1/1999
CID: 246
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 8/1/1999
Spill Record Last Update: 8/23/2005
Spiller Name: Not reported
Spiller Company: CONSOLIDATED TRANSPORTATI
Spiller Address: ON
Spiller City,St,Zip: ENWOOD LONG ISLAND, NY
Spiller County: 001
Spiller Contact: JULIO CALDER
Spiller Phone: (718) 389-4910
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 11535
DEC Memo: Not reported
Remarks: tank was overfilled at location - speedy dry applied - cleanup crew
enroute - some material may have flowed into storm drain and
streetupdate 0400 hrs - spill only 5-7 gal all cleaned up - none
entered waterway

Material:

Site ID: 250195
Operable Unit ID: 1079677
Operable Unit: 01
Material ID: 301550
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO (Continued)

S107410233

Tank Test:

DB631
SW
1/4-1/2
0.424 mi.
2237 ft.

AMOCO
436 TENTH AVE
NEW YORK, NY 10018

NY LTANKS S107410213
N/A

Site 2 of 2 in cluster DB

Relative:
Higher

LTANKS:

Actual:
40 ft.

Site ID: 158202
Spill Number/Closed Date: 9506257 / 5/3/2002
Spill Date: 8/21/1995
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: O'DOWD
Referred To: Not reported
Reported to Dept: 8/21/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/27/1995
Spill Record Last Update: 8/23/2005
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 11535
DEC Memo: O'Dowd Notes(KMF):Amoco will submit affadavit of work done, any contamination noted and passing tank test results. Will have to look up PBS# to see if any old USTs were here and if a site assessment was done.8/21/95 2X4K failed UST-2000 Ullage Test.8/22/95 Spoke to Jerry Kasper, Crompco. 1X4K has the extractor valve and 1X4K doesn't. Leak was above the liquid line. Problem believed to be with extractor valve. 5/3/2002-VOUGHT-See spill #0201270 at same location. This spill closed by Vought.

Remarks: TANKS WERE OINSPECTED AND BOTH FAILED

Material:

Site ID: 158202
Operable Unit ID: 1017138
Operable Unit: 01
Material ID: 558531

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO (Continued)

S107410213

Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 158202
Spill Tank Test: 1544101
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

632
SSE
1/4-1/2
0.428 mi.
2258 ft.

500 7TH AVENUE
500 7TH AVENUE
NEW YORK, NY

NY LTANKS S102671393
N/A

Relative:
Higher

Actual:
45 ft.

LTANKS:
Site ID: 79518
Spill Number/Closed Date: 8901132 / 2/13/2003
Spill Date: 5/4/1989
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 5/4/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/5/1989
Spill Record Last Update: 3/14/2003
Spiller Name: Not reported
Spiller Company: HEMSLEY-SPEAR INC
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

500 7TH AVENUE (Continued)

S102671393

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 73826
DEC Memo: Not reported
Remarks: (3) 10,000 GALLON TANKS LEAKING, SPILL TOOK PLACE IN TANK ROOM.

Material:
Site ID: 79518
Operable Unit ID: 927270
Operable Unit: 01
Material ID: 452440
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 79518
Spill Tank Test: 1535426
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

DC633 **ATC MANAGEMENT**
NNW **605 WEST 48TH ST**
1/4-1/2 **MANHATTAN, NY 10036**
0.429 mi.
2266 ft. **Site 1 of 2 in cluster DC**

NY LTANKS **S107417116**
N/A

Relative:
Lower

LTANKS:
Site ID: 354734
Spill Number/Closed Date: 0509022 / 3/17/2006
Spill Date: 10/27/2005
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 10/27/2005
CID: 409

Actual:
19 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATC MANAGEMENT (Continued)

S107417116

Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/27/2005
Spill Record Last Update: 3/29/2006
Spiller Name: JOE BERNADI
Spiller Company: ATC MANAGEMENT
Spiller Address: 605 WEST 48TH ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: JOE BERNADI
Spiller Phone: (917) 337-1702
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 304748
DEC Memo: need to send a TTF letter 11/7/05 - Raphael Ketani. I am sending a TTF letter today regarding the site. I will send one copy to Angela Donnolo, ATC Management, 1501 Broadway, NY, 10036, and one to 605 West 48 Street, LLC. Nov. 7, 2005 A "Tank Test Failure Letter" was sent to: Joseph Dounolo Advanced Cout. Corporation 605 West 48th St. New York, NY 10036 12/1/05 - Raphael Ketani. Letter received from Thomas Leddy, President of Pro Test ((718) 815-6292. Piping is disconnected from the two tanks. Tanks are partially excavated. Studying feasibility of removing the tanks or bioremediation of soil around and under tanks. 12/21/05 - Raphael Ketani. I spoke to Mr. Leddy and he said that one tank was pumped out, but the other is still leaking into the sub-basement. Nothing has happened at the site, as far as he knows, and he doesn't know if another contractor was hired to cleanup the site. 1/4/06 - Raphael Ketani. I spoke to Mr. Joe Bernotas of ATC Management ((917) 337-1702). He is not the owner, but works for the owner. He said that the tanks are out of the ground and empty, but he is waiting for the environmental company to clean out the tanks and get rid of them. 2/8/06 - Raphael Ketani. Jerry Tiss of JLC ((212) 420-8119/ (917) 617-3894) called me to say that they removed the tanks. He said that the problem was a leaking fill line. I told him all of the contaminated soil has to be removed. He asked whether the soil under the sidewalk had to be removed. I told him "yes." He said he couldn't get too close to a neighboring building to get more contaminated soil as the wall is brick. I told him I would need an engineers letter telling me that he can't go any further. He said he would get it. Mr. Tiss said that he will take 2 end-point samples after removing the contaminated soil. I told him to send me the results. He said he would. 2/13/06 - Raphael Ketani. I received a FAX from Mr. Tiss. The letter discusses whether there is a need to remove more soil, but doesn't address safety, structural integrity issues. The letter states that the site has been satisfactorily remediated, pending the results of samples that were sent to the lab. 2/15/06 - Raphael Ketani. I received a revised 2/10/06 letter from Mr. Tiss of JLC. It states that they can't go any further without damage to the foundation and structural elements. 3/2/06 - Raphael Ketani. I tried to call Mr. Tiss, but could only leave a message. 3/15/06 - Raphael Ketani. I spoke to Mr. Tiss today. I asked him what is happening on the site. He said that they filled in the pit and have received the analytical soil results. I asked him to send the results. 3/16/06 -

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ATC MANAGEMENT (Continued)

S107417116

Remarks: Raphael Ketani. I received the soil analytical results today. 3/17/06
- Raphael Ketani. I reviewed the soil analytical results and found
them as either non-detect or a few SVOCs that were just above TAGM.
In light of the received documentation and the engineer's letter, I
am closing the case.3/29/06 - Raphael Ketani. Mr. Bernotas of ATC
Management called to request an NFA letter. I told him I will send
one out for the site.
no remarks.

Material:

Site ID: 354734
Operable Unit ID: 1112126
Operable Unit: 01
Material ID: 2102166
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 354734
Spill Tank Test: 1549461
Tank Number: 1
Tank Size: 550
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 10/27/2005
Test Method: Horner EZ Check I or II
Site ID: 354734
Spill Tank Test: 1549462
Tank Number: 2
Tank Size: 550
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Watchdog
Last Modified: 10/27/2005
Test Method: Horner EZ Check I or II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

634
North
1/4-1/2
0.433 mi.
2288 ft.

X
520 WEST 50TH ST
MANHATTAN, NY

NY LTANKS

S105997526
N/A

Relative:
Lower

LTANKS:

Actual:
22 ft.

Site ID: 69513
Spill Number/Closed Date: 0209190 / 1/24/2006
Spill Date: 12/6/2002
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3101
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 12/6/2002
CID: 199
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/6/2002
Spill Record Last Update: 1/24/2006
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: MARIA AILIVA
Spiller Phone: (212) 362-9298
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 66082
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"SAWYER"ARAKHAN 12/09/2002 TANK TEST FAILURE LETTER SENT ON
12/09.02/04/04Transferred from Vought to Sawyer12/1/05- DEC Piper
spoke w/ property manger Marcia Trainor, at Merlot Mangement. TTF
Letter faxed and mailed to her attention F 212.362.1036She will start
pulling file.1/24/06- DEC Piper reviewed info provided by Merlot
Mgmt., replaced vent line and passed test on 2/26/03. Spill closed.
Remarks: vent line is leaking - line will be repaired and retested

Material:

Site ID: 69513
Operable Unit ID: 862359
Operable Unit: 01
Material ID: 516168
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

X (Continued)

S105997526

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 69513
Spill Tank Test: 1527798
Tank Number: 1
Tank Size: 2000
Test Method: 03
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

DD635 **34TH ST. & 10TH AVE./AMOC**
SW **34TH ST. & 10TH AVE.**
1/4-1/2 **NEW YORK CITY, NY**
0.435 mi.
2297 ft. **Site 1 of 2 in cluster DD**

NY LTANKS **S100143829**
N/A

Relative:
Higher

LTANKS:

Actual:
35 ft.

Site ID: 122904
Spill Number/Closed Date: 8705645 / 10/5/1987
Spill Date: 10/5/1987
Spill Cause: Tank Failure
Spill Source: Tank Truck
Spill Class: Not reported
Cleanup Ceased: 10/5/1987
Cleanup Meets Standard: True
SWIS: 3101
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 10/5/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/7/1987
Spill Record Last Update: 5/2/1989
Spiller Name: Not reported
Spiller Company: AMOCO
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 106534
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "
Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

34TH ST. & 10TH AVE./AMOC (Continued)

S100143829

Remarks: TANK OVERFILL ONE OR TWO TIMES A WEEK DURING SERVICE, APPROXIMATELY 50 GALLONS.

Material:

Site ID: 122904
Operable Unit ID: 909469
Operable Unit: 01
Material ID: 468231
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 122904
Spill Tank Test: 1531827
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

DD636 **34TH ST. AND 10TH AVE./AM**
SW **34TH ST.& 10TH AVE.**
1/4-1/2 **NEW YORK CITY, NY**
0.435 mi.
2297 ft.

NY LTANKS **S102671194**
N/A

Site 2 of 2 in cluster DD

Relative:
Higher

LTANKS:

Site ID: 86947
Spill Number/Closed Date: 8704567 / 9/1/1987
Spill Date: 9/1/1987
Spill Cause: Tank Overfill
Spill Source: Gasoline Station
Spill Class: Not reported
Cleanup Ceased: 9/1/1987
Cleanup Meets Standard: True
SWIS: 3101
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 9/1/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Citizen
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0

Actual:
35 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

34TH ST. AND 10TH AVE./AM (Continued)

S102671194

Date Entered In Computer: 9/10/1987
Spill Record Last Update: 10/7/1988
Spiller Name: Not reported
Spiller Company: AMOCO GAS STATION
Spiller Address: 34TH ST.& 10TH AVE.
Spiller City,St,Zip: N.Y., NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 79704
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "
Not reported
Remarks: TANK TRUCK (LICENSE PLATE # AP7359) INVOLVED IN TANK OVERFILL.

Material:
Site ID: 86947
Operable Unit ID: 911052
Operable Unit: 01
Material ID: 467199
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DC637
NNW
1/4-1/2
0.438 mi.
2311 ft.

**624 WEST 48TH ST
624 WEST 48TH ST
NEW YORK CITY, NY
Site 2 of 2 in cluster DC**

**NY LTANKS S102147958
N/A**

**Relative:
Lower**

LTANKS:
Site ID: 82463
Spill Number/Closed Date: 8709100 / 2/23/1993
Spill Date: 1/25/1988
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 2/23/1993
Cleanup Meets Standard: False
SWIS: 3101
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 1/25/1988
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester

**Actual:
18 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 WEST 48TH ST (Continued)

S102147958

Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/26/1988
Spill Record Last Update: 7/18/1996
Spiller Name: Not reported
Spiller Company: NEW YORK TELEPHONE
Spiller Address: 624 WEST 48TH ST
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 76031
DEC Memo: Not reported
Remarks: 7.5K TANK ISOLATED FROM PIPING, FAILED PETRO TITE TEST WITH A LEAK RATE OF -.395GPH.

Material:

Site ID: 82463
Operable Unit ID: 914190
Operable Unit: 01
Material ID: 464438
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 82463
Spill Tank Test: 1533091
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

638
SSE
1/4-1/2
0.438 mi.
2315 ft.

240 WEST 36TH ST./COMMERC
240 WEST 36TH ST.
NEW YORK CITY, NY

NY LTANKS S104275484
N/A

Relative:
Higher

LTANKS:

Actual:
39 ft.

Site ID: 197832
Spill Number/Closed Date: 8705735 / 10/7/1987
Spill Date: 10/7/1987
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 10/7/1987
Cleanup Meets Standard: True
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 10/7/1987
CID: Not reported
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/30/1987
Spill Record Last Update: 8/4/1995
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 164632
DEC Memo: Not reported
Remarks: OVERFLOW IN BASEMENT BUT WAS CONTAINED.

Material:

Site ID: 197832
Operable Unit ID: 911796
Operable Unit: 01
Material ID: 468313
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 500
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

639
NE
1/4-1/2
0.439 mi.
2318 ft.

EXCAVATION SITE
763 9TH AVE
MANHATTAN, NY

NY LTANKS
NY Spills

S105058468
N/A

Relative:
Higher

Actual:
54 ft.

LTANKS:

Site ID: 75595
Spill Number/Closed Date: 0102767 / 5/10/2005
Spill Date: 6/8/2001
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: LNKLAAS
Referred To: Not reported
Reported to Dept: 6/13/2001
CID: 257
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 6/13/2001
Spill Record Last Update: 2/9/2006
Spiller Name: RICHARD DELASANDRO
Spiller Company: Not reported
Spiller Address: 763 9TH AVE
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: RICHARD DELASANDRO
Spiller Phone: (917) 806-0995
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 70742
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M
TIBBE"Transferred from Tibbe to Klaas.Refer to 0103420.
Remarks: TANK HAS A SMALL LEAK - PROPERTY MANAGER IS MK REALITY 212-974-5400

Material:

Site ID: 75595
Operable Unit ID: 841454
Operable Unit: 01
Material ID: 534876
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXCAVATION SITE (Continued)

S105058468

Tank Test:

SPILLS:

Facility ID: 0103420
Facility Type: ER
DER Facility ID: 168168
Site ID: 202162
DEC Region: 2
Spill Date: 5/15/2001
Spill Number/Closed Date: 0103420 / 9/7/2001
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 6/28/2001
CID: 323
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 6/28/2001
Spill Record Last Update: 12/11/2003
Spiller Name: RICHARD D'ALESSANDRO
Spiller Company: ANNA'S
Spiller Address: 763 NINTH AVE
Spiller City,St,Zip: MANHATTAN, ZZ
Spiller Company: 001
Contact Name: RICHARD D'ALESSANDRO
Contact Phone: (917) 806-0995
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"A.L. Eastmond was originally called out to the site. Smell in the resturant from the oil tank in the basement.Eastmond found an open flap on the top of a 275gal? tank in the basement. Eastmond Cleaned the tank and rewelded the patch. Eastmond also said that the area was clean.8/13/2001 Sangesland went to the site and met Bonnie Weiss from Ferrantino Fuel Oil (718-832-6700) and the property owner. The building is empty except for the resturant. The upper floors are under renovation for new apartments.The tank had a cement case built around it. Upon inspection, an area of heavy black oil was coming out from under this enclosure. Sangesland said that the area must be opened up to look under the tank, if a leak existed, then the floor around the tank would need to be inspected and if cracks were found, the floor would need to be opened. Ms. Weiss suggested that the owner would probably install a new 275 gal tank elsewhere in the basement and totally remove the old tank and enclosure. Sangesland requested a reinspection when the area was cleaned. Sangesland will send a letter to Ms. Weiss with detail directions of what to do.9/6/2001 Sangesland re inspected the site today. Cement enclosure

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXCAVATION SITE (Continued)

S105058468

around the tank had been removed, tank was cleaned and free standing on the floor. 1" thick skim layer of cement floor had been chopped up under the tank. Cement floor under this 1" thick layer appeared to be solid and secure. Area was clean and no sign of further contamination. Spill Will Be Closed NOTE: DEC will require follow up documentation within 3 months (by Dec. 6, 2001) that either a new oil tank was installed at this site, OR the existing tank was reinstalled and then pressure tested to confirm the tank's structural integrity. 11/19/2001 - Bonnie Weiss called to find specific details of what additional work the DEC required for the newly installed tank. DEC requested a notice from the tank company describing what work they did and that the tank was tested and passed (by what method?) Tank work is being done now, Bonnie will forward this information to the DEC when it is done.

Remarks: OIL TANK LEAKING IN THE BASEMENT. THERE IS A STRONG ODOR AND IT IS VERY UNHEALTHY.

Material:

Site ID: 202162
Operable Unit ID: 840096
Operable Unit: 01
Material ID: 555642
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 1010363
Facility Type: ER
DER Facility ID: 70742
Site ID: 443965
DEC Region: 2
Spill Date: 1/4/2011
Spill Number/Closed Date: 1010363 / 2/24/2011
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 1/4/2011
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EXCAVATION SITE (Continued)

S105058468

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/4/2011
Spill Record Last Update: 2/24/2011
Spiller Name: CON EDISON
Spiller Company: OWNER
Spiller Address: 763 9TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 999
Contact Name: CON EDISON
Contact Phone: (212) 580-6763
DEC Memo: 2/24/11 - Austin - Con Ed discovered product in vicinity of fill line i/f/o 763 Ninth Ave. - Location had at least two spil events (#0103420 and 0102767) reported previously, including a bad tank No indication that either prior spill led to this problem - Con Ed contained and cleaned up the spill - see additional info in the eDocs files - spill closed - end

Remarks: 1 Pint of fuel oil spilled on site. Cleanup is in process.

Material:
Site ID: 443965
Operable Unit ID: 1194409
Operable Unit: 01
Material ID: 2190209
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0.01
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

640
WSW
1/4-1/2
0.441 mi.
2329 ft.

527 WEST 34TH ST
527 WEST 34TH ST
NEW YORK (County), NY

NY LTANKS S112231173
N/A

Relative:
Higher

LTANKS:
Site ID: 380286
Spill Number/Closed Date: 0750112 / 4/23/2007
Spill Date: 4/10/2007
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 4/23/2007

Actual:
36 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

527 WEST 34TH ST (Continued)

S112231173

CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/23/2007
Spill Record Last Update: 4/23/2007
Spiller Name: Not reported
Spiller Company: 527 WEST 34TH ST
Spiller Address: 527 WEST 34TH ST
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 329760
DEC Memo: referred from COn Ed See also Spill #0700391duplicate spill. case closed. refer to old case.
Remarks: Leaked from a building into Vault #3863

Material:

Site ID: 380286
Operable Unit ID: 1137770
Operable Unit: 01
Material ID: 2127726
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Gallons
Recovered: 4
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**641
NNW
1/4-1/2
0.443 mi.
2341 ft.**

**624 W. 48TH STREET
624 WEST 48TH STREET
MANHATTAN, NY**

**NY LTANKS
NY Spills
S102148544
N/A**

**Relative:
Lower**

LTANKS:

Site ID: 315734
Spill Number/Closed Date: 9408956 / 8/6/1996
Spill Date: 10/5/1994
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

**Actual:
17 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 W. 48TH STREET (Continued)

S102148544

SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 10/5/1994
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/2/1994
Spill Record Last Update: 4/17/1997
Spiller Name: Not reported
Spiller Company: NYNEX
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 130848
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"
Remarks: WILL INVESTIGATE-POSS. REPLACE TANK

Material:

Site ID: 315734
Operable Unit ID: 1003024
Operable Unit: 01
Material ID: 378379
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 315734
Spill Tank Test: 1543214
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 W. 48TH STREET (Continued)

S102148544

SPILLS:

Facility ID: 9405727
Facility Type: ER
DER Facility ID: 130848
Site ID: 112763
DEC Region: 2
Spill Date: 7/26/1994
Spill Number/Closed Date: 9405727 / 2/13/2003
Spill Cause: Unknown
Spill Class: No spill occurred. No DEC Response. No corrective action required.
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 7/27/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/18/1994
Spill Record Last Update: 11/17/2003
Spiller Name: Not reported
Spiller Company: 630 W. 48TH STREET
Spiller Address: Not reported
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: DISCOVERED SOIL IN EXCAVATION OF OLD TANKS- TO REPLACE WITH NEW TANKS

Material:

Site ID: 112763
Operable Unit ID: 1002928
Operable Unit: 01
Material ID: 382312
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9405547
Facility Type: ER
DER Facility ID: 130848

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 W. 48TH STREET (Continued)

S102148544

Site ID: 315732
DEC Region: 2
Spill Date: 7/23/1994
Spill Number/Closed Date: 9405547 / 7/25/1994
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 7/25/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: 7/25/1994
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/18/1994
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: NYNEX
Spiller Address: 624 W. 48TH STREET
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MARTINKAT"
Remarks: VAN'S GAS TANK RUPTURED NYCFD ON SCENE-CLEANED UP WITH SPEEDY DRY AND
ABSORBENT.

Material:
Site ID: 315732
Operable Unit ID: 1002757
Operable Unit: 01
Material ID: 382127
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 12
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9405647
Facility Type: ER
DER Facility ID: 130848
Site ID: 315733

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 W. 48TH STREET (Continued)

S102148544

DEC Region: 2
Spill Date: 7/23/1994
Spill Number/Closed Date: 9405647 / 8/11/1994
Spill Cause: Traffic Accident
Spill Class: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 7/26/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 8/11/1994
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/17/1994
Spill Record Last Update: 10/20/1994
Spiller Name: Not reported
Spiller Company: NYNEX
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"TIBBE"10/10/95: This is additional information about material
spilled from the translation of the old spill file: HYDRAL OIL.
HYDRAL-LINE BROKE-ABSORP USED-DRUMMED UP

Remarks:

Material:

Site ID: 315733
Operable Unit ID: 999953
Operable Unit: 01
Material ID: 382232
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9314832
Facility Type: ER
DER Facility ID: 130848
Site ID: 154293
DEC Region: 2
Spill Date: 3/18/1994

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

624 W. 48TH STREET (Continued)

S102148544

Spill Number/Closed Date: 9314832 / 8/6/1996
Spill Cause: Unknown
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 3/18/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 3/21/1994
Spill Record Last Update: 4/17/1997
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"TIBBE"10/10/95: This is additional information about material
spilled from the translation of the old spill file: SOIL BORE HOLES.
Remarks: TANK WILL BE REMOVED & NEW TANKS INSTALL (MARK TIBBE).

Material:

Site ID: 154293
Operable Unit ID: 996765
Operable Unit: 01
Material ID: 386613
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

642
ENE
1/4-1/2
0.444 mi.
2344 ft.

233 W 49TH ST
233 W 49TH ST
MANHATTAN, NY

NY LTANKS

S103038519
N/A

Relative:
Higher

Actual:
55 ft.

LTANKS:

Site ID: 155306
Spill Number/Closed Date: 9713530 / 3/6/1998
Spill Date: 3/6/1998
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 3/6/1998
CID: 255
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/6/1998
Spill Record Last Update: 3/2/1999
Spiller Name: CHARLES LAHEY
Spiller Company: WEATHER FUEL
Spiller Address: 802 JAMAICA AV
Spiller City,St,Zip: BROOKLYN, NY 11208-001
Spiller Contact: CHARLES LAHEY
Spiller Phone: (718) 647-1268
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 131552
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" Tank overfill. Speedy dry already deployed. Looks like around 10 gallons on sidewalk and in street. A few gallons on floor in basement. Oil in sump. Instructed super and ABC tank cleaners that sidewalk should be cleaned of speedy dry, cleaned with hot water and the wash water collected in a vac truck. Basement should have free oil removed, hot water cleaned and the oil/oily water vac'd from the sump. Sump pump to be di-activated until cleanup complete. Nick Marsic is building super ((212)265-3266 extension 386)). Monica Clark is building manager ((212) 265-3266 extension 309)). Notified DEP. Briefed Al Gordon.

Remarks: Customer order - tank overfill - outside and some in basement - is calling clean up crew now for basement - speedy dry put down outside.

Material:

Site ID: 155306
Operable Unit ID: 1059488
Operable Unit: 01
Material ID: 324543
Material Code: 0001A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

233 W 49TH ST (Continued)

S103038519

Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 12
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

643
NE
1/4-1/2
0.444 mi.
2346 ft.

360 WEST 51ST STREET
360 WEST 51ST STREET
MANHATTAN, NY

NY LTANKS **S104620794**
N/A

Relative:
Higher

LTANKS:

Actual:
57 ft.

Site ID: 148731
Spill Number/Closed Date: 9911885 / 11/16/2005
Spill Date: 1/13/2000
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: iabeilby
Referred To: Not reported
Reported to Dept: 1/13/2000
CID: 266
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/13/2000
Spill Record Last Update: 11/16/2005
Spiller Name: Not reported
Spiller Company: EMPIRE STATE OIL
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: JUDY SHOTWELL
Spiller Phone: (212) 397-5944
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 126554
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M
TIBBE"11/16/05 - Ian Beilby: Fax was received from former property
owner with affidavit that <0.5 gal of #2 fuel oil had been spilled
and cleaned up at that site on 1/13/00. NFA Letter sent 11/16/05.
Remarks: SPILLER OVERFILLED TANK, SPILLING OIL ONTO OUTSIDE OF RESIDENCE.
NOTIFIER DIDN'T NOTICE THIS UNTIL AFTER OIL DELIVERY TRUCK LEFT.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

360 WEST 51ST STREET (Continued)

S104620794

SPILLER HAS DONE THIS NUMEROUS TIMES BEFORE. THE LAST SPILL WAS ON 1/3/00 (DEP #111354). NOTIFIER HAS NOT CONTACTED SPILLER YET BECAUSE THEY GAVE HERE A HARD TIME LAST TIME. NOTIFIER WOULD LIKE DEC AND/OR DEP ASSISTANCE.

Material:

Site ID: 148731
Operable Unit ID: 1086424
Operable Unit: 01
Material ID: 297323
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DE644
NW
1/4-1/2
0.448 mi.
2363 ft.

**CON EDISON (12TH AVE AND 45TH STREET)
12TH AVENUE AND 45TH STREET
NEW YORK, NY 10036**

**NY SWF/LF S105265278
N/A**

Site 1 of 2 in cluster DE

**Relative:
Lower**

SWF/LF:

Flag: INACTIVE
Region Code: 2
Phone Number: 2124602362
Owner Name: CON EDISON CO OF NY; INC.
Owner Type: Private
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Email: Not reported
Owner Phone: 2124604833
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: C&D processing - registration
Activity Number: [31W17]
Active: No
East Coordinate: 0
North Coordinate: 0
Accuracy Code: Not reported
Regulatory Status: Registration
Waste Type: Not reported
Authorization #: 0
Authorization Date: Not reported
Expiration Date: Not reported

**Actual:
9 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DE645
NW
1/4-1/2
0.448 mi.
2363 ft.
CON-EDISON @ SERVICE CENTER
12TH AVENUE &45TH STREET
NEW YORK, NY 10036
Site 2 of 2 in cluster DE

NY SWF/LF
NY MANIFEST
S105841933
N/A

Relative:
Lower

SWF/LF:

Flag: INACTIVE
Region Code: 2
Phone Number: 2124604833
Owner Name: Not reported
Owner Type: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Email: Not reported
Owner Phone: Not reported
Contact Name: HARRY A. COATES
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: C&D processing - registration
Activity Number: [31W19]
Active: No
East Coordinate: Not reported
North Coordinate: Not reported
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported

Actual:
9 ft.

NY MANIFEST:

EPA ID: NYP004246171
Country: USA

Mailing Info:

Name: CONED
Contact: CONED
Address: 4 IRVING PLACE
Address 2: 15TH FLOOR
City/State/Zip: NEW YORK, NY 10003
Country: USA
Phone: Not reported

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-01-06
Trans1 Recv Date: 2012-01-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-01-06
Part A Recv Date: Not reported
Part B Recv Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON-EDISON @ SERVICE CENTER (Continued)

S105841933

Generator EPA ID: NYP004246171
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 009204649JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 2012-01-06
Trans1 Recv Date: 2012-01-06
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2012-01-06
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004246171
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSD ID: NJD002200046
Waste Code: Not reported
Quantity: 1000.0
Units: P - Pounds
Number of Containers: 1.0
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1.0
Year: 2012
Manifest Tracking Num: 009204649JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CON-EDISON @ SERVICE CENTER (Continued)

S105841933

Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H111

646
NNE
1/4-1/2
0.452 mi.
2385 ft.

CLINTON GREEN DEVELOPMENT PROJECT
51ST - 53RD ST. & 10TH AVE.
NEW YORK, NY 10109

NY BROWNFIELDS

S106906459
N/A

Relative:
Lower

BROWNFIELDS:

Program: BCP
Site Code: 416811

Actual:
31 ft.

Site Description: Location: The Off-site Clinton Green Development Project Site, defined by a shallow off-site petroleum-contaminated groundwater plume, involves the intersection of West 53rd Street and 10th Avenue in Manhattan, New York City. Site Features: This location is an urban area of commercial/light industrial and residential use including multi-story buildings, sidewalks and open city streets. A paved elementary school playground is located on the southeast corner of this intersection and the Hudson River is approximately two blocks west of the Site. Zoning/Historical Use: The Site is in an Environmental Zone which is part of the Clinton Green Urban Renewal Area. This is an off-site remedial project associated with the now-completed Clinton Green Development Brownfield Cleanup Project. Site Geology and Hydrogeology: The depth to groundwater ranges between 12 to 20 feet below the surface. The soil, below the urban fill, is fine to coarse-grained sand. Bedrock is encountered between 11 feet and 15 feet below the surface.

Env Problem: Nature and Extent of Contamination: The on-site source area (Clinton Green Development BCP Site) was cleaned up by Dermot Clinton Green in 2006, and this project includes the remediation of the off-site petroleum-contaminated plume. Contaminants: Based upon investigations conducted to date, the primary contaminants are petroleum-related volatile organic compounds (VOCs) in a shallow off-site groundwater plume. Concentrations: Concentrations of benzene in the groundwater ranged from non-detect to 330 parts per billion (ppb), exceeding the groundwater standard of 1 ppb. Ten other VOCs also exceeded the groundwater standard. Naphthalene (290 ppb) was the only semi-volatile organic compound detected and it exceeded the groundwater standard of 5 ppb. This very localized plume has migrated off-site approximately 100 feet down-gradient. Significant Threat: The BCP site presented a significant environmental threat due to the off-site release of contaminants from source areas.

Health Problem: Direct contact with contaminated groundwater is not expected since contamination is located at depth and below pavement. Ingestion of contaminated groundwater is not expected since the area is served with public water. An evaluation of the potential for vapor intrusion to occur is part of the approved Remedial Action Workplan currently underway.

Program: BCP
Site Code: 57349
Site Description: The site consists of several parcels located on West 53rd Street between 10th Avenue and the Amtrak easement, on West 52nd Street adjacent to the east side of the Amtrak easement, and along the Amtrak easement between West 51st and 53rd Streets in the City of New York, Borough of Manhattan. Railroad tracks pass through the site. A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLINTON GREEN DEVELOPMENT PROJECT (Continued)

S106906459

former ExxonMobil gas station was present on this portion of the Site from approximately 1950 - 1992. By February 2006, all original buildings on-site were torn down and all on-site contaminated soil was excavated and removed off-site. The property is currently owned by Dermot Clinton Green LLC. The Site now consists of two residential towers, a mixed-use low-rise building, public park, and subsurface parking garage (all currently under construction). A Certificate of Completion was issued on October 20, 2006.

Env Problem: Past environmental investigations revealed that this BCP site had on-site and off-site petroleum impacted soil and groundwater as a result of petroleum spills from the former Exxon/Mobil Service Station at the corner of 53rd Street and 10th Avenue. Dissolved phase groundwater contamination (BTEX, lead and MTBE) has impacted the shallow groundwater table exceeding standards. An adjacent off-site building has experienced liquid petroleum in the basement. On-site and off-site remedial work occurred in early 2000. Although all on-site contamination has been removed through the BCP program in 2006, an off-site groundwater plume still exists and additional cleanup work is required to remediate the off-site contamination. The City of New York has accepted the responsibility for the off-site contamination and a final Site Investigation Work Plan was approved by NYSDEC on February 9, 2009. Field work will begin in the spring of 2009.

Health Problem: All on-site contamination has been remediated through remedial actions completed in 2005-2006. Remedial actions included demolition of all site buildings, removal of all soil to the top of bedrock, and associated dewatering of the site. No contamination is known to exist beneath the top of bedrock. Therefore, all on-site exposures have been mitigated. A shallow off-site petroleum-contaminated groundwater plume was documented in 1993 (NYSDEC Spill No. 93-08101). Migration of the plume has been limited due to the geology of the area. NYSDEC is currently pursuing the responsible party (Clinton Green OU#2) to investigate and remediate any off-site contamination.

647
SSE
1/4-1/2
0.453 mi.
2392 ft.

498 SEVENTH AVENUE
498 7TH AVENUE
NEW YORK, NY

NY LTANKS S104782245
N/A

Relative:
Higher

LTANKS:

Actual:
43 ft.

Site ID: 85759
Spill Number/Closed Date: 0006741 / 10/4/2000
Spill Date: 9/7/2000
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 9/7/2000
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

498 SEVENTH AVENUE (Continued)

S104782245

Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/7/2000
Spill Record Last Update: 10/5/2000
Spiller Name: MICHAEL S. MAY
Spiller Company: GEORGE COMFORT & SONS
Spiller Address: 200 MADISON AVENUE
Spiller City,St,Zip: NEW YORK, NY 10016-
Spiller County: 001
Spiller Contact: MICHAEL MAY
Spiller Phone: (212) 695-3820
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 78744
DEC Memo: Not reported
Remarks: Caller states tank was removed by ace atlas and soil contamination was found - caller was contacted for clean up

Material:

Site ID: 85759
Operable Unit ID: 829568
Operable Unit: 01
Material ID: 547851
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DF648
NE
1/4-1/2
0.455 mi.
2404 ft.

SPILL NUMBER 9815045
305 W. 50TH ST
MANHATTAN, NY
Site 1 of 2 in cluster DF

NY LTANKS **S104620052**
N/A

Relative:
Higher

LTANKS:

Site ID: 75261
Spill Number/Closed Date: 9815045 / 3/19/1999
Spill Date: 3/19/1999
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JXZHAO
Referred To: Not reported
Reported to Dept: 3/19/1999

Actual:
59 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 9815045 (Continued)

S104620052

CID: 322
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/19/1999
Spill Record Last Update: 3/19/1999
Spiller Name: ROCKY VENUTO
Spiller Company: T AND S TRUCKING
Spiller Address: 53 2ND AVE
Spiller City,St,Zip: BROOKLYN, NY 11215-001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 70467
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ZHAO"
Remarks: DEFECTIVE GAUGE CAUSED DRIVER TO OVERFILL TANK - SPILL ON SIDEWALKAND HAS BEEN CLEANED UP

Material:

Site ID: 75261
Operable Unit ID: 1072901
Operable Unit: 01
Material ID: 308166
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: 5
Resource Affected: Not reported
Oxygenate: False

Tank Test:

**DG649
NW
1/4-1/2
0.461 mi.
2433 ft.**

**CLOSED-LACKOF RECENT INFO
711 12TH AVENUE
NEW YORK CITY, NY**

NY LTANKS

**S100167579
N/A**

Site 1 of 2 in cluster DG

**Relative:
Lower**

LTANKS:

Site ID: 195532
Spill Number/Closed Date: 8804962 / 3/5/2003
Spill Date: 9/7/1988
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported

**Actual:
10 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLOSED-LACKOF RECENT INFO (Continued)

S100167579

Cleanup Meets Standard: False
SWIS: 3101
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 9/7/1988
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/8/1988
Spill Record Last Update: 3/19/2003
Spiller Name: Not reported
Spiller Company: NYC/PORT AUTH. OF NY/NJ
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 279166
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"ADMIN.CLOSED"03/05/2003- Closed Due To The Nature / Extent Of The
Spill Report
Remarks: 7.5K TANK SYSTEM FAILED HORNER EZY WITH A LEAK RATE OF .07996GPH,
LEAKIS POSSIBLY FROM ABOVEGROUND PIPING, TO PUMP TANK AND
INVESTIGATE.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY
CLEAN UP REQUIREMENTS.

Material:
Site ID: 195532
Operable Unit ID: 922131
Operable Unit: 01
Material ID: 456884
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 195532
Spill Tank Test: 1534573
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CLOSED-LACKOF RECENT INFO (Continued)

S100167579

Last Modified: 10/1/2004
Test Method: Unknown

DH650
SSE
1/4-1/2
0.463 mi.
2442 ft.

APARTMENT BUILDING
501 7TH AVE.
MANHATTAN, NY
Site 1 of 2 in cluster DH

NY LTANKS **S106702779**
N/A

Relative:
Higher

LTANKS:

Actual:
46 ft.

Site ID: 165986
Spill Number/Closed Date: 0406590 / 7/20/2006
Spill Date: 9/8/2004
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: qxabidi
Referred To: Not reported
Reported to Dept: 9/15/2004
CID: 408
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/15/2004
Spill Record Last Update: 7/20/2006
Spiller Name: JOHN LEDDY
Spiller Company: PRO-TEST
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: ANGEL
Spiller Phone: (718) 367-9880
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 139881
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"9/20/2004 Sangesland spoke to John Leddy to find out if this case could be closed out. Leddy said he was subcontracted to do the testing. He has NOT done any repairs and has NOT been hired to retest the tanks again.Sangesland called "Angel"(building super???) and got no answer07/14/06: This spill is transferred from Mr. Koon Tang to Q.Abidi.Contacted to John Leddy he said he will find the data and he will send it to me. -QA07/19/06: Contacted Mr. Jerry William of Controlled Combustion Company. He said there is not any waste Manifest record and no soil sampling. They removed older tank and they have put in a new tank. He will fax me the supporting documents to close the spill. -QA07/20/06: Reviewed letter from Mr. Jerry William (General Operational Manager), Controlled Combustion Co. Inc. They removed the old oil tank and they installed a brand new 10,000

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

APARTMENT BUILDING (Continued)

S106702779

Remarks: gallon oil tank. He mentioned in his letter that there were only very small oil stains on the floor, which were cleaned up. The letter also included a copy of the tank test failure report, and documents indicating that the old tank had been removed and replaced with a new tank. Based on the information provided by Mr. Jerry William, this spill is closed. -QA
TEST METHOD WAS EZ THREE LOCATOR PLUS. TNAK IS ON LEGS, 95% VISABLE. THE DELAY IN REPORTING WAS DUE TO CONFUSION DUE TO WHO WAS GOING TO REPORT IT.

Material:

Site ID: 165986
Operable Unit ID: 890105
Operable Unit: 01
Material ID: 487760
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 165986
Spill Tank Test: 1529670
Tank Number: Not reported
Tank Size: 10000
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

651
ENE
1/4-1/2
0.463 mi.
2443 ft.

SPILL NUMBER 0105774
1650 BROADWAY
MANHATTAN, NY

NY LTANKS S105135113
N/A

Relative:
Higher

LTANKS:

Site ID: 303296
Spill Number/Closed Date: 0105774 / 3/17/2004
Spill Date: 8/29/2001
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported

Actual:
53 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SPILL NUMBER 0105774 (Continued)

S105135113

Reported to Dept: 8/29/2001
CID: 270
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/29/2001
Spill Record Last Update: 3/17/2004
Spiller Name: LISETT
Spiller Company: BEN BRAKA US REALITY
Spiller Address: 450 7TH AV
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: LISETT
Spiller Phone: (212) 244-6650
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 245062
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"9/10/03 tippie sent documentation request.3/17/04 tippie recieves documrntation//nfa
Remarks: BOTTOM OF TANK LET GO CAUSING SPILL. CLEAN UP IN PROGRESS

Material:

Site ID: 303296
Operable Unit ID: 842815
Operable Unit: 01
Material ID: 571715
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 300
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DF652
NE
1/4-1/2
0.463 mi.
2446 ft.

840 EAST 8TH ST.
840 EAST 8TH STREET
NEW YORK CITY, NY
Site 2 of 2 in cluster DF

NY LTANKS **S104275614**
N/A

Relative:
Higher

LTANKS:

Actual:
59 ft.

Site ID: 165640
Spill Number/Closed Date: 9008696 / 9/30/1992
Spill Date: 11/8/1990
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

840 EAST 8TH ST. (Continued)

S104275614

Cleanup Ceased: 9/30/1992
Cleanup Meets Standard: False
SWIS: 2401
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 11/8/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 11/20/1990
Spill Record Last Update: 5/12/1994
Spiller Name: Not reported
Spiller Company: 840 EAST 8TH STREET
Spiller Address: 840 EAST 8TH STREET
Spiller City,St,Zip: BROOKLYN, NY
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 139581
DEC Memo: Not reported
Remarks: 20K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, VISIBLE LEAK IN PIPING, WILL REPAIR & RETEST.

Material:

Site ID: 165640
Operable Unit ID: 949329
Operable Unit: 01
Material ID: 432494
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 165640
Spill Tank Test: 1537843
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

653
SSW
1/4-1/2
0.466 mi.
2460 ft.

ST MICHEAL'S SCHOOL
425 WEST 33RD STREET
MANHATTAN, NY

NY LTANKS

S106703793
N/A

Relative:
Higher

Actual:
44 ft.

LTANKS:

Site ID: 240388
Spill Number/Closed Date: 9608649 / 10/11/1996
Spill Date: 10/11/1996
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 10/11/1996
CID: 257
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/11/1996
Spill Record Last Update: 6/3/2004
Spiller Name: JIM CAREY
Spiller Company: CASTLE OIL
Spiller Address: 290 LOCUST AVE
Spiller City,St,Zip: BRONX, NY 10454-001
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: (212) 563-2575
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 197687
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MARTINKAT"
Remarks: overfill of storage tank cleanup crew on the way

Material:

Site ID: 240388
Operable Unit ID: 1039859
Operable Unit: 01
Material ID: 344379
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST MICHEAL'S SCHOOL (Continued)

S106703793

Tank Test:

Site ID: 369290
Spill Number/Closed Date: 0606006 / 9/11/2006
Spill Date: 8/24/2006
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported

Cleanup Meets Standard: False

SWIS: 3101

Investigator: rmpiper

Referred To: Not reported

Reported to Dept: 8/24/2006

CID: 444

Water Affected: Not reported

Spill Notifier: Other

Last Inspection: Not reported

Recommended Penalty: False

UST Involvement: False

Remediation Phase: 0

Date Entered In Computer: 8/24/2006

Spill Record Last Update: 9/11/2006

Spiller Name: SISTER KATHLEEN

Spiller Company: ST MICHEAL'S SCHOOL

Spiller Address: 425 WEST 33RD STREET

Spiller City,St,Zip: MANHATTEN, NY

Spiller County: 001

Spiller Contact: SISTER KATHLEEN

Spiller Phone: (212) 594-9056

Spiller Extention: Not reported

DEC Region: 2

DER Facility ID: 319177

DEC Memo: DEC Piper spoke w/ Charles Rose. Assistant to the principal. As per conversation, they were getting ready for winter and noticed a leak. When the janitor inspected found approx 200 gal in vaulted area. Spill is contained and in vault. PTC to respond today and pump out remaining oil and oil on floor. No drains, sewers effected. PTC to contact DEC upon completion of emergency cleanup. School is not in session and no children are present. Odors present in basement only and not in school.9/11/06- DEC Piper spoke w/ Sister Katheleen, PTC had cleaned up emergency spill. Piper spoke w/ PTC, tank was above ground on concrete. Concrete was in good shape. School is going to replace tank. 6 drums of oil soaked speedy dry removed. CLOsed.

Remarks: TANK IS LEAKING IN THE TANK ROOM OF SCHOOL: CREW ENROUTE TO PUMP OUT TANK AND CLEAN UP SPILL: NO DRAINS EFFECTED:

Material:

Site ID: 369290
Operable Unit ID: 1127130
Operable Unit: 01
Material ID: 2116713
Material Code: 0002A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ST MICHEAL'S SCHOOL (Continued)

S106703793

Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

654
NNE
1/4-1/2
0.467 mi.
2465 ft.

**JANOVIC PAINT
771 9TH AV
MANHATTAN, NY**

**NY LTANKS S105997628
N/A**

**Relative:
Higher**

LTANKS:

**Actual:
55 ft.**

Site ID: 216271
Spill Number/Closed Date: 0209507 / 12/12/2007
Spill Date: 12/16/2002
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 12/16/2002
CID: 365
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/16/2002
Spill Record Last Update: 12/11/2008
Spiller Name: CARMELLA
Spiller Company: JANOVIC PAINT
Spiller Address: 771 9TH AV
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: CARMELLA DEL GEORGE
Spiller Phone: (718) 392-3999
Spiller Extention: 204
DEC Region: 2
DER Facility ID: 179047
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND/DO"6/7/06- DECP iper took lead from Sue LAsdin due to associated spill at same address.According to Environ, talks w/ employees revealed that there was a UST on site that has recently been abandoned in place. The Dept has no information on this tank and may be less than 1100 gal. Regardless, soil analytical and/or passing

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

JANOVIC PAINT (Continued)

S105997628

results before abandonment has not been received. Address currently using 2 manifolded 275 AST though used old fill line. This fill line has recently been replaced. If passing tank results cannot be provided, then boring will need to be performed. 9/28/06= DEC Piper reviewed subsurface investigation report. Due to refusal at shallow depths < 3 ft., soil samples were not able to be collected. No organic vapors detected in these borings around tank. Borings around fill line revealed soil contamination. Further work is warranted. 6/19/07 DEC Piper spoke w. Drew Bonas w. Environ, He has been back and forth w. owner and will let me know outcome of upcoming meeting. 12/12/07- DEC Piper reviewed case. Based on spill info and site conditions, spill to subsurface was minimal and poses no significant threat to health and env. Residual contamination exists. This spill will be consolidated into 0514611. 0209507 will be closed.

Remarks: recommend uncover, reapi & retest

Material:

Site ID: 216271
Operable Unit ID: 860807
Operable Unit: 01
Material ID: 512929
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 216271
Spill Tank Test: 1527835
Tank Number: 1
Tank Size: 2500
Test Method: 03
Leak Rate: 0
Gross Fail: F
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Horner EZ Check I or II

DI655
East
1/4-1/2
0.467 mi.
2466 ft.

COMMERCIAL BUILDING
701 7TH AVE
MANHATTAN, NY
Site 1 of 2 in cluster DI

NY LTANKS
NY Spills

S106869316
N/A

Relative:
Higher

LTANKS:

Site ID: 344455
Spill Number/Closed Date: 0501223 / 6/30/2006
Spill Date: 4/29/2005
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Actual:
49 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106869316

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 4/29/2005
CID: 408
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/2/2005
Spill Record Last Update: 6/30/2006
Spiller Name: JIM CAREY
Spiller Company: CASTLE OIL TERMINAL
Spiller Address: 290 LOCUST AVE.
Spiller City,St,Zip: BRONX, NY 10454
Spiller County: 001
Spiller Contact: GLENN GORAL
Spiller Phone: (508) 795-0110
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 291145
DEC Memo: 4/29/05 Tipple responded, Response off the case and Ambrose Env overseeing cleanup. PTC arrived with a vac truck, oil spread to thin and too many under many things be effective, Tristate began cleanup, PTC to continue.4/30/05 Ambrose off case, Response back, PTC off, Tristate back conducting cleanup.5/2/05 Tipple got conflicting descriptions of site status, re-visited site.Oil in tank appears to remain in tank, + - 1/16 inch wide cut from prior tank work visible, apparently the tank was opened, the cut steel was re-attached with a few screws and glue. Over time minor the glue let loose and the "patch" reveals a cut line around it. Ultimately the vent line is not effective, the hole atop of the tank is the primary acting vent, although oil also shot out the sidewalk vent onto the walk. Upon further inspection, the steel at the bottom end of the tank closest to the boiler room appears to show signs of a serious corrosion problem.Tipple sent a letter requiring the cleanup be completed and the tank system pass a tank test prior to receiving future deliveries, and the tank registration be updated/corrected. T&S - delivery Company, Castle Oil - fuel supplier.The tank surround must be removed and replaced due to the saturated cinder block, at that time it was suggested that the tank be replaced/repared.1/5/06 - Raphael Ketani. The party in charge of managing the building is Ernest Faraci at Vimar Realty (212) 696-7127. The PBS case is #2-600047 for the 1500 gal. tank. About 400 gals. of #4 oil were spilled. I called Tri-State Environmental ((888) 938-2658) to try to find out if they knew anything about the cleanup. The person who answered the phone said he wasn't sure, but would get back to me.1/6/06 - Raphael Ketani. Joanne Peretti of Tri-State called to ask what documentation I needed to close the case. I described what I needed and she said she would get it to me next week.Ms. Peretti called back and said that Response Env. would have the documentation as they were the subcontractor. She told me to call Glen Goral at

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106869316

(508) 795-0110, ext. 202. 1/24/06 - Raphael Ketani. I received the cleanup report from Resonse Env. However, they mentioned a broken epoxy seal on the tank as the source of the leak. I called up Anthony Lara of PTC (718) 624-4842 and asked him whether the tank was repaired or removed. He said that the patch was welded onto the tank. I asked him for a letter describing this. He said he would send it. 1/27/06 - Raphael Ketani. A new oil spill #0512449 was called in yesterday night. Castle Oil (718) 579-3413 made a delivery of 300 gals. and discovered oil in a deep sump. There were 20 gals. of oil in the sump. The newer spill case is being closed and referred back to this one. PTC is going to the site to investigate. Super's phone: (646) 764-0511/(212) 869-1290. Super is Carrie Tucker. PTC (718) 624-4842 will be on site at between 12 and 2 today. I spoke to Ms. Tucker at 12:13PM today and she said that PTC is on sight. She said that the oil is black (same color as in tank). I told her to have PTC come over to suck out the sump as needed and to keep track of the thickness of the oil layer, and let me know what's happening. She said she would. I asked her whether the system lines were in the ground or concrete floor. She said they were not. Ms. Tucker called me back. She said PTC will do a full system test next week to try and find out where the oil is coming from. 1/31/06 - Raphael Ketani. Ms. Tucker called me back and said that PTC tested the tank and the pipes. She said that only the return line failed. They told her, she said, that the leak in the return line was a slow drip and that they will repair the line. I told Ms. Tucker that I needed a report of the testing and the repair. She said she would get it for me. She added that there is still some very slow seepage into the 4'X6' sump. She said that after awhile it might measure one cup. I told her to keep an eye on the seepage and to let me know how it does. She said she would. She said that, right now, the sump is clean. 2/8/06 - Raphael Ketani. Ms. Tucker called to say that she had Robert J. Keaney, Jr. of John Anderson & Associates, and Rich Gilbert of Westfair Restoration Services on site to inspect the damage from the two previous oil spills. He said that Mr. Keaney is an insurance adjuster. Ms. Tucker said that he was trying to get money to rebuild the tank vault, replace the oil damaged cinder block wall behind the tank, replace the damaged sump pump, and to clean up the oil seeping into the sump. She said that they agreed that Castle Oil was responsible for the spills, and she said that they admitted responsibility. Ms. Tucker asked me to send a letter to Castle to get them to clean up the seeping oil. I told her I would only address the seepage in the letter, not order them to do construction/replacement work. She said that was alright. 2/24/06 - Raphael Ketani. Ms. Tucker called to ask what DEC wanted to get to close the spill case. I told her that we wanted the system test results, and statements regarding the fixing of the return line leak, the cleanup of the sump, removal of staining, revaulting of the tank, and welding of the patch on the tank. Ms. Tucker said he would have PTC send me such a letter. 3/22/06 - Raphael Ketani. I contacted Carrie Tucker. She said that all of the work has been done. I asked her to call PTC and get me a closure report. She said he would contact the building's owner and he will contact PTC. 4/6/06 - Raphael Ketani. I spoke to Mark at PTC. He said they haven't been paid and so they are not sending any documentation to the management company or to the DEC. I called up the management company, Walter and Samuels (646) 764-0511, and spoke to a woman [Ernest Faraci, Director, Walter & Samuels, 419 Park Avenue South, NY, 10016]. She said to send a letter regarding all of the

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106869316

documentation that DEC needs to close the case. I told her I would. I sent the letter today. 4/21/06 - Raphael Ketani. I spoke to Ms. Tucker. She said that she is still getting the paperwork together for the report regarding the spill. She said that, partly, the delay is because she's waiting for manifests and such from the contractor. She asked that I give her another week or 10 days to get the report sent to DEC. I told her this would be alright. 5/15/06 - Raphael Ketani. I received a FAXed letter from Castle Oil on 5/4/06. The letter had an invoice attached for cleanup work that was done on 4/29/05. THIS IS NOT THE CLOSURE REPORT I NEEDED! 5/16/06 - Raphael Ketani. I received a letter with attached documentation from Walter & Samuels. It still doesn't have documentation of the patch repair, repair of the return line, removal of the oil contaminated cinder blocks, system test results from 2/06, and sump cleanup. 5/17/06 - Raphael Ketani. I sent Walter & Samuels a letter stating that I still haven't received the necessary documentation describing the above issues and other issues mentioned in the April 6 DEC letter to them. 6/30/06 - Raphael Ketani. Yesterday I received a package of documentation from Ernest Faraci, Director of Management at the management company Walter and Samuels. The package included: the cover letter dated 6/27; failing tank system results; passing tank only results; passing tank system results; a letter from Ms. Tucker stating that everything has been cleaned up; and repair work documents from Castle Oil and PTC. Based upon the above documentation which was received on June 29, the May 10, 2006 package of documents that were submitted by Walter and Samuels and received on May 16, and other documents in the file, I am closing the case.

Remarks: Confined in the basement of the commercial building. Clean up is in process.

Material:

Site ID: 344455
Operable Unit ID: 1103096
Operable Unit: 01
Material ID: 583302
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 400
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 1213801
Facility Type: ER
DER Facility ID: 291145
Site ID: 477013
DEC Region: 2
Spill Date: 12/21/2012
Spill Number/Closed Date: 1213801 / Not Reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106869316

Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 12/21/2012
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 12/21/2012
Spill Record Last Update: 2/21/2013
Spiller Name: RICH
Spiller Company: PROPERTY OWNER
Spiller Address: 701 7TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 999
Contact Name: RICH
Contact Phone: (917) 202-5119
DEC Memo: ConEd Manhole impacted - See Emis #23230812/21/12-Zhune responded to this spill. The fill line was cut from the fill port from where they hooked the hoze and not sealed. They installed a new fill port and fill line few feet from the one that they made the wrong delivery. Approximately 800 gallons spilled. Most of oil went under the sidewalk into Con-ED structures. Some through the basement wall enter the basement and went into two sumps. one of this sumps ended up in the sewer. The pumps were disconnected. Petroleum tank cleaner is doing the cleanup. DEP was notified. Company Name: Waltert Samuels 419 Park Ave South 15FIOwner information: Norman Silver 217-646-7134 Super information: Vate Pepushy 347-992-647402/07/13- Zhune spoke to Mark from PTC. He said they Pumped out the oil from the tank room.the oil that went to the Con-Ed structure was managed by Con-Ed contractors.

Remarks: Delivery made and hooked up to the wrong, disconnected fill pipe pumping 800 gals of fuel into the basement. Petroleum Tank Cleaners responding for cleanup.

Material:
Site ID: 477013
Operable Unit ID: 1226825
Operable Unit: 01
Material ID: 2224185
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 800
Units: Gallons
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S106869316

Tank Test:

DJ656
NNW
1/4-1/2
0.469 mi.
2478 ft.

660 12TH AVE (A/K/A)
618-628 W 49TH ST
NEW YORK, NY

NY LTANKS

S104877137
N/A

Site 1 of 2 in cluster DJ

Relative:
Lower

LTANKS:

Actual:
19 ft.

Site ID: 331291
Spill Number/Closed Date: 0008970 / 2/4/2002
Spill Date: 11/1/2000
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 11/2/2000
CID: 390
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 11/2/2000
Spill Record Last Update: 2/4/2002
Spiller Name: SAL RUSSO
Spiller Company: PARKING LOT..
Spiller Address: 660 12TH AVE (SAME ADDRS)
Spiller City,St,Zip: NEW YORK, NY
Spiller County: 001
Spiller Contact: SAL RUSSO
Spiller Phone: (516) 239-8823
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 266445
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND" On August 15, 2001, DEC Sigona received spill closure report from AKRF dated August 14, 2001. See file for details and copy of report. 12/01 Spill re-assigned to Sangesland AKRF submitted a letter dated Dec 27, 2001 which included a second copy of the Aug 14, 2001 report and a series of photographs showing the complete excavation of the city block down to bedrock. There was a problem with the PBS registration on the site. Sangesland asked AKRF to re-submit the PBS forms with the correct address (old PBS had the wrong city block) along with info on ALL of the tanks found and removed from the site. From a technical/environmental point of view the site is clean and will be closed out as soon as all of the administrative paperwork has been submitted and reviewed. 2/4/2002 AKRF has submitted copies of all updated PBS registration forms (PBS # 2-604810). All tanks have been removed from the site. The whole site has been excavated

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

660 12TH AVE (A/K/A) (Continued)

S104877137

Remarks: down to bedrock. All petroleum related contamination on this site has been removed. Spill Closed.
UNDERGROUND STORAGE TANK FAILED OVER TIME AND CAUSED SOIL CONTAMINATION - SOIL WILL BE STOCKPILED

Material:

Site ID: 331291
Operable Unit ID: 829563
Operable Unit: 01
Material ID: 546472
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DG657
NW
1/4-1/2
0.470 mi.
2479 ft.

**CE - W. 45TH ST. GAS WORKS
12TH AVE. BETWEEN WEST 44TH & WEST 46TH STS.
NEW YORK, NY 10036**

**NY VCP S106934681
N/A**

Site 2 of 2 in cluster DG

Relative:
Lower

VCP:

Actual:
10 ft.

Program Type: VCP
Site Code: 57602
HW Code: V00532
Site Class: A
SWIS: 3101
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 03/05/2002
Date Record Updated: 04/16/2014
Updated By: GWCROSS
Site Description: Location: The West 45th Street Gas Works site is located on the west side of mid-town Manhattan in an urban area. The site is located on the blocks between 11th and 12th Avenue and between West 44th and West 46th Streets although the footprint of the former MGP extended into the area currently beneath 12th Avenue. Site Features: The main site features include a large self-storage building, a private truck refueling facility and a parking lot. Current Zoning/Uses: The site is zoned M2 for medium manufacturing and currently used as a storage facility, truck parking and refueling facility, and for parking. The surrounding parcels are a highly urbanized combination of commercial, industrial, and residential uses. The nearest residence is within 250 feet of the site to the east. Past Use of the Site: The site was operated as a manufactured gas plant (MGP) by the Consolidated Gas Company from 1877 to 1913. By-products of the gas production are the main sources of contamination and are found to be associated with the historic MGP structures in the subsurface. Operable Units: The site

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 45TH ST. GAS WORKS (Continued)

S106934681

Env Problem:

has been divided into 2 operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 consists of the main plant site between West 44th Street and West 46th street and 11th to 12th Avenues including the area beneath 12th Avenue as well as all off-site areas where contamination has spread. Operable Unit 2 is the portion of the MGP site between West 45th and West 46th streets. It is currently a parking lot associated with the Intrepid Museum. Site Geology/Hydrogeology: The entire site and its surroundings lie on fill materials which were placed in the Hudson River to extend the shoreline westward prior to construction of the MGP. Thus, the soils immediately beneath the ground surface consist of varying thicknesses of urban fill, ranging in depth from 3 to 12 feet. Beneath that are layers of peat, sand, silt, and some gravel. Bedrock is encountered between 25 and 35 feet below the ground surface. Groundwater at the site is found anywhere from about two feet to ten feet below the ground surface. Groundwater generally flows westward toward the Hudson River beneath the western portion of the site, and eastward on the southeastern side of the site. This pattern is complicated somewhat by tidal variations in some areas.

Nature and Extent of Contamination: Based on the investigations, the chemicals of concern at the site are the constituents of MGP tar which leaked from gas holders, tar tanks, and subsurface pipes during the period when the MGP was operating. MGP tar is a black, oily liquid which was produced as a byproduct of the gas manufacturing process. The principal contaminants in the tar are benzene, toluene, ethylbenzene, xylene (collectively referred to as BTEX compounds); and polycyclic aromatic hydrocarbons (PAHs). BTEX and PAHs have been found in the soil and groundwater at the site in exceedance of standards, criteria, and guidance. The MGP tar is found in close proximity to historic structures in the subsurface, including the original gas holder foundations on OU-1, and the tar storage tanks on OU-2. Under OU-1, there is little evidence of tar. It has migrated roughly 120 feet to the southeast, mostly in thin seams, into an apparent depression in the bedrock surface at depths ranging from 12 feet to 25 feet below the ground surface. The amount of tar in the depression is minimal creating a small pool roughly 8 feet thick but less than 5,000 square feet, making a total volume of less than 500 cubic yards of impacted soils at least 15 feet below ground. Total BTEX concentrations range from non-detect to 5,230 parts per million (ppm), found at 30 feet below grade. PAHs are primarily co-located with the BTEX contamination, adjacent to the coal tar, with values ranging from non-detect to 2,808 ppm found at 20 feet grade, as compared to the soil cleanup objective of 500 ppm for commercial properties. Groundwater contamination is found down gradient of the tar contamination and includes the same contaminants as the soil contamination. Total BTEX concentrations range from 1.3 parts per billion (ppb) to 12,000 ppb. Total PAHs concentrations range from non-detect to 5,128 ppb. These levels of both BTEX and PAHs are well in excess of ambient water quality standards. The soil vapor sampling showed a range of contaminants, including benzene, naphthalene, xylene, and ethanol. While some of the contaminants could have been related to the former MGP plant, many were not. Values ranged from non-detect for naphthalene in several samples to 480 micrograms per cubic meter for 2,2,4-trimethylpentane. Based on the sampling

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CE - W. 45TH ST. GAS WORKS (Continued)

S106934681

Health Problem: results, it was determined that soil vapor intrusion was not a current issue that needed to be addressed. Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Actions are not needed to address the potential for soil vapor intrusion given the current use of the site. However, if the site is redeveloped or the use changes, the potential for soil vapor intrusion must be re-evaluated. Sampling indicates that off-site soil vapor intrusion as a result of site contamination is not a concern.

DK658
WSW
1/4-1/2
0.473 mi.
2498 ft.

528 W 34TH ST
528 W 34TH ST
MANHATTAN, NY

NY LTANKS **S102672155**
N/A

Site 1 of 2 in cluster DK

Relative:
Higher

LTANKS:

Actual:
32 ft.

Site ID: 153341
Spill Number/Closed Date: 9300804 / 4/16/1993
Spill Date: 4/16/1993
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased: 4/16/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 4/16/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 4/21/1993
Spill Record Last Update: 7/20/1993
Spiller Name: Not reported
Spiller Company: WHALECO
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 130112
DEC Memo: Not reported
Remarks: CONTAINED IN SIDEWALK SENDING SPILL TEAM TO CLEANUP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

528 W 34TH ST (Continued)

S102672155

Material:

Site ID: 153341
Operable Unit ID: 979410
Operable Unit: 01
Material ID: 401544
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

659
ESE
1/4-1/2
0.475 mi.
2510 ft.

131 WEST 42ND ST/MANH
131 WEST 42ND STREET
NEW YORK CITY, NY

NY LTANKS

S104275566
N/A

Relative:
Higher

Actual:
59 ft.

LTANKS:

Site ID: 71701
Spill Number/Closed Date: 8911074 / 2/22/1990
Spill Date: 2/21/1990
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 2/22/1990
Cleanup Meets Standard: True
SWIS: 3101
Investigator: WILSON
Referred To: Not reported
Reported to Dept: 2/21/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/11/1990
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 67809
DEC Memo: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

131 WEST 42ND ST/MANH (Continued)

S104275566

Remarks: FAULTY GAUGE, OVERFILL, FUEL ON SIDEWALK, SPEEDY DRY APPLIED, PICKED UP & DISPOSED OF PROPERLY.

Material:

Site ID: 71701
Operable Unit ID: 938062
Operable Unit: 01
Material ID: 440619
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DK660 530 WEST 34TH ST/MANH
WSW 530 WEST 34TH STREET
1/4-1/2 NEW YORK CITY, NY
0.477 mi.
2518 ft. Site 2 of 2 in cluster DK

NY LTANKS S104275563
N/A

Relative:
Higher

LTANKS:

Actual:
32 ft.

Site ID: 115809
Spill Number/Closed Date: 8910499 / 2/2/1990
Spill Date: 2/2/1990
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Not reported
Cleanup Ceased: 2/2/1990
Cleanup Meets Standard: True
SWIS: 3101
Investigator: WILSON
Referred To: Not reported
Reported to Dept: 2/2/1990
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2/5/1990
Spill Record Last Update: 9/30/2004
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

530 WEST 34TH ST/MANH (Continued)

S104275563

DEC Region: 2
DER Facility ID: 100856
DEC Memo: Not reported
Remarks: INACCURATE GAUGE RESULTING IN OVERFILL ON SIDEWALK, CONTAINED ON SIDEWALK, SPILL CLEANED UP WITH SPEEDY DRY.

Material:

Site ID: 115809
Operable Unit ID: 935860
Operable Unit: 01
Material ID: 443601
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DL661
SSE
1/4-1/2
0.480 mi.
2533 ft.

237 WEST 35TH ST
237 WEST 35TH ST
MANHATTAN, NY
Site 1 of 2 in cluster DL

NY LTANKS

S103558837
N/A

Relative:
Higher

LTANKS:

Actual:
39 ft.

Site ID: 117113
Spill Number/Closed Date: 9811630 / 2/11/1999
Spill Date: 12/16/1998
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 12/16/1998
CID: 216
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/16/1998
Spill Record Last Update: 5/20/2002
Spiller Name: LEE POWERS
Spiller Company: MYSTIC TRANSPORTATION
Spiller Address: 1901 STEINWAY AVE
Spiller City,St,Zip: ASTORIA, NY 11105-

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

237 WEST 35TH ST (Continued)

S103558837

Spiller County: 001
Spiller Contact: LEE POWERS
Spiller Phone: (718) 932-9075
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 101888
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" Engelhardt was off hour responder. Spoke to Lee Powers - Spill to cement outside house. No sewers or drains affected. Cleanup being performed by Mystic crew.
Remarks: IT APPEARS THAT A OIL DELIVERY WAS DONE TWICE TO THE SAME RESIDENCE CAUSING A SPILL THEY ARE IN THE PROCESS OF CLEANING UP THE SPILL AT THIS TIME

Material:
Site ID: 117113
Operable Unit ID: 1068924
Operable Unit: 01
Material ID: 311914
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15
Units: Gallons
Recovered: 15
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DJ662
NNW
1/4-1/2
0.481 mi.
2541 ft.
WEST 49TH ST SUBSTATION
637 WEST 49TH STREET
MANHATTAN, NY
Site 2 of 2 in cluster DJ

NY LTANKS
NY Spills
S104496063
N/A

Relative: LTANKS:
Lower Site ID: 320303
Spill Number/Closed Date: 0306463 / 10/15/2003
Actual: Spill Date: 9/18/2003
18 ft. Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 9/18/2003
CID: 365
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/18/2003
Spill Record Last Update: 10/27/2003
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 193697
DEC Memo: 9-18-0 @ 12:05P Keelan #19995 reports that while refueling the diesel vault @ w 49 st sub station (637 w 49 st). W Zwirz #20206 discovered that 10 gallons of diesel fuel had spilled onto the concrete floor of the structure. There was or is no smoke or fire involved . No sewer or waterway affected. No injuries and weather had no affect. Spill was caused by overfilling the tank and it spilled from the diesel tank vent line. No measuring device used to determine the amount of the spill. No private property affected. Oil absorbent pads and socks were applied to contain the spill. Cleanup pending J Moran CIG P Didonato # 01669 notified @ 12:33 J Moran #09/18/03While filling up the main diesel tank the day tank overflowed spilling approx ten gallons of oil out of the vent line on the corrugated roof of the desiel generator. The oil ran down the sides of the shed onto concrete. Speedy dry and pads were used to clean the roof walls and concrete. The day tank oil level was lowered and there is no further leaking equipment. Spill cleanup was supervised by Mike Butchar using SSM personnel.P.Keelan
Remarks: contained inside the structure - clean up pending - ref #150395

Material:
Site ID: 320303
Operable Unit ID: 875225
Operable Unit: 01
Material ID: 503685
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:
Facility ID: 9807609
Facility Type: ER
DER Facility ID: 193697
Site ID: 125026

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

DEC Region: 2
Spill Date: 9/22/1998
Spill Number/Closed Date: 9807609 / 11/5/2003
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 9/22/1998
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/22/1998
Spill Record Last Update: 11/12/2003
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 999
Contact Name: FRANK MASSERIA
Contact Phone: (212) 580-6763
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'CONNELL"Con Ed e2mis #119949:9/22/98 1210pm2 drops dielectric fluid leaking from 5" pipe of feeder M55 going to the cooling plant in the fire pump room. Leaked onto concrete floor. 10/14/98 Area was cleaned and containment set up. Sample was taken but there was insufficient material to run sample. A sample will be taken prior to disposal. Repairs pending outage.On January 7, 2003 a inspection was performed of W49 St substation. Joe Susco, Robert Sanchez, Patrick Keelan, Mike Butchar represented SSO. Kerry Foley represented the DEC. This incident was inspected and all agreed that the source of the initial spill was a leaking valve that was reported under incident # 129845.Ms. Foley agreed to close out this incident and keep the incident for the source of the spill open until repairs are completed. Clean up of this incident was completed and the spill tag was removed.DEC Notes:9/22/98 ERT Dan Shah-1:20pm, he is going to instruct station not to sample but to clean as 50-499ppm PCB.1/7/03 Inspected equipment. No leaks were seen. Cleanup appears to have been completed. (KMF)
Remarks: 5 INCH PIPE LEAKING - 2 DROPS SPILLED - NO CLEAN - SAMPLE TAKEN TO DETERMINE PCB COUNT
Material:
Site ID: 125026
Operable Unit ID: 1068674
Operable Unit: 01
Material ID: 318691
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9907446
Facility Type: ER
DER Facility ID: 193697
Site ID: 235166
DEC Region: 2
Spill Date: 9/21/1999
Spill Number/Closed Date: 9907446 / 7/31/2003
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 9/21/1999
CID: 266
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/21/1999
Spill Record Last Update: 7/31/2003
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"O'CONNELL"see spill #0209963
Remarks: CIRCULATING PLANT 5, FEEDER M52. LEAK FROM A VALVE. 1 PINT OF
DIELECTRIC FLUID SPILLED ONTO METAL FLOOR. NON-PCB. LEAK TO BE
REPAIRED. TO BE CLEANED UP. CON EDISON REFERENCE NUMBER 127919.

Material:
Site ID: 235166
Operable Unit ID: 1086025
Operable Unit: 01
Material ID: 300151
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0306511
Facility Type: ER
DER Facility ID: 193697
Site ID: 125018
DEC Region: 2
Spill Date: 9/19/2003
Spill Number/Closed Date: 0306511 / 3/24/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 9/19/2003
CID: 405
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 9/19/2003
Spill Record Last Update: 3/24/2006
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller City,St,Zip: NEW YORK, NY 10003
Spiller Company: 001
Contact Name: PAUL DIDONATO
Contact Phone: (212) 580-6763
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

"O'CONNELL"Consolidated under DEC # 0002070. (JHO,
3/24/06)-----E2MIS 150-411:9/19/03 11:25
hrs.Pat Keelan #19995 found at 11:00 hrs. approx. 1 pint of
transformer oil had leaked from the radiator pump of transformer no.
5 onto the bluestone at the W. 49th Street Substation. Mr. Keelan was
performing a station inspection when he discovered the spill. Spill
tag #S-01864 to be installed. No samples taken since there is prior
historical knowledge. No initial cleanup action taken. Cleanup is
pending. The operator will place pads down.
transformer leaked in the substation - 1 pint leaked onto blue stone
- spill is contained and clean up pending - con ed # 150411

Material:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

Site ID: 125018
Operable Unit ID: 872992
Operable Unit: 01
Material ID: 503731
Material Code: 0020A
Material Name: TRANSFORMER OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9506757
Facility Type: ER
DER Facility ID: 193697
Site ID: 75117
DEC Region: 2
Spill Date: 9/1/1995
Spill Number/Closed Date: 9506757 / 7/23/2004
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 9/1/1995
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility > 400,000 gal
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/6/1995
Spill Record Last Update: 7/23/2004
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller City,St,Zip: NN
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"7/23/04: Con Ed submitted copy of 10/2/95 notification letter to DEP, which states: "Description of Areas Affected by Release:Bluestone and soil beneath the pothead. Inside Con Edison fence, but within 100M of property line. No entry into sewers or waterways. The cable oil was contained by absorbent pads. The contaminated bluestone and sub-soil were excavated and replaced with

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

Remarks: new bluestone." Close out. (JHO)
LEAK IN "C" PHASE POT HEAD - 138KV FEEDER 38M74 - 1 PINT

Material:

Site ID: 75117
Operable Unit ID: 1017488
Operable Unit: 01
Material ID: 364717
Material Code: 0016A
Material Name: NON PCB OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: Yes
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9805711
Facility Type: ER
DER Facility ID: 193697
Site ID: 125025
DEC Region: 2
Spill Date: 8/7/1998
Spill Number/Closed Date: 9805711 / 11/6/2003
Spill Cause: Equipment Failure
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

SWIS: 3101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 8/7/1998
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/7/1998
Spill Record Last Update: 11/12/2003
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Company: Not reported
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT"Con Ed e2mis #118907:8/7/98 1412hrsLeaked 4oz tranmission

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WEST 49TH ST SUBSTATION (Continued)

S104496063

Remarks: feeder oil from pothead flanges of fdr 38M74 and 45. Hit bluestone.8/26/98 TO Tallini reports one flange was re-tightened and the leak from that flange was stopped. Second flange requires an outage for repairs.Used absorbants to remove residual fluids. Removed/recovered liquids/solids. Removed visible traces of oil. Washed stained areas. Cleanup completed on 10/9/98 1400hrs.DEC Notes:1/7/03 Inspected. No evidence of spill or leak apparent. (KMF) 4 ounces spilled out of defective pothead onto bluestone

Material:

Site ID: 125025
Operable Unit ID: 1063489
Operable Unit: 01
Material ID: 320454
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

[Click this hyperlink](#) while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

DH663
SSE
1/4-1/2
0.483 mi.
2548 ft.

491 7TH AVE
491 7TH AVE.
MANHATTAN, NY

Site 2 of 2 in cluster DH

NY LTANKS
NY Spills
S102142464
N/A

Relative:
Higher

Actual:
46 ft.

LTANKS:

Site ID: 142539
Spill Number/Closed Date: 9213026 / 2/23/1993
Spill Date: 2/21/1993
Spill Cause: Tank Overfill
Spill Source: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 2/23/1993
Cleanup Meets Standard: True
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 2/21/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/31/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

491 7TH AVE (Continued)

S102142464

Spill Record Last Update: 5/22/1998
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 121621
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"SEE 94-06980. ALSO 91-10075.
Remarks: OVER FILL AT SITE, PETROLEUM WILL CLEAN UP.

Material:

Site ID: 142539
Operable Unit ID: 977416
Operable Unit: 01
Material ID: 402846
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 9406980
Facility Type: ER
DER Facility ID: 246330
Site ID: 304953
DEC Region: 2
Spill Date: 8/23/1994
Spill Number/Closed Date: 9406980 / 1/3/2011
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: hrpatel
Referred To: Not reported
Reported to Dept: 8/23/1994
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

491 7TH AVE (Continued)

S102142464

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 12/27/1948
Spill Record Last Update: 1/3/2011
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M TIBBE"SEE ALSO 91-10075 & 92-13026.12/1/05- DEC Piper spoke w/ property manger. Charlie Reed, 499 Fashion Tower, LLC. 212.471.4351 in regards to status of the spill. I had discussed this with Mark Tibbe. Mark had informed me that the spill file has been transferred to Albany. Piper had e-mailed DEC lead as to phone call from property manager.7/7/06 - Spoke with Charlie Reed concerning status of spill in which Reed indicated that the oil spill had been cleaned and signed off by the building managers. The spill case itself was due to a report of a oil vapor spreading into a subway line. However, since then no further reports have been made. Reed indicated he needed to gather his files and speak with current property manager Peter Nichols at 212-471-4351 concerning possibly closing the site. Johnathan Antonizio, NYSDEC8/9/06 - Additional steps needed to attempt to close site: Call Charlie Reed and/or Peter Nichols to gather files together. Would like to see documents to confirm oil spill cleanup. Since no reports of vapor smell since the time of the spill, site can be closed when documents are available. Johnathan Antonizio, NYSDEC-Albany10/29/10 - Austin - Reassigned from Antonizio in Albany to Patel in Region 2 for following up and closing - end12/07/10-Hiralkumar Patel.3:30 PM:- visited site. met Steve Corbo, building super. he is working on-site since 2007. site has one 7,500 gal #4 oil AST on saddles. tank is located inside a tank vault with access. tank vault is under the sidewalk of W 37th Street. during inspection, found monitoring well inside the boiler room, near the sump. Steve doesn't know purpose of well inside building.alternate addresses: 491-499 7th Ave, 154 W 37th StreetPBS #: 2-404861, 2-404888other spills: 9110075, 9213026spill #: 9110075 was reported on 12/22/1991 due to 1,000 gal #6 oil spill. case closed and referred to this open spill case.spill #: 9213026 was reported on 02/21/1993 due to tank overfill. case closed and referred to this open spill case.as per PBS #: 2-404861, site has one 3,000 gal #2 oil UST installed in Jan. 1925. tank was tested on 10/13/06.as per PBS #: 2-404888, site has/had following tanks:- one 7,500 gal #2 oil AST in contact with soil which was removed in Jan. 2002- one 7,500 gal #6 oil AST on saddles which was installed in Jan. 2002as per permit dated 11/21/96, permit was filed to replace two boilers and two oil burners with one boiler and one oil burner. changed oil grade from #6 to #4 and antisiphon valve was installed on oil supply line.as per permit dated 01/19/2000, permit was filed to install additional boiler.as per permit dated 11/26/2001, permit was filed to replace a 7,500 gal tank.Steve Corbo **building super**PH. (212) 967-8795499 Fashion Tower LLC. **property owner**c/o Savitt Partners LLC. **property management company**530 7th Avenue, Suite 401New York, NY 10018Attn.: Sal Robustelli **property manager**Ph. (212) 452-6051 (212) 944-8006email:

S102142464

srobustelli@savittpartners.com12/08/10-Hiralkumar Patel.12:42 PM:- spoke with Steve regarding another tank on property. Steve mentioned that building 491 has 3,000 gal tank wrapped in concrete. building 491 is along 7th ave, south of building 499. Steve mentioned that building 499 is called north tower and building 491 is called south tower.12:55 PM:- left message for property manager.reviewed documents available under spill #:

9110075.*****1) 09/09/94: SL Green Real Estate sent letter to FDNY stating that tank is in satisfactory condition. this letter was based on letter from American Pipe and Tank Lining dated 09/02/94. American Pipe and Tank did pressure test and found no loss of pressure.2) 01/31/96: Site Investigation Report prepared by Apex Environmental. abstract:- installed three borings through the building floor slab: two in the south tower boiler room and one in the eastern freight elevator shaft of the south tower- boring B1 was advanced, to 36 inches below surface, immediately south of a sump pit in the boiler room in the south tower- competent materials were encountered at depth of approx. 36 inches in boring B1 and B2- boring B2 was advanced, to 48 inches below surface, immediately west of the heating oil storage tank in the south tower boiler room- building floor slab was noted to be approx. 19 inches thick in borings B1 and B2- boring B3 was advanced, to 43 inches below surface, in the eastern freight elevator shaft of the south tower- elevator shaft is located immediately west of the south tower boiler room- height of the elevator shaft floor is six inches higher than boiler room floor- building floor slab in elevator shaft was approx. 8 inches thick- competent material was encountered at depth of 24 inches- found heavy, black oil coating on barrel of core drill when removed from all three borings- found free product on water in boreholes B1 (about less than one inch), B2 and B3 (about 3 inches)- depth to the top of the product layer was recorded at 24 inches below surface in all borings- under the elevator shaft, observed a 10 inches void beneath the floor slab, 3 inches of solid material, then another 3 inch void- oil was observed to be flowing into borehole B3 from both voids- sump pit was observed in the floor at the west end of the south tower boiler room- sump pit was approx. four ft square and appeared to contain a large volume of oil- black staining was obvious on the south wall to the shaft, which is also the exterior building wall (towards building 485 7th ave)- fingerprint analysis of oils from B2, B3 and sump pit indicate that each sample was #6 oil3) 03/11/96: letter from ERM summarizing spill history and site observations. abstract:- site occupies with two separate buildings with two separate boiler rooms- boiler room in north tower contains 7,500 gal #6 oil AST- boiler room in south tower contains 3,000 gal #6 oil UST <----- as per building employee who was present at the time of 1991 spill (spill #: 9110075): the 1,000 gal release occurred when a valve on the line between the fuel tank in the south tower and the fuel tank in the north tower was left open. the line is used to transfer oil between the two tanks when necessary. outside contractor was called into to clean the spill. free standing oil was vacuumed up. some oil also spilled into the sump and sump was cleaned.- as per building employee who was present at the time of 1993 spill (spill #: 9213026): spill occurred during the filling of 3,000 gal tank in the south tower. employee estimated that up to 1,000 gal oil may have been spilled and that some of the oil was discharged through the tank vent into the trench adjacent to the building (which may be subway

S102142464

vents). outside company cleaned up the spill- an unidentified caller reported spill (spill #: 9406980) in Aug. 1994. as per building super, who was present at the time of spill, it was in Aug. 1994 that the NYC Transit Authority noted oil in a subway tunnel adjacent to the building. representative of several city agencies inspected the 499 7th ave building but could find no evidence that the source of the oil was the building. it is possible that one of the transit worker reported spill, but was unable to provide any information since no spill was observed and no source could be found <----- tank was tested in Sep. 1994 and tank found tight (this tank test doesn't include information about which tank was tested: 7,500 gal tank in north tower or 3,000 gal tank in south tower) <----- during site inspection, ERM noted a small sump underneath one of the boiler and that small sump connects to the larger sump in the boiler room (most probably in south tower)- ERM cleaned out both sumps- found oil seepage through sump walls about one ft below top of sump- PID survey done in basements of both towers and also in vaults on sidewalk (MTA vents)- found high PID readings in MTA vaults: 100 ppm in vaulted area and 190 ppm in northwest corner of the vaulted area4) 05/09/96: letter from ERM with boring proposal for delineation purpose. abstract:- there are no accessible locations for borings on the east or on the west side of the boiler room in the south tower- there is no open area on the east side of building- the sidewalk and 7th ave are located on the west side of the building at ground level, and a ConEd vault is located on the basement level- an alley on south side of the boiler room at ground level; this alley belongs to 485 7th ave- boiler room of the north tower is on the north side of the boiler room of the south tower5) 01/21/97: update status letter from ERM. abstract:- installed three wells (MW-1, MW-2 and MW-4), between 2 and 3 ft deep as bedrock encountered in each well- proposed well MW-3 in the next door alley was not installed as no access allowed- MW-1 (probably 6 inch diameter) was installed adjacent to the oil tank in south tower boiler room- MW-2 (probably 6 inch diameter) was installed in the service elevator shaft in the south tower basement- MW-4 (probably 2 inch diameter) was installed in the boiler room of the north tower- no oil found in wells MW-1 and MW-4- approx. 1 ft of product found in well MW-26) 02/17/00: Oil Remediation Closure Report. abstract:- injected Biosolve surfactant through the basement wall and into soil underlying the trench, adjacent to building- did high vacuum extraction of product, water and air- upgraded monitoring/recovery well in the elevator pit in north tower, by replacing 6 inch diameter well with 10 inch diameter well- well was installed to 2.5 ft bg where bedrock found- conducted monthly monitoring of wells- no oil found in well MW-4 from 09/98 to 10/99- found no petroleum to a thin layer of oil in well MW-2 in elevator shaft- during 13 month monitoring period (09/98 to 10/99), a total of approx. 10 gal of petroleum recovered from MW-2*****3:45 PM:- visited site again and inspected south tower. found a 3,000 gal tank completely wrapped in concrete in the boiler room. no tank label found near gauge. found a monitoring well near the tank (this could be well MW-1). during inspection, found one boiler and one water tank in the boiler room. also found three horizontal PVC pipes in southern wall of the tank room (this wall towards the alley at building 485). one PVC pipe is near the tank and remaining two pipes are near the elevator shaft area. another well found in elevator shaft (this could be well MW-2). found sump in

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

491 7TH AVE (Continued)

S102142464

boiler room near the elevator shaft area. found dry oil stains on southern foundation wall- both in tank room (closer to elevator shaft area) as well as elevator shaft. met Robert Facciola (212-967-8797) in south tower. Robert is working on-site since 1996. he mentioned that building was using #6 oil and then switched to #4 oil. also, tanks in both north and south towers are no longer connected. as per Robert, tank/boiler room and elevator shaft are the two lowest points in entire basement. they stopped monitoring the site about four years ago as no more oil found in wells. he also mentioned that MTA cleans out their vents every two years to prevent drain plugs which cause water flooding in the south tower. Robert did not get any complaints from MTA for long time. found vent pipe in foundation wall towards the next door alley and fill port on sidewalk near the building foundation wall, on north side of the south tower entrance (on other side from the alleyway). alley is about 4.5 ft wide. after reviewing available information, changed address in spill report from 499 7th ave to 491 7th Ave. discussed with DEC Austin. based on available information, Austin asked for monitoring and sampling from existing wells in both towers and soil and groundwater investigation in alley at building 485. he also asked to find out location of pipe which was connecting two tanks in past. alternate addresses for building 485: 481-489 7th Ave, 155-163 West 36th Street. no spill reports found at building 485. PBS for building 485: 2-606511. as per the PBS record, building 485 has one 10,000 gal #6 oil AST on legs. tank was installed in Oct. 1981. 3:32 PM:- left message for Robert Kelly, super of building 485. Robert Kelly **super of building 485**PH. (917) 295-2958. Gedula 26, LLC. and 485 Shur LLC. **owners of building 485**c/o Eretz Group **management company**485 7th Avenue, Suite 717 New York, NY Attn.: Danny Talass PH. (212) 714-2270 (212) 971-4000 email: jrose@eretzgroup.com 12/13/10-Hiralkumar Patel. 11:50 AM:- visited site. met Mr. Kelly at building 485. building 485 has one 10,000 gal #6 oil AST on legs. tank is in secondary containment. tank is location along 7th ave and almost in middle of basement. tank at building 485 is away from alley between the building 485 and building 491. as per Mr. Kelly, the tank is about 28 years old and he is working in the building for about 26 years. Mr. Kelly never observed any oil leak into the building from alley side. all the lines for tank are aboveground. fill box for the tank at the building 485 is in middle of the sidewalk, close to E 36th street. 12:11 PM:- left message for Mr. Robustelli. 12/14/10-Hiralkumar Patel. 11:55 AM:- left message for Mr. Robustelli. 12:28 PM:- received message from Mr. Robustelli. 12:31 PM:- spoke with Mr. Robustelli and informed him that based on available information, the Department requires further investigation in alleyway and monitoring/sampling of wells. 12:45 PM:- left message for Mr. Talass, property manager for building 485. 12:51 PM:- spoke with Mr. Kelly, super of building 485. he mentioned that the alley between two buildings is the community alley and serves five building in total. he mentioned that the alley doesn't belong to any particular building, but a combined property. 12/17/10-Hiralkumar Patel. 9:10 AM:- visited site. met Robert Facciola. Robert showed old pipe which was connecting tanks in both tower. old connecting pipe was running aboveground along ceiling. piece of old pipe found in northern wall of the boiler room, no top of the 3,000 gal tank. during visit, Robert opened valve on pipe installed in southern wall of the boiler room and this pipe goes under the alleyway. no oil or water came out of this pipe. Robert mentioned that they open this valve every six months. sometimes they get water, but no oil observed

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

491 7TH AVE (Continued)

S102142464

in last couple of years. inspected alley. vent pipe for the 3,000 gal tank is running aboveground along the foundation wall of the south tower. alley is about 4.5 ft wide in front, but about 15 ft wide in rear, but alley is full of stuff (AC units, storage etc.).12/22/10-Hiralkumar Patel.7:41 AM:- received message from Mr. Robustelli.3:10 PM:- left message for Mr. Robustelli.01/03/11-Hiralkumar Patel. after discussing with Randy, case closed as no product found in wells or sump in south tower and no oil from recovery pipes installed in southern wall under the alleyway.summary:- 3,000 gal tank in south tower was used to store #6 oil, but now contains #2 oil- tanks in south and north towers were connected in past- about 1,000 gal oil spilled from valve on pipe connecting tanks in both towers- about 1,000 gal oil spilled due to tank overfill; some oil got into MTA vent on 7th ave sidewalk- tank test from Sep. 1994 doesn't include information about which tank was tested: 7,500 gal tank in north tower or 3,000 gal tank in south tower- wells installed in south tower boiler room, south tower elevator shaft and in boiler room in north tower- an alley on south of south tower and this alley belongs to 485 7th Ave
Not reported

Remarks:

Material:

Site ID: 304953
Operable Unit ID: 1001256
Operable Unit: 01
Material ID: 380000
Material Code: 0064A
Material Name: UNKNOWN MATERIAL
Case No.: Not reported
Material FA: Other
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 9110075
Facility Type: ER
DER Facility ID: 92890
Site ID: 105260
DEC Region: 2
Spill Date: 12/22/1991
Spill Number/Closed Date: 9110075 / 12/26/1991
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 3101
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 12/22/1991
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 12/26/1991

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

491 7TH AVE (Continued)

S102142464

Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1/31/1992
Spill Record Last Update: 5/22/1998
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: ***Update***, ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIBBE"SEE94-06980. ALSO 92-13026.
Remarks: Not reported

Material:
Site ID: 105260
Operable Unit ID: 960095
Operable Unit: 01
Material ID: 418647
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1000
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DM664
SE
1/4-1/2
0.483 mi.
2550 ft.

1410 BRODAWAY OFFICE BLDG
1410 BROADWAY
NY, NY

NY LTANKS

S104276721
N/A

Site 1 of 2 in cluster DM

Relative:
Higher

LTANKS:
Site ID: 226089
Spill Number/Closed Date: 9513787 / 2/11/2003
Spill Date: 1/30/1996
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1/30/1996
CID: 312
Water Affected: Not reported

Actual:
55 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1410 BRODAWAY OFFICE BLDG (Continued)

S104276721

Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1/30/1996
Spill Record Last Update: 2/11/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN OIL COMPANY
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: RICHARD EISENHART - MGR
Spiller Phone: (212) 391-0060
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 186631
DEC Memo: Not reported
Remarks: UNK OIL COMPANY OVERFILLED OIL TANK FOR THE BLDG

Material:

Site ID: 226089
Operable Unit ID: 1028282
Operable Unit: 01
Material ID: 357496
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DM665
SE
1/4-1/2
0.483 mi.
2550 ft.

ROADWAY
1410 BROADWAY
MANHATTAN, NY
Site 2 of 2 in cluster DM

NY LTANKS S108299198
N/A

Relative:
Higher

LTANKS:
Site ID: 375424
Spill Number/Closed Date: 0610898 / 12/28/2006
Spill Date: 12/28/2006
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 12/28/2006

Actual:
55 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ROADWAY (Continued)

S108299198

CID: 410
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/28/2006
Spill Record Last Update: 12/28/2006
Spiller Name: FDNY HAZMAT
Spiller Company: UNKNOWN
Spiller Address: 1410 BROADWAY
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: FDNY HAZMAT
Spiller Phone: (347) 203-6886
Spiller Extention: CELL
DEC Region: 2
DER Facility ID: 325053
DEC Memo: spoke with Paul in FDNY. it was vegetable oil not #2 oil. case closed.
Not reported
Remarks: SPILL IS DUE TO OVERFILL THIRD PARTY INFO UNKNOWN, SOME MATERIAL HAS
ENTERED SEWER AT THIS LOCATION: HAZMAT IN ROUTE TO SCENE:

Material:

Site ID: 375424
Operable Unit ID: 1133060
Operable Unit: 01
Material ID: 2122865
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 40
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 375424
Operable Unit ID: 1133060
Operable Unit: 01
Material ID: 2122863
Material Code: 1856A
Material Name: VEGETABLE OIL (DYE/GREASE)
Case No.: Not reported
Material FA: Other
Quantity: 40
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DL666
South
1/4-1/2
0.484 mi.
2557 ft.
M B HAMPTONS LLC. - TTF
224 WEST 30TH STREET
NEW YORK, NY 10001
Site 2 of 2 in cluster DL

NY LTANKS **S103478240**
N/A

Relative:
Higher

Actual:
39 ft.

LTANKS:

Site ID: 60072
Spill Number/Closed Date: 9806038 / Not Reported
Spill Date: 8/14/1998
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: TJDEMEO
Referred To: MACDONALD
Reported to Dept: 8/14/1998
CID: 322
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 1
Date Entered In Computer: 8/14/1998
Spill Record Last Update: 8/13/2012
Spiller Name: DONALD LEE
Spiller Company: M B HAMPTONS
Spiller Address: 224 WEST 30TH ST
Spiller City,St,Zip: MANHATTAN, NY 999
Spiller Contact: DONALD LEE
Spiller Phone: (212) 714- 2902
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 10092
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "M TIBBE"Jeremy Musklin224 W. 30th StreetManhattan, NY 718-643-5461Spill assigned to James Drumm for SCIpresent owner is M.B. Hamptons phone # 212 714 2902Donald Lee is contactowner is not aware that there was a spill on the property. spill was reported before they bought the building. spill report faxed to them on 10/19/0508/13/12 - LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo tank test failure

Remarks:

Material:

Site ID: 60072
Operable Unit ID: 1067217
Operable Unit: 01
Material ID: 317211
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

M B HAMPTONS LLC. - TTF (Continued)

S103478240

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DI667
East
1/4-1/2
0.484 mi.
2558 ft.

COMMERCIAL PROPERTY
150 W 47TH ST
MANHATTAN, NY
Site 2 of 2 in cluster DI

NY LTANKS **S104782441**
N/A

Relative:
Higher

LTANKS:

Actual:
51 ft.

Site ID: 250226
Spill Number/Closed Date: 0007888 / 5/28/2004
Spill Date: 7/27/2000
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 10/4/2000
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 10/4/2000
Spill Record Last Update: 5/28/2004
Spiller Name: Not reported
Spiller Company: COMMERCIAL PROPERTY
Spiller Address: 150 W 47TH ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: ANR KALIMIN REALTY
Spiller Phone: (212) 751-8050
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 205108
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"5/28/2004 PTC submitted a report for this site which outlines excavation work done in Oct 2001. According to PTC, 24 drums of contaminated soil was removed from the basement area. Bedrock was hit at about 3 ft depth and no further digging could be done. There was still some minor contamination left, but the majority of the problem was removed.Spill Closed - No further action
Remarks: THEY REMOVED A TANK BACK IN JULY & DISCOVERED IT HAD BEEN LEAKING - CLEAN UP HAS BEEN IN PROGRESS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL PROPERTY (Continued)

S104782441

Material:

Site ID: 250226
Operable Unit ID: 828533
Operable Unit: 01
Material ID: 545410
Material Code: 0002A
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DN668
North
1/4-1/2
0.488 mi.
2576 ft.

ASTOR SUBSTATION PROJECT SITE
700 11TH AVE, 549-551 & 553-557 W 49TH ST
NEW YORK, NY 10019

NY BROWNFIELDS

S106906504
N/A

Site 1 of 2 in cluster DN

Relative:
Lower

BROWNFIELDS:

Program: BCP
Site Code: 337122

Actual:
24 ft.

Site Description: The Astor substation site was formerly called the Riverside Substation site. Con Edison, the project applicant, changed the project name to Astor Substation site in response to discussion with various community members in October 2005. The Astor substation site (~ 0.6 acres in size) is located along the eastern side of 11th Avenue between west 49th and West 50th Street in the Clinton section of the borough of Manhattan, city of New York, at latitude 40 degree 45' 57.2" and longitude 73 degree 59' 40.9", and designated as tax parcels Block 1078, Lots 1 and 5 on the Tax Map of the City of New York, New York County. The street address for the parcel is 700 11th Avenue (which also known as 549-551 and 553-557 West 49th Street), New York, NY 10019. During 1930 to 1940, the site had been used for gasoline filling station and automobile service garage. Prior to its acquisition by Con Edison on April 12, 2005, the site was owned and operated by Martin Motors Sales, Inc. (MMS) as a retail automobile sales and service facility. The area around the site is fully developed as commercial, residential and institutional uses to the east, north and south; with another Con Edison electrical substation located west of the site across 11th Avenue. The building on the site had been demolished in connection with Con Edisons redevelopment of the Site into an electrical substation that is needed to meet the increasing demand for power in midtown Manhattan. The site is currently being redevelop and the electrical substation construction is anticipated to be completed sometime in 2008. Investigations completed at the site include a Limited Phase II Environmental Site Assessment (January, 2005) and Remedial Investigation Report (November 2005). The volunteer has submitted and the Department has approved a Remedial Action Work Plan(RAWP) which involves excavation of soil at the entire site and the northern portion of 11th avenue sidewalk area along the western site property

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION PROJECT SITE (Continued)

S106906504

line down to top of bedrock surface. Contaminated media will be removal and properly disposed off-site. Implementation of the approved RAWP started on 4/25/06. Remedial construction was completed on February 2007. Remedial Action Report(RAR) date March 2007 and RAR addendums dated April 2007 and November 2007 respectively, collectively equivalent to a Final Engineering Report. FER was approved on 12/21/2007 and a Certificate of Completion was issued on 12/21/2007.

Env Problem: Site investigations conducted prior and after implementation of the BCP agreement revealed that the presence of underground storage Tanks (USTs) that were associated with the former gas station or automobile repair facility; petroleum contamination in the northwest corner of the site (both on-site and off-site) in soil and groundwater, including petroleum product on the groundwater surface(up to 5 feet of separate-phase product has been detected in an off-site well in the vicinity of the former gasoline filling station located in the north west portion of the site); soil and groundwater near the location of a former oil/water separator in the garage area which is located south east of the site had been impacted by the former site uses (automobile service garage); Soil Gas sampling indicates the presence of VOCs, including both gasoline related compounds and chlorinated solvents (PCE, and TCE) that are consistent with findings in soil, groundwater, and pass site use, The remedial investigation report also identify a NYSDEC spill site (spill # 8904939 petroleum origin) is located at the southeast corner of west 51st street and 11th avenue about one block north of Astor substation site, these off-site properties may be contributing to the soil vapor detections; Low level of PAHs and Metals were detected from on site soil; Sediment samples from the floor drain in the service garage indicated the presence of PCE, TCE and gasoline related compounds with concentration above the TAGM4046 recommended soil clean up objective. The applicant had implemented the approved Interim Remedial Measures (IRM) to recover petroleum product identify in the on and off site wells since September of 2005. The thickness of the petroleum product in groundwater monitoring wells show significant drop as the result of the IRM activities. The quality exposure assessment indicated the lack of exposure pathways at the site because of the current ground surface is covered with impervious surface. DEC has determined, in consultation with NYSDOH, that the conditions at this site do not pose a significant threat to human health or the environment. The RAWP dated December 2005 was approved March 31, 2006 has been implemented. The FER has been approved and the COC issued in December 2007.

Health Problem: Public water is provided to the area, thereby preventing exposures to groundwater. The site is currently covered with buildings and pavement, preventing direct contact exposures.

DN669
North
1/4-1/2
0.488 mi.
2576 ft.

ASTOR SUBSTATION BCP SITE
700 11TH AVE
MANHATTAN, NY

NY LTANKS
NY Spills

S108058473
N/A

Site 2 of 2 in cluster DN

Relative:
Lower

LTANKS:
Site ID: 265946
Spill Number/Closed Date: 0103148 / Not Reported
Spill Date: 6/21/2001
Spill Cause: Tank Test Failure

Actual:
24 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: AAOBLIGA
Referred To: STIP SIGNED 12/5/08. IWP DUE 12/26/08.
Reported to Dept: 6/21/2001
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 1
Date Entered In Computer: 6/21/2001
Spill Record Last Update: 11/28/2011
Spiller Name: CALLER
Spiller Company: MARTIN MOTORS
Spiller Address: 700 11TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 216711
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "VOUGHT"7/1/02 TJDReceived work plan from Emteque (John Raguso). Expedited review at consultant's request. Unable to approve plan as report missing key information and site not complete deliniated. Consultant directed to provide a modified plan which includes installation of wells and contains missing report data. Missing data includes: boring logs, MTBE analysis, plume boundaries, scaled map which includes all tanks and relevant site features, groundwater flow direction etc..7/1/03 TJDStu Bassel (LMS 845 735 8300) contacted DeMeo to inform DEC that LMS had taken over project. A work plan will be submitted to remove tanks, excavate accessible soils, use bio-remediation to treat groundwater contamination and soil vapor extraction to remediate the soil contamination. LMS was also directed to provide any recent sampling data & all relevant information regarding the proposed bio-remediation application. In addition LMS was informed hydraulic control would be required if bio remediation is approved for the site.8/29/03 TJDRereassigned to Vought9/18/03: Martin Motors submits Supplemental Conceptual Remedial Plan prepared by LMS. In cover letter, Martin Motors reports that approximatley 5 feet of product was found in well MW-2 on or around July 28. Manual bailing program initiated - approx. 20 gallons product recovered through 8/21/03. Product thickness in well dropped to approx 2 feet as of 8/21. (JHO, 1/13/05)1/6/05-Vought-Vought spoke David Rubin (Con Ed 718-204-4219) who is looking to install a substation at this site. Con Ed looking to resolve open spill issue and have BCP pre-application meeting. Con Ed will notify current owner of meeting.1/10/05Spill reassigned to O'Connell. Con Ed will be attending pre-app meting with DEC on 1/21/05. Con Ed apparently conducted preliminary off-site investigation, but no report was

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

submitted to the Department. Will request copy at pre-app meeting.
(JHO)5/10/07: On-site cleanup was completed by Con Edison under a Brownfield Cleanup Agreement (site no. C231047, Astor Substation). There is still off-site gasoline contamination that remains beneath the sidewalk and street on 11th Avenue. This spill number is being transferred to the Petroleum Remediation group for follow up with the responsible party.
(JHO)

-----8/28/08: Reassigned from Vadim Brevdo to Kartik Chanda. (Chanda)9/3/08: Chanda updated this spill site and discussed with Mark Tibbe and Bryan (NYSDEC) regarding the off-site contamination originated from this site. It is concluded that a Stipulation Agreement (STIP) with a Corrective Action Plan (CAP) will be sent to RP (previous owner of this site).9/8/08: Chanda sent a STIP and CAP to RP (Anthony Chianese, vice president of Martin Motors) via certified mail. (see eDocs)9/19/08: The letter was undeliverable. Chanda made a phone call to David B. Rubin, Con Edison to get the previous property owner's name and address. Mr. David B. Rubin (Con Edison) sent the following contact information: The RP name is: Martin Schlanger Martin Motor Sales, Inc. 677 11th Avenue New York, NY 10019 The RP's Attorney is: Mr. Joseph P. Baratta Baratta & Goldstein 597 Fifth Avenue New York, NY 10017 Ph. (212) 750-97009/22/08: Chanda discuss with Mark Tibbe(NYSDEC)and resent a STIP and CAP to RP (Martin Schlanger, Martin Motors) via certified mail and a copy to RP's Attorney via regular mail.10/09/08: The letter comes back to DEC. Chanda discussed with Mark Tibbe and John Urda regarding this site. John Urda search NYS Department of State database and find out the following information:* Chairman or Chief Executive Officer: Janet Schlanger 1281 Gulf of Mexico DR/#802 Long Boat Key, Florida, 34228* Principal Executive Office Martin Motors Sales Inc. 677 11th Avenue New York, New York 1001910/14/08: Chanda performed a site visit at 700 11th Avenue (Astor Substation) and across the street at 677 11th Avenue (Martin's Manhattan). The Martin Motor Business is still at 677 11th Avenue. Chanda has taken several photographs regarding the current location of Martin Motors.10/16/08: Chanda discussed with Mark Tibbe and John Urda (NYSDEC) and sent another letter to Ms. Janet Schlanger (Florida) via certified mail and Martin Motors via DEC's Conservation Officer.10/24/08: Chanda received a phone call from Andrew E. Skroback. he is the environmental attorney for this site. He request time extension to submit the signed STIP. Chanda received an extension request via the following email:" Dear Mr. Chanda: It was a pleasure speaking with you today. As discussed, I write on behalf of Martin Motor Sales, Inc. to request an extension of our deadline to respond to your letter of September 22, 2008, such that our response to your letter would now be due on or before Monday November 24, 2008. Please confirm this extension by return email. Once we have time to review the past technical reports, I propose that we arrange a meeting between NYDEC, myself and ERM to discuss the scope of what should be done at the site and the scope of the proposed corrective action plan, as well as other potential sources of area contamination. I look forward to working with you on this matter. Best regards, Andrew E. Skroback (Drew) Stroock & Stroock & Lavan LLP 180 Maiden Lane New York, NY 10038 (212) 806-6446 askroback@stroock.com " 10/28/08: Chanda discussed with Mark Tibbe (NYSDEC) and approved one month extension to submit the signed STIP. The signed STIP must be submitted to DEC by November 24,

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Remarks: 2008.12/08/08: Transferred from Chanda to Tibbe. STIP effective 12/05/08. 9/20/09 - Austin - closed and referred spill # 0609005 to this one, a report from Con Ed of finding gasoline contaminated soils in the immediate vicinity of this site. See report and eDocs - end 11/12/10 - spill re-assigned from Tibbe to Joe O'Connell 11/28/11 - Obligado - Spill re-assigned from O'Connell to Obligado site work found contaminated soil.

Material:

Site ID: 265946
Operable Unit ID: 841848
Operable Unit: 01
Material ID: 535242
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Site ID: 369108
Spill Number/Closed Date: 0605854 / 12/21/2006
Spill Date: 8/21/2006
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 8/21/2006
CID: 444
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 8/21/2006
Spill Record Last Update: 12/21/2006
Spiller Name: ERTS
Spiller Company: EXCAVATION
Spiller Address: 700 11TH AVE
Spiller City,St,Zip: MANHATTEN, NY
Spiller County: 001
Spiller Contact: ERTS
Spiller Phone: (212) 580-8383
Spiller Extention: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

DEC Region: 2
DER Facility ID: 216711
DEC Memo: 12/21/06 - See e-docs for Con Ed report detailing cleanup and closure. Spill assigned to Yuk Yin Wong, DER project manager for Astor Substation BCP, for follow up. (JHO)
Remarks: coming from an old tank that was leaking: 1 pint of motor oil: coned # 202049

Material:
Site ID: 369108
Operable Unit ID: 1126956
Operable Unit: 01
Material ID: 2116524
Material Code: 0015
Material Name: Motor Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

SPILLS:

Facility ID: 0604159
Facility Type: ER
DER Facility ID: 216711
Site ID: 367076
DEC Region: 2
Spill Date: 7/14/2006
Spill Number/Closed Date: 0604159 / 11/15/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 7/14/2006
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 7/14/2006
Spill Record Last Update: 11/15/2006
Spiller Name: ERTS
Spiller Company: CON EDISON
Spiller Address: 711 AVE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 999
Contact Name: ERTS
Contact Phone: (212) 580-8383
DEC Memo: 11/15/06 - See e-docs for Con Ed report detailing cleanup and closure.201143. see eDocs
Remarks: CONED # 201143- NO TO 5 QUESTIONS

Material:

Site ID: 367076
Operable Unit ID: 1125000
Operable Unit: 01
Material ID: 2114506
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0601353
Facility Type: ER
DER Facility ID: 216711
Site ID: 363572
DEC Region: 2
Spill Date: 5/5/2006
Spill Number/Closed Date: 0601353 / 5/25/2007
Spill Cause: Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 5/5/2006
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 5/5/2006
Spill Record Last Update: 5/25/2007
Spiller Name: ERT DESK
Spiller Company: CON EDISON
Spiller Address: 700 11TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Contact Name: ERT DESK'
Contact Phone: (212) 580-8383
DEC Memo: 164125.5/25/07: All soil at site was removed under BCA (see site no C231047). Close. (JHO)
Remarks: FOUND DURING EXCAVATION ; LAB TAKING RESULTS AND CHECKING OUT: CONED #164125

Material:
Site ID: 363572
Operable Unit ID: 1121621
Operable Unit: 01
Material ID: 2111123
Material Code: 0066A
Material Name: UNKNOWN PETROLEUM
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0607790
Facility Type: ER
DER Facility ID: 216711
Site ID: 371607
DEC Region: 2
Spill Date: 10/9/2006
Spill Number/Closed Date: 0607790 / 10/10/2006
Spill Cause: Equipment Failure
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 10/9/2006
CID: 408
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/9/2006
Spill Record Last Update: 10/10/2006
Spiller Name: ERTS
Spiller Company: ASTERO SUB STATION
Spiller Address: 700 11TH AVE
Spiller City,St,Zip: MANHATTAN, NY
Spiller Company: 001
Contact Name: ERTS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Contact Phone: (212) 580-8383
DEC Memo: Con Ed no. 202816 - see eDocs for closure info. (JHO)
Remarks: contained and cleaned;escavator; ref# 202816

Material:

Site ID: 371607
Operable Unit ID: 1129364
Operable Unit: 01
Material ID: 2119019
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 0608770
Facility Type: ER
DER Facility ID: 216711
Site ID: 372769
DEC Region: 2
Spill Date: 10/31/2006
Spill Number/Closed Date: 0608770 / 5/25/2007
Spill Cause: Human Error
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
SWIS: 3101
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 10/31/2006
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/31/2006
Spill Record Last Update: 5/25/2007
Spiller Name: ERTS
Spiller Company: CON EDISON
Spiller Address: 700 11TH AVE
Spiller City,St,Zip: NEW YORK, NY
Spiller Company: 999
Contact Name: ERTS
Contact Phone: (212) 580-8383
DEC Memo: 203105. see eDocs5/25/07: spill was not dielectric fluid - it was unknown petroleum from a tank. All soil at site was removed under BCA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ASTOR SUBSTATION BCP SITE (Continued)

S108058473

Remarks: (see site no C231047). Close. (JHO)
moving a storage tank: and oil spilled on to soil; no to 5 questions:
leak is stoppped and cleaning up at this time coned#203105

Material:

Site ID: 372769
Operable Unit ID: 1130503
Operable Unit: 01
Material ID: 2120175
Material Code: 0541A
Material Name: DIELECTRIC FLUID
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

670
NNW
1/4-1/2
0.494 mi.
2607 ft.

BETWEEN 11TH & 12TH
49TH
MANHATTAN, NY

NY LTANKS **S105999950**
N/A

Relative:
Lower

LTANKS:

Actual:
17 ft.

Site ID: 160458
Spill Number/Closed Date: 0306468 / 9/18/2003
Spill Date: 9/18/2003
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MXTIPPLE
Referred To: Not reported
Reported to Dept: 9/18/2003
CID: 365
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 9/18/2003
Spill Record Last Update: 9/18/2003
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BETWEEN 11TH & 12TH (Continued)

S105999950

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 135495
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "TIPPLE"9/18/03 1359 Hrs DDO Sawyer talked to Cindy Tadler at Century Petroleum and she assured me that this spill would be cleaned up. Closed. Further information should be noted under spill #0306463.
Remarks: they were on site making a delivery to a tank & the whistle blew so they stopped filling - a con ed employee then started to transfer oil from that just filled tank to a generator & overfilled it - caller would like a call back as to who's responsibility this is for clean up
Not reported

Material:
Site ID: 160458
Operable Unit ID: 875227
Operable Unit: 01
Material ID: 503690
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

671
NNE
1/4-1/2
0.494 mi.
2609 ft.

**COMMERCIAL BUILDING
500 WEST 52ND STREET
MANHATTAN, NY**

NY LTANKS

**S111012249
N/A**

**Relative:
Lower**

LTANKS:
Site ID: 447753
Spill Number/Closed Date: 1100355 / 4/15/2014
Spill Date: 4/11/2011
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: VXBREVDO
Referred To: Not reported
Reported to Dept: 4/11/2011
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False

**Actual:
25 ft.**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S111012249

Remediation Phase: 0
Date Entered In Computer: 4/11/2011
Spill Record Last Update: 4/15/2014
Spiller Name: Not reported
Spiller Company: HOUSING PERSERVATION DEVELOPMENT
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller County: 999
Spiller Contact: DEREK PARSONS
Spiller Phone: (917) 559-4337
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 402345
DEC Memo: "Modified" TTF letter e-mailed to HPD property manager -Derek Parsons.Director, Environmental Compliance NYC HPD - Office of Development100 Gold St, Rm 9V-5, NY, NY 10038(p) 212-863-7172; (f) 212-863-7988, (C) 917-559-4337parsonsd@hpd.nyc.gov e-mail message sent:Attn: Derrick Parsons, HPD Property ManagerThe following spill cases refer to two Tank Test Failures that both occurred on April 11, 2011.Spill #1100355 - 500 West 52nd St, Manhattan Spill #1100365 - 400 Grand St, ManhattanBelow is the standard text sent out to all property owners/managers after a tank test failure:On April 11, 2011 the New York State Department of Environmental Conservation (the Department) received notification of a tank system integrity failure at the above mentioned facility. You have been identified as either the owner of this tank or the owner's representative. Because the tank system was found not to be tight, a petroleum release may have occurred at this property, which is a violation of the New York State Environmental Conservation and Navigation Laws. Therefore, the Department requires that you take immediate action to prevent and stop any additional release of petroleum, determine the cause of the failure, and investigate/remediate any soil and/or groundwater contamination, if a petroleum release has occurred. The following steps are required by the Department: 1. Determine if the "wet" portion of the tank system failed. If so or if it is inconclusive as to which part of the system failed, then the tank's contents must be emptied immediately to ensure that no further release occurs.2. Determine the cause of the tank system integrity failure. This process may include, but is not limited to, excavation of a part of the tank system, isolation of the tank from the piping and separate retesting, or tank and/or piping repair/replacement with subsequent system retesting.3. Remove any contaminated soil found during the excavation of the tank or piping to the extent feasible and properly disposed of it under applicable regulations for petroleum contaminated soil. 4. Submit a letter or report to this office no later than one month from the date of this letter. The report must be prepared by a qualified professional. The report must reference the spill case number and the site address. The report must specify the cause of the tank system failure and the actions taken to stop, minimize, or remove the petroleum release and must also include conclusions and recommendations for further action. Specific mention must be made if any contamination was found, and how it was dealt with. *****
*****Mr. Parsons - As per our telephone conversation, it sounds as though your office is proceeding with the required isolation and retesting necessary to determine the location of the leaking problem. In terms of the NYSDEC, we are most concerned with

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S111012249

the identification of any actual spill or soil contamination which may have resulted from a leak. Please get back in touch with our office as soon as this additional investigation is completed with any results you may be able to provide. Thank you, Steven Sangesland Environmental Engineer NYSDEC - Region 2 Spills Unit *****

*****5/12/2011

Sangesland spoke to Derrick Parsons at HPD. He had the environmental consultant in his office. He said the issue with 500 W 52nd St site was a dry leak from an old weld on the top of the tank. They tried to repair it, but it didn't work. (AST wrapped) Tank is being taken out of service and removed. Sangesland asked for a color photo of the tank area AFTER the tank was removed. If there is oil staining, a boring will be required. 07/16/13 - Spill Case is transferred from Brian Falvey (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision - Tank Test Failure Spill Case. VB03/24/2014 - V. Brevdoe-mail inquiry to NYCHPD: parsonsd@hpd.nyc.gov March 24, 2014 Dear Mr. Parsons: I am writing to inform you that the NYCHPD has two open petroleum spill cases: 400 Grand Street, New York Spill #1100365 and 500 West 52 Street, New York Spill #1100355. Attached to this e-mail are spill reports for these spill cases. The New York State Department of Environmental Conservation (the Department) communicated with you in 2011 regarding both of these spill cases. Based on the spill report for 400 Grand Street, NY Spill # 1100365, the last communication between the Department and yourself was on 5/12/2011 - telephone conversation. Based on the said telephone conversation it appears that the cause of spill was a bad oil fill line. Testing determined that the fill line under the sidewalk had failed and needed to be dug out, soil needed to be remediated, and replaced. It also appears that the remedial work was being scheduled at the time - See attached Spill Report. Based on spill report for 500 West 52 Street, New York Spill #1100355, it appears that this spill was a dry leak where no petroleum product was actually spilled / released into the environment. Could you please review documents in your possession regarding these two spills cases and submit said documents to my attention, so that the Department and NYCHPD can work together on these cases, determine whether any investigative/remedial activities are warranted, determine appropriate course of action, and bring these open spill cases to closure. Please contact me at your earliest convenience regarding this important matter. Thank you. Sincerely, Vadim Brevdo 04/15/2014 - V. Brevdo Received e-mail and attachments from Mr. Derek Parsons, director of Field Operations, Personnel and Environmental Compliance at NYCHPD. In regards to Spill # 1100355 which the tightness test failure at weld at top of tank, the tank was removed. Submitted is the FDNY letter and Gas free certificate closure notice for tank which were submitted to DEC. VB04/15 - V. Brevdo Based on documents provided by NYCHPD, the Department closed this spill case on 04/15/2014. No spill closure letter is issued. V. B.

Remarks:

1247 THE CALLER ADVISED DISPATCH THE SPILL AMOUNT IS UNKNOWN AT THIS TIME. THE TANK TEST REFLECTED A FAILURE IN THE SYSTEM. THE CLEAN UP IS PENDING UPON TANK REMOVAL. THE TANK IS ABOVE GROUND.

Material:

Site ID: 447753
Operable Unit ID: 1197962
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BUILDING (Continued)

S111012249

Material ID: 2194233
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DO672
West
1/4-1/2
0.497 mi.
2622 ft.

SILVERSTEIN 42ND ASSOC.
500-516 12TH AVE
MANHATTAN, NY
Site 1 of 2 in cluster DO

NY LTANKS **S104275739**
N/A

Relative:
Lower

LTANKS:

Actual:
12 ft.

Site ID: 106418
Spill Number/Closed Date: 9504838 / 7/3/1996
Spill Date: 7/20/1995
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 7/20/1995
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 8/15/1995
Spill Record Last Update: 9/14/2006
Spiller Name: Not reported
Spiller Company: ROSENMAN & COLIN
Spiller Address: 575 MADISON AVE
Spiller City,St,Zip: NEW YORK, NY 10022-2585
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 93753
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
"MULQUEEN"SITE OF FORMER COAL GASIFICATION PLANT & WAS INVESTIGATED
BY HAZ. WASTE REM. BUT FOUND NO 371 WASTES. SOILS AROUND USTS WERE
STOCKPILED AND REMOVED, GROUNDWATER HAD MINOR AMOUNTS OF BENZENE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SILVERSTEIN 42ND ASSOC. (Continued)

S104275739

Remarks: ALONG NORTH WEST CORNER OF SITE. F & T MODEL INDICATES THAT CONCENTRATIONS WILL NOT IMPACT SENSITIVE RECEPTORS - NFA.7/16/98
mmm:FILE TRANSFERED TO NYS RECORDS CENTER BOX # 306858.
SOIL CONTAMINATION/ GROUND WATER CONTAMINATION FOUND DURING TANK REMOVAL FROM MAY 8TH TO MAY 25TH, 1995

Material:

Site ID: 106418
Operable Unit ID: 1015753
Operable Unit: 01
Material ID: 366357
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 106418
Operable Unit ID: 1015753
Operable Unit: 01
Material ID: 366358
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

673
SE
1/4-1/2
0.497 mi.
2625 ft.

IN FORNT OF
146 WEST 38TH ST
MANHATTAN, NY

NY LTANKS S107523175
N/A

Relative:
Higher

LTANKS:

Actual:
52 ft.

Site ID: 356919
Spill Number/Closed Date: 0510869 / 12/16/2005
Spill Date: 12/16/2005
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 3101
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 12/16/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IN FORNT OF (Continued)

S107523175

CID: 409
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 12/16/2005
Spill Record Last Update: 12/16/2005
Spiller Name: UNKNOWN NAME
Spiller Company: HESS FUELS
Spiller Address: UNKNOWN
Spiller City,St,Zip: BAYONNE, NY
Spiller County: 001
Spiller Contact: JOHN LARAOCCHIA
Spiller Phone: (347) 203-6886
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 306966
DEC Memo: This is a duplicate spill - This one is closed outRef to 0510865 --
Alt address for this site is: 1385 Broadway
Remarks: CLEAN UP IN PROCESS.

Material:
Site ID: 356919
Operable Unit ID: 1114210
Operable Unit: 01
Material ID: 2104290
Material Code: 0003A
Material Name: #6 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

DO674
West
1/4-1/2
0.498 mi.
2627 ft.

PIER 79
WEST ST & 39TH ST
MANHATTAN, NY

Site 2 of 2 in cluster DO

NY LTANKS S105998978
N/A

Relative:
Lower

LTANKS:
Site ID: 187014
Spill Number/Closed Date: 0301651 / 1/30/2004
Spill Date: 5/15/2003
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Cleanup Ceased: Not reported
Cleanup Meets Standard: False

Actual:
12 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PIER 79 (Continued)

S105998978

SWIS: 3101
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 5/15/2003
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/15/2003
Spill Record Last Update: 1/30/2004
Spiller Name: KAY ZIAS
Spiller Company: PIER 79
Spiller Address: WEST ST & 39TH ST
Spiller City,St,Zip: MANHATTAN, NY
Spiller County: 001
Spiller Contact: KAY ZIAS
Spiller Phone: (212) 312-3752
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 156293
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEMEO"5/15/03 - ROSSAN, DDO - Contaminated soil letter was prepared and sent to: Ms. Kay Zias NYC Economic Development Corporation 110 William Street New York, NY 100381/30/04 TJD Closure report submitted by Metcalf & Eddy Consulting Engineers. Three tanks were removed from property and approximately 81 tons of contaminated soils were excavated and disposed of under manifest. Site is a NYC Pier which extends over Hudson River. The tanks formerly were located in an area supported by piles on a concrete slab. The soils between the slab and tanks and the soils above tank to grade are those which were excavated and disposed in accordance with applicable regulations. Endpoint sampling was performed which revealed minor exceedances to TAGM likely due to the historic fill material on site. No further action is required. Spill closed.
Remarks: DURING DEMOLITION OF PIER SOIL SAMPLES WERE TAKEN AND ANALYTICAL RESULTS SHOW CONTAMINATION

Material:
Site ID: 187014
Operable Unit ID: 868207
Operable Unit: 01
Material ID: 506143
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

675
North
1/2-1
0.859 mi.
4535 ft.

CON EDISON - WEST 58TH ST. STATION MGP
11TH AVE. BETWEEN W. 58TH - W. 59TH STS.
NEW YORK, NY 10019

EDR MGP

1008407996
N/A

Relative:
Lower

Manufactured Gas Plants:

No additional information available

Actual:
19 ft.

676
North
1/2-1
0.874 mi.
4617 ft.

ARTKRAFT STRAUSS SIGN CO
500 W 56TH ST
NEW YORK, NY 10019

RCRA NonGen / NLR
FINDS
NY SHWS
NY MANIFEST

1000271844
NYD986893360

Relative:
Lower

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007

Facility name: ARTKRAFT STRAUSS SIGN CO

Facility address: 500 W 56TH ST
NEW YORK, NY 10019

EPA ID: NYD986893360

Mailing address: 12TH AVE
NEW YORK, NY 10019

Contact: Not reported

Contact address: 12TH AVE
NEW YORK, NY 10019

Contact country: US

Contact telephone: Not reported

Contact email: Not reported

EPA Region: 02

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ARTKRAFT STRAUSS SIGN CO

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Operator

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Owner/operator name: ARTKRAFT STRAUSS SIGN CO

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212

Legal status: Private

Owner/Operator Type: Owner

Owner/Op start date: Not reported

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: ARTKRAFT STRAUSS SIGN CO
Classification: Not a generator, verified

Date form received by agency: 04/17/1995
Site name: ARTKRAFT STRAUSS SIGN CO
Classification: Not a generator, verified

Date form received by agency: 03/15/1990
Site name: ARTKRAFT STRAUSS SIGN CO
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 06/19/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004443781

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SHWS:

Program: HW
Site Code: 438965
Classification: N
Region: 2
Acres: 1.170

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

HW Code: 231071
Record Add: 08/20/2010
Record Upd: 01/12/2012
Updated By: BXANDERS
Site Description: The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. See site no. C231062A.
Env Problem: The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. See site no. C231062A.
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Owner
Sub Type: 09
Owner Name: Eva Billeci
Owner Company: Durst Development LLC
Owner Address: One Bryant Park, Floor 49
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10036
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

NY MANIFEST:

EPA ID: NYD986893360
Country: USA

Mailing Info:

Name: ART KRAFT
Contact: ART KRAFT
Address: 830 12TH AVENUE
City/State/Zip: NEW YORK, NY 10019
Country: USA
Phone: 212-265-5153

Document ID: NJA1216275
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

Generator Ship Date: 910814
Trans1 Recv Date: 910814
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910814
Part A Recv Date: Not reported
Part B Recv Date: 910826
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA1336815
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 911010
Trans1 Recv Date: 911010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 911010
Part A Recv Date: Not reported
Part B Recv Date: 911101
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA1072968
Manifest Status: Completed copy
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 920603
Trans1 Recv Date: 920603
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920610
Part A Recv Date: 920701
Part B Recv Date: 920623
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

TSD ID: NJD002182897
Waste Code: F005 - UNKNOWN
Quantity: 00840
Units: P - Pounds
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 92

Document ID: NJA0792725
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900404
Trans1 Recv Date: 900404
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900406
Part A Recv Date: 900618
Part B Recv Date: 900418
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01650
Units: P - Pounds
Number of Containers: 003
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NJA0706801
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900404
Trans1 Recv Date: 900404
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900404
Part A Recv Date: 900618
Part B Recv Date: 900412
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

Document ID: NJA0797101
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 000000000
Trans2 State ID: 000000000
Generator Ship Date: 900416
Trans1 Recv Date: 900416
Trans2 Recv Date: Not reported
TSD Site Recv Date: 900417
Part A Recv Date: 900723
Part B Recv Date: 900503
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00550
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NJA1081178
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 901207
Trans1 Recv Date: 901207
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901207
Part A Recv Date: 910409
Part B Recv Date: 910116
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NJA1071255
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 901009
Trans1 Recv Date: 901009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901009
Part A Recv Date: 910211

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

Part B Recv Date: 901116
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 90

Document ID: NJA0981928
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910104
Trans1 Recv Date: 910104
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910104
Part A Recv Date: 910416
Part B Recv Date: 910130
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA1205011
Manifest Status: Completed after the designated time period for a TSD to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910620
Trans1 Recv Date: 910620
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910620
Part A Recv Date: 910826
Part B Recv Date: 910701
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSD ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARTKRAFT STRAUSS SIGN CO (Continued)

1000271844

Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Document ID: NJA1139035
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NJDEPS869
Trans2 State ID: Not reported
Generator Ship Date: 910425
Trans1 Recv Date: 910425
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910425
Part A Recv Date: 910702
Part B Recv Date: 910510
Generator EPA ID: NYD986893360
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: NJD000768093
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00045
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 91

Count: 21 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CAMBRIA	1000556008	FORMER LOCKPORT AIR FORCE THE	COR OF NYS RTE 31 &	14132	RCRA NonGen / NLR, NY MANIFEST
FREEPORT	1007205959	VERIZON NEW YORK INC	37 GUY LOMBARDO & SUNRISE HWY	10016	RCRA NonGen / NLR
NEW YORK	S109584950	VERIZON NEW YORK INC. MANHOLE	ROUTE 110 E/S	10016	NY MANIFEST
NEW YORK	1008195877	RIVERSIDE PARK	145TH ST & W SIDE HWY	10031	RCRA-SQG, NJ MANIFEST, NY MANIFEST
NEW YORK	S109064422	BELL ATLANTIC NY	30TH ST & WESTSIDE HWY SE MANH		NY MANIFEST
NEW YORK	S109064446	BELL ATLANTIC NY	W 31ST ST & WESTSIDE HWY MANHL		NY MANIFEST
NEW YORK	S105912830	NYC DOS WEST 30TH STREET RECYCLING	WEST 30TH STREET & WEST SIDE H	10001	NY SWF/LF
NEW YORK	S112258046	NYCDOS WEST 59TH STREET MTS	WEST 59TH WEST 59TH STREET & W	10023	NY SWF/LF
NEW YORK	S109942993	59TH GENERATION STATION	59TH ST OFF THE WEST SIDE HIGH		NY Spills
NEW YORK	1014399395	NYSDOT BIN 107706C	RTE 907L 0.04 MI SW OF I-495	10016	RCRA-LQG
NEW YORK	1014399394	NYSDOT BIN 107706A	RTE 907L BETWEEN 30TH & 29TH	10016	RCRA-LQG
NEW YORK	1012187134	NYSDOT BIN 107706B	RTE 907L OVER 34TH ST SITE 2	10016	RCRA-LQG
NEW YORK	1007205804	BELL ATLANTIC-NY	KINGS HWY E 12	10016	RCRA NonGen / NLR
NEW YORK	1000332638	SUNOHIO PCBX UNIT LONG ISLAND RAIL	LYNBROOK HWY	10001	RCRA NonGen / NLR, NY MANIFEST
NEW YORK	1009238515	CONSOLIDATED EDISON	MH10820-NEW HWY & MAIN ST	10001	NY MANIFEST
NEW YORK	S113921848	NYCDOT BIN 2257569	MILLER HWY OVER TERRAIN W SIDE	10023	NY MANIFEST
NEW YORK	1016144307	NYCDOT BIN 2257569	MILLER HWY OVER TERRAIN	10023	RCRA-LQG
NEW YORK	1007571215	LAW & ORDER PRODUCTIONS	PIER 62 W 23RD ST WESTSIDE HWY	10011	RCRA-CESQG, NJ MANIFEST, NY MANIFEST
NEW YORK CITY	1007207470	VS3610	E.14TH ST. AND KINGS HIGHWAY	11235	RCRA NonGen / NLR, NY MANIFEST
PARAMUS	S108065423	THE CONTAINER STORE	350 RTE 17 N & 15 POWERS DR	10019	NJ VCP
SOUTH BRUNSWICK	S106763378	S BRUNSWICK SQUARE SHOPPING CENTER	4095 RTE 1	10019	NJ VCP

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/25/2013	Source: EPA
Date Data Arrived at EDR: 11/11/2013	Telephone: N/A
Date Made Active in Reports: 01/28/2014	Last EDR Contact: 07/08/2014
Number of Days to Update: 78	Next Scheduled EDR Contact: 10/20/2014
	Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/25/2013	Source: EPA
Date Data Arrived at EDR: 11/11/2013	Telephone: N/A
Date Made Active in Reports: 01/28/2014	Last EDR Contact: 07/08/2014
Number of Days to Update: 78	Next Scheduled EDR Contact: 10/20/2014
	Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991	Source: EPA
Date Data Arrived at EDR: 02/02/1994	Telephone: 202-564-4267
Date Made Active in Reports: 03/30/1994	Last EDR Contact: 08/15/2011
Number of Days to Update: 56	Next Scheduled EDR Contact: 11/28/2011
	Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/25/2013	Source: EPA
Date Data Arrived at EDR: 11/11/2013	Telephone: N/A
Date Made Active in Reports: 01/28/2014	Last EDR Contact: 07/08/2014
Number of Days to Update: 78	Next Scheduled EDR Contact: 10/20/2014
	Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/25/2013	Source: EPA
Date Data Arrived at EDR: 11/11/2013	Telephone: 703-412-9810
Date Made Active in Reports: 02/13/2014	Last EDR Contact: 08/28/2014
Number of Days to Update: 94	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/01/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 07/08/2014	Telephone: 703-603-8704
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 07/08/2014
Number of Days to Update: 45	Next Scheduled EDR Contact: 10/20/2014
	Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 10/25/2013	Source: EPA
Date Data Arrived at EDR: 11/11/2013	Telephone: 703-412-9810
Date Made Active in Reports: 02/13/2014	Last EDR Contact: 08/28/2014
Number of Days to Update: 94	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/11/2014
Date Data Arrived at EDR: 03/13/2014
Date Made Active in Reports: 04/09/2014
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/19/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/21/2014	Telephone: 703-603-0695
Date Made Active in Reports: 07/15/2014	Last EDR Contact: 06/05/2014
Number of Days to Update: 116	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/19/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/21/2014	Telephone: 703-603-0695
Date Made Active in Reports: 07/15/2014	Last EDR Contact: 06/05/2014
Number of Days to Update: 116	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2014	Source: Department of the Navy
Date Data Arrived at EDR: 05/30/2014	Telephone: 843-820-7326
Date Made Active in Reports: 06/17/2014	Last EDR Contact: 08/14/2014
Number of Days to Update: 18	Next Scheduled EDR Contact: 12/01/2014
	Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/30/2013	Source: National Response Center, United States Coast Guard
Date Data Arrived at EDR: 10/01/2013	Telephone: 202-267-2180
Date Made Active in Reports: 12/06/2013	Last EDR Contact: 07/03/2014
Number of Days to Update: 66	Next Scheduled EDR Contact: 07/14/2014
	Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

NY SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 07/16/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 07/17/2014	Telephone: 518-402-9622
Date Made Active in Reports: 08/14/2014	Last EDR Contact: 08/19/2014
Number of Days to Update: 28	Next Scheduled EDR Contact: 12/01/2014
	Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NJ SHWS: Known Contaminated Sites in New Jersey

The Known Contaminated Sites in New Jersey includes sites under the purview of the Site Remediation Program which have contamination present at levels greater than the applicable cleanup criteria for soil and/or groundwater standards. The sites appearing in Known Contaminated Sites in New Jersey are classified as either active, where the site is assigned to a specific remedial program area, or pending, where the site is awaiting assignment to a specific remedial program area. Sites where no further action (NFA) designation has been given are not included in this report unless there are other areas of identified contamination which have not been remediated. This report includes sites being remediated under all of the various regulatory programs administered by the Site Remediation Program such as: Federal Superfund Program, Federal Resource Conservation and Recovery Act (RCRA), New Jersey's Industrial Site Recovery Act (ISRA), New Jersey's Underground Storage of Hazardous Substances Act, New Jersey's Spill Compensation and Control Act, New Jersey's Solid Waste Management Act, New Jersey's Water Pollution Control Act.

Date of Government Version: 06/04/2014
Date Data Arrived at EDR: 06/05/2014
Date Made Active in Reports: 06/18/2014
Number of Days to Update: 13

Source: New Jersey Department of Environmental Protection
Telephone: 609-292-8761
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/08/2014
Data Release Frequency: Varies

NY VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 05/22/2014
Date Made Active in Reports: 06/13/2014
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/22/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/08/2014
Date Data Arrived at EDR: 07/10/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/08/2014
Data Release Frequency: Semi-Annually

NJ SWF/LF: Solid Waste Facility Directory

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/01/2014
Date Data Arrived at EDR: 02/07/2014
Date Made Active in Reports: 03/11/2014
Number of Days to Update: 32

Source: Department of Environmental Protection
Telephone: 609-984-6741
Last EDR Contact: 08/08/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/19/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 05/22/2014	Telephone: 518-402-9549
Date Made Active in Reports: 06/11/2014	Last EDR Contact: 08/19/2014
Number of Days to Update: 20	Next Scheduled EDR Contact: 12/01/2014
	Data Release Frequency: Varies

NY HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 07/08/2005	Telephone: 518-402-9549
Date Made Active in Reports: 07/14/2005	Last EDR Contact: 07/07/2005
Number of Days to Update: 6	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/28/2014	Source: EPA Region 7
Date Data Arrived at EDR: 05/01/2014	Telephone: 913-551-7003
Date Made Active in Reports: 06/17/2014	Last EDR Contact: 04/28/2014
Number of Days to Update: 47	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/13/2014	Source: EPA Region 8
Date Data Arrived at EDR: 08/15/2014	Telephone: 303-312-6271
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 7	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/01/2013	Telephone: 415-972-3372
Date Made Active in Reports: 04/12/2013	Last EDR Contact: 07/22/2014
Number of Days to Update: 42	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013	Source: EPA Region 1
Date Data Arrived at EDR: 05/01/2013	Telephone: 617-918-1313
Date Made Active in Reports: 11/01/2013	Last EDR Contact: 08/01/2014
Number of Days to Update: 184	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 08/04/2014	Source: EPA, Region 5
Date Data Arrived at EDR: 08/05/2014	Telephone: 312-886-7439
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 04/28/2014
Number of Days to Update: 17	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/14/2014	Source: EPA Region 6
Date Data Arrived at EDR: 05/15/2014	Telephone: 214-665-6597
Date Made Active in Reports: 07/15/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 61	Next Scheduled EDR Contact: 11/20/2014
	Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 07/30/2014	Source: EPA Region 4
Date Data Arrived at EDR: 08/12/2014	Telephone: 404-562-8677
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 04/22/2014
Number of Days to Update: 10	Next Scheduled EDR Contact: 08/11/2014
	Data Release Frequency: Semi-Annually

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/20/2014	Source: EPA Region 10
Date Data Arrived at EDR: 06/10/2014	Telephone: 206-553-2857
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 04/28/2014
Number of Days to Update: 73	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

State and tribal registered storage tank lists

NY TANKS: Storage Tank Facility Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 07/01/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 07/02/2014	Telephone: 518-402-9543
Date Made Active in Reports: 08/14/2014	Last EDR Contact: 08/29/2014
Number of Days to Update: 43	Next Scheduled EDR Contact: 10/13/2014
	Data Release Frequency: Quarterly

NY UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 07/01/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 07/02/2014	Telephone: 518-402-9549
Date Made Active in Reports: 08/21/2014	Last EDR Contact: 08/29/2014
Number of Days to Update: 50	Next Scheduled EDR Contact: 10/13/2014
	Data Release Frequency: No Update Planned

NJ UST: Underground Storage Tank Data

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 04/14/2014
Date Data Arrived at EDR: 05/12/2014
Date Made Active in Reports: 05/20/2014
Number of Days to Update: 8

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 08/11/2014
Next Scheduled EDR Contact: 11/24/2014
Data Release Frequency: Varies

NY CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

NY MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

NY AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 07/02/2014
Date Made Active in Reports: 08/21/2014
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/29/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: No Update Planned

NY CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

NY MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 07/02/2014
Date Made Active in Reports: 08/21/2014
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/29/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 07/02/2014
Date Made Active in Reports: 08/21/2014
Number of Days to Update: 50

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/29/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 01/27/2014
Number of Days to Update: 271

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/01/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 07/30/2014
Date Data Arrived at EDR: 08/12/2014
Date Made Active in Reports: 08/22/2014
Number of Days to Update: 10

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/22/2014
Next Scheduled EDR Contact: 08/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/04/2014
Date Data Arrived at EDR: 08/05/2014
Date Made Active in Reports: 08/22/2014
Number of Days to Update: 17

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 07/25/2014
Date Data Arrived at EDR: 07/28/2014
Date Made Active in Reports: 08/22/2014
Number of Days to Update: 25

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/22/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 05/28/2014
Date Data Arrived at EDR: 05/01/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 47

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/13/2014	Source: EPA Region 8
Date Data Arrived at EDR: 08/15/2014	Telephone: 303-312-6137
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 7	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 08/14/2014	Source: EPA Region 9
Date Data Arrived at EDR: 08/15/2014	Telephone: 415-972-3368
Date Made Active in Reports: 08/22/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 7	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/20/2014	Source: EPA Region 10
Date Data Arrived at EDR: 06/10/2014	Telephone: 206-553-2857
Date Made Active in Reports: 08/15/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 66	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010	Source: FEMA
Date Data Arrived at EDR: 02/16/2010	Telephone: 202-646-5797
Date Made Active in Reports: 04/12/2010	Last EDR Contact: 07/08/2014
Number of Days to Update: 55	Next Scheduled EDR Contact: 10/27/2014
	Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 07/16/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 07/17/2014	Telephone: 518-402-9553
Date Made Active in Reports: 08/14/2014	Last EDR Contact: 08/19/2014
Number of Days to Update: 28	Next Scheduled EDR Contact: 12/01/2014
	Data Release Frequency: Quarterly

NJ ENG CONTROLS: Declaration Environmental Restriction/Deed Notice Sites

Legal Document that restricts the use of contaminated property; holds owner(s) to the regulatory/statutory requirements for cleanup.

Date of Government Version: 05/29/2014	Source: Department of Environmental Protection
Date Data Arrived at EDR: 07/03/2014	Telephone: 609-341-3121
Date Made Active in Reports: 07/30/2014	Last EDR Contact: 08/19/2014
Number of Days to Update: 27	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 07/16/2014
Date Data Arrived at EDR: 07/17/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Quarterly

NJ INST CONTROL: Classification Exception Area Sites

A Classification Exception Area is an institutional control providing notice that ground water contamination exists in a particular location above State standards.

Date of Government Version: 05/29/2014
Date Data Arrived at EDR: 07/03/2014
Date Made Active in Reports: 07/30/2014
Number of Days to Update: 27

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/08/2014
Data Release Frequency: Varies

NY RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/26/2014
Next Scheduled EDR Contact: 10/06/2014
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 07/16/2014
Date Data Arrived at EDR: 07/17/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Semi-Annually

NJ VCP: Voluntary Cleanup Program Sites

Through the VCP, responsible parties, developers, local officials, or individuals may work with the department to remediate non-priority contaminated sites that pose no immediate threat to human health or the environment.

Date of Government Version: 08/17/2013
Date Data Arrived at EDR: 11/27/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 44

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 05/30/2014
Date Data Arrived at EDR: 07/01/2014
Date Made Active in Reports: 08/15/2014
Number of Days to Update: 45

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 07/01/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN VCP R7: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

NY ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a \$200 million Environmental Restoration or Brownfields Fund as part of the \$1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 07/16/2014
Date Data Arrived at EDR: 07/17/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Quarterly

NY BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 07/16/2014
Date Data Arrived at EDR: 07/17/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Semi-Annually

NJ BROWNFIELDS: Brownfields Database

Brownfields are identified as former or current commercial or industrial use sites that are presently vacant or underutilized, on which there is suspected to have been a discharge of a contamination to the soil or groundwater at concentrations greater than applicable cleanup criteria.

Date of Government Version: 12/03/2012
Date Data Arrived at EDR: 02/27/2013
Date Made Active in Reports: 04/05/2013
Number of Days to Update: 37

Source: Department of Environmental Protection
Telephone: 609-292-1251
Last EDR Contact: 07/28/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 07/03/2014
Date Made Active in Reports: 07/28/2014
Number of Days to Update: 25

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 07/03/2014
Next Scheduled EDR Contact: 10/06/2014
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/25/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 07/21/2014
Next Scheduled EDR Contact: 11/03/2014
Data Release Frequency: Annually

NY SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 07/08/2014
Date Data Arrived at EDR: 07/10/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Semi-Annually

NJ SWRCY: Approved Class B Recycling Facilities

"Class B recyclable material" means a source separated recyclable material which is subject to Department approval prior to receipt, storage, processing or transfer at a recycling center in accordance with N.J.S.A. 13:1E-99.34b.

Date of Government Version: 01/01/2014
Date Data Arrived at EDR: 02/07/2014
Date Made Active in Reports: 03/11/2014
Number of Days to Update: 32

Source: Department of Environmental Protection
Telephone: 609-984-6650
Last EDR Contact: 08/08/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 08/01/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/28/2014
Date Data Arrived at EDR: 06/20/2014
Date Made Active in Reports: 07/15/2014
Number of Days to Update: 25

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/03/2014
Next Scheduled EDR Contact: 12/15/2014
Data Release Frequency: Quarterly

NY DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 07/16/2014
Date Data Arrived at EDR: 07/17/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/28/2014
Date Data Arrived at EDR: 06/20/2014
Date Made Active in Reports: 07/15/2014
Number of Days to Update: 25

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/03/2014
Next Scheduled EDR Contact: 12/15/2014
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

NY HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/22/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Varies

NY LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 05/21/2014
Date Data Arrived at EDR: 05/22/2014
Date Made Active in Reports: 06/10/2014
Number of Days to Update: 19

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 08/11/2014
Next Scheduled EDR Contact: 11/24/2014
Data Release Frequency: Varies

NJ LIENS: Environmental LIENS

A listing of properties with environmental liens. The listing includes sites from the Site Remediation & Waste Management Program Sites where the Department has placed either a 1st Priority or Regular Spill Fund Lien against. 1st Priority Type Lien - a lien placed against the property where the discharged occurred providing that the owners of the property have some responsibility towards the discharge. First Priority Lien is superior to other types of liens. Non-Priority (Regular) Type Lien - a lien placed against the Responsible Party & their revenues and all real and personal property, other than the real property comprising the location of the discharge.

Date of Government Version: 05/28/2014
Date Data Arrived at EDR: 07/03/2014
Date Made Active in Reports: 07/29/2014
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 08/15/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/31/2014
Date Data Arrived at EDR: 04/01/2014
Date Made Active in Reports: 07/15/2014
Number of Days to Update: 105

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 07/01/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Annually

NY SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 05/19/2014
Date Data Arrived at EDR: 05/22/2014
Date Made Active in Reports: 06/11/2014
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Varies

NY HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NY SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NJ SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/15/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/11/2013
Number of Days to Update: 39

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NJ SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 09/02/1997
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/06/2013
Number of Days to Update: 62

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/11/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/13/2014	Telephone: (212) 637-3660
Date Made Active in Reports: 04/09/2014	Last EDR Contact: 07/02/2014
Number of Days to Update: 27	Next Scheduled EDR Contact: 10/13/2014
	Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012	Source: Department of Transportation, Office of Pipeline Safety
Date Data Arrived at EDR: 08/07/2012	Telephone: 202-366-4595
Date Made Active in Reports: 09/18/2012	Last EDR Contact: 08/06/2014
Number of Days to Update: 42	Next Scheduled EDR Contact: 11/17/2014
	Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005	Source: USGS
Date Data Arrived at EDR: 11/10/2006	Telephone: 888-275-8747
Date Made Active in Reports: 01/11/2007	Last EDR Contact: 07/18/2014
Number of Days to Update: 62	Next Scheduled EDR Contact: 10/27/2014
	Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2012	Source: U.S. Army Corps of Engineers
Date Data Arrived at EDR: 02/28/2014	Telephone: 202-528-4285
Date Made Active in Reports: 04/24/2014	Last EDR Contact: 06/04/2014
Number of Days to Update: 55	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2013	Source: Department of Justice, Consent Decree Library
Date Data Arrived at EDR: 01/24/2014	Telephone: Varies
Date Made Active in Reports: 02/24/2014	Last EDR Contact: 06/30/2014
Number of Days to Update: 31	Next Scheduled EDR Contact: 10/13/2014
	Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013	Source: EPA
Date Data Arrived at EDR: 12/12/2013	Telephone: 703-416-0223
Date Made Active in Reports: 02/24/2014	Last EDR Contact: 06/10/2014
Number of Days to Update: 74	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010	Source: Department of Energy
Date Data Arrived at EDR: 10/07/2011	Telephone: 505-845-0011
Date Made Active in Reports: 03/01/2012	Last EDR Contact: 08/20/2014
Number of Days to Update: 146	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 01/30/2014	Source: Department of Labor, Mine Safety and Health Administration
Date Data Arrived at EDR: 03/05/2014	Telephone: 303-231-5959
Date Made Active in Reports: 07/15/2014	Last EDR Contact: 06/06/2014
Number of Days to Update: 132	Next Scheduled EDR Contact: 09/15/2014
	Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011	Source: EPA
Date Data Arrived at EDR: 07/31/2013	Telephone: 202-566-0250
Date Made Active in Reports: 09/13/2013	Last EDR Contact: 08/29/2014
Number of Days to Update: 44	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006	Source: EPA
Date Data Arrived at EDR: 09/29/2010	Telephone: 202-260-5521
Date Made Active in Reports: 12/02/2010	Last EDR Contact: 06/25/2014
Number of Days to Update: 64	Next Scheduled EDR Contact: 10/06/2014
	Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009	Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Date Data Arrived at EDR: 04/16/2009	Telephone: 202-566-1667
Date Made Active in Reports: 05/11/2009	Last EDR Contact: 08/19/2014
Number of Days to Update: 25	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009	Source: EPA
Date Data Arrived at EDR: 04/16/2009	Telephone: 202-566-1667
Date Made Active in Reports: 05/11/2009	Last EDR Contact: 08/19/2014
Number of Days to Update: 25	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/22/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 05/06/2014
Date Data Arrived at EDR: 05/16/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 10/09/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2013
Date Data Arrived at EDR: 07/17/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 107

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/18/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013	Source: Nuclear Regulatory Commission
Date Data Arrived at EDR: 08/02/2013	Telephone: 301-415-7169
Date Made Active in Reports: 11/01/2013	Last EDR Contact: 06/05/2014
Number of Days to Update: 91	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/07/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 07/10/2014	Telephone: 202-343-9775
Date Made Active in Reports: 07/28/2014	Last EDR Contact: 07/10/2014
Number of Days to Update: 18	Next Scheduled EDR Contact: 10/20/2014
	Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/18/2013	Source: EPA
Date Data Arrived at EDR: 02/27/2014	Telephone: (212) 637-3000
Date Made Active in Reports: 03/12/2014	Last EDR Contact: 06/13/2014
Number of Days to Update: 13	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/02/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: No Update Planned

RMP: Risk Management Plans

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/01/2014	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/23/2014	Telephone: 202-564-8600
Date Made Active in Reports: 07/28/2014	Last EDR Contact: 07/22/2014
Number of Days to Update: 66	Next Scheduled EDR Contact: 11/10/2014
	Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011	Source: EPA/NTIS
Date Data Arrived at EDR: 02/26/2013	Telephone: 800-424-9346
Date Made Active in Reports: 04/19/2013	Last EDR Contact: 08/29/2014
Number of Days to Update: 52	Next Scheduled EDR Contact: 12/08/2014
	Data Release Frequency: Biennially

NY HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 10/20/2006	Telephone: 518-402-9564
Date Made Active in Reports: 11/30/2006	Last EDR Contact: 05/26/2009
Number of Days to Update: 41	Next Scheduled EDR Contact: 08/24/2009
	Data Release Frequency: No Update Planned

NY UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/09/2014	Source: Department of Environmental Conservation
Date Data Arrived at EDR: 06/12/2014	Telephone: 518-402-8056
Date Made Active in Reports: 08/05/2014	Last EDR Contact: 06/12/2014
Number of Days to Update: 54	Next Scheduled EDR Contact: 09/22/2014
	Data Release Frequency: Quarterly

NJ UIC: Underground Injection Wells Database

A listing of underground injection well locations. The UIC Program is responsible for regulating the construction, operation, permitting, and closure of injection wells that place fluids underground for storage or disposal.

Date of Government Version: 01/09/2009	Source: Department of Environmental Protection
Date Data Arrived at EDR: 02/25/2009	Telephone: 609-292-0407
Date Made Active in Reports: 03/11/2009	Last EDR Contact: 08/05/2014
Number of Days to Update: 14	Next Scheduled EDR Contact: 11/17/2014
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 05/01/2014
Date Data Arrived at EDR: 05/07/2014
Date Made Active in Reports: 06/10/2014
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 08/07/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/17/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Annually

NY DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 07/17/2014
Date Data Arrived at EDR: 07/18/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/16/2014
Next Scheduled EDR Contact: 09/29/2014
Data Release Frequency: Varies

NJ DRYCLEANERS: Drycleaner List

A listing of registered drycleaners.

Date of Government Version: 08/11/2014
Date Data Arrived at EDR: 08/12/2014
Date Made Active in Reports: 08/15/2014
Number of Days to Update: 3

Source: Department of Environmental Protection
Telephone: 609-292-2795
Last EDR Contact: 08/11/2014
Next Scheduled EDR Contact: 11/24/2014
Data Release Frequency: Varies

NY SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 05/29/2014
Date Data Arrived at EDR: 05/30/2014
Date Made Active in Reports: 06/12/2014
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/28/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: No Update Planned

NJPDES: New Jersey Pollutant Discharge Elimination System Dischargers

The NJPDES contains the names, addresses and other information of all permitted New Jersey Pollutant Discharge Elimination System dischargers.

Date of Government Version: 05/01/2014
Date Data Arrived at EDR: 05/21/2014
Date Made Active in Reports: 06/13/2014
Number of Days to Update: 23

Source: Department of Environmental Protection
Telephone: 609-984-4428
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NY AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 11/01/2013
Date Made Active in Reports: 01/09/2014
Number of Days to Update: 69

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 11/10/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Annually

NY E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 06/18/2014
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/02/2014
Number of Days to Update: 2

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/20/2014
Next Scheduled EDR Contact: 10/06/2014
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/18/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 07/25/2014
Next Scheduled EDR Contact: 11/03/2014
Data Release Frequency: Varies

NY Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/01/2013
Date Data Arrived at EDR: 12/05/2013
Date Made Active in Reports: 02/17/2014
Number of Days to Update: 74

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Varies

NY Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 07/08/2014
Date Data Arrived at EDR: 07/10/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Quarterly

NY COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 07/09/2014
Date Data Arrived at EDR: 07/10/2014
Date Made Active in Reports: 08/14/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/02/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Varies

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 07/03/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 72

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 07/01/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Quarterly

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931 and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/04/2014
Date Data Arrived at EDR: 06/12/2014
Date Made Active in Reports: 07/28/2014
Number of Days to Update: 46

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/01/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: Varies

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011
Date Data Arrived at EDR: 05/18/2012
Date Made Active in Reports: 05/25/2012
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/15/2014
Next Scheduled EDR Contact: 11/24/2014
Data Release Frequency: Varies

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 08/15/2014
Next Scheduled EDR Contact: 11/24/2014
Data Release Frequency: Quarterly

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 07/18/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/01/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 03/14/2014
Date Data Arrived at EDR: 06/11/2014
Date Made Active in Reports: 07/28/2014
Number of Days to Update: 47

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/11/2014
Next Scheduled EDR Contact: 09/22/2014
Data Release Frequency: Varies

NJ Financial Assurance: Financial Assurance Information Listing

Financial Assurance information.

Date of Government Version: 05/02/2014
Date Data Arrived at EDR: 05/28/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 20

Source: Department of Environmental Protection
Telephone: 609-341-3121
Last EDR Contact: 07/28/2014
Next Scheduled EDR Contact: 11/10/2014
Data Release Frequency: Semi-Annually

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/19/2014
Date Data Arrived at EDR: 06/20/2014
Date Made Active in Reports: 07/28/2014
Number of Days to Update: 38

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 08/14/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: Quarterly

NJ COAL ASH: Coal Ash Listing

Coal combustion survey ash listing.

Date of Government Version: 05/10/2010
Date Data Arrived at EDR: 05/12/2010
Date Made Active in Reports: 06/28/2010
Number of Days to Update: 47

Source: Department of Environmental Protection
Telephone: 609-984-6985
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/23/2013
Date Data Arrived at EDR: 11/06/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 30

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/25/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/18/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: N/A

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/23/2013
Date Data Arrived at EDR: 11/06/2013
Date Made Active in Reports: 12/06/2013
Number of Days to Update: 30

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/25/2014
Next Scheduled EDR Contact: 10/13/2014
Data Release Frequency: Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NY RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NJ RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the New Jersey Department of Environmental Protection in New Jersey.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: New Jersey Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

NJ RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the New Jersey Department of Environmental Protection in New Jersey.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/24/2013
Number of Days to Update: 176

Source: New Jersey Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 05/30/2014
Date Data Arrived at EDR: 05/30/2014
Date Made Active in Reports: 06/13/2014
Number of Days to Update: 14

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 05/30/2014
Date Data Arrived at EDR: 05/30/2014
Date Made Active in Reports: 06/13/2014
Number of Days to Update: 14

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/07/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/07/2014
Next Scheduled EDR Contact: 10/20/2014
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 06/23/2014
Date Data Arrived at EDR: 06/25/2014
Date Made Active in Reports: 08/05/2014
Number of Days to Update: 41

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/09/2014
Next Scheduled EDR Contact: 09/22/2014
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 06/23/2014
Date Data Arrived at EDR: 06/25/2014
Date Made Active in Reports: 08/05/2014
Number of Days to Update: 41

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/09/2014
Next Scheduled EDR Contact: 09/22/2014
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 01/30/2014
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/03/2014
Number of Days to Update: 34

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 01/30/2014
Date Data Arrived at EDR: 02/28/2014
Date Made Active in Reports: 04/03/2014
Number of Days to Update: 34

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 06/12/2014
Date Data Arrived at EDR: 06/13/2014
Date Made Active in Reports: 08/05/2014
Number of Days to Update: 53

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 06/12/2014
Date Data Arrived at EDR: 06/13/2014
Date Made Active in Reports: 08/05/2014
Number of Days to Update: 53

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 08/05/2014
Next Scheduled EDR Contact: 11/17/2014
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/19/2014
Next Scheduled EDR Contact: 12/01/2014
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/17/2014
Next Scheduled EDR Contact: 10/27/2014
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/21/2014
Date Made Active in Reports: 08/25/2014
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/18/2014
Next Scheduled EDR Contact: 11/03/2014
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/15/2014
Date Made Active in Reports: 08/13/2014
Number of Days to Update: 29

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/26/2014
Next Scheduled EDR Contact: 12/08/2014
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 03/27/2014
Date Data Arrived at EDR: 06/12/2014
Date Made Active in Reports: 07/17/2014
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/21/2014
Next Scheduled EDR Contact: 11/03/2014
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2013

Date Data Arrived at EDR: 06/20/2014

Date Made Active in Reports: 08/07/2014

Number of Days to Update: 48

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 06/16/2014

Next Scheduled EDR Contact: 09/29/2014

Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers

Source: Department of Health

Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands

Source: Department of Environmental Conservation

Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK[®] - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

OLLIE?S
411 WEST 42ND STREET
NEW YORK, NY 10036

TARGET PROPERTY COORDINATES

Latitude (North):	40.7589 - 40° 45' 32.04"
Longitude (West):	73.9931 - 73° 59' 35.16"
Universal Transverse Mercator:	Zone 18
UTM X (Meters):	584992.6
UTM Y (Meters):	4512269.5
Elevation:	32 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40073-G8 CENTRAL PARK, NY NJ
Most Recent Revision:	1995
South Map:	40073-F8 BROOKLYN, NY
Most Recent Revision:	1995
Southwest Map:	40074-F1 JERSEY CITY, NJ NY
Most Recent Revision:	1981
West Map:	40074-G1 WEEHAWKEN, NJ NY
Most Recent Revision:	1995

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General West

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County
NEW YORK, NY

FEMA Flood
Electronic Data
YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 3604970039B - FEMA Q3 Flood data

Additional Panels in search area:
3604970031B - FEMA Q3 Flood data
3604970030B - FEMA Q3 Flood data
3604970038B - FEMA Q3 Flood data
34017C - FEMA DFIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property
CENTRAL PARK

NWI Electronic
Data Coverage
YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data:*

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile SSW
Site Name:	MANHATTAN GENERAL MAIL FACILITY
Site EPA ID Number:	NY6180000352
Groundwater Flow Direction:	NOT AVAILABLE.
Inferred Depth to Water:	not available. Saturated layers impacted by salt water intrusion are present in the overburden. It is generally inferred that the depth to the uppermost 'aquifer' is greater than 70 feet at the surface of the bedrock/sediment interface.
Hydraulic Connection:	Detailed hydraulic connection information is not available. Glacial till and outwash deposit sediments overlie the Manhattan Schist, the uppermost bedrock unit at the site. The surface elevation of bedrock decreases to the southwest of the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

<u>MAP ID</u>	<u>LOCATION</u> <u>FROM TP</u>	<u>GENERAL DIRECTION</u> <u>GROUNDWATER FLOW</u>
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era: Paleozoic
System: Ordovician
Series: Lower Ordovician and Cambrian carbonate rocks
Code: OC (*decoded above as Era, System & Series*)

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Permeability Rate (in/hr)	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

<u>DATABASE</u>	<u>SEARCH DISTANCE (miles)</u>
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000831703	1/4 - 1/2 Mile SW
2	USGS40000831957	1/4 - 1/2 Mile NW
3	USGS40000832014	1/4 - 1/2 Mile North
A4	USGS40000832025	1/4 - 1/2 Mile NNW
A5	USGS40000832026	1/4 - 1/2 Mile NNW
7	USGS40000831625	1/4 - 1/2 Mile SW
8	USGS40000832052	1/4 - 1/2 Mile NNW
9	USGS40000831497	1/2 - 1 Mile SW
10	USGS40000831418	1/2 - 1 Mile SSW
11	USGS40000832118	1/2 - 1 Mile NNE
12	USGS40000831335	1/2 - 1 Mile South
13	USGS40000831552	1/2 - 1 Mile WSW
14	USGS40000831419	1/2 - 1 Mile SW
15	USGS40000831406	1/2 - 1 Mile SW
16	USGS40000832210	1/2 - 1 Mile NNE
17	USGS40000831482	1/2 - 1 Mile ESE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
6	NY0022417	1/4 - 1/2 Mile SE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG70000000160	1/8 - 1/4 Mile NNW
2	NYOG70000000157	1/4 - 1/2 Mile SW
A3	NYOG70000000162	1/4 - 1/2 Mile North
A4	NYOG70000000163	1/4 - 1/2 Mile North
5	NYOG70000000156	1/4 - 1/2 Mile SW
6	NYOG70000000166	1/2 - 1 Mile NNE
7	NYOG70000000153	1/2 - 1 Mile SSW
8	NYOG70000000170	1/2 - 1 Mile NNE
9	NYOG70000000151	1/2 - 1 Mile South
10	NYOG70000000152	1/2 - 1 Mile SW
11	NYOG70000000149	1/2 - 1 Mile SSE
B12	NYOG70000000130	1/2 - 1 Mile South
B13	NYOG70000000126	1/2 - 1 Mile South

PHYSICAL SETTING SOURCE MAP - 4056019.6s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME: Ollie?s
 ADDRESS: 411 West 42nd Street
 New York NY 10036
 LAT/LONG: 40.7589 / 73.9931

CLIENT: Environmental Data Resources
 CONTACT: Thomas M. Valentine
 INQUIRY #: 4056019.6s
 DATE: September 04, 2014 11:45 am

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

1
SW
1/4 - 1/2 Mile
Higher

FED USGS USGS40000831703

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404523073595241		
Monloc name:	NY 220		
Monloc type:	Well		
Monloc desc:	WEST 37 ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7566016
Longitude:	-73.9975005	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	41.32
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported		
Welldepth units:	ft	Welldepth:	651.4
Wellholedepth units:	Not Reported	Wellholedepth:	Not Reported

Ground-water levels, Number of Measurements: 0

2
NW
1/4 - 1/2 Mile
Lower

FED USGS USGS40000831957

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404542073595401		
Monloc name:	NY 103		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7617681
Longitude:	-73.9979171	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported	Welldepth:	148
Construction date:	Not Reported	Wellholeddepth:	Not Reported
Welldepth units:	ft		
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

3 North 1/4 - 1/2 Mile Higher

FED USGS USGS40000832014

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404549073593501		
Monloc name:	NY 246. 1		
Monloc type:	Well		
Monloc desc:	W48ST-W		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7637681
Longitude:	-73.9926947	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	41.32
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	31.5
Welldepth units:	ft	Wellholeddepth:	Not Reported
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4 NNW 1/4 - 1/2 Mile Lower

FED USGS USGS40000832025

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404550073594501		
Monloc name:	NY 75		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7639903
Longitude:	-73.995417	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported	Welldepth:	175
Construction date:	Not Reported	Wellholeddepth:	Not Reported
Welldepth units:	ft		
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A5
NNW
1/4 - 1/2 Mile
Lower

FED USGS USGS40000832026

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404550073594502		
Monloc name:	NY 76		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7639903
Longitude:	-73.995417	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refs:	NAD83	Vert measure val:	20
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refs:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	125
Welldepth units:	ft	Wellholeddepth:	Not Reported
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

6
SE
1/4 - 1/2 Mile
Higher

FRDS PWS NY0022417

PWS ID:	NY0022417		
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	BREWSTER SQUARE		
	RT 6		
	BREWSTER, NY 10509		
Addressee / Facility:	System Owner/Responsible Party		
	GOSTFRAND DAVID		
	C/O DAVID GOSTFRAND		
	463 7TH AVENUE, SUITE 703		
	NEW YORK, NY 10018		
Facility Latitude:	40 45 18	Facility Longitude:	073 59 18
City Served:	SOUTHEAST (T)		
Treatment Class	Not Reported	Population:	Not Reported

Violations information not reported.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

7
SW
1/4 - 1/2 Mile
Higher

FED USGS USGS40000831625

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404517073595901		
Monloc name:	NY 219		
Monloc type:	Well		
Monloc desc:	WEST 34 ST-B		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.754796
Longitude:	-73.9993061	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	40.27
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	625.7
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

8
NNW
1/4 - 1/2 Mile
Lower

FED USGS USGS40000832052

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404553073595001		
Monloc name:	NY 156		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7648237
Longitude:	-73.996806	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported	Welldepth:	132
Construction date:	Not Reported	Wellholeddepth:	Not Reported
Welldepth units:	ft		
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

9
SW
1/2 - 1 Mile
Lower

FED USGS USGS40000831497

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404508074000501		
Monloc name:	NY 239. 1		
Monloc type:	Well		
Monloc desc:	26B-CS-BW		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7523239
Longitude:	-74.0009728	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	18.86
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Pleistocene Series		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	41.9
Welldepth units:	ft	Wellholeddepth:	Not Reported
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

10
SSW
1/2 - 1 Mile
Lower

FED USGS USGS40000831418

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404459073594501		
Monloc name:	NY 227. 1		
Monloc type:	Well		
Monloc desc:	WEST 30 ST-A		
Huc code:	02030101	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7498434
Longitude:	-73.9955699	Sourcemap scale:	24000
Horiz Acc measure:	.01	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	31.45
Vert measure units:	feet	Vertacc measure val:	.01
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	New England crystalline-rock aquifers		
Formation type:	Basement Complex		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer type:	Not Reported	Welldepth:	192
Construction date:	20031114	Wellholeddepth:	600.5
Welldepth units:	ft		
Wellholeddepth units:	ft		

Ground-water levels, Number of Measurements: 13

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2005-02-09		9.03	2004-11-29		9.18
2004-11-10		9.16	2004-07-21		9.80
2004-06-28		9.69	2004-06-16		9.54
2004-04-21		9.82	2004-04-12		9.75
2004-03-15		9.74	2004-03-03		10.04
2004-03-03		9.64	2004-02-18		10.12
2004-01-07		10.09			

11
NNE
1/2 - 1 Mile
Higher

FED USGS USGS40000832118

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404604073592301		
Monloc name:	NY 221		
Monloc type:	Well		
Monloc desc:	WEST 55 ST-A		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7680181
Longitude:	-73.989528	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	39.41
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	650.7
Welldepth units:	ft	Wellholeddepth:	Not Reported
Wellholeddepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

12
South
1/2 - 1 Mile
Higher

FED USGS USGS40000831335

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404452073593001		
Monloc name:	NY 240. 1		
Monloc type:	Well		
Monloc desc:	W30ST-C		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7480462
Longitude:	-73.9912781	Sourcemap scale:	24000

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	38.87
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Bedrock		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	600
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

13
WSW
1/2 - 1 Mile
Lower

FED USGS USGS40000831552

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404513074002501		
Monloc name:	NY 83		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7537127
Longitude:	-74.0065285	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	10
Vert measure units:	feet	Vertacc measure val:	5
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Sand and gravel aquifers (glaciated regions)		
Formation type:	Sand and Gravel		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	25
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

14
SW
1/2 - 1 Mile
Lower

FED USGS USGS40000831419

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404459074001301		
Monloc name:	NY 176. 1		
Monloc type:	Well		
Monloc desc:	WEST 26TH STREET		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7498239
Longitude:	-74.0031951	Sourcemap scale:	24000

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Horiz Acc measure: 1 Horiz Collection method: Unknown Horiz coord refs: NAD83 Vert measure units: feet Vert accmeasure units: feet Vertcollection method: Unknown Vert coord refs: NGVD29 Aquifername: Not Reported Formation type: Bedrock Aquifer type: Not Reported Construction date: 19990902 Welldepth units: ft Wellholedepth units: Not Reported	Horiz Acc measure units: minutes Vert measure val: 13.25 Vertacc measure val: 0.1 Countrycode: US Welldepth: 596.3 Wellholedepth: Not Reported

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
2002-10-09		3.54	2002-06-25		3.48
2002-04-03		4.09	2002-01-09		4.00

15

SW

1/2 - 1 Mile

Lower

FED USGS

USGS40000831406

Org. Identifier: USGS-NY Formal name: USGS New York Water Science Center Monloc Identifier: USGS-404458074001801 Monloc name: NY 154 Monloc type: Well Monloc desc: Not Reported Huc code: Not Reported Drainagearea Units: Not Reported Contrib drainagearea units: Not Reported Longitude: -74.004584 Horiz Acc measure: 3 Horiz Collection method: Interpolated from map Horiz coord refs: NAD83 Vert measure units: feet Vert accmeasure units: feet Vertcollection method: Interpolated from topographic map Vert coord refs: NGVD29 Aquifername: Sand and gravel aquifers (glaciated regions) Formation type: Sand Aquifer type: Not Reported Construction date: Not Reported Welldepth units: ft Wellholedepth units: Not Reported	Drainagearea value: Not Reported Contrib drainagearea: Not Reported Latitude: 40.7495461 Sourcemap scale: 24000 Horiz Acc measure units: seconds Vert measure val: 10 Vertacc measure val: 5 Countrycode: US Welldepth: 63 Wellholedepth: Not Reported

Ground-water levels, Number of Measurements: 0

16

NNE

1/2 - 1 Mile

Higher

FED USGS

USGS40000832210

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404615073591401		
Monloc name:	NY 243. 1		
Monloc type:	Well		
Monloc desc:	W60ST-W		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7710458
Longitude:	-73.9868612	Sourcemap scale:	24000
Horiz Acc measure:	.1	Horiz Acc measure units:	seconds
Horiz Collection method:	Transit, theodolite, or other surveying method		
Horiz coord refsys:	NAD83	Vert measure val:	82.01
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	30.6
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

17
ESE
1/2 - 1 Mile
Higher

FED USGS USGS40000831482

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-404506073584001		
Monloc name:	NY 155		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	40.7517684
Longitude:	-73.977361	Sourcemap scale:	24000
Horiz Acc measure:	3	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	55
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	420
Welldepth units:	ft	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1

NNW

1/8 - 1/4 Mile

OIL_GAS

NYOG70000000160

Api wellno:	31061237430000	Cnty:	New York
Hole:	23743	Sidetck:	0
Completion:	0		
Well nm:	W44 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	25-MAR-97
Dt comp:	10-APR-97	Well typ:	Stratigraphic
Dtd:	564		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Fordham Gneiss
Xloc:	-73.99469		
Yloc:	40.76109		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Central Park	Quadsec:	G
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000160

2

SW

1/4 - 1/2 Mile

OIL_GAS

NYOG70000000157

Api wellno:	31061237420000	Cnty:	New York
Hole:	23742	Sidetck:	0
Completion:	0		
Well nm:	W37 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	15-OCT-98
Dt comp:	16-NOV-98	Well typ:	Stratigraphic
Dtd:	651		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Manhattan Schist
Xloc:	-73.9975		
Yloc:	40.75659		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Central Park	Quadsec:	G
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000157

A3

North

1/4 - 1/2 Mile

OIL_GAS

NYOG70000000162

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Api wellno:	31061237440000	Cnty:	New York
Hole:	23744	Sidetrck:	0
Completion:	0		
Well nm:	W48 St - C		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	13-DEC-96
Dt comp:	27-JAN-97	Well typ:	Stratigraphic
Dtd:	561		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.99302		
Yloc:	40.76372		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Central Park	Quadsec:	G
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000162

A4
North
1/4 - 1/2 Mile

OIL_GAS **NYOG70000000163**

Api wellno:	31061237450000	Cnty:	New York
Hole:	23745	Sidetrck:	0
Completion:	0		
Well nm:	W48 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	15-OCT-96
Dt comp:	15-NOV-96	Well typ:	Stratigraphic
Dtd:	582		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Fordham Gneiss
Xloc:	-73.99297		
Yloc:	40.76373		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Central Park	Quadsec:	G
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000163

5
SW
1/4 - 1/2 Mile

OIL_GAS **NYOG70000000156**

Api wellno:	31061237410000	Cnty:	New York
Hole:	23741	Sidetrck:	0
Completion:	0		
Well nm:	W34 St - B		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	17-SEP-98
Dt comp:	13-OCT-98	Well typ:	Confidential
Dtd:	626		
WI status:	Confidential	Town:	Manhattan
Field:	Confidential	Prodform:	Confidential

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Xloc:	-73.99931		
Yloc:	40.75479		
Confid:	We have confidential information for 6 months.		
Wellst:	CON		
Quad:	Central Park	Quadsec:	C
Deepestfor:	Confidential	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000156

6

NNE

1/2 - 1 Mile

OIL_GAS

NYOG70000000166

Api wellno:	31061237460000	Cnty:	New York
Hole:	23746	Sidetrck:	0
Completion:	0		
Well nm:	W53 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	28-JAN-97
Dt comp:	18-FEB-97	Well typ:	Stratigraphic
Dtd:	534		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.99038		
Yloc:	40.76655		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Not Reported	Quadsec:	Not Reported
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	24-JAN-07	Site id:	NYOG70000000166

7

SSW

1/2 - 1 Mile

OIL_GAS

NYOG70000000153

Api wellno:	31061210540000	Cnty:	New York
Hole:	21054	Sidetrck:	0
Completion:	0		
Well nm:	W. 30 St. - A		
Coname:	U.S. Geological Survey		
Opno:	2370		
Dt approv:	08-OCT-03	Dt spud:	16-OCT-03
Dt comp:	14-NOV-03	Well typ:	Stratigraphic
Dtd:	600		
WI status:	Active	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.99592		
Yloc:	40.74985		
Confid:	Released		
Wellst:	Other Well		
Quad:	Brooklyn	Quadsec:	A
Deepestfor:	Manhattan Schist	Elevation:	35
Dt mod:	26-JUN-09	Site id:	NYOG70000000153

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

8

NNE

1/2 - 1 Mile

OIL_GAS

NYOG70000000170

Api wellno:	31061237470000	Cnty:	New York
Hole:	23747	Sidetck:	0
Completion:	0		
Well nm:	W55 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	17-NOV-98
Dt comp:	18-DEC-98	Well typ:	Stratigraphic
Dtd:	651		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.98953		
Yloc:	40.76803		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Central Park	Quadsec:	G
Deepestfor:	Not Reported	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000170

9

South

1/2 - 1 Mile

OIL_GAS

NYOG70000000151

Api wellno:	31061210550000	Cnty:	New York
Hole:	21055	Sidetck:	0
Completion:	0		
Well nm:	W. 30 St. - C		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	08-OCT-03	Dt spud:	05-APR-04
Dt comp:	22-APR-04	Well typ:	Stratigraphic
Dtd:	600		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.99151		
Yloc:	40.74801		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Brooklyn	Quadsec:	A
Deepestfor:	Manhattan Schist	Elevation:	39
Dt mod:	20-APR-06	Site id:	NYOG70000000151

10

SW

1/2 - 1 Mile

OIL_GAS

NYOG70000000152

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Api wellno:	31061237400000	Cnty:	New York
Hole:	23740	Sidetrck:	0
Completion:	0		
Well nm:	W26 St - A		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	29-JAN-07	Dt spud:	02-SEP-99
Dt comp:	01-OCT-99	Well typ:	Stratigraphic
Dtd:	596		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Fordham Gneiss
Xloc:	-74.00318		
Yloc:	40.74983		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Jersey City	Quadsec:	C
Deepestfor:	Not Applicable	Elevation:	Not Reported
Dt mod:	20-JUL-07	Site id:	NYOG70000000152

11 SSE

1/2 - 1 Mile

OIL_GAS

NYOG70000000149

Api wellno:	31061210650000	Cnty:	New York
Hole:	21065	Sidetrck:	0
Completion:	0		
Well nm:	W. 30 St. - B		
Coname:	New York City Dept. of Environmental Protection		
Opno:	2127		
Dt approv:	31-OCT-01	Dt spud:	20-OCT-03
Dt comp:	20-JAN-04	Well typ:	Stratigraphic
Dtd:	0		
WI status:	Plugged and Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.98685		
Yloc:	40.74614		
Confid:	Released		
Wellst:	Other Well Plugged		
Quad:	Brooklyn	Quadsec:	Not Reported
Deepestfor:	Manhattan Schist	Elevation:	40
Dt mod:	08-DEC-08	Site id:	NYOG70000000149

B12 South

1/2 - 1 Mile

OIL_GAS

NYOG70000000130

Api wellno:	31061237640000	Cnty:	New York
Hole:	23764	Sidetrck:	0
Completion:	0		
Well nm:	Geothermal 1		
Coname:	Ancona, Jack		
Opno:	2426		
Dt approv:	07-MAY-08	Dt spud:	19-AUG-08
Dt comp:	31-OCT-08	Well typ:	Not Listed
Dtd:	1120		
WI status:	Temporarily Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Xloc:	-73.99289		
Yloc:	40.74526		
Confid:	Released		
Wellst:	Other Well		
Quad:	Brooklyn	Quadsec:	A
Deepestfor:	Not Applicable	Elevation:	15
Dt mod:	13-JAN-11	Site id:	NYOG70000000130

B13 South 1/2 - 1 Mile

OIL_GAS NYOG70000000126

Api wellno:	31061237650000	Cnty:	New York
Hole:	23765	Sidetrck:	0
Completion:	0		
Well nm:	Geothermal 2		
Coname:	Ancona, Jack		
Opno:	2426		
Dt approv:	07-MAY-08	Dt spud:	20-AUG-08
Dt comp:	31-OCT-08	Well typ:	Not Listed
Dtd:	1100		
WI status:	Temporarily Abandoned	Town:	Manhattan
Field:	Not Applicable	Prodform:	Not Applicable
Xloc:	-73.993		
Yloc:	40.74513		
Confid:	Released		
Wellst:	Other Well		
Quad:	Brooklyn	Quadsec:	A
Deepestfor:	Not Applicable	Elevation:	15
Dt mod:	13-JAN-11	Site id:	NYOG70000000126

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
NEW YORK	NYC (BRONX)	91	1.59	0.85	16
NEW YORK	NYC (KINGS)	416	1.93	1.19	28.2
NEW YORK	NYC (NEW YORK)	108	2.15	0.98	49.5
NEW YORK	NYC (QUEENS)	501	1.24	0.77	23.8
NEW YORK	NYC (RICHMOND)	225	1.44	0.76	14.1

Federal EPA Radon Zone for NEW YORK County: 3

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands

Source: Department of Environmental Conservation

Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells

Source: New York Department of Health

Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database

Department of Environmental Conservation

Telephone: 518-402-8072

These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon

Source: Department of Health

Telephone: 518-402-7556

Radon Test Results

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRRA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.